

**VT8235 Integrated LAN Software Package (VIA version) for
LAN-On-Motherboard Usage Version: 1.1**

Drivers

Name	Ver.	Supporting OSes	Note
NDIS3	3.15	Win95, Win95OSR2, Win98, Win98SE,	
NDIS4		NT3.51, NT4.0, WinME, Win2000,	
NDIS5		WinXP	
Server ODI (C version)	5.16	Client 32 for DOS, Netware Server 5.0, 5.1, 6.0	
DOS ODI	4.14	MS DOS 6.22 (Netware client for DOS)	
Linux	4.22	Linux Kernel 2.2.x ~ 2.4.17	
DIAG	3.17	MS DOS 6.22	<ul style="list-style-type: none"> 1. Modify F1 help content.
Winsetup	2.10	Win95, Win95OSR2, Win98, Win98SE, NT3.51, NT4.0, WinME, Win2000, WinXP	<ul style="list-style-type: none"> 1. Fix bug about driver source and nt4 source in different CD-ROM in NT4. 2. Fix bug on 2000/XP where winsetup.exe will scan PCI bug 0~1 only. 3. Add parameter 'p' to display progress bar while install driver for network adapter. 4. Fix command parameter bug in NT4.

Drivers/Utilities for Boot ROM users

Name	Ver.	Supported OSes	Note
PXE	2.20		<ul style="list-style-type: none"> 1. Fixed the problem on AMI BIOS. 2. Skipping the offset 8 when calculated new checksum of EEPROM context. 3. Fixed the bug that PXE is fail when restart from Win98.