

Driver Installation/Removal Procedure For Realtek High Definition Audio Codec:

<<< For Windows 2000/XP/Vista x86/x64 (WDM driver) >>>

Setup Driver at first time:

Windows 2000 , XP :

- Step 1. Before installing the Realtek HD Audio Drivers, Press the [Cancel] button if Windows detect the Multimedia Audio device.
- Step 2. Run the setup.exe program to start the installation.
- Step 3. Click on [Next/OK/Go] to continue the procedure. If the Windows popup "Digital Signature Not Found" message, press [Yes] to continue the installation.
- Step 4. Finally, select to restart the system and press [Finish] to complete the installation.

Windows Vista :

- Step 1. Run the setup.exe program to start the installation.
- Step 2. Click on [Next/OK/Go] to continue the procedure. If the Windows popup "Windows can't verify the publisher of this driver software" message, press "Install this driver software anyway" to continue the installation.
- Step 3. Finally, select to restart the system and press [Finish] to complete the installation.

Update Driver:

Windows 2000 , XP :

- Step 1. Follow Step 2,3,4 described in [Setup at first time] above to complete the procedure.

Windows Vista :

- Step 1. Run setup.exe, it will remove the original driver in your system
- Step 2. Click "Next" to remove the original audio driver in your system
- Step 3. Once after the original driver removed , reboot the computer.
- Step 4. Please go back to the new driver package after computer restarted.
- Step 5. Run setup.exe, it will install the new audio driver then.

Remove Driver:

Windows 2000 , XP :

- Step 1. Go to Start\Settings\Control Panel.
- Step 2. Select [Add/Remove Programs] icon.
- Step 3. Select "Realtek HD Audio Drivers" and press [Change/Remove] button.
- Step 4. Click on [Next/OK/Go] to finish the uninstallation.
- Step 5. At the end of the procedure, select to restart the system and press [Finish] to complete the uninstallation.

Windows Vista :

- Step 1. Go to Start\Settings\Control Panel.
- Step 2. Select [Programs] icon.
- Step 3. Select [Programs and Features] icon.

Readme.txt

- Step 4. Select "Realtek HD Audio Drivers" and press [uninstall] button.
- Step 5. Click on [Next/OK/Go] to finish the uninstallation.
- Step 6. At the end of the procedure, select to restart the system and press [Finish] to complete the uninstallation.

<< Other Informations >>

Silent Installation:

Run "Setup.exe /s /f2<path\LogFile> /z[-rp<path\LogFile>]"
i.e. setup.exe /s /f2c:\mylog.log /z[-rpC:\RHDSetup.log]

Silent Uninstallation:

Run "Setup.exe /removeonly /s /f1<path\USetup.iss> /f2<path\LogFile> /z[-rp<path\LogFile>]"
i.e. setup.exe /removeonly /s /f1C:\AudioDriver\USetup.iss /f2c:\mylog.log /z[-rpC:\RHDSetup.log]

Note: 1. Please update Directx version to DirectX8.1 or above.

Version Informations:

If driver package include below drivers :

Windows 2000/XP :
RTKHDA64.sys : 5.10.0.5755
RTKHDAUD.sys : 5.10.0.5755
AlcMtr.exe : 1.6.0.3
AlcWzrd.exe : 1.1.0.37
MicCal.exe : 1.1.2.0
RTHDCPL.exe : 2.2.5.5
RtkAudioService64.exe : 1.0.0.17
RtkAudioService.exe : 1.0.0.16
RTLCP.exe : 1.0.1.66
RtlUpd64.exe : 2.7.1.1
RtlUpd.exe : 2.7.1.1
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.32
vncutil64.exe : 1.0.0.22
vncutil.exe : 1.0.0.22
AMBFilt64.sys : 5.10.0.4240
AMBFilt.sys : 5.10.0.4240
Mbnfilt64.sys : 5.10.0.4115
Mbnfilt.sys : 5.10.0.4112
ALSndMgr.cpl : 1.0.0.11
RTSndMgr.cpl : 1.0.1.0
RCoInst64XP.dll : 1.0.4.1
RTCOMDLL.dll : 1.0.0.97
RtkCoInstXP.dll : 1.0.4.1
RtlCPAPI.dll : 1.0.1.9

Vista driver : -----
Vista driver for x86
RTKVHDA.sys : 6.0.1.5755
AERTSrv.exe : 1.0.32.8
RtHDVCpl.exe : 1.0.0.281
RtkAudioService.exe : 1.0.0.17
RtlUpd.exe : 2.7.1.1
SkyTel.exe : 2.0.2.2
vncutil.exe : 1.0.0.23
RTSndMgr.cpl : 1.0.0.13
AERTACap.dll : 2.0.32.1
AERTARen.dll : 1.0.32.7
CTAP032.dll : 1.0.0.530
ctppld.dll : 1.0.0.530
DaisyWrp.dll : 1.0.0.70

Readme.txt

FMAP0.dll : 0.0.12.1
 MaxxAudioAPO.dll : 1.2.2.0
 MaxxAudioAPO20.dll : 2.2.2.0
 MaxxAudioEQ.dll : 5.9.7.0
 ppchain.dll : 1.0.0.70
 RTCOMDLL.dll : 2.0.0.103
 RtkAPO.dll : 11.0.6000.81
 RtkApoApi.dll : 1.0.0.9
 RtkCfg.dll : 1.0.0.1
 RtkCoInst.dll : 1.0.4.1
 RtkPgExt.dll : 6.0.6000.65
 RtlCPAPI.dll : 1.0.2.1
 slcshp32.dll : 1.0.3.0
 slgeq32.dll : 1.0.1.0
 slh36032.dll : 1.0.2.0
 slInit32.dll : 1.1.1.0
 sltshd32.dll : 1.1.0.0
 sluapo32.dll : 1.2.6.0
 SRSHP360.dll : 1.1.0.0
 SRSTSHD.dll : 1.1.4.0
 SRSTSXT.dll : 3.2.0.0
 SRSWOW.dll : 1.1.3.0
 WavesLib.dll : 5.9.7.0

Vista driver for x64

RTKVHD64.sys : 6.0.1.5755
 AERTSr64.exe : 1.0.64.8
 RAVCpl64.exe : 1.0.0.281
 RtkAudioService64.exe : 1.0.0.17
 RtlUpd64.exe : 2.7.1.1
 SkyTel.exe : 2.0.2.2
 vncutil64.exe : 1.0.0.23
 GWfilt64.sys : 6.10.0.3
 RTSnM64.cpl : 1.0.0.13
 AERTAC64.dll : 2.0.64.1
 AERTAR64.dll : 1.0.64.7
 CTAP032.dll : 1.0.0.530
 CTAP064.dll : 1.0.0.530
 ctppld.dll : 1.0.0.530
 DaisyWp.dll : 1.0.0.70
 FMAP064.dll : 0.0.12.1
 MaxxAudioAPO20.dll : 2.2.2.0
 ppchain.dll : 1.0.0.70
 RCoInst64.dll : 1.0.4.1
 RtCOM64.dll : 2.0.0.103
 RTCOMDLL.dll : 2.0.0.103
 RtkApi64.dll : 1.0.0.9
 RtkAPO64.dll : 11.0.6000.81
 RtkCfg.dll : 1.0.0.1
 RtkCfg64.dll : 1.0.0.1
 RtlCPAPI.dll : 1.0.2.1
 RtlCPAPI64.dll : 1.0.2.1
 RtPgEx64.dll : 6.0.6000.65
 slcshp64.dll : 1.0.3.0
 slgeq64.dll : 1.0.1.0
 slh36064.dll : 1.0.2.0
 slInit64.dll : 1.1.1.0
 sltshd64.dll : 1.1.0.0
 sluapo64.dll : 1.2.6.0
 SRSHP64.dll : 1.1.0.0
 SRSTSH64.dll : 1.1.4.0
 SRSTSX64.dll : 3.2.0.0
 SRSWOW64.dll : 1.1.3.0

HDMI Driver : -----

Vista x86:

RtHDMV.sys : 6.0.1.5735
 RtkUpd.exe : 2.7.1.1
 RHCoInst.dll : 1.0.3.2
 RHDMExt.dll : 6.0.6000.64
 RtkHDM.dll : 11.0.6000.80

Vista x64:

RtHDMVX.sys : 6.0.1.5735

| | | |
|----------------|------------|--------------|
| | Readme.txt | |
| RtkUpd64.exe | : | 2.7.1.1 |
| RHCoInst64.dll | : | 1.0.3.2 |
| RHDMEx64.dll | : | 6.0.6000.64 |
| RtkHDM64.dll | : | 11.0.6000.80 |

| | | |
|------------|---|-------------|
| XP/2K x86: | | |
| RtHDM.sys | : | 5.10.0.5735 |
| RtkUpd.exe | : | 2.7.1.1 |

| | | |
|--------------|---|-------------|
| XP/2K x64: | | |
| RtHDMX.sys | : | 5.10.0.5735 |
| RtkUpd64.exe | : | 2.7.1.1 |

| | | |
|----------------------|---|------|
| Driver Setup Program | : | 2.69 |
|----------------------|---|------|

History:

Driver Package R2.11

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Driver :
 1. Customizations.
 2. Add DisplayVersion registry key in INF files.

Windows 2000/XP : -----

| | | |
|-----------------------|---|-------------|
| Windows 2000/XP : | | |
| RTKHDA64.sys | : | 5.10.0.5755 |
| RTKHDAUD.sys | : | 5.10.0.5755 |
| Alcmtr.exe | : | 1.6.0.3 |
| AlcWzrd.exe | : | 1.1.0.37 |
| McCal.exe | : | 1.1.2.0 |
| RTHDCPL.exe | : | 2.2.5.5 |
| RtkAudioService64.exe | : | 1.0.0.17 |
| RtkAudioService.exe | : | 1.0.0.16 |
| RTLCPPL.exe | : | 1.0.1.66 |
| RtlUpd64.exe | : | 2.7.1.1 |
| RtlUpd.exe | : | 2.7.1.1 |
| SkyTel.exe | : | 2.0.2.0 |
| SoundMan.exe | : | 1.0.0.32 |
| vncutil64.exe | : | 1.0.0.22 |
| vncutil.exe | : | 1.0.0.22 |
| AMBfilt64.sys | : | 5.10.0.4240 |
| AMBfilt.sys | : | 5.10.0.4240 |
| Monfilt64.sys | : | 5.10.0.4115 |
| Monfilt.sys | : | 5.10.0.4112 |
| ALSndMgr.cpl | : | 1.0.0.11 |
| RTSndMgr.cpl | : | 1.0.1.0 |
| RCoInst64XP.dll | : | 1.0.4.1 |
| RTCOMDLL.dll | : | 1.0.0.97 |
| RtkCoInstXP.dll | : | 1.0.4.1 |
| RtlCPAPI.dll | : | 1.0.1.9 |

Vista driver : -----

| | | |
|----------------------|---|------------|
| Vista driver for x86 | | |
| RTKVHDA.sys | : | 6.0.1.5755 |
| AERTSrv.exe | : | 1.0.32.8 |
| RtHDVCpl.exe | : | 1.0.0.281 |
| RtkAudioService.exe | : | 1.0.0.17 |
| RtlUpd.exe | : | 2.7.1.1 |
| SkyTel.exe | : | 2.0.2.2 |
| vncutil.exe | : | 1.0.0.23 |
| RTSndMgr.cpl | : | 1.0.0.13 |
| AERTACap.dll | : | 2.0.32.1 |
| AERTARen.dll | : | 1.0.32.7 |
| CTAP032.dll | : | 1.0.0.530 |
| ctppld.dll | : | 1.0.0.530 |

Readme.txt

| | |
|-----------------------|----------------|
| DaisyWrp.dll | : 1.0.0.70 |
| FMAP0.dll | : 0.0.12.1 |
| MaxxAudioAPO.dll | : 1.2.2.0 |
| MaxxAudioAPO20.dll | : 2.2.2.0 |
| MaxxAudioEQ.dll | : 5.9.7.0 |
| ppchain.dll | : 1.0.0.70 |
| RTCOMDLL.dll | : 2.0.0.103 |
| RtkAPO.dll | : 11.0.6000.81 |
| RtkApoApi.dll | : 1.0.0.9 |
| RtkCfg.dll | : 1.0.0.1 |
| RtkCoInst.dll | : 1.0.4.1 |
| RtkPgExt.dll | : 6.0.6000.65 |
| RtlCPAPI.dll | : 1.0.2.1 |
| slcshp32.dll | : 1.0.3.0 |
| slgeq32.dll | : 1.0.1.0 |
| slh36032.dll | : 1.0.2.0 |
| slinit32.dll | : 1.1.1.0 |
| sltshd32.dll | : 1.1.0.0 |
| sluapo32.dll | : 1.2.6.0 |
| SRSHP360.dll | : 1.1.0.0 |
| SRSTSHD.dll | : 1.1.4.0 |
| SRSTSXT.dll | : 3.2.0.0 |
| SRSWOW.dll | : 1.1.3.0 |
| WavesLib.dll | : 5.9.7.0 |
| Vista driver for x64 | |
| RTKVHD64.sys | : 6.0.1.5755 |
| AERTSr64.exe | : 1.0.64.8 |
| RAVCpl64.exe | : 1.0.0.281 |
| RtkAudioService64.exe | : 1.0.0.17 |
| RtlUpd64.exe | : 2.7.1.1 |
| SkyTel.exe | : 2.0.2.2 |
| vncutil64.exe | : 1.0.0.23 |
| GWfilt64.sys | : 6.10.0.3 |
| RTSnMg64.cpl | : 1.0.0.13 |
| AERTAC64.dll | : 2.0.64.1 |
| AERTAR64.dll | : 1.0.64.7 |
| CTAP032.dll | : 1.0.0.530 |
| CTAP064.dll | : 1.0.0.530 |
| ctppld.dll | : 1.0.0.530 |
| DaisyWrp.dll | : 1.0.0.70 |
| FMAP064.dll | : 0.0.12.1 |
| MaxxAudioAPO20.dll | : 2.2.2.0 |
| ppchain.dll | : 1.0.0.70 |
| RCoInst64.dll | : 1.0.4.1 |
| RtCOM64.dll | : 2.0.0.103 |
| RTCOMDLL.dll | : 2.0.0.103 |
| RtkApi64.dll | : 1.0.0.9 |
| RtkAPO64.dll | : 11.0.6000.81 |
| RtkCfg.dll | : 1.0.0.1 |
| RtkCfg64.dll | : 1.0.0.1 |
| RtlCPAPI.dll | : 1.0.2.1 |
| RtlCPAPI64.dll | : 1.0.2.1 |
| RtPgEx64.dll | : 6.0.6000.65 |
| slcshp64.dll | : 1.0.3.0 |
| slgeq64.dll | : 1.0.1.0 |
| slh36064.dll | : 1.0.2.0 |
| slinit64.dll | : 1.1.1.0 |
| sltshd64.dll | : 1.1.0.0 |
| sluapo64.dll | : 1.2.6.0 |
| SRSHP64.dll | : 1.1.0.0 |
| SRSTSH64.dll | : 1.1.4.0 |
| SRSTSX64.dll | : 3.2.0.0 |
| SRSWOW64.dll | : 1.1.3.0 |
| HDMI Driver : ----- | |
| Vista x86: | |
| RtHDMV.sys | : 6.0.1.5735 |
| RtkUpd.exe | : 2.7.1.1 |
| RHCoInst.dll | : 1.0.3.2 |
| RHDMExt.dll | : 6.0.6000.64 |
| RtkHDM.dll | : 11.0.6000.80 |
| Vista x64: | |
| RtHDMVX.sys | : 6.0.1.5735 |
| RtkUpd64.exe | : 2.7.1.1 |

Readme.txt

RHCoInst64.dll : 1.0.3.2
 RHDMEx64.dll : 6.0.6000.64
 RtkHDM64.dll : 11.0.6000.80

XP/2K x86:
 RtHDM.sys : 5.10.0.5735
 RtkUpd.exe : 2.7.1.1
 XP/2K x64:
 RtHDMX.sys : 5.10.0.5735
 RtkUpd64.exe : 2.7.1.1

Driver Setup Program : 2.69

Windows 2000/XP Operate on :
 Microsoft High Definition Audio Driver Package - KB888111
 Package file version (kb888111.exe) : 6.1.22.0
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.10

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Win2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Driver :
 1. Customizations.
 2. Support ALC665.

Windows 2000/XP : -----

Windows 2000/XP :
 RTKHDA64.sys : 5.10.0.5745
 RTKHDAUD.sys : 5.10.0.5745
 McCal.exe : 1.1.2.0
 RTHDCPL.exe : 2.2.5.2
 RtkAudioService64.exe : 1.0.0.17
 RtkAudioService.exe : 1.0.0.16
 RTLCPPL.exe : 1.0.1.66
 RtlUpd64.exe : 2.7.1.1
 RtlUpd.exe : 2.7.1.1
 SkyTel.exe : 2.0.2.0
 SoundMan.exe : 1.0.0.32
 vncutil64.exe : 1.0.0.22
 vncutil.exe : 1.0.0.22
 Alcmtr.exe : 1.6.0.3
 AlcWzrd.exe : 1.1.0.37
 AMBFilt64.sys : 5.10.0.4240
 AMBFilt.sys : 5.10.0.4240
 Mnfilt64.sys : 5.10.0.4115
 Mnfilt.sys : 5.10.0.4112
 RTSndMgr.cpl : 1.0.1.0
 ALSndMgr.cpl : 1.0.0.11
 RCoInst64XP.dll : 1.0.4.1
 RTCOMDLL.dll : 1.0.0.97
 RtkCoInstXP.dll : 1.0.4.1
 RtlCPAPI.dll : 1.0.1.9

Vista driver : -----

Vista driver for x86
 RTKVHDA.sys : 6.0.1.5745
 AERTSrv.exe : 1.0.32.8
 RtHDVCpl.exe : 1.0.0.273
 RtkAudioService.exe : 1.0.0.17
 RtlUpd.exe : 2.7.1.1
 SkyTel.exe : 2.0.2.2
 vncutil.exe : 1.0.0.22
 RTSndMgr.cpl : 1.0.0.13
 AERTACap.dll : 2.0.32.1
 AERTARen.dll : 1.0.32.7
 CTAP032.dll : 1.0.0.530

Readme.txt

| | |
|-----------------------|----------------|
| ctpld.dll | : 1.0.0.530 |
| DaisyWrp.dll | : 1.0.0.70 |
| FMAP0.dll | : 0.0.12.1 |
| MaxxAudioAPO.dll | : 1.2.2.0 |
| MaxxAudioAPO20.dll | : 2.2.2.0 |
| MaxxAudioEQ.dll | : 5.9.7.0 |
| ppchain.dll | : 1.0.0.70 |
| RCoInst64.dll | : 1.0.4.0 |
| RTCOMDLL.dll | : 2.0.0.103 |
| RtkAPO.dll | : 11.0.6000.81 |
| RtkApoApi.dll | : 1.0.0.9 |
| RtkCfg.dll | : 1.0.0.1 |
| RtkCoInst.dll | : 1.0.4.1 |
| RtkPgExt.dll | : 6.0.6000.65 |
| RtlCPAPI.dll | : 1.0.2.1 |
| slcshp32.dll | : 1.0.3.0 |
| slgeq32.dll | : 1.0.1.0 |
| slh36032.dll | : 1.0.2.0 |
| slInit32.dll | : 1.1.1.0 |
| sltshd32.dll | : 1.1.0.0 |
| sluapo32.dll | : 1.2.6.0 |
| SRSHP360.dll | : 1.1.0.0 |
| SRSTSHD.dll | : 1.1.4.0 |
| SRSTSXT.dll | : 3.2.0.0 |
| SRSWOW.dll | : 1.1.3.0 |
| WavesLib.dll | : 5.9.7.0 |
| Vista driver for x64 | |
| RTKVHD64.sys | : 6.0.1.5745 |
| AERTSr64.exe | : 1.0.64.8 |
| RAVCpl64.exe | : 1.0.0.273 |
| RtkAudioService64.exe | : 1.0.0.17 |
| RtlUpd64.exe | : 2.7.1.1 |
| SkyTel.exe | : 2.0.2.2 |
| vncutil64.exe | : 1.0.0.22 |
| GWfilt64.sys | : 6.10.0.3 |
| RTSnMg64.cpl | : 1.0.0.13 |
| AERTAC64.dll | : 2.0.64.1 |
| AERTAR64.dll | : 1.0.64.7 |
| CTAP032.dll | : 1.0.0.530 |
| CTAP064.dll | : 1.0.0.530 |
| ctpld.dll | : 1.0.0.530 |
| DaisyWrp.dll | : 1.0.0.70 |
| FMAP064.dll | : 0.0.12.1 |
| MaxxAudioAPO20.dll | : 2.2.2.0 |
| ppchain.dll | : 1.0.0.70 |
| RCoInst64.dll | : 1.0.4.1 |
| RtCOM64.dll | : 2.0.0.103 |
| RTCOMDLL.dll | : 2.0.0.103 |
| RtkApi64.dll | : 1.0.0.9 |
| RtkAPO64.dll | : 11.0.6000.81 |
| RtkCfg.dll | : 1.0.0.1 |
| RtkCfg64.dll | : 1.0.0.1 |
| RtkCoInst.dll | : 1.0.4.0 |
| RtlCPAPI.dll | : 1.0.2.1 |
| RtlCPAPI64.dll | : 1.0.2.1 |
| RtPgEx64.dll | : 6.0.6000.65 |
| slcshp64.dll | : 1.0.3.0 |
| slgeq64.dll | : 1.0.1.0 |
| slh36064.dll | : 1.0.2.0 |
| slInit64.dll | : 1.1.1.0 |
| sltshd64.dll | : 1.1.0.0 |
| sluapo64.dll | : 1.2.6.0 |
| SRSHP64.dll | : 1.1.0.0 |
| SRSTSH64.dll | : 1.1.4.0 |
| SRSTSX64.dll | : 3.2.0.0 |
| SRSWOW64.dll | : 1.1.3.0 |
| HDMI Driver : ----- | |
| Vista x86: | |
| RtHDMV.sys | : 6.0.1.5735 |
| RtkUpd.exe | : 2.7.1.1 |
| RHCoInst.dll | : 1.0.3.2 |
| RHDMExt.dll | : 6.0.6000.64 |
| RtkHDM.dll | : 11.0.6000.80 |

Readme.txt

Vista x64:
RtHDM VX. sys : 6.0.1.5735
RtkUpd64.exe : 2.7.1.1
RHCoInst64.dll : 1.0.3.2
RHDME64.dll : 6.0.6000.64
RtkHDM64.dll : 11.0.6000.80

XP/2K x86:
RtHDM.sys : 5.10.0.5735
RtkUpd.exe : 2.7.1.1
XP/2K x64:
RtHDM X.sys : 5.10.0.5735
RtkUpd64.exe : 2.7.1.1

Driver Setup Program : 2.69

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.09

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WnXP/Wn2000/Wn2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Widnows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Driver :
 1. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :
RTKHDA64.sys : 5.10.0.5735
RTKHDAUD.sys : 5.10.0.5735
Alcmttr.exe : 1.6.0.3
AlcWzrd.exe : 1.1.0.37
MicCal.exe : 1.1.2.0
RTHDCPL.exe : 2.2.5.1
RtkAudioService.exe : 1.0.0.16
RtkAudioService64.exe : 1.0.0.17
RTLCPPL.exe : 1.0.1.66
RtlUpd.exe : 2.7.1.1
RtlUpd64.exe : 2.7.1.1
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.32
vncutil.exe : 1.0.0.22
vncutil64.exe : 1.0.0.22
AMBfilt.sys : 5.10.0.4240
AMBfilt64.sys : 5.10.0.4240
Mnfiltr.sys : 5.10.0.4112
Mnfiltr64.sys : 5.10.0.4115
ALSndMgr.cpl : 1.0.0.11
RTSndMgr.cpl : 1.0.1.0
RCoInst64XP.dll : 1.0.3.9
RtCOMDLL.dll : 1.0.0.97
RtkCoInstXP.dll : 1.0.3.9
RtlCPAPI.dll : 1.0.1.9

Vista driver : -----

Vista driver for x86
RTKVHDA.sys : 6.0.1.5735
AERTSrv.exe : 1.0.32.8
RtHDVCpl.exe : 1.0.0.264
RtkAudioService.exe : 1.0.0.17
RtlUpd.exe : 2.7.1.1
SkyTel.exe : 2.0.2.1
vncutil.exe : 1.0.0.22
RTSndMgr.cpl : 1.0.0.13
AERTACap.dll : 2.0.32.1

Readme.txt

| | |
|-----------------------|----------------|
| AERTARen.dll | : 1.0.32.7 |
| CTAP032.dll | : 1.0.0.530 |
| ctppld.dll | : 1.0.0.530 |
| DaisyWrp.dll | : 1.0.0.70 |
| FMAP0.dll | : 0.0.12.1 |
| MaxxAudioAPO.dll | : 1.2.2.0 |
| MaxxAudioAPO20.dll | : 2.2.2.0 |
| MaxxAudioEQ.dll | : 5.9.7.0 |
| ppchain.dll | : 1.0.0.70 |
| RTCOMDLL.dll | : 2.0.0.100 |
| RtkAPO.dll | : 11.0.6000.80 |
| RtkApoApi.dll | : 1.0.0.8 |
| RtkCoInst.dll | : 1.0.3.9 |
| RtkPgExt.dll | : 6.0.6000.64 |
| RtlCPAPI.dll | : 1.0.1.9 |
| slcshp32.dll | : 1.0.3.0 |
| slgeq32.dll | : 1.0.1.0 |
| slh36032.dll | : 1.0.2.0 |
| slInit32.dll | : 1.1.1.0 |
| sltshd32.dll | : 1.1.0.0 |
| sluapo32.dll | : 1.2.6.0 |
| SRSHP360.dll | : 1.1.0.0 |
| SRSTSHD.dll | : 1.1.4.0 |
| SRSTSXT.dll | : 3.2.0.0 |
| SRSWOW.dll | : 1.1.3.0 |
| WavesLib.dll | : 5.9.7.0 |
| Vista driver for x64 | |
| RTKVHD64.sys | : 6.0.1.5735 |
| AERTSr64.exe | : 1.0.64.8 |
| RAVCpl64.exe | : 1.0.0.264 |
| RtkAudioService64.exe | : 1.0.0.17 |
| RtlUpd64.exe | : 2.7.1.1 |
| SkyTel.exe | : 2.0.2.1 |
| vncutil64.exe | : 1.0.0.22 |
| GWfilt64.sys | : 6.10.0.3 |
| RTSnMg64.cpl | : 1.0.0.13 |
| AERTAC64.dll | : 2.0.64.1 |
| AERTAR64.dll | : 1.0.64.7 |
| CTAP032.dll | : 1.0.0.530 |
| CTAP064.dll | : 1.0.0.530 |
| ctppld.dll | : 1.0.0.530 |
| DaisyWrp.dll | : 1.0.0.70 |
| FMAP064.dll | : 0.0.12.1 |
| MaxxAudioAPO20.dll | : 2.2.2.0 |
| ppchain.dll | : 1.0.0.70 |
| RCoInst64.dll | : 1.0.3.9 |
| RtCOM64.dll | : 2.0.0.100 |
| RTCOMDLL.dll | : 2.0.0.100 |
| RtkApi64.dll | : 1.0.0.8 |
| RtkAPO64.dll | : 11.0.6000.80 |
| RtlCPAPI.dll | : 1.0.1.9 |
| RtkPgEx64.dll | : 6.0.6000.64 |
| slcshp64.dll | : 1.0.3.0 |
| slgeq64.dll | : 1.0.1.0 |
| slh36064.dll | : 1.0.2.0 |
| slInit64.dll | : 1.1.1.0 |
| sltshd64.dll | : 1.1.0.0 |
| sluapo64.dll | : 1.2.6.0 |
| SRSHP64.dll | : 1.1.0.0 |
| SRSTSH64.dll | : 1.1.4.0 |
| SRSTSX64.dll | : 3.2.0.0 |
| SRSWOW64.dll | : 1.1.3.0 |
| HDMI Driver : ----- | |
| Vista x86: | |
| RtHDMV.sys | : 6.0.1.5735 |
| RtkUpd.exe | : 2.7.1.1 |
| RHCoInst.dll | : 1.0.3.2 |
| RHDMExt.dll | : 6.0.6000.64 |
| RtkHDM.dll | : 11.0.6000.80 |
| Vista x64: | |
| RtHDMVX.sys | : 6.0.1.5735 |
| RtkUpd64.exe | : 2.7.1.1 |
| RHCoInst64.dll | : 1.0.3.2 |

Readme.txt

RHDMx64.dll : 6.0.6000.64
 RtkHDM64.dll : 11.0.6000.80

XP/2K x86:
 RtHDM.sys : 5.10.0.5735
 RtkUpd.exe : 2.7.1.1
 XP/2K x64:
 RtHDMX.sys : 5.10.0.5735
 RtkUpd64.exe : 2.7.1.1

Driver Setup Program : 2.67

Windows 2000/XP Operate on :
 Microsoft High Definition Audio Driver Package - KB888111
 Package file version (kb888111.exe) : 6.1.22.0
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.08

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WnXP/Wn2000/Wn2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Widnows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix

- 1.) Driver :
 1. Customizations.
 2. Support Andrea microphone effect mixer type GUI.
- 2.) Package:

1. Change setup program install location to meet the requirements of OEM Ready Certification

Tool 1.1.0.1101

Windows 2000/XP : -----

Windows 2000/XP :
 RTKHDA64.sys : 5.10.0.5730
 RTKHDAUD.sys : 5.10.0.5730
 McCal.exe : 1.1.2.0
 RTHDCPL.exe : 2.2.4.9
 RtkAudioService64.exe : 1.0.0.17
 RtkAudioService.exe : 1.0.0.16
 RTLCPPL.exe : 1.0.1.66
 RtlUpd64.exe : 2.7.1.1
 RtlUpd.exe : 2.7.1.1
 SkyTel.exe : 2.0.2.0
 SoundMn.exe : 1.0.0.32
 vncutil64.exe : 1.0.0.22
 vncutil.exe : 1.0.0.22
 Alcmtr.exe : 1.6.0.3
 AlcWzrd.exe : 1.1.0.37
 Mbnfilt64.sys : 5.10.0.4115
 Mbnfilt.sys : 5.10.0.4112
 AMBFilt64.sys : 5.10.0.4240
 AMBFilt.sys : 5.10.0.4240
 RTSndMgr.cpl : 1.0.1.0
 ALSndMgr.cpl : 1.0.0.11
 RCoInst64XP.dll : 1.0.3.8
 RTCOMDLL.dll : 1.0.0.97
 RtkCoInstXP.dll : 1.0.3.8
 RtlCPAPI.dll : 1.0.1.9

Vista driver : -----

Vista driver for x86
 RTKVHDA.sys : 6.0.1.5730
 AERTSrv.exe : 1.0.32.8
 RtHDVCpl.exe : 1.0.0.257
 RtkAudioService.exe : 1.0.0.17
 RtlUpd.exe : 2.7.1.1
 SkyTel.exe : 2.0.2.1
 vncutil.exe : 1.0.0.22
 RTSndMgr.cpl : 1.0.0.10
 AERTACap.dll : 2.0.32.1

Readme.txt

| | |
|-----------------------|----------------|
| AERTARen.dll | : 1.0.32.7 |
| CTAP032.dll | : 1.0.0.530 |
| ctppld.dll | : 1.0.0.530 |
| DaisyWrp.dll | : 1.0.0.70 |
| FMAP0.dll | : 0.0.12.1 |
| MaxxAudioAPO.dll | : 1.2.2.0 |
| MaxxAudioAPO20.dll | : 2.0.13.0 |
| MaxxAudioEQ.dll | : 5.9.7.0 |
| ppchain.dll | : 1.0.0.70 |
| RTCOMDLL.dll | : 2.0.0.100 |
| RtkAPO.dll | : 11.0.6000.79 |
| RtkApoApi.dll | : 1.0.0.8 |
| RtkCoInst.dll | : 1.0.3.8 |
| RtkPgExt.dll | : 6.0.6000.64 |
| RtlCPAPI.dll | : 1.0.1.9 |
| slcshp32.dll | : 1.0.3.0 |
| slgeq32.dll | : 1.0.1.0 |
| slh36032.dll | : 1.0.2.0 |
| slInit32.dll | : 1.1.1.0 |
| sltshd32.dll | : 1.1.0.0 |
| sluapo32.dll | : 1.2.6.0 |
| SRSHP360.dll | : 1.1.0.0 |
| SRSTSHD.dll | : 1.1.4.0 |
| SRSTSXT.dll | : 3.2.0.0 |
| SRSWOW.dll | : 1.1.3.0 |
| WavesLib.dll | : 5.9.7.0 |
| Vista driver for x64 | |
| RTKVHD64.sys | : 6.0.1.5730 |
| AERTSr64.exe | : 1.0.64.8 |
| RAVCpl64.exe | : 1.0.0.257 |
| RtkAudioService64.exe | : 1.0.0.17 |
| RtlUpd64.exe | : 2.7.1.1 |
| SkyTel.exe | : 2.0.2.1 |
| vncutil64.exe | : 1.0.0.22 |
| GWfilt64.sys | : 6.10.0.3 |
| RTSnMg64.cpl | : 1.0.0.10 |
| AERTAC64.dll | : 2.0.64.1 |
| AERTAR64.dll | : 1.0.64.7 |
| CTAP032.dll | : 1.0.0.530 |
| CTAP064.dll | : 1.0.0.530 |
| ctppld.dll | : 1.0.0.530 |
| DaisyWrp.dll | : 1.0.0.70 |
| FMAP064.dll | : 0.0.12.1 |
| MaxxAudioAPO20.dll | : 2.0.12.0 |
| ppchain.dll | : 1.0.0.70 |
| RCoInst64.dll | : 1.0.3.8 |
| RtCOM64.dll | : 2.0.0.100 |
| RTCOMDLL.dll | : 2.0.0.100 |
| RtkApi64.dll | : 1.0.0.8 |
| RtkAPO64.dll | : 11.0.6000.79 |
| RtlCPAPI.dll | : 1.0.1.9 |
| RtkPgEx64.dll | : 6.0.6000.64 |
| slcshp64.dll | : 1.0.3.0 |
| slgeq64.dll | : 1.0.1.0 |
| slh36064.dll | : 1.0.2.0 |
| slInit64.dll | : 1.1.1.0 |
| sltshd64.dll | : 1.1.0.0 |
| sluapo64.dll | : 1.2.6.0 |
| SRSHP64.dll | : 1.1.0.0 |
| SRSTSH64.dll | : 1.1.4.0 |
| SRSTSX64.dll | : 3.2.0.0 |
| SRSWOW64.dll | : 1.1.3.0 |
| HDMI Driver : ----- | |
| Vista x86: | |
| RtHDMV.sys | : 6.0.1.5692 |
| RtkUpd.exe | : 2.7.1.0 |
| RHCoInst.dll | : 1.0.3.2 |
| RHDMExt.dll | : 6.0.6000.54 |
| RtkHDM.dll | : 11.0.6000.72 |
| Vista x64: | |
| RtHDMVX.sys | : 6.0.1.5692 |
| RtkUpd64.exe | : 2.7.1.0 |
| RHCoInst64.dll | : 1.0.3.2 |
| RHDMEx64.dll | : 6.0.6000.54 |

Readme.txt

RtkHDM64.dll : 11.0.6000.72

XP/2K x86:
 RtkHDM.sys : 5.10.0.5692
 RtkUpd.exe : 2.7.1.0
 XP/2K x64:
 RtkHDMX.sys : 5.10.0.5692
 RtkUpd64.exe : 2.7.1.0

Driver Setup Program : 2.67

Windows 2000/XP Operate on :
 Microsoft High Definition Audio Driver Package - KB888111
 Package file version (kb888111.exe) : 6.1.22.0
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.07

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Win2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Driver :
 1. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :

RTKHDA64.sys : 5.10.0.5717
 RTKHDAUD.sys : 5.10.0.5717
 Alcmtr.exe : 1.6.0.3
 AlcWzrd.exe : 1.1.0.37
 MicCal.exe : 1.1.2.0
 RTHDCPL.exe : 2.2.4.8
 RTLCPPL.exe : 1.0.1.66
 RtlUpd.exe : 2.7.1.1
 RtlUpd64.exe : 2.7.1.1
 SkyTel.exe : 2.0.2.0
 SoundMan.exe : 1.0.0.32
 AMBFilt.sys : 5.10.0.4240
 AMBFilt64.sys : 5.10.0.4240
 Monfilt.sys : 5.10.0.4112
 Monfilt64.sys : 5.10.0.4115
 ALSndMgr.cpl : 1.0.0.11
 RTSndMgr.cpl : 1.0.1.0
 RTCOMDLL.dll : 1.0.0.97
 RtlCPAPI.dll : 1.0.1.9

Vista driver : -----

Vista driver for x86

RTKVHDA.sys : 6.0.1.5717
 AERTSrv.exe : 1.0.32.7
 RtkHdvcpl.exe : 1.0.0.251
 RtkAudioService.exe : 1.0.0.17
 RtlUpd.exe : 2.7.1.1
 SkyTel.exe : 2.0.2.1
 vncutil.exe : 1.0.0.22
 RTSndMgr.cpl : 1.0.0.10
 AERTACap.dll : 1.0.32.7
 AERTARen.dll : 1.0.32.3
 CTAP032.dll : 1.0.0.530
 ctppld.dll : 1.0.0.530
 DaisyWrp.dll : 1.0.0.70
 FMAPO.dll : 40.59.0.0
 MaxxAudioAPO.dll : 1.2.2.0
 MaxxAudioAPO20.dll : 2.0.13.0
 MaxxAudioEQ.dll : 5.9.7.0
 ppchain.dll : 1.0.0.70
 RTCOMDLL.dll : 2.0.0.100
 RtkAPO.dll : 11.0.6000.78
 RtkApoApi.dll : 1.0.0.6
 RtkCoInst.dll : 1.0.3.7

Readme.txt

```

RtkPgExt.dll : 6.0.6000.61
RtlCPAPI.dll : 1.0.1.9
slcshp32.dll : 1.0.3.0
slgeq32.dll : 1.0.1.0
slh36032.dll : 1.0.2.0
slInit32.dll : 1.1.1.0
sltshd32.dll : 1.1.0.0
sluapo32.dll : 1.2.6.0
SRSHp360.dll : 1.1.0.0
SRSTSHD.dll : 1.1.4.0
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.1.3.0
WavesLib.dll : 5.9.7.0
Vista driver for x64
RTKVHD64.sys : 6.0.1.5717
AERTSr64.exe : 1.0.64.7
RAVCpl64.exe : 1.0.0.251
RtkAudioService.exe : 1.0.0.17
RtlUpd64.exe : 2.7.1.1
SkyTel.exe : 2.0.2.1
vncutil.exe : 1.0.0.22
GWfilt64.sys : 6.10.0.3
RTSnMg64.cpl : 1.0.0.10
AERTAC64.dll : 1.0.64.7
AERTAR64.dll : 1.0.64.3
CTAP032.dll : 1.0.0.530
CTAP064.dll : 1.0.0.530
ctppld.dll : 1.0.0.530
DaisyWrp.dll : 1.0.0.70
FMAP064.dll : 40.59.0.0
MaxxAudioAP020.dll : 2.0.12.0
ppchain.dll : 1.0.0.70
RCoInst64.dll : 1.0.3.7
RtCOMB4.dll : 2.0.0.100
RTCOMDLL.dll : 2.0.0.100
RtkApi64.dll : 1.0.0.6
RtkAP064.dll : 11.0.6000.78
RtlCPAPI.dll : 1.0.1.9
RtPgEx64.dll : 6.0.6000.61
slcshp64.dll : 1.0.3.0
slgeq64.dll : 1.0.1.0
slh36064.dll : 1.0.2.0
slInit64.dll : 1.1.1.0
sltshd64.dll : 1.1.0.0
sluapo64.dll : 1.2.6.0
SRSHp64.dll : 1.1.0.0
SRSTSH64.dll : 1.1.4.0
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
HDM Driver : -----
Vista x86:
RtHDM.V.sys : 6.0.1.5692
RtkUpd.exe : 2.7.1.0
RHCoInst.dll : 1.0.3.2
RHDMExt.dll : 6.0.6000.54
RtkHDM.dll : 11.0.6000.72

Vista x64:
RtHDM.VX.sys : 6.0.1.5692
RtkUpd64.exe : 2.7.1.0
RHCoInst64.dll : 1.0.3.2
RHDMEx64.dll : 6.0.6000.54
RtkHDM64.dll : 11.0.6000.72

XP/2K x86:
RtHDM.sys : 5.10.0.5692
RtkUpd.exe : 2.7.1.0
XP/2K x64:
RtHDM.X.sys : 5.10.0.5692
RtkUpd64.exe : 2.7.1.0

```

Driver Setup Program : 2.64

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111

Readme.txt

Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.06

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WnXP/Wn2000/Wn2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Driver :
 1. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :

| | |
|---------------|---------------|
| RTKHDA64.sys | : 5.10.0.5713 |
| RTKHDAUD.sys | : 5.10.0.5713 |
| Alcmtr.exe | : 1.6.0.3 |
| AlcWzrd.exe | : 1.1.0.37 |
| McCal.exe | : 1.1.2.0 |
| RTHDCPL.exe | : 2.2.4.6 |
| RTLCPAPI.exe | : 1.0.1.66 |
| RtlUpd64.exe | : 2.7.1.1 |
| RtlUpd.exe | : 2.7.1.1 |
| SkyTel.exe | : 2.0.2.0 |
| SoundMan.exe | : 1.0.0.32 |
| AMBFilt64.sys | : 5.10.0.4240 |
| AMBFilt.sys | : 5.10.0.4240 |
| Mnfil64.sys | : 5.10.0.4115 |
| Mnfil.sys | : 5.10.0.4112 |
| ALSndMgr.cpl | : 1.0.0.11 |
| RTSndMgr.cpl | : 1.0.1.0 |
| RTCOMDLL.dll | : 1.0.0.97 |
| RtlCPAPI.dll | : 1.0.1.9 |

Vista driver : -----

Vista driver for x86

| | |
|---------------------|----------------|
| RTKVHDA.sys | : 6.0.1.5713 |
| AERTSrv.exe | : 1.0.32.7 |
| RtHDVCpl.exe | : 1.0.0.248 |
| RtkAudioService.exe | : 1.0.0.16 |
| RtlUpd.exe | : 2.7.1.1 |
| SkyTel.exe | : 2.0.2.1 |
| vncutil.exe | : 1.0.0.22 |
| RTSndMgr.cpl | : 1.0.0.10 |
| AERTACap.dll | : 1.0.32.7 |
| AERTARen.dll | : 1.0.32.3 |
| CTAP032.dll | : 1.0.0.530 |
| ctppld.dll | : 1.0.0.530 |
| DaisyWrp.dll | : 1.0.0.70 |
| FMAP0.dll | : 40.59.0.0 |
| MaxxAudioAPO.dll | : 1.2.2.0 |
| MaxxAudioAPO20.dll | : 2.0.13.0 |
| MaxxAudioEQ.dll | : 5.9.7.0 |
| ppchain.dll | : 1.0.0.70 |
| RTCOMDLL.dll | : 2.0.0.100 |
| RtkAPO.dll | : 11.0.6000.77 |
| RtkApoApi.dll | : 1.0.0.6 |
| RtkCoInst.dll | : 1.0.3.6 |
| RtkPgExt.dll | : 6.0.6000.61 |
| RtlCPAPI.dll | : 1.0.1.9 |
| slcshp32.dll | : 1.0.3.0 |
| slgeq32.dll | : 1.0.1.0 |
| slh36032.dll | : 1.0.2.0 |
| slinit32.dll | : 1.1.1.0 |
| sltshd32.dll | : 1.1.0.0 |
| sluapo32.dll | : 1.2.6.0 |
| SRSHP360.dll | : 1.1.0.0 |
| SRSTSHD.dll | : 1.1.4.0 |
| SRSTSXT.dll | : 3.2.0.0 |
| SRSWOW.dll | : 1.1.3.0 |
| WavesLib.dll | : 5.9.7.0 |

Readme.txt

Vista driver for x64

| | |
|---------------------|----------------|
| RTKVHD64.sys | : 6.0.1.5713 |
| AERTSr64.exe | : 1.0.64.7 |
| RAVCpl64.exe | : 1.0.0.248 |
| RtkAudioService.exe | : 1.0.0.16 |
| RtlUpd64.exe | : 2.7.1.1 |
| SkyTel.exe | : 2.0.2.1 |
| vncutil.exe | : 1.0.0.22 |
| GWfilt64.sys | : 6.10.0.3 |
| RTSnMg64.cpl | : 1.0.0.10 |
| AERTAC64.dll | : 1.0.64.7 |
| AERTAR64.dll | : 1.0.64.3 |
| CTAP032.dll | : 1.0.0.530 |
| CTAP064.dll | : 1.0.0.530 |
| ctppld.dll | : 1.0.0.530 |
| DaisyWrp.dll | : 1.0.0.70 |
| FMAP064.dll | : 40.59.0.0 |
| MaxxAudioAPO20.dll | : 2.0.12.0 |
| ppchain.dll | : 1.0.0.70 |
| RCoInst64.dll | : 1.0.3.6 |
| RtCOM64.dll | : 2.0.0.100 |
| RTCOMDLL.dll | : 2.0.0.100 |
| RtkApi64.dll | : 1.0.0.6 |
| RtkAPO64.dll | : 11.0.6000.77 |
| RtlCPAPI.dll | : 1.0.1.9 |
| RtPgEx64.dll | : 6.0.6000.61 |
| slcshp64.dll | : 1.0.3.0 |
| slgeq64.dll | : 1.0.1.0 |
| slh36064.dll | : 1.0.2.0 |
| slInit64.dll | : 1.1.1.0 |
| sltshd64.dll | : 1.1.0.0 |
| sluapo64.dll | : 1.2.6.0 |
| SRSHP64.dll | : 1.1.0.0 |
| SRSTSH64.dll | : 1.1.4.0 |
| SRSTSX64.dll | : 3.2.0.0 |
| SRSWOW64.dll | : 1.1.3.0 |

HDMI Driver : -----

| | |
|--------------|----------------|
| Vista x86: | |
| RtHDMV.sys | : 6.0.1.5692 |
| RtkUpd.exe | : 2.7.1.0 |
| RHCoInst.dll | : 1.0.3.2 |
| RHDMExt.dll | : 6.0.6000.54 |
| RtkHDM.dll | : 11.0.6000.72 |

| | |
|----------------|----------------|
| Vista x64: | |
| RtHDMVX.sys | : 6.0.1.5692 |
| RtkUpd64.exe | : 2.7.1.0 |
| RHCoInst64.dll | : 1.0.3.2 |
| RHDMEx64.dll | : 6.0.6000.54 |
| RtkHDM64.dll | : 11.0.6000.72 |

| | |
|------------|---------------|
| XP/2K x86: | |
| RtHDM.sys | : 5.10.0.5692 |
| RtkUpd.exe | : 2.7.1.0 |

| | |
|--------------|---------------|
| XP/2K x64: | |
| RtHDMX.sys | : 5.10.0.5692 |
| RtkUpd64.exe | : 2.7.1.0 |

Driver Setup Program : 2.64

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111
 Package file version (kb888111.exe) : 6.1.22.0
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.05

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix

Readme.txt

- 1.) Driver :
 1. Customizations.
 2. Meet Microsoft OEM Ready program requirements.
- 2.) Package :
 1. Meet Microsoft OEM Ready program requirements.

Windows 2000/XP : -----

Windows 2000/XP :

| | |
|--------------|---------------|
| RTKHDA64.sys | : 5.10.0.5708 |
| RTKHDAUD.sys | : 5.10.0.5708 |
| MicCal.exe | : 1.1.1.9 |
| RTHDCPL.exe | : 2.2.4.5 |
| RTLCPPL.exe | : 1.0.1.66 |
| RtlUpd64.exe | : 2.7.1.1 |
| RtlUpd.exe | : 2.7.1.1 |
| SkyTel.exe | : 2.0.2.0 |
| SoundMan.exe | : 1.0.0.32 |
| Alcmtr.exe | : 1.6.0.3 |
| AlcWzrd.exe | : 1.1.0.37 |
| Mnfil64.sys | : 5.10.0.4115 |
| Mnfil.sys | : 5.10.0.4112 |
| AMBFil64.sys | : 5.10.0.4240 |
| AMBFil.sys | : 5.10.0.4240 |
| RTSndMgr.cpl | : 1.0.1.0 |
| ALSndMgr.cpl | : 1.0.0.11 |
| RTCOMDLL.dll | : 1.0.0.97 |
| RtlCPAPI.dll | : 1.0.1.9 |

Vista driver : -----

Vista driver for x86

| | |
|---------------------|----------------|
| RTKVHDA.sys | : 6.0.1.5708 |
| AERTSrv.exe | : 1.0.32.7 |
| RtHDVCpl.exe | : 1.0.0.246 |
| RtkAudioService.exe | : 1.0.0.16 |
| RtlUpd.exe | : 2.7.1.1 |
| SkyTel.exe | : 2.0.2.1 |
| vncutil.exe | : 1.0.0.21 |
| RTSndMgr.cpl | : 1.0.0.10 |
| AERTACap.dll | : 1.0.32.7 |
| AERTARen.dll | : 1.0.32.3 |
| CTAP032.dll | : 1.0.0.530 |
| ctppld.dll | : 1.0.0.530 |
| DaisyWrp.dll | : 1.0.0.70 |
| FMAP0.dll | : 40.59.0.0 |
| MaxxAudioAPO.dll | : 1.2.2.0 |
| MaxxAudioAPO20.dll | : 2.0.13.0 |
| MaxxAudioEQ.dll | : 5.9.7.0 |
| ppchain.dll | : 1.0.0.70 |
| RTCOMDLL.dll | : 2.0.0.100 |
| RtkAPO.dll | : 11.0.6000.76 |
| RtkApoApi.dll | : 1.0.0.4 |
| RtkCoInst.dll | : 1.0.3.5 |
| RtkPgExt.dll | : 6.0.6000.60 |
| RtlCPAPI.dll | : 1.0.1.9 |
| slcshp32.dll | : 1.0.3.0 |
| slgeq32.dll | : 1.0.1.0 |
| slh36032.dll | : 1.0.2.0 |
| slinit32.dll | : 1.1.1.0 |
| sltshd32.dll | : 1.1.0.0 |
| sluapo32.dll | : 1.2.6.0 |
| SRSHP360.dll | : 1.1.0.0 |
| SRSTSHD.dll | : 1.1.4.0 |
| SRSTSXT.dll | : 3.2.0.0 |
| SRSWOW.dll | : 1.1.3.0 |
| WavesLib.dll | : 5.9.7.0 |

Vista driver for x64

| | |
|---------------------|--------------|
| RTKVHD64.sys | : 6.0.1.5708 |
| AERTSr64.exe | : 1.0.64.7 |
| RAVCpl64.exe | : 1.0.0.246 |
| RtkAudioService.exe | : 1.0.0.16 |
| RtlUpd64.exe | : 2.7.1.1 |
| SkyTel.exe | : 2.0.2.1 |
| vncutil.exe | : 1.0.0.21 |
| GWfil64.sys | : 6.10.0.3 |
| RTSnMg64.cpl | : 1.0.0.10 |

Readme.txt

AERTAC64.dll : 1.0.64.7
 AERTAR64.dll : 1.0.64.3
 CTAP032.dll : 1.0.0.530
 CTAP064.dll : 1.0.0.530
 ctpld.dll : 1.0.0.530
 DaisyWrp.dll : 1.0.0.70
 FMAP064.dll : 40.59.0.0
 MaxxAudioAPO20.dll : 2.0.12.0
 ppchain.dll : 1.0.0.70
 RCoInst64.dll : 1.0.3.5
 RtCOMB4.dll : 2.0.0.100
 RTCOMDLL.dll : 2.0.0.100
 RtkApi64.dll : 1.0.0.4
 RtkAPO64.dll : 11.0.6000.76
 RtLCPAPI.dll : 1.0.1.9
 RtPgEx64.dll : 6.0.6000.60
 slcshp64.dll : 1.0.3.0
 slgeq64.dll : 1.0.1.0
 slh36064.dll : 1.0.2.0
 slInit64.dll : 1.1.1.0
 sltshd64.dll : 1.1.0.0
 sluapo64.dll : 1.2.6.0
 SRSHP64.dll : 1.1.0.0
 SRSTSH64.dll : 1.1.4.0
 SRSTSX64.dll : 3.2.0.0
 SRSWOW64.dll : 1.1.3.0

HDMI Driver : -----

Vista x86:
 RtHDMV.sys : 6.0.1.5692
 RtkUpd.exe : 2.7.1.0
 RHCoInst.dll : 1.0.3.2
 RHDMExt.dll : 6.0.6000.54
 RtkHDM.dll : 11.0.6000.72

Vista x64:
 RtHDMVX.sys : 6.0.1.5692
 RtkUpd64.exe : 2.7.1.0
 RHCoInst64.dll : 1.0.3.2
 RHDMEx64.dll : 6.0.6000.54
 RtkHDM64.dll : 11.0.6000.72

XP/2K x86:
 RtHDM.sys : 5.10.0.5692
 RtkUpd.exe : 2.7.1.0
 XP/2K x64:
 RtHDMX.sys : 5.10.0.5692
 RtkUpd64.exe : 2.7.1.0

Driver Setup Program : 2.64

Windows 2000/XP Operate on :
 Microsoft High Definition Audio Driver Package - KB888111
 Package file version (kb888111.exe) : 6.1.22.0
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.04

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

2. Support ALC887.

Windows 2000/XP : -----

Windows 2000/XP :
 RTKHDA64.sys : 5.10.0.5700
 RTKHDAUD.sys : 5.10.0.5700
 Alcmtr.exe : 1.6.0.3

Readme.txt

| | |
|----------------------|----------------|
| AlcWzrd.exe | : 1.1.0.37 |
| Mccal.exe | : 1.1.1.8 |
| RTHDCPL.exe | : 2.2.4.0 |
| RTLCPAPI.exe | : 1.0.1.66 |
| RtlUpd64.exe | : 2.7.1.0 |
| RtlUpd.exe | : 2.7.1.0 |
| SkyTel.exe | : 2.0.2.0 |
| SoundMan.exe | : 1.0.0.32 |
| AMBFilt64.sys | : 5.10.0.4240 |
| AMBFilt.sys | : 5.10.0.4240 |
| Mnfil64.sys | : 5.10.0.4115 |
| Mnfil.sys | : 5.10.0.4112 |
| ALSndMgr.cpl | : 1.0.0.11 |
| RTSndMgr.cpl | : 1.0.1.0 |
| RTCOMDLL.dll | : 1.0.0.97 |
| RtlCPAPI.dll | : 1.0.1.9 |
| ----- | |
| Vista driver : | |
| Vista driver for x86 | |
| RTKVHDA.sys | : 6.0.1.5700 |
| AERTSrv.exe | : 1.0.32.7 |
| RtHDVCpl.exe | : 1.0.0.240 |
| RtkAudioService.exe | : 1.0.0.16 |
| RtlUpd.exe | : 2.7.1.0 |
| SkyTel.exe | : 2.0.2.1 |
| vncutil.exe | : 1.0.0.21 |
| RTSndMgr.cpl | : 1.0.0.9 |
| AERTACap.dll | : 1.0.32.7 |
| AERTARen.dll | : 1.0.32.3 |
| CTAP032.dll | : 1.0.0.520 |
| ctpld.dll | : 1.0.0.510 |
| DaisyWrp.dll | : 1.0.0.70 |
| FMAP0.dll | : 40.59.0.0 |
| MaxxAudioAP0.dll | : 1.2.2.0 |
| MaxxAudioAP020.dll | : 2.0.13.0 |
| MaxxAudioEQ.dll | : 5.9.7.0 |
| ppchain.dll | : 1.0.0.70 |
| RTCOMDLL.dll | : 2.0.0.100 |
| RtkAP0.dll | : 11.0.6000.74 |
| RtkApoApi.dll | : 1.0.0.4 |
| RtkCoInst.dll | : 1.0.3.2 |
| RtkPgExt.dll | : 6.0.6000.56 |
| RtlCPAPI.dll | : 1.0.1.9 |
| SRSHP360.dll | : 1.1.0.0 |
| SRSTSHD.dll | : 1.1.4.0 |
| SRSTSXT.dll | : 3.2.0.0 |
| SRSWOW.dll | : 1.1.3.0 |
| WavesLib.dll | : 5.9.7.0 |
| Vista driver for x64 | |
| GWfilt64.sys | : 6.10.0.3 |
| RTKVHD64.sys | : 6.0.1.5700 |
| AERTSr64.exe | : 1.0.64.7 |
| RAVCpl64.exe | : 1.0.0.240 |
| RtkAudioService.exe | : 1.0.0.16 |
| RtlUpd64.exe | : 2.7.1.0 |
| SkyTel.exe | : 2.0.2.1 |
| vncutil.exe | : 1.0.0.21 |
| RTSnMg64.cpl | : 1.0.0.9 |
| AERTAC64.dll | : 1.0.64.7 |
| AERTAR64.dll | : 1.0.64.3 |
| CTAP032.dll | : 1.0.0.520 |
| CTAP064.dll | : 1.0.0.520 |
| ctpld.dll | : 1.0.0.510 |
| DaisyWrp.dll | : 1.0.0.70 |
| FMAP064.dll | : 40.59.0.0 |
| MaxxAudioAP020.dll | : 2.0.12.0 |
| ppchain.dll | : 1.0.0.70 |
| RCoInst64.dll | : 1.0.3.2 |
| RtCOMB4.dll | : 2.0.0.100 |
| RTCOMDLL.dll | : 2.0.0.100 |
| RtkApi64.dll | : 1.0.0.4 |
| RtkAP064.dll | : 11.0.6000.74 |
| RtlCPAPI.dll | : 1.0.1.9 |
| RtPgEx64.dll | : 6.0.6000.56 |
| SRSHP64.dll | : 1.1.0.0 |
| SRSTSH64.dll | : 1.1.4.0 |

Readme.txt

SRSTSX64.dll : 3.2.0.0
 SRSWOW64.dll : 1.1.3.0
 HDM Driver : -----
 Vista x86:
 RtHDMV.sys : 6.0.1.5692
 RtkUpd.exe : 2.7.1.0
 RHCoInst.dll : 1.0.3.2
 RHDMExt.dll : 6.0.6000.54
 RtkHDM.dll : 11.0.6000.72

 Vista x64:
 RtHDMVX.sys : 6.0.1.5692
 RtkUpd64.exe : 2.7.1.0
 RHCoInst64.dll : 1.0.3.2
 RHDMEx64.dll : 6.0.6000.54
 RtkHDM64.dll : 11.0.6000.72

 XP/2K x86:
 RtHDM.sys : 5.10.0.5692
 RtkUpd.exe : 2.7.1.0
 XP/2K x64:
 RtHDMX.sys : 5.10.0.5692
 RtkUpd64.exe : 2.7.1.0

 Driver Setup Program : 2.62

Windows 2000/XP Operate on :
 Microsoft High Definition Audio Driver Package - KB888111
 Package file version (kb888111.exe) : 6.1.22.0
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.03

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Win2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Driver :
 1. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :
 RTKHDA64.sys : 5.10.0.5694
 RTKHDAUD.sys : 5.10.0.5694
 Alcmtr.exe : 1.6.0.3
 AlcWzrd.exe : 1.1.0.37
 McCal.exe : 1.1.1.8
 RTHDCPL.exe : 2.2.3.8
 RTLCPPL.exe : 1.0.1.66
 RtlUpd64.exe : 2.7.1.0
 RtlUpd.exe : 2.7.1.0
 SkyTel.exe : 2.0.2.0
 SoundMn.exe : 1.0.0.32
 ALSndMgr.cpl : 1.0.0.11
 RTSndMgr.cpl : 1.0.1.0
 RTCOMDL.dll : 1.0.0.97
 RtlCPAPI.dll : 1.0.1.9

Vista driver : -----

Vista driver for x86
 RTKVHDA.sys : 6.0.1.5694
 AERTSrv.exe : 1.0.32.7
 RtHDVCpl.exe : 1.0.0.235
 RtkAudioService.exe : 1.0.0.16
 RtlUpd.exe : 2.7.1.0
 SkyTel.exe : 2.0.2.1
 vncutil.exe : 1.0.0.21
 RTSndMgr.cpl : 1.0.0.9
 AERTACap.dll : 1.0.32.7
 AERTARen.dll : 1.0.32.3
 FMAPO.dll : 40.59.0.0

Readme.txt

```

MaxxAudioAPO.dll : 1.2.2.0
MaxxAudioAPO20.dll : 2.0.13.0
MaxxAudioEQ.dll : 5.9.7.0
RTCOMDLL.dll : 2.0.0.99
RtkAPO.dll : 11.0.6000.72
RtkApoApi.dll : 1.0.0.4
RtkCoInst.dll : 1.0.3.2
RtkPgExt.dll : 6.0.6000.54
RtlCPAPI.dll : 1.0.1.9
SRSH360.dll : 1.1.0.0
SRSTSHD.dll : 1.1.4.0
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.1.3.0
WavesLib.dll : 5.9.7.0
Vista driver for x64
RTKVHD64.sys : 6.0.1.5694
AERTSr64.exe : 1.0.64.7
RAVCpl64.exe : 1.0.0.235
RtkAudioService.exe : 1.0.0.16
RtlUpd64.exe : 2.7.1.0
SkyTel.exe : 2.0.2.1
vncutil.exe : 1.0.0.21
RTSnMg64.cpl : 1.0.0.9
AERTAC64.dll : 1.0.64.7
AERTAR64.dll : 1.0.64.3
FMAP064.dll : 40.59.0.0
MaxxAudioAPO20.dll : 2.0.12.0
RCoInst64.dll : 1.0.3.2
RtCOM64.dll : 2.0.0.99
RTCOMDLL.dll : 2.0.0.99
RtkApi64.dll : 1.0.0.4
RtkAPO64.dll : 11.0.6000.72
RtlCPAPI.dll : 1.0.1.9
RtPgEx64.dll : 6.0.6000.54
SRSH64.dll : 1.1.0.0
SRSTSH64.dll : 1.1.4.0
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
HDMI Driver : -----
Vista x86:
RtHDMV.sys : 6.0.1.5692
RtkUpd.exe : 2.7.1.0
RHCoInst.dll : 1.0.3.2
RHDMExt.dll : 6.0.6000.54
RtkHDM.dll : 11.0.6000.72

Vista x64:
RtHDMVX.sys : 6.0.1.5692
RtkUpd64.exe : 2.7.1.0
RHCoInst64.dll : 1.0.3.2
RHDMEx64.dll : 6.0.6000.54
RtkHDM64.dll : 11.0.6000.72

XP/2K x86:
RtHDM.sys : 5.10.0.5692
RtkUpd.exe : 2.7.1.0
XP/2K x64:
RtHDMX.sys : 5.10.0.5692
RtkUpd64.exe : 2.7.1.0

Driver Setup Program : 2.62

```

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111
 Package file version (kb888111.exe) : 6.1.22.0
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.02

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64

Readme.txt

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.
2. Update ForteMedia microphone effect library.

Windows 2000/XP : -----

Windows 2000/XP :

| | |
|--------------|---------------|
| RTKHDA64.sys | : 5.10.0.5683 |
| RTKHDAUD.sys | : 5.10.0.5683 |
| Alcmtr.exe | : 1.6.0.3 |
| AlcWzrd.exe | : 1.1.0.37 |
| McCal.exe | : 1.1.1.8 |
| RTHDCPL.exe | : 2.2.3.3 |
| RTLCPPL.exe | : 1.0.1.66 |
| RtlUpd64.exe | : 2.7.1.0 |
| RtlUpd.exe | : 2.7.1.0 |
| SkyTel.exe | : 2.0.2.0 |
| SoundMan.exe | : 1.0.0.31 |
| ALSndMgr.cpl | : 1.0.0.11 |
| RTSndMgr.cpl | : 1.0.1.0 |
| RTCOMDLL.dll | : 1.0.0.97 |
| RtlCPAPI.dll | : 1.0.1.9 |

Vista driver : -----

Vista driver for x86

| | |
|---------------------|----------------|
| RTKVHDA.sys | : 6.0.1.5683 |
| AERTSrv.exe | : 1.0.32.7 |
| RtHDVCpl.exe | : 1.0.0.227 |
| RtkAudioService.exe | : 1.0.0.16 |
| RtlUpd.exe | : 2.7.1.0 |
| SkyTel.exe | : 2.0.2.1 |
| vncutil.exe | : 1.0.0.19 |
| RTSndMgr.cpl | : 1.0.0.8 |
| AERTACap.dll | : 1.0.32.7 |
| AERTARen.dll | : 1.0.32.3 |
| FMAP0.dll | : 40.59.0.0 |
| MaxxAudioAPO.dll | : 1.2.2.0 |
| MaxxAudioAPO20.dll | : 2.0.13.0 |
| MaxxAudioEQ.dll | : 5.9.7.0 |
| RTCOMDLL.dll | : 2.0.0.99 |
| RtkAPO.dll | : 11.0.6000.71 |
| RtkApoApi.dll | : 1.0.0.4 |
| RtkCoInst.dll | : 1.0.3.2 |
| RtkPgExt.dll | : 6.0.6000.53 |
| RtlCPAPI.dll | : 1.0.1.9 |
| SRSHP360.dll | : 1.1.0.0 |
| SRSTSHD.dll | : 1.1.4.0 |
| SRSTSXT.dll | : 3.2.0.0 |
| SRSWOW.dll | : 1.1.3.0 |
| WavesLib.dll | : 5.9.7.0 |

Vista driver for x64

| | |
|---------------------|----------------|
| RTKVHD64.sys | : 6.0.1.5683 |
| AERTSr64.exe | : 1.0.64.7 |
| RAVCpl64.exe | : 1.0.0.227 |
| RtkAudioService.exe | : 1.0.0.16 |
| RtlUpd64.exe | : 2.7.1.0 |
| SkyTel.exe | : 2.0.2.1 |
| vncutil.exe | : 1.0.0.19 |
| RTSnMg64.cpl | : 1.0.0.8 |
| AERTAC64.dll | : 1.0.64.7 |
| AERTAR64.dll | : 1.0.64.3 |
| FMAP064.dll | : 40.59.0.0 |
| MaxxAudioAPO20.dll | : 2.0.12.0 |
| RCoInst64.dll | : 1.0.3.2 |
| RtCOMB4.dll | : 2.0.0.99 |
| RTCOMDLL.dll | : 2.0.0.99 |
| RtkApi64.dll | : 1.0.0.4 |
| RtkAPO64.dll | : 11.0.6000.71 |
| RtlCPAPI.dll | : 1.0.1.9 |
| RtPgEx64.dll | : 6.0.6000.53 |
| SRSHP64.dll | : 1.1.0.0 |
| SRSTSH64.dll | : 1.1.4.0 |
| SRSTSX64.dll | : 3.2.0.0 |
| SRSWOW64.dll | : 1.1.3.0 |

Readme.txt

```

HDM Driver : -----
Vista x86:
RtHDMV.sys           : 6.0.1.5668
RtkUpd.exe           : 2.7.0.9
RHCoInst.dll         : 1.0.2.9
RHDMExt.dll          : 6.0.6000.52
RtkHDM.dll           : 11.0.6000.69

Vista x64:
RtHDMVX.sys          : 6.0.1.5668
RtkUpd64.exe         : 2.7.0.9
RHCoInst64.dll       : 1.0.2.9
RHDMEx64.dll         : 6.0.6000.52
RtkHDM64.dll         : 11.0.6000.69

XP/2K x86:
RtHDM.sys            : 5.10.0.5668
RtkUpd.exe           : 2.7.0.9
XP/2K x64:
RtHDMX.sys           : 5.10.0.5668
RtkUpd64.exe         : 2.7.0.9

Driver Setup Program : 2.62
  
```

Windows 2000/XP Operate on :
 Microsoft High Definition Audio Driver Package - KB888111
 Package file version (kb888111.exe) : 6.1.22.0
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.01

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Win2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Driver :
 1. Customizations.
 2. Support ALC273.
 - 2.) Package :
 1. Change warning message for upgrade driver .
 2. ChCfg.exe add version and manifest embedded feature .
 3. Add Manifest to Rtlupd.exe and HideWin.exe .
 4. The SetCDFmt function was included by RtlExUpd.dll Ver.1.0.1.1

Windows 2000/XP : -----

```

Windows 2000/XP :
RTKHDA64.sys         : 5.10.0.5680
RTKHDAUD.sys         : 5.10.0.5680
Alcmtr.exe           : 1.6.0.3
AlcWzrd.exe          : 1.1.0.37
McCal.exe            : 1.1.1.8
RTHDCPL.exe          : 2.2.3.3
RTLCPPL.exe          : 1.0.1.66
RtlUpd64.exe         : 2.7.0.9
RtlUpd.exe           : 2.7.0.9
SkyTel.exe           : 2.0.2.0
SoundMn.exe          : 1.0.0.31
ALSndMgr.cpl         : 1.0.0.11
RTSndMgr.cpl         : 1.0.1.0
RTCOMDLL.dll         : 1.0.0.97
RtlCPAPI.dll         : 1.0.1.9
  
```

Vista driver : -----

```

Vista driver for x86
RTKVHDA.sys          : 6.0.1.5680
AERTSrv.exe          : 1.0.32.7
RtHDVCpl.exe         : 1.0.0.224
RtkAudioService.exe : 1.0.0.16
RtlUpd.exe           : 2.7.0.9
SkyTel.exe           : 2.0.2.1
  
```

Readme.txt

```

vncutil.exe : 1.0.0.19
RTSnMgr.cpl : 1.0.0.8
AERTACap.dll : 1.0.32.7
AERTARen.dll : 1.0.32.3
FMAP0.dll : 40.59.0.0
MaxxAudioAPO.dll : 1.2.2.0
MaxxAudioAPO20.dll : 2.0.13.0
MaxxAudioEQ.dll : 5.9.7.0
RTCOMDLL.dll : 2.0.0.99
RtkAPO.dll : 11.0.6000.71
RtkApoApi.dll : 1.0.0.4
RtkCoInst.dll : 1.0.3.2
RtkPgExt.dll : 6.0.6000.53
RtlCPAPI.dll : 1.0.1.9
SRSH360.dll : 1.1.0.0
SRSTSHD.dll : 1.1.4.0
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.1.3.0
WavesLib.dll : 5.9.7.0
Vista driver for x64
RTKVHD64.sys : 6.0.1.5680
AERTSr64.exe : 1.0.64.7
RAVCpl64.exe : 1.0.0.224
RtkAudioService.exe : 1.0.0.16
RtlUpd64.exe : 2.7.0.9
SkyTel.exe : 2.0.2.1
vncutil.exe : 1.0.0.19
RTSnMgr64.cpl : 1.0.0.8
AERTAC64.dll : 1.0.64.7
AERTAR64.dll : 1.0.64.3
FMAP064.dll : 40.59.0.0
MaxxAudioAPO20.dll : 2.0.12.0
RCoInst64.dll : 1.0.3.2
RtCOMB4.dll : 2.0.0.99
RTCOMDLL.dll : 2.0.0.99
RtkApi64.dll : 1.0.0.4
RtkAPO64.dll : 11.0.6000.71
RtlCPAPI.dll : 1.0.1.9
RtPgEx64.dll : 6.0.6000.53
SRSH64.dll : 1.1.0.0
SRSTSH64.dll : 1.1.4.0
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
HDM Driver : -----
Vista x86:
RtHDM.V.sys : 6.0.1.5668
RtkUpd.exe : 2.7.0.9
RHCoInst.dll : 1.0.2.9
RHDMExt.dll : 6.0.6000.52
RtkHDM.dll : 11.0.6000.69

Vista x64:
RtHDM.VX.sys : 6.0.1.5668
RtkUpd64.exe : 2.7.0.9
RHCoInst64.dll : 1.0.2.9
RHDMEx64.dll : 6.0.6000.52
RtkHDM64.dll : 11.0.6000.69

XP/2K x86:
RtHDM.sys : 5.10.0.5668
RtkUpd.exe : 2.7.0.9
XP/2K x64:
RtHDM.X.sys : 5.10.0.5668
RtkUpd64.exe : 2.7.0.9

Driver Setup Program : 2.61

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

```

//=====

Driver Package R2.00
Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WnXP/Wn2000/Wn2003 .
1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663,

Readme.txt

ALC260, ALC262, ALC267, ALC268, ALC269, ALC272

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272

3. HDM Device WHQL Support: ATI HDM Devices

4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :

| | |
|--------------|---------------|
| RTKHDA64.sys | : 5.10.0.5672 |
| RTKHDAUD.sys | : 5.10.0.5672 |
| Alcmtr.exe | : 1.6.0.3 |
| AlcWzrd.exe | : 1.1.0.37 |
| McCal.exe | : 1.1.1.8 |
| RTHDCPL.exe | : 2.2.3.1 |
| RTLCPAPI.dll | : 1.0.1.66 |
| RtlUpd64.exe | : 2.7.0.9 |
| RtlUpd.exe | : 2.7.0.9 |
| SkyTel.exe | : 2.0.2.0 |
| SoundMan.exe | : 1.0.0.31 |
| ALSndMgr.cpl | : 1.0.0.11 |
| RTSndMgr.cpl | : 1.0.1.0 |
| RTCOMDLL.dll | : 1.0.0.97 |
| RtlCPAPI.dll | : 1.0.1.9 |

Vista driver : -----

Vista driver for x86

| | |
|---------------------|----------------|
| RTKVHDA.sys | : 6.0.1.5672 |
| AERTSrv.exe | : 1.0.32.7 |
| RtHDVCpl.exe | : 1.0.0.219 |
| RtkAudioService.exe | : 1.0.0.16 |
| RtlUpd.exe | : 2.7.0.9 |
| SkyTel.exe | : 2.0.2.1 |
| vncutil.exe | : 1.0.0.19 |
| RTSndMgr.cpl | : 1.0.0.8 |
| AERTACap.dll | : 1.0.32.7 |
| AERTARen.dll | : 1.0.32.3 |
| FMAPO.dll | : 40.59.0.0 |
| MaxxAudioAPO.dll | : 1.2.2.0 |
| MaxxAudioAPO20.dll | : 2.0.13.0 |
| MaxxAudioEQ.dll | : 5.9.7.0 |
| RTCOMDLL.dll | : 2.0.0.98 |
| RtkAPO.dll | : 11.0.6000.70 |
| RtkApoApi.dll | : 1.0.0.4 |
| RtkCoInst.dll | : 1.0.3.1 |
| RtkPgExt.dll | : 6.0.6000.53 |
| RtlCPAPI.dll | : 1.0.1.9 |
| SRSH360.dll | : 1.1.0.0 |
| SRSTSHD.dll | : 1.1.4.0 |
| SRSTSXT.dll | : 3.2.0.0 |
| SRSWOW.dll | : 1.1.3.0 |
| WavesLib.dll | : 5.9.7.0 |

Vista driver for x64

| | |
|---------------------|----------------|
| RTKVHD64.sys | : 6.0.1.5672 |
| AERTSr64.exe | : 1.0.64.7 |
| RAVCpl64.exe | : 1.0.0.219 |
| RtkAudioService.exe | : 1.0.0.16 |
| RtlUpd64.exe | : 2.7.0.9 |
| SkyTel.exe | : 2.0.2.1 |
| vncutil.exe | : 1.0.0.19 |
| RTSnMg64.cpl | : 1.0.0.8 |
| AERTAC64.dll | : 1.0.64.7 |
| AERTAR64.dll | : 1.0.64.3 |
| FMAPO64.dll | : 40.59.0.0 |
| MaxxAudioAPO20.dll | : 2.0.12.0 |
| RCoInst64.dll | : 1.0.3.1 |
| RtCOMB4.dll | : 2.0.0.98 |
| RTCOMDLL.dll | : 2.0.0.98 |
| RtkApi64.dll | : 1.0.0.4 |
| RtkAPO64.dll | : 11.0.6000.70 |
| RtlCPAPI.dll | : 1.0.1.9 |
| RtPgEx64.dll | : 6.0.6000.53 |

Readme.txt

SRSHP64.dll : 1.1.0.0
 SRSTSH64.dll : 1.1.4.0
 SRSTSX64.dll : 3.2.0.0
 SRSWOW64.dll : 1.1.3.0

HDM Driver : -----
 Vista x86:
 RtHDMV.sys : 6.0.1.5668
 RtkUpd.exe : 2.7.0.9
 RHCoInst.dll : 1.0.2.9
 RHDMExt.dll : 6.0.6000.52
 RtkHDM.dll : 11.0.6000.69

Vista x64:
 RtHDMVX.sys : 6.0.1.5668
 RtkUpd64.exe : 2.7.0.9
 RHCoInst64.dll : 1.0.2.9
 RHDMEx64.dll : 6.0.6000.52
 RtkHDM64.dll : 11.0.6000.69

XP/2K x86:
 RtHDM.sys : 5.10.0.5668
 RtkUpd.exe : 2.7.0.9

XP/2K x64:
 RtHDMX.sys : 5.10.0.5668
 RtkUpd64.exe : 2.7.0.9

Driver Setup Program : 2.60

Windows 2000/XP Operate on :
 Microsoft High Definition Audio Driver Package - KB888111
 Package file version (kb888111.exe) : 6.1.22.0
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.99

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Driver :
 1. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :
 RTKHDA64.sys : 5.10.0.5667
 RTKHDAUD.sys : 5.10.0.5667
 MicCal.exe : 1.1.1.8
 RTHDCPL.exe : 2.2.3.0
 RTLCPPL.exe : 1.0.1.66
 RtlUpd64.exe : 2.7.0.9
 RtlUpd.exe : 2.7.0.9
 SkyTel.exe : 2.0.2.0
 SoundMan.exe : 1.0.0.31
 Alcmtr.exe : 1.6.0.3
 AlcWzrd.exe : 1.1.0.37
 RTSndMgr.cpl : 1.0.1.0
 ALSndMgr.cpl : 1.0.0.11
 RTCOMDL.dll : 1.0.0.97
 RtlCPAPI.dll : 1.0.1.9

Vista driver : -----

Vista driver for x86
 RTKVHDA.sys : 6.0.1.5667
 AERTSrv.exe : 1.0.32.2
 RtHDVCpl.exe : 1.0.0.215
 RtkAudioService.exe : 1.0.0.16
 RtlUpd.exe : 2.7.0.9
 SkyTel.exe : 2.0.2.1
 vncutil.exe : 1.0.0.18
 RTSndMgr.cpl : 1.0.0.8
 AERTACap.dll : 1.0.32.7

Readme.txt

```

AERTARen.dll : 1.0.32.3
FMAP0.dll : 40.59.0.0
MaxxAudioAPO.dll : 1.2.2.0
MaxxAudioAPO20.dll : 2.0.13.0
MaxxAudioEQ.dll : 5.9.7.0
RTCOMDLL.dll : 2.0.0.98
RtkAPO.dll : 11.0.6000.69
RtkApoApi.dll : 1.0.0.4
RtkCoInst.dll : 1.0.3.1
RtkPgExt.dll : 6.0.6000.52
RtlCPAPI.dll : 1.0.1.9
SRSH360.dll : 1.1.0.0
SRSTSHD.dll : 1.1.4.0
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.1.3.0
WavesLib.dll : 5.9.7.0
Vista driver for x64
RTKVHD64.sys : 6.0.1.5667
AERTSr64.exe : 1.0.64.2
RAVCpl64.exe : 1.0.0.215
RtkAudioService.exe : 1.0.0.16
RtlUpd64.exe : 2.7.0.9
SkyTel.exe : 2.0.2.1
vncutil.exe : 1.0.0.18
RTSnMg64.cpl : 1.0.0.8
AERTAC64.dll : 1.0.64.7
AERTAR64.dll : 1.0.64.3
FMAP064.dll : 40.59.0.0
MaxxAudioAPO20.dll : 2.0.12.0
RCoInst64.dll : 1.0.3.1
RtCOM64.dll : 2.0.0.98
RTCOMDLL.dll : 2.0.0.98
RtkApi64.dll : 1.0.0.4
RtkAPO64.dll : 11.0.6000.69
RtlCPAPI.dll : 1.0.1.9
RtPgEx64.dll : 6.0.6000.52
SRSH64.dll : 1.1.0.0
SRSTSH64.dll : 1.1.4.0
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
-----
HDM Driver :
Vista x86:
RtHDMV.sys : 6.0.1.5645
RtkUpd.exe : 2.7.0.9
RHCoInst.dll : 1.0.2.9
RHDMExt.dll : 6.0.6000.50
RtkHDM.dll : 11.0.6000.67

Vista x64:
RtHDMVX.sys : 6.0.1.5645
RtkUpd64.exe : 2.7.0.9
RHCoInst64.dll : 1.0.2.9
RHDMEx64.dll : 6.0.6000.50
RtkHDM64.dll : 11.0.6000.67

XP/2K x86:
RtHDM.sys : 5.10.0.5645
RtkUpd.exe : 2.7.0.9
XP/2K x64:
RtHDMX.sys : 5.10.0.5645
RtkUpd64.exe : 2.7.0.9

Driver Setup Program : 2.60

```

Windows 2000/XP Operate on :

```

Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

```

//=====

Driver Package R1.98

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272

Readme.txt

3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Widnows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Driver :
 1. Customizations.
 2. Fix the potential risk that audio driver can't be installed completely under Vista.

Windows 2000/XP : -----

Windows 2000/XP :

| | |
|--------------|---------------|
| RTKHDA64.sys | : 5.10.0.5657 |
| RTKHDAUD.sys | : 5.10.0.5657 |
| Alcmttr.exe | : 1.6.0.3 |
| AlcWzrd.exe | : 1.1.0.37 |
| MicCal.exe | : 1.1.1.8 |
| RTHDCPL.exe | : 2.2.2.5 |
| RTLCPPL.exe | : 1.0.1.66 |
| RtlUpd64.exe | : 2.7.0.9 |
| RtlUpd.exe | : 2.7.0.9 |
| SkyTel.exe | : 2.0.2.0 |
| SoundMan.exe | : 1.0.0.31 |
| ALSndMgr.cpl | : 1.0.0.11 |
| RTSndMgr.cpl | : 1.0.1.0 |
| RTCOMDLL.dll | : 1.0.0.97 |
| RtlCPAPI.dll | : 1.0.1.9 |

Vista driver : -----

Vista driver for x86

| | |
|---------------------|----------------|
| RTKVHDA.sys | : 6.0.1.5657 |
| AERTSrv.exe | : 1.0.32.2 |
| RtHDVCpl.exe | : 1.0.0.208 |
| RtkAudioService.exe | : 1.0.0.16 |
| RtlUpd.exe | : 2.7.0.9 |
| SkyTel.exe | : 2.0.2.1 |
| vncutil.exe | : 1.0.0.14 |
| RTSndMgr.cpl | : 1.0.0.8 |
| AERTACap.dll | : 1.0.32.7 |
| AERTARen.dll | : 1.0.32.3 |
| FMAPO.dll | : 40.59.0.0 |
| MaxxAudioAPO.dll | : 1.2.2.0 |
| MaxxAudioAPO20.dll | : 2.0.13.0 |
| MaxxAudioEQ.dll | : 5.9.7.0 |
| RTCOMDLL.dll | : 2.0.0.98 |
| RtkAPO.dll | : 11.0.6000.69 |
| RtkApoApi.dll | : 1.0.0.4 |
| RtkCoInst.dll | : 1.0.2.10 |
| RtkPgExt.dll | : 6.0.6000.52 |
| RtlCPAPI.dll | : 1.0.1.9 |
| SRSH360.dll | : 1.1.0.0 |
| SRSTSHD.dll | : 1.1.4.0 |
| SRSTSXT.dll | : 3.2.0.0 |
| SRSWOW.dll | : 1.1.3.0 |
| WavesLib.dll | : 5.9.7.0 |

Vista driver for x64

| | |
|---------------------|----------------|
| RTKVHD64.sys | : 6.0.1.5657 |
| AERTSr64.exe | : 1.0.64.2 |
| RAVCpl64.exe | : 1.0.0.208 |
| RtkAudioService.exe | : 1.0.0.16 |
| RtlUpd64.exe | : 2.7.0.9 |
| SkyTel.exe | : 2.0.2.1 |
| vncutil.exe | : 1.0.0.14 |
| RTSnMg64.cpl | : 1.0.0.8 |
| AERTAC64.dll | : 1.0.64.7 |
| AERTAR64.dll | : 1.0.64.3 |
| FMAPO64.dll | : 40.59.0.0 |
| MaxxAudioAPO20.dll | : 2.0.12.0 |
| RCoInst64.dll | : 1.0.2.10 |
| RtCOMB4.dll | : 2.0.0.98 |
| RTCOMDLL.dll | : 2.0.0.98 |
| RtkApi64.dll | : 1.0.0.4 |
| RtkAPO64.dll | : 11.0.6000.69 |
| RtlCPAPI.dll | : 1.0.1.9 |
| RtPgEx64.dll | : 6.0.6000.52 |
| SRSHP64.dll | : 1.1.0.0 |
| SRSTSH64.dll | : 1.1.4.0 |

Readme.txt

SRSTSX64.dll : 3.2.0.0
 SRSWOW64.dll : 1.1.3.0
 HDM Driver : -----
 Vista x86:
 RtHDMV.sys : 6.0.1.5645
 RtkUpd.exe : 2.7.0.9
 RHCoInst.dll : 1.0.2.9
 RHDMExt.dll : 6.0.6000.50
 RtkHDM.dll : 11.0.6000.67

 Vista x64:
 RtHDMVX.sys : 6.0.1.5645
 RtkUpd64.exe : 2.7.0.9
 RHCoInst64.dll : 1.0.2.9
 RHDMEx64.dll : 6.0.6000.50
 RtkHDM64.dll : 11.0.6000.67

 XP/2K x86:
 RtHDM.sys : 5.10.0.5645
 RtkUpd.exe : 2.7.0.9
 XP/2K x64:
 RtHDMX.sys : 5.10.0.5645
 RtkUpd64.exe : 2.7.0.9

 Driver Setup Program : 2.60

Windows 2000/XP Operate on :
 Microsoft High Definition Audio Driver Package - KB888111
 Package file version (kb888111.exe) : 6.1.22.0
 Hdaudiobus.sys version : 5.10.00.5013

//=====

Driver Package R1.97

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Win2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Driver :
 1. Customizations.
 2. Add 24-bits recording feature.
 3. Fix EAX direct parameter issue under XP.
 4. Fix dummy noise issue under XP.

Windows 2000/XP : -----

Windows 2000/XP :
 RTKHDA64.sys : 5.10.0.5653
 RTKHDAUD.sys : 5.10.0.5653
 Alcmtr.exe : 1.6.0.3
 AlcWzrd.exe : 1.1.0.37
 MicCal.exe : 1.1.1.8
 RTHDCPL.exe : 2.2.2.4
 RTLCPL.exe : 1.0.1.66
 RtlUpd64.exe : 2.7.0.9
 RtlUpd.exe : 2.7.0.9
 SkyTel.exe : 2.0.2.0
 SoundMan.exe : 1.0.0.31
 ALSndMgr.cpl : 1.0.0.11
 RTSndMgr.cpl : 1.0.1.0
 RTCOMDLL.dll : 1.0.0.97
 RtlCPAPI.dll : 1.0.1.9

Vista driver : -----

Vista driver for x86
 RTKVHDA.sys : 6.0.1.5653
 AERTSrv.exe : 1.0.32.2
 RtHDVCpl.exe : 1.0.0.206
 RtkAudioService.exe : 1.0.0.16
 RtlUpd.exe : 2.7.0.9
 SkyTel.exe : 2.0.2.1
 vncutil.exe : 1.0.0.12
 RTSndMgr.cpl : 1.0.0.8

Readme.txt

```

AERTACap.dll : 1.0.32.7
AERTARen.dll : 1.0.32.3
FMAP0.dll : 40.59.0.0
MaxxAudioAPO.dll : 1.2.2.0
MaxxAudioAPO20.dll : 2.0.13.0
MaxxAudioEQ.dll : 5.9.7.0
RTCOMDLL.dll : 2.0.0.98
RtkAPO.dll : 11.0.6000.67
RtkApoApi.dll : 1.0.0.4
RtkCoInst.dll : 1.0.2.10
RtkPgExt.dll : 6.0.6000.50
RtlCPAPI.dll : 1.0.1.9
SRSH360.dll : 1.1.0.0
SRSTSHD.dll : 1.1.4.0
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.1.3.0
WavesLib.dll : 5.9.7.0
Vista driver for x64
RTKVHD64.sys : 6.0.1.5653
AERTSr64.exe : 1.0.64.2
RAVCpl64.exe : 1.0.0.206
RtkAudioService.exe : 1.0.0.16
RtlUpd64.exe : 2.7.0.9
SkyTel.exe : 2.0.2.1
vncutil.exe : 1.0.0.12
RTSnMg64.cpl : 1.0.0.8
AERTAC64.dll : 1.0.64.7
AERTAR64.dll : 1.0.64.3
FMAP064.dll : 40.59.0.0
MaxxAudioAPO20.dll : 2.0.12.0
RCoInst64.dll : 1.0.2.10
RtCOM64.dll : 2.0.0.98
RTCOMDLL.dll : 2.0.0.98
RtkApi64.dll : 1.0.0.4
RtkAPO64.dll : 11.0.6000.67
RtlCPAPI.dll : 1.0.1.9
RtPgEx64.dll : 6.0.6000.50
SRSHP64.dll : 1.1.0.0
SRSTSH64.dll : 1.1.4.0
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
HDMI Driver : -----
Vista x86:
RtHDMV.sys : 6.0.1.5645
RtkUpd.exe : 2.7.0.9
RHCoInst.dll : 1.0.2.9
RHDMExt.dll : 6.0.6000.50
RtkHDM.dll : 11.0.6000.67

Vista x64:
RtHDMVX.sys : 6.0.1.5645
RtkUpd64.exe : 2.7.0.9
RHCoInst64.dll : 1.0.2.9
RHDMEx64.dll : 6.0.6000.50
RtkHDM64.dll : 11.0.6000.67

XP/2K x86:
RtHDM.sys : 5.10.0.5645
RtkUpd.exe : 2.7.0.9
XP/2K x64:
RtHDMX.sys : 5.10.0.5645
RtkUpd64.exe : 2.7.0.9

Driver Setup Program : 2.60

```

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111
 Package file version (kb888111.exe) : 6.1.22.0
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.96

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC,

Readme.txt

ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272

3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Driver :
 1. Customizations.
 - 2.) Package :
 1. Fix uninstalled message_2 problem (French language) .

Windows 2000/XP : -----

Windows 2000/XP :

| | |
|--------------|---------------|
| RTKHDA64.sys | : 5.10.0.5643 |
| RTKHDAUD.sys | : 5.10.0.5643 |
| Alcmtr.exe | : 1.6.0.2 |
| AlcWzrd.exe | : 1.1.0.36 |
| MicCal.exe | : 1.1.1.8 |
| RTHDCPL.exe | : 2.2.1.8 |
| RTLCPPL.exe | : 1.0.1.65 |
| RtlUpd64.exe | : 2.7.0.9 |
| RtlUpd.exe | : 2.7.0.9 |
| SkyTel.exe | : 2.0.2.0 |
| SoundMan.exe | : 1.0.0.30 |
| ALSndMgr.cpl | : 1.0.0.10 |
| RTSndMgr.cpl | : 1.0.1.0 |
| RTCOMDLL.dll | : 1.0.0.97 |
| RtlCPAPI.dll | : 1.0.1.9 |

Vista driver : -----

Vista driver for x86

| | |
|---------------------|----------------|
| RTKVHDA.sys | : 6.0.1.5643 |
| AERTSrv.exe | : 1.0.32.2 |
| RtHDVCpl.exe | : 1.0.0.198 |
| RtkAudioService.exe | : 1.0.0.14 |
| RtlUpd.exe | : 2.7.0.9 |
| SkyTel.exe | : 2.0.2.0 |
| vncutil.exe | : 1.0.0.7 |
| RTSndMgr.cpl | : 1.0.0.8 |
| AERTACap.dll | : 1.0.32.7 |
| AERTARen.dll | : 1.0.32.3 |
| FMAP0.dll | : 40.59.0.0 |
| MaxxAudioAPO.dll | : 1.2.2.0 |
| MaxxAudioAPO20.dll | : 2.0.13.0 |
| MaxxAudioEQ.dll | : 5.9.7.0 |
| RTCOMDLL.dll | : 2.0.0.98 |
| RtkAPO.dll | : 11.0.6000.67 |
| RtkApoApi.dll | : 1.0.0.4 |
| RtkCoInst.dll | : 1.0.2.6 |
| RtkPgExt.dll | : 6.0.6000.49 |
| RtlCPAPI.dll | : 1.0.1.9 |
| SRSHP360.dll | : 1.1.0.0 |
| SRSTSHD.dll | : 1.1.4.0 |
| SRSTSXT.dll | : 3.2.0.0 |
| SRSWOW.dll | : 1.1.3.0 |
| WavesLib.dll | : 5.9.7.0 |

Vista driver for x64

| | |
|---------------------|----------------|
| RTKVHD64.sys | : 6.0.1.5643 |
| AERTSr64.exe | : 1.0.64.2 |
| RAVCpl64.exe | : 1.0.0.198 |
| RtkAudioService.exe | : 1.0.0.14 |
| RtlUpd64.exe | : 2.7.0.9 |
| SkyTel.exe | : 2.0.2.0 |
| vncutil.exe | : 1.0.0.7 |
| RTSnMg64.cpl | : 1.0.0.8 |
| AERTAC64.dll | : 1.0.64.7 |
| AERTAR64.dll | : 1.0.64.3 |
| FMAP064.dll | : 40.59.0.0 |
| MaxxAudioAPO20.dll | : 2.0.12.0 |
| RCoInst64.dll | : 1.0.2.6 |
| RtCOM64.dll | : 2.0.0.98 |
| RTCOMDLL.dll | : 2.0.0.98 |
| RtkApi64.dll | : 1.0.0.4 |
| RtkAPO64.dll | : 11.0.6000.67 |
| RtlCPAPI.dll | : 1.0.1.9 |

Readme.txt

```

RtPgEx64.dll : 6.0.6000.49
SRSHp64.dll : 1.1.0.0
SRSTSH64.dll : 1.1.4.0
SRSTSx64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
HDMI Driver : -----
Vista x86:
RtHDMV.sys : 6.0.1.5633
RtkUpd.exe : 2.7.0.9
RHDMExt.dll : 6.0.6000.48
RtkHDM.dll : 11.0.6000.66

Vista x64:
RtHDMVX.sys : 6.0.1.5633
RtkUpd64.exe : 2.7.0.9
RHDMEx64.dll : 6.0.6000.48
RtkHDM64.dll : 11.0.6000.66

XP/2K x86:
RtHDM.sys : 5.10.0.5633
RtkUpd.exe : 2.7.0.9
XP/2K x64:
RtHDMX.sys : 5.10.0.5633
RtkUpd64.exe : 2.7.0.9

Driver Setup Program : 2.60

```

Windows 2000/XP Operate on :
 Microsoft High Definition Audio Driver Package - KB888111
 Package file version (kb888111.exe) : 6.1.22.0
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.95

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Driver :
 1. Customizations.
 2. Fix encryption stream issue for ALC889.
 3. Fix DRM issue.

Windows 2000/XP : -----

```

Windows 2000/XP :
RTKHDA64.sys : 5.10.0.5636
RTKHDAUD.sys : 5.10.0.5636
Alcmtr.exe : 1.6.0.2
AlcWzrd.exe : 1.1.0.36
Mccal.exe : 1.1.1.8
RTHDCPL.exe : 2.2.1.6
RTLCPPL.exe : 1.0.1.65
RtlUpd64.exe : 2.7.0.9
RtlUpd.exe : 2.7.0.9
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.30
ALSndMgr.cpl : 1.0.0.10
RTSndMgr.cpl : 1.0.1.0
RTCOMDLL.dll : 1.0.0.96
RtlCPAPI.dll : 1.0.1.9

```

Vista driver : -----

```

RTKVHDA.sys : 6.0.1.5636
AERTSrv.exe : 1.0.32.2
RtHDVCpl.exe : 1.0.0.192
RtkAudioService.exe : 1.0.0.12
RtlUpd.exe : 2.7.0.9
SkyTel.exe : 2.0.2.0
vncutil.exe : 1.0.0.5
RTSndMgr.cpl : 1.0.0.8
AERTACap.dll : 1.0.32.7

```

Readme.txt

AERTARen.dll : 1.0.32.3
 FMAP0.dll : 40.59.0.0
 MaxxAudioAPO.dll : 1.2.2.0
 MaxxAudioAPO20.dll : 2.0.13.0
 MaxxAudioEQ.dll : 5.9.7.0
 RTCOMDLL.dll : 2.0.0.98
 RtkAPO.dll : 11.0.6000.66
 RtkApoApi.dll : 1.0.0.4
 RtkCoInst.dll : 1.0.2.5
 RtkPgExt.dll : 6.0.6000.48
 RtlCPAPI.dll : 1.0.1.9
 SRSH360.dll : 1.1.0.0
 SRSTSHD.dll : 1.1.4.0
 SRSTSXT.dll : 3.2.0.0
 SRSWOW.dll : 1.1.3.0
 WavesLib.dll : 5.9.7.0
 Vista driver for x64
 RTKVHD64.sys : 6.0.1.5636
 AERTSr64.exe : 1.0.64.2
 RAVCpl64.exe : 1.0.0.192
 RtkAudioService.exe : 1.0.0.12
 RtlUpd64.exe : 2.7.0.9
 SkyTel.exe : 2.0.2.0
 vncutil.exe : 1.0.0.5
 RTSnMg64.cpl : 1.0.0.8
 AERTAC64.dll : 1.0.64.7
 AERTAR64.dll : 1.0.64.3
 FMAP064.dll : 40.59.0.0
 MaxxAudioAPO20.dll : 2.0.12.0
 RCoInst64.dll : 1.0.2.5
 RtCOM64.dll : 2.0.0.98
 RTCOMDLL.dll : 2.0.0.98
 RtkApi64.dll : 1.0.0.4
 RtkAPO64.dll : 11.0.6000.66
 RtlCPAPI.dll : 1.0.1.9
 RtlPgEx64.dll : 6.0.6000.48
 SRSH64.dll : 1.1.0.0
 SRSTSH64.dll : 1.1.4.0
 SRSTSX64.dll : 3.2.0.0
 SRSWOW64.dll : 1.1.3.0

HDMI Driver : -----

Vista x86:
 RtHDMV.sys : 6.0.1.5612
 RtkUpd.exe : 2.7.0.9
 RHDMExt.dll : 6.0.6000.44
 RtkHDM.dll : 11.0.6000.63

Vista x64:
 RtHDMVX.sys : 6.0.1.5612
 RtkUpd64.exe : 2.7.0.9
 RHDMEx64.dll : 6.0.6000.44
 RtkHDM64.dll : 11.0.6000.63

XP/2K x86:
 RtHDM.sys : 5.10.0.5612
 RtkUpd.exe : 2.7.0.9

XP/2K x64:
 RtHDMX.sys : 5.10.0.5612
 RtkUpd64.exe : 2.7.0.9

Driver Setup Program : 2.59

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111
 Package file version (kb888111.exe) : 6.1.22.0
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.94

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272

3. HDMI Device WHQL Support: ATI HDMI Devices

Readme.txt

4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Driver :
 1. Customizations.
 2. Zero recorded data for SPDIF-IN copy-protection stream under Vista.

```

Windows 2000/XP : -----
Windows 2000/XP :
RTKHDA64.sys           : 5.10.0.5628
RTKHDAUD.sys          : 5.10.0.5628
Alcmtr.exe            : 1.6.0.2
AlcWzrd.exe           : 1.1.0.36
Mccal.exe             : 1.1.1.8
RTHDCPL.exe          : 2.2.1.3
RTLCPPL.exe          : 1.0.1.65
RtlUpd.exe           : 2.7.0.9
RtlUpd64.exe         : 2.7.0.9
SkyTel.exe           : 2.0.2.0
SoundMan.exe         : 1.0.0.30
ALSndMgr.cpl         : 1.0.0.10
RTSndMgr.cpl         : 1.0.1.0
RTCOMDLL.dll         : 1.0.0.96
RtlCPAPI.dll         : 1.0.1.9
Vista driver : -----
RTKVHDA.sys           : 6.0.1.5628
AERTSrv.exe          : 1.0.32.2
RtHDVCpl.exe         : 1.0.0.188
RtkAudioService.exe : 1.0.0.12
RtkSmbus.exe         : 1.0.0.2
RtlUpd.exe           : 2.7.0.9
SkyTel.exe           : 2.0.2.0
RTSndMgr.cpl         : 1.0.0.8
AERTACap.dll         : 1.0.32.7
AERTARen.dll         : 1.0.32.3
FMAP0.dll            : 40.59.0.0
MaxxAudioAPO.dll    : 1.2.2.0
MaxxAudioAPO20.dll  : 2.0.13.0
MaxxAudioEQ.dll     : 5.9.7.0
RTCOMDLL.dll         : 2.0.0.97
RtkAPO.dll           : 11.0.6000.65
RtkApoApi.dll        : 1.0.0.4
RtkCoInst.dll        : 1.0.2.3
RtkPgExt.dll         : 6.0.6000.47
RtlCPAPI.dll         : 1.0.1.9
SRSHP360.dll         : 1.1.0.0
SRSTSHD.dll          : 1.1.4.0
SRSTSXT.dll          : 3.2.0.0
SRSWOW.dll           : 1.1.3.0
WavesLib.dll         : 5.9.7.0
Vista driver for x64
RTKVHD64.sys         : 6.0.1.5628
AERTSr64.exe         : 1.0.64.2
RAVCpl64.exe         : 1.0.0.188
RtkAudioService.exe : 1.0.0.12
RtkSmbus.exe         : 1.0.0.2
RtlUpd64.exe         : 2.7.0.9
SkyTel.exe           : 2.0.2.0
RTSnMg64.cpl         : 1.0.0.8
AERTAC64.dll         : 1.0.64.7
AERTAR64.dll         : 1.0.64.3
FMAP064.dll          : 40.59.0.0
MaxxAudioAPO20.dll  : 2.0.12.0
RCoInst64.dll        : 1.0.2.3
RtCOMB4.dll          : 2.0.0.97
RTCOMDLL.dll         : 2.0.0.97
RtkApi64.dll         : 1.0.0.4
RtkAPO64.dll         : 11.0.6000.65
RtlCPAPI.dll         : 1.0.1.9
RtPgEx64.dll         : 6.0.6000.47
SRSHP64.dll          : 1.1.0.0
SRSTSH64.dll         : 1.1.4.0
SRSTSX64.dll         : 3.2.0.0
SRSWOW64.dll         : 1.1.3.0
    
```

Readme.txt

```
HDM Driver : -----
Vista x86:
RtHDMV.sys           : 6.0.1.5612
RtkUpd.exe           : 2.7.0.9
RHDMEExt.dll         : 6.0.6000.44
RtkHDM.dll           : 11.0.6000.63

Vista x64:
RtHDMVX.sys          : 6.0.1.5612
RtkUpd64.exe         : 2.7.0.9
RHDMEx64.dll         : 6.0.6000.44
RtkHDM64.dll         : 11.0.6000.63

XP/2K x86:
RtHDM.sys            : 5.10.0.5612
RtkUpd.exe           : 2.7.0.9

XP/2K x64:
RtHDMX.sys           : 5.10.0.5612
RtkUpd64.exe         : 2.7.0.9

Driver Setup Program : 2.59
```

Windows 2000/XP Operate on :
 Microsoft High Definition Audio Driver Package - KB888111
 Package file version (kb888111.exe) : 6.1.22.0
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.93

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Driver :
 1. Customizations.
 - 2.) Package :
 1. Small VGA mode should not be checked in silent installation .

Windows 2000/XP : -----

```
Windows 2000/XP :
RTKHDA64.sys         : 5.10.0.5624
RTKHDAUD.sys         : 5.10.0.5624
Alcmtr.exe           : 1.6.0.2
AlcWzrd.exe          : 1.1.0.36
McCal.exe            : 1.1.1.8
RTHDCPL.exe          : 2.2.1.1
RTLCPPL.exe          : 1.0.1.65
RtlUpd64.exe         : 2.7.0.9
RtlUpd.exe           : 2.7.0.9
SkyTel.exe           : 2.0.2.0
SoundMan.exe         : 1.0.0.30
ALSndMgr.cpl         : 1.0.0.10
RTSndMgr.cpl         : 1.0.1.0
RTCOMDLL.dll         : 1.0.0.96
RtlCPAPI.dll         : 1.0.1.9
```

Vista driver : -----

```
RTKVHDA.sys         : 6.0.1.5624
AERTSrv.exe         : 1.0.32.2
RtHDVCpl.exe        : 1.0.0.185
RtkAudioService.exe : 1.0.0.12
RtkSmbus.exe        : 1.0.0.2
RtlUpd.exe           : 2.7.0.9
SkyTel.exe           : 2.0.2.0
RTSndMgr.cpl         : 1.0.0.7
AERTACap.dll         : 1.0.32.7
AERTARen.dll         : 1.0.32.3
FMAPO.dll            : 40.59.0.0
MaxxAudioAPO.dll    : 1.2.2.0
MaxxAudioAPO20.dll  : 2.0.13.0
```

Readme.txt

MaxxAudioEQ.dll : 5.9.7.0
 RTCOMDLL.dll : 2.0.0.97
 RtkAPO.dll : 11.0.6000.65
 RtkApoApi.dll : 1.0.0.4
 RtkCoInst.dll : 1.0.2.3
 RtkPgExt.dll : 6.0.6000.46
 RtlCPAPI.dll : 1.0.1.9
 SRSH360.dll : 1.1.0.0
 SRSTSHD.dll : 1.1.4.0
 SRSTSXT.dll : 3.2.0.0
 SRSWOW.dll : 1.1.3.0
 WavesLib.dll : 5.9.7.0
 Vista driver for x64
 RTKVHD64.sys : 6.0.1.5624
 AERTSr64.exe : 1.0.64.2
 RAVCpl64.exe : 1.0.0.185
 RtkAudioService.exe : 1.0.0.12
 RtkSmbus.exe : 1.0.0.2
 RtlUpd64.exe : 2.7.0.9
 SkyTel.exe : 2.0.2.0
 RTSnMg64.cpl : 1.0.0.7
 AERTAC64.dll : 1.0.64.7
 AERTAR64.dll : 1.0.64.3
 FMAP064.dll : 40.59.0.0
 MaxxAudioAPO20.dll : 2.0.12.0
 RCoInst64.dll : 1.0.2.3
 RtCOM64.dll : 2.0.0.97
 RTCOMDLL.dll : 2.0.0.97
 RtkApi64.dll : 1.0.0.4
 RtkAPO64.dll : 11.0.6000.65
 RtlCPAPI.dll : 1.0.1.9
 RtlPgEx64.dll : 6.0.6000.46
 SRSH64.dll : 1.1.0.0
 SRSTSH64.dll : 1.1.4.0
 SRSTSX64.dll : 3.2.0.0
 SRSWOW64.dll : 1.1.3.0

HDMI Driver : -----

Vista x86:
 RtHDMV.sys : 6.0.1.5612
 RtkUpd.exe : 2.7.0.9
 RHDMEExt.dll : 6.0.6000.44
 RtkHDM.dll : 11.0.6000.63

Vista x64:
 RtHDMVX.sys : 6.0.1.5612
 RtkUpd64.exe : 2.7.0.9
 RHDMEx64.dll : 6.0.6000.44
 RtkHDM64.dll : 11.0.6000.63

XP/2K x86:
 RtHDM.sys : 5.10.0.5612
 RtkUpd.exe : 2.7.0.9

XP/2K x64:
 RtHDMX.sys : 5.10.0.5612
 RtkUpd64.exe : 2.7.0.9

Driver Setup Program : 2.59

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.92

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WnXP/Wn2000/Wn2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft WindowsXP, Widnows2000, Vista x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

Readme.txt

1. Fix Stereo Mix issue with codec which support capless output pin.
2. Customizations.

```

Windows 2000/XP : -----
Windows 2000/XP :
RTKHDA64.sys           : 5.10.0.5618
RTKHDAUD.sys          : 5.10.0.5618
McCal.exe             : 1.1.1.8
RTHDCPL.exe          : 2.2.1.0
RTLCPPL.exe          : 1.0.1.65
RtlUpd64.exe         : 2.7.0.9
RtlUpd.exe           : 2.7.0.9
SkyTel.exe           : 2.0.2.0
SoundMan.exe         : 1.0.0.30
AlcMtr.exe           : 1.6.0.2
AlcWzrd.exe          : 1.1.0.36
RTSndMgr.cpl         : 1.0.1.0
ALSndMgr.cpl         : 1.0.0.10
RTCOMDLL.dll         : 1.0.0.96
RtlCPAPI.dll         : 1.0.1.9
Vista driver : -----
Vista driver for x86
RTKVHDA.sys           : 6.0.1.5618
AERTSrv.exe          : 1.0.32.2
RtHDVCpl.exe         : 1.0.0.183
RtkAudioService.exe : 1.0.0.12
RtkSmbus.exe         : 1.0.0.2
RtlUpd.exe           : 2.7.0.9
SkyTel.exe           : 2.0.2.0
RTSndMgr.cpl         : 1.0.0.7
AERTACap.dll         : 1.0.32.7
AERTARen.dll         : 1.0.32.3
FMAP0.dll            : 40.58.0.0
MaxxAudioAPO.dll     : 1.2.2.0
MaxxAudioAPO20.dll  : 2.0.13.0
MaxxAudioEQ.dll     : 5.9.7.0
RTCOMDLL.dll         : 2.0.0.97
RtkAPO.dll           : 11.0.6000.64
RtkApoApi.dll        : 1.0.0.4
RtkCoInst.dll        : 1.0.2.1
RtkPgExt.dll         : 6.0.6000.45
RtlCPAPI.dll         : 1.0.1.9
SRSH360.dll          : 1.0.1.0
SRSTSHD.dll          : 1.1.4.0
SRSTSXT.dll          : 3.2.0.0
SRSWOW.dll           : 1.1.3.0
WavesLib.dll         : 5.9.7.0
Vista driver for x64
RTKVHD64.sys         : 6.0.1.5618
AERTSr64.exe         : 1.0.64.2
RAVCpl64.exe         : 1.0.0.183
RtkAudioService.exe : 1.0.0.12
RtkSmbus.exe         : 1.0.0.2
RtlUpd64.exe         : 2.7.0.9
SkyTel.exe           : 2.0.2.0
RTSnMg64.cpl         : 1.0.0.7
AERTAC64.dll         : 1.0.64.7
AERTAR64.dll         : 1.0.64.3
FMAP064.dll          : 40.58.0.0
MaxxAudioAPO20.dll  : 2.0.12.0
RCoInst64.dll        : 1.0.2.1
RtCOM64.dll          : 2.0.0.97
RTCOMDLL.dll         : 2.0.0.97
RtkApi64.dll         : 1.0.0.4
RtkAPO64.dll         : 11.0.6000.64
RtlCPAPI.dll         : 1.0.1.9
RtPgEx64.dll         : 6.0.6000.45
SRSH64.dll           : 1.0.1.0
SRSTSH64.dll         : 1.1.4.0
SRSTSX64.dll         : 3.2.0.0
SRSWOW64.dll         : 1.1.3.0
HDMI Driver : -----
Vista x86:
RtHDMV.sys           : 6.0.1.5612

```

Readme.txt

RtkUpd.exe : 2.7.0.9
 RHDMEExt.dll : 6.0.6000.44
 RtkHDM.dll : 11.0.6000.63

Vista x64:
 RtHDMVX.sys : 6.0.1.5612
 RtkUpd64.exe : 2.7.0.9
 RHDMEx64.dll : 6.0.6000.44
 RtkHDM64.dll : 11.0.6000.63

XP/2K x86:
 RtHDM.sys : 5.10.0.5612
 RtkUpd.exe : 2.7.0.9

XP/2K x64:
 RtHDMX.sys : 5.10.0.5612
 RtkUpd64.exe : 2.7.0.9

Driver Setup Program : 2.58

Windows 2000/XP Operate on :
 Microsoft High Definition Audio Driver Package - KB888111
 Package file version (kb888111.exe) : 6.1.22.0
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.91

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272

3. HDM Device WHQL Support: ATI HDM Devices

4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Fix DTM 1.2 KS topology test fail issue.

2. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :
 RTKHDA64.sys : 5.10.0.5605
 RTKHDAUD.sys : 5.10.0.5605
 McCal.exe : 1.1.1.8
 RTHDCPL.exe : 2.2.0.2
 RTLCPL.exe : 1.0.1.65
 RtlUpd64.exe : 2.7.0.9
 RtlUpd.exe : 2.7.0.9
 SkyTel.exe : 2.0.2.0
 SoundMan.exe : 1.0.0.30
 Alcmtr.exe : 1.6.0.2
 AlcWzrd.exe : 1.1.0.36
 RTSndMgr.cpl : 1.0.1.0
 ALSndMgr.cpl : 1.0.0.10
 RTCOMDLL.dll : 1.0.0.96
 RtlCPAPI.dll : 1.0.1.9

Vista driver : -----

Vista driver for x86
 RTKVHDA.sys : 6.0.1.5605
 AERTSrv.exe : 1.0.32.2
 RtHDVCpl.exe : 1.0.0.172
 RtkAudioService.exe : 1.0.0.11
 RtkSmbus.exe : 1.0.0.1
 RtlUpd.exe : 2.7.0.9
 SkyTel.exe : 2.0.2.0
 RTSndMgr.cpl : 1.0.0.7
 AERTACap.dll : 1.0.32.7
 AERTARen.dll : 1.0.32.3
 FMAPO.dll : 6.0.6000.16386
 MaxxAudioAPO.dll : 1.2.2.0
 MaxxAudioAPO20.dll : 2.0.12.0
 MaxxAudioEQ.dll : 5.9.7.0
 RTCOMDLL.dll : 2.0.0.96
 RtkAPO.dll : 11.0.6000.63

Readme.txt

```

RtkApoApi.dll : 1.0.0.4
RtkCoInst.dll : 1.0.2.0
RtkPgExt.dll : 6.0.6000.42
RtlCPAPI.dll : 1.0.1.9
SRSH360.dll : 1.0.1.0
SRSTSHD.dll : 1.1.4.0
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.1.3.0
WavesLib.dll : 5.9.7.0
Vista driver for x64
RTKVHD64.sys : 6.0.1.5605
AERTSr64.exe : 1.0.64.2
RAVCpl64.exe : 1.0.0.172
RtkAudioService.exe : 1.0.0.11
RtkSmbus.exe : 1.0.0.1
RtlUpd64.exe : 2.7.0.9
SkyTel.exe : 2.0.2.0
RTSnMg64.cpl : 1.0.0.7
AERTAC64.dll : 1.0.64.7
AERTAR64.dll : 1.0.64.3
FMAP064.dll : 6.0.6000.16386
MaxxAudioAPO20.dll : 2.0.12.0
RCoInst64.dll : 1.0.2.0
RtCOM64.dll : 2.0.0.96
RTCOMDLL.dll : 2.0.0.96
RtkApi64.dll : 1.0.0.4
RtkAPO64.dll : 11.0.6000.63
RtlCPAPI.dll : 1.0.1.9
RtPgEx64.dll : 6.0.6000.42
SRSH64.dll : 1.0.1.0
SRSTSH64.dll : 1.1.4.0
SRSTS64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
HDMI Driver : -----
Vista x86:
RtHDM V.sys : 6.0.1.5602
RtkUpd.exe : 2.7.0.9
RHDM Ext.dll : 6.0.6000.42
RtkHDM.dll : 11.0.6000.62

Vista x64:
RtHDM VX.sys : 6.0.1.5602
RtkUpd64.exe : 2.7.0.9
RHDMEx64.dll : 6.0.6000.42
RtkHDM64.dll : 11.0.6000.62

XP/2K x86:
RtHDM.sys : 5.10.0.5602
RtkUpd.exe : 2.7.0.9

XP/2K x64:
RtHDM X.sys : 5.10.0.5602
RtkUpd64.exe : 2.7.0.9

Driver Setup Program : 2.58

```

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111
 Package file version (kb888111.exe) : 6.1.22.0
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.90

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Support ALC663/ALC272.

2. Support ForteMedia microphone effect APO feature.

3. Customizations.

Readme.txt

Windows 2000/XP : -----
 Windows 2000/XP :
 WDM driver for Win2000/WinXP : 5.10.0.5591
 WDM driver for Winx64 : 5.10.0.5591
 Realtek Soundman : 1.0.0.30
 Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
 Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.1.0
 Realtek Sound Effect Manager(RtlCpl) : 1.0.1.65
 Realtek Sound Effect Manager(RTHDCPL) : 2.1.9.6
 Alcwzrd.exe : 1.1.0.36
 SkyTel.exe : 2.0.2.0

Vista driver : -----
 Vista driver for x86 : 6.0.1.5591
 RtHdVcpl.exe : 1.0.0.159
 RtkAPO.dll : 11.0.6000.60
 RtkPgExt.dll : 6.0.6000.40
 RTCOMDLL.dll : 2.0.0.96
 RtlCPAPI.dll : 1.0.1.8
 RTSndMgr.cpl : 1.0.0.7
 RtkCoInst.dll : 1.0.1.29
 SRSTSXT.dll : 3.2.0.0
 SRSWOW.dll : 1.1.3.0
 SRSHP360.dll : 1.0.1.0
 SRSTSHD.dll : 1.1.4.0
 RtkApoApi.dll : 1.0.0.3
 Vista driver for x64 : 6.0.1.5591
 RAVCpl64.exe : 1.0.0.159
 RtkAPO64.dll : 11.0.6000.60
 RtkPgEx64.dll : 6.0.6000.40
 RTCOMDLL.dll : 2.0.0.96
 RtlCPAPI.dll : 1.0.1.8
 RTSnMg64.cpl : 1.0.0.7
 RCoInst64.dll : 1.0.1.29
 SRSTSX64.dll : 3.2.0.0
 SRSWOW64.dll : 1.1.3.0
 SRSHP64.dll : 1.0.1.0
 SRSTSH64.dll : 1.1.4.0
 RtkApi64.dll : 1.0.0.3

HDMI Driver : -----
 Vista x64:
 RtHDMVX.sys : 6.0.1.5575
 RtkHDM64.dll : 6.0.6000.57
 RHDMEx64.dll : 6.0.6000.39
 Vista x86:
 RtHDMV.sys : 6.0.1.5575
 RtkHDM.dll : 6.0.6000.57
 RHDMExt.dll : 6.0.6000.39
 XP/2K x64:
 RtHDMX.sys : 5.10.0.5575
 XP/2K x86:
 RtHDM.sys : 5.10.0.5575

Driver Setup Program : 2.57

Windows 2000/XP Operate on :
 Microsoft High Definition Audio Driver Package - KB888111
 Package file version (kb888111.exe) : 6.1.22.0
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.89

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268, ALC269
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268, ALC269
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix

1.) Driver :

1. Support "Event/Notification mode" under Vista.
2. Fix Vista GUI issue when video adapter's resolution is low.
3. Customizations.

Readme.txt

- 2.) Package :
1. Uninstallation language selected by OS system .
 2. "Uninstall" word issue in Japanese language .

```

Windows 2000/XP : -----
Windows 2000/XP :
WDM driver for Win2000/WinXP      : 5.10.0.5582
WDM driver for Winx64             : 5.10.0.5582
Realtek Soundman                  : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtlCpl)   : 1.0.1.65
Realtek Sound Effect Manager(RTHDCPL)  : 2.1.9.3
Alcwzrd.exe                       : 1.1.0.36
SkyTel.exe                         : 2.0.2.0
Vista driver : -----
Vista driver for x86              : 6.0.1.5582
RtHDVCpl.exe                     : 1.0.0.153
RtkAPO.dll                        : 11.0.6000.59
RtkPgExt.dll                      : 6.0.6000.40
RTCOMDLL.dll                     : 2.0.0.93
RtlCPAPI.dll                      : 1.0.1.7
RTSndMgr.cpl                      : 1.0.0.7
RtkCoInst.dll                     : 1.0.1.27
SRSTSXT.dll                       : 3.2.0.0
SRSWOW.dll                        : 1.1.3.0
SRSH360.dll                       : 1.0.1.0
SRSTSHD.dll                       : 1.1.4.0
RtkApoApi.dll                     : 1.0.0.3
Vista driver for x64              : 6.0.1.5582
RAVCpl64.exe                     : 1.0.0.153
RtkAPO64.dll                      : 11.0.6000.59
RtPgEx64.dll                      : 6.0.6000.40
RTCOMDLL.dll                     : 2.0.0.93
RtlCPAPI.dll                      : 1.0.1.7
RTSnMg64.cpl                      : 1.0.0.7
RCoInst64.dll                     : 1.0.1.27
SRSTSX64.dll                      : 3.2.0.0
SRSWOW64.dll                      : 1.1.3.0
SRSH64.dll                        : 1.0.1.0
SRSTSH64.dll                      : 1.1.4.0
RtkApi64.dll                      : 1.0.0.3
HDMI Driver : -----
Vista x64:
RtHDMVX.sys                       : 6.0.1.5575
RtkHDM64.dll                      : 6.0.6000.57
RHDMEx64.dll                      : 6.0.6000.39
Vista x86:
RtHDMV.sys                        : 6.0.1.5575
RtkHDM.dll                        : 6.0.6000.57
RHDMExt.dll                       : 6.0.6000.39
XP/2K x64:
RtHDMX.sys                         : 5.10.0.5575
XP/2K x86:
RtHDM.sys                          : 5.10.0.5575

Driver Setup Program               : 2.56

```

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111
 Package file version (kb888111.exe) : 6.1.22.0
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.88

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268, ALC269
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268, ALC269
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft WindowsXP, Win2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix

- 1.) Driver :

Readme.txt

1. Fix BSOD issue for WLK 1.1 System-Common Scenario Stress With IO test and System-Disable
 Enable With IO test under XP.
 2. Customizations.

Windows 2000/XP : -----
 Windows 2000/XP :
 WDM driver for Win2000/WinXP : 5.10.0.5574
 WDM driver for Winx64 : 5.10.0.5574
 Realtek Soundman : 1.0.0.30
 Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
 Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
 Realtek Sound Effect Manager(RtlCpl) : 1.0.1.65
 Realtek Sound Effect Manager(RTHDCPL) : 2.1.9.1
 Alcwzrd.exe : 1.1.0.36
 SkyTel.exe : 2.0.2.0

Vista driver : -----
 Vista driver for x86 : 6.0.1.5574
 RtHDVCpl.exe : 1.0.0.145
 RtkAPO.dll : 11.0.6000.58
 RtkPgExt.dll : 6.0.6000.38
 RTCOMDLL.dll : 2.0.0.90
 RtlCPAPI.dll : 1.0.1.7
 RTSndMgr.cpl : 1.0.0.7
 RtkCoInst.dll : 1.0.1.25
 SRSTSXT.dll : 3.2.0.0
 SRSWOW.dll : 1.1.3.0
 SRSH360.dll : 1.0.1.0
 SRSTSHD.dll : 1.1.4.0
 RtkApoApi.dll : 1.0.0.3
 Vista driver for x64 : 6.0.1.5574
 RAVCpl64.exe : 1.0.0.145
 RtkAPO64.dll : 11.0.6000.58
 RtkPgEx64.dll : 6.0.6000.38
 RTCOMDLL.dll : 2.0.0.90
 RtlCPAPI.dll : 1.0.1.7
 RTSnMg64.cpl : 1.0.0.7
 RCoInst64.dll : 1.0.1.25
 SRSTSX64.dll : 3.2.0.0
 SRSWOW64.dll : 1.1.3.0
 SRSH64.dll : 1.0.1.0
 SRSTSH64.dll : 1.1.4.0
 RtkApi64.dll : 1.0.0.3

HDMI Driver : -----
 Vista x64:
 RtHDMVX.sys : 6.0.1.5413
 RtkHDM64.dll : 6.0.6000.37
 RHDMEx64.dll : 6.0.6000.25
 Vista x86:
 RtHDMV.sys : 6.0.1.5413
 RtkHDM.dll : 6.0.6000.37
 RHDMEExt.dll : 6.0.6000.25
 XP/2K x64:
 RtHDMX.sys : 5.10.0.5413
 XP/2K x86:
 RtHDM.sys : 5.10.0.5413

Driver Setup Program : 2.55

Windows 2000/XP Operate on :
 Microsoft High Definition Audio Driver Package - KB888111
 Package file version (kb888111.exe) : 6.1.22.0
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.87

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268, ALC269
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268, ALC269
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Driver :

Readme.txt

1. Fix recording issue for ALC269.
2. Customizations.

```

Windows 2000/XP : -----
Windows 2000/XP :
WDM driver for Win2000/WinXP      : 5.10.0.5567
WDM driver for Winx64             : 5.10.0.5567
Realtek Soundman                  : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtlCpl)   : 1.0.1.65
Realtek Sound Effect Manager(RTHDCPL)  : 2.1.8.9
Alcwzrd.exe                       : 1.1.0.36
SkyTel.exe                         : 2.0.2.0
Vista driver : -----
Vista driver for x86              : 6.0.1.5567
RtHDVCpl.exe                     : 1.0.0.139
RtkAPO.dll                        : 11.0.6000.56
RtkPgExt.dll                      : 6.0.6000.35
RTCOMDLL.dll                     : 2.0.0.89
RtlCPAPI.dll                     : 1.0.1.7
RTSndMgr.cpl                      : 1.0.0.7
RtkCoInst.dll                    : 1.0.1.25
SRSTSXT.dll                       : 3.2.0.0
SRSWOW.dll                        : 1.1.3.0
SRSHP360.dll                      : 1.0.1.0
SRSTSHD.dll                       : 1.1.4.0
RtkApoApi.dll                    : 1.0.0.3
Vista driver for x64             : 6.0.1.5567
RAVCpl64.exe                     : 1.0.0.139
RtkAPO64.dll                      : 11.0.6000.56
RtPgEx64.dll                     : 6.0.6000.35
RTCOMDLL.dll                     : 2.0.0.89
RtlCPAPI.dll                     : 1.0.1.7
RTSnMg64.cpl                     : 1.0.0.7
RCoInst64.dll                    : 1.0.1.25
SRSTSX64.dll                     : 3.2.0.0
SRSWOW64.dll                     : 1.1.3.0
SRSHP64.dll                      : 1.0.1.0
SRSTSH64.dll                     : 1.1.4.0
RtkApi64.dll                     : 1.0.0.3
HDMI Driver : -----
Vista x64:
RtHDMVX.sys                      : 6.0.1.5413
RtkHDM64.dll                     : 6.0.6000.37
RHDMEx64.dll                     : 6.0.6000.25
Vista x86:
RtHDMV.sys                       : 6.0.1.5413
RtkHDM.dll                       : 6.0.6000.37
RHDMExt.dll                      : 6.0.6000.25
XP/2K x64:
RtHDMX.sys                       : 5.10.0.5413
XP/2K x86:
RtHDM.sys                        : 5.10.0.5413

Driver Setup Program              : 2.54

```

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111
 Package file version (kb888111.exe) : 6.1.22.0
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.86

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268, ALC269
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268, ALC269
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix

1.) Driver :

1. Fix the issue that SPDIF-out device broadcast 2nd output device's stream when turn on

- multi-streaming under Windows XP.
2. Indexed DRC file supported.
 3. Customizations.
- 2.) Package :
1. Installer failed code.
 2. Copy .dat file rule.

Windows 2000/XP : -----

Windows 2000/XP :

| | |
|--------------------------------------------|---------------|
| WDM driver for Win2000/WinXP | : 5.10.0.5559 |
| WDM driver for Winx64 | : 5.10.0.5559 |
| Realtek Soundman | : 1.0.0.30 |
| Realtek Sound Effect Manager(ALSndMgr.cpl) | : 1.0.0.10 |
| Realtek Sound Effect Manager(RTSndMgr.cpl) | : 1.0.0.9 |
| Realtek Sound Effect Manager(RtlCpl) | : 1.0.1.65 |
| Realtek Sound Effect Manager(RTHDCPL) | : 2.1.8.7 |
| Alcwzrd.exe | : 1.1.0.36 |
| SkyTel.exe | : 2.0.2.0 |

Vista driver : -----

| | |
|----------------------|----------------|
| Vista driver for x86 | : 6.0.1.5559 |
| RtHdVCpl.exe | : 1.0.0.132 |
| RtkAPO.dll | : 11.0.6000.54 |
| RtkPgExt.dll | : 6.0.6000.35 |
| RTCOMDLL.dll | : 2.0.0.87 |
| RtlCPAPI.dll | : 1.0.1.7 |
| RTSndMgr.cpl | : 1.0.0.7 |
| RtkCoInst.dll | : 1.0.1.25 |
| SRSTSXT.dll | : 3.2.0.0 |
| SRSWOW.dll | : 1.1.3.0 |
| SRSHP360.dll | : 1.0.1.0 |
| SRSTSHD.dll | : 1.1.4.0 |
| RtkApoApi.dll | : 1.0.0.3 |
| Vista driver for x64 | : 6.0.1.5559 |
| RAVCpl64.exe | : 1.0.0.132 |
| RtkAPO64.dll | : 11.0.6000.54 |
| RtPgEx64.dll | : 6.0.6000.35 |
| RTCOMDLL.dll | : 2.0.0.87 |
| RtlCPAPI.dll | : 1.0.1.7 |
| RTSnMg64.cpl | : 1.0.0.7 |
| RCoInst64.dll | : 1.0.1.25 |
| SRSTSx64.dll | : 3.2.0.0 |
| SRSWOW64.dll | : 1.1.3.0 |
| SRSHP64.dll | : 1.0.1.0 |
| SRSTSH64.dll | : 1.1.4.0 |
| RtkApi64.dll | : 1.0.0.3 |

HDMI Driver : -----

| | |
|--------------|---------------|
| Vista x64: | |
| RtHDMVX.sys | : 6.0.1.5413 |
| RtkHDM64.dll | : 6.0.6000.37 |
| RHDMEx64.dll | : 6.0.6000.25 |
| Vista x86: | |
| RtHDMV.sys | : 6.0.1.5413 |
| RtkHDM.dll | : 6.0.6000.37 |
| RHDMExt.dll | : 6.0.6000.25 |
| XP/2K x64: | |
| RtHDMX.sys | : 5.10.0.5413 |
| XP/2K x86: | |
| RtHDM.sys | : 5.10.0.5413 |

Driver Setup Program : 2.52

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.85

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268, ALC269
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268, ALC269
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64

Readme.txt

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Fix PC-Beep mute issue for ALC268/ALC267.

2. Fix the potential risk that system-thread is still running when driver is already unloaded

under Vista.

3. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :

WDM driver for Win2000/WinXP : 5.10.0.5548

WDM driver for Winx64 : 5.10.0.5548

Realtek Soundman : 1.0.0.30

Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10

Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9

Realtek Sound Effect Manager(RtlCpl) : 1.0.1.65

Realtek Sound Effect Manager(RTHDCPL) : 2.1.8.6

Alcwzrd.exe : 1.1.0.36

SkyTel.exe : 2.0.2.0

Vista driver : -----

Vista driver for x86 : 6.0.1.5548

RtHDVCpl.exe : 1.0.0.128

RtkAPO.dll : 11.0.6000.51

RtkPgExt.dll : 6.0.6000.33

RTCOMDLL.dll : 2.0.0.86

RtlCPAPI.dll : 1.0.1.7

RTSndMgr.cpl : 1.0.0.7

RtkCoInst.dll : 1.0.1.25

SRSTSXT.dll : 3.2.0.0

SRSWOW.dll : 1.1.3.0

SRSHP360.dll : 1.0.1.0

SRSTSHD.dll : 1.1.4.0

RtkApoApi.dll : 1.0.0.3

Vista driver for x64 : 6.0.1.5548

RAVCpl64.exe : 1.0.0.128

RtkAPO64.dll : 11.0.6000.51

RtPgEx64.dll : 6.0.6000.33

RTCOMDLL.dll : 2.0.0.86

RtlCPAPI.dll : 1.0.1.7

RTSnMg64.cpl : 1.0.0.7

RCoInst64.dll : 1.0.1.25

SRSTSX64.dll : 3.2.0.0

SRSWOW64.dll : 1.1.3.0

SRSHP64.dll : 1.0.1.0

SRSTSH64.dll : 1.1.4.0

RtkApi64.dll : 1.0.0.3

HDMI Driver : -----

Vista x64:

RtHDMVX.sys : 6.0.1.5413

RtkHDM64.dll : 6.0.6000.37

RHDMEx64.dll : 6.0.6000.25

Vista x86:

RtHDMV.sys : 6.0.1.5413

RtkHDM.dll : 6.0.6000.37

RHDMExt.dll : 6.0.6000.25

XP/2K x64:

RtHDMX.sys : 5.10.0.5413

XP/2K x86:

RtHDM.sys : 5.10.0.5413

Driver Setup Program : 2.51

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.84

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268, ALC269

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268, ALC269

3. HDMI Device WHQL Support: ATI HDMI Devices

Readme.txt

4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Driver :
 1. Fix potential risk for re-direct headphone mode under Vista.
 2. Customizations.

Windows 2000/XP : -----
Windows 2000/XP :
WDM driver for Win2000/WinXP : 5.10.0.5532
WDM driver for Winx64 : 5.10.0.5532
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.65
Realtek Sound Effect Manager(RTHDCPL) : 2.1.8.2
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 2.0.2.0
Vista driver : -----
Vista driver for x86 : 6.0.1.5532
RtHDVCpl.exe : 1.0.0.116
RtkAPO.dll : 11.0.6000.48
RtkPgExt.dll : 6.0.6000.31
RTCOMDLL.dll : 2.0.0.86
RtlCPAPI.dll : 1.0.1.6
RTSndMgr.cpl : 1.0.0.7
RtkCoInst.dll : 1.0.1.18
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.1.3.0
SRSHP360.dll : 1.0.1.0
SRSTSHD.dll : 1.1.4.0
RtkApoApi.dll : 1.0.0.2
Vista driver for x64 : 6.0.1.5532
RAVCpl64.exe : 1.0.0.116
RtkAPO64.dll : 11.0.6000.48
RtPgEx64.dll : 6.0.6000.31
RTCOMDLL.dll : 2.0.0.86
RtlCPAPI.dll : 1.0.1.6
RTSnMg64.cpl : 1.0.0.7
RCoInst64.dll : 1.0.1.18
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
SRSHP64.dll : 1.0.1.0
SRSTSH64.dll : 1.1.4.0
RtkApi64.dll : 1.0.0.2
HDMI Driver : -----
Vista x64:
RtHDMVX.sys : 6.0.1.5413
RtkHDM64.dll : 6.0.6000.37
RHDMEx64.dll : 6.0.6000.25
Vista x86:
RtHDMV.sys : 6.0.1.5413
RtkHDM.dll : 6.0.6000.37
RHDMExt.dll : 6.0.6000.25
XP/2K x64:
RtHDMX.sys : 5.10.0.5413
XP/2K x86:
RtHDM.sys : 5.10.0.5413
Driver Setup Program : 2.51

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.83
Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .
1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268, ALC269
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268, ALC269
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64

Readme.txt

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Driver :
 1. Support ALC269.
 2. Customizations.
 3. Turn on amplifier mask control for ALC885.
 4. Fix volume issue when turn on "Limited Output" feature under Windows XP.

Windows 2000/XP : -----
Windows 2000/XP :
WDM driver for Win2000/WinXP : 5.10.0.5523
WDM driver for Winx64 : 5.10.0.5523
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.65
Realtek Sound Effect Manager(RTHDCPL) : 2.1.7.7
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 2.0.2.0
Vista driver : -----
Vista driver for x86 : 6.0.1.5523
RtHdVCpl.exe : 1.0.0.112
RtkAPO.dll : 11.0.6000.48
RtkPgExt.dll : 6.0.6000.31
RTCOMDLL.dll : 2.0.0.85
RtlCPAPI.dll : 1.0.1.6
RTSndMgr.cpl : 1.0.0.7
RtkCoInst.dll : 1.0.1.15
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.1.3.0
SRSHP360.dll : 1.0.1.0
SRSTSHD.dll : 1.1.4.0
RtkApoApi.dll : 1.0.0.2
Vista driver for x64 : 6.0.1.5523
RAVCpl64.exe : 1.0.0.112
RtkAPO64.dll : 11.0.6000.48
RtPgEx64.dll : 6.0.6000.31
RTCOMDLL.dll : 2.0.0.85
RtlCPAPI.dll : 1.0.1.6
RTSnMg64.cpl : 1.0.0.7
RCoInst64.dll : 1.0.1.15
SRSTSx64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
SRSHP64.dll : 1.0.1.0
SRSTSH64.dll : 1.1.4.0
RtkApi64.dll : 1.0.0.2
HDMI Driver : -----
Vista x64:
RtHDMVX.sys : 6.0.1.5413
RtkHDM64.dll : 6.0.6000.37
RHDMEx64.dll : 6.0.6000.25
Vista x86:
RtHDMV.sys : 6.0.1.5413
RtkHDM.dll : 6.0.6000.37
RHDMExt.dll : 6.0.6000.25
XP/2K x64:
RtHDMX.sys : 5.10.0.5413
XP/2K x86:
RtHDM.sys : 5.10.0.5413
Driver Setup Program : 2.51

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.82
Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .
1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64

Readme.txt

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Driver :
 1. Support IMiniportWaveRTStreamNotification interface under Vista.
 2. Customizations.
 3. Fix bug for the specific customer.
 - 2.) Installer :
 1. Add silent uninstall option .

```

Windows 2000/XP : -----
Windows 2000/XP :
WDM driver for Win2000/WinXP      : 5.10.0.5512
WDM driver for Winx64             : 5.10.0.5512
Realtek Soundman                  : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtlCpl)   : 1.0.1.65
Realtek Sound Effect Manager(RTHDCPL)  : 2.1.7.1
Alcwzrd.exe                       : 1.1.0.36
SkyTel.exe                         : 2.0.1.21
Vista driver : -----
Vista driver for x86              : 6.0.1.5512
RtHDVCpl.exe                     : 1.0.0.106
RtkAPO.dll                        : 11.0.6000.48
RtkPgExt.dll                     : 6.0.6000.31
RTCOMDLL.dll                     : 2.0.0.83
RtlCPAPI.dll                     : 1.0.1.6
RTSndMgr.cpl                     : 1.0.0.7
RtkCoInst.dll                    : 1.0.1.13
SRSTSXT.dll                      : 3.2.0.0
SRSWOW.dll                       : 1.1.3.0
SRSH360.dll                      : 1.0.1.0
SRSTSHD.dll                      : 1.1.4.0
RtkApoApi.dll                   : 1.0.0.2
Vista driver for x64             : 6.0.1.5512
RAVCpl64.exe                    : 1.0.0.106
RtkAPO64.dll                     : 11.0.6000.48
RtPgEx64.dll                     : 6.0.6000.31
RTCOMDLL.dll                     : 2.0.0.83
RtlCPAPI.dll                     : 1.0.1.6
RTSnMg64.cpl                    : 1.0.0.7
RCoInst64.dll                   : 1.0.1.13
SRSTSX64.dll                    : 3.2.0.0
SRSWOW64.dll                    : 1.1.3.0
SRSH64.dll                      : 1.0.1.0
SRSTSH64.dll                    : 1.1.4.0
RtkApi64.dll                    : 1.0.0.2
HDM Driver : -----
Vista x64:
RtHDMVX.sys                      : 6.0.1.5413
RtkHDM64.dll                     : 6.0.6000.37
RHDMEx64.dll                     : 6.0.6000.25
Vista x86:
RtHDMV.sys                       : 6.0.1.5413
RtkHDM.dll                       : 6.0.6000.37
RHDMExt.dll                      : 6.0.6000.25
XP/2K x64:
RtHDMX.sys                       : 5.10.0.5413
XP/2K x86:
RtHDM.sys                        : 5.10.0.5413

Driver Setup Program              : 2.51

```

Windows 2000/XP Operate on :
 Microsoft High Definition Audio Driver Package - KB888111
 Package file version (kb888111.exe) : 6.1.22.0
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.81

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
3. HDM Device WHQL Support: ATI HDM Devices

Readme.txt

4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Driver :
 1. Support real 2.1 output capability under Vista.
 2. Improve Doppler effect for XP driver.
 3. Fix Vista DTM topology testing issue.
 4. Fix dead lock issue when more than 3 jacks set as headphone output under XP.
 - 2.) Installer :
 1. VSS event error for InstallShield .

Windows 2000/XP : -----

Windows 2000/XP :
 WDM driver for Win2000/WinXP : 5.10.0.5506
 WDM driver for Winx64 : 5.10.0.5506
 Realtek Soundman : 1.0.0.30
 Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
 Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
 Realtek Sound Effect Manager(RtlCpl) : 1.0.1.65
 Realtek Sound Effect Manager(RTHDCPL) : 2.1.7.0
 Alcwzrd.exe : 1.1.0.36
 SkyTel.exe : 2.0.1.21

Vista driver : -----

Vista driver for x86 : 6.0.1.5506
 RtHDVCpl.exe : 1.0.0.103
 RtkAPO.dll : 11.0.6000.48
 RtkPgExt.dll : 6.0.6000.31
 RTCOMDLL.dll : 2.0.0.82
 RtlCPAPI.dll : 1.0.1.6
 RTSndMgr.cpl : 1.0.0.6
 RtkCoInst.dll : 1.0.1.13
 SRSTSXT.dll : 3.2.0.0
 SRSWOW.dll : 1.1.3.0
 SRSHP360.dll : 1.0.1.0
 SRSTSHD.dll : 1.1.4.0
 RtkApoApi.dll : 1.0.0.2
 Vista driver for x64 : 6.0.1.5506
 RAVCpl64.exe : 1.0.0.103
 RtkAPO64.dll : 11.0.6000.48
 RtkPgEx64.dll : 6.0.6000.31
 RTCOMDLL.dll : 2.0.0.82
 RtlCPAPI.dll : 1.0.1.6
 RTSnMg64.cpl : 1.0.0.6
 RCoInst64.dll : 1.0.1.13
 SRSTSX64.dll : 3.2.0.0
 SRSWOW64.dll : 1.1.3.0
 SRSHP64.dll : 1.0.1.0
 SRSTSH64.dll : 1.1.4.0
 RtkApi64.dll : 1.0.0.2

HDM Driver : -----

Vista x64:
 RtHDMVX.sys : 6.0.1.5413
 RtkHDM64.dll : 6.0.6000.37
 RHDMEx64.dll : 6.0.6000.25
 Vista x86:
 RtHDMV.sys : 6.0.1.5413
 RtkHDM.dll : 6.0.6000.37
 RHDMExt.dll : 6.0.6000.25
 XP/2K x64:
 RtHDMX.sys : 5.10.0.5413
 XP/2K x86:
 RtHDM.sys : 5.10.0.5413

Driver Setup Program : 2.50

Windows 2000/XP Operate on :
 Microsoft High Definition Audio Driver Package - KB888111
 Package file version (kb888111.exe) : 6.1.22.0
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.80

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD,

Readme.txt

ALC660, ALC662, ALC260, ALC262, ALC267, ALC268

3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Driver :
 1. Customizations.
 2. Add new feature to smooth gap between 2 different output stream under Vista.
 - 2.) Installer :
 1. "Program Compatibility Assistant" issue for InstallShield 11.5 .
 2. VSR stop setting .

Windows 2000/XP : -----

Windows 2000/XP :
 WDM driver for Win2000/WinXP : 5.10.0.5497
 WDM driver for Winx64 : 5.10.0.5497
 Realtek Soundman : 1.0.0.30
 Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
 Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
 Realtek Sound Effect Manager(RtlCpl) : 1.0.1.65
 Realtek Sound Effect Manager(RTHDCPL) : 2.1.6.7
 Alcwzrd.exe : 1.1.0.36
 SkyTel.exe : 2.0.1.21

Vista driver : -----

Vista driver for x86 : 6.0.1.5497
 RtHdVcpl.exe : 1.0.0.99
 RtkAPO.dll : 11.0.6000.45
 RtkPgExt.dll : 6.0.6000.30
 RTCOMDLL.dll : 2.0.0.80
 RtlCPAPI.dll : 1.0.1.6
 RTSndMgr.cpl : 1.0.0.6
 RtkCoInst.dll : 1.0.1.10
 SRSTSXT.dll : 3.2.0.0
 SRSWOW.dll : 1.1.3.0
 SRSHP360.dll : 1.0.1.0
 SRSTSHD.dll : 1.1.4.0
 RtkApoApi.dll : 1.0.0.2
 Vista driver for x64 : 6.0.1.5497
 RAVCpl64.exe : 1.0.0.99
 RtkAPO64.dll : 11.0.6000.45
 RtkPgEx64.dll : 6.0.6000.30
 RTCOMDLL.dll : 2.0.0.80
 RtlCPAPI.dll : 1.0.1.6
 RTSnMg64.cpl : 1.0.0.6
 RCoInst64.dll : 1.0.1.10
 SRSTSx64.dll : 3.2.0.0
 SRSWOW64.dll : 1.1.3.0
 SRSHP64.dll : 1.0.1.0
 SRSTSH64.dll : 1.1.4.0
 RtkApi64.dll : 1.0.0.2

HDM Driver : -----

Vista x64:
 RtHDM VX.sys : 6.0.1.5413
 RtkHDM64.dll : 6.0.6000.37
 RHDMEx64.dll : 6.0.6000.25
 Vista x86:
 RtHDM V.sys : 6.0.1.5413
 RtkHDM.dll : 6.0.6000.37
 RHDMExt.dll : 6.0.6000.25
 XP/2K x64:
 RtHDM X.sys : 5.10.0.5413
 XP/2K x86:
 RtHDM.sys : 5.10.0.5413

Driver Setup Program : 2.49

Windows 2000/XP Operate on :
 Microsoft High Definition Audio Driver Package - KB888111
 Package file version (kb888111.exe) : 6.1.22.0
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.79

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268

Readme.txt

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Driver :
 1. Customizations.
 2. Fix potential risk from dividing by zero while the input signal power approach zero under Windows XP.
 3. Support digital mic software boost for ALC888.
 - 2.) Installer :
 1. Remove Realtek registry key in upgrade mode.
 2. Change MCE GUI installation procedure for Windows Vista by Microsoft requirement.
 3. Add install procedure for VSR feature.

Windows 2000/XP : -----

Windows 2000/XP :
WDM driver for Win2000/WinXP : 5.10.0.5490
WDM driver for Winx64 : 5.10.0.5490
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.65
Realtek Sound Effect Manager(RTHDCPL) : 2.1.6.2
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 2.0.1.20

Vista driver : -----

Vista driver for x86 : 6.0.1.5490
RtHdVCpl.exe : 1.0.0.96
RtkAPO.dll : 11.0.6000.45
RtkPgExt.dll : 6.0.6000.30
RTCOMDLL.dll : 2.0.0.79
RtlCPAPI.dll : 1.0.1.6
RTSndMgr.cpl : 1.0.0.6
RtkCoInst.dll : 1.0.1.9
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.1.3.0
SRSHP360.dll : 1.0.1.0
SRSTSHD.dll : 1.1.4.0
RtkApoApi.dll : 1.0.0.2
Vista driver for x64 : 6.0.1.5490
RAVCpl64.exe : 1.0.0.96
RtkAPO64.dll : 11.0.6000.45
RtkPgEx64.dll : 6.0.6000.30
RTCOMDLL.dll : 2.0.0.79
RtlCPAPI.dll : 1.0.1.6
RTSnMg64.cpl : 1.0.0.6
RCoInst64.dll : 1.0.1.9
SRSTSx64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
SRSHP64.dll : 1.0.1.0
SRSTSH64.dll : 1.1.4.0
RtkApi64.dll : 1.0.0.2

HDMI Driver : -----

Vista x64:
RtHDMVX.sys : 6.0.1.5413
RtkHDM64.dll : 6.0.6000.37
RHDMEx64.dll : 6.0.6000.25
Vista x86:
RtHDMV.sys : 6.0.1.5413
RtkHDM.dll : 6.0.6000.37
RHDMExt.dll : 6.0.6000.25
XP/2K x64:
RtHDMX.sys : 5.10.0.5413
XP/2K x86:
RtHDM.sys : 5.10.0.5413

Driver Setup Program : 2.47

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Readme.txt

Driver Package R1.78

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Customization.

Windows 2000/XP : -----

Windows 2000/XP :
WDM driver for Win2000/WinXP : 5.10.0.5485
WDM driver for Winx64 : 5.10.0.5485
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.65
Realtek Sound Effect Manager(RTHDCPL) : 2.1.6.0
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 2.0.1.20

Vista driver : -----

Vista driver for x86 :
RtHdVCpl.exe : 1.0.0.92
RtkAPO.dll : 11.0.6000.45
RtkPgExt.dll : 6.0.6000.29
RTCOMDLL.dll : 2.0.0.79
RtlCPAPI.dll : 1.0.1.6
RTSndMgr.cpl : 1.0.0.6
RtkCoInst.dll : 1.0.1.8
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.1.3.0
SRSH360.dll : 1.0.1.0
SRSTSHD.dll : 1.1.4.0
RtkApoApi.dll : 1.0.0.2
Vista driver for x64 :
RAVCpl64.exe : 1.0.0.92
RtkAPO64.dll : 11.0.6000.45
RtPgEx64.dll : 6.0.6000.29
RTCOMDLL.dll : 2.0.0.79
RtlCPAPI.dll : 1.0.1.6
RTSnMg64.cpl : 1.0.0.6
RCoInst64.dll : 1.0.1.8
SRSTSx64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
SRSH64.dll : 1.0.1.0
SRSTSH64.dll : 1.1.4.0
RtkApi64.dll : 1.0.0.2

HDMI Driver : -----

Vista x64:
RtHDMVX.sys : 6.0.1.5413
RtkHDM64.dll : 6.0.6000.37
RHDMEx64.dll : 6.0.6000.25
Vista x86:
RtHDMV.sys : 6.0.1.5413
RtkHDM.dll : 6.0.6000.37
RHDMExt.dll : 6.0.6000.25
XP/2K x64:
RtHDMX.sys : 5.10.0.5413
XP/2K x86:
RtHDM.sys : 5.10.0.5413

Driver Setup Program : 2.45

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.77

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268

Readme.txt

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Customization.
 - 2.) Uninstall procedure for checking Rtlupd.exe file .

Windows 2000/XP : -----

Windows 2000/XP :
WDM driver for Win2000/WinXP : 5.10.0.5480
WDM driver for Winx64 : 5.10.0.5480
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.65
Realtek Sound Effect Manager(RTHDCPL) : 2.1.5.7
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 2.0.1.20

Vista driver : -----

Vista driver for x86 : 6.0.1.5480
RtHDVCpl.exe : 1.0.0.90
RtkAPO.dll : 11.0.6000.45
RtkPgExt.dll : 6.0.6000.29
RTCOMDLL.dll : 2.0.0.79
RtlCPAPI.dll : 1.0.1.6
RTSndMgr.cpl : 1.0.0.6
RtkCoInst.dll : 1.0.1.7
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.1.3.0
SRSH360.dll : 1.0.1.0
SRSTSHD.dll : 1.1.4.0
RtkApoApi.dll : 1.0.0.2
Vista driver for x64 : 6.0.1.5480
RAVCpl64.exe : 1.0.0.90
RtkAPO64.dll : 11.0.6000.45
RtPgEx64.dll : 6.0.6000.29
RTCOMDLL.dll : 2.0.0.79
RtlCPAPI.dll : 1.0.1.6
RTSnMg64.cpl : 1.0.0.6
RCoInst64.dll : 1.0.1.7
SRSTX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
SRSH64.dll : 1.0.1.0
SRSTSH64.dll : 1.1.4.0
RtkApi64.dll : 1.0.0.2

HDMI Driver : -----

Vista x64:
RtHDMVX.sys : 6.0.1.5413
RtkHDM64.dll : 6.0.6000.37
RHDMEx64.dll : 6.0.6000.25
Vista x86:
RtHDMV.sys : 6.0.1.5413
RtkHDM.dll : 6.0.6000.37
RHDMExt.dll : 6.0.6000.25
XP/2K x64:
RtHDMX.sys : 5.10.0.5413
XP/2K x86:
RtHDM.sys : 5.10.0.5413

Driver Setup Program : 2.45

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.76

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
3. HDMI Device WHQL Support: ATI HDMI Devices

Readme.txt

4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Customization.
 - 2.) Installer package language wrong for Japanese translation . (Upgrade operation for Vista)

Windows 2000/XP : -----

Windows 2000/XP :
 WDM driver for Win2000/WinXP : 5.10.0.5477
 WDM driver for Winx64 : 5.10.0.5477
 Realtek Soundman : 1.0.0.30
 Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
 Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
 Realtek Sound Effect Manager(RtlCpl) : 1.0.1.65
 Realtek Sound Effect Manager(RTHDCPL) : 2.1.5.5
 Alcwzrd.exe : 1.1.0.36
 SkyTel.exe : 2.0.1.20

Vista driver : -----

Vista driver for x86 : 6.0.1.5477
 RtHdVcpl.exe : 1.0.0.89
 RtkAPO.dll : 11.0.6000.45
 RtkPgExt.dll : 6.0.6000.29
 RTCOMDLL.dll : 2.0.0.79
 RtlCPAPI.dll : 1.0.1.6
 RTSndMgr.cpl : 1.0.0.6
 RtkCoInst.dll : 1.0.1.7
 SRSTSXT.dll : 3.2.0.0
 SRSWOW.dll : 1.1.3.0
 SRSHP360.dll : 1.0.1.0
 SRSTSHD.dll : 1.1.4.0
 RtkApoApi.dll : 1.0.0.2
 Vista driver for x64 : 6.0.1.5477
 RAVCpl64.exe : 1.0.0.89
 RtkAPO64.dll : 11.0.6000.45
 RtkPgEx64.dll : 6.0.6000.29
 RTCOMDLL.dll : 2.0.0.79
 RtlCPAPI.dll : 1.0.1.6
 RTSnMg64.cpl : 1.0.0.6
 RCoInst64.dll : 1.0.1.7
 SRSTSx64.dll : 3.2.0.0
 SRSWOW64.dll : 1.1.3.0
 SRSHP64.dll : 1.0.1.0
 SRSTSH64.dll : 1.1.4.0
 RtkApi64.dll : 1.0.0.2

HDMI Driver : -----

Vista x64:
 RtHDMVX.sys : 6.0.1.5413
 RtkHDM64.dll : 6.0.6000.37
 RHDMEx64.dll : 6.0.6000.25
 Vista x86:
 RtHDMV.sys : 6.0.1.5413
 RtkHDM.dll : 6.0.6000.37
 RHDMEExt.dll : 6.0.6000.25
 XP/2K x64:
 RtHDMX.sys : 5.10.0.5413
 XP/2K x86:
 RtHDM.sys : 5.10.0.5413

Driver Setup Program : 2.44

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111
 Package file version (kb888111.exe) : 6.1.22.0
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.75

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix

1.) Customization.

For New architecture:

1.) Customization .

CPL :

1.) Customization.

```

Windows 2000/XP : -----
Windows 2000/XP :
WDM driver for Win2000/WinXP      : 5.10.0.5473
WDM driver for Winx64             : 5.10.0.5473
Realtek Soundman                  : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtlCpl)   : 1.0.1.65
Realtek Sound Effect Manager(RTHDCPL)  : 2.1.5.2
Alcwzrd.exe                       : 1.1.0.36
SkyTel.exe                         : 2.0.1.20
Vista driver : -----
Vista driver for x86              : 6.0.1.5473
RtHDVCpl.exe                     : 1.0.0.88
RtkAPO.dll                        : 11.0.6000.44
RtkPgExt.dll                      : 6.0.6000.29
RTCOMDLL.dll                     : 2.0.0.79
RtlCPAPI.dll                      : 1.0.1.6
RTSndMgr.cpl                      : 1.0.0.6
RtkCoInst.dll                    : 1.0.1.7
SRSTSXT.dll                       : 3.2.0.0
SRSWOW.dll                        : 1.1.3.0
SRSHP360.dll                      : 1.0.1.0
SRSTSHD.dll                       : 1.1.4.0
RtkApoApi.dll                    : 1.0.0.2
Vista driver for x64              : 6.0.1.5473
RAVCpl64.exe                     : 1.0.0.88
RtkAPO64.dll                      : 11.0.6000.44
RtPgEx64.dll                     : 6.0.6000.29
RTCOMDLL.dll                     : 2.0.0.79
RtlCPAPI.dll                      : 1.0.1.6
RTSnMg64.cpl                     : 1.0.0.6
RtkCoInst.dll                    : 1.0.1.7
SRSTSX64.dll                     : 3.2.0.0
SRSWOW64.dll                     : 1.1.3.0
SRSHP64.dll                      : 1.0.1.0
SRSTSH64.dll                     : 1.1.4.0
RtkApi64.dll                     : 1.0.0.2
HDMI Driver : -----
Vista x64:
RtHDMVX.sys                       : 6.0.1.5413
RtkHDM64.dll                      : 6.0.6000.37
RHDMEx64.dll                      : 6.0.6000.25
Vista x86:
RtHDMV.sys                        : 6.0.1.5413
RtkHDM.dll                        : 6.0.6000.37
RHDMExt.dll                       : 6.0.6000.25
XP/2K x64:
RtHDMX.sys                        : 5.10.0.5413
XP/2K x86:
RtHDM.sys                         : 5.10.0.5413
Driver Setup Program               : 2.42

```

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.74

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64

Readme.txt

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization .

CPL :

- 1.) Customization.

Windows 2000/XP : -----
Windows 2000/XP :
WDM driver for Win2000/WinXP : 5.10.0.5470
WDM driver for Winx64 : 5.10.0.5470
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.65
Realtek Sound Effect Manager(RTHDCPL) : 2.1.5.2
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 2.0.1.20
Vista driver : -----
Vista driver for x86 : 6.0.1.5470
RtHdVCpl.exe : 1.0.0.87
RtkAPO.dll : 11.0.6000.44
RtkPgExt.dll : 6.0.6000.28
RTCOMDLL.dll : 2.0.0.79
RtlCPAPI.dll : 1.0.1.6
RTSndMgr.cpl : 1.0.0.6
RtkCoInst.dll : 1.0.1.7
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.1.3.0
SRSHP360.dll : 1.0.1.0
SRSTSHD.dll : 1.1.4.0
RtkApoApi.dll : 1.0.0.2
Vista driver for x64 : 6.0.1.5470
RAVCpl64.exe : 1.0.0.87
RtkAPO64.dll : 11.0.6000.44
RtPgEx64.dll : 6.0.6000.28
RTCOMDLL.dll : 2.0.0.79
RtlCPAPI.dll : 1.0.1.6
RTSnMg64.cpl : 1.0.0.6
RtkCoInst.dll : 1.0.1.7
SRSTSx64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
SRSHP64.dll : 1.0.1.0
SRSTSH64.dll : 1.1.4.0
RtkApi64.dll : 1.0.0.2
HDMI Driver : -----
Vista x64:
RtHDMVX.sys : 6.0.1.5413
RtkHDM64.dll : 6.0.6000.37
RHDMEx64.dll : 6.0.6000.25
Vista x86:
RtHDMV.sys : 6.0.1.5413
RtkHDM.dll : 6.0.6000.37
RHDMExt.dll : 6.0.6000.25
XP/2K x64:
RtHDMX.sys : 5.10.0.5413
XP/2K x86:
RtHDM.sys : 5.10.0.5413
Driver Setup Program : 2.40

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.73

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268

Readme.txt

3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization .

CPL :

- 1.) Customization.

Windows 2000/XP : -----

Windows 2000/XP :
WDM driver for Win2000/WinXP : 5.10.0.5464
WDM driver for Winx64 : 5.10.0.5464
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.65
Realtek Sound Effect Manager(RTHDCPL) : 2.1.4.9
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 2.0.1.20

Vista driver : -----

Vista driver for x86 : 6.0.1.5464
RtHdVcpl.exe : 1.0.0.84
RtkAPO.dll : 11.0.6000.43
RtkPgExt.dll : 6.0.6000.27
RTCOMDLL.dll : 2.0.0.76
RtlCPAPI.dll : 1.0.1.6
RTSndMgr.cpl : 1.0.0.6
RtkCoInst.dll : 1.0.1.7
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.1.3.0
SRSHP360.dll : 1.0.1.0
SRSTSHD.dll : 1.1.4.0
RtkApoApi.dll : 1.0.0.2
Vista driver for x64 : 6.0.1.5464
RAVCpl64.exe : 1.0.0.84
RtkAPO64.dll : 11.0.6000.43
RtPgEx64.dll : 6.0.6000.27
RTCOMDLL.dll : 2.0.0.76
RtlCPAPI.dll : 1.0.1.6
RTSnMg64.cpl : 1.0.0.6
RtkCoInst.dll : 1.0.1.7
SRSTSx64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
SRSHP64.dll : 1.0.1.0
SRSTSH64.dll : 1.1.4.0
RtkApi64.dll : 1.0.0.2

HDM Driver : -----

Vista x64:
RtHDMVX.sys : 6.0.1.5413
RtkHDM64.dll : 6.0.6000.37
RHDMEx64.dll : 6.0.6000.25
Vista x86:
RtHDMV.sys : 6.0.1.5413
RtkHDM.dll : 6.0.6000.37
RHDMExt.dll : 6.0.6000.25
XP/2K x64:
RtHDMX.sys : 5.10.0.5413
XP/2K x86:
RtHDM.sys : 5.10.0.5413

Driver Setup Program : 2.38

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.72

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268

Readme.txt

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization .

CPL :

- 1.) Customization.

Windows 2000/XP : -----

Windows 2000/XP :

| | |
|--------------------------------------------|---------------|
| WDM driver for Win2000/WinXP | : 5.10.0.5449 |
| WDM driver for Winx64 | : 5.10.0.5449 |
| Realtek Soundman | : 1.0.0.30 |
| Realtek Sound Effect Manager(ALSndMgr.cpl) | : 1.0.0.10 |
| Realtek Sound Effect Manager(RTSndMgr.cpl) | : 1.0.0.9 |
| Realtek Sound Effect Manager(RtlCpl) | : 1.0.1.65 |
| Realtek Sound Effect Manager(RTHDCPL) | : 2.1.4.2 |
| Alcwzrd.exe | : 1.1.0.36 |
| SkyTel.exe | : 2.0.1.19 |

Vista driver : -----

| | |
|----------------------|----------------|
| Vista driver for x86 | : 6.0.1.5449 |
| RtHdVcpl.exe | : 1.0.0.73 |
| RtkAPO.dll | : 11.0.6000.41 |
| RtkPgExt.dll | : 6.0.6000.27 |
| RTCOMDLL.dll | : 2.0.0.76 |
| RtlCPAPI.dll | : 1.0.1.6 |
| RTSndMgr.cpl | : 1.0.0.6 |
| RtkCoInst.dll | : 1.0.1.7 |
| SRSTSXT.dll | : 3.2.0.0 |
| SRSWOW.dll | : 1.1.2.0 |
| SRSHP360.dll | : 1.0.1.0 |
| SRSTSHD.dll | : 1.1.4.0 |
| RtkApoApi.dll | : 1.0.0.2 |
| Vista driver for x64 | : 6.0.1.5449 |
| RAVCpl64.exe | : 1.0.0.73 |
| RtkAPO64.dll | : 11.0.6000.41 |
| RtkPgEx64.dll | : 6.0.6000.27 |
| RTCOMDLL.dll | : 2.0.0.76 |
| RtlCPAPI.dll | : 1.0.1.6 |
| RTSnMg64.cpl | : 1.0.0.6 |
| RtkCoInst.dll | : 1.0.1.7 |
| SRSTSx64.dll | : 3.2.0.0 |
| SRSWOW64.dll | : 1.1.2.0 |
| SRSHP64.dll | : 1.0.1.0 |
| SRSTSH64.dll | : 1.1.4.0 |
| RtkApi64.dll | : 1.0.0.2 |

HDMI Driver : -----

| | |
|--------------|---------------|
| Vista x64: | |
| RtHDMVX.sys | : 6.0.1.5413 |
| RtkHDM64.dll | : 6.0.6000.37 |
| RHDMEx64.dll | : 6.0.6000.25 |
| Vista x86: | |
| RtHDMV.sys | : 6.0.1.5413 |
| RtkHDM.dll | : 6.0.6000.37 |
| RHDMExt.dll | : 6.0.6000.25 |
| XP/2K x64: | |
| RtHDMX.sys | : 5.10.0.5413 |
| XP/2K x86: | |
| RtHDM.sys | : 5.10.0.5413 |

Driver Setup Program : 2.36

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.71

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

Readme.txt

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization .

CPL :

- 1.) Customization.

Windows 2000/XP : -----

| | |
|--------------------------------------------|---------------|
| WDM driver for Win2000/WinXP | : 5.10.0.5443 |
| WDM driver for Winx64 | : 5.10.0.5443 |
| Realtek Soundman | : 1.0.0.30 |
| Realtek Sound Effect Manager(ALSndMgr.cpl) | : 1.0.0.10 |
| Realtek Sound Effect Manager(RTSndMgr.cpl) | : 1.0.0.9 |
| Realtek Sound Effect Manager(RtlCpl) | : 1.0.1.65 |
| Realtek Sound Effect Manager(RTHDCPL) | : 2.1.4.2 |
| Alcwzrd.exe | : 1.1.0.36 |
| SkyTel.exe | : 2.0.1.19 |

Vista driver : -----

| | |
|----------------------|----------------|
| Vista driver for x86 | : 6.0.1.5443 |
| RtHDVCpl.exe | : 1.0.0.73 |
| RtkAPO.dll | : 11.0.6000.40 |
| RtkPgExt.dll | : 6.0.6000.27 |
| RTCOMDLL.dll | : 2.0.0.74 |
| RtlCPAPI.dll | : 1.0.1.6 |
| RTSndMgr.cpl | : 1.0.0.6 |
| RtkCoInst.dll | : 1.0.1.7 |
| SRSTSXT.dll | : 3.2.0.0 |
| SRSWOW.dll | : 1.1.2.0 |
| SRSHP360.dll | : 1.0.1.0 |
| SRSTSHD.dll | : 1.1.4.0 |
| RtkApoApi.dll | : 1.0.0.2 |
| Vista driver for x64 | : 6.0.1.5443 |
| RAVCpl64.exe | : 1.0.0.73 |
| RtkAPO64.dll | : 11.0.6000.40 |
| RtPgEx64.dll | : 6.0.6000.27 |
| RTCOMDLL.dll | : 2.0.0.74 |
| RtlCPAPI.dll | : 1.0.1.6 |
| RTSnMg64.cpl | : 1.0.0.6 |
| RtkCoInst.dll | : 1.0.1.7 |
| SRSTSX64.dll | : 3.2.0.0 |
| SRSWOW64.dll | : 1.1.2.0 |
| SRSHP64.dll | : 1.0.1.0 |
| SRSTSH64.dll | : 1.1.4.0 |
| RtkApi64.dll | : 1.0.0.2 |

HDMI Driver : -----

| | |
|--------------|---------------|
| Vista x64: | |
| RtHDMVX.sys | : 6.0.1.5413 |
| RtkHDM64.dll | : 6.0.6000.37 |
| RHDMEx64.dll | : 6.0.6000.25 |
| Vista x86: | |
| RtHDMV.sys | : 6.0.1.5413 |
| RtkHDM.dll | : 6.0.6000.37 |
| RHDMExt.dll | : 6.0.6000.25 |
| XP/2K x64: | |
| RtHDMX.sys | : 5.10.0.5413 |
| XP/2K x86: | |
| RtHDM.sys | : 5.10.0.5413 |

Driver Setup Program : 2.36

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.70

Readme.txt

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization .

CPL :

- 1.) Customization.

| | |
|--------------------------------------------|----------------|
| Windows 2000/XP : | ----- |
| WDM driver for Win2000/WinXP | : 5.10.0.5436 |
| WDM driver for Winx64 | : 5.10.0.5436 |
| Realtek Soundman | : 1.0.0.30 |
| Realtek Sound Effect Manager(ALSndMgr.cpl) | : 1.0.0.10 |
| Realtek Sound Effect Manager(RTSndMgr.cpl) | : 1.0.0.9 |
| Realtek Sound Effect Manager(RtlCpl) | : 1.0.1.65 |
| Realtek Sound Effect Manager(RTHDCPL) | : 2.1.3.9 |
| Alcwzrd.exe | : 1.1.0.36 |
| SkyTel.exe | : 2.0.1.19 |
| Vista driver : | ----- |
| Vista driver for x86 | : 6.0.1.5436 |
| RtHDVCpl.exe | : 1.0.0.69 |
| RtkAPO.dll | : 11.0.6000.38 |
| RtkPgExt.dll | : 6.0.6000.27 |
| RTCOMDLL.dll | : 2.0.0.74 |
| RtlCPAPI.dll | : 1.0.1.6 |
| RTSndMgr.cpl | : 1.0.0.5 |
| RtkCoInst.dll | : 1.0.1.5 |
| SRSTSXT.dll | : 3.2.0.0 |
| SRSWOW.dll | : 1.1.2.0 |
| SRSHP360.dll | : 1.0.1.0 |
| SRSTSHD.dll | : 1.1.4.0 |
| RtkApoApi.dll | : 1.0.0.2 |
| Vista driver for x64 | : 6.0.1.5436 |
| RAVCpl64.exe | : 1.0.0.69 |
| RtkAPO64.dll | : 11.0.6000.38 |
| RtkPgEx64.dll | : 6.0.6000.27 |
| RTCOMDLL.dll | : 2.0.0.74 |
| RtlCPAPI.dll | : 1.0.1.6 |
| RTSnMg64.cpl | : 1.0.0.5 |
| RtkCoInst.dll | : 1.0.1.5 |
| SRSTSx64.dll | : 3.2.0.0 |
| SRSWOW64.dll | : 1.1.2.0 |
| SRSHP64.dll | : 1.0.1.0 |
| SRSTSH64.dll | : 1.1.4.0 |
| RtkApi64.dll | : 1.0.0.2 |
| HDM Driver : | ----- |
| Vista x64: | |
| RtHDMVX.sys | : 6.0.1.5413 |
| RtkHDM64.dll | : 6.0.6000.37 |
| RHDMEx64.dll | : 6.0.6000.25 |
| Vista x86: | |
| RtHDMV.sys | : 6.0.1.5413 |
| RtkHDM.dll | : 6.0.6000.37 |
| RHDMExt.dll | : 6.0.6000.25 |
| XP/2K x64: | |
| RtHDMX.sys | : 5.10.0.5413 |
| XP/2K x86: | |
| RtHDM.sys | : 5.10.0.5413 |
| Driver Setup Program | : 2.35 |

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Readme.txt

Driver Package R1.69

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization .

CPL :

- 1.) Customization.

Windows 2000/XP :

```
-----
WDM driver for Win2000/WinXP      : 5.10.0.5433
WDM driver for Winx64             : 5.10.0.5433
Realtek Soundman                  : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtlCpl)      : 1.0.1.65
Realtek Sound Effect Manager(RTHDCPL)     : 2.1.3.6
Alcwzrd.exe                       : 1.1.0.36
SkyTel.exe                         : 2.0.1.17
-----
```

Vista driver :

```
-----
Vista driver for x86              : 6.0.1.5433
RtHDVCpl.exe                     : 1.0.0.68
RtkAPO.dll                        : 11.0.6000.38
RtkPgExt.dll                      : 6.0.6000.27
RTCOMDLL.dll                     : 2.0.0.74
RtlCPAPI.dll                     : 1.0.1.6
RTSndMgr.cpl                      : 1.0.0.5
RtkCoInst.dll                    : 1.0.1.5
SRSTSXT.dll                       : 3.2.0.0
SRSWOW.dll                        : 1.1.2.0
SRSHP360.dll                      : 1.0.1.0
SRSTSHD.dll                       : 1.1.4.0
RtkApoApi.dll                     : 1.0.0.2
Vista driver for x64             : 6.0.1.5433
RAVCpl64.exe                     : 1.0.0.68
RtkAPO64.dll                      : 11.0.6000.38
RtPgEx64.dll                      : 6.0.6000.27
RTCOMDLL.dll                     : 2.0.0.74
RtlCPAPI.dll                     : 1.0.1.6
RTSnMg64.cpl                      : 1.0.0.5
RtkCoInst.dll                    : 1.0.1.5
SRSTSX64.dll                      : 3.2.0.0
SRSWOW64.dll                      : 1.1.2.0
SRSHP64.dll                       : 1.0.1.0
SRSTSH64.dll                      : 1.1.4.0
RtkApi64.dll                      : 1.0.0.2
-----
```

HDMI Driver :

```
-----
Vista x64:
RtHDMVX.sys                       : 6.0.1.5413
RtkHDM64.dll                       : 6.0.6000.37
RHDMEx64.dll                       : 6.0.6000.25
Vista x86:
RtHDMV.sys                         : 6.0.1.5413
RtkHDM.dll                         : 6.0.6000.37
RHDMExt.dll                        : 6.0.6000.25
XP/2K x64:
RtHDMX.sys                         : 5.10.0.5413
XP/2K x86:
RtHDM.sys                          : 5.10.0.5413
-----
```

Driver Setup Program : 2.34

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111
 Package file version (kb888111.exe) : 6.1.22.0
 Hdaudio.sys version : 5.10.00.5013

Readme.txt

//=====

Driver Package R1.68

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization .

CPL :

- 1.) Customization.

| | |
|--------------------------------------------|----------------|
| Windows 2000/XP : | ----- |
| WDM driver for Win2000/WinXP | : 5.10.0.5413 |
| WDM driver for Winx64 | : 5.10.0.5413 |
| Realtek Soundman | : 1.0.0.30 |
| Realtek Sound Effect Manager(ALSndMgr.cpl) | : 1.0.0.10 |
| Realtek Sound Effect Manager(RTSndMgr.cpl) | : 1.0.0.9 |
| Realtek Sound Effect Manager(RtlCpl) | : 1.0.1.65 |
| Realtek Sound Effect Manager(RTHDCPL) | : 2.1.3.2 |
| Alcwzrd.exe | : 1.1.0.36 |
| SkyTel.exe | : 2.0.1.12 |
| Vista driver : | ----- |
| Vista driver for x86 | : 6.0.1.5413 |
| RtHdVcpl.exe | : 1.0.0.60 |
| RtkAPO.dll | : 11.0.6000.37 |
| RtkPgExt.dll | : 6.0.6000.25 |
| RTCOMDLL.dll | : 2.0.0.73 |
| RtlCPAPI.dll | : 1.0.1.6 |
| RTSndMgr.cpl | : 1.0.0.5 |
| RtkCoInst.dll | : 1.0.1.2 |
| SRSTSXT.dll | : 3.2.0.0 |
| SRSWOW.dll | : 1.1.2.0 |
| SRSHP360.dll | : 1.0.1.0 |
| SRSTSHD.dll | : 1.1.3.0 |
| RtkApoApi.dll | : 1.0.0.2 |
| Vista driver for x64 | : 6.0.1.5413 |
| RAVCpl64.exe | : 1.0.0.60 |
| RtkAPO64.dll | : 11.0.6000.37 |
| RtkPgEx64.dll | : 6.0.6000.25 |
| RTCOMDLL.dll | : 2.0.0.73 |
| RtlCPAPI.dll | : 1.0.1.6 |
| RTSnMg64.cpl | : 1.0.0.5 |
| RtkCoInst.dll | : 1.0.1.2 |
| SRSTSx64.dll | : 3.2.0.0 |
| SRSWOW64.dll | : 1.1.2.0 |
| SRSHP64.dll | : 1.0.1.0 |
| SRSTSH64.dll | : 1.1.3.0 |
| RtkApi64.dll | : 1.0.0.2 |
| HDM Driver : | ----- |
| Vista x64: | |
| RtHDMVX.sys | : 6.0.1.5413 |
| RtkHDM64.dll | : 6.0.6000.37 |
| RHDMEx64.dll | : 6.0.6000.25 |
| Vista x86: | |
| RtHDMV.sys | : 6.0.1.5413 |
| RtkHDM.dll | : 6.0.6000.37 |
| RHDMExt.dll | : 6.0.6000.25 |
| XP/2K x64: | |
| RtHDMX.sys | : 5.10.0.5413 |
| XP/2K x86: | |
| RtHDM.sys | : 5.10.0.5413 |
| Driver Setup Program | : 2.33 |

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111

Package file version (kb888111.exe) : 6.1.22.0

Readme.txt

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.67

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/Wi nXP/Wi n2000/Wi n2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization .

CPL :

- 1.) Customization.

Windows 2000/XP : -----

| | |
|---------------------------------------------|---------------|
| WDM driver for Win2000/Wi nXP | : 5.10.0.5413 |
| WDM driver for Wi nx64 | : 5.10.0.5413 |
| Realtek Soundman | : 1.0.0.30 |
| Realtek Sound Effect Manager(ALSndMgr. cpl) | : 1.0.0.10 |
| Realtek Sound Effect Manager(RTSndMgr. cpl) | : 1.0.0.9 |
| Realtek Sound Effect Manager(RtlCpl) | : 1.0.1.65 |
| Realtek Sound Effect Manager(RTHDCPL) | : 2.1.3.2 |
| Alcwzrd.exe | : 1.1.0.36 |
| SkyTel.exe | : 2.0.1.12 |

Vista driver : -----

| | |
|----------------------|----------------|
| Vista driver for x86 | : 6.0.1.5413 |
| RtHDVCpl.exe | : 1.0.0.60 |
| RtkAPO.dll | : 11.0.6000.37 |
| RtkPgExt.dll | : 6.0.6000.25 |
| RTCOMDLL.dll | : 2.0.0.73 |
| RtlCPAPI.dll | : 1.0.1.6 |
| RTSndMgr.cpl | : 1.0.0.5 |
| RtkCoInst.dll | : 1.0.1.2 |
| SRSTSXT.dll | : 3.2.0.0 |
| SRSWOW.dll | : 1.1.2.0 |
| SRSHP360.dll | : 1.0.1.0 |
| SRSTSHD.dll | : 1.1.3.0 |
| RtkApoApi.dll | : 1.0.0.2 |
| Vista driver for x64 | : 6.0.1.5413 |
| RAVCpl64.exe | : 1.0.0.60 |
| RtkAPO64.dll | : 11.0.6000.37 |
| RtkPgEx64.dll | : 6.0.6000.25 |
| RTCOMDLL.dll | : 2.0.0.73 |
| RtlCPAPI.dll | : 1.0.1.6 |
| RTSnMg64.cpl | : 1.0.0.5 |
| RtkCoInst.dll | : 1.0.1.2 |
| SRSTSX64.dll | : 3.2.0.0 |
| SRSWOW64.dll | : 1.1.2.0 |
| SRSHP64.dll | : 1.0.1.0 |
| SRSTSH64.dll | : 1.1.3.0 |
| RtkApi64.dll | : 1.0.0.2 |

HDMI Driver : -----

| | |
|--------------|---------------|
| Vista x64: | |
| RtHDM.VX.sys | : 6.0.1.5368 |
| RtkHDM64.dll | : 6.0.6000.26 |
| RHDMEx64.dll | : 6.0.6000.20 |
| Vista x86: | |
| RtHDM.V.sys | : 6.0.1.5368 |
| RtkHDM.dll | : 6.0.6000.26 |
| RHDMExt.dll | : 6.0.6000.20 |
| XP/2K x64: | |
| RtHDM.X.sys | : 5.10.0.5368 |
| XP/2K x86: | |
| RtHDM.sys | : 5.10.0.5368 |

Driver Setup Program : 2.32

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111

Readme.txt

Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.66

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Win2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization .

CPL :

- 1.) Customization.

Windows 2000/XP : -----

| | |
|--------------------------------------------|---------------|
| WDM driver for Win2000/WinXP | : 5.10.0.5404 |
| WDM driver for Winx64 | : 5.10.0.5404 |
| Realtek Soundman | : 1.0.0.30 |
| Realtek Sound Effect Manager(ALSndMgr.cpl) | : 1.0.0.10 |
| Realtek Sound Effect Manager(RTSndMgr.cpl) | : 1.0.0.9 |
| Realtek Sound Effect Manager(RtlCpl) | : 1.0.1.65 |
| Realtek Sound Effect Manager(RTHDCPL) | : 2.1.3.2 |
| Alcwzrd.exe | : 1.1.0.36 |
| SkyTel.exe | : 2.0.1.11 |

Vista driver : -----

| | |
|----------------------|----------------|
| Vista driver for x86 | : 6.0.1.5404 |
| RtHDVCpl.exe | : 1.0.0.54 |
| RtkAPO.dll | : 11.0.6000.35 |
| RtkPgExt.dll | : 6.0.6000.24 |
| RTCOMDLL.dll | : 2.0.0.72 |
| RtlCPAPI.dll | : 1.0.1.6 |
| RTSndMgr.cpl | : 1.0.0.5 |
| RtkCoInst.dll | : 1.0.1.1 |
| SRSTSXT.dll | : 3.2.0.0 |
| SRSWOW.dll | : 1.1.2.0 |
| SRSHP360.dll | : 1.0.0.0 |
| SRSTSHD.dll | : 1.1.2.0 |
| Vista driver for x64 | : 6.0.1.5404 |
| RAVCpl64.exe | : 1.0.0.54 |
| RtkAPO64.dll | : 11.0.6000.35 |
| RtkPgEx64.dll | : 6.0.6000.24 |
| RTCOMDLL.dll | : 2.0.0.72 |
| RtlCPAPI.dll | : 1.0.1.6 |
| RTSnMg64.cpl | : 1.0.0.5 |
| RtkCoInst.dll | : 1.0.1.1 |
| SRSTSX64.dll | : 3.2.0.0 |
| SRSWOW64.dll | : 1.1.2.0 |
| SRSHP64.dll | : 1.0.0.0 |
| SRSTSH64.dll | : 1.1.2.0 |

HDM Driver : -----

| | |
|--------------|---------------|
| Vista x64: | |
| RtHDM VX.sys | : 6.0.1.5368 |
| RtkHDM64.dll | : 6.0.6000.26 |
| RHDMEx64.dll | : 6.0.6000.20 |
| Vista x86: | |
| RtHDM V.sys | : 6.0.1.5368 |
| RtkHDM.dll | : 6.0.6000.26 |
| RHDMExt.dll | : 6.0.6000.20 |
| XP/2K x64: | |
| RtHDM X.sys | : 5.10.0.5368 |
| XP/2K x86: | |
| RtHDM.sys | : 5.10.0.5368 |

Driver Setup Program : 2.32

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0

Readme.txt

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.65

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization .

CPL :

- 1.) Customization.

Windows 2000/XP : -----

| | |
|--------------------------------------------|---------------|
| WDM driver for Win2000/WinXP | : 5.10.0.5397 |
| WDM driver for Winx64 | : 5.10.0.5397 |
| Realtek Soundman | : 1.0.0.30 |
| Realtek Sound Effect Manager(ALSndMgr.cpl) | : 1.0.0.10 |
| Realtek Sound Effect Manager(RTSndMgr.cpl) | : 1.0.0.9 |
| Realtek Sound Effect Manager(RtlCpl) | : 1.0.1.65 |
| Realtek Sound Effect Manager(RTHDCPL) | : 2.1.3.0 |
| Alcwzrd.exe | : 1.1.0.36 |
| SkyTel.exe | : 2.0.1.9 |

Vista driver : -----

| | |
|----------------------|----------------|
| Vista driver for x86 | : 6.0.1.5397 |
| RtHDVCpl.exe | : 1.0.0.50 |
| RtkAPO.dll | : 11.0.6000.32 |
| RtkPgExt.dll | : 6.0.6000.22 |
| RTCOMDLL.dll | : 2.0.0.70 |
| RtlCPAPI.dll | : 1.0.1.6 |
| RTSndMgr.cpl | : 1.0.0.5 |
| RtkCoInst.dll | : 1.0.1.1 |
| SRSTSXT.dll | : 3.2.0.0 |
| SRSWOW.dll | : 1.0.6.0 |
| Vista driver for x64 | : 6.0.1.5397 |
| RAVCpl64.exe | : 1.0.0.50 |
| RtkAPO64.dll | : 11.0.6000.32 |
| RtkPgEx64.dll | : 6.0.6000.22 |
| RTCOMDLL.dll | : 2.0.0.70 |
| RtlCPAPI.dll | : 1.0.1.6 |
| RTSnMg64.cpl | : 1.0.0.5 |
| RtkCoInst.dll | : 1.0.1.1 |
| SRSTSx64.dll | : 3.2.0.0 |
| SRSWOW64.dll | : 1.0.6.0 |

HDMI Driver : -----

| | |
|--------------|---------------|
| Vista x64: | |
| RtHDMVX.sys | : 6.0.1.5368 |
| RtkHDM64.dll | : 6.0.6000.26 |
| RHDMEx64.dll | : 6.0.6000.20 |
| Vista x86: | |
| RtHDMV.sys | : 6.0.1.5368 |
| RtkHDM.dll | : 6.0.6000.26 |
| RHDMExt.dll | : 6.0.6000.20 |
| XP/2K x64: | |
| RtHDMX.sys | : 5.10.0.5368 |
| XP/2K x86: | |
| RtHDM.sys | : 5.10.0.5368 |

Driver Setup Program : 2.31

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.64

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262,

Readme.txt

ALC268

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix

1.) Customization.

For New architecture:

1.) Customization .

CPL :

1.) Customization.

Windows 2000/XP :

WDM driver for Win2000/WinXP : 5.10.0.5391
WDM driver for Winx64 : 5.10.0.5391
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.65
Realtek Sound Effect Manager(RTHDCPL) : 2.1.2.9
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 2.0.1.7

Vista driver :

Vista driver for x86 : 6.0.1.5391
RtHdvcpl.exe : 1.0.0.46
RtkAPO.dll : 11.0.6000.31
RtkPgExt.dll : 6.0.6000.22
RTCOMDLL.dll : 2.0.0.69
RtlCPAPI.dll : 1.0.1.6
RTSndMgr.cpl : 1.0.0.5
RtkCoInst.dll : 1.0.0.12
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.0.6.0
Vista driver for x64 : 6.0.1.5391
RAVCpl64.exe : 1.0.0.46
RtkAPO64.dll : 11.0.6000.31
RtPgEx64.dll : 6.0.6000.22
RTCOMDLL.dll : 2.0.0.69
RtlCPAPI.dll : 1.0.1.6
RTSnMg64.cpl : 1.0.0.5
RtkCoInst.dll : 1.0.0.12
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.0.6.0

HDM Driver :

Vista x64:
RtHDMVX.sys : 6.0.1.5368
RtkHDM64.dll : 6.0.6000.26
RHDMEx64.dll : 6.0.6000.20
Vista x86:
RtHDMV.sys : 6.0.1.5368
RtkHDM.dll : 6.0.6000.26
RHDMExt.dll : 6.0.6000.20
XP/2K x64:
RtHDMX.sys : 5.10.0.5368
XP/2K x86:
RtHDM.sys : 5.10.0.5368

Driver Setup Program : 2.30

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.63

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC268

ALC268

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64

Readme.txt

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization .

CPL :

- 1.) Customization.

Windows 2000/XP : -----

| | |
|--------------------------------------------|---------------|
| WDM driver for Win2000/WinXP | : 5.10.0.5377 |
| WDM driver for Winx64 | : 5.10.0.5377 |
| Realtek Soundman | : 1.0.0.30 |
| Realtek Sound Effect Manager(ALSndMgr.cpl) | : 1.0.0.10 |
| Realtek Sound Effect Manager(RTSndMgr.cpl) | : 1.0.0.9 |
| Realtek Sound Effect Manager(RtlCpl) | : 1.0.1.64 |
| Realtek Sound Effect Manager(RTHDCPL) | : 2.1.2.4 |
| Alcwzrd.exe | : 1.1.0.36 |
| SkyTel.exe | : 1.0.0.0 |

Vista driver : -----

| | |
|----------------------|----------------|
| Vista driver for x86 | : 6.0.1.5386 |
| RtHDVCpl.exe | : 1.0.0.43 |
| RtkAPO.dll | : 11.0.6000.29 |
| RtkPgExt.dll | : 6.0.6000.22 |
| RTCOMDLL.dll | : 2.0.0.69 |
| RtlCPAPI.dll | : 1.0.1.6 |
| RTSndMgr.cpl | : 1.0.0.4 |
| RtkCoInst.dll | : 1.0.0.9 |
| SRSTSXT.dll | : 3.2.0.0 |
| SRSWOW.dll | : 1.0.6.0 |
| Vista driver for x64 | : 6.0.1.5386 |
| RAVCpl64.exe | : 1.0.0.43 |
| RtkAPO64.dll | : 11.0.6000.29 |
| RtkPgEx64.dll | : 6.0.6000.22 |
| RTCOMDLL.dll | : 2.0.0.69 |
| RtlCPAPI.dll | : 1.0.1.6 |
| RTSnMg64.cpl | : 1.0.0.4 |
| RtkCoInst.dll | : 1.0.0.9 |
| SRSTSX64.dll | : 3.2.0.0 |
| SRSWOW64.dll | : 1.0.6.0 |

HDMI Driver : -----

| | |
|--------------|---------------|
| Vista x64: | |
| RtHDMVX.sys | : 6.0.1.5368 |
| RtkHDM64.dll | : 6.0.6000.26 |
| RHDMEx64.dll | : 6.0.6000.20 |
| Vista x86: | |
| RtHDMV.sys | : 6.0.1.5368 |
| RtkHDM.dll | : 6.0.6000.26 |
| RHDMExt.dll | : 6.0.6000.20 |
| XP/2K x64: | |
| RtHDMX.sys | : 5.10.0.5368 |
| XP/2K x86: | |
| RtHDM.sys | : 5.10.0.5368 |

Driver Setup Program : 2.30

Windows 2000/XP Operate on :

- Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.62

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Customization.

For New architecture:

1.) Customization .

CPL :

1.) Customization.

```

Windows 2000/XP : -----
WDM driver for Win2000/WinXP      : 5.10.0.5377
WDM driver for Winx64             : 5.10.0.5377
Realtek Soundman                  : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtlCpl)   : 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL)  : 2.1.2.4
Alcwzrd.exe                       : 1.1.0.36
SkyTel.exe                         : 1.0.0.0
Vista driver : -----
Vista driver for x86              : 6.0.1.5384
RtHDVCpl.exe                     : 1.0.0.41
RtkAPO.dll                        : 11.0.6000.28
RtkPgExt.dll                      : 6.0.6000.21
RTCOMDLL.dll                     : 2.0.0.69
RtlCPAPI.dll                      : 1.0.1.6
RTSndMgr.cpl                      : 1.0.0.4
RtkCoInst.dll                    : 1.0.0.9
SRSTSXT.dll                       : 3.2.0.0
SRSWOW.dll                        : 1.0.6.0
Vista driver for x64             : 6.0.1.5384
RAVCpl64.exe                     : 1.0.0.41
RtkAPO64.dll                      : 11.0.6000.28
RtPgEx64.dll                     : 6.0.6000.21
RTCOMDLL.dll                     : 2.0.0.69
RtlCPAPI.dll                      : 1.0.1.6
RTSnMg64.cpl                     : 1.0.0.4
RtkCoInst.dll                    : 1.0.0.9
SRSTSX64.dll                     : 3.2.0.0
SRSWOW64.dll                     : 1.0.6.0
HDMI Driver : -----
Vista x64:
RtHDMVX.sys                       : 6.0.1.5368
RtkHDM64.dll                       : 6.0.6000.26
RHDME64.dll                        : 6.0.6000.20
Vista x86:
RtHDMV.sys                         : 6.0.1.5368
RtkHDM.dll                         : 6.0.6000.26
RHDMEExt.dll                       : 6.0.6000.20
XP/2K x64:
RtHDMX.sys                         : 5.10.0.5368
XP/2K x86:
RtHDM.sys                          : 5.10.0.5368

Driver Setup Program                : 2.30

```

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111
 Package file version (kb888111.exe) : 6.1.22.0
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.61

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Customization.

For New architecture:

1.) Customization .

CPL :

1.) Customization.

Readme.txt

Windows 2000/XP : -----
 WDM driver for Win2000/WinXP : 5.10.0.5377
 WDM driver for Winx64 : 5.10.0.5377
 Realtek Soundman : 1.0.0.30
 Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
 Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
 Realtek Sound Effect Manager(RtlCpl) : 1.0.1.64
 Realtek Sound Effect Manager(RTHDCPL) : 2.1.2.4
 Alcwzrd.exe : 1.1.0.36
 SkyTel.exe : 1.0.0.0

Vista driver : -----
 Vista driver for x86 : 6.0.1.5377
 RtHDVCpl.exe : 1.0.0.38
 RtkAPO.dll : 11.0.6000.26
 RtkPgExt.dll : 6.0.6000.20
 RTCOMDLL.dll : 2.0.0.68
 RtlCPAPI.dll : 1.0.1.5
 RTSndMgr.cpl : 1.0.0.4
 RtkCoInst.dll : 1.0.0.7
 SRSTSXT.dll : 3.2.0.0
 SRSWOW.dll : 1.0.6.0
 Vista driver for x64 : 6.0.1.5377
 RAVCpl64.exe : 1.0.0.38
 RtkAPO64.dll : 11.0.6000.26
 RtkPgEx64.dll : 6.0.6000.20
 RTCOMDLL.dll : 2.0.0.68
 RtlCPAPI.dll : 1.0.1.5
 RTSnMg64.cpl : 1.0.0.4
 RtkCoInst.dll : 1.0.0.7
 SRSTSX64.dll : 3.2.0.0
 SRSWOW64.dll : 1.0.6.0

HDMI Driver : -----
 Vista x64:
 RtHDMVX.sys : 6.0.1.5356
 RtkHDM64.dll : 6.0.6000.20
 RHDMEx64.dll : 6.0.6000.17
 Vista x86:
 RtHDMV.sys : 6.0.1.5356
 RtkHDM.dll : 6.0.6000.20
 RHDMExt.dll : 6.0.6000.17
 XP/2K x64:
 RtHDMX.sys : 5.10.0.5356
 XP/2K x86:
 RtHDM.sys : 5.10.0.5356
 Driver Setup Program : 2.30

Windows 2000/XP Operate on :
 Microsoft High Definition Audio Driver Package - KB888111
 Package file version (kb888111.exe) : 6.1.22.0
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.60

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft WindowsXP, Winnows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Customization.

For New architecture:
 1.) Customization .

CPL :
 1.) Customization.

Windows 2000/XP : -----
 WDM driver for Win2000/WinXP : 5.10.0.5366
 WDM driver for Winx64 : 5.10.0.5366
 Realtek Soundman : 1.0.0.30
 Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10

Readme.txt

```

Realtek Sound Effect Manager(RTSndMgr. cpl)      : 1.0.0.9
Realtek Sound Effect Manager(RtlCpl)            : 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL)          : 2.1.2.0
Alcwzrd.exe                                     : 1.1.0.36
SkyTel.exe                                      : 1.0.0.0
Vista driver : -----
Vista driver for x86                           : 6.0.1.5374
RtHdVcpl.exe                                   : 1.0.0.36
RtkAPO.dll                                     : 11.0.6000.25
RtkPgExt.dll                                   : 6.0.6000.20
RTCOMDLL.dll                                  : 2.0.0.66
RtlCPAPI.dll                                  : 1.0.1.5
RTSndMgr.cpl                                   : 1.0.0.4
RtkCoInst.dll                                 : 1.0.0.7
SRSTSXT.dll                                   : 3.2.0.0
SRSWOW.dll                                     : 1.0.6.0
Vista driver for x64                           : 6.0.1.5374
RAVCpl64.exe                                  : 1.0.0.36
RtkAPO64.dll                                  : 11.0.6000.25
RtPgEx64.dll                                  : 6.0.6000.20
RTCOMDLL.dll                                  : 2.0.0.65
RtlCPAPI.dll                                  : 1.0.1.5
RTSnMg64.cpl                                  : 1.0.0.4
RtkCoInst.dll                                 : 1.0.0.7
SRSTSX64.dll                                  : 3.2.0.0
SRSWOW64.dll                                  : 1.0.6.0
HDMI Driver : -----
Vista x64:
RtHDMVX.sys                                   : 6.0.1.5356
RtkHDM64.dll                                  : 6.0.6000.20
RHDMEx64.dll                                  : 6.0.6000.17
Vista x86:
RtHDMV.sys                                    : 6.0.1.5356
RtkHDM.dll                                    : 6.0.6000.20
RHDMExt.dll                                   : 6.0.6000.17
XP/2K x64:
RtHDMX.sys                                    : 5.10.0.5356
XP/2K x86:
RtHDM.sys                                     : 5.10.0.5356

Driver Setup Program                          : 2.28

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013
//=====
Driver Package R1.59
Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/Wi nXP/Wi n2000/Wi n2003 .
1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262,
ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD,
ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft WindowsXP, Winnows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
    1.) Customization.

For New architecture:
    1.) Customization .

CPL :
    1.) Customization.

Windows 2000/XP : -----
WDM driver for Win2000/Wi nXP                  : 5.10.0.5366
WDM driver for Wi nx64                        : 5.10.0.5366
Realtek Soundman                             : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr. cpl)   : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr. cpl)   : 1.0.0.9
Realtek Sound Effect Manager(RtlCpl)         : 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL)       : 2.1.2.0
Alcwzrd.exe                                   : 1.1.0.36
SkyTel.exe                                    : 1.0.0.0

```

Readme.txt

Vista driver : -----
 Vista driver for x86 : 6.0.1.5372
 RtHDVCpl.exe : 1.0.0.33
 RtkAPO.dll : 11.0.6000.25
 RtkPgExt.dll : 6.0.6000.20
 RTCOMDLL.dll : 2.0.0.66
 RtlCPAPI.dll : 1.0.1.5
 RTSndMgr.cpl : 1.0.0.4
 RtkCoInst.dll : 1.0.0.7
 SRSTSXT.dll : 3.2.0.0
 SRSWOW.dll : 1.0.6.0
 Vista driver for x64 : 6.0.1.5372
 RAVCpl64.exe : 1.0.0.33
 RtkAPO64.dll : 11.0.6000.25
 RtkPgEx64.dll : 6.0.6000.20
 RTCOMDLL.dll : 2.0.0.65
 RtlCPAPI.dll : 1.0.1.5
 RTSnMg64.cpl : 1.0.0.4
 RtkCoInst.dll : 1.0.0.7
 SRSTSX64.dll : 3.2.0.0
 SRSWOW64.dll : 1.0.6.0

HDMI Driver : -----
 Vista x64:
 RtHDMVX.sys : 6.0.1.5356
 RtkHDM64.dll : 6.0.6000.20
 RHDMEx64.dll : 6.0.6000.17
 Vista x86:
 RtHDMV.sys : 6.0.1.5356
 RtkHDM.dll : 6.0.6000.20
 RHDMEExt.dll : 6.0.6000.17
 XP/2K x64:
 RtHDMX.sys : 5.10.0.5356
 XP/2K x86:
 RtHDM.sys : 5.10.0.5356
 Driver Setup Program : 2.28

Windows 2000/XP Operate on :
 Microsoft High Definition Audio Driver Package - KB888111
 Package file version (kb888111.exe) : 6.1.22.0
 Hdaudio.sys version : 5.10.00.5013

//=====

- Driver Package R1.58
 Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/Wi nXP/Wi n2000/Wi n2003 .
 1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC268
 2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
 3. HDMI Device WHQL Support: ATI HDMI Devices
 4. OS Supporting: Microsoft WindowsXP, Widnows2000, Vista x86/x64
 5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
 6. Add/Fix
 1.) Customization.

For New architecture:
 1.) Customization .

CPL :
 1.) Customization.

Windows 2000/XP : -----
 WDM driver for Wi n2000/Wi nXP : 5.10.0.5366
 WDM driver for Wi nx64 : 5.10.0.5366
 Realtek Soundman : 1.0.0.30
 Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
 Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
 Realtek Sound Effect Manager(RtlCpl) : 1.0.1.64
 Realtek Sound Effect Manager(RTHDCPL) : 2.1.2.0
 Alcwzrd.exe : 1.1.0.36
 SkyTel.exe : 1.0.0.0
 Vista driver : -----
 Vista driver for x86 : 6.0.1.5371
 RtHDVCpl.exe : 1.0.0.32
 RtkAPO.dll : 11.0.6000.25
 RtkPgExt.dll : 6.0.6000.20

Readme.txt

RTCOMDLL.dll : 2.0.0.66
 RtlCPAPI.dll : 1.0.1.5
 RTSndMgr.cpl : 1.0.0.4
 RtkCoInst.dll : 1.0.0.7
 SRSTSXT.dll : 3.2.0.0
 SRSWOW.dll : 1.0.6.0
 Vista driver for x64 : 6.0.1.5371
 RAVCpl64.exe : 1.0.0.32
 RtkAPO64.dll : 11.0.6000.25
 RtkPgEx64.dll : 6.0.6000.20
 RTCOMDLL.dll : 2.0.0.65
 RtlCPAPI.dll : 1.0.1.5
 RTSndMgr64.cpl : 1.0.0.4
 RtkCoInst.dll : 1.0.0.7
 SRSTSX64.dll : 3.2.0.0
 SRSWOW64.dll : 1.0.6.0

HDMI Driver : -----

Vista x64:
 RtHDMVX.sys : 6.0.1.5356
 RtkHDM64.dll : 6.0.6000.20
 RHDME64.dll : 6.0.6000.17
 Vista x86:
 RtHDMV.sys : 6.0.1.5356
 RtkHDM.dll : 6.0.6000.20
 RHDMEExt.dll : 6.0.6000.17
 XP/2K x64:
 RtHDMX.sys : 5.10.0.5356
 XP/2K x86:
 RtHDM.sys : 5.10.0.5356

Driver Setup Program : 2.28

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111
 Package file version (kb888111.exe) : 6.1.22.0
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.57

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization .

CPL :

- 1.) Customization.

Windows 2000/XP : -----

WDM driver for Win2000/WinXP : 5.10.0.5366
 WDM driver for Winx64 : 5.10.0.5366
 Realtek Soundman : 1.0.0.30
 Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
 Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
 Realtek Sound Effect Manager(RtlCpl) : 1.0.1.64
 Realtek Sound Effect Manager(RTHDCPL) : 2.1.2.0
 Alcwzrd.exe : 1.1.0.36
 SkyTel.exe : 1.0.0.0

Vista driver : -----

Vista driver for x86 : 6.0.1.5361
 RtHDVCpl.exe : 1.0.0.27
 RtkAPO.dll : 11.0.6000.20
 RtkPgExt.dll : 6.0.6000.17
 RTCOMDLL.dll : 2.0.0.65
 RtlCPAPI.dll : 1.0.1.5
 RTSndMgr.cpl : 1.0.0.1
 RtkCoInst.dll : 1.0.0.6
 SRSTSXT.dll : 3.2.0.0

Readme.txt

SRSWOW.dll : 1.0.6.0
 Vista driver for x64 : 6.0.1.5361
 RAVCpl64.exe : 1.0.0.27
 RtkAPO64.dll : 11.0.6000.20
 RtpgExt64.dll : 6.0.6000.17
 RTCOMDLL.dll : 2.0.0.65
 RtlCPAPI.dll : 1.0.1.5
 RTSndMgr64.cpl : 1.0.0.1
 RtkCoInst.dll : 1.0.0.6
 SRSTSX64.dll : 3.2.0.0
 SRSWOW64.dll : 1.0.6.0

HDMI Driver : -----

Vista x64:
 RtHDMVX.sys : 6.0.1.5356
 RtkHDM64.dll : 6.0.6000.20
 RHDMEx64.dll : 6.0.6000.17
 Vista x86:
 RtHDMV.sys : 6.0.1.5356
 RtkHDM.dll : 6.0.6000.20
 RHDMExt.dll : 6.0.6000.17
 XP/2K x64:
 RtHDMX.sys : 5.10.0.5356
 XP/2K x86:
 RtHDM.sys : 5.10.0.5356
 Driver Setup Program : 2.27

Windows 2000/XP Operate on :
 Microsoft High Definition Audio Driver Package - KB888111
 Package file version (kb888111.exe) : 6.1.22.0
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.56

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
3. OS Supporting: Microsoft WindowsXP, Win2000, Vista x86/x64
4. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
5. Add/Fix
 - 1.) Customization.

For New architecture:
 1.) Customization .

CPL :
 1.) Customization.

Windows 2000/XP :
 WDM driver for Win2000/WinXP : 5.10.0.5345
 WDM driver for Winx64 : 5.10.0.5345
 Realtek Soundman : 1.0.0.30
 Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
 Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
 Realtek Sound Effect Manager(RtlCpl) : 1.0.1.64
 Realtek Sound Effect Manager(RTHDCPL) : 2.1.1.4
 Alcwzrd.exe : 1.1.0.36
 SkyTel.exe : 1.0.0.0
 Vista driver :
 Vista driver for x86 : 6.0.1.5361
 RtHDVCpl.exe : 1.0.0.27
 RtkAPO.dll : 11.0.6000.20
 RtkPgExt.dll : 6.0.6000.17
 RTCOMDLL.dll : 2.0.0.65
 RtlCPAPI.dll : 1.0.1.5
 RTSndMgr.cpl : 1.0.0.1
 RtkCoInst.dll : 1.0.0.6
 SRSTSXT.dll : 3.2.0.0
 SRSWOW.dll : 1.0.6.0
 Vista driver for x64 : 6.0.1.5361
 RAVCpl64.exe : 1.0.0.27
 RtkAPO64.dll : 11.0.6000.20
 RtpgExt64.dll : 6.0.6000.17
 RTCOMDLL.dll : 2.0.0.65

Readme.txt

RtlCPAPI.dll : 1.0.1.5
RTSnMg64.cpl : 1.0.0.1
RtkCoInst.dll : 1.0.0.6
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.0.6.0

Driver Setup Program : 2.27

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.55

1. Vista logo Codec Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC268
2. Windows 2000/XP logo Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
3. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
4. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
5. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization .

CPL :

- 1.) Customization.

Windows 2000/XP :

WDM driver for Win2000/WinXP : 5.10.0.5345
WDM driver for Winx64 : 5.10.0.5345
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL) : 2.1.1.4
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 1.0.0.0
Vista driver :
Vista driver for x86 : 6.0.1.5350
RtHdVCpl.exe : 1.0.0.21
RtkAPO.dll : 11.0.6000.16
RtkPgExt.dll : 6.0.6000.15
RTCOMDLL.dll : 2.0.0.65
RtlCPAPI.dll : 1.0.1.5
RTSnMgr.cpl : 1.0.0.1
RtkCoInst.dll : 1.0.0.3
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.0.6.0
Vista driver for x64 : 6.0.1.5350
RAVCpl64.exe : 1.0.0.21
RtkAPO64.dll : 11.0.6000.16
RtPgEx64.dll : 6.0.6000.15
RTCOMDLL.dll : 2.0.0.65
RtlCPAPI.dll : 1.0.1.5
RTSnMg64.cpl : 1.0.0.1
RtkCoInst.dll : 1.0.0.4
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.0.6.0

Driver Setup Program : 2.24

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.54

1. Vista logo Codec Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC268
2. Windows 2000/XP logo Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
3. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
4. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

5. Add/Fix
 1.) Customization.

For New architecture:
 1.) Customization .

CPL :
 1.) Customization.

Windows 2000/XP :
 WDM driver for Win2000/WinXP : 5.10.0.5345
 WDM driver for Winx64 : 5.10.0.5345
 Realtek Soundman : 1.0.0.30
 Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
 Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
 Realtek Sound Effect Manager(RtlCpl) : 1.0.1.64
 Realtek Sound Effect Manager(RTHDCPL) : 2.1.1.4
 Alcwzrd.exe : 1.1.0.36
 SkyTel.exe : 1.0.0.0
 Vista driver :
 Vista driver for x86 : 6.0.1.5334
 RtHdVCpl.exe : 1.0.0.11
 RtkAPO.dll : 11.0.5600.13
 RtkPgExt.dll : 6.0.5600.12
 RTCOMDLL.dll : 1.0.0.63
 RtlCPAPI.dll : 1.0.1.5
 RTSndMgr.cpl : 1.0.0.1
 RtkCoInst.dll : 1.0.0.2
 Vista driver for x64 : 6.0.1.5334
 RAVCpl64.exe : 1.0.0.11
 RtkAPO64.dll : 11.0.5600.13
 RtpgEx64.dll : 6.0.5600.12
 RTCOMDLL.dll : 1.0.0.63
 RtlCPAPI.dll : 1.0.1.5
 RTSnMg64.cpl : 1.0.0.1
 RtkCoInst.dll : 1.0.0.2

 Driver Setup Program : 2.23

Windows 2000/XP Operate on :
 Microsoft High Definition Audio Driver Package - KB888111
 Package file version (kb888111.exe) : 6.1.22.0
 Hdaudio.sys version : 5.10.00.5013

//=====

- Driver Package R1.53
 1. Vista logo Codec Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC268
 2. Windows 2000/XP logo Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
 3. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
 4. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
 5. Add/Fix
 1.) Customization.

For New architecture:
 1.) Customization .
 2.) Fixed issue -> DTM Test \ Hal timer issue for V5331 Vista driver (Potential risk).

CPL :
 1.) Customization.

Windows 2000/XP :
 WDM driver for Win2000/WinXP : 5.10.0.5324
 WDM driver for Winx64 : 5.10.0.5324
 Realtek Soundman : 1.0.0.30
 Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
 Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
 Realtek Sound Effect Manager(RtlCpl) : 1.0.1.64
 Realtek Sound Effect Manager(RTHDCPL) : 2.1.1.1
 Alcwzrd.exe : 1.1.0.36
 SkyTel.exe : 1.0.0.0
 Vista driver :
 Vista driver for x86 : 6.0.1.5334
 RtHdVCpl.exe : 1.0.0.11
 RtkAPO.dll : 11.0.5600.13

Readme.txt

RtkPgExt.dll : 6.0.5600.12
RTCOMDLL.dll : 1.0.0.63
RtlCPAPI.dll : 1.0.1.5
RTSndMgr.cpl : 1.0.0.1
RtkColnst.dll : 1.0.0.2
Vista driver for x64 : 6.0.1.5334
RAVCpl64.exe : 1.0.0.11
RtkAPO64.dll : 11.0.5600.13
RtPgEx64.dll : 6.0.5600.12
RTCOMDLL.dll : 1.0.0.63
RtlCPAPI.dll : 1.0.1.5
RTSndMgr64.cpl : 1.0.0.1
RtkColnst.dll : 1.0.0.2

Driver Setup Program : 2.21

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.52

1. Vista logo Codec Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC268
2. Windows 2000/XP logo Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
3. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
4. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
5. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization .
- 2.) Known issue -> DTM Test \ Hal timer issue for V5331 Vista driver (Potential risk).

CPL :

- 1.) Customization.

Windows 2000/XP :

WDM driver for Win2000/WinXP : 5.10.0.5324
WDM driver for Winx64 : 5.10.0.5324
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL) : 2.1.1.1
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 1.0.0.0
Vista driver :
Vista driver for x86 : 6.0.1.5331
RtHDVCpl.exe : 1.0.0.9
RtkAPO.dll : 11.0.5600.13
RtkPgExt.dll : 6.0.5600.12
RTCOMDLL.dll : 1.0.0.63
RtlCPAPI.dll : 1.0.0.7
RTSndMgr.cpl : 1.0.0.1
RtkColnst.dll : 1.0.0.1
Vista driver for x64 : 6.0.1.5331
RAVCpl64.exe : 1.0.0.9
RtkAPO64.dll : 11.0.5600.13
RtPgEx64.dll : 6.0.5600.12
RTCOMDLL.dll : 1.0.0.63
RtlCPAPI.dll : 1.0.0.7
RTSndMgr64.cpl : 1.0.0.1
RtkColnst.dll : 1.0.0.1

Driver Setup Program : 2.20

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.51

1. Vista logo Codec Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260,

Readme.txt

- ALC262, ALC268
2. Windows 2000/XP logo Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD,
ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
3. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
4. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
5. Add/Fix
1.) Customization.

For New architecture:

- 1.) Customization .

CPL :

- 1.) Customization.

Windows 2000/XP :
WDM driver for Win2000/WinXP : 5.10.0.5324
WDM driver for Winx64 : 5.10.0.5324
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL) : 2.1.1.1
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 1.0.0.0
Vista driver :
Vista driver for x86 : 6.0.1.5322
RtHDVCpl.exe : 1.0.0.7
RtkAPO.dll : 11.0.5600.13
RtkPgExt.dll : 6.0.5600.12
RTCOMDLL.dll : 1.0.0.63
RtlCPAPI.dll : 1.0.0.7
RTSndMgr.cpl : 1.0.0.1
Vista driver for x64 : 6.0.1.5322
RAVCpl64.exe : 1.0.0.7
RtkAPO64.dll : 11.0.5600.13
RtPgEx64.dll : 6.0.5600.12
RTCOMDLL.dll : 1.0.0.63
RtlCPAPI.dll : 1.0.0.7
RTSnMg64.cpl : 1.0.0.1
Driver Setup Program : 2.20

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.50

1. Vista logo Codec Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260,
ALC262, ALC268
2. Windows 2000/XP logo Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD,
ALC660, ALC662, ALC260, ALC262, ALC268
3. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
4. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
5. Add/Fix
1.) Customization.

For New architecture:

- 1.) Customization .

CPL :

- 1.) Customization.

Windows 2000/XP :
WDM driver for Win2000/WinXP : 5.10.0.5319
WDM driver for Winx64 : 5.10.0.5319
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL) : 2.1.0.8
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 1.0.0.0
Vista driver :
Vista driver for x86 : 6.0.1.5322
RtHDVCpl.exe : 1.0.0.7

Readme.txt

RtkAPO.dll : 11.0.5600.13
RtkPgExt.dll : 6.0.5600.12
RTCOMDLL.dll : 1.0.0.63
RtlCPAPI.dll : 1.0.0.7
RTSndMgr.cpl : 1.0.0.1
Vista driver for x64 : 6.0.1.5322
RAVCpl64.exe : 1.0.0.7
RtkAPO64.dll : 11.0.5600.13
RtPgEx64.dll : 6.0.5600.12
RTCOMDLL.dll : 1.0.0.63
RtlCPAPI.dll : 1.0.0.7
RTSndMgr64.cpl : 1.0.0.1
Driver Setup Program : 2.19

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.49

1. Vista logo Codec Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC268
2. Windows 2000/XP logo Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC268
3. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
4. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
5. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization .

CPL :

- 1.) Customization.

Windows 2000/XP :

WDM driver for Win2000/WinXP : 5.10.0.5319
WDM driver for Winx64 : 5.10.0.5319
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL) : 2.1.0.8
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 1.0.0.0
Vista driver :
Vista driver for x86 : 6.0.1.5317
RtHDVCpl.exe : 1.0.0.6
RtkAPO.dll : 11.0.5600.12
RtkPgExt.dll : 6.0.5600.12
RTCOMDLL.dll : 1.0.0.63
RtlCPAPI.dll : 1.0.0.7
RTSndMgr.cpl : 1.0.0.1
Vista driver for x64 : 6.0.1.5317
RAVCpl64.exe : 1.0.0.6
RtkAPO64.dll : 11.0.5600.12
RtPgEx64.dll : 6.0.5600.12
RTCOMDLL.dll : 1.0.0.63
RtlCPAPI.dll : 1.0.0.7
RTSndMgr64.cpl : 1.0.0.1
Driver Setup Program : 2.19

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.48

Vista driver Version: 5.10.0.5317

1. Vista logo Codec Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC268
2. OS Supporting: Microsoft Windows Vista x86/x64

Vista driver for x86 : 6.10.0.5317
RtHDVCpl.exe : 1.0.0.6

```

Readme.txt
RtkAPO.dll : 11.0.5600.12
RtkPgExt.dll : 6.0.5600.12
RTCOMDLL.dll : 1.0.0.63
RtlCPAPI.dll : 1.0.0.7
RTSndMgr.cpl : 1.0.0.1
Vista driver for x64 : 6.10.0.5317
RAVCpl64.exe : 1.0.0.6
RtkAPO64.dll : 11.0.5600.12
RtPgEx64.dll : 6.0.5600.12
RTCOMDLL.dll : 1.0.0.63
RtlCPAPI.dll : 1.0.0.7
RTSndMgr64.cpl : 1.0.0.1
Driver Setup Program : 2.19
//=====
Driver Package R1.47
RtkHDAud.sys Version: 5.10.0.5296
1. Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861, ALC861VD, ALC660, ALC260,
ALC262, ALC268
2. OS Supporting: Microsoft WindowsXP, Windows2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
    1.) Customization.

For New architecture:
    1.) Customization .

CPL :
    1.) Customization.

WDM driver for Win2000/WinXP : 5.10.0.5296
WDM driver for Winx64 : 5.10.0.5296
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL) : 2.0.9.8
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 1.0.0.0
Driver Setup Program : 2.18

Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013
//=====
Driver Package R1.46
RtkHDAud.sys Version: 5.10.0.5294
1. Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861, ALC861VD, ALC660, ALC260,
ALC262, ALC268
2. OS Supporting: Microsoft WindowsXP, Windows2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
    1.) Customization.

For New architecture:
    1.) Customization .

CPL :
    1.) Customization.

WDM driver for Win2000/WinXP : 5.10.0.5294
WDM driver for Winx64 : 5.10.0.5294
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL) : 2.0.9.6
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 1.0.0.0
Driver Setup Program : 2.16

Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

```

Readme.txt

//=====

Driver Package R1.45

RtkHDAud.sys Version: 5.10.0.5288

1. Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861, ALC861VD, ALC660, ALC260, ALC262, ALC268

2. OS Supporting: Microsoft WindowsXP, Windows2000, Winx64

3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

4. Add/Fix

1.) Customization.

For New architecture:

1.) Customization .

CPL :

1.) Customization.

WDM driver for Win2000/WinXP : 5.10.0.5288

WDM driver for Winx64 : 5.10.0.5288

Realtek Soundman : 1.0.0.30

Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10

Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9

Realtek Sound Effect Manager(RtlCpl) : 1.0.1.64

Realtek Sound Effect Manager(RTHDCPL) : 2.0.9.1

Alcwzrd.exe : 1.1.0.36

SkyTel.exe : 1.0.0.0

Driver Setup Program : 2.15

Operate on :

Microsoft High Definition Audio Driver Package - KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.44

RtkHDAud.sys Version: 5.10.0.5286

1. Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861, ALC861VD, ALC660, ALC260, ALC262, ALC268

2. OS Supporting: Microsoft WindowsXP, Windows2000, Winx64

3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

4. Add/Fix

1.) Customization.

For New architecture:

1.) Customization .

CPL :

1.) Customization.

WDM driver for Win2000/WinXP : 5.10.0.5286

WDM driver for Winx64 : 5.10.0.5286

Realtek Soundman : 1.0.0.30

Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10

Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.8

Realtek Sound Effect Manager(RtlCpl) : 1.0.1.64

Realtek Sound Effect Manager(RTHDCPL) : 2.0.8.7

Alcwzrd.exe : 1.1.0.36

SkyTel.exe : 1.0.0.0

Driver Setup Program : 2.15

Operate on :

Microsoft High Definition Audio Driver Package - KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.43

RtkHDAud.sys Version: 5.10.0.5283

1. Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861, ALC861VD, ALC660, ALC260, ALC262, ALC268

2. OS Supporting: Microsoft WindowsXP, Windows2000, Winx64

3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

4. Add/Fix

1.) Customization.

For New architecture:

1.) Customization .

Readme.txt

CPL :

1.) Customization.

WDM driver for Win2000/WinXP : 5.10.0.5283
WDM driver for Winx64 : 5.10.0.5283
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.8
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL) : 2.0.8.3
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 1.0.0.0
Driver Setup Program : 2.15

Operate on :

Microsoft High Definition Audio Driver Package - KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.42

RtkHDAud.sys Version: 5.10.0.5282

1. Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861, ALC861VD, ALC660, ALC260, ALC262, ALC268

2. OS Supporting: Microsoft WindowsXP, Win2000, Winx64

3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

4. Add/Fix

1.) Customization.

For New architecture:

1.) Customization .

2.) Fix some game issue .

CPL :

1.) Customization.

WDM driver for Win2000/WinXP : 5.10.0.5282
WDM driver for Winx64 : 5.10.0.5282
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.8
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL) : 2.0.8.0
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 1.0.0.0
Driver Setup Program : 2.15

Operate on :

Microsoft High Definition Audio Driver Package - KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.41

RtkHDAud.sys Version: 5.10.0.5273

1. Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861, ALC861VD, ALC660, ALC260, ALC262, ALC268

2. OS Supporting: Microsoft WindowsXP, Win2000, Winx64

3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

4. Add/Fix

1.) Customization.

For New architecture:

1.) Customization.

CPL :

1.) Customization.

WDM driver for Win2000/WinXP : 5.10.0.5273
WDM driver for Winx64 : 5.10.0.5273
Realtek Soundman : 1.0.0.29
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.8
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL) : 2.0.7.3
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 1.0.0.0

Readme.txt

Driver Setup Program : 2.14

Operate on :

Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.40

RtkHDAud.sys Version: 5.10.0.5268

1. Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861, ALC861VD, ALC660, ALC260, ALC262, ALC268
2. OS Supporting: Microsoft WindowsXP, Windows2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization .

CPL :

- 1.) Customization.

InstallShield package :

- 1.) Correct present driver version in "Add or Remove Programs \ Support Information" .
- 2.) Windows 2000 installation reboot twice problem .

WDM driver for Win2000/WinXP : 5.10.0.5268
WDM driver for Winx64 : 5.10.0.5268
Realtek Soundman : 1.0.0.29
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.8
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL) : 2.0.7.0
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 1.0.0.0
Driver Setup Program : 2.14

Operate on :

Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.39

RtkHDAud.sys Version: 5.10.0.5265

1. Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861, ALC861VD, ALC260, ALC262
2. OS Supporting: Microsoft WindowsXP, Windows2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization .

CPL :

- 1.) Customization.
- 2.) Add support for left panel and right panel config.

InstallShield package :

- 1.) Copy file rule in Vista system .
- 2.) Show driver version in "Add or Remove Programs \ Support Information" .

WDM driver for Win2000/WinXP : 5.10.0.5265
WDM driver for Winx64 : 5.10.0.5265
Realtek Soundman : 1.0.0.29
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.8
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL) : 2.0.6.9
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 1.0.0.0
Driver Setup Program : 2.13

Operate on :

Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.38

RtkHDAud.sys Version: 5.10.0.5257

1. Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861, ALC260, ALC262
2. OS Supporting: Microsoft WindowsXP, Windows2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization .

CPL :

- 1.) Customization.

InstallShield package :

- 1.) Add "XP2K" and "Vista" folder name for installation .
- 2.) Abort flag setting .

| | |
|--------------------------------------------|---------------|
| WDM driver for Win2000/WinXP | : 5.10.0.5257 |
| WDM driver for Winx64 | : 5.10.0.5257 |
| Realtek Soundman | : 1.0.0.29 |
| Realtek Sound Effect Manager(ALSndMgr.cpl) | : 1.0.0.10 |
| Realtek Sound Effect Manager(RTSndMgr.cpl) | : 1.0.0.8 |
| Realtek Sound Effect Manager(RtlCpl) | : 1.0.1.64 |
| Realtek Sound Effect Manager(RTHDCPL) | : 2.0.6.6 |
| Alcwzrd.exe | : 1.1.0.36 |
| SkyTel.exe | : 1.0.0.0 |
| Driver Setup Program | : 2.11 |

Operate on :

Microsoft High Definition Audio Driver Package - KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.37

RtkHDAud.sys Version: 5.10.0.5253

1. Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861, ALC260, ALC262
2. OS Supporting: Microsoft WindowsXP, Windows2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization .

CPL :

- 1.) Customization.

InstallShield package :

- 1.) Upgrade to IS11.5 .

| | |
|--------------------------------------------|---------------|
| WDM driver for Win2000/WinXP | : 5.10.0.5253 |
| WDM driver for Winx64 | : 5.10.0.5253 |
| Realtek Soundman | : 1.0.0.29 |
| Realtek Sound Effect Manager(ALSndMgr.cpl) | : 1.0.0.10 |
| Realtek Sound Effect Manager(RTSndMgr.cpl) | : 1.0.0.8 |
| Realtek Sound Effect Manager(RtlCpl) | : 1.0.1.64 |
| Realtek Sound Effect Manager(RTHDCPL) | : 2.0.6.4 |
| Alcwzrd.exe | : 1.1.0.36 |
| SkyTel.exe | : 1.0.0.0 |
| Driver Setup Program | : 2.09 |

Operate on :

Microsoft High Definition Audio Driver Package - KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.36

RtkHDAud.sys Version: 5.10.0.5247

1. Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861, ALC260, ALC262
2. OS Supporting: Microsoft WindowsXP, Windows2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix

Readme.txt

1.) Customization.

For New architecture:

- 1.) Customization .
- 2.) Add ALC888 .

CPL :

1.) Customization.

InstallShield package :

| | |
|--------------------------------------------|---------------|
| WDM driver for Win2000/WinXP | : 5.10.0.5247 |
| WDM driver for Winx64 | : 5.10.0.5247 |
| Realtek Soundman | : 1.0.0.28 |
| Realtek Sound Effect Manager(ALSndMgr.cpl) | : 1.0.0.10 |
| Realtek Sound Effect Manager(RTSndMgr.cpl) | : 1.0.0.8 |
| Realtek Sound Effect Manager(RtlCpl) | : 1.0.1.62 |
| Realtek Sound Effect Manager(RTHDCPL) | : 2.0.5.9 |
| Alcwzrd.exe | : 1.1.0.35 |
| Driver Setup Program | : 2.06 |

Operate on :

Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.35

RtkHDAud.sys Version: 5.10.0.5242

1. Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC861, ALC260, ALC262
2. OS Supporting: Microsoft WindowsXP, Windows2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
 - 1.) Customization.

For New architecture:

1.) Customization .

CPL :

1.) Customization.

InstallShield package :

| | |
|--------------------------------------------|---------------|
| WDM driver for Win2000/WinXP | : 5.10.0.5242 |
| WDM driver for Winx64 | : 5.10.0.5242 |
| Realtek Soundman | : 1.0.0.28 |
| Realtek Sound Effect Manager(ALSndMgr.cpl) | : 1.0.0.10 |
| Realtek Sound Effect Manager(RTSndMgr.cpl) | : 1.0.0.8 |
| Realtek Sound Effect Manager(RtlCpl) | : 1.0.1.62 |
| Realtek Sound Effect Manager(RTHDCPL) | : 2.0.5.4 |
| Alcwzrd.exe | : 1.1.0.35 |
| Driver Setup Program | : 2.06 |

Operate on :

Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.34

RtkHDAud.sys Version: 5.10.0.5233

1. Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC861, ALC260, ALC262
2. OS Supporting: Microsoft WindowsXP, Windows2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization .
- 2.) Fixed Adobe Premiere Pro 1.5 Crash issue .

CPL :

1.) Customization.

InstallShield package :

- 1.) Rtlupd termination return error code .
- 2.) Receive error code rule from Rtlupd SetupAPI .

3.) SetupCopyOEM install rule .

WDM driver for Win2000/WinXP : 5.10.0.5233
 WDM driver for Winx64 : 5.10.0.5233
 Realtek Soundman : 1.0.0.28
 Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
 Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.8
 Realtek Sound Effect Manager(RtlCpl) : 1.0.1.62
 Realtek Sound Effect Manager(RTHDCPL) : 2.0.4.9
 Alcwzrd.exe : 1.1.0.35
 Driver Setup Program : 2.06

Operate on :

Microsoft High Definition Audio Driver Package - KB888111
 Package file version (kb888111.exe) : 6.1.22.0
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.33

RtkHDAud.sys Version: 5.10.0.5229

1. Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC861, ALC260, ALC262
2. OS Supporting: Microsoft WindowsXP, Win2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization .

CPL :

- 1.) Customization.

InstallShield package :

- 1.) Bus driver detect issue .

WDM driver for Win2000/WinXP : 5.10.0.5229
 WDM driver for Winx64 : 5.10.0.5229
 Realtek Soundman : 1.0.0.28
 Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
 Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.8
 Realtek Sound Effect Manager(RtlCpl) : 1.0.1.61
 Realtek Sound Effect Manager(RTHDCPL) : 2.0.4.7
 Alcwzrd.exe : 1.1.0.34
 Driver Setup Program : 2.05

Operate on :

Microsoft High Definition Audio Driver Package - KB888111
 Package file version (kb888111.exe) : 6.1.22.0
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.32

RtkHDAud.sys Version: 5.10.0.5224

1. Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC861, ALC260, ALC262
2. OS Supporting: Microsoft WindowsXP, Win2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization .

CPL :

- 1.) Customization.

InstallShield package :

- 1.) Report installation progress and result to "C:\RTHSetup.log" within silent mode .
- 2.) Rtlupd setup API will not appear message dialog in silent mode .

WDM driver for Win2000/WinXP : 5.10.0.5224
 WDM driver for Winx64 : 5.10.0.5224
 Realtek Soundman : 1.0.0.28
 Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
 Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.8
 Realtek Sound Effect Manager(RtlCpl) : 1.0.1.61
 Realtek Sound Effect Manager(RTHDCPL) : 2.0.4.4
 Alcwzrd.exe : 1.1.0.34

Driver Setup Program : 2.04

Operate on :

Microsoft High Definition Audio Driver Package - KB888111
 Package file version (kb888111.exe) : 6.1.22.0
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.31

RtkHDAud.sys Version: 5.10.0.5221

1. Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC861, ALC260, ALC262
2. OS Supporting: Microsoft WindowsXP, Windows2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization .
- 2.) Add ALC885 HD Audio Codec for WHQL .

CPL :

- 1.) Customization.

InstallShield package :

| | |
|--------------------------------------------|---------------|
| WDM driver for Win2000/WinXP | : 5.10.0.5221 |
| WDM driver for Winx64 | : 5.10.0.5221 |
| Realtek Soundman | : 1.0.0.27 |
| Realtek Sound Effect Manager(ALSndMgr.cpl) | : 1.0.0.10 |
| Realtek Sound Effect Manager(RTSndMgr.cpl) | : 1.0.0.8 |
| Realtek Sound Effect Manager(RtlCpl) | : 1.0.1.60 |
| Realtek Sound Effect Manager(RTHDCPL) | : 2.0.4.2 |
| Alcwzrd.exe | : 1.1.0.33 |
| Driver Setup Program | : 2.03 |

Operate on :

Microsoft High Definition Audio Driver Package - KB888111
 Package file version (kb888111.exe) : 6.1.22.0
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.30

RtkHDAud.sys Version: 5.10.0.5211

1. Codec Supporting: ALC880, ALC882, ALC883, ALC861, ALC260, ALC262
2. OS Supporting: Microsoft WindowsXP, Windows2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization .
- 2.) Bug fixed when recording AEC device failed on 880 .

CPL :

- 1.) Customization.

InstallShield package :

| | |
|--------------------------------------------|---------------|
| WDM driver for Win2000/WinXP | : 5.10.0.5211 |
| WDM driver for Winx64 | : 5.10.0.5211 |
| Realtek Soundman | : 1.0.0.24 |
| Realtek Sound Effect Manager(ALSndMgr.cpl) | : 1.0.0.10 |
| Realtek Sound Effect Manager(RTSndMgr.cpl) | : 1.0.0.8 |
| Realtek Sound Effect Manager(RtlCpl) | : 1.0.1.58 |
| Realtek Sound Effect Manager(RTHDCPL) | : 2.0.3.9 |
| Alcwzrd.exe | : 1.1.0.31 |
| Driver Setup Program | : 2.03 |

Operate on :

Microsoft High Definition Audio Driver Package - KB888111
 Package file version (kb888111.exe) : 6.1.22.0
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.29

RtkHDAud.sys Version: 5.10.0.5202

1. Codec Supporting: ALC880, ALC882, ALC883, ALC861, ALC260, ALC262
2. OS Supporting: Microsoft WindowsXP, Windows2000, Winx64

Readme.txt

3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization.

CPL :

- 1.) Customization.

InstallShield package :

| | |
|--------------------------------------------|---------------|
| WDM driver for Win2000/WinXP | : 5.10.0.5202 |
| WDM driver for Winx64 | : 5.10.0.5202 |
| Realtek Soundman | : 1.0.0.21 |
| Realtek Sound Effect Manager(ALSndMgr.cpl) | : 1.0.0.10 |
| Realtek Sound Effect Manager(RTSndMgr.cpl) | : 1.0.0.7 |
| Realtek Sound Effect Manager(RtlCpl) | : 1.0.1.54 |
| Realtek Sound Effect Manager(RTHDCPL) | : 2.0.3.4 |
| Alcwzrd.exe | : 1.1.0.29 |
| Driver Setup Program | : 2.02c |

Operate on :

Microsoft High Definition Audio Driver Package - KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.28

RtkHDAud.sys Version: 5.10.0.5200

1. Codec Supporting: ALC880, ALC882, ALC883, ALC861, ALC260, ALC262
2. OS Supporting: Microsoft WindowsXP, Winows2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization.
- 2.) Add ALC265 .

CPL :

- 1.) Side speaker testing has no sound when 3D engine is disabled.

InstallShield package :

- 1.) Add Chipset ID VEN_1002&DEV_4383 .

| | |
|--------------------------------------------|---------------|
| WDM driver for Win2000/WinXP | : 5.10.0.5200 |
| WDM driver for Winx64 | : 5.10.0.5200 |
| Realtek Soundman | : 1.0.0.21 |
| Realtek Sound Effect Manager(ALSndMgr.cpl) | : 1.0.0.10 |
| Realtek Sound Effect Manager(RTSndMgr.cpl) | : 1.0.0.7 |
| Realtek Sound Effect Manager(RtlCpl) | : 1.0.1.53 |
| Realtek Sound Effect Manager(RTHDCPL) | : 2.0.3.2 |
| Alcwzrd.exe | : 1.1.0.28 |
| Driver Setup Program | : 2.02c |

Operate on :

Microsoft High Definition Audio Driver Package - KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.27

RtkHDAud.sys Version: 5.10.0.5188

1. Codec Supporting: ALC880, ALC882, ALC883, ALC861, ALC260, ALC262
2. OS Supporting: Microsoft WindowsXP, Winows2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization.

InstallShield package :

Fix :

1. Add installation file "RTHDAEQ*.dat" .
2. Add Package version in setup.ini .

3. Manual installation setting for InstallShield .

WDM driver for Win2000/WinXP : 5.10.0.5188
 WDM driver for Winx64 : 5.10.0.5188
 Realtek Soundman : 1.0.0.21
 Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
 Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.7
 Realtek Sound Effect Manager(RtlCpl) : 1.0.1.53
 Realtek Sound Effect Manager(RTHDCPL) : 2.0.2.6
 Alcwzrd.exe : 1.1.0.28
 Driver Setup Program : 2.02a

Operate on :

Microsoft High Definition Audio Driver Package - KB888111
 Package file version (kb888111.exe) : 6.1.22.0
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.26

RtkHDAud.sys Version: 5.10.0.5178

1. Codec Supporting: ALC880, ALC882, ALC883, ALC861, ALC260, ALC262
2. OS Supporting: Microsoft WindowsXP, Win2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization.

InstallShield package :

Fix :

1. Set rebooting twice for installation UAA QFE on Win2000 .

WDM driver for Win2000/WinXP : 5.10.0.5178
 WDM driver for Winx64 : 5.10.0.5178
 Realtek Soundman : 1.0.0.21
 Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
 Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.6
 Realtek Sound Effect Manager(RtlCpl) : 1.0.1.52
 Realtek Sound Effect Manager(RTHDCPL) : 2.0.2.1
 Alcwzrd.exe : 1.1.0.28
 Driver Setup Program : 2.00

Operate on :

Microsoft High Definition Audio Driver Package - KB888111
 Package file version (kb888111.exe) : 6.1.22.0
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.25

RtkHDAud.sys Version: 5.10.0.5172

1. Codec Supporting: ALC880, ALC882, ALC883, ALC861, ALC260, ALC262
2. OS Supporting: Microsoft WindowsXP, Win2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization.

InstallShield package :

Fix :

1. Rtlupd.exe(2.5.0.5) fixed roll-back problem (It can not delete oem inf file before update driver).

2. Change Azalia name in setup.ini file .

3. Don't popup Rtlupd dialog when you select "No" on Hotfix installation dialog .

Add :

1. System language identifier .

2. Change pop-up dialog Product name (Azalia->High Definition) .

WDM driver for Win2000/WinXP : 5.10.0.5172
 WDM driver for Winx64 : 5.10.0.5172
 Realtek Soundman : 1.0.0.21
 Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
 Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.6
 Realtek Sound Effect Manager(RtlCpl) : 1.0.1.51
 Realtek Sound Effect Manager(RTHDCPL) : 2.0.1.7

Readme.txt

Alcwzrd.exe : 1.1.0.27
Driver Setup Program : 1.99

Operate on :

Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.24

RtkHDAud.sys Version: 5.10.0.5152

1. Codec Supporting: ALC880, ALC882, ALC883, ALC861, ALC260, ALC262
2. OS Supporting: Microsoft WindowsXP, Windows2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization.
- 2.) Support 192KHz sample rate output.

InstallShield package :

Fix :

1. Reboot timing after installation MS QFE (UAA driver) .
2. Uninstallation dialog description .

Add :

1. MS hotfix KB901105 can be included by HD package (If get MS licence) .
2. Hotfix KB901105 Warning message .

WDM driver for Win2000/WinXP : 5.10.0.5152
WDM driver for Winx64 : 5.10.0.5152
Realtek Soundman : 1.0.0.18
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.7
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.4
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.46
Realtek Sound Effect Manager(RTHDCPL) : 2.0.0.8
Alcwzrd.exe : 1.1.0.24
Driver Setup Program : 1.96

Operate on :

Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.23

RtkHDAud.sys Version: 5.10.0.5136

1. Codec Supporting: ALC880, ALC882, ALC883, ALC861, ALC260, ALC262
2. OS Supporting: Microsoft WindowsXP, Windows2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization.
- 2.) Support new codec ALC262, ALC883

InstallShield package :

- 1.) Check OS service pack number with InstallShield .
- 2.) Change audio wizard quitting procedure .

WDM driver for Win2000/WinXP : 5.10.0.5136
WDM driver for Winx64 : 5.10.0.5136
Realtek Soundman : 1.0.0.17
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.7
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.4
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.43
Realtek Sound Effect Manager(RTHDCPL) : 1.1.2.3
Alcwzrd.exe : 1.1.0.23
Driver Setup Program : 1.92

Operate on :

Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.22

Readme.txt

RtkHDAud.sys Version: 5.10.0.5128

1. Codec Supporting: ALC880, ALC882, ALC861, ALC260
2. OS Supporting: Microsoft WindowsXP, Windows2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization.

InstallShield package :

- 1.) Setup progress backward .
- 2.) Driver size on Add and remove programs .
- 3.) Refresh driver size on Add and Remove Programs .
- 4.) Check RtlExupd.dll version .
- 5.) Check RtlHDCpl.exe version .

| | |
|--------------------------------------------|---------------|
| WDM driver for Win2000/WinXP | : 5.10.0.5128 |
| WDM driver for Winx64 | : 5.10.0.5128 |
| Realtek Soundman | : 1.0.0.17 |
| Realtek Sound Effect Manager(ALSndMgr.cpl) | : 1.0.0.7 |
| Realtek Sound Effect Manager(RTSndMgr.cpl) | : 1.0.0.4 |
| Realtek Sound Effect Manager(RtlCpl) | : 1.0.1.40 |
| Realtek Sound Effect Manager(RTHDCPL) | : 1.1.1.9 |
| Alcwzrd.exe | : 1.1.0.20 |
| Driver Setup Program | : 1.91 |

Operate on :

Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.21

RtkHDAud.sys Version: 5.10.0.5127

1. Codec Supporting: ALC880, ALC882, ALC260
2. OS Supporting: Microsoft WindowsXP, Windows2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization.
- 2.) Support DTS Encoder and DTS Neo for special version codec .

SoundMan.exe Version: 1.0.0.17

ALSndMgr.cpl Version: 1.0.0.7

Rtlcpl.exe Version: 1.0.1.40

Alcwzrd.exe Version: 1.1.0.20

Operate on :

Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.20

RtkHDAud.sys Version: 5.10.0.5125

1. Codec Supporting: ALC880, ALC882, ALC260
2. OS Supporting: Microsoft WindowsXP, Windows2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization.
- 2.) Fixed the issue of SPDIF-In capture

SoundMan.exe Version: 1.0.0.17

ALSndMgr.cpl Version: 1.0.0.7

Rtlcpl.exe Version: 1.0.1.40

Alcwzrd.exe Version: 1.1.0.20

Operate on :

Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

Readme.txt

//=====

Driver Package R1.19

RtkHDAud.sys Version: 5.10.0.5123

1. Codec Supporting: ALC880, ALC882, ALC260
2. OS Supporting: Microsoft WindowsXP, Windows2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
 1. Customization.
 2. Avoid Pop noise when toggle output sampling rate for ALC260.
 3. Restore the original timer resolution first before check the original system timer resolution.

For New architecture:

- 1.) Customization.
- 2.) Driver store mixer setting after windows reboot

SoundMan.exe Version: 1.0.0.14

ALSndMgr.cpl Version: 1.0.0.5

Rtlcpl.exe Version: 1.0.1.39

Alcwzrd.exe Version: 1.1.0.19

Operate on :

Microsoft High Definition Audio Driver Package - KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.18

RtkHDAud.sys Version: 5.10.0.5122

1. Codec Supporting: ALC880, ALC882, ALC260
2. OS Supporting: Microsoft WindowsXP, Windows2000
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
 1. Customization.
 2. Add 2 default values of codec subsystem ID for ALC260.

For New architecture:

- 1.) Customization.
- 2.) Fixed the issue of uncontinuous sound after suspend on some machine.

SoundMan.exe Version: 1.0.0.14

ALSndMgr.cpl Version: 1.0.0.5

Rtlcpl.exe Version: 1.0.1.38

Alcwzrd.exe Version: 1.1.0.18

Operate on :

Microsoft High Definition Audio Driver Package - KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.17

RtkHDAud.sys Version: 5.10.0.5120

1. Codec Supporting: ALC880, ALC882, ALC260, ALC861
2. OS Supporting: Microsoft WindowsXP, Windows2000
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
 1. Customization.
 2. Restore certain register value when resume from system suspend.

For New architecture:

- 1.) Customization.
- 2.) Improve reliability for switching mutiple streaming.

SoundMan.exe Version: 1.0.0.14

ALSndMgr.cpl Version: 1.0.0.5

Rtlcpl.exe Version: 1.0.1.38

Alcwzrd.exe Version: 1.1.0.18

Operate on :

Microsoft High Definition Audio Driver Package - KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.16

RtkHDAud.sys Version: 5.10.0.5119

1. Codec Supporting: ALC880, ALC882, ALC260, ALC861
2. OS Supporting: Microsoft WindowsXP, Windows2000

Readme.txt

3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
 1. Customization.
 2. Fix initial noise issue for the certain models.
 3. Check codec SubsystemID verb to decide the driver path when driver initialize.
 4. Don't modify Configuration byte Verbs when driver initialize.
 5. Fix Buffer size un-alignment issue.

For New architecture:

- 1.) Customization.
- 2.) Fix the problem when play AC-3 stream by SPDIF interface
- 3.) Change device name for mutiple streaming issue.

SoundMan.exe Version: 1.0.0.14
ALSndMgr.cpl Version: 1.0.0.5
Rtlcpl.exe Version: 1.0.1.38
Alcwzrd.exe Version: 1.1.0.17

Operate on :

Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.15

RtkHDAud.sys Version: 5.10.0.5116

1. Codec Supporting: ALC880, ALC882, ALC260, ALC861
2. OS Supporting: Microsoft WindowsXP, Widnows2000
3. Pack with Microsoft High Definition Audio UAAV1(5011)
4. Add/Fix
 - 1.) Customization.
 - 2.) Auto lock SPDIF-in signal when SPDIF-in signal is unlocked.
 - 3.) Fix SPDIF out copy protection issue.
 - 4.) Add patch code for ALC260 potential risk.

For New architecture:

- 1.) Customization.
- 2.) Fix new feature problem on mutiple streaming.
- 3.) Fix capture problem on ALC882.

SoundMan.exe Version: 1.0.0.14
ALSndMgr.cpl Version: 1.0.0.5
Rtlcpl.exe Version: 1.0.1.38
Alcwzrd.exe Version: 1.1.0.17

Operate on :

Microsoft High Definition Audio Driver Package - KB835221
Package file version (kb835221.exe) : 6.1.1.0
Hdaudio.sys version : 5.10.00.5011

//=====

Driver Package R1.14

RtkHDAud.sys Version: 5.10.0.5109

1. Codec Supporting: ALC880, ALC882, ALC260, ALC861
2. OS Supporting: Microsoft WindowsXP, Widnows2000
3. Pack with Microsoft High Definition Audio UAAV1(5011)
4. Add/Fix
 - 1.) Customization.
 - 2.) Reduce delay time when volume is adjusted.
 - 3.) Fix hang up issue when system resume from S3.

For New architecture:

- 1.) New architecture of HD audio driver formal release.

SoundMan.exe Version: 1.0.0.14
ALSndMgr.cpl Version: 1.0.0.4
Rtlcpl.exe Version: 1.0.1.37
Alcwzrd.exe Version: 1.1.0.16

Operate on :

Microsoft High Definition Audio Driver Package - KB835221
Package file version (kb835221.exe) : 6.1.1.0
Hdaudio.sys version : 5.10.00.5011

//=====

Driver Package R1.13

RtkHDAud.sys Version: 5.10.0.5038

1. Codec Supporting: ALC880, ALC260, ALC861

Readme.txt

2. OS Supporting: Microsoft WindowsXP, Windows2000
3. Pack with Microsoft High Definition Audio UAAV1(5011)
4. Add/Fix
 - 1) Reduce initialize noise

SoundMan.exe Version: 1.0.0.14
ALSndMgr.cpl Version: 1.0.0.5
Rtlcpl.exe Version: 1.0.1.36
Alcwzrd.exe Version: 1.1.0.15

Operate on :

- Microsoft High Definition Audio Driver Package - KB835221
- Package file version (kb835221.exe) : 6.1.1.0
- Hdaudio.sys version : 5.10.00.5011

//=====

Driver Package R1.12

- RtkHDAud.sys Version: 5.10.0.5037
1. Codec Supporting: ALC880, ALC260, ALC861
 2. OS Supporting: Microsoft WindowsXP, Windows2000
 3. Pack with Microsoft High Definition Audio UAAV1(5011)
 4. Add/Fix
 - 1) Improve recording performance.
 - 2) Reduce initialize noise

SoundMan.exe Version: 1.0.0.14
ALSndMgr.cpl Version: 1.0.0.5
Rtlcpl.exe Version: 1.0.1.36
Alcwzrd.exe Version: 1.1.0.15

Operate on :

- Microsoft High Definition Audio Driver Package - KB835221
- Package file version (kb835221.exe) : 6.1.1.0
- Hdaudio.sys version : 5.10.00.5011

//=====

Driver Package R1.11

- RtkHDAud.sys Version: 5.10.0.5036
1. Codec Supporting: ALC880, ALC260, ALC861
 2. OS Supporting: Microsoft WindowsXP, Windows2000
 3. Pack with Microsoft High Definition Audio UAAV1(5011)
 4. Add/Fix

SoundMan.exe Version: 1.0.0.14
ALSndMgr.cpl Version: 1.0.0.5
Rtlcpl.exe Version: 1.0.1.35
Alcwzrd.exe Version: 1.1.0.15

Operate on :

- Microsoft High Definition Audio Driver Package - KB835221
- Package file version (kb835221.exe) : 6.1.1.0
- Hdaudio.sys version : 5.10.00.5011

//=====

Driver Package R1.10

- RtkHDAud.sys Version: 5.10.0.5034
1. Codec Supporting: ALC880, ALC260, ALC861
 2. OS Supporting: Microsoft WindowsXP, Windows2000
 3. Pack with Microsoft High Definition Audio UAAV1(5011)
 4. Add/Fix
 - 1) Fix the problem that there is little noise when start stream playing
 - 2) Fix the problem that in WinDVD, the SPDIF option still exist even there is no SPDIF

SoundMan.exe Version: 1.0.0.14

1. Set the default recording device as "Realtek HD Audio rear input" device

ALSndMgr.cpl Version: 1.0.0.5

Rtlcpl.exe Version: 1.0.1.34

Alcwzrd.exe Version: 1.1.0.15

1. Keep previous Jack setting.
2. Check whether have any jack plugin when restart OS, and popup the device window if wizard detect any new device plugin.

Operate on :

Readme.txt

Microsoft High Definition Audio Driver Package - KB835221

Package file version (kb835221.exe) : 6.1.1.0

Hdaudio.sys version : 5.10.00.5011

//=====

Driver Package R1.09

RtkHDAud.sys Version: 5.10.0.5033

1. Codec Supporting: ALC880, ALC260, ALC861
2. OS Supporting: Microsoft WindowsXP, Windows2000
3. Pack with Microsoft High Definition Audio OOB Binaries V1.0

SoundMan.exe Version: 1.0.0.14

1. Set the default recording device as "Realtek HD Audio rear input" device

ALSndMgr.cpl Version: 1.0.0.5

Rtlcpl.exe Version: 1.0.1.33

Alcwzrd.exe Version: 1.1.0.14

Operate on :

Microsoft High Definition Audio Driver Package - KB835221

Package file version (kb835221.exe) : 6.1.1.0

Hdaudio.sys version : 5.10.00.5010

//=====

Driver Package R1.08

RtkHDAud.sys Version: 5.10.0.5032

1. Codec Supporting: ALC880, ALC260, ALC861
2. OS Supporting: Microsoft WindowsXP, Windows2000
3. Pack with Microsoft High Definition Audio OOB Binaries V1.0

SoundMan.exe Version: 1.0.0.12

ALSndMgr.cpl Version: 1.0.0.5

Rtlcpl.exe Version: 1.0.1.33

Alcwzrd.exe Version: 1.1.0.14

Operate on :

Microsoft High Definition Audio Driver Package - KB835221

Package file version (kb835221.exe) : 6.1.1.0

Hdaudio.sys version : 5.10.00.5010

//=====

Driver Package R1.07

RtkHDAud.sys Version: 5.10.0.5031

1. Codec Supporting: ALC880, ALC260, ALC861
2. OS Supporting: Microsoft WindowsXP, Windows2000
3. Pack with Microsoft High Definition Audio OOB Binaries V1.0
4. Add/Fix
 - 1) Fix the problem when playback with sound recorder, when change frequency from 48k to 44.1k in SPDIF page, playback will stop
 - 2) Support for ALC880G, ALC880D, ALC260D
 - 3) Fix the the problem that system will hang up while perform audio test in 3DMark 2003

SoundMan.exe Version: 1.0.0.12

ALSndMgr.cpl Version: 1.0.0.5

Rtlcpl.exe Version: 1.0.1.32

1. Fix word collision problem in Multi-Language.

Alcwzrd.exe Version: 1.1.0.13

1. Restore previous jack setting when reboot system

Operate on :

Microsoft High Definition Audio Driver Package - KB835221

Package file version (kb835221.exe) : 6.1.1.0

Hdaudio.sys version : 5.10.00.5010

//=====

Driver Package R1.06

RtkHDAud.sys Version: 5.10.0.5030

1. Codec Supporting: ALC880, ALC260, ALC861
2. OS Supporting: Microsoft WindowsXP, Windows2000
3. Pack with Microsoft High Definition Audio OOB Binaries V1.0
4. Add/Fix

SoundMan.exe Version: 1.0.0.12

ALSndMgr.cpl Version: 1.0.0.3

Rtlcpl.exe Version: 1.0.1.31

Alcwzrd.exe Version: 1.1.0.12

Readme.txt

Operate on :

Microsoft High Definition Audio Driver Package - KB835221
Package file version (kb835221.exe) : 6.1.1.0
Hdaudio.sys version : 5.10.00.5010

//=====

Driver Package R1.05

RtkHDAud.sys Version: 5.10.0.5029

1. Codec Supporting: ALC880, ALC260, ALC861
2. OS Supporting: Microsoft WindowsXP, Widnows2000
3. Pack with Microsoft High Definition Audio OOB Binaries V1.0
4. Add/Fix
 - 1) Add support for ALC861
 - 2) Fix the noise problem that when recording from SPDIF In at 96khz

SoundMan.exe Version: 1.0.0.12

ALSndMgr.cpl Version: 1.0.0.5

Rtlcpl.exe Version: 1.0.1.31

Alcwzrd.exe Version: 1.1.0.12

Operate on :

Microsoft High Definition Audio Driver Package - KB835221
Package file version (kb835221.exe) : 6.1.1.0
Hdaudio.sys version : 5.10.00.5010

//=====

Driver Package R1.04

RtkHDAud.sys Version: 5.10.0.5028

1. Codec Supporting: ALC880, ALC260
2. OS Supporting: Microsoft WindowsXP, Widnows2000
3. Pack with Microsoft High Definition Audio OOB Binaries V1.0
4. Add/Fix
 - 1) For UAJ A to A volume line, change type from KSNODETYPE_MICROPHONE to KSNODETYPE_ANALOG_CONNECTOR
 - 2) Fix the problem that SPDIF out no sound in WinDVD
 - 3) Fix the problem that there is balance conrtol in Center and Subwoofer volume line in W2k
 - 4) Change the component tye of SPDIF-In from "KSNODETYPE_ANALOG_CONNECTOR" to "KSNODETYPE_SPDIF_INTERFACE"
 - 5) Fix the problem that mute SPDIF out in mixer doesn't work

SoundMan.exe Version: 1.0.0.12

ALSndMgr.cpl Version: 1.0.0.3

Rtlcpl.exe Version: 1.0.1.31

1. Turn off all sound effect when speaker test!

Alcwzrd.exe Version: 1.1.0.12

Operate on :

Microsoft High Definition Audio Driver Package - KB835221
Package file version (kb835221.exe) : 6.1.1.0
Hdaudio.sys version : 5.10.00.5010

//=====

Driver Package R1.03

RtkHDAud.sys Version: 5.10.0.5027

SoundMan.exe Version: 1.0.0.4

ALSndMgr.cpl Version: 1.0.0.2

Rtlcpl.exe Version: 1.0.1.29

1. Sync the status which Enable/Disable wizard with alcwzrd
2. Make the tab of "Audio Wizard" independent from menu tabs.
3. Stop the play sound when menu tab is change.

Alcwzrd.exe Version: 1.1.0.12

1. Fixed broken wizard image.
2. Sync the status which Enable/Disable wizard with rtlcpl.

Operate on :

Microsoft High Definition Audio Driver Package - KB835221
Package file version (kb835221.exe) : 6.1.1.0
Hdaudio.sys version : 5.10.00.5010

//=====

Driver Package R1.01/R1.02

Readme.txt

RtkHDAud.sys Version: 5.10.0.5022

1. Codec Supporting:
2. OS Supporting: Microsoft WindowsXP, Windows2000
3. Pack with Microsoft High Definition Audio OOB Binaries V1.0
4. Add/Fix

SoundMan.exe Version: 1.0.0.4

ALSndMgr.cpl Version: 1.0.0.2

Rtlcpl.exe Version: 1.0.1.23

Alcwzrd.exe Version: 1.1.0.5

Operate on :

Microsoft High Definition Audio Driver Package - KB835221

Package file version (kb835221.exe) : 6.1.1.0

Hdaudio.sys version : 5.10.00.5010

//=====

Driver Package R1.0

RtkHDAud.sys Version: 5.10.0.5017

1. Codec Supporting: Add ALC880/ALC880M Rev. F Rev. G, ALC860
2. OS Supporting: Microsoft WindowsXP, Windows2000
3. Pack with Microsoft High Definition Audio OOB Binaries V1.0
4. Add/Fix

SoundMan.exe Version: 1.0.0.4

ALSndMgr.cpl Version: 1.0.0.2

Rtlcpl.exe Version: 1.0.1.23

Alcwzrd.exe Version: 1.1.0.5

Operate on :

Microsoft High Definition Audio Driver Package - KB835221

Package file version (kb835221.exe) : 6.1.1.0

Hdaudio.sys version : 5.10.00.5010