

Driver Installation/Removal Procedure For Realtek High Definition Audio Codec:

<<< For Windows 2000/XP/Vista/Windows7 x86/x64 Driver >>>

Setup Driver at first time:

Windows 2000 , XP :

- Step 1. Before installing the Realtek High Definition Audio Driver, Press the [Cancel] button if Windows detect the Multimedia Audio device.
- Step 2. Run the setup.exe program to start the installation.
- Step 3. Click on [Next] to continue the procedure. If the screen resolution is lower than 1024*768, press [Yes] to continue the installation. If the Windows popup "Digital Signature Not Found" message, press [Yes] to continue the installation.
- Step 4. Finally, select to restart the system and press [Finish] to complete the installation.

Windows Vista, Windows7 :

- Step 1. Run the setup.exe program to start the installation.
- Step 2. Click on [Next] to continue the procedure. If the screen resolution is lower than 1024*768, press [Yes] to continue the installation. If the Windows popup "Windows can't verify the publisher of this driver software" message, press "Install this driver software anyway" to continue the installation.
- Step 3. Finally, select to restart the system and press [Finish] to complete the installation.

Update Driver:

Windows 2000 , XP :

- Step 1. Follow Step 2,3,4 described in [Setup at first time] above to complete the procedure.

Windows Vista, Windows7 :

- Step 1. Run setup.exe, it will remove the original driver in your system
- Step 2. Click "Next" to remove the original audio driver in your system
- Step 3. Once after the original driver removed , reboot the computer.
- Step 4. It will install audio driver automatically after computer restarted.

Remove Driver:

Windows 2000 , XP :

- Step 1. Go to Start\Settings\Control Panel.
- Step 2. Select [Add or Remove Programs] icon.
- Step 3. Select "Realtek High Definition Audio Driver" and press [Remove] button.
- Step 4. Click on [Yes] to finish the uninstallation.
- Step 5. At the end of the procedure, select to restart the system and press [Finish] to complete the uninstallation.

Readme.txt

Windows Vista, Windows7 :

Step 1. Go to Start\Settings\Control Panel.

Step 2. Select [Programs] icon.

Step 3. Select [Programs and Features] icon.

Step 4. Select "Realtek High Definition Audio Driver" and press [uninstall] button.

Step 5. Click on [Yes] to finish the uninstallation.

Step 6. At the end of the procedure, select to restart the system and press [Finish] to complete the uninstallation.

<< Other Information >>

Silent Installation:

Run "Setup.exe /s /f2<path\LogFile> /z[-rp<path\LogFile>]"
i. e. setup.exe /s /f2c:\mylog.log /z[-rpC:\RHDS\Setup.log]

Silent Uninstallation:

Run "Setup.exe /removeonly /s /f1<path\USetup.iss> /f2<path\LogFile> /z[-rp<path\LogFile>]"
i. e. setup.exe /removeonly /s /f1C:\AudioDriver\USetup.iss /f2c:\mylog.log /z[-rpC:\RHDS\Setup.log]

Note: 1. Please update DirectX version to DirectX8.1 or above.

Version Informations:

If driver package include below drivers :

Windows 2000/XP :
RTKHDA64.sys : 5.10.0.6438
RtkHDAud.sys : 5.10.0.6438
Alcmtl.exe : 1.6.0.4
AlcWzrd.exe : 1.1.0.37
MlcCal.exe : 1.1.2.4
RTHDCPL.exe : 2.4.0.2
RtkAudioService.exe : 1.0.0.19
RtkAudioService64.exe : 1.0.0.19
RTLCP.exe : 1.0.1.66
RtlUpd.exe : 2.8.0.4
RtlUpd64.exe : 2.8.0.4
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.32
vncutil.exe : 1.0.0.38
vncutil64.exe : 1.0.0.38
AMBFilt.sys : 5.10.0.4240
AMBFt64.sys : 5.10.0.4240
Mbnfilt.sys : 5.10.0.4112
Mbnft64.sys : 5.10.0.4115
OA017Afx.sys : 1.0.7.3
ALSndMgr.cpl : 1.0.0.11
RTSndMgr.cpl : 1.0.1.7
RCoInst64XP.dll : 1.1.6.3
RTCOMDLL.dll : 1.0.0.113
RtkCoInstXP.dll : 1.1.6.3
RtlCPAPI.dll : 1.0.2.3

Vista/Win7 driver : -----
Vista/Win7 driver for x86

RTKVHDA.sys	: 6.0.1.6438
AERTSrv.exe	: 1.0.32.10
DTSAudioService.exe	: 1.0.0.0
DTSU2PAuSrv32.exe	: 2.0.15.0
FMAPP.exe	: 1.32.0.1
RtHDVBg.exe	: 1.0.0.75
RtHDVCpl.exe	: 1.0.0.723
RtkAudioService.exe	: 1.0.0.29
RtkNGUI.exe	: 1.0.0.130
RtlUpd.exe	: 2.8.0.4
SkyTel.exe	: 2.0.2.2
vncutil.exe	: 1.0.0.45
mbfilt32.sys	: 6.10.0.8
RTSndMgr.cpl	: 1.0.0.25
AERTACap.dll	: 2.0.32.13
AERTARen.dll	: 1.0.32.9
BlackSkinImages.dll	: 1.0.0.130
DarkSkinImages.dll	: 1.0.0.130
DTSBassEnhancementDLL.dll	: 1.0.0.1
DTSBoostDLL.dll	: 1.0.0.1
DTSGainCompensatorDLL.dll	: 1.0.0.1
DTSGFXAPO.dll	: 1.0.0.3
DTSGFXAPONS.dll	: 1.0.0.3
DTSLFXAPO.dll	: 1.0.0.3
DTSLimitDLL.dll	: 1.0.0.1
DTSNeoPCDLL.dll	: 1.0.0.1
DTSS2HeadphoneDLL.dll	: 1.0.0.1
DTSS2SpeakerDLL.dll	: 1.0.0.1
DTSSymmetryDLL.dll	: 1.0.0.1
DTSU2PGFX32.dll	: 2.0.15.0
DTSU2PLFX32.dll	: 2.0.15.0
DTSU2PREC32.dll	: 2.0.15.0
DTSVoiceClarityDLL.dll	: 1.0.0.1
FMAPO.dll	: 43.5.16.65
GrayJadeSkinImages.dll	: 1.0.0.130
KAAPORT.dll	: 4.1104.6000.52
LightSkinImages.dll	: 1.0.0.130
MaxxAudioAPO.dll	: 1.2.2.0
MaxxAudioAPO20.dll	: 2.2.9.0
MaxxAudioAPO30.dll	: 3.2.1.1
MaxxAudioEQ.dll	: 2.0.0.0
MaxxAudioRealtek.dll	: 1.3.0.0
MaxxAudioRealtek2.dll	: 1.0.7.0
MaxxVolumeSDAPO.dll	: 3.1.0.0
MBAP032.dll	: 1.0.48.0
MBPPCn32.dll	: 1.0.0.110
MBppld32.dll	: 1.0.48.0
MBTHX32.dll	: 1.0.15.146
MBWrp32.dll	: 1.0.0.180
PremiumBlackSkinImages.dll	: 1.0.0.130
R4EEA32A.dll	: 7.2.7000.6
R4EED32A.dll	: 7.2.7000.6
R4EEG32A.dll	: 7.2.7000.6
R4EEL32A.dll	: 7.2.7000.6
R4EEP32A.dll	: 7.2.7000.6
RP3DAA32.dll	: 6.0.6001.18
RP3DHT32.dll	: 6.0.6001.18
RTCOMDLL.dll	: 2.0.0.146
RTEED32A.dll	: 6.1.6001.33
RTEEG32A.dll	: 6.1.6001.33
RTEEL32A.dll	: 6.1.6001.33
RTEEP32A.dll	: 6.1.6001.33
RtkAPO.dll	: 11.0.6000.233
RtkApoApi.dll	: 1.0.0.41
RtkCfg.dll	: 1.0.0.2
RtkCoInst.dll	: 1.1.6.3
RtkGuiCompLib.dll	: 1.0.0.2
RtkPgExt.dll	: 6.0.6000.221
RtlCPAPI.dll	: 1.0.2.4

	Readme.txt	
SFAPO.dll	: 3.0.0.14	
SFCOM.dll	: 3.0.0.14	
SFFXComm.dll	: 2.0.0.13	
SFFXDAP0.dll	: 2.0.0.13	
SFFXHAP0.dll	: 2.0.0.13	
SFFXProc.dll	: 2.0.0.13	
SFFXSAP0.dll	: 2.0.0.13	
SFNHK.dll	: 3.0.0.14	
slcc3d32.dll	: 1.0.0.100	
slcshp32.dll	: 1.0.3.0	
slcsii32.dll	: 1.0.3.0	
slgeq32.dll	: 1.0.1.0	
slh36032.dll	: 1.0.2.0	
slhlm32.dll	: 2.1.0.0	
slInit32.dll	: 1.1.3.0	
slmaxv32.dll	: 1.2.1.0	
sltshd32.dll	: 1.2.0.0	
sluapo32.dll	: 2.3.8.0	
slvi pp32.dll	: 1.0.1.0	
slviq32.dll	: 2.1.0.0	
SRSHP360.dll	: 1.1.0.0	
SRSTSHD.dll	: 1.1.4.0	
SRSTSXT.dll	: 3.2.0.0	
SRSWOW.dll	: 1.1.3.0	
tadefxapo.dll	: 1.0.1.12	
tadefxapo2.dll	: 1.1.0.31	
tosade.dll	: 1.0.1.12	
WavesGUILib.dll	: 2.0.0.0	
WavesLib.dll	: 5.9.7.0	
RCORES.dat	: 1.1.1.6	
Vista/Win7 driver for x64		
RTKVHD64.sys	: 6.0.1.6438	
AERTSr64.exe	: 1.0.64.10	
DTSAudioService64.exe	: 1.0.0.0	
DTSU2PAuSrv64.exe	: 2.0.15.0	
FMAPP.exe	: 1.64.0.1	
RAVBg64.exe	: 1.0.0.75	
RAVCpl64.exe	: 1.0.0.723	
RtkAudioService64.exe	: 1.0.0.29	
RtkNGUI64.exe	: 1.0.0.130	
RtlUpd64.exe	: 2.8.0.4	
SkyTel.exe	: 2.0.2.2	
vncutil64.exe	: 1.0.0.45	
GWfilt64.sys	: 6.10.0.3	
mbfilt64.sys	: 6.10.0.8	
RTSnMg64.cpl	: 1.0.0.25	
AERTAC64.dll	: 2.0.64.13	
AERTAR64.dll	: 1.0.64.9	
BlackSkinImages64.dll	: 1.0.0.130	
DarkSkinImages64.dll	: 1.0.0.130	
DTSBassEnhancementDLL64.dll	: 1.0.0.1	
DTSBoostDLL64.dll	: 1.0.0.1	
DTSGainCompensatorDLL64.dll	: 1.0.0.1	
DTS GFXAP064.dll	: 1.0.0.3	
DTS GFXAPONS64.dll	: 1.0.0.3	
DTS LFXAP064.dll	: 1.0.0.3	
DTS LimiterDLL64.dll	: 1.0.0.1	
DTS NeoPCDLL64.dll	: 1.0.0.1	
DTSS2HeadphoneDLL64.dll	: 1.0.0.1	
DTSS2SpeakerDLL64.dll	: 1.0.0.1	
DTSSymmetryDLL64.dll	: 1.0.0.1	
DTSU2PGFX64.dll	: 2.0.15.0	
DTSU2PLFX64.dll	: 2.0.15.0	
DTSU2PREC64.dll	: 2.0.15.0	
DTSVoiceClarityDLL64.dll	: 1.0.0.1	
FMAP064.dll	: 43.6.16.65	
GrayJadeSkinImages64.dll	: 1.0.0.130	
KAAPORT64.dll	: 4.1104.6000.52	

LightSkinImages64.dll	: 1.0.0.130
MaxxAudioAPO20.dll	: 2.2.9.0
MaxxAudioAPO30.dll	: 3.2.1.1
MaxxAudioEQ.dll	: 2.0.0.0
MaxxAudioRealtek.dll	: 1.3.0.0
MaxxAudioRealtek2.dll	: 1.0.7.0
MaxxVolumeSDAPO.dll	: 3.1.0.0
MBAP032.dll	: 1.0.48.0
MBAP064.dll	: 1.0.48.0
MBPPCn64.dll	: 1.0.0.110
MBppld64.dll	: 1.0.48.0
MBTHX32.dll	: 1.0.15.146
MBTHX64.dll	: 1.0.15.146
MBWrp64.dll	: 1.0.0.180
PremiumBlackSkinImages64.dll	: 1.0.0.130
R4EEA64A.dll	: 7.2.7000.6
R4EED64A.dll	: 7.2.7000.6
R4EEG64A.dll	: 7.2.7000.6
R4EEL64A.dll	: 7.2.7000.6
R4EEP64A.dll	: 7.2.7000.6
RCoInst64.dll	: 1.1.6.3
RP3DAA64.dll	: 6.0.6001.18
RP3DHT64.dll	: 6.0.6001.18
RtCOM64.dll	: 2.0.0.146
RtCOMDLL.dll	: 2.0.0.146
RTEED64A.dll	: 6.1.6001.33
RTEEG64A.dll	: 6.1.6001.33
RTEEL64A.dll	: 6.1.6001.33
RTEEP64A.dll	: 6.1.6001.33
RtkApi64.dll	: 1.0.0.41
RtkAP064.dll	: 11.0.6000.233
RtkCfg.dll	: 1.0.0.1
RtkCfg64.dll	: 1.0.0.2
RtkGuiCompLib.dll	: 1.0.0.2
RtlCPAPI.dll	: 1.0.2.4
RtlCPAPI64.dll	: 1.0.2.4
RtPgEx64.dll	: 6.0.6000.221
SFAP064.dll	: 3.0.0.14
SFCOM.dll	: 3.0.0.11
SFCOM64.dll	: 3.0.0.14
SFComm64.dll	: 2.0.0.13
SFDAP064.dll	: 2.0.0.13
SFHAP064.dll	: 2.0.0.13
SFNHK64.dll	: 3.0.0.14
SFProc64.dll	: 2.0.0.13
SFSAP064.dll	: 2.0.0.13
SFSS_APO.dll	: 1.0.0.11110
slcc3d64.dll	: 1.0.0.100
slcshp64.dll	: 1.0.3.0
slcsii64.dll	: 1.0.3.0
slgeq64.dll	: 1.0.1.0
slh36064.dll	: 1.0.2.0
slhl1m64.dll	: 2.1.0.0
slInit64.dll	: 1.1.3.0
slmaxv64.dll	: 1.2.1.0
sltshd64.dll	: 1.2.0.0
sluapo64.dll	: 2.3.8.0
slvip64.dll	: 1.0.1.0
slviq64.dll	: 2.1.0.0
SRSHP64.dll	: 1.1.0.0
SRSTSH64.dll	: 1.1.4.0
SRSTSX64.dll	: 3.2.0.0
SRSWOW64.dll	: 1.1.3.0
tadefxapo.dll	: 1.0.1.12
tadefxapo264.dll	: 1.1.0.31
tepeqapo64.dll	: 1.0.0.3
tosade.dll	: 1.0.1.12
WavesGUILib.dll	: 2.0.0.0
RCORES64.dat	: 1.1.1.6

Readme.txt

HDM Driver : -----

Windows 2000/XP x86 :

RtkHDM.sys : 5.10.0.6409
Rtaupd.exe : 2.8.0.3
RHCoInstXP.dll : 1.1.5.1

Windows XP x64 :

RtkHDMX.sys : 5.10.0.6409
Rtaupd64.exe : 2.8.0.3
RHCoInst64XP.dll : 1.1.5.1

Vista/Win7 x86 :

RtHDMV.sys : 6.0.1.6409
RtkAudioSrvATI.exe : 1.0.0.23
RtkUpd.exe : 2.8.0.3
R4EEA32H.dll : 7.2.7000.6
R4EED32H.dll : 7.2.7000.6
R4EEG32H.dll : 7.2.7000.6
R4EEL32H.dll : 7.2.7000.6
R4EEP32H.dll : 7.2.7000.6
RH3DAA32.dll : 6.0.6001.18
RH3DHT32.dll : 6.0.6001.18
RHCoInst.dll : 1.1.5.1
RHDMExt.dll : 6.0.6000.213
RTEED32H.dll : 6.1.6001.33
RTEEG32H.dll : 6.1.6001.33
RTEEL32H.dll : 6.1.6001.33
RTEEP32H.dll : 6.1.6001.33
RtkHDM.dll : 11.0.6000.224

Vista/Win7 x64 :

RtHDMVX.sys : 6.0.1.6409
RtkAudioSrvATI64.exe : 1.0.0.23
RtkUpd64.exe : 2.8.0.3
R4EEA64H.dll : 7.2.7000.6
R4EED64H.dll : 7.2.7000.6
R4EEG64H.dll : 7.2.7000.6
R4EEL64H.dll : 7.2.7000.6
R4EEP64H.dll : 7.2.7000.6
RH3DAA64.dll : 6.0.6001.18
RH3DHT64.dll : 6.0.6001.18
RHCoInst64.dll : 1.1.5.1
RHDMEx64.dll : 6.0.6000.213
RTEED64H.dll : 6.1.6001.33
RTEEG64H.dll : 6.1.6001.33
RTEEL64H.dll : 6.1.6001.33
RTEEP64H.dll : 6.1.6001.33
RtkHDM64.dll : 11.0.6000.224

Driver Setup Program : 3.31

History:

Driver Package R2.64

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting:

ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889, ALC892, ALC899, ALC861VD, ALC660,
ALC662, ALC663, ALC665, ALC670, ALC672, ALC676, ALC680, ALC221, ALC231, ALC260, ALC262,
ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC275, ALC276

2. Windows 2000/XP WHQL Supporting:

ALC880, ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889, ALC892, ALC899, ALC861VC,
ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC670, ALC672, ALC676, ALC680, ALC221, ALC231,
ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC275, ALC276

3. HDM Device WHQL Support: ATI HDM Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008,

Windows7 - x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013) For Windows 2000 SP4, XP SP1, XP SP2, Server

2003 SP1.

6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :

RTKHDA64.sys	: 5.10.0.6438
RtkHDAud.sys	: 5.10.0.6438
Alcmtr.exe	: 1.6.0.4
AlcWzrd.exe	: 1.1.0.37
MicCal.exe	: 1.1.2.4
RTHDCPL.exe	: 2.4.0.2
RtkAudioService.exe	: 1.0.0.19
RtkAudioService64.exe	: 1.0.0.19
RTLCPPL.exe	: 1.0.1.66
RtlUpd.exe	: 2.8.0.4
RtlUpd64.exe	: 2.8.0.4
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.32
vncutil.exe	: 1.0.0.38
vncutil64.exe	: 1.0.0.38
AMBfilt.sys	: 5.10.0.4240
AMBft64.sys	: 5.10.0.4240
Mbnfilt.sys	: 5.10.0.4112
Mbnft64.sys	: 5.10.0.4115
0A017Afx.sys	: 1.0.7.3
ALSndMgr.cpl	: 1.0.0.11
RTSndMgr.cpl	: 1.0.1.7
RCoInst64XP.dll	: 1.1.6.3
RTCOMDLL.dll	: 1.0.0.113
RtkCoInstXP.dll	: 1.1.6.3
RtlCPAPI.dll	: 1.0.2.3

Vista/Win7 driver : -----

Vista/Win7 driver for x86

RTKVHDA.sys	: 6.0.1.6438
AERTSrv.exe	: 1.0.32.10
DTSAudioService.exe	: 1.0.0.0
DTSU2PAuSrv32.exe	: 2.0.15.0
FMAPP.exe	: 1.32.0.1
RtHDVBg.exe	: 1.0.0.75
RtHDVCpl.exe	: 1.0.0.723
RtkAudioService.exe	: 1.0.0.29
RtkNGUI.exe	: 1.0.0.130
RtlUpd.exe	: 2.8.0.4
SkyTel.exe	: 2.0.2.2
vncutil.exe	: 1.0.0.45
mbfilt32.sys	: 6.10.0.8
RTSndMgr.cpl	: 1.0.0.25
AERTACap.dll	: 2.0.32.13
AERTARen.dll	: 1.0.32.9
BlackSkinImages.dll	: 1.0.0.130
DarkSkinImages.dll	: 1.0.0.130
DTSBassEnhancementDLL.dll	: 1.0.0.1
DTSBoostDLL.dll	: 1.0.0.1
DTSGainCompensatorDLL.dll	: 1.0.0.1
DTSAFXAPO.dll	: 1.0.0.3
DTSAFXAPONS.dll	: 1.0.0.3
DTSLFXAPO.dll	: 1.0.0.3
DTSLimitterDLL.dll	: 1.0.0.1
DTSNeoPCDLL.dll	: 1.0.0.1
DTSS2HeadphoneDLL.dll	: 1.0.0.1
DTSS2SpeakerDLL.dll	: 1.0.0.1
DTSSymmetryDLL.dll	: 1.0.0.1
DTSU2PGFX32.dll	: 2.0.15.0
DTSU2PLFX32.dll	: 2.0.15.0
DTSU2PREC32.dll	: 2.0.15.0
DTSVoiceClarityDLL.dll	: 1.0.0.1

	Readme.txt	
FMAP0.dll		: 43.5.16.65
GrayJadeSkinImages.dll		: 1.0.0.130
KAAPORT.dll		: 4.1104.6000.52
LightSkinImages.dll		: 1.0.0.130
MaxxAudioAP0.dll		: 1.2.2.0
MaxxAudioAP020.dll		: 2.2.9.0
MaxxAudioAP030.dll		: 3.2.1.1
MaxxAudioEQ.dll		: 2.0.0.0
MaxxAudioRealtek2.dll		: 1.3.0.0
MaxxAudioRealtek.dll		: 1.0.7.0
MaxxVolumeSDAP0.dll		: 3.1.0.0
MBAP032.dll		: 1.0.48.0
MBPPCn32.dll		: 1.0.0.110
MBpld32.dll		: 1.0.48.0
MBTHX32.dll		: 1.0.15.146
MBWrp32.dll		: 1.0.0.180
PremiumBlackSkinImages.dll		: 1.0.0.130
R4EEA32A.dll		: 7.2.7000.6
R4EED32A.dll		: 7.2.7000.6
R4EEG32A.dll		: 7.2.7000.6
R4EEL32A.dll		: 7.2.7000.6
R4EEP32A.dll		: 7.2.7000.6
RP3DAA32.dll		: 6.0.6001.18
RP3DHT32.dll		: 6.0.6001.18
RTCOMDLL.dll		: 2.0.0.146
RTEED32A.dll		: 6.1.6001.33
RTEEG32A.dll		: 6.1.6001.33
RTEEL32A.dll		: 6.1.6001.33
RTEEP32A.dll		: 6.1.6001.33
RtkAP0.dll		: 11.0.6000.233
RtkApoApi.dll		: 1.0.0.41
RtkCfg.dll		: 1.0.0.2
RtkCoInst.dll		: 1.1.6.3
RtkGuiCompLib.dll		: 1.0.0.2
RtkPgExt.dll		: 6.0.6000.221
RtlCPAPI.dll		: 1.0.2.4
SFAP0.dll		: 3.0.0.14
SFCOM.dll		: 3.0.0.14
SFFXComm.dll		: 2.0.0.13
SFFXDAP0.dll		: 2.0.0.13
SFFXHAP0.dll		: 2.0.0.13
SFFXProc.dll		: 2.0.0.13
SFFXSAP0.dll		: 2.0.0.13
SFNHK.dll		: 3.0.0.14
slcc3d32.dll		: 1.0.0.100
slcshp32.dll		: 1.0.3.0
slcsii32.dll		: 1.0.3.0
slgeq32.dll		: 1.0.1.0
slh36032.dll		: 1.0.2.0
slhlimg32.dll		: 2.1.0.0
slInit32.dll		: 1.1.3.0
slmaxv32.dll		: 1.2.1.0
sltshd32.dll		: 1.2.0.0
sluapo32.dll		: 2.3.8.0
slvi pp32.dll		: 1.0.1.0
slviq32.dll		: 2.1.0.0
SRSHP360.dll		: 1.1.0.0
SRSTSHD.dll		: 1.1.4.0
SRSTSXT.dll		: 3.2.0.0
SRSWOW.dll		: 1.1.3.0
tadefxapo.dll		: 1.0.1.12
tadefxapo2.dll		: 1.1.0.31
tosade.dll		: 1.0.1.12
WavesGUILib.dll		: 2.0.0.0
WavesLib.dll		: 5.9.7.0
RCORES.dat		: 1.1.1.6
Vista/Win7 driver for x64 RTKVHD64.sys		: 6.0.1.6438

	Readme.txt	
AERTSr64.exe	:	1.0.64.10
DTSAudioService64.exe	:	1.0.0.0
DTSU2PAUSrv64.exe	:	2.0.15.0
FMAPP.exe	:	1.64.0.1
RAVBg64.exe	:	1.0.0.75
RAVCpl64.exe	:	1.0.0.723
RtkAudioService64.exe	:	1.0.0.29
RtkNGUI64.exe	:	1.0.0.130
RtlUpd64.exe	:	2.8.0.4
SkyTel.exe	:	2.0.2.2
vncutil64.exe	:	1.0.0.45
GWfilt64.sys	:	6.10.0.3
mbfilt64.sys	:	6.10.0.8
RTSnMg64.cpl	:	1.0.0.25
AERTAC64.dll	:	2.0.64.13
AERTAR64.dll	:	1.0.64.9
BlackSkinImages64.dll	:	1.0.0.130
DarkSkinImages64.dll	:	1.0.0.130
DTSBassEnhancementDLL64.dll	:	1.0.0.1
DTSBoostDLL64.dll	:	1.0.0.1
DTSGainCompensatorDLL64.dll	:	1.0.0.1
DTSAFXAP064.dll	:	1.0.0.3
DTSAFXAPONS64.dll	:	1.0.0.3
DTSAFXAP064.dll	:	1.0.0.3
DTSLimitDLL64.dll	:	1.0.0.1
DTSNeoPCDLL64.dll	:	1.0.0.1
DTSS2HeadphoneDLL64.dll	:	1.0.0.1
DTSS2SpeakerDLL64.dll	:	1.0.0.1
DTSSymmetryDLL64.dll	:	1.0.0.1
DTSU2PGFX64.dll	:	2.0.15.0
DTSU2PLFX64.dll	:	2.0.15.0
DTSU2PREC64.dll	:	2.0.15.0
DTSVoiceClarityDLL64.dll	:	1.0.0.1
FMAP064.dll	:	43.6.16.65
GrayJadeSkinImages64.dll	:	1.0.0.130
KAAPORT64.dll	:	4.1104.6000.52
LghtSkinImages64.dll	:	1.0.0.130
MaxxAudioAP020.dll	:	2.2.9.0
MaxxAudioAP030.dll	:	3.2.1.1
MaxxAudioEQ.dll	:	2.0.0.0
MaxxAudioRealtek.dll	:	1.3.0.0
MaxxAudioRealtek2.dll	:	1.0.7.0
MaxxVolumeSDAP0.dll	:	3.1.0.0
MBAP032.dll	:	1.0.48.0
MBAP064.dll	:	1.0.48.0
MBPPcn64.dll	:	1.0.0.110
Mbpld64.dll	:	1.0.48.0
MBTHX32.dll	:	1.0.15.146
MBTHX64.dll	:	1.0.15.146
MBWrp64.dll	:	1.0.0.180
PremiunBlackSkinImages64.dll	:	1.0.0.130
R4EEA64A.dll	:	7.2.7000.6
R4EED64A.dll	:	7.2.7000.6
R4EEG64A.dll	:	7.2.7000.6
R4EEL64A.dll	:	7.2.7000.6
R4EEP64A.dll	:	7.2.7000.6
RCoInst64.dll	:	1.1.6.3
RP3DAA64.dll	:	6.0.6001.18
RP3DHT64.dll	:	6.0.6001.18
RtCOMB4.dll	:	2.0.0.146
RTCOMDLL.dll	:	2.0.0.146
RTEED64A.dll	:	6.1.6001.33
RTEEG64A.dll	:	6.1.6001.33
RTEEL64A.dll	:	6.1.6001.33
RTEEP64A.dll	:	6.1.6001.33
RtkApi64.dll	:	1.0.0.41
RtkAP064.dll	:	11.0.6000.233
RtkCfg.dll	:	1.0.0.1
RtkCfg64.dll	:	1.0.0.2

	Readme.txt	
RtkGuiCompLib.dll	:	1.0.0.2
RtLCPAPI.dll	:	1.0.2.4
RtLCPAPI64.dll	:	1.0.2.4
RtPgEx64.dll	:	6.0.6000.221
SFAP064.dll	:	3.0.0.14
SFCOM.dll	:	3.0.0.11
SFCOM64.dll	:	3.0.0.14
SFComm64.dll	:	2.0.0.13
SFDAP064.dll	:	2.0.0.13
SFHAP064.dll	:	2.0.0.13
SFNHK64.dll	:	3.0.0.14
SFProc64.dll	:	2.0.0.13
SFSAP064.dll	:	2.0.0.13
SFSS_AP0.dll	:	1.0.0.11110
slcc3d64.dll	:	1.0.0.100
slcshp64.dll	:	1.0.3.0
slcsii64.dll	:	1.0.3.0
slgeq64.dll	:	1.0.1.0
slh36064.dll	:	1.0.2.0
slhlime64.dll	:	2.1.0.0
slInit64.dll	:	1.1.3.0
slmaxv64.dll	:	1.2.1.0
sltshd64.dll	:	1.2.0.0
sluapo64.dll	:	2.3.8.0
slvip64.dll	:	1.0.1.0
slviq64.dll	:	2.1.0.0
SRSHP64.dll	:	1.1.0.0
SRSTSH64.dll	:	1.1.4.0
SRSTX64.dll	:	3.2.0.0
SRSWOW64.dll	:	1.1.3.0
tadefxapo.dll	:	1.0.1.12
tadefxapo264.dll	:	1.1.0.31
tepeqapo64.dll	:	1.0.0.3
tosade.dll	:	1.0.1.12
WavesGUILib.dll	:	2.0.0.0
RCORES64.dat	:	1.1.1.6

HDM Driver :		
Windows 2000/XP x86 :		
RtkHDM.sys	:	5.10.0.6409
Rtaupd.exe	:	2.8.0.3
RHCoInstXP.dll	:	1.1.5.1
Windows XP x64 :		
RtkHDMX.sys	:	5.10.0.6409
Rtaupd64.exe	:	2.8.0.3
RHCoInst64XP.dll	:	1.1.5.1
Vista/Win7 x86 :		
RtHDMV.sys	:	6.0.1.6409
RtkAudioSrvATI.exe	:	1.0.0.23
RtkUpd.exe	:	2.8.0.3
R4EEA32H.dll	:	7.2.7000.6
R4EED32H.dll	:	7.2.7000.6
R4EEG32H.dll	:	7.2.7000.6
R4EEL32H.dll	:	7.2.7000.6
R4EEP32H.dll	:	7.2.7000.6
RH3DAA32.dll	:	6.0.6001.18
RH3DHT32.dll	:	6.0.6001.18
RHCoInst.dll	:	1.1.5.1
RHDMExt.dll	:	6.0.6000.213
RTEED32H.dll	:	6.1.6001.33
RTEEG32H.dll	:	6.1.6001.33
RTEEL32H.dll	:	6.1.6001.33
RTEEP32H.dll	:	6.1.6001.33
RtkHDM.dll	:	11.0.6000.224
Vista/Win7 x64 :		
RtHDMVX.sys	:	6.0.1.6409
RtkAudioSrvATI64.exe	:	1.0.0.23

Readme.txt

RtkUpd64.exe : 2.8.0.3
R4EEA64H.dll : 7.2.7000.6
R4EED64H.dll : 7.2.7000.6
R4EEG64H.dll : 7.2.7000.6
R4EEL64H.dll : 7.2.7000.6
R4EEP64H.dll : 7.2.7000.6
RH3DAA64.dll : 6.0.6001.18
RH3DHT64.dll : 6.0.6001.18
RHCoInst64.dll : 1.1.5.1
RHDME64.dll : 6.0.6000.213
RTEED64H.dll : 6.1.6001.33
RTEEG64H.dll : 6.1.6001.33
RTEEL64H.dll : 6.1.6001.33
RTEEP64H.dll : 6.1.6001.33
RtkHDM64.dll : 11.0.6000.224

Driver Setup Program : 3.31

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.63

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting:

ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889, ALC892, ALC899, ALC861VD, ALC660,
ALC662, ALC663, ALC665, ALC670, ALC672, ALC676, ALC680, ALC221, ALC231, ALC260, ALC262,
ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC275, ALC276

2. Windows 2000/XP WHQL Supporting:

ALC880, ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889, ALC892, ALC899, ALC861VC,
ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC670, ALC672, ALC676, ALC680 ALC221, ALC231,
ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC275, ALC276

3. HDM Device WHQL Support: ATI HDM Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008,

Windows7 - x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013) For Windows 2000 SP4, XP SP1, XP SP2, Server 2003 SP1.

6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :

RTKHDA64.sys : 5.10.0.6410
RtkHDAud.sys : 5.10.0.6410
MicCal.exe : 1.1.2.4
RTHDCPL.exe : 2.3.9.9
RtkAudioService64.exe : 1.0.0.19
RtkAudioService.exe : 1.0.0.19
RTLCP.exe : 1.0.1.66
RtlUpd64.exe : 2.8.0.3
RtlUpd.exe : 2.8.0.3
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.32
vncutil64.exe : 1.0.0.38
vncutil.exe : 1.0.0.38
Alcmtr.exe : 1.6.0.4
AlcWzrd.exe : 1.1.0.37
AMBfilt.sys : 5.10.0.4240
AMBft64.sys : 5.10.0.4240
Mbnfilt.sys : 5.10.0.4112
Mnft64.sys : 5.10.0.4115
OA017Afx.sys : 1.0.7.3
ALSndMgr.cpl : 1.0.0.11
RTSndMgr.cpl : 1.0.1.7
RCoInst64XP.dll : 1.1.5.1
RTCOMDLL.dll : 1.0.0.112

Readme.txt

RtkCoInstXP.dll : 1.1.5.1
 RtlCPAPI.dll : 1.0.2.3

Vista/Win7 driver : -----

Vista/Win7 driver for x86
 RTKVHDA.sys : 6.0.1.6410
 AERTSrv.exe : 1.0.32.10
 DTSAudioService.exe : 1.0.0.0
 FMAPP.exe : 1.32.0.1
 RtHDVBg.exe : 1.0.0.70
 RtHDVCpl.exe : 1.0.0.710
 RtkAudioService.exe : 1.0.0.29
 RtkNGUI.exe : 1.0.0.122
 RtlUpd.exe : 2.8.0.3
 SkyTel.exe : 2.0.2.2
 vncutil.exe : 1.0.0.44
 mbfilt32.sys : 6.10.0.8
 RTSndMgr.cpl : 1.0.0.25
 AERTACap.dll : 2.0.32.13
 AERTARen.dll : 1.0.32.9
 BlackSkinImages.dll : 1.0.0.122
 DarkSkinImages.dll : 1.0.0.122
 DTSBassEnhancementDLL.dll : 1.0.0.1
 DTSTBoostDLL.dll : 1.0.0.1
 DTSGainCompensatorDLL.dll : 1.0.0.1
 DTSGFXAPO.dll : 1.0.0.3
 DTSGFXAPONS.dll : 1.0.0.3
 DTSLFXAPO.dll : 1.0.0.3
 DTSLimiterDLL.dll : 1.0.0.1
 DTSSNeoPCDLL.dll : 1.0.0.1
 DTSS2HeadphoneDLL.dll : 1.0.0.1
 DTSS2SpeakerDLL.dll : 1.0.0.1
 DTSSymmetryDLL.dll : 1.0.0.1
 DTSSVoiceClarityDLL.dll : 1.0.0.1
 FMAP0.dll : 43.5.16.65
 GrayJadeSkinImages.dll : 1.0.0.122
 KAAPORT.dll : 4.1104.6000.51
 LightSkinImages.dll : 1.0.0.122
 MaxxAudioAPO.dll : 1.2.2.0
 MaxxAudioAPO20.dll : 2.2.9.0
 MaxxAudioAPO30.dll : 3.2.1.1
 MaxxAudioEQ.dll : 5.9.7.0
 MaxxAudioRealtek.dll : 1.3.0.0
 MaxxAudioRealtek2.dll : 1.0.7.0
 MaxxVolumeSDAPO.dll : 3.1.0.0
 MBAP032.dll : 1.0.43.0
 MBPPCn32.dll : 1.0.0.110
 MBpld32.dll : 1.0.43.0
 MBTHX32.dll : 1.0.15.142
 MBWrp32.dll : 1.0.0.180
 PremiumBlackSkinImages.dll : 1.0.0.122
 R4EEA32A.dll : 7.2.7000.6
 R4EED32A.dll : 7.2.7000.6
 R4EEG32A.dll : 7.2.7000.6
 R4EEL32A.dll : 7.2.7000.6
 R4EEP32A.dll : 7.2.7000.6
 RP3DAA32.dll : 6.0.6001.18
 RP3DHT32.dll : 6.0.6001.18
 RTCOMDLL.dll : 2.0.0.145
 RTEED32A.dll : 6.1.6001.33
 RTEEG32A.dll : 6.1.6001.33
 RTEEL32A.dll : 6.1.6001.33
 RTEEP32A.dll : 6.1.6001.33
 RtkAPO.dll : 11.0.6000.222
 RtkApoApi.dll : 1.0.0.39
 RtkCfg.dll : 1.0.0.2
 RtkCoInst.dll : 1.1.5.1
 RtkGuiCompLib.dll : 1.0.0.2
 RtkPgExt.dll : 6.0.6000.212

	Readme.txt	
Rt1CPAPI.dll	:	1.0.2.4
SFAPO.dll	:	3.0.0.14
SFCOM.dll	:	3.0.0.14
SFFXComm.dll	:	2.0.0.13
SFFXDAP0.dll	:	2.0.0.13
SFFXHAP0.dll	:	2.0.0.13
SFFXProc.dll	:	2.0.0.13
SFFXSAP0.dll	:	2.0.0.13
SFNHK.dll	:	3.0.0.14
slcc3d32.dll	:	1.0.0.100
slcshp32.dll	:	1.0.3.0
slcsi32.dll	:	1.0.3.0
slgeq32.dll	:	1.0.1.0
slh36032.dll	:	1.0.2.0
slhlimg32.dll	:	2.1.0.0
slInit32.dll	:	1.1.3.0
slmaxv32.dll	:	1.2.1.0
sltshd32.dll	:	1.2.0.0
sluapo32.dll	:	2.2.2.0
slvi pp32.dll	:	1.0.1.0
slviq32.dll	:	2.1.0.0
SRSHP360.dll	:	1.1.0.0
SRSTSHD.dll	:	1.1.4.0
SRSTSXT.dll	:	3.2.0.0
SRSWOW.dll	:	1.1.3.0
tadefxapo.dll	:	1.0.1.12
tadefxapo2.dll	:	1.1.0.31
tosade.dll	:	1.0.1.12
WavesGUILib.dll	:	1.1.0.0
WavesLib.dll	:	5.9.7.0
RCORES.dat	:	1.1.1.0
Vista/Win7 driver for x64		
RTKVHD64.sys	:	6.0.1.6410
AERTSr64.exe	:	1.0.64.10
DTSAudioService64.exe	:	1.0.0.0
FMAPP.exe	:	1.64.0.1
RAVBg64.exe	:	1.0.0.70
RAVCpl64.exe	:	1.0.0.710
RtkAudioService64.exe	:	1.0.0.29
RtkNGUI64.exe	:	1.0.0.122
RtlUpd64.exe	:	2.8.0.3
SkyTel.exe	:	2.0.2.2
vncutil64.exe	:	1.0.0.44
GWfilt64.sys	:	6.10.0.3
mbfilt64.sys	:	6.10.0.8
RTSnMg64.cpl	:	1.0.0.25
AERTAC64.dll	:	2.0.64.13
AERTAR64.dll	:	1.0.64.9
BlackSkinImages64.dll	:	1.0.0.122
DarkSkinImages64.dll	:	1.0.0.122
DTSBassEnhancementDLL64.dll	:	1.0.0.1
DTSBoostDLL64.dll	:	1.0.0.1
DTSGainCompensatorDLL64.dll	:	1.0.0.1
DTSAFXAP064.dll	:	1.0.0.3
DTSAFXAPONS64.dll	:	1.0.0.3
DTSAFXAP064.dll	:	1.0.0.3
DTSLimitDLL64.dll	:	1.0.0.1
DTSNeoPCDLL64.dll	:	1.0.0.1
DTSS2HeadphoneDLL64.dll	:	1.0.0.1
DTSS2SpeakerDLL64.dll	:	1.0.0.1
DTSSymmetryDLL64.dll	:	1.0.0.1
DTSVoiceClarityDLL64.dll	:	1.0.0.1
FMAP064.dll	:	43.6.16.65
GrayJadeSkinImages64.dll	:	1.0.0.122
KAAPORT64.dll	:	4.1104.6000.51
LghtSkinImages64.dll	:	1.0.0.122
MaxxAudioAP020.dll	:	2.2.9.0
MaxxAudioAP030.dll	:	3.2.1.1

	Readme.txt	
MaxxAudioEQ.dll		: 5.9.7.0
MaxxAudioRealtek.dll		: 1.3.0.0
MaxxAudioRealtek2.dll		: 1.0.7.0
MaxxVolumeSDAPO.dll		: 3.1.0.0
MBAP032.dll		: 1.0.43.0
MBAP064.dll		: 1.0.43.0
MBPPCn64.dll		: 1.0.0.110
MBpld64.dll		: 1.0.43.0
MBTHX32.dll		: 1.0.15.142
MBTHX64.dll		: 1.0.15.142
MBWrp64.dll		: 1.0.0.180
PremiumBlackSkinImages64.dll		: 1.0.0.122
R4EEA64A.dll		: 7.2.7000.6
R4EED64A.dll		: 7.2.7000.6
R4EEG64A.dll		: 7.2.7000.6
R4EEL64A.dll		: 7.2.7000.6
R4EEP64A.dll		: 7.2.7000.6
RCoInst64.dll		: 1.1.5.1
RP3DAA64.dll		: 6.0.6001.18
RP3DHT64.dll		: 6.0.6001.18
RtCOM64.dll		: 2.0.0.145
RTCOMDLL.dll		: 2.0.0.145
RTEED64A.dll		: 6.1.6001.33
RTEEG64A.dll		: 6.1.6001.33
RTEEL64A.dll		: 6.1.6001.33
RTEEP64A.dll		: 6.1.6001.33
RtkApi64.dll		: 1.0.0.39
RtkAPO64.dll		: 11.0.6000.222
RtkCfg.dll		: 1.0.0.1
RtkCfg64.dll		: 1.0.0.2
RtkGuiCompLib.dll		: 1.0.0.2
RtLCPAPI.dll		: 1.0.2.4
RtLCPAPI64.dll		: 1.0.2.4
RtPgEx64.dll		: 6.0.6000.212
SFAP064.dll		: 3.0.0.14
SFCOM.dll		: 3.0.0.11
SFCOM64.dll		: 3.0.0.14
SFComm64.dll		: 2.0.0.13
SFDAP064.dll		: 2.0.0.13
SFHAP064.dll		: 2.0.0.13
SFNHK64.dll		: 3.0.0.14
SFProc64.dll		: 2.0.0.13
SFSAP064.dll		: 2.0.0.13
SFSS_APO.dll		: 1.0.0.11110
slcc3d64.dll		: 1.0.0.100
slcshp64.dll		: 1.0.3.0
slcsii64.dll		: 1.0.3.0
slgeq64.dll		: 1.0.1.0
slh36064.dll		: 1.0.2.0
slhlimg64.dll		: 2.1.0.0
slInit64.dll		: 1.1.3.0
slmaxv64.dll		: 1.2.1.0
sltshd64.dll		: 1.2.0.0
sluapo64.dll		: 2.2.2.0
slvi pp64.dll		: 1.0.1.0
slviq64.dll		: 2.1.0.0
SRSHP64.dll		: 1.1.0.0
SRSTSH64.dll		: 1.1.4.0
SRSTX64.dll		: 3.2.0.0
SRSWOW64.dll		: 1.1.3.0
tadefxapo.dll		: 1.0.1.12
tadefxapo264.dll		: 1.1.0.31
tosade.dll		: 1.0.1.12
WavesGUILib.dll		: 1.1.0.0
RCORES64.dat		: 1.1.1.0

HDMI Driver :		
Vista/Win7 x86:		
RtHDMV.sys		: 6.0.1.6358
RtkAudioSrvATI.exe		: 1.0.0.23

Readme.txt

RtkUpd.exe : 2.8.0.3
RH3DAA32.dll : 6.0.6001.18
RH3DHT32.dll : 6.0.6001.18
RHCoInst.dll : 1.1.1.2
RHDMEExt.dll : 6.0.6000.172
RTEED32H.dll : 6.1.6001.33
RTEEG32H.dll : 6.1.6001.33
RTEEL32H.dll : 6.1.6001.33
RTEEP32H.dll : 6.1.6001.33
RtkHDM.dll : 11.0.6000.183

Vista/Win7 x64:

RtkHDMVX.sys : 6.0.1.6358
RtkAudioSrvATI64.exe : 1.0.0.23
RtkUpd64.exe : 2.8.0.3
RH3DAA64.dll : 6.0.6001.18
RH3DHT64.dll : 6.0.6001.18
RHCoInst64.dll : 1.1.1.2
RHDME64.dll : 6.0.6000.172
RTEED64H.dll : 6.1.6001.33
RTEEG64H.dll : 6.1.6001.33
RTEEL64H.dll : 6.1.6001.33
RTEEP64H.dll : 6.1.6001.33
RtkHDM64.dll : 11.0.6000.183

XP/2K x86:

RtkHDM.sys : 5.10.0.6358
Rtaupd.exe : 2.8.0.3
RHCoInstXP.dll : 1.1.1.2

XP/2K x64:

RtkHDMX.sys : 5.10.0.6358
Rtaupd64.exe : 2.8.0.3
RHCoInst64XP.dll : 1.1.1.2

Driver Setup Program : 3.30

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.62

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting:

ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889, ALC892, ALC899, ALC861VD, ALC660,
ALC662, ALC663, ALC665, ALC670, ALC672, ALC676, ALC680, ALC221, ALC231, ALC260, ALC262,
ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC275, ALC276

2. Windows 2000/XP WHQL Supporting:

ALC880, ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889, ALC892, ALC899, ALC861VC,
ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC670, ALC672, ALC676, ALC680, ALC221, ALC231,
ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC275, ALC276

3. HDM Device WHQL Support: ATI HDM Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008,

Windows7 - x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013) For Windows 2000 SP4, XP SP1, XP SP2, Server 2003 SP1.

6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :

RTKHDA64.sys : 5.10.0.6392
RtkHDAud.sys : 5.10.0.6392
Alcmtr.exe : 1.6.0.4
AlcWzrd.exe : 1.1.0.37
McCal.exe : 1.1.2.4

```

Readme.txt
RTHDCPL.exe : 2.3.9.5
RtkAudioService.exe : 1.0.0.19
RtkAudioService64.exe : 1.0.0.19
RTLCPPL.exe : 1.0.1.66
RtlUpd.exe : 2.8.0.3
RtlUpd64.exe : 2.8.0.3
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.32
vncutil.exe : 1.0.0.38
vncutil64.exe : 1.0.0.38
AMBfilt.sys : 5.10.0.4240
AMBft64.sys : 5.10.0.4240
Mbnfilt.sys : 5.10.0.4112
Mbnft64.sys : 5.10.0.4115
OA017Afx.sys : 1.0.7.3
ALSndMgr.cpl : 1.0.0.11
RTSndMgr.cpl : 1.0.1.6
RCoInst64XP.dll : 1.1.3.8
RTCOMDLL.dll : 1.0.0.112
RtkCoInstXP.dll : 1.1.3.8
RtlCPAPI.dll : 1.0.2.3
Vista/Win7 driver : -----
Vista/Win7 driver for x86
RTKVHDA.sys : 6.0.1.6392
AERTSrv.exe : 1.0.32.10
DTSAudioService.exe : 1.0.0.0
FMAPP.exe : 1.32.0.1
RtHDVBg.exe : 1.0.0.70
RtHDVCpl.exe : 1.0.0.700
RtkAudioService.exe : 1.0.0.29
RtkNGUI.exe : 1.0.0.116
RtlUpd.exe : 2.8.0.3
SkyTel.exe : 2.0.2.2
vncutil.exe : 1.0.0.44
mbfilt32.sys : 6.10.0.8
RTSndMgr.cpl : 1.0.0.24
AERTACap.dll : 2.0.32.13
AERTARen.dll : 1.0.32.9
BlackSkinImages.dll : 1.0.0.116
DarkSkinImages.dll : 1.0.0.116
DTSBassEnhancementDLL.dll : 1.0.0.1
DTSBoostDLL.dll : 1.0.0.1
DTSGainCompensatorDLL.dll : 1.0.0.1
DTSGFXAPO.dll : 1.0.0.3
DTSGFXAPONS.dll : 1.0.0.3
DTSLFXAPO.dll : 1.0.0.3
DTSLimiterDLL.dll : 1.0.0.1
DTSNeoPCDLL.dll : 1.0.0.1
DTSS2HeadphoneDLL.dll : 1.0.0.1
DTSS2SpeakerDLL.dll : 1.0.0.1
DTSSymmetryDLL.dll : 1.0.0.1
DTSVoiceClarityDLL.dll : 1.0.0.1
FMAP0.dll : 43.5.16.65
GrayJadeSkinImages.dll : 1.0.0.116
KAAPORT.dll : 4.1104.6000.51
LightSkinImages.dll : 1.0.0.116
MaxxAudioAPO.dll : 1.2.2.0
MaxxAudioAPO20.dll : 2.2.9.0
MaxxAudioAPO30.dll : 3.2.1.1
MaxxAudioEQ.dll : 5.9.7.0
MaxxAudioRealtek.dll : 1.2.0.0
MaxxAudioRealtek2.dll : 1.0.7.0
MaxxVolumeSDAPO.dll : 3.1.0.0
MBAP032.dll : 1.0.43.0
MBPPCn32.dll : 1.0.0.110
MBppld32.dll : 1.0.43.0
MBTHX32.dll : 1.0.15.141
MBWrp32.dll : 1.0.0.180
PremiumBlackSkinImages.dll : 1.0.0.116

```


	Readme.txt	
R4EEA32A.dll		: 7.2.7000.6
R4EED32A.dll		: 7.2.7000.6
R4EEG32A.dll		: 7.2.7000.6
R4EEL32A.dll		: 7.2.7000.6
R4EEP32A.dll		: 7.2.7000.6
RP3DAA32.dll		: 6.0.6001.18
RP3DHT32.dll		: 6.0.6001.18
RTCOMDLL.dll		: 2.0.0.145
RTEED32A.dll		: 6.1.6001.33
RTEEG32A.dll		: 6.1.6001.33
RTEEL32A.dll		: 6.1.6001.33
RTEEP32A.dll		: 6.1.6001.33
RtkAPO.dll		: 11.0.6000.216
RtkApoApi.dll		: 1.0.0.38
RtkCfg.dll		: 1.0.0.2
RtkCoInst.dll		: 1.1.4.5
RtkGuiCompLib.dll		: 1.0.0.2
RtkPgExt.dll		: 6.0.6000.204
RtlCPAPI.dll		: 1.0.2.4
SFAPO.dll		: 3.0.0.14
SFCOM.dll		: 3.0.0.14
SFFXComm.dll		: 2.0.0.13
SFFXDAP0.dll		: 2.0.0.13
SFFXHAP0.dll		: 2.0.0.13
SFFXProc.dll		: 2.0.0.13
SFFXSAP0.dll		: 2.0.0.13
SFNHK.dll		: 3.0.0.14
slcc3d32.dll		: 1.0.0.100
slcshp32.dll		: 1.0.3.0
slcsi32.dll		: 1.0.3.0
slgeq32.dll		: 1.0.1.0
slh36032.dll		: 1.0.2.0
slhlimg32.dll		: 2.1.0.0
slInit32.dll		: 1.1.3.0
slmaxv32.dll		: 1.2.1.0
sltshd32.dll		: 1.2.0.0
sluapo32.dll		: 2.2.2.0
slvi32.dll		: 1.0.1.0
slviq32.dll		: 2.1.0.0
SRSHP360.dll		: 1.1.0.0
SRSTSHD.dll		: 1.1.4.0
SRSTSXT.dll		: 3.2.0.0
SRSWOW.dll		: 1.1.3.0
tadefxapo.dll		: 1.0.1.12
tosade.dll		: 1.0.1.12
WavesGUILib.dll		: 1.2.0.0
WavesLib.dll		: 5.9.7.0
Vista/Win7 driver for x64		
RTKVHD64.sys		: 6.0.1.6392
AERTSr64.exe		: 1.0.64.10
DTSAudioService64.exe		: 1.0.0.0
FMAPP.exe		: 1.64.0.1
RAVBg64.exe		: 1.0.0.70
RAVCpl64.exe		: 1.0.0.700
RtkAudioService64.exe		: 1.0.0.29
RtkNGUI64.exe		: 1.0.0.116
RtlUpd64.exe		: 2.8.0.3
SkyTel.exe		: 2.0.2.2
vncutil64.exe		: 1.0.0.44
GWfilt64.sys		: 6.10.0.3
mbfilt64.sys		: 6.10.0.8
RTSnMg64.cpl		: 1.0.0.24
AERTAC64.dll		: 2.0.64.13
AERTAR64.dll		: 1.0.64.9
BlackSkinImages64.dll		: 1.0.0.116
DarkSkinImages64.dll		: 1.0.0.116
DTSBassEnhancementDLL64.dll		: 1.0.0.1
DTSBoostDLL64.dll		: 1.0.0.1
DTSGainCompensatorDLL64.dll		: 1.0.0.1

	Readme.txt	
DTSGFXAP064.dll	:	1.0.0.3
DTSGFXAPONS64.dll	:	1.0.0.3
DTSLFXAP064.dll	:	1.0.0.3
DTSLimiterDLL64.dll	:	1.0.0.1
DTSSNeoPCDLL64.dll	:	1.0.0.1
DTSS2HeadphoneDLL64.dll	:	1.0.0.1
DTSS2SpeakerDLL64.dll	:	1.0.0.1
DTSSymmetryDLL64.dll	:	1.0.0.1
DTSVoiceClarityDLL64.dll	:	1.0.0.1
FMAP064.dll	:	43.6.16.65
GrayJadeSkinImages64.dll	:	1.0.0.116
KAAPORT64.dll	:	4.1104.6000.51
LightSkinImages64.dll	:	1.0.0.116
MaxxAudioAP020.dll	:	2.2.9.0
MaxxAudioAP030.dll	:	3.2.1.1
MaxxAudioEQ.dll	:	5.9.7.0
MaxxAudioRealtek.dll	:	1.2.0.0
MaxxAudioRealtek2.dll	:	1.0.7.0
MaxxVolumeSDAPO.dll	:	3.1.0.0
MBAP032.dll	:	1.0.43.0
MBAP064.dll	:	1.0.43.0
MBPPcn64.dll	:	1.0.0.110
Mbpld64.dll	:	1.0.43.0
MBTHX32.dll	:	1.0.15.141
MBTHX64.dll	:	1.0.15.141
MBWrp64.dll	:	1.0.0.180
PremiumBlackSkinImages64.dll	:	1.0.0.116
R4EEA64A.dll	:	7.2.7000.6
R4EED64A.dll	:	7.2.7000.6
R4EEG64A.dll	:	7.2.7000.6
R4EEL64A.dll	:	7.2.7000.6
R4EEP64A.dll	:	7.2.7000.6
RCoInst64.dll	:	1.1.4.5
RP3DAA64.dll	:	6.0.6001.18
RP3DHT64.dll	:	6.0.6001.18
RtCOMB4.dll	:	2.0.0.145
RTCOMDLL.dll	:	2.0.0.145
RTEED64A.dll	:	6.1.6001.33
RTEEG64A.dll	:	6.1.6001.33
RTEEL64A.dll	:	6.1.6001.33
RTEEP64A.dll	:	6.1.6001.33
RtkApi64.dll	:	1.0.0.38
RtkAP064.dll	:	11.0.6000.216
RtkCfg.dll	:	1.0.0.1
RtkCfg64.dll	:	1.0.0.2
RtkGuiCompLib.dll	:	1.0.0.2
RtLCPAPI.dll	:	1.0.2.4
RtLCPAPI64.dll	:	1.0.2.4
RtPgEx64.dll	:	6.0.6000.204
SFAP064.dll	:	3.0.0.14
SFCOM.dll	:	3.0.0.11
SFCOMB4.dll	:	3.0.0.14
SFComm64.dll	:	2.0.0.13
SFDAP064.dll	:	2.0.0.13
SFHAP064.dll	:	2.0.0.13
SFNHK64.dll	:	3.0.0.14
SFProc64.dll	:	2.0.0.13
SFSAP064.dll	:	2.0.0.13
SFSS_AP0.dll	:	1.0.0.11110
slcc3d64.dll	:	1.0.0.100
slcshp64.dll	:	1.0.3.0
slcsi64.dll	:	1.0.3.0
slgeq64.dll	:	1.0.1.0
slh36064.dll	:	1.0.2.0
slhl1m64.dll	:	2.1.0.0
slInit64.dll	:	1.1.3.0
slmaxv64.dll	:	1.2.1.0
sltshd64.dll	:	1.2.0.0
sluapo64.dll	:	2.2.2.0

Readme.txt

```

slvi pp64.dll : 1.0.1.0
slvi q64.dll : 2.1.0.0
SRSHp64.dll : 1.1.0.0
SRSTSH64.dll : 1.1.4.0
SRSTSx64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
tadefxapo.dll : 1.0.1.12
tosade.dll : 1.0.1.12
WavesGUILib.dll : 1.2.0.0
HDM Driver : -----
Vista/WIn7 x86:
RtHDMV.sys : 6.0.1.6358
RtkAudioSrvATI.exe : 1.0.0.23
RtkUpd.exe : 2.8.0.3
RH3DAA32.dll : 6.0.6001.18
RH3DHT32.dll : 6.0.6001.18
RHCoInst.dll : 1.1.1.2
RHDMEExt.dll : 6.0.6000.172
RTEED32H.dll : 6.1.6001.33
RTEEG32H.dll : 6.1.6001.33
RTEEL32H.dll : 6.1.6001.33
RTEEP32H.dll : 6.1.6001.33
RtkHDM.dll : 11.0.6000.183

Vista/WIn7 x64:
RtHDMVX.sys : 6.0.1.6358
RtkAudioSrvATI64.exe : 1.0.0.23
RtkUpd64.exe : 2.8.0.3
RH3DAA64.dll : 6.0.6001.18
RH3DHT64.dll : 6.0.6001.18
RHCoInst64.dll : 1.1.1.2
RHDMEx64.dll : 6.0.6000.172
RTEED64H.dll : 6.1.6001.33
RTEEG64H.dll : 6.1.6001.33
RTEEL64H.dll : 6.1.6001.33
RTEEP64H.dll : 6.1.6001.33
RtkHDM64.dll : 11.0.6000.183

XP/2K x86:
RtkHDM.sys : 5.10.0.6358
Rtaupd.exe : 2.8.0.3
RHCoInstXP.dll : 1.1.1.2

XP/2K x64:
RtkHDMX.sys : 5.10.0.6358
Rtaupd64.exe : 2.8.0.3
RHCoInst64XP.dll : 1.1.1.2

Driver Setup Program : 3.25

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

```

//=====

Driver Package R2.61

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting:

ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889, ALC892, ALC899, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC670, ALC672, ALC676, ALC680, ALC221, ALC231, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC275, ALC276

2. Windows 2000/XP WHQL Supporting:

ALC880, ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889, ALC892, ALC899, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC670, ALC672, ALC676, ALC680, ALC221, ALC231, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC275, ALC276

3. HDM Device WHQL Support: ATI HDM Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008,

Windows7 - x86/x64

Readme.txt

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013) For Windows 2000 SP4, XP SP1, XP SP2, Server 2003 SP1.

6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :
 RTKHDA64.sys : 5.10.0.6383
 RtkHDAud.sys : 5.10.0.6383
 Alcmtr.exe : 1.6.0.4
 AlcWzrd.exe : 1.1.0.37
 McCal.exe : 1.1.2.4
 RTHDCPL.exe : 2.3.9.5
 RtkAudioService64.exe : 1.0.0.19
 RtkAudioService.exe : 1.0.0.19
 RTLCPL.exe : 1.0.1.66
 RtlUpd64.exe : 2.8.0.3
 RtlUpd.exe : 2.8.0.3
 SkyTel.exe : 2.0.2.0
 SoundMan.exe : 1.0.0.32
 vncutil64.exe : 1.0.0.38
 vncutil.exe : 1.0.0.38
 AMBFilt.sys : 5.10.0.4240
 AMBFt64.sys : 5.10.0.4240
 Mbnfilt.sys : 5.10.0.4112
 Mbnft64.sys : 5.10.0.4115
 OA017Afx.sys : 1.0.7.3
 ALSndMgr.cpl : 1.0.0.11
 RTSndMgr.cpl : 1.0.1.6
 RCoInst64XP.dll : 1.1.3.8
 RTCOMDLL.dll : 1.0.0.112
 RtkCoInstXP.dll : 1.1.3.8
 RtlCPAPI.dll : 1.0.2.3

Vista/Wn7 driver : -----

Vista/Wn7 driver for x86
 RTKVHDA.sys : 6.0.1.6383
 AERTSrv.exe : 1.0.32.10
 DTSAudioService.exe : 1.0.0.0
 FMAPP.exe : 1.32.0.1
 RtHDVBg.exe : 1.0.0.69
 RtHDVCpl.exe : 1.0.0.667
 RtkAudioService.exe : 1.0.0.29
 RtkNGUI.exe : 1.0.0.113
 RtlUpd.exe : 2.8.0.3
 SkyTel.exe : 2.0.2.2
 vncutil.exe : 1.0.0.44
 mbfilt32.sys : 6.10.0.8
 RTSndMgr.cpl : 1.0.0.22
 AERTACap.dll : 2.0.32.13
 AERTARen.dll : 1.0.32.9
 BlackSkinImages.dll : 1.0.0.113
 DarkSkinImages.dll : 1.0.0.113
 DTSSBassEnhancementDLL.dll : 1.0.0.1
 DTSSBoostDLL.dll : 1.0.0.1
 DTSSGainCompensatorDLL.dll : 1.0.0.1
 DTSSGFXAPO.dll : 1.0.0.3
 DTSSGFXAPONS.dll : 1.0.0.3
 DTSSLFXAPO.dll : 1.0.0.3
 DTSLimiterDLL.dll : 1.0.0.1
 DTSSNeoPCDLL.dll : 1.0.0.1
 DTSS2HeadphoneDLL.dll : 1.0.0.1
 DTSS2SpeakerDLL.dll : 1.0.0.1
 DTSSSymmetryDLL.dll : 1.0.0.1
 DTSSVoiceClarityDLL.dll : 1.0.0.1
 FMAPO.dll : 43.5.16.65
 GrayJadeSkinImages.dll : 1.0.0.113
 KAAPORT.dll : 4.1102.6000.49
 LightSkinImages.dll : 1.0.0.113

	Readme.txt	
MaxxAudioAPO.dll		: 1.2.2.0
MaxxAudioAPO20.dll		: 2.2.9.0
MaxxAudioAPO30.dll		: 3.2.1.1
MaxxAudioEQ.dll		: 5.9.7.0
MaxxAudioRealtek.dll		: 1.2.0.0
MaxxAudioRealtek2.dll		: 1.0.7.0
MaxxVolumeSDAPO.dll		: 3.1.0.0
MBAP032.dll		: 1.0.43.0
MBPPCn32.dll		: 1.0.0.110
MBpld32.dll		: 1.0.43.0
MBTHX32.dll		: 1.0.15.138
MBWrp32.dll		: 1.0.0.180
PremiumBlackSkinImages.dll		: 1.0.0.113
R4EEA32A.dll		: 7.2.7000.6
R4EED32A.dll		: 7.2.7000.6
R4EEG32A.dll		: 7.2.7000.6
R4EEL32A.dll		: 7.2.7000.6
R4EEP32A.dll		: 7.2.7000.6
RP3DAA32.dll		: 6.0.6001.18
RP3DHT32.dll		: 6.0.6001.18
RTCOMDLL.dll		: 2.0.0.145
RTEED32A.dll		: 6.1.6001.33
RTEEG32A.dll		: 6.1.6001.33
RTEEL32A.dll		: 6.1.6001.33
RTEEP32A.dll		: 6.1.6001.33
RtkAPO.dll		: 11.0.6000.216
RtkApoApi.dll		: 1.0.0.36
RtkCfg.dll		: 1.0.0.2
RtkColInst.dll		: 1.1.4.4
RtkGuiCompLib.dll		: 1.0.0.2
RtkPgExt.dll		: 6.0.6000.203
RtlCPAPI.dll		: 1.0.2.4
SFAP0.dll		: 3.0.0.14
SFCOM.dll		: 3.0.0.14
SFFXComm.dll		: 2.0.0.13
SFFXDAP0.dll		: 2.0.0.13
SFFXHAP0.dll		: 2.0.0.13
SFFXProc.dll		: 2.0.0.13
SFFXSAP0.dll		: 2.0.0.13
SFNHK.dll		: 3.0.0.14
slcc3d32.dll		: 1.0.0.100
slcshp32.dll		: 1.0.3.0
slcsl32.dll		: 1.0.3.0
slgeq32.dll		: 1.0.1.0
slh36032.dll		: 1.0.2.0
slhlin32.dll		: 2.1.0.0
slInit32.dll		: 1.1.3.0
slmaxv32.dll		: 1.2.1.0
sltshd32.dll		: 1.2.0.0
sluapo32.dll		: 2.2.2.0
slvip32.dll		: 1.0.1.0
slviq32.dll		: 2.1.0.0
SRSHP360.dll		: 1.1.0.0
SRSTSHD.dll		: 1.1.4.0
SRSTSXT.dll		: 3.2.0.0
SRSWOW.dll		: 1.1.3.0
tadefxapo.dll		: 1.0.1.12
tosade.dll		: 1.0.1.12
WavesGUILib.dll		: 1.2.0.0
WavesLib.dll		: 5.9.7.0
Vista/Win7 driver for x64		
RTKVHD64.sys		: 6.0.1.6383
AERTSr64.exe		: 1.0.64.10
DTSAudioService64.exe		: 1.0.0.0
FMAPP.exe		: 1.64.0.1
RAVBg64.exe		: 1.0.0.69
RAVCpl64.exe		: 1.0.0.667
RtkAudioService64.exe		: 1.0.0.29
RtkNGUI64.exe		: 1.0.0.113

RtlUpd64.exe	: 2.8.0.3
SkyTel.exe	: 2.0.2.2
vncutil64.exe	: 1.0.0.44
GWfilt64.sys	: 6.10.0.3
mbfilt64.sys	: 6.10.0.8
RTSnMg64.cpl	: 1.0.0.22
AERTAC64.dll	: 2.0.64.13
AERTAR64.dll	: 1.0.64.9
BlackSkinImages64.dll	: 1.0.0.113
DarkSkinImages64.dll	: 1.0.0.113
DTSBassEnhancementDLL64.dll	: 1.0.0.1
DTSBoostDLL64.dll	: 1.0.0.1
DTSGainCompensatorDLL64.dll	: 1.0.0.1
DTSAFXAP064.dll	: 1.0.0.3
DTSAFXAPONS64.dll	: 1.0.0.3
DTSAFXAP064.dll	: 1.0.0.3
DTSLimitDLL64.dll	: 1.0.0.1
DTSNeoPCDLL64.dll	: 1.0.0.1
DTSS2HeadphoneDLL64.dll	: 1.0.0.1
DTSS2SpeakerDLL64.dll	: 1.0.0.1
DTSSymmetryDLL64.dll	: 1.0.0.1
DTSVoiceClarityDLL64.dll	: 1.0.0.1
FMAP064.dll	: 43.6.16.65
GrayJadeSkinImages64.dll	: 1.0.0.113
KAAPORT64.dll	: 4.1102.6000.49
LightSkinImages64.dll	: 1.0.0.113
MaxxAudioAPO20.dll	: 2.2.9.0
MaxxAudioAPO30.dll	: 3.2.1.1
MaxxAudioEQ.dll	: 5.9.7.0
MaxxAudioRealtek.dll	: 1.2.0.0
MaxxAudioRealtek2.dll	: 1.0.7.0
MaxxVolumeSDAPO.dll	: 3.1.0.0
MBAP032.dll	: 1.0.43.0
MBAP064.dll	: 1.0.43.0
MBPPCn64.dll	: 1.0.0.110
MBpld64.dll	: 1.0.43.0
MBTHX32.dll	: 1.0.15.138
MBTHX64.dll	: 1.0.15.138
MBWrp64.dll	: 1.0.0.180
PremiumBlackSkinImages64.dll	: 1.0.0.113
R4EEA64A.dll	: 7.2.7000.6
R4EED64A.dll	: 7.2.7000.6
R4EEG64A.dll	: 7.2.7000.6
R4EEL64A.dll	: 7.2.7000.6
R4EEP64A.dll	: 7.2.7000.6
RCoInst64.dll	: 1.1.4.4
RP3DAA64.dll	: 6.0.6001.18
RP3DHT64.dll	: 6.0.6001.18
RtCOM64.dll	: 2.0.0.145
RTCOMDLL.dll	: 2.0.0.145
RTEED64A.dll	: 6.1.6001.33
RTEEG64A.dll	: 6.1.6001.33
RTEEL64A.dll	: 6.1.6001.33
RTEEP64A.dll	: 6.1.6001.33
RtkApi64.dll	: 1.0.0.36
RtkAPO64.dll	: 11.0.6000.216
RtkCfg.dll	: 1.0.0.1
RtkCfg64.dll	: 1.0.0.2
RtkGuiCompLib.dll	: 1.0.0.2
RtlCPAPI.dll	: 1.0.2.4
RtlCPAPI64.dll	: 1.0.2.4
RtPgEx64.dll	: 6.0.6000.203
SFAP064.dll	: 3.0.0.14
SFCOM.dll	: 3.0.0.11
SFCOM64.dll	: 3.0.0.14
SFComm64.dll	: 2.0.0.13
SFDAP064.dll	: 2.0.0.13
SFHAP064.dll	: 2.0.0.13
SFNHK64.dll	: 3.0.0.14

Readme.txt

```

Readme.txt
SFProc64.dll : 2.0.0.13
SFSAP064.dll : 2.0.0.13
SFSS_APO.dll : 1.0.0.11110
slcc3d64.dll : 1.0.0.100
slcshp64.dll : 1.0.3.0
slcsi64.dll : 1.0.3.0
slgeq64.dll : 1.0.1.0
slh36064.dll : 1.0.2.0
slhlim64.dll : 2.1.0.0
slInit64.dll : 1.1.3.0
slmaxv64.dll : 1.2.1.0
sltshd64.dll : 1.2.0.0
sluapo64.dll : 2.2.2.0
slvipp64.dll : 1.0.1.0
slviq64.dll : 2.1.0.0
SRSHp64.dll : 1.1.0.0
SRSTSH64.dll : 1.1.4.0
SRSTX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
tadefxapo.dll : 1.0.1.12
tosade.dll : 1.0.1.12
WavesGUILib.dll : 1.2.0.0
HDMI Driver : -----
Vista/WIn7 x86:
RtHDMV.sys : 6.0.1.6358
RtkAudioSrvATI.exe : 1.0.0.23
RtkUpd.exe : 2.8.0.3
RH3DAA32.dll : 6.0.6001.18
RH3DHT32.dll : 6.0.6001.18
RHCoInst.dll : 1.1.1.2
RHDMExt.dll : 6.0.6000.172
RTEED32H.dll : 6.1.6001.33
RTEEG32H.dll : 6.1.6001.33
RTEEL32H.dll : 6.1.6001.33
RTEEP32H.dll : 6.1.6001.33
RtkHDM.dll : 11.0.6000.183

Vista/WIn7 x64:
RtHDMVX.sys : 6.0.1.6358
RtkAudioSrvATI64.exe : 1.0.0.23
RtkUpd64.exe : 2.8.0.3
RH3DAA64.dll : 6.0.6001.18
RH3DHT64.dll : 6.0.6001.18
RHCoInst64.dll : 1.1.1.2
RHDMEx64.dll : 6.0.6000.172
RTEED64H.dll : 6.1.6001.33
RTEEG64H.dll : 6.1.6001.33
RTEEL64H.dll : 6.1.6001.33
RTEEP64H.dll : 6.1.6001.33
RtkHDM64.dll : 11.0.6000.183

XP/2K x86:
RtkHDM.sys : 5.10.0.6358
Rtaupd.exe : 2.8.0.3
RHCoInstXP.dll : 1.1.1.2

XP/2K x64:
RtkHDMX.sys : 5.10.0.6358
Rtaupd64.exe : 2.8.0.3
RHCoInst64XP.dll : 1.1.1.2

Driver Setup Program : 3.25

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

```

//=====

Readme.txt

Driver Package R2.60

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting:

ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889, ALC892, ALC899, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC670, ALC672, ALC676, ALC680, ALC221, ALC231, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC275, ALC276

2. Windows 2000/XP WHQL Supporting:

ALC880, ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889, ALC892, ALC899, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC670, ALC672, ALC676, ALC680, ALC221, ALC231, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC275, ALC276

3. HDM Device WHQL Support: ATI HDM Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008,

Windows7 - x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013) For Windows 2000 SP4, XP SP1, XP SP2, Server 2003 SP1.

6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :

RTKHDA64.sys : 5.10.0.6363
RtkHDAud.sys : 5.10.0.6363
McCal.exe : 1.1.2.4
RTHDCPL.exe : 2.3.9.4
RtkAudioService64.exe : 1.0.0.19
RtkAudioService.exe : 1.0.0.19
RTLCP.exe : 1.0.1.66
RtlUpd64.exe : 2.8.0.3
RtlUpd.exe : 2.8.0.3
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.32
vncutil64.exe : 1.0.0.38
vncutil.exe : 1.0.0.38
Alcmtr.exe : 1.6.0.4
AlcWzrd.exe : 1.1.0.37
AMBfilt.sys : 5.10.0.4240
AMBft64.sys : 5.10.0.4240
Mbnfilt.sys : 5.10.0.4112
Mbnft64.sys : 5.10.0.4115
OA017Afx.sys : 1.0.7.3
RTSndMgr.cpl : 1.0.1.6
ALSndMgr.cpl : 1.0.0.11
RCoInst64XP.dll : 1.1.2.4
RTCOMDLL.dll : 1.0.0.112
RtkCoInstXP.dll : 1.1.2.4
RtlCPAPI.dll : 1.0.2.3

Vista/Win7 driver : -----

Vista/Win7 driver for x86

RTKVHDA.sys : 6.0.1.6363
AERTSrv.exe : 1.0.32.10
FMAPP.exe : 1.32.0.1
RtHDVBg.exe : 1.0.0.65
RtHDVCpl.exe : 1.0.0.660
RtkAudioService.exe : 1.0.0.28
RtkNGUI.exe : 1.0.0.107
RtlUpd.exe : 2.8.0.3
SkyTel.exe : 2.0.2.2
vncutil.exe : 1.0.0.44
mbfilt32.sys : 6.10.0.8
RTSndMgr.cpl : 1.0.0.19
AERTACap.dll : 2.0.32.13
AERTARen.dll : 1.0.32.9
BlackSkinImages.dll : 1.0.0.107
DarkSkinImages.dll : 1.0.0.107
DTSBassEnhancementDLL.dll : 1.0.0.1
DTSBoostDLL.dll : 1.0.0.1
DTSGainCompensatorDLL.dll : 1.0.0.1
DTSGFXAPO.dll : 1.0.0.3

	Readme.txt	
DTSGFXAPONS.dll	:	1.0.0.3
DTSLFXAPO.dll	:	1.0.0.3
DTSLimiterDLL.dll	:	1.0.0.1
DTSSNeoPCDLL.dll	:	1.0.0.1
DTSS2HeadphoneDLL.dll	:	1.0.0.1
DTSS2SpeakerDLL.dll	:	1.0.0.1
DTSSymmetryDLL.dll	:	1.0.0.1
DTSVoiceClarityDLL.dll	:	1.0.0.1
FMAP0.dll	:	43.5.14.65
GrayJadeSkinImages.dll	:	1.0.0.107
LightSkinImages.dll	:	1.0.0.107
MaxxAudioAPO.dll	:	1.2.2.0
MaxxAudioAPO20.dll	:	2.2.9.0
MaxxAudioAPO30.dll	:	3.2.1.1
MaxxAudioEQ.dll	:	5.9.7.0
MaxxAudioRealtek.dll	:	1.2.0.0
MaxxAudioRealtek2.dll	:	1.0.7.0
MaxxVolumeSDAPO.dll	:	3.1.0.0
MBAP032.dll	:	1.0.43.0
MBPPCn32.dll	:	1.0.0.110
MBpld32.dll	:	1.0.43.0
MBTHX32.dll	:	1.0.15.136
MBWrp32.dll	:	1.0.0.180
R4EEA32A.dll	:	7.2.7000.5
R4EED32A.dll	:	7.2.7000.5
R4EEG32A.dll	:	7.2.7000.5
R4EEL32A.dll	:	7.2.7000.5
R4EEP32A.dll	:	7.2.7000.5
RP3DAA32.dll	:	6.0.6001.18
RP3DHT32.dll	:	6.0.6001.18
RTCOMDLL.dll	:	2.0.0.144
RTEED32A.dll	:	6.1.6001.33
RTEEG32A.dll	:	6.1.6001.33
RTEEL32A.dll	:	6.1.6001.33
RTEEP32A.dll	:	6.1.6001.33
RtkAPO.dll	:	11.0.6000.210
RtkApoApi.dll	:	1.0.0.36
RtkCfg.dll	:	1.0.0.2
RtkColInst.dll	:	1.1.3.2
RtkGuiCompLib.dll	:	1.0.0.2
RtkPgExt.dll	:	6.0.6000.200
RtlCPAPI.dll	:	1.0.2.4
SFAPO.dll	:	3.0.0.11
SFCOM.dll	:	3.0.0.11
SFFXComm.dll	:	2.0.0.13
SFFXDAP0.dll	:	2.0.0.13
SFFXHAP0.dll	:	2.0.0.13
SFFXProc.dll	:	2.0.0.13
SFFXSAP0.dll	:	2.0.0.13
SFNHK.dll	:	3.0.0.11
slcc3d32.dll	:	1.0.0.100
slcshp32.dll	:	1.0.3.0
slcsii32.dll	:	1.0.3.0
slgeq32.dll	:	1.0.1.0
slh36032.dll	:	1.0.2.0
slhlim32.dll	:	2.1.0.0
slInit32.dll	:	1.1.3.0
slmaxv32.dll	:	1.2.1.0
sltshd32.dll	:	1.2.0.0
sluapo32.dll	:	2.2.2.0
slvip32.dll	:	1.0.1.0
slviq32.dll	:	2.1.0.0
SRSHP360.dll	:	1.1.0.0
SRSTSHD.dll	:	1.1.4.0
SRSTSXT.dll	:	3.2.0.0
SRSWOW.dll	:	1.1.3.0
tadefxapo.dll	:	1.0.1.12
tosade.dll	:	1.0.1.12
WavesGUILib.dll	:	1.2.0.0

WavesLib.dll	Readme.txt	: 5.9.7.0
Vista/Win7 driver for x64		
RTKVHD64.sys		: 6.0.1.6363
AERTSr64.exe		: 1.0.64.10
FMAPP.exe		: 1.64.0.1
RAVBg64.exe		: 1.0.0.65
RAVCpl64.exe		: 1.0.0.660
RtkAudioService64.exe		: 1.0.0.28
RtkNGUI64.exe		: 1.0.0.107
RtlUpd64.exe		: 2.8.0.3
SkyTel.exe		: 2.0.2.2
vncutil64.exe		: 1.0.0.44
GWfilt64.sys		: 6.10.0.3
mbfilt64.sys		: 6.10.0.8
RTSnMg64.cpl		: 1.0.0.19
AERTAC64.dll		: 2.0.64.13
AERTAR64.dll		: 1.0.64.9
BlackSkinImages64.dll		: 1.0.0.107
DarkSkinImages64.dll		: 1.0.0.107
DTSBassEnhancementDLL64.dll		: 1.0.0.1
DTSBoostDLL64.dll		: 1.0.0.1
DTSGainCompensatorDLL64.dll		: 1.0.0.1
DTSAFXAP064.dll		: 1.0.0.3
DTSAFXAPONS64.dll		: 1.0.0.3
DTSAFXAP064.dll		: 1.0.0.3
DTSLimitDLL64.dll		: 1.0.0.1
DTSNeoPCDLL64.dll		: 1.0.0.1
DTSS2HeadphoneDLL64.dll		: 1.0.0.1
DTSS2SpeakerDLL64.dll		: 1.0.0.1
DTSSymmetryDLL64.dll		: 1.0.0.1
DTSVoiceClarityDLL64.dll		: 1.0.0.1
FMAP064.dll		: 43.6.14.65
GrayJadeSkinImages64.dll		: 1.0.0.107
LightSkinImages64.dll		: 1.0.0.107
MaxxAudioAP020.dll		: 2.2.9.0
MaxxAudioAP030.dll		: 3.2.1.1
MaxxAudioEQ.dll		: 5.9.7.0
MaxxAudioRealtek.dll		: 1.2.0.0
MaxxAudioRealtek2.dll		: 1.0.7.0
MaxxVolumeSDAPO.dll		: 3.1.0.0
MBAP032.dll		: 1.0.43.0
MBAP064.dll		: 1.0.43.0
MBPPCn64.dll		: 1.0.0.110
MBpld64.dll		: 1.0.43.0
MBTHX32.dll		: 1.0.15.136
MBTHX64.dll		: 1.0.15.136
MBWrp64.dll		: 1.0.0.180
R4EEA64A.dll		: 7.2.7000.5
R4EED64A.dll		: 7.2.7000.5
R4EEG64A.dll		: 7.2.7000.5
R4EEL64A.dll		: 7.2.7000.5
R4EEP64A.dll		: 7.2.7000.5
RCoInst64.dll		: 1.1.3.2
RP3DAA64.dll		: 6.0.6001.18
RP3DHT64.dll		: 6.0.6001.18
RtCOMB4.dll		: 2.0.0.144
RTCOMDLL.dll		: 2.0.0.144
RTEED64A.dll		: 6.1.6001.33
RTEEG64A.dll		: 6.1.6001.33
RTEEL64A.dll		: 6.1.6001.33
RTEEP64A.dll		: 6.1.6001.33
RtkApi64.dll		: 1.0.0.36
RtkAP064.dll		: 11.0.6000.210
RtkCfg.dll		: 1.0.0.1
RtkCfg64.dll		: 1.0.0.2
RtkGuiCompLib.dll		: 1.0.0.2
RtlCPAPI.dll		: 1.0.2.4
RtlCPAPI64.dll		: 1.0.2.4
RtPgEx64.dll		: 6.0.6000.200

Readme.txt

```

SFAP064. dll           : 3.0.0.11
SFCOM.dll             : 3.0.0.11
SFCOM64.dll          : 3.0.0.11
SFComm64.dll         : 2.0.0.13
SFDAP064.dll         : 2.0.0.13
SFHAP064.dll         : 2.0.0.13
SFNHK64.dll          : 3.0.0.11
SFProc64.dll         : 2.0.0.13
SFSAP064.dll         : 2.0.0.13
SFSS_AP0.dll         : 1.0.0.11110
slcc3d64.dll         : 1.0.0.100
slcshp64.dll         : 1.0.3.0
slcsii64.dll         : 1.0.3.0
slgeq64.dll          : 1.0.1.0
slh36064.dll         : 1.0.2.0
slhl i n64.dll       : 2.1.0.0
slIni t64.dll        : 1.1.3.0
slmaxv64.dll         : 1.2.1.0
sltshd64.dll         : 1.2.0.0
sluapo64.dll         : 2.2.2.0
slvi pp64.dll        : 1.0.1.0
slvi q64.dll         : 2.1.0.0
SRSHP64.dll          : 1.1.0.0
SRSTSH64.dll         : 1.1.4.0
SRSTX64.dll          : 3.2.0.0
SRSWOW64.dll         : 1.1.3.0
tadefxapo.dll        : 1.0.1.12
tosade.dll           : 1.0.1.12
WavesGUILib.dll      : 1.2.0.0
HDM Driver : -----
Vista/Win7 x86:
RtHDM.V.sys          : 6.0.1.6251
RtkAudioSrvATI.exe  : 1.0.0.23
RtkUpd.exe           : 2.8.0.3
RH3DAA32.dll         : 6.0.6001.18
RH3DHT32.dll         : 6.0.6001.18
RHCoInst.dll         : 1.1.1.2
RHDMExt.dll          : 6.0.6000.172
RTEED32H.dll         : 6.1.6001.33
RTEEG32H.dll         : 6.1.6001.33
RTEEL32H.dll         : 6.1.6001.33
RTEEP32H.dll         : 6.1.6001.33
RtkHDM.dll           : 11.0.6000.183

Vista/Win7 x64:
RtHDM.VX.sys         : 6.0.1.6251
RtkAudioSrvATI64.exe : 1.0.0.23
RtkUpd64.exe         : 2.8.0.3
RH3DAA64.dll         : 6.0.6001.18
RH3DHT64.dll         : 6.0.6001.18
RHCoInst64.dll       : 1.1.1.2
RHDMEx64.dll         : 6.0.6000.172
RTEED64H.dll         : 6.1.6001.33
RTEEG64H.dll         : 6.1.6001.33
RTEEL64H.dll         : 6.1.6001.33
RTEEP64H.dll         : 6.1.6001.33
RtkHDM64.dll         : 11.0.6000.183

XP/2K x86:
RtkHDM.sys           : 5.10.0.6251
Rtaupd.exe           : 2.8.0.3
RHCoInstXP.dll       : 1.1.1.2

XP/2K x64:
RtkHDMX.sys          : 5.10.0.6251
Rtaupd64.exe         : 2.8.0.3
RHCoInst64XP.dll     : 1.1.1.2

Driver Setup Program : 3.21

```

Readme.txt

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.59

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889, ALC892, ALC899, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC670, ALC672, ALC680, ALC221, ALC231, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC275

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889, ALC892, ALC899, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC670, ALC672, ALC680, ALC221, ALC231, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC275

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows 7 - x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013) For Windows 2000 SP4, XP SP1, XP SP2, Server 2003 SP1.

6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :

RTKHDA64.sys	: 5.10.0.6343
RTKHDAUD.sys	: 5.10.0.6343
Alcmtr.exe	: 1.6.0.4
AlcWzrd.exe	: 1.1.0.37
McCal.exe	: 1.1.2.4
RTHDCPL.exe	: 2.3.9.2
RtkAudioService.exe	: 1.0.0.19
RtkAudioService64.exe	: 1.0.0.19
RTLCPPL.exe	: 1.0.1.66
RtlUpd.exe	: 2.8.0.3
RtlUpd64.exe	: 2.8.0.3
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.32
vncutil.exe	: 1.0.0.38
vncutil64.exe	: 1.0.0.38
AMBFilt.sys	: 5.10.0.4240
AMBFt64.sys	: 5.10.0.4240
Mnfilt.sys	: 5.10.0.4112
Mnft64.sys	: 5.10.0.4115
OA017Afx.sys	: 1.0.7.3
ALSndMgr.cpl	: 1.0.0.11
RTSndMgr.cpl	: 1.0.1.6
RCoInst64XP.dll	: 1.1.2.2
RTCOMDLL.dll	: 1.0.0.112
RtkCoInstXP.dll	: 1.1.2.2
RtlCPAPI.dll	: 1.0.2.3

Vista/Win7 driver : -----

Vista/Win7 driver for x86

RTKVHDA.sys	: 6.0.1.6343
AERTSrv.exe	: 1.0.32.10
FMAPP.exe	: 1.32.0.1
RtHDVBg.exe	: 1.0.0.63
RtHDVCpl.exe	: 1.0.0.653
RtkAudioService.exe	: 1.0.0.28
RtkNGUI.exe	: 1.0.0.102
RtlUpd.exe	: 2.8.0.3
SkyTel.exe	: 2.0.2.2
vncutil.exe	: 1.0.0.43
mbfilt32.sys	: 6.10.0.8
RTSndMgr.cpl	: 1.0.0.19
AERTACap.dll	: 2.0.32.13
AERTARen.dll	: 1.0.32.9
BlackSkinImages.dll	: 1.0.0.102

	Readme.txt	
DarkSkinImages.dll	:	1.0.0.102
DTSBassEnhancementDLL.dll	:	1.0.0.1
DTSBoostDLL.dll	:	1.0.0.1
DTSGainCompensatorDLL.dll	:	1.0.0.1
DTSGFXAPO.dll	:	1.0.0.3
DTSGFXAPONS.dll	:	1.0.0.3
DTSLFXAPO.dll	:	1.0.0.3
DTSLimiterDLL.dll	:	1.0.0.1
DTSNeoPCDLL.dll	:	1.0.0.1
DTSS2HeadphoneDLL.dll	:	1.0.0.1
DTSS2SpeakerDLL.dll	:	1.0.0.1
DTSSymmetryDLL.dll	:	1.0.0.1
DTSVoiceClarityDLL.dll	:	1.0.0.1
FMAPO.dll	:	43.5.14.65
GrayJadeSkinImages.dll	:	1.0.0.102
LightSkinImages.dll	:	1.0.0.102
MaxxAudioAPO.dll	:	1.2.2.0
MaxxAudioAPO20.dll	:	2.2.9.0
MaxxAudioAPO30.dll	:	3.2.1.1
MaxxAudioEQ.dll	:	5.9.7.0
MaxxAudioRealtek.dll	:	1.2.0.0
MaxxAudioRealtek2.dll	:	1.0.7.0
MaxxVolumeSDAPO.dll	:	3.1.0.0
MBAP032.dll	:	1.0.43.0
MBPPCn32.dll	:	1.0.0.110
MBpld32.dll	:	1.0.43.0
MBTHX32.dll	:	1.0.15.132
MBWrp32.dll	:	1.0.0.180
R4EEA32A.dll	:	7.2.7000.5
R4EED32A.dll	:	7.2.7000.5
R4EEG32A.dll	:	7.2.7000.5
R4EEL32A.dll	:	7.2.7000.5
R4EEP32A.dll	:	7.2.7000.5
RP3DAA32.dll	:	6.0.6001.18
RP3DHT32.dll	:	6.0.6001.18
RTCOMDLL.dll	:	2.0.0.144
RTEED32A.dll	:	6.1.6001.33
RTEEG32A.dll	:	6.1.6001.33
RTEEL32A.dll	:	6.1.6001.33
RTEEP32A.dll	:	6.1.6001.33
RtkAPO.dll	:	11.0.6000.209
RtkApoApi.dll	:	1.0.0.36
RtkCfg.dll	:	1.0.0.2
RtkCoInst.dll	:	1.1.2.2
RtkGuiCompLib.dll	:	1.0.0.2
RtkPgExt.dll	:	6.0.6000.198
RtlCPAPI.dll	:	1.0.2.4
SFAPO.dll	:	3.0.0.11
SFCOM.dll	:	3.0.0.11
SFFXComm.dll	:	2.0.0.13
SFFXDAP0.dll	:	2.0.0.13
SFFXHAP0.dll	:	2.0.0.13
SFFXProc.dll	:	2.0.0.13
SFFXSAP0.dll	:	2.0.0.13
SFNHK.dll	:	3.0.0.11
slcc3d32.dll	:	1.0.0.100
slcshp32.dll	:	1.0.3.0
slcsi32.dll	:	1.0.3.0
slgeq32.dll	:	1.0.1.0
slh36032.dll	:	1.0.2.0
slhlimg32.dll	:	2.1.0.0
slinit32.dll	:	1.1.3.0
slmaxv32.dll	:	1.2.1.0
sltshd32.dll	:	1.2.0.0
sluapo32.dll	:	2.2.2.0
slvi pp32.dll	:	1.0.1.0
slviq32.dll	:	2.1.0.0
SRSHP360.dll	:	1.1.0.0
SRSTSHD.dll	:	1.1.4.0

	Readme.txt	
SRSTSXT.dll	:	3.2.0.0
SRSWOW.dll	:	1.1.3.0
tadefxapo.dll	:	1.0.1.12
tosade.dll	:	1.0.1.12
WavesGUILib.dll	:	1.2.0.0
WavesLib.dll	:	5.9.7.0
Vista/Win7 driver for x64		
RTKVHD64.sys	:	6.0.1.6343
AERTSr64.exe	:	1.0.64.10
FMAPP.exe	:	1.64.0.1
RAVBg64.exe	:	1.0.0.63
RAVCpl64.exe	:	1.0.0.653
RtkAudioService64.exe	:	1.0.0.28
RtkNGUI64.exe	:	1.0.0.102
RtlUpd64.exe	:	2.8.0.3
SkyTel.exe	:	2.0.2.2
vncutil64.exe	:	1.0.0.43
GWfilt64.sys	:	6.10.0.3
mbfilt64.sys	:	6.10.0.8
RTSnMg64.cpl	:	1.0.0.19
AERTAC64.dll	:	2.0.64.13
AERTAR64.dll	:	1.0.64.9
BlackSkinImages64.dll	:	1.0.0.102
DarkSkinImages64.dll	:	1.0.0.102
DTSBassEnhancementDLL64.dll	:	1.0.0.1
DTSBoostDLL64.dll	:	1.0.0.1
DTSGainCompensatorDLL64.dll	:	1.0.0.1
DTSAFXAP064.dll	:	1.0.0.3
DTSAFXAPONS64.dll	:	1.0.0.3
DTSLFXAP064.dll	:	1.0.0.3
DTSLimitDLL64.dll	:	1.0.0.1
DTSNeoPCDLL64.dll	:	1.0.0.1
DTSS2HeadphoneDLL64.dll	:	1.0.0.1
DTSS2SpeakerDLL64.dll	:	1.0.0.1
DTSSymmetryDLL64.dll	:	1.0.0.1
DTSVoiceClarityDLL64.dll	:	1.0.0.1
FMAP064.dll	:	43.6.14.65
GrayJadeSkinImages64.dll	:	1.0.0.102
LightSkinImages64.dll	:	1.0.0.102
MaxxAudioAP020.dll	:	2.2.9.0
MaxxAudioAP030.dll	:	3.2.1.1
MaxxAudioEQ.dll	:	5.9.7.0
MaxxAudioRealtek.dll	:	1.2.0.0
MaxxAudioRealtek2.dll	:	1.0.7.0
MaxxVolumeSDAPO.dll	:	3.1.0.0
MBAP032.dll	:	1.0.43.0
MBAP064.dll	:	1.0.43.0
MBPPCn64.dll	:	1.0.0.110
Mbpld64.dll	:	1.0.43.0
MBTHX32.dll	:	1.0.15.132
MBTHX64.dll	:	1.0.15.132
MBWrp64.dll	:	1.0.0.180
R4EEA64A.dll	:	7.2.7000.5
R4EED64A.dll	:	7.2.7000.5
R4EEG64A.dll	:	7.2.7000.5
R4EEL64A.dll	:	7.2.7000.5
R4EEP64A.dll	:	7.2.7000.5
RCoInst64.dll	:	1.1.2.2
RP3DAA64.dll	:	6.0.6001.18
RP3DHT64.dll	:	6.0.6001.18
RtCOM64.dll	:	2.0.0.144
RTCOMDLL.dll	:	2.0.0.144
RTEED64A.dll	:	6.1.6001.33
RTEEG64A.dll	:	6.1.6001.33
RTEEL64A.dll	:	6.1.6001.33
RTEEP64A.dll	:	6.1.6001.33
RtkApi64.dll	:	1.0.0.36
RtkAPO64.dll	:	11.0.6000.209
RtkCfg.dll	:	1.0.0.1

	Readme.txt	
RtkCfg64.dll	:	1.0.0.2
RtkGuiCompLib.dll	:	1.0.0.2
RtlCPAPI.dll	:	1.0.2.4
RtlCPAPI64.dll	:	1.0.2.4
RtPgEx64.dll	:	6.0.6000.198
SFAP064.dll	:	3.0.0.11
SFCOM.dll	:	3.0.0.11
SFCOM64.dll	:	3.0.0.11
SFComm64.dll	:	2.0.0.13
SFDAPO64.dll	:	2.0.0.13
SFHAP064.dll	:	2.0.0.13
SFNHK64.dll	:	3.0.0.11
SFProc64.dll	:	2.0.0.13
SFSAP064.dll	:	2.0.0.13
SFSS_APO.dll	:	1.0.0.11110
slcc3d64.dll	:	1.0.0.100
slcshp64.dll	:	1.0.3.0
slcsi64.dll	:	1.0.3.0
slgeq64.dll	:	1.0.1.0
slh36064.dll	:	1.0.2.0
slhlim64.dll	:	2.1.0.0
slInit64.dll	:	1.1.3.0
slmaxv64.dll	:	1.2.1.0
sltshd64.dll	:	1.2.0.0
sluapo64.dll	:	2.2.2.0
slvi64.dll	:	1.0.1.0
slviq64.dll	:	2.1.0.0
SRSHP64.dll	:	1.1.0.0
SRSTSH64.dll	:	1.1.4.0
SRSTX64.dll	:	3.2.0.0
SRSWOW64.dll	:	1.1.3.0
tadefxapo.dll	:	1.0.1.12
tosade.dll	:	1.0.1.12
WavesGUILib.dll	:	1.2.0.0
HDM Driver : -----		
Vista/Win7 x86:		
RtHDMV.sys	:	6.0.1.6251
RtkAudioSrvATI.exe	:	1.0.0.23
RtkUpd.exe	:	2.8.0.3
RH3DAA32.dll	:	6.0.6001.18
RH3DHT32.dll	:	6.0.6001.18
RHCoInst.dll	:	1.1.1.2
RHDMExt.dll	:	6.0.6000.172
RTEED32H.dll	:	6.1.6001.33
RTEEG32H.dll	:	6.1.6001.33
RTEEL32H.dll	:	6.1.6001.33
RTEEP32H.dll	:	6.1.6001.33
RtkHDM.dll	:	11.0.6000.183
Vista/Win7 x64:		
RtHDMVX.sys	:	6.0.1.6251
RtkAudioSrvATI64.exe	:	1.0.0.23
RtkUpd64.exe	:	2.8.0.3
RH3DAA64.dll	:	6.0.6001.18
RH3DHT64.dll	:	6.0.6001.18
RHCoInst64.dll	:	1.1.1.2
RHDMEx64.dll	:	6.0.6000.172
RTEED64H.dll	:	6.1.6001.33
RTEEG64H.dll	:	6.1.6001.33
RTEEL64H.dll	:	6.1.6001.33
RTEEP64H.dll	:	6.1.6001.33
RtkHDM64.dll	:	11.0.6000.183
XP/2K x86:		
RtkHDM.sys	:	5.10.0.6251
Rtaupd.exe	:	2.8.0.3
RHCoInstXP.dll	:	1.1.1.2
XP/2K x64:		

Readme.txt

RtkHDMX.sys : 5.10.0.6251
Rtaupd64.exe : 2.8.0.3
RHCInst64XP.dll : 1.1.1.2

Driver Setup Program : 3.20

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.58

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889, ALC892, ALC899, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC670, ALC680 ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC275

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889, ALC892, ALC899, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC670, ALC680 ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC275

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 - x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013) For Windows 2000 SP4, XP SP1, XP SP2, Server 2003 SP1.

6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :

RTKHDA64.sys : 5.10.0.6316
RtkHDAud.sys : 5.10.0.6316
AlcWzrd.exe : 1.1.0.37
McCal.exe : 1.1.2.4
RTHDCPL.exe : 2.3.8.7
RtkAudioService64.exe : 1.0.0.19
RtkAudioService.exe : 1.0.0.19
RTLCPPL.exe : 1.0.1.66
RtlUpd64.exe : 2.8.0.3
RtlUpd.exe : 2.8.0.3
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.32
vncutil64.exe : 1.0.0.38
vncutil.exe : 1.0.0.38
Alcmtr.exe : 1.6.0.4
AMBfilt.sys : 5.10.0.4240
AMBft64.sys : 5.10.0.4240
Mbnfilt.sys : 5.10.0.4112
Mnft64.sys : 5.10.0.4115
OA017Afx.sys : 1.0.7.3
ALSndMgr.cpl : 1.0.0.11
RTSndMgr.cpl : 1.0.1.6
RCoInst64XP.dll : 1.1.1.2
RTCOMDLL.dll : 1.0.0.112
RtkCoInstXP.dll : 1.1.1.2
RtlCPAPI.dll : 1.0.2.3

Vista/Win7 driver : -----

Vista/Win7 driver for x86

RTKVHDA.sys : 6.0.1.6316
AERTSrv.exe : 1.0.32.10
FMAPP.exe : 1.32.0.1
RtHDVBg.exe : 1.0.0.58
RtHDVCpl.exe : 1.0.0.647
RtkAudioService.exe : 1.0.0.27
RtkNGUI.exe : 1.0.0.99
RtlUpd.exe : 2.8.0.3
SkyTel.exe : 2.0.2.2
vncutil.exe : 1.0.0.41

	Readme.txt
mbfilt32.sys	: 6.10.0.8
RTSndMgr.cpl	: 1.0.0.19
AERTACap.dll	: 2.0.32.13
AERTARen.dll	: 1.0.32.9
BlackSkinImages.dll	: 1.0.0.99
DarkSkinImages.dll	: 1.0.0.99
DTSBassEnhancementDLL.dll	: 1.0.0.1
DTSBoostDLL.dll	: 1.0.0.1
DTSGainCompensatorDLL.dll	: 1.0.0.1
DTSGFXAPO.dll	: 1.0.0.3
DTSGFXAPONS.dll	: 1.0.0.3
DTSLFXAPO.dll	: 1.0.0.3
DTSLimitterDLL.dll	: 1.0.0.1
DTSNeoPCDLL.dll	: 1.0.0.1
DTSS2HeadphoneDLL.dll	: 1.0.0.1
DTSS2SpeakerDLL.dll	: 1.0.0.1
DTSSymmetryDLL.dll	: 1.0.0.1
DTSVoiceClarityDLL.dll	: 1.0.0.1
FMAP0.dll	: 43.5.14.65
GrayJadeSkinImages.dll	: 1.0.0.99
LightSkinImages.dll	: 1.0.0.99
MaxxAudioAPO.dll	: 1.2.2.0
MaxxAudioAPO20.dll	: 2.2.9.0
MaxxAudioAPO30.dll	: 3.2.1.1
MaxxAudioEQ.dll	: 5.9.7.0
MaxxAudioRealtek.dll	: 1.2.0.0
MaxxAudioRealtek2.dll	: 1.0.7.0
MaxxVolumeSDAPO.dll	: 3.1.0.0
MBAPO32.dll	: 1.0.43.0
MBPPCn32.dll	: 1.0.0.110
MBppld32.dll	: 1.0.43.0
MBTHX32.dll	: 1.0.15.130
MBWrp32.dll	: 1.0.0.180
R4EEA32A.dll	: 7.1.7000.5
R4EED32A.dll	: 7.1.7000.5
R4EEG32A.dll	: 7.1.7000.5
R4EEL32A.dll	: 7.1.7000.5
R4EEP32A.dll	: 7.1.7000.5
RP3DAA32.dll	: 6.0.6001.18
RP3DHT32.dll	: 6.0.6001.18
RTCOMDLL.dll	: 2.0.0.143
RTEED32A.dll	: 6.1.6001.33
RTEEG32A.dll	: 6.1.6001.33
RTEEL32A.dll	: 6.1.6001.33
RTEEP32A.dll	: 6.1.6001.33
RtkAPO.dll	: 11.0.6000.201
RtkApoApi.dll	: 1.0.0.34
RtkCfg.dll	: 1.0.0.2
RtkColnst.dll	: 1.1.1.6
RtkGuiCompLib.dll	: 1.0.0.2
RtkPgExt.dll	: 6.0.6000.192
RtlCPAPI.dll	: 1.0.2.4
SFAP0.dll	: 3.0.0.11
SFCOM.dll	: 3.0.0.11
SFFXComm.dll	: 2.0.0.13
SFFXDAP0.dll	: 2.0.0.13
SFFXHAP0.dll	: 2.0.0.13
SFFXProc.dll	: 2.0.0.13
SFFXSAP0.dll	: 2.0.0.13
SFNHK.dll	: 3.0.0.11
slcc3d32.dll	: 1.0.0.100
slcshp32.dll	: 1.0.3.0
slcsii32.dll	: 1.0.3.0
slgeq32.dll	: 1.0.1.0
slh36032.dll	: 1.0.2.0
slhlimg32.dll	: 2.1.0.0
slInit32.dll	: 1.1.3.0
slmaxv32.dll	: 1.2.1.0
sltshd32.dll	: 1.2.0.0

sluapo32.dll	: 2.2.2.0
slvi pp32.dll	: 1.0.1.0
slvi q32.dll	: 2.1.0.0
SRSHP360.dll	: 1.1.0.0
SRSTSHD.dll	: 1.1.4.0
SRSTSXT.dll	: 3.2.0.0
SRSWOW.dll	: 1.1.3.0
WavesGUILib.dll	: 1.2.0.0
WavesLib.dll	: 5.9.7.0
Vista/Win7 driver for x64	
RTKVHD64.sys	: 6.0.1.6316
AERTSr64.exe	: 1.0.64.10
FMAPP.exe	: 1.64.0.1
RAVBg64.exe	: 1.0.0.58
RAVCpl64.exe	: 1.0.0.647
RtkAudioService64.exe	: 1.0.0.27
RtkNGUI64.exe	: 1.0.0.99
RtlUpd64.exe	: 2.8.0.3
SkyTel.exe	: 2.0.2.2
vncutil64.exe	: 1.0.0.41
GWfilt64.sys	: 6.10.0.3
mbfilt64.sys	: 6.10.0.8
RTSnMg64.cpl	: 1.0.0.19
AERTAC64.dll	: 2.0.64.13
AERTAR64.dll	: 1.0.64.9
BlackSkinImages64.dll	: 1.0.0.99
DarkSkinImages64.dll	: 1.0.0.99
DTSBassEnhancementDLL64.dll	: 1.0.0.1
DTSBoostDLL64.dll	: 1.0.0.1
DTSGainCompensatorDLL64.dll	: 1.0.0.1
DTSAFXAP064.dll	: 1.0.0.3
DTSAFXAPONS64.dll	: 1.0.0.3
DTSAFXAP064.dll	: 1.0.0.3
DTSLimitDLL64.dll	: 1.0.0.1
DTSNeoPCDLL64.dll	: 1.0.0.1
DTSS2HeadphoneDLL64.dll	: 1.0.0.1
DTSS2SpeakerDLL64.dll	: 1.0.0.1
DTSSymmetryDLL64.dll	: 1.0.0.1
DTSVoiceClarityDLL64.dll	: 1.0.0.1
FMAP064.dll	: 43.6.14.65
GrayJadeSkinImages64.dll	: 1.0.0.99
LightSkinImages64.dll	: 1.0.0.99
MaxxAudioAP020.dll	: 2.2.9.0
MaxxAudioAP030.dll	: 3.2.1.1
MaxxAudioEQ.dll	: 5.9.7.0
MaxxAudioRealtek.dll	: 1.2.0.0
MaxxAudioRealtek2.dll	: 1.0.7.0
MaxxVolumeSDAPO.dll	: 3.1.0.0
MBAP032.dll	: 1.0.43.0
MBAP064.dll	: 1.0.43.0
MBPPCn64.dll	: 1.0.0.110
MBpld64.dll	: 1.0.43.0
MBTHX32.dll	: 1.0.15.130
MBTHX64.dll	: 1.0.15.130
MBWrp64.dll	: 1.0.0.180
R4EEA64A.dll	: 7.1.7000.5
R4EED64A.dll	: 7.1.7000.5
R4EEG64A.dll	: 7.1.7000.5
R4EEL64A.dll	: 7.1.7000.5
R4EEP64A.dll	: 7.1.7000.5
RCoInst64.dll	: 1.1.1.6
RP3DAA64.dll	: 6.0.6001.18
RP3DHT64.dll	: 6.0.6001.18
RtCOMB4.dll	: 2.0.0.143
RTCOMDLL.dll	: 2.0.0.143
RTEED64A.dll	: 6.1.6001.33
RTEEG64A.dll	: 6.1.6001.33
RTEEL64A.dll	: 6.1.6001.33
RTEEP64A.dll	: 6.1.6001.33

Readme.txt

	Readme.txt	
RtkApi64.dll		: 1.0.0.34
RtkAPO64.dll		: 11.0.6000.201
RtkCfg.dll		: 1.0.0.1
RtkCfg64.dll		: 1.0.0.2
RtkGuiCompLib.dll		: 1.0.0.2
RtLCPAPI.dll		: 1.0.2.4
RtLCPAPI64.dll		: 1.0.2.4
RtPgEx64.dll		: 6.0.6000.192
SFAP064.dll		: 3.0.0.11
SFCOM.dll		: 3.0.0.11
SFCOM64.dll		: 3.0.0.11
SFComm64.dll		: 2.0.0.13
SFDAP064.dll		: 2.0.0.13
SFHAP064.dll		: 2.0.0.13
SFNHK64.dll		: 3.0.0.11
SFProc64.dll		: 2.0.0.13
SFSAP064.dll		: 2.0.0.13
SFSS_AP0.dll		: 1.0.0.11110
slcc3d64.dll		: 1.0.0.100
slcshp64.dll		: 1.0.3.0
slcsii64.dll		: 1.0.3.0
slgeq64.dll		: 1.0.1.0
slh36064.dll		: 1.0.2.0
slhlime64.dll		: 2.1.0.0
slInit64.dll		: 1.1.3.0
slmaxv64.dll		: 1.2.1.0
sltshd64.dll		: 1.2.0.0
sluapo64.dll		: 2.2.2.0
slvip64.dll		: 1.0.1.0
slviq64.dll		: 2.1.0.0
SRSHP64.dll		: 1.1.0.0
SRSTSH64.dll		: 1.1.4.0
SRSTX64.dll		: 3.2.0.0
SRSWOW64.dll		: 1.1.3.0
WavesGUILib.dll		: 1.2.0.0
HDM Driver : -----		
Vista/Win7 x86:		
RtHDMV.sys		: 6.0.1.6251
RtkAudioSrvATI.exe		: 1.0.0.23
RtkUpd.exe		: 2.8.0.3
RH3DAA32.dll		: 6.0.6001.18
RH3DHT32.dll		: 6.0.6001.18
RHCoInst.dll		: 1.1.1.2
RHDMExt.dll		: 6.0.6000.172
RTEED32H.dll		: 6.1.6001.33
RTEEG32H.dll		: 6.1.6001.33
RTEEL32H.dll		: 6.1.6001.33
RTEEP32H.dll		: 6.1.6001.33
RtkHDM.dll		: 11.0.6000.183
Vista/Win7 x64:		
RtHDMVX.sys		: 6.0.1.6251
RtkAudioSrvATI64.exe		: 1.0.0.23
RtkUpd64.exe		: 2.8.0.3
RH3DAA64.dll		: 6.0.6001.18
RH3DHT64.dll		: 6.0.6001.18
RHCoInst64.dll		: 1.1.1.2
RHDMEx64.dll		: 6.0.6000.172
RTEED64H.dll		: 6.1.6001.33
RTEEG64H.dll		: 6.1.6001.33
RTEEL64H.dll		: 6.1.6001.33
RTEEP64H.dll		: 6.1.6001.33
RtkHDM64.dll		: 11.0.6000.183
XP/2K x86:		
RtkHDM.sys		: 5.10.0.6251
Rtaupd.exe		: 2.8.0.3
RHCoInstXP.dll		: 1.1.1.2

Readme.txt

XP/2K x64:
RtkHDMX.sys : 5.10.0.6251
Rtaupd64.exe : 2.8.0.3
RHCoInst64XP.dll : 1.1.1.2

Driver Setup Program : 3.18

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.57

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889, ALC892, ALC899, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC670, ALC680 ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC275

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889, ALC892, ALC899, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC670, ALC680 ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC275

3. HDM Device WHQL Support: ATI HDM Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 - x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

2.) Package :

1. Realtek Setup program will update audio driver automatically in update Realtek audio driver case under Vista/Windows 7.

Realtek setup program will un-install the previous version Realtek audio driver on the system first.

And it will re-install Realtek audio driver automatically after system re-boot.

Windows 2000/XP : -----

Windows 2000/XP :

RTKHDA64.sys : 5.10.0.6299
RtkHDAud.sys : 5.10.0.6299
Alcmtr.exe : 1.6.0.4
AlcWzrd.exe : 1.1.0.37
Mccal.exe : 1.1.2.4
RTHDCPL.exe : 2.3.8.5
RtkAudioService64.exe : 1.0.0.19
RtkAudioService.exe : 1.0.0.19
RTLCPPL.exe : 1.0.1.66
RtlUpd64.exe : 2.8.0.3
RtlUpd.exe : 2.8.0.3
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.32
vncutil64.exe : 1.0.0.38
vncutil.exe : 1.0.0.38
AMBfilt.sys : 5.10.0.4240
AMBft64.sys : 5.10.0.4240
Mbnfilt.sys : 5.10.0.4112
Mnft64.sys : 5.10.0.4115
OA017Afx.sys : 1.0.7.3
ALSndMgr.cpl : 1.0.0.11
RTSndMgr.cpl : 1.0.1.6
RCoInst64XP.dll : 1.1.1.2
RtCOMDLL.dll : 1.0.0.112
RtkCoInstXP.dll : 1.1.1.2
RtlCPAPI.dll : 1.0.2.3

Vista/Win7 driver : -----

Vista/Win7 driver for x86

RTKVHDA.sys : 6.0.1.6299
AERTSrv.exe : 1.0.32.10
FMAPP.exe : 1.32.0.1
RtHDVbg.exe : 1.0.0.58

	Readme.txt	
RtHDVCpl.exe	:	1.0.0.637
RtkAudioService.exe	:	1.0.0.27
RtkNGUI.exe	:	1.0.0.96
RtlUpd.exe	:	2.8.0.3
SkyTel.exe	:	2.0.2.2
vncutil.exe	:	1.0.0.40
mbfilt32.sys	:	6.10.0.8
RTSndMgr.cpl	:	1.0.0.19
AERTACap.dll	:	2.0.32.13
AERTARen.dll	:	1.0.32.9
BlackSkinImages.dll	:	1.0.0.96
DarkSkinImages.dll	:	1.0.0.96
DTSBassEnhancementDLL.dll	:	1.0.0.1
DTSBoostDLL.dll	:	1.0.0.1
DTSGainCompensatorDLL.dll	:	1.0.0.1
DTSAFXAPO.dll	:	1.0.0.3
DTSAFXAPONS.dll	:	1.0.0.3
DTSLFXAPO.dll	:	1.0.0.3
DTSLimitDLL.dll	:	1.0.0.1
DTSNeoPCDLL.dll	:	1.0.0.1
DTSS2HeadphoneDLL.dll	:	1.0.0.1
DTSS2SpeakerDLL.dll	:	1.0.0.1
DTSSymmetryDLL.dll	:	1.0.0.1
DTSVoiceClarityDLL.dll	:	1.0.0.1
FMAP0.dll	:	42.5.38.65
GrayJadeSkinImages.dll	:	1.0.0.96
LightSkinImages.dll	:	1.0.0.96
MaxxAudioAPO.dll	:	1.2.2.0
MaxxAudioAPO20.dll	:	2.2.9.0
MaxxAudioAPO30.dll	:	3.2.1.1
MaxxAudioEQ.dll	:	5.9.7.0
MaxxAudioRealtek.dll	:	1.2.0.0
MaxxAudioRealtek2.dll	:	1.0.7.0
MaxxVolumeSDAPO.dll	:	3.1.0.0
MBAP032.dll	:	1.0.43.0
MBPPCn32.dll	:	1.0.0.110
MBppld32.dll	:	1.0.43.0
MBTHX32.dll	:	1.0.15.129
MBWrp32.dll	:	1.0.0.180
R4EEA32A.dll	:	7.1.7000.5
R4EED32A.dll	:	7.1.7000.5
R4EEG32A.dll	:	7.1.7000.5
R4EEL32A.dll	:	7.1.7000.5
R4EEP32A.dll	:	7.1.7000.5
RP3DAA32.dll	:	6.0.6001.18
RP3DHT32.dll	:	6.0.6001.18
RTCOMDLL.dll	:	2.0.0.142
RTEED32A.dll	:	6.1.6001.33
RTEEG32A.dll	:	6.1.6001.33
RTEEL32A.dll	:	6.1.6001.33
RTEEP32A.dll	:	6.1.6001.33
RtkAPO.dll	:	11.0.6000.198
RtkApoApi.dll	:	1.0.0.33
RtkCfg.dll	:	1.0.0.2
RtkColnst.dll	:	1.1.1.2
RtkGuiCompLib.dll	:	1.0.0.2
RtkPgExt.dll	:	6.0.6000.190
RtlCPAPI.dll	:	1.0.2.4
SFAPO.dll	:	3.0.0.11
SFCOM.dll	:	3.0.0.11
SFFXComm.dll	:	2.0.0.13
SFFXDAP0.dll	:	2.0.0.13
SFFXHAP0.dll	:	2.0.0.13
SFFXProc.dll	:	2.0.0.13
SFFXSAP0.dll	:	2.0.0.13
SFNHK.dll	:	3.0.0.11
slcc3d32.dll	:	1.0.0.100
slcshp32.dll	:	1.0.3.0
slcsii32.dll	:	1.0.3.0

	Readme.txt	
slgeq32.dll	:	1.0.1.0
slh36032.dll	:	1.0.2.0
slhlim32.dll	:	2.1.0.0
slInit32.dll	:	1.1.3.0
slmaxv32.dll	:	1.2.1.0
sltshd32.dll	:	1.2.0.0
sluapo32.dll	:	2.2.2.0
slvip32.dll	:	1.0.1.0
slviq32.dll	:	2.1.0.0
SRSHP360.dll	:	1.1.0.0
SRSTSHD.dll	:	1.1.4.0
SRSTSXT.dll	:	3.2.0.0
SRSWOW.dll	:	1.1.3.0
WavesGUILib.dll	:	1.2.0.0
WavesLib.dll	:	5.9.7.0
Vista/Win7 driver for x64		
RTKVHD64.sys	:	6.0.1.6299
AERTSr64.exe	:	1.0.64.10
FMAPP.exe	:	1.64.0.1
RAVBg64.exe	:	1.0.0.58
RAVCpl64.exe	:	1.0.0.637
RtkAudioService64.exe	:	1.0.0.27
RtkNGUI64.exe	:	1.0.0.96
RtlUpd64.exe	:	2.8.0.3
SkyTel.exe	:	2.0.2.2
vncutil64.exe	:	1.0.0.40
GWfilt64.sys	:	6.10.0.3
mbfilt64.sys	:	6.10.0.8
RTSnMg64.cpl	:	1.0.0.19
AERTAC64.dll	:	2.0.64.13
AERTAR64.dll	:	1.0.64.9
BlackSkinImages64.dll	:	1.0.0.96
DarkSkinImages64.dll	:	1.0.0.96
DTSBassEnhancementDLL64.dll	:	1.0.0.1
DTSBoostDLL64.dll	:	1.0.0.1
DTSGainCompensatorDLL64.dll	:	1.0.0.1
DTSAFXAP064.dll	:	1.0.0.3
DTSAFXAPONS64.dll	:	1.0.0.3
DTSAFXAP064.dll	:	1.0.0.3
DTSLimitDLL64.dll	:	1.0.0.1
DTSNeoPCDLL64.dll	:	1.0.0.1
DTSS2HeadphoneDLL64.dll	:	1.0.0.1
DTSS2SpeakerDLL64.dll	:	1.0.0.1
DTSSymmetryDLL64.dll	:	1.0.0.1
DTSVoiceClarityDLL64.dll	:	1.0.0.1
FMAP064.dll	:	42.6.38.65
GrayJadeSkinImages64.dll	:	1.0.0.96
LightSkinImages64.dll	:	1.0.0.96
MaxxAudioAP020.dll	:	2.2.9.0
MaxxAudioAP030.dll	:	3.2.1.1
MaxxAudioEQ.dll	:	5.9.7.0
MaxxAudioRealtek.dll	:	1.2.0.0
MaxxAudioRealtek2.dll	:	1.0.7.0
MaxxVolumeSDAP0.dll	:	3.1.0.0
MBAP032.dll	:	1.0.43.0
MBAP064.dll	:	1.0.43.0
MBPPCn64.dll	:	1.0.0.110
MBpld64.dll	:	1.0.43.0
MBTHX32.dll	:	1.0.15.129
MBTHX64.dll	:	1.0.15.129
MBWrp64.dll	:	1.0.0.180
R4EEA64A.dll	:	7.1.7000.5
R4EED64A.dll	:	7.1.7000.5
R4EEG64A.dll	:	7.1.7000.5
R4EEL64A.dll	:	7.1.7000.5
R4EEP64A.dll	:	7.1.7000.5
RCoInst64.dll	:	1.1.1.2
RP3DAA64.dll	:	6.0.6001.18
RP3DHT64.dll	:	6.0.6001.18

```

Readme.txt
RtCOMB4.dll : 2.0.0.142
RTCOMDLL.dll : 2.0.0.142
RTEED64A.dll : 6.1.6001.33
RTEEG64A.dll : 6.1.6001.33
RTEEL64A.dll : 6.1.6001.33
RTEEP64A.dll : 6.1.6001.33
RtkApi64.dll : 1.0.0.33
RtkAPO64.dll : 11.0.6000.198
RtkCfg.dll : 1.0.0.1
RtkCfg64.dll : 1.0.0.2
RtkGuiCompLib.dll : 1.0.0.2
RtlCPAPI.dll : 1.0.2.4
RtlCPAPI64.dll : 1.0.2.4
RtPgEx64.dll : 6.0.6000.190
SFAP064.dll : 3.0.0.11
SFCOM.dll : 3.0.0.11
SFCOMB4.dll : 3.0.0.11
SFCOMM64.dll : 2.0.0.13
SFDAP064.dll : 2.0.0.13
SFHAP064.dll : 2.0.0.13
SFNHK64.dll : 3.0.0.11
SFProc64.dll : 2.0.0.13
SFSAP064.dll : 2.0.0.13
SFSS_APO.dll : 1.0.0.11110
slcc3d64.dll : 1.0.0.100
slcshp64.dll : 1.0.3.0
slcsii64.dll : 1.0.3.0
slgeq64.dll : 1.0.1.0
slh36064.dll : 1.0.2.0
slhlime64.dll : 2.1.0.0
slInit64.dll : 1.1.3.0
slmaxv64.dll : 1.2.1.0
sltshd64.dll : 1.2.0.0
sluapo64.dll : 2.2.2.0
slvi pp64.dll : 1.0.1.0
slviq64.dll : 2.1.0.0
SRSHP64.dll : 1.1.0.0
SRSTSH64.dll : 1.1.4.0
SRSTX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
WavesGUILib.dll : 1.2.0.0
HDM Driver : -----
Vista/Win7 x86:
RtHDMV.sys : 6.0.1.6251
RtkAudioSrvATI.exe : 1.0.0.23
RtkUpd.exe : 2.8.0.3
RH3DAA32.dll : 6.0.6001.18
RH3DHT32.dll : 6.0.6001.18
RHCoInst.dll : 1.1.1.2
RHDMEExt.dll : 6.0.6000.172
RTEED32H.dll : 6.1.6001.33
RTEEG32H.dll : 6.1.6001.33
RTEEL32H.dll : 6.1.6001.33
RTEEP32H.dll : 6.1.6001.33
RtkHDM.dll : 11.0.6000.183

Vista/Win7 x64:
RtHDMVX.sys : 6.0.1.6251
RtkAudioSrvATI64.exe : 1.0.0.23
RtkUpd64.exe : 2.8.0.3
RH3DAA64.dll : 6.0.6001.18
RH3DHT64.dll : 6.0.6001.18
RHCoInst64.dll : 1.1.1.2
RHDME64.dll : 6.0.6000.172
RTEED64H.dll : 6.1.6001.33
RTEEG64H.dll : 6.1.6001.33
RTEEL64H.dll : 6.1.6001.33
RTEEP64H.dll : 6.1.6001.33
RtkHDM64.dll : 11.0.6000.183

```

Readme.txt

XP/2K x86:
RtkHDM.sys : 5.10.0.6251
Rtaupd.exe : 2.8.0.3
RHCoInstXP.dll : 1.1.1.2

XP/2K x64:
RtkHDMX.sys : 5.10.0.6251
Rtaupd64.exe : 2.8.0.3
RHCoInst64XP.dll : 1.1.1.2

Driver Setup Program : 3.15

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.56

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889, ALC892, ALC899, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC670, ALC680 ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC275

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889, ALC892, ALC899, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC670, ALC680 ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC275

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008,

Windows7 - x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :

RTKHDA64.sys : 5.10.0.6278
RtkHDAud.sys : 5.10.0.6278
MicCal.exe : 1.1.2.4
RTHDCPL.exe : 2.3.8.0
RtkAudioService64.exe : 1.0.0.19
RtkAudioService.exe : 1.0.0.19
RTLCPPL.exe : 1.0.1.66
RtlUpd64.exe : 2.8.0.3
RtlUpd.exe : 2.8.0.3
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.32
vncutil64.exe : 1.0.0.38
vncutil.exe : 1.0.0.38
Alcmtr.exe : 1.6.0.4
AlcWzrd.exe : 1.1.0.37
AMBft64.sys : 5.10.0.4240
Mnflt.sys : 5.10.0.4112
Mnft64.sys : 5.10.0.4115
OA017Afx.sys : 1.0.7.3
AMBFlt.sys : 5.10.0.4240
RTSndMgr.cpl : 1.0.1.6
ALSndMgr.cpl : 1.0.0.11
RCoInst64XP.dll : 1.1.1.2
RtCOMDLL.dll : 1.0.0.112
RtkCoInstXP.dll : 1.1.1.2
RtlCPAPI.dll : 1.0.2.3

Vista/Win7 driver : -----

Vista/Win7 driver for x86

RTKVHDA.sys : 6.0.1.6278
AERTSrv.exe : 1.0.32.10
FMAPP.exe : 1.32.0.1
RtHDVBg.exe : 1.0.0.55

	Readme.txt	: 1.0.0.629
RtHdVCpl.exe		: 1.0.0.27
RtkAudioService.exe		: 1.0.0.89
RtkNGUI.exe		: 2.8.0.3
RtlUpd.exe		: 2.0.2.2
SkyTel.exe		: 1.0.0.40
vncutil.exe		: 6.10.0.8
mbfilt32.sys		: 1.0.0.19
RTSndMgr.cpl		: 2.0.32.13
AERTACap.dll		: 1.0.32.9
AERTARen.dll		: 1.0.0.89
BlackSkinImages.dll		: 1.0.0.89
DarkSkinImages.dll		: 1.0.0.1
DTSBassEnhancementDLL.dll		: 1.0.0.1
DTSBoostDLL.dll		: 1.0.0.1
DTSGainCompensatorDLL.dll		: 1.0.0.3
DTSAFXAPO.dll		: 1.0.0.3
DTSAFXAPONS.dll		: 1.0.0.3
DTSLFXAPO.dll		: 1.0.0.1
DTSLimitDLL.dll		: 1.0.0.1
DTSNeoPCDLL.dll		: 1.0.0.1
DTSS2HeadphoneDLL.dll		: 1.0.0.1
DTSS2SpeakerDLL.dll		: 1.0.0.1
DTSSymmetryDLL.dll		: 1.0.0.1
DTSVoiceClarityDLL.dll		: 43.5.7.65
FMAP0.dll		: 1.0.0.89
GrayJadeSkinImages.dll		: 1.0.0.89
LghtSkinImages.dll		: 1.2.2.0
MaxxAudioAPO.dll		: 2.2.9.0
MaxxAudioAPO20.dll		: 3.2.1.1
MaxxAudioAPO30.dll		: 5.9.7.0
MaxxAudioEQ.dll		: 1.2.0.0
MaxxAudioRealtek.dll		: 1.0.7.0
MaxxAudioRealtek2.dll		: 3.1.0.0
MaxxVolumeSDAPO.dll		: 1.0.43.0
MBAP032.dll		: 1.0.0.110
MBPPCn32.dll		: 1.0.43.0
MBppld32.dll		: 1.0.15.127
MBTHX32.dll		: 1.0.0.180
MBWrp32.dll		: 7.1.7000.5
R4EEA32A.dll		: 7.1.7000.5
R4EED32A.dll		: 7.1.7000.5
R4EEG32A.dll		: 7.1.7000.5
R4EEL32A.dll		: 7.1.7000.5
R4EEP32A.dll		: 6.0.6001.18
RP3DAA32.dll		: 6.0.6001.18
RP3DHT32.dll		: 2.0.0.142
RTCOMDLL.dll		: 6.1.6001.33
RTEED32A.dll		: 6.1.6001.33
RTEEG32A.dll		: 6.1.6001.33
RTEEL32A.dll		: 6.1.6001.33
RTEEP32A.dll		: 11.0.6000.193
RtkAPO.dll		: 1.0.0.2
RtkApoApi.dll		: 1.0.0.2
RtkCfg.dll		: 1.1.1.2
RtkColnst.dll		: 1.0.0.2
RtkGuiCompLib.dll		: 6.0.6000.181
RtkPgExt.dll		: 1.0.2.4
RtlCPAPI.dll		: 3.0.0.11
SFAPO.dll		: 3.0.0.11
SFCOM.dll		: 2.0.0.13
SFFXComm.dll		: 2.0.0.13
SFFXDAP0.dll		: 2.0.0.13
SFFXHAP0.dll		: 2.0.0.13
SFFXProc.dll		: 2.0.0.13
SFFXSAP0.dll		: 2.0.0.13
SFNHK.dll		: 3.0.0.11
slcc3d32.dll		: 1.0.0.100
slcshp32.dll		: 1.0.3.0
slcsii32.dll		: 1.0.3.0

	Readme.txt	
slgeq32.dll		: 1.0.1.0
slh36032.dll		: 1.0.2.0
slhlim32.dll		: 2.1.0.0
slinit32.dll		: 1.1.3.0
slmaxv32.dll		: 1.2.1.0
sltshd32.dll		: 1.2.0.0
sluapo32.dll		: 2.2.0.0
slvip32.dll		: 1.0.1.0
slviq32.dll		: 2.1.0.0
SRSHP360.dll		: 1.1.0.0
SRSTSHD.dll		: 1.1.4.0
SRSTSXT.dll		: 3.2.0.0
SRSWOW.dll		: 1.1.3.0
WavesGUILib.dll		: 1.2.0.0
WavesLib.dll		: 5.9.7.0
Vista/Win7 driver for x64		
RTKVHD64.sys		: 6.0.1.6278
AERTSr64.exe		: 1.0.64.10
FMAPP.exe		: 1.64.0.1
RAVBg64.exe		: 1.0.0.55
RAVCpl64.exe		: 1.0.0.629
RtkAudioService64.exe		: 1.0.0.27
RtkNGUI64.exe		: 1.0.0.89
RtlUpd64.exe		: 2.8.0.3
SkyTel.exe		: 2.0.2.2
vncutil64.exe		: 1.0.0.40
GWfilt64.sys		: 6.10.0.3
mbfilt64.sys		: 6.10.0.8
RTSnMg64.cpl		: 1.0.0.19
AERTAC64.dll		: 2.0.64.13
AERTAR64.dll		: 1.0.64.9
BlackSkinImages64.dll		: 1.0.0.89
DarkSkinImages64.dll		: 1.0.0.89
DTSBassEnhancementDLL64.dll		: 1.0.0.1
DTSBoostDLL64.dll		: 1.0.0.1
DTSGainCompensatorDLL64.dll		: 1.0.0.1
DTSAFXAP064.dll		: 1.0.0.3
DTSAFXAPONS64.dll		: 1.0.0.3
DTSAFXAP064.dll		: 1.0.0.3
DTSLimitDLL64.dll		: 1.0.0.1
DTSNeoPCDLL64.dll		: 1.0.0.1
DTSS2HeadphoneDLL64.dll		: 1.0.0.1
DTSS2SpeakerDLL64.dll		: 1.0.0.1
DTSSymmetryDLL64.dll		: 1.0.0.1
DTSVoiceClarityDLL64.dll		: 1.0.0.1
FMAP064.dll		: 43.6.7.65
GrayJadeSkinImages64.dll		: 1.0.0.89
LightSkinImages64.dll		: 1.0.0.89
MaxxAudioAP020.dll		: 2.2.9.0
MaxxAudioAP030.dll		: 3.2.1.1
MaxxAudioEQ.dll		: 5.9.7.0
MaxxAudioRealtek.dll		: 1.2.0.0
MaxxAudioRealtek2.dll		: 1.0.7.0
MaxxVolumeSDAP0.dll		: 3.1.0.0
MBAP032.dll		: 1.0.43.0
MBAP064.dll		: 1.0.43.0
MBPPCn64.dll		: 1.0.0.110
MBpld64.dll		: 1.0.43.0
MBTHX32.dll		: 1.0.15.127
MBTHX64.dll		: 1.0.15.127
MBWrp64.dll		: 1.0.0.180
R4EEA64A.dll		: 7.1.7000.5
R4EED64A.dll		: 7.1.7000.5
R4EEG64A.dll		: 7.1.7000.5
R4EEL64A.dll		: 7.1.7000.5
R4EEP64A.dll		: 7.1.7000.5
RCoInst64.dll		: 1.1.1.2
RP3DAA64.dll		: 6.0.6001.18
RP3DHT64.dll		: 6.0.6001.18

```

RtCOMB4.dll : 2.0.0.142
RTCOMDLL.dll : 2.0.0.142
RTEED64A.dll : 6.1.6001.33
RTEEG64A.dll : 6.1.6001.33
RTEEL64A.dll : 6.1.6001.33
RTEEP64A.dll : 6.1.6001.33
RtkApi64.dll : 1.0.0.32
RtkAPO64.dll : 11.0.6000.193
RtkCfg.dll : 1.0.0.1
RtkCfg64.dll : 1.0.0.2
RtkGuiCompLib.dll : 1.0.0.2
RtlCPAPI.dll : 1.0.2.4
RtlCPAPI64.dll : 1.0.2.4
RtPgEx64.dll : 6.0.6000.181
SFAP064.dll : 3.0.0.11
SFCOM.dll : 3.0.0.11
SFCOMB4.dll : 3.0.0.11
SFCOMM64.dll : 2.0.0.13
SFDAP064.dll : 2.0.0.13
SFHAP064.dll : 2.0.0.13
SFNHK64.dll : 3.0.0.11
SFProc64.dll : 2.0.0.13
SFSAP064.dll : 2.0.0.13
SFSS_APO.dll : 1.0.0.11110
slcc3d64.dll : 1.0.0.100
slcshp64.dll : 1.0.3.0
slcsii64.dll : 1.0.3.0
slgeq64.dll : 1.0.1.0
slh36064.dll : 1.0.2.0
slhlime64.dll : 2.1.0.0
slinit64.dll : 1.1.3.0
slmaxv64.dll : 1.2.1.0
sltshd64.dll : 1.2.0.0
sluapo64.dll : 2.2.0.0
slvi pp64.dll : 1.0.1.0
slviq64.dll : 2.1.0.0
SRSHP64.dll : 1.1.0.0
SRSTSH64.dll : 1.1.4.0
SRSTX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
WavesGUILib.dll : 1.2.0.0
HDM Driver : -----
Vista/Win7 x86:
RtHDMV.sys : 6.0.1.6251
RtkAudioSrvATI.exe : 1.0.0.23
RtkUpd.exe : 2.8.0.3
RH3DAA32.dll : 6.0.6001.18
RH3DHT32.dll : 6.0.6001.18
RHCoInst.dll : 1.1.1.2
RHDMExt.dll : 6.0.6000.172
RTEED32H.dll : 6.1.6001.33
RTEEG32H.dll : 6.1.6001.33
RTEEL32H.dll : 6.1.6001.33
RTEEP32H.dll : 6.1.6001.33
RtkHDM.dll : 11.0.6000.183

Vista/Win7 x64:
RtHDMVX.sys : 6.0.1.6251
RtkAudioSrvATI64.exe : 1.0.0.23
RtkUpd64.exe : 2.8.0.3
RH3DAA64.dll : 6.0.6001.18
RH3DHT64.dll : 6.0.6001.18
RHCoInst64.dll : 1.1.1.2
RHDMEX64.dll : 6.0.6000.172
RTEED64H.dll : 6.1.6001.33
RTEEG64H.dll : 6.1.6001.33
RTEEL64H.dll : 6.1.6001.33
RTEEP64H.dll : 6.1.6001.33
RtkHDM64.dll : 11.0.6000.183

```

Readme.txt

XP/2K x86:
RtkHDM.sys : 5.10.0.6251
Rtaupd.exe : 2.8.0.3
RHCoInstXP.dll : 1.1.1.2

XP/2K x64:
RtkHDMX.sys : 5.10.0.6251
Rtaupd64.exe : 2.8.0.3
RHCoInst64XP.dll : 1.1.1.2

Driver Setup Program : 3.14

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.55

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889, ALC892, ALC899, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC670, ALC680 ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC275

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889, ALC892, ALC899, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC670, ALC680 ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC275

3. HDM Device WHQL Support: ATI HDM Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008,

Windows7 - x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :

RTKHDA64.sys : 5.10.0.6257
RtkHDAud.sys : 5.10.0.6257
Alcmtr.exe : 1.6.0.4
AlcWzrd.exe : 1.1.0.37
Mccal.exe : 1.1.2.4
RTHDCPL.exe : 2.3.7.5
RtkAudioService.exe : 1.0.0.19
RtkAudioService64.exe : 1.0.0.19
RTLCPPL.exe : 1.0.1.66
RtlUpd.exe : 2.8.0.3
RtlUpd64.exe : 2.8.0.3
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.32
vncutil.exe : 1.0.0.38
vncutil64.exe : 1.0.0.38
AMBfilt.sys : 5.10.0.4240
AMBft64.sys : 5.10.0.4240
Mbnfilt.sys : 5.10.0.4112
Mnft64.sys : 5.10.0.4115
OA017Afx.sys : 1.0.7.3
ALSndMgr.cpl : 1.0.0.11
RTSndMgr.cpl : 1.0.1.6
RCoInst64XP.dll : 1.1.1.2
RtCOMDLL.dll : 1.0.0.112
RtkCoInstXP.dll : 1.1.1.2
RtlCPAPI.dll : 1.0.2.3

Vista/Win7 driver : -----

Vista/Win7 driver for x86

RTKVHDA.sys : 6.0.1.6257
AERTSrv.exe : 1.0.32.10
FMAPP.exe : 1.32.0.1
RtHDVbg.exe : 1.0.0.54

	Readme.txt	
RtHdVCpl.exe	:	1.0.0.617
RtkAudioService.exe	:	1.0.0.27
RtkNGUI.exe	:	1.0.0.81
RtlUpd.exe	:	2.8.0.3
SkyTel.exe	:	2.0.2.2
vncutil.exe	:	1.0.0.40
mbfilt32.sys	:	6.10.0.8
RTSndMgr.cpl	:	1.0.0.19
AERTACap.dll	:	2.0.32.13
AERTARen.dll	:	1.0.32.9
BlackSkinImages.dll	:	1.0.0.81
DarkSkinImages.dll	:	1.0.0.81
DTSBassEnhancementDLL.dll	:	1.0.0.1
DTSBoostDLL.dll	:	1.0.0.1
DTSGainCompensatorDLL.dll	:	1.0.0.1
DTSAFXAPO.dll	:	1.0.0.3
DTSAFXAPONS.dll	:	1.0.0.3
DTSLFXAPO.dll	:	1.0.0.3
DTSLimiterDLL.dll	:	1.0.0.1
DTSNeoPCDLL.dll	:	1.0.0.1
DTSS2HeadphoneDLL.dll	:	1.0.0.1
DTSS2SpeakerDLL.dll	:	1.0.0.1
DTSSymmetryDLL.dll	:	1.0.0.1
DTSVoiceClarityDLL.dll	:	1.0.0.1
FMAP0.dll	:	43.5.7.65
GrayJadeSkinImages.dll	:	1.0.0.81
LghtSkinImages.dll	:	1.0.0.81
MaxxAudioAPO.dll	:	1.2.2.0
MaxxAudioAPO20.dll	:	2.2.9.0
MaxxAudioAPO30.dll	:	3.2.1.1
MaxxAudioEQ.dll	:	5.9.7.0
MaxxAudioRealtek.dll	:	1.2.0.0
MaxxAudioRealtek2.dll	:	1.0.7.0
MaxxVolumeSDAPO.dll	:	3.1.0.0
MBAP032.dll	:	1.0.41.0
MBPPCn32.dll	:	1.0.0.110
MBppld32.dll	:	1.0.41.0
MBTHX32.dll	:	1.0.15.123
MBWrp32.dll	:	1.0.0.180
R4EEA32A.dll	:	7.1.7000.5
R4EED32A.dll	:	7.1.7000.5
R4EEG32A.dll	:	7.1.7000.5
R4EEL32A.dll	:	7.1.7000.5
R4EEP32A.dll	:	7.1.7000.5
RP3DAA32.dll	:	6.0.6001.18
RP3DHT32.dll	:	6.0.6001.18
RTCOMDLL.dll	:	2.0.0.142
RTEED32A.dll	:	6.1.6001.33
RTEEG32A.dll	:	6.1.6001.33
RTEEL32A.dll	:	6.1.6001.33
RTEEP32A.dll	:	6.1.6001.33
RtkAPO.dll	:	11.0.6000.184
RtkApoApi.dll	:	1.0.0.32
RtkCfg.dll	:	1.0.0.2
RtkColnst.dll	:	1.1.1.2
RtkGuiCompLib.dll	:	1.0.0.2
RtkPgExt.dll	:	6.0.6000.173
RtlCPAPI.dll	:	1.0.2.4
SFAPO.dll	:	3.0.0.11
SFCOM.dll	:	3.0.0.11
SFFXComm.dll	:	2.0.0.13
SFFXDAP0.dll	:	2.0.0.13
SFFXHAP0.dll	:	2.0.0.13
SFFXProc.dll	:	2.0.0.13
SFFXSAP0.dll	:	2.0.0.13
SFNHK.dll	:	3.0.0.11
slcshp32.dll	:	1.0.3.0
slgeq32.dll	:	1.0.1.0
slh36032.dll	:	1.0.2.0

	Readme.txt	
slInit32.dll	:	1.1.3.0
slMaxv32.dll	:	1.1.2.0
slTshd32.dll	:	1.2.0.0
sluapo32.dll	:	1.8.34.0
slvi pp32.dll	:	1.0.1.0
SRSHp360.dll	:	1.1.0.0
SRSTSHD.dll	:	1.1.4.0
SRSTSXT.dll	:	3.2.0.0
SRSWOW.dll	:	1.1.3.0
WavesGUILib.dll	:	1.2.0.0
WavesLib.dll	:	5.9.7.0
Vista/Win7 driver for x64		
RTKVHD64.sys	:	6.0.1.6257
AERTSr64.exe	:	1.0.64.10
FMAPP.exe	:	1.64.0.1
RAVBg64.exe	:	1.0.0.54
RAVCpl64.exe	:	1.0.0.617
RtkAudioService64.exe	:	1.0.0.27
RtkNGUI64.exe	:	1.0.0.81
RtlUpd64.exe	:	2.8.0.3
SkyTel.exe	:	2.0.2.2
vncutil64.exe	:	1.0.0.40
GWfilt64.sys	:	6.10.0.3
mbfilt64.sys	:	6.10.0.8
RTSnMg64.cpl	:	1.0.0.19
AERTAC64.dll	:	2.0.64.13
AERTAR64.dll	:	1.0.64.9
BlackSkinImages64.dll	:	1.0.0.81
DarkSkinImages64.dll	:	1.0.0.81
DTSBassEnhancementDLL64.dll	:	1.0.0.1
DTSBoostDLL64.dll	:	1.0.0.1
DTSGainCompensatorDLL64.dll	:	1.0.0.1
DTSGFXAP064.dll	:	1.0.0.3
DTSGFXAPONS64.dll	:	1.0.0.3
DTSLFXAP064.dll	:	1.0.0.3
DTSLimiterDLL64.dll	:	1.0.0.1
DTSNeoPCDLL64.dll	:	1.0.0.1
DTSS2HeadphoneDLL64.dll	:	1.0.0.1
DTSS2SpeakerDLL64.dll	:	1.0.0.1
DTSSymmetryDLL64.dll	:	1.0.0.1
DTSVoiceClarityDLL64.dll	:	1.0.0.1
FMAP064.dll	:	43.6.7.65
GrayJadeSkinImages64.dll	:	1.0.0.81
LightSkinImages64.dll	:	1.0.0.81
MaxxAudioAP020.dll	:	2.2.9.0
MaxxAudioAP030.dll	:	3.2.1.1
MaxxAudioEQ.dll	:	5.9.7.0
MaxxAudioRealtek.dll	:	1.2.0.0
MaxxAudioRealtek2.dll	:	1.0.7.0
MaxxVolumeSDAP0.dll	:	3.1.0.0
MBAP032.dll	:	1.0.41.0
MBAP064.dll	:	1.0.41.0
MBPPCn64.dll	:	1.0.0.110
MBppld64.dll	:	1.0.41.0
MBTHX32.dll	:	1.0.15.123
MBTHX64.dll	:	1.0.15.123
MBWrp64.dll	:	1.0.0.180
R4EEA64A.dll	:	7.1.7000.5
R4EED64A.dll	:	7.1.7000.5
R4EEG64A.dll	:	7.1.7000.5
R4EEL64A.dll	:	7.1.7000.5
R4EEP64A.dll	:	7.1.7000.5
RCoInst64.dll	:	1.1.1.2
RP3DAA64.dll	:	6.0.6001.18
RP3DHT64.dll	:	6.0.6001.18
RtCOMB4.dll	:	2.0.0.142
RTCOMDLL.dll	:	2.0.0.142
RTEED64A.dll	:	6.1.6001.33
RTEEG64A.dll	:	6.1.6001.33

Readme.txt

RTEEL64A.dll	: 6.1.6001.33
RTEEP64A.dll	: 6.1.6001.33
RtkApi64.dll	: 1.0.0.32
RtkAPO64.dll	: 11.0.6000.184
RtkCfg.dll	: 1.0.0.1
RtkCfg64.dll	: 1.0.0.2
RtkGuiCompLib.dll	: 1.0.0.2
RtLCPAPI.dll	: 1.0.2.4
RtLCPAPI64.dll	: 1.0.2.4
RtPgEx64.dll	: 6.0.6000.173
SFAP064.dll	: 3.0.0.11
SFCOM.dll	: 3.0.0.11
SFCOM64.dll	: 3.0.0.11
SFComm64.dll	: 2.0.0.13
SFDAP064.dll	: 2.0.0.13
SFHAP064.dll	: 2.0.0.13
SFNHK64.dll	: 3.0.0.11
SFProc64.dll	: 2.0.0.13
SFSAP064.dll	: 2.0.0.13
SFSS_APO.dll	: 1.0.0.11110
slcshp64.dll	: 1.0.3.0
slgeq64.dll	: 1.0.1.0
slh36064.dll	: 1.0.2.0
slInit64.dll	: 1.1.3.0
slmaxv64.dll	: 1.1.2.0
sltshd64.dll	: 1.2.0.0
sluapo64.dll	: 1.8.34.0
slvi pp64.dll	: 1.0.1.0
SRSHP64.dll	: 1.1.0.0
SRSTSH64.dll	: 1.1.4.0
SRSTX64.dll	: 3.2.0.0
SRSWOW64.dll	: 1.1.3.0
WavesGUILib.dll	: 1.2.0.0

HDM Driver :	
Vista/Win7 x86:	
RtHDMV.sys	: 6.0.1.6251
RtkAudioSrvATI.exe	: 1.0.0.23
RtkUpd.exe	: 2.8.0.3
RH3DAA32.dll	: 6.0.6001.18
RH3DHT32.dll	: 6.0.6001.18
RHCoInst.dll	: 1.1.1.2
RHDMExt.dll	: 6.0.6000.172
RTEED32H.dll	: 6.1.6001.33
RTEEG32H.dll	: 6.1.6001.33
RTEEL32H.dll	: 6.1.6001.33
RTEEP32H.dll	: 6.1.6001.33
RtkHDM.dll	: 11.0.6000.183
Vista/Win7 x64:	
RtHDMVX.sys	: 6.0.1.6251
RtkAudioSrvATI64.exe	: 1.0.0.23
RtkUpd64.exe	: 2.8.0.3
RH3DAA64.dll	: 6.0.6001.18
RH3DHT64.dll	: 6.0.6001.18
RHCoInst64.dll	: 1.1.1.2
RHDMEx64.dll	: 6.0.6000.172
RTEED64H.dll	: 6.1.6001.33
RTEEG64H.dll	: 6.1.6001.33
RTEEL64H.dll	: 6.1.6001.33
RTEEP64H.dll	: 6.1.6001.33
RtkHDM64.dll	: 11.0.6000.183
XP/2K x86:	
RtkHDM.sys	: 5.10.0.6251
Rtaupd.exe	: 2.8.0.3
RHCoInstXP.dll	: 1.1.1.2
XP/2K x64:	
RtkHDMX.sys	: 5.10.0.6251

Readme.txt

Rtaupd64.exe : 2.8.0.3
RHCoInst64XP.dll : 1.1.1.2

Driver Setup Program : 3.14

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.54

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889, ALC892, ALC899, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC670, ALC680 ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC275

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889, ALC892, ALC899, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC670, ALC680 ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC275

3. HDM Device WHQL Support: ATI HDM Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008,

Windows7 - x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :

RTKHDA64.sys : 5.10.0.6235
RtkHDAud.sys : 5.10.0.6235
AlcWzrd.exe : 1.1.0.37
McCal.exe : 1.1.2.4
RTHDCPL.exe : 2.3.7.4
RtkAudioService64.exe : 1.0.0.19
RtkAudioService.exe : 1.0.0.19
RTLCPPL.exe : 1.0.1.66
RtlUpd64.exe : 2.8.0.3
RtlUpd.exe : 2.8.0.3
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.32
vncutil64.exe : 1.0.0.38
vncutil.exe : 1.0.0.38
Alcmtr.exe : 1.6.0.4
AMBfilt.sys : 5.10.0.4240
AMBft64.sys : 5.10.0.4240
Mbnfilt.sys : 5.10.0.4112
Mnft64.sys : 5.10.0.4115
0A017Afx.sys : 1.0.7.3
ALSndMgr.cpl : 1.0.0.11
RTSndMgr.cpl : 1.0.1.6
RCoInst64XP.dll : 1.1.1.0
RTCOMDLL.dll : 1.0.0.110
RtkCoInstXP.dll : 1.1.1.0
RtlCPAPI.dll : 1.0.2.3

Vista/Win7 driver : -----

Vista/Win7 driver for x86

RTKVHDA.sys : 6.0.1.6235
AERTSrv.exe : 1.0.32.10
FMAPP.exe : 1.32.0.1
RtHDVBg.exe : 1.0.0.51
RtHDVCpl.exe : 1.0.0.603
RtkAudioService.exe : 1.0.0.27
RtkNGUI.exe : 1.0.0.76
RtlUpd.exe : 2.8.0.3
SkyTel.exe : 2.0.2.2
vncutil.exe : 1.0.0.40
mbfilt32.sys : 6.10.0.8
RTSndMgr.cpl : 1.0.0.19

	Readme.txt	
AERTACap.dll		: 2.0.32.13
AERTARen.dll		: 1.0.32.9
BlackSkinImages.dll		: 1.0.0.76
DarkSkinImages.dll		: 1.0.0.76
DTSBassEnhancementDLL.dll		: 1.0.0.1
DTSBoostDLL.dll		: 1.0.0.1
DTSGainCompensatorDLL.dll		: 1.0.0.1
DTS GFXAPO.dll		: 1.0.0.3
DTS GFXAPONS.dll		: 1.0.0.3
DTS LFXAPO.dll		: 1.0.0.3
DTS LimiterDLL.dll		: 1.0.0.1
DTS NeoPCDLL.dll		: 1.0.0.1
DTSS2HeadphoneDLL.dll		: 1.0.0.1
DTSS2SpeakerDLL.dll		: 1.0.0.1
DTSSymmetryDLL.dll		: 1.0.0.1
DTSVoiceClarityDLL.dll		: 1.0.0.1
FMAP0.dll		: 43.5.6.68
GrayJadeSkinImages.dll		: 1.0.0.76
LightSkinImages.dll		: 1.0.0.76
MaxxAudioAPO.dll		: 1.2.2.0
MaxxAudioAPO20.dll		: 2.2.9.0
MaxxAudioAPO30.dll		: 3.2.1.1
MaxxAudioEQ.dll		: 5.9.7.0
MaxxAudioRealtek.dll		: 1.1.0.0
MaxxAudioRealtek2.dll		: 1.0.3.0
MaxxVolumeSDAPO.dll		: 3.1.0.0
MBAP032.dll		: 1.0.41.0
MBPPCn32.dll		: 1.0.0.110
MBpld32.dll		: 1.0.41.0
MBTHX32.dll		: 1.0.15.122
MBWrp32.dll		: 1.0.0.180
R4EEA32A.dll		: 7.1.7000.5
R4EED32A.dll		: 7.1.7000.5
R4EEG32A.dll		: 7.1.7000.5
R4EEL32A.dll		: 7.1.7000.5
R4EEP32A.dll		: 7.1.7000.5
RP3DAA32.dll		: 6.0.6001.18
RP3DHT32.dll		: 6.0.6001.18
RTCOMDLL.dll		: 2.0.0.140
RTEED32A.dll		: 6.1.6001.33
RTEEG32A.dll		: 6.1.6001.33
RTEEL32A.dll		: 6.1.6001.33
RTEEP32A.dll		: 6.1.6001.33
RtkAPO.dll		: 11.0.6000.178
RtkApoApi.dll		: 1.0.0.31
RtkCfg.dll		: 1.0.0.2
RtkColnst.dll		: 1.1.1.1
RtkGuiCompLib.dll		: 1.0.0.2
RtkPgExt.dll		: 6.0.6000.165
RtlCPAPI.dll		: 1.0.2.4
SFAPO.dll		: 3.0.0.11
SFCOM.dll		: 3.0.0.11
SFFXComm.dll		: 2.0.0.13
SFFXDAP0.dll		: 2.0.0.13
SFFXHAP0.dll		: 2.0.0.13
SFFXProc.dll		: 2.0.0.13
SFFXSAP0.dll		: 2.0.0.13
SFNHK.dll		: 3.0.0.11
slcshp32.dll		: 1.0.3.0
slgeq32.dll		: 1.0.1.0
slh36032.dll		: 1.0.2.0
slinit32.dll		: 1.1.3.0
slmaxv32.dll		: 1.1.2.0
sltshd32.dll		: 1.2.0.0
sluapo32.dll		: 1.8.34.0
slvi pp32.dll		: 1.0.1.0
SRSHP360.dll		: 1.1.0.0
SRSTSHD.dll		: 1.1.4.0
SRSTSXT.dll		: 3.2.0.0

	Readme.txt	
SRSWOW.dll	:	1.1.3.0
WavesGUILib.dll	:	1.1.0.0
WavesLib.dll	:	5.9.7.0
Vista/Win7 driver for x64		
RTKVHD64.sys	:	6.0.1.6235
AERTSr64.exe	:	1.0.64.10
FMAPP.exe	:	1.64.0.1
RAVBg64.exe	:	1.0.0.51
RAVCpl64.exe	:	1.0.0.603
RtkAudioService64.exe	:	1.0.0.27
RtkNGUI64.exe	:	1.0.0.76
RtlUpd64.exe	:	2.8.0.3
SkyTel.exe	:	2.0.2.2
vncutil64.exe	:	1.0.0.40
GWfilt64.sys	:	6.10.0.3
mbfilt64.sys	:	6.10.0.8
RTSnMg64.cpl	:	1.0.0.19
AERTAC64.dll	:	2.0.64.13
AERTAR64.dll	:	1.0.64.9
BlackSkinImages64.dll	:	1.0.0.76
DarkSkinImages64.dll	:	1.0.0.76
DTSBassEnhancementDLL64.dll	:	1.0.0.1
DTSBoostDLL64.dll	:	1.0.0.1
DTSGainCompensatorDLL64.dll	:	1.0.0.1
DTSAFXAP064.dll	:	1.0.0.3
DTSAFXAPONS64.dll	:	1.0.0.3
DTSAFXAP064.dll	:	1.0.0.3
DTSLimitDLL64.dll	:	1.0.0.1
DTSNeoPCDLL64.dll	:	1.0.0.1
DTSS2HeadphoneDLL64.dll	:	1.0.0.1
DTSS2SpeakerDLL64.dll	:	1.0.0.1
DTSSymmetryDLL64.dll	:	1.0.0.1
DTSVoiceClarityDLL64.dll	:	1.0.0.1
FMAP064.dll	:	43.6.6.68
GrayJadeSkinImages64.dll	:	1.0.0.76
LightSkinImages64.dll	:	1.0.0.76
MaxxAudioAP020.dll	:	2.2.9.0
MaxxAudioAP030.dll	:	3.2.1.1
MaxxAudioEQ.dll	:	5.9.7.0
MaxxAudioRealtek.dll	:	1.1.0.0
MaxxAudioRealtek2.dll	:	1.0.3.0
MaxxVolumeSDAP0.dll	:	3.1.0.0
MBAP032.dll	:	1.0.41.0
MBAP064.dll	:	1.0.41.0
MBPPCn64.dll	:	1.0.0.110
MBpld64.dll	:	1.0.41.0
MBTHX32.dll	:	1.0.15.122
MBTHX64.dll	:	1.0.15.122
MBWrp64.dll	:	1.0.0.180
R4EEA64A.dll	:	7.1.7000.5
R4EED64A.dll	:	7.1.7000.5
R4EEG64A.dll	:	7.1.7000.5
R4EEL64A.dll	:	7.1.7000.5
R4EEP64A.dll	:	7.1.7000.5
RCoInst64.dll	:	1.1.1.1
RP3DAA64.dll	:	6.0.6001.18
RP3DHT64.dll	:	6.0.6001.18
RtCOMB4.dll	:	2.0.0.140
RTCOMDLL.dll	:	2.0.0.140
RTEED64A.dll	:	6.1.6001.33
RTEEG64A.dll	:	6.1.6001.33
RTEEL64A.dll	:	6.1.6001.33
RTEEP64A.dll	:	6.1.6001.33
RtkApi64.dll	:	1.0.0.31
RtkAP064.dll	:	11.0.6000.178
RtkCfg.dll	:	1.0.0.1
RtkCfg64.dll	:	1.0.0.2
RtkGuiCompLib.dll	:	1.0.0.2
RtlCPAPI.dll	:	1.0.2.4

Readme.txt

```

Rt1CPAPI64.dll : 1.0.2.4
RtPgEx64.dll : 6.0.6000.165
SFAP064.dll : 3.0.0.11
SFCOM.dll : 3.0.0.11
SFCOM64.dll : 3.0.0.11
SFCOMM64.dll : 2.0.0.13
SFDAP064.dll : 2.0.0.13
SFHAP064.dll : 2.0.0.13
SFNHK64.dll : 3.0.0.11
SFProc64.dll : 2.0.0.13
SFSAP064.dll : 2.0.0.13
SFSS_APO.dll : 1.0.0.10280
slcshp64.dll : 1.0.3.0
slgeq64.dll : 1.0.1.0
slh36064.dll : 1.0.2.0
slInit64.dll : 1.1.3.0
slmaxv64.dll : 1.1.2.0
sltshd64.dll : 1.2.0.0
sluapo64.dll : 1.8.34.0
slvip64.dll : 1.0.1.0
SRSHP64.dll : 1.1.0.0
SRSTSH64.dll : 1.1.4.0
SRSTX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
WavesGUILib.dll : 1.1.0.0
HDM Driver : -----
Vista/Win7 x86:
RtHDMV.sys : 6.0.1.6121
RtkAudioSrvATI.exe : 1.0.0.23
RtkUpd.exe : 2.8.0.3
RH3DAA32.dll : 6.0.6001.18
RH3DHT32.dll : 6.0.6001.18
RHCoInst.dll : 1.0.8.6
RHDMEExt.dll : 6.0.6000.127
RTEED32H.dll : 6.1.6001.33
RTEEG32H.dll : 6.1.6001.33
RTEEL32H.dll : 6.1.6001.33
RTEEP32H.dll : 6.1.6001.33
RtkHDM.dll : 11.0.6000.151

Vista/Win7 x64:
RtHDMVX.sys : 6.0.1.6121
RtkAudioSrvATI64.exe : 1.0.0.23
RtkUpd64.exe : 2.8.0.3
RH3DAA64.dll : 6.0.6001.18
RH3DHT64.dll : 6.0.6001.18
RHCoInst64.dll : 1.0.8.6
RHDME64.dll : 6.0.6000.127
RTEED64H.dll : 6.1.6001.33
RTEEG64H.dll : 6.1.6001.33
RTEEL64H.dll : 6.1.6001.33
RTEEP64H.dll : 6.1.6001.33
RtkHDM64.dll : 11.0.6000.151

XP/2K x86:
RtkHDM.sys : 5.10.0.6121
Rtaupd.exe : 2.8.0.3
RHCoInstXP.dll : 1.0.8.6

XP/2K x64:
RtkHDMX.sys : 5.10.0.6121
Rtaupd64.exe : 2.8.0.3
RHCoInst64XP.dll : 1.0.8.6

Driver Setup Program : 3.13

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0

```

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.53

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC892, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC892, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680

3. HDM Device WHQL Support: ATI HDM Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 - x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :

RTKHDA64.sys	: 5.10.0.6215
RtkHDAud.sys	: 5.10.0.6215
Alcmtr.exe	: 1.6.0.4
AlcWzrd.exe	: 1.1.0.37
MicCal.exe	: 1.1.2.4
RTHDCPL.exe	: 2.3.7.2
RtkAudioService64.exe	: 1.0.0.19
RtkAudioService.exe	: 1.0.0.19
RTLCPPL.exe	: 1.0.1.66
RtlUpd64.exe	: 2.8.0.3
RtlUpd.exe	: 2.8.0.3
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.32
vncutil64.exe	: 1.0.0.38
vncutil.exe	: 1.0.0.38
AMBFilt.sys	: 5.10.0.4240
AMBft64.sys	: 5.10.0.4240
Mnft64.sys	: 5.10.0.4112
Mnft64.sys	: 5.10.0.4115
OA017Afx.sys	: 1.0.7.3
ALSndMgr.cpl	: 1.0.0.11
RTSndMgr.cpl	: 1.0.1.6
RCoInst64.dll	: 1.1.0.3
RCoInst64XP.dll	: 1.1.0.4
RTCOMDLL.dll	: 1.0.0.108
RtkCoInst.dll	: 1.1.0.3
RtkCoInstXP.dll	: 1.1.0.4
RtlCPAPI.dll	: 1.0.2.3

Vista/Win7 driver : -----

Vista/Win7 driver for x86

RTKVHDA.sys	: 6.0.1.6215
AERTSrv.exe	: 1.0.32.10
RtHDVBg.exe	: 1.0.0.46
RtHDVCpl.exe	: 1.0.0.590
RtkAudioService.exe	: 1.0.0.27
RtkNGUI.exe	: 1.0.0.65
RtlUpd.exe	: 2.8.0.3
SkyTel.exe	: 2.0.2.2
vncutil.exe	: 1.0.0.40
mbfilt32.sys	: 6.10.0.8
RTSndMgr.cpl	: 1.0.0.19
AERTACap.dll	: 2.0.32.13
AERTARen.dll	: 1.0.32.9
BlackSkinImages.dll	: 1.0.0.65
DarkSkinImages.dll	: 1.0.0.65
DTSBassEnhancementDLL.dll	: 1.0.0.1
DTSBoostDLL.dll	: 1.0.0.1
DTSGainCompensatorDLL.dll	: 1.0.0.1

Readme.txt

DTSGFXAPO.dll : 1.0.0.3
 DTSGFXAPONS.dll : 1.0.0.3
 DTSLFXAPO.dll : 1.0.0.3
 DTSLimiterDLL.dll : 1.0.0.1
 DTSSNeoPCDLL.dll : 1.0.0.1
 DTSS2HeadphoneDLL.dll : 1.0.0.1
 DTSS2SpeakerDLL.dll : 1.0.0.1
 DTSSymmetryDLL.dll : 1.0.0.1
 DTSSVoiceClarityDLL.dll : 1.0.0.1
 FMAPO.dll : 42.5.35.67
 GrayJadeSkinImages.dll : 1.0.0.65
 LightSkinImages.dll : 1.0.0.65
 MaxxAudioAPO.dll : 1.2.2.0
 MaxxAudioAPO20.dll : 2.2.9.0
 MaxxAudioAPO30.dll : 3.2.0.2
 MaxxAudioEQ.dll : 5.9.7.0
 MaxxAudioRealtek.dll : 1.0.0.0
 MaxxAudioRealtek2.dll : 1.0.2.0
 MaxxVolumeSDAPO.dll : 3.1.0.0
 MBAP032.dll : 1.0.41.0
 MBPPCn32.dll : 1.0.0.110
 MBpld32.dll : 1.0.41.0
 MBTHX32.dll : 1.0.15.122
 MBWrp32.dll : 1.0.0.180
 RP3DAA32.dll : 6.0.6001.18
 RP3DHT32.dll : 6.0.6001.18
 RTCOMDLL.dll : 2.0.0.137
 RTEED32A.dll : 6.1.6001.33
 RTEEG32A.dll : 6.1.6001.33
 RTEEL32A.dll : 6.1.6001.33
 RTEEP32A.dll : 6.1.6001.33
 RtkAPO.dll : 11.0.6000.168
 RtkApoApi.dll : 1.0.0.28
 RtkCfg.dll : 1.0.0.2
 RtkColnst.dll : 1.1.0.8
 RtkGuiCompLib.dll : 1.0.0.2
 RtkPgExt.dll : 6.0.6000.159
 RtlCPAPI.dll : 1.0.2.4
 SFAPO.dll : 3.0.0.11
 SFCOM.dll : 3.0.0.11
 SFFXComm.dll : 2.0.0.13
 SFFXDAP0.dll : 2.0.0.13
 SFFXHAP0.dll : 2.0.0.13
 SFFXProc.dll : 2.0.0.13
 SFFXSAP0.dll : 2.0.0.13
 SFNHK.dll : 3.0.0.11
 slcshp32.dll : 1.0.3.0
 slgeq32.dll : 1.0.1.0
 slh36032.dll : 1.0.2.0
 slInit32.dll : 1.1.3.0
 slmaxv32.dll : 1.1.2.0
 sltshd32.dll : 1.2.0.0
 sluapo32.dll : 1.8.34.0
 slvi pp32.dll : 1.0.1.0
 SRSHP360.dll : 1.1.0.0
 SRSTSHD.dll : 1.1.4.0
 SRSTSXT.dll : 3.2.0.0
 SRSWOW.dll : 1.1.3.0
 WavesGUILib.dll : 1.0.0.0
 WavesLib.dll : 5.9.7.0
 Vista/Win7 driver for x64
 RTKVHD64.sys : 6.0.1.6215
 AERTSr64.exe : 1.0.64.10
 RAVBg64.exe : 1.0.0.46
 RAVCpl64.exe : 1.0.0.590
 RtkAudioService64.exe : 1.0.0.27
 RtkNGUI64.exe : 1.0.0.65
 RtlUpd64.exe : 2.8.0.3
 SkyTel.exe : 2.0.2.2

Readme.txt

vncutil64.exe : 1.0.0.40
GWfilt64.sys : 6.10.0.3
mbfilt64.sys : 6.10.0.8
RTSnMg64.cpl : 1.0.0.19
AERTAC64.dll : 2.0.64.13
AERTAR64.dll : 1.0.64.9
BlackSkinImages64.dll : 1.0.0.65
DarkSkinImages64.dll : 1.0.0.65
DTSBassEnhancementDLL64.dll : 1.0.0.1
DTSTBoostDLL64.dll : 1.0.0.1
DTSGainCompensatorDLL64.dll : 1.0.0.1
DTSGFXAPO64.dll : 1.0.0.3
DTSGFXAPONS64.dll : 1.0.0.3
DTSLFXAPO64.dll : 1.0.0.3
DTSLimiterDLL64.dll : 1.0.0.1
DTSSNeoPCDLL64.dll : 1.0.0.1
DTSS2HeadphoneDLL64.dll : 1.0.0.1
DTSS2SpeakerDLL64.dll : 1.0.0.1
DTSSymmetryDLL64.dll : 1.0.0.1
DTSVoiceClarityDLL64.dll : 1.0.0.1
FMAP064.dll : 42.6.35.67
GrayJadeSkinImages64.dll : 1.0.0.65
LightSkinImages64.dll : 1.0.0.65
MaxxAudioAPO20.dll : 2.2.9.0
MaxxAudioAPO30.dll : 3.2.0.2
MaxxAudioEQ.dll : 5.9.7.0
MaxxAudioRealtek.dll : 1.0.0.0
MaxxAudioRealtek2.dll : 1.0.2.0
MaxxVolumeSDAPO.dll : 3.1.0.0
MBAP032.dll : 1.0.41.0
MBAP064.dll : 1.0.41.0
MBPPCn64.dll : 1.0.0.110
Mbpld64.dll : 1.0.41.0
MBTHX32.dll : 1.0.15.122
MBTHX64.dll : 1.0.15.122
MBWrp64.dll : 1.0.0.180
RCoInst64.dll : 1.1.0.8
RP3DAA64.dll : 6.0.6001.18
RP3DHT64.dll : 6.0.6001.18
RtCOMB4.dll : 2.0.0.137
RtCOMDLL.dll : 2.0.0.137
RTEED64A.dll : 6.1.6001.33
RTEEG64A.dll : 6.1.6001.33
RTEEL64A.dll : 6.1.6001.33
RTEEP64A.dll : 6.1.6001.33
RtkApi64.dll : 1.0.0.28
RtkAPO64.dll : 11.0.6000.168
RtkCfg.dll : 1.0.0.1
RtkCfg64.dll : 1.0.0.2
RtkGuiCompLib.dll : 1.0.0.2
RtLCPAPI.dll : 1.0.2.4
RtLCPAPI64.dll : 1.0.2.4
RtPgEx64.dll : 6.0.6000.159
SFAP064.dll : 3.0.0.11
SFCOM.dll : 3.0.0.11
SFCOMB4.dll : 3.0.0.11
SFComm64.dll : 2.0.0.13
SFDAP064.dll : 2.0.0.13
SFHAP064.dll : 2.0.0.13
SFNHK64.dll : 3.0.0.11
SFProc64.dll : 2.0.0.13
SFSAP064.dll : 2.0.0.13
SFSS_APO.dll : 1.0.0.8310
slcshp64.dll : 1.0.3.0
slgeq64.dll : 1.0.1.0
slh36064.dll : 1.0.2.0
slInit64.dll : 1.1.3.0
slmaxv64.dll : 1.1.2.0
sltshd64.dll : 1.2.0.0

Readme.txt

sluapo64.dll : 1.8.34.0
slvipp64.dll : 1.0.1.0
SRSHP64.dll : 1.1.0.0
SRSTSH64.dll : 1.1.4.0
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
WavesGUILib.dll : 1.0.0.0
HDM Driver : -----
Vista/WIn7 x86:
RtHDMV.sys : 6.0.1.6121
RtkAudioSrvATI.exe : 1.0.0.23
RtkUpd.exe : 2.8.0.3
RH3DAA32.dll : 6.0.6001.18
RH3DHT32.dll : 6.0.6001.18
RHCoInst.dll : 1.0.8.6
RHDMExt.dll : 6.0.6000.127
RTEED32H.dll : 6.1.6001.33
RTEEG32H.dll : 6.1.6001.33
RTEEL32H.dll : 6.1.6001.33
RTEEP32H.dll : 6.1.6001.33
RtkHDM.dll : 11.0.6000.151

Vista/WIn7 x64:
RtHDMVX.sys : 6.0.1.6121
RtkAudioSrvATI64.exe : 1.0.0.23
RtkUpd64.exe : 2.8.0.3
RH3DAA64.dll : 6.0.6001.18
RH3DHT64.dll : 6.0.6001.18
RHCoInst64.dll : 1.0.8.6
RHDMEx64.dll : 6.0.6000.127
RTEED64H.dll : 6.1.6001.33
RTEEG64H.dll : 6.1.6001.33
RTEEL64H.dll : 6.1.6001.33
RTEEP64H.dll : 6.1.6001.33
RtkHDM64.dll : 11.0.6000.151

XP/2K x86:
RtkHDM.sys : 5.10.0.6121
Rtaupd.exe : 2.8.0.3
RHCoInstXP.dll : 1.0.8.6

XP/2K x64:
RtkHDMX.sys : 5.10.0.6121
Rtaupd64.exe : 2.8.0.3
RHCoInst64XP.dll : 1.0.8.6

Driver Setup Program : 3.10

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.52

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC892, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC892, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680

3. HDM Device WHQL Support: ATI HDM Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 - x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

Readme.txt

Windows 2000/XP : -----
 Windows 2000/XP :
 RTKHDA64.sys : 5.10.0.6194
 RtkHDAud.sys : 5.10.0.6194
 AlcWzrd.exe : 1.1.0.37
 McCal.exe : 1.1.2.4
 RTHDCPL.exe : 2.3.6.9
 RtkAudioService64.exe : 1.0.0.19
 RtkAudioService.exe : 1.0.0.19
 RTLCPL.exe : 1.0.1.66
 RtlUpd64.exe : 2.8.0.3
 RtlUpd.exe : 2.8.0.3
 SkyTel.exe : 2.0.2.0
 SoundMan.exe : 1.0.0.32
 vncutil64.exe : 1.0.0.38
 vncutil.exe : 1.0.0.38
 Alcmtr.exe : 1.6.0.4
 AMBFilt.sys : 5.10.0.4240
 AMBFt64.sys : 5.10.0.4240
 Mbnfilt.sys : 5.10.0.4112
 Mbnft64.sys : 5.10.0.4115
 OA017Afx.sys : 1.0.7.3
 ALSndMgr.cpl : 1.0.0.11
 RTSndMgr.cpl : 1.0.1.6
 RCoInst64.dll : 1.1.0.3
 RCoInst64XP.dll : 1.1.0.3
 RTCOMDLL.dll : 1.0.0.108
 RtkCoInst.dll : 1.1.0.3
 RtkCoInstXP.dll : 1.1.0.3
 RtlCPAPI.dll : 1.0.2.3

Vista/Win7 driver : -----
 Vista/Win7 driver for x86
 RTKVHDA.sys : 6.0.1.6194
 AERTSrv.exe : 1.0.32.10
 RtHDVBg.exe : 1.0.0.41
 RtHDVCpl.exe : 1.0.0.576
 RtkAudioService.exe : 1.0.0.27
 RtkNGUI.exe : 1.0.0.57
 RtlUpd.exe : 2.8.0.3
 SkyTel.exe : 2.0.2.2
 vncutil.exe : 1.0.0.40
 mbfilt32.sys : 6.10.0.8
 RTSndMgr.cpl : 1.0.0.19
 AERTACap.dll : 2.0.32.13
 AERTARen.dll : 1.0.32.9
 BlackSkinImages.dll : 1.0.0.57
 DarkSkinImages.dll : 1.0.0.57
 DTSBassEnhancementDLL.dll : 1.0.0.1
 DTSSBoostDLL.dll : 1.0.0.1
 DTSSGainCompensatorDLL.dll : 1.0.0.1
 DTSGFXAPO.dll : 1.0.0.2
 DTSGFXAPONS.dll : 1.0.0.2
 DTSLFXAPO.dll : 1.0.0.2
 DTSLimiterDLL.dll : 1.0.0.1
 DTSSNeoPCDLL.dll : 1.0.0.1
 DTSS2HeadphoneDLL.dll : 1.0.0.1
 DTSS2SpeakerDLL.dll : 1.0.0.1
 DTSSymmetryDLL.dll : 1.0.0.1
 DTSSVoiceClarityDLL.dll : 1.0.0.1
 FMAP0.dll : 42.5.35.66
 GrayJadeSkinImages.dll : 1.0.0.57
 LightSkinImages.dll : 1.0.0.57
 MaxxAudioAPO.dll : 1.2.2.0
 MaxxAudioAPO20.dll : 2.2.8.0
 MaxxAudioAPO30.dll : 3.2.0.2
 MaxxAudioEQ.dll : 5.9.7.0
 MaxxAudioRealtek.dll : 1.0.0.0
 MaxxAudioRealtek2.dll : 1.0.2.0

	Readme.txt	
MaxxVolumeSDAP0.dll		: 3.1.0.0
MBAP032.dll		: 1.0.40.0
MBPPCn32.dll		: 1.0.0.110
MBpld32.dll		: 1.0.40.0
MBTHX32.dll		: 1.0.15.120
MBWrp32.dll		: 1.0.0.180
RP3DAA32.dll		: 6.0.6001.18
RP3DHT32.dll		: 6.0.6001.18
RTCOMDLL.dll		: 2.0.0.137
RTEED32A.dll		: 6.1.6001.33
RTEEG32A.dll		: 6.1.6001.33
RTEEL32A.dll		: 6.1.6001.33
RTEEP32A.dll		: 6.1.6001.33
RtkAPO.dll		: 11.0.6000.165
RtkApoApi.dll		: 1.0.0.24
RtkCfg.dll		: 1.0.0.2
RtkColnst.dll		: 1.1.0.3
RtkGuiCompLib.dll		: 1.0.0.2
RtkPgExt.dll		: 6.0.6000.152
RtlCPAPI.dll		: 1.0.2.4
SFAP0.dll		: 3.0.0.11
SFCOM.dll		: 3.0.0.11
SFFXComm.dll		: 2.0.0.13
SFFXDAP0.dll		: 2.0.0.13
SFFXHAP0.dll		: 2.0.0.13
SFFXProc.dll		: 2.0.0.13
SFFXSAP0.dll		: 2.0.0.13
SFNHK.dll		: 3.0.0.11
slcshp32.dll		: 1.0.3.0
slgeq32.dll		: 1.0.1.0
slh36032.dll		: 1.0.2.0
slInit32.dll		: 1.1.3.0
slmaxv32.dll		: 1.1.2.0
sltshd32.dll		: 1.2.0.0
sluapo32.dll		: 1.8.34.0
slvi pp32.dll		: 1.0.1.0
SRSHP360.dll		: 1.1.0.0
SRSTSHD.dll		: 1.1.4.0
SRSTSXT.dll		: 3.2.0.0
SRSWOW.dll		: 1.1.3.0
WavesGUILib.dll		: 1.0.0.0
WavesLib.dll		: 5.9.7.0
Vista/Win7 driver for x64		
RTKVHD64.sys		: 6.0.1.6194
AERTSr64.exe		: 1.0.64.10
RAVBg64.exe		: 1.0.0.41
RAVCpl64.exe		: 1.0.0.576
RtkAudioService64.exe		: 1.0.0.27
RtkNGUI64.exe		: 1.0.0.57
RtlUpd64.exe		: 2.8.0.3
SkyTel.exe		: 2.0.2.2
vncutil64.exe		: 1.0.0.40
GWfilt64.sys		: 6.10.0.3
mbfilt64.sys		: 6.10.0.8
RTSnMg64.cpl		: 1.0.0.19
AERTAC64.dll		: 2.0.64.13
AERTAR64.dll		: 1.0.64.9
BlackSkinImages64.dll		: 1.0.0.57
DarkSkinImages64.dll		: 1.0.0.57
DTSBassEnhancementDLL64.dll		: 1.0.0.1
DTSBoostDLL64.dll		: 1.0.0.1
DTSGainCompensatorDLL64.dll		: 1.0.0.1
DTSAFXAP064.dll		: 1.0.0.2
DTSAFXAPONS64.dll		: 1.0.0.2
DTSLFXAP064.dll		: 1.0.0.2
DTSLimitDLL64.dll		: 1.0.0.1
DTSNeoPCDLL64.dll		: 1.0.0.1
DTSS2HeadphoneDLL64.dll		: 1.0.0.1
DTSS2SpeakerDLL64.dll		: 1.0.0.1

	Readme.txt	
DTSSymmetryDLL64.dll	:	1.0.0.1
DTSVoiceClarityDLL64.dll	:	1.0.0.1
FMAP064.dll	:	42.6.35.66
GrayJadeSkinImages64.dll	:	1.0.0.57
LightSkinImages64.dll	:	1.0.0.57
MaxxAudioAP020.dll	:	2.2.8.0
MaxxAudioAP030.dll	:	3.2.0.2
MaxxAudioEQ.dll	:	5.9.7.0
MaxxAudioRealtek.dll	:	1.0.0.0
MaxxAudioRealtek2.dll	:	1.0.2.0
MaxxVolumeSDAPO.dll	:	3.1.0.0
MBAP032.dll	:	1.0.40.0
MBAP064.dll	:	1.0.40.0
MBPPCn64.dll	:	1.0.0.110
Mbpld64.dll	:	1.0.40.0
MBTHX32.dll	:	1.0.15.120
MBTHX64.dll	:	1.0.15.120
MBWrp64.dll	:	1.0.0.180
RCoInst64.dll	:	1.1.0.3
RP3DAA64.dll	:	6.0.6001.18
RP3DHT64.dll	:	6.0.6001.18
RtCOMB4.dll	:	2.0.0.137
RTCOMDLL.dll	:	2.0.0.137
RTEED64A.dll	:	6.1.6001.33
RTEEG64A.dll	:	6.1.6001.33
RTEEL64A.dll	:	6.1.6001.33
RTEEP64A.dll	:	6.1.6001.33
RtkApi64.dll	:	1.0.0.24
RtkAP064.dll	:	11.0.6000.165
RtkCfg.dll	:	1.0.0.1
RtkCfg64.dll	:	1.0.0.2
RtkGuiCompLib.dll	:	1.0.0.2
RtLCPAPI.dll	:	1.0.2.4
RtLCPAPI64.dll	:	1.0.2.4
RtPgEx64.dll	:	6.0.6000.152
SFAP064.dll	:	3.0.0.11
SFCOM.dll	:	3.0.0.11
SFCOMB4.dll	:	3.0.0.11
SFComm64.dll	:	2.0.0.13
SFDAP064.dll	:	2.0.0.13
SFHAP064.dll	:	2.0.0.13
SFNHK64.dll	:	3.0.0.11
SFProc64.dll	:	2.0.0.13
SFSAP064.dll	:	2.0.0.13
SFSS_AP0.dll	:	1.0.0.8020
slcshp64.dll	:	1.0.3.0
slgeq64.dll	:	1.0.1.0
slh36064.dll	:	1.0.2.0
slInit64.dll	:	1.1.3.0
slmaxv64.dll	:	1.1.2.0
sltshd64.dll	:	1.2.0.0
sluapo64.dll	:	1.8.34.0
slvip64.dll	:	1.0.1.0
SRSHP64.dll	:	1.1.0.0
SRSTSH64.dll	:	1.1.4.0
SRSTSX64.dll	:	3.2.0.0
SRSW064.dll	:	1.1.3.0
WavesGUILib.dll	:	1.0.0.0
HDMI Driver :	-----	
Vista/WIn7 x86:		
RtHDMV.sys	:	6.0.1.6121
RtkAudioSrvATI.exe	:	1.0.0.23
RtkUpd.exe	:	2.8.0.3
RH3DAA32.dll	:	6.0.6001.18
RH3DHT32.dll	:	6.0.6001.18
RHCoInst.dll	:	1.0.8.6
RHDMExt.dll	:	6.0.6000.127
RTEED32H.dll	:	6.1.6001.33
RTEEG32H.dll	:	6.1.6001.33

Readme.txt

RTEEL32H.dll : 6.1.6001.33
RTEEP32H.dll : 6.1.6001.33
RtkHDM.dll : 11.0.6000.151

Vista/Win7 x64:

RtHDMVX.sys : 6.0.1.6121
RtkAudioSrvATI64.exe : 1.0.0.23
RtkUpd64.exe : 2.8.0.3
RH3DAA64.dll : 6.0.6001.18
RH3DHT64.dll : 6.0.6001.18
RHCoInst64.dll : 1.0.8.6
RHDME64.dll : 6.0.6000.127
RTEED64H.dll : 6.1.6001.33
RTEEG64H.dll : 6.1.6001.33
RTEEL64H.dll : 6.1.6001.33
RTEEP64H.dll : 6.1.6001.33
RtkHDM64.dll : 11.0.6000.151

XP/2K x86:

RtkHDM.sys : 5.10.0.6121
Rtaupd.exe : 2.8.0.3
RHCoInstXP.dll : 1.0.8.6

XP/2K x64:

RtkHDMX.sys : 5.10.0.6121
Rtaupd64.exe : 2.8.0.3
RHCoInst64XP.dll : 1.0.8.6

Driver Setup Program : 3.07

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.51

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC892, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC892, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 - x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :

RTKHDA64.sys : 5.10.0.6167
RtkHDAud.sys : 5.10.0.6167
Alcmtr.exe : 1.6.0.4
AlcWzrd.exe : 1.1.0.37
McCal.exe : 1.1.2.4
RTHDCPL.exe : 2.3.6.2
RtkAudioService64.exe : 1.0.0.19
RtkAudioService.exe : 1.0.0.19
RTLCPPL.exe : 1.0.1.66
RtlUpd64.exe : 2.8.0.3
RtlUpd.exe : 2.8.0.3
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.32
vncutil64.exe : 1.0.0.38
vncutil.exe : 1.0.0.38

Readme.txt

```

AMBFilt.sys : 5.10.0.4240
AMBFt64.sys : 5.10.0.4240
Mnfiltr.sys : 5.10.0.4112
Mnft64.sys : 5.10.0.4115
0A017Afx.sys : 1.0.7.3
ALSndMgr.cpl : 1.0.0.11
RTSndMgr.cpl : 1.0.1.5
RCoInst64XP.dll : 1.0.9.9
RTCOMDLL.dll : 1.0.0.108
RtkCoInstXP.dll : 1.0.9.9
RtlCPAPI.dll : 1.0.2.3
Vista/Win7 driver : -----
Vista/Win7 driver for x86
RTKVHDA.sys : 6.0.1.6167
AERTSrv.exe : 1.0.32.10
RtHDVBg.exe : 1.0.0.40
RtHDVCpl.exe : 1.0.0.553
RtkAudioService.exe : 1.0.0.27
RtkNGUI.exe : 1.0.0.53
RtlUpd.exe : 2.8.0.3
SkyTel.exe : 2.0.2.2
vncutil.exe : 1.0.0.38
mbfilt32.sys : 6.10.0.8
RTSndMgr.cpl : 1.0.0.19
AERTACap.dll : 2.0.32.13
AERTARen.dll : 1.0.32.9
BlackSkinImages.dll : 1.0.0.53
DarkSkinImages.dll : 1.0.0.53
DTSBassEnhancementDLL.dll : 1.0.0.1
DTSBoostDLL.dll : 1.0.0.1
DTSGainCompensatorDLL.dll : 1.0.0.1
DTSGFXAPO.dll : 1.0.0.2
DTSGFXAPONS.dll : 1.0.0.2
DTSLFXAPO.dll : 1.0.0.2
DTSLimitDLL.dll : 1.0.0.1
DTSNeoPCDLL.dll : 1.0.0.1
DTSS2HeadphoneDLL.dll : 1.0.0.1
DTSS2SpeakerDLL.dll : 1.0.0.1
DTSSTSymmetryDLL.dll : 1.0.0.1
DTSVoiceClarityDLL.dll : 1.0.0.1
FMAP0.dll : 42.5.32.66
GrayJadeSkinImages.dll : 1.0.0.53
LightSkinImages.dll : 1.0.0.53
MaxxAudioAPO.dll : 1.2.2.0
MaxxAudioAPO20.dll : 2.2.8.0
MaxxAudioAPO30.dll : 3.2.0.2
MaxxAudioEQ.dll : 5.9.7.0
MaxxAudioRealtek.dll : 1.0.0.0
MaxxAudioRealtek2.dll : 1.0.0.0
MaxxVolumeSDAPO.dll : 3.1.0.0
MBAP032.dll : 1.0.19.0
MBPPCn32.dll : 1.0.0.110
MBppld32.dll : 1.0.22.0
MBTHX32.dll : 1.0.15.115
MBWrp32.dll : 1.0.0.180
RP3DAA32.dll : 6.0.6001.18
RP3DHT32.dll : 6.0.6001.18
RTCOMDLL.dll : 2.0.0.136
RTEED32A.dll : 6.1.6001.33
RTEEG32A.dll : 6.1.6001.33
RTEEL32A.dll : 6.1.6001.33
RTEEP32A.dll : 6.1.6001.33
RtkAPO.dll : 11.0.6000.160
RtkApoApi.dll : 1.0.0.21
RtkCfg.dll : 1.0.0.2
RtkCoInst.dll : 1.1.0.0
RtkGuiCompLib.dll : 1.0.0.1
RtkPgExt.dll : 6.0.6000.141
RtlCPAPI.dll : 1.0.2.4

```

Readme.txt

SFAP0.dll : 3.0.0.11
 SFCOM.dll : 3.0.0.11
 SFFXComm.dll : 2.0.0.13
 SFFXDAP0.dll : 2.0.0.13
 SFFXHAP0.dll : 2.0.0.13
 SFFXProc.dll : 2.0.0.13
 SFFXSAP0.dll : 2.0.0.13
 SFNHK.dll : 3.0.0.11
 slcshp32.dll : 1.0.3.0
 slgeq32.dll : 1.0.1.0
 slh36032.dll : 1.0.2.0
 slInit32.dll : 1.1.3.0
 slmaxv32.dll : 1.1.2.0
 sltshd32.dll : 1.2.0.0
 sluapo32.dll : 1.8.34.0
 SRSHp360.dll : 1.1.0.0
 SRSTSHD.dll : 1.1.4.0
 SRSTSTX.dll : 3.2.0.0
 SRSWOW.dll : 1.1.3.0
 WavesGUILib.dll : 1.0.0.0
 WavesLib.dll : 5.9.7.0
 Vista/Win7 driver for x64
 RTKVHD64.sys : 6.0.1.6167
 AERTSr64.exe : 1.0.64.10
 RAVBg64.exe : 1.0.0.40
 RAVCpl64.exe : 1.0.0.553
 RtkAudioService64.exe : 1.0.0.27
 RtkNGUI64.exe : 1.0.0.53
 RtlUpd64.exe : 2.8.0.3
 SkyTel.exe : 2.0.2.2
 vncutil64.exe : 1.0.0.38
 GWfilt64.sys : 6.10.0.3
 mbfilt64.sys : 6.10.0.8
 RTSnMg64.cpl : 1.0.0.19
 AERTAC64.dll : 2.0.64.13
 AERTAR64.dll : 1.0.64.9
 BlackSkinImages64.dll : 1.0.0.53
 DarkSkinImages64.dll : 1.0.0.53
 DTSBassEnhancementDLL64.dll : 1.0.0.1
 DTSTBoostDLL64.dll : 1.0.0.1
 DTSGainCompensatorDLL64.dll : 1.0.0.1
 DTSGFXAP064.dll : 1.0.0.2
 DTSGFXAPONS64.dll : 1.0.0.2
 DTSLFXAP064.dll : 1.0.0.2
 DTSLimiterDLL64.dll : 1.0.0.1
 DTSSNeoPCDLL64.dll : 1.0.0.1
 DTSS2HeadphoneDLL64.dll : 1.0.0.1
 DTSS2SpeakerDLL64.dll : 1.0.0.1
 DTSSymmetryDLL64.dll : 1.0.0.1
 DTSSVoiceClarityDLL64.dll : 1.0.0.1
 FMAP064.dll : 42.6.32.66
 GrayJadeSkinImages64.dll : 1.0.0.53
 LightSkinImages64.dll : 1.0.0.53
 MaxxAudioAP020.dll : 2.2.8.0
 MaxxAudioAP030.dll : 3.2.0.2
 MaxxAudioEQ.dll : 5.9.7.0
 MaxxAudioRealtek.dll : 1.0.0.0
 MaxxAudioRealtek2.dll : 1.0.0.0
 MaxxVolumeSDAP0.dll : 3.1.0.0
 MBAP032.dll : 1.0.19.0
 MBAP064.dll : 1.0.19.0
 MBPPCn64.dll : 1.0.0.110
 Mbpld64.dll : 1.0.22.0
 MBTHX32.dll : 1.0.15.115
 MBTHX64.dll : 1.0.15.115
 MBWrp64.dll : 1.0.0.180
 RCoInst64.dll : 1.1.0.0
 RP3DAA64.dll : 6.0.6001.18
 RP3DHT64.dll : 6.0.6001.18

```

Readme.txt
RtCOMB4.dll : 2.0.0.136
RTCOMDLL.dll : 2.0.0.136
RTEED64A.dll : 6.1.6001.33
RTEEG64A.dll : 6.1.6001.33
RTEEL64A.dll : 6.1.6001.33
RTEEP64A.dll : 6.1.6001.33
RtkApi64.dll : 1.0.0.21
RtkAPO64.dll : 11.0.6000.160
RtkCfg.dll : 1.0.0.1
RtkCfg64.dll : 1.0.0.2
RtkGuiCompLib.dll : 1.0.0.1
RtlCPAPI.dll : 1.0.2.4
RtlCPAPI64.dll : 1.0.2.4
RtPgEx64.dll : 6.0.6000.141
SFAP064.dll : 3.0.0.11
SFCOM.dll : 3.0.0.11
SFCOMB4.dll : 3.0.0.11
SFCOMM64.dll : 2.0.0.13
SFDAP064.dll : 2.0.0.13
SFHAP064.dll : 2.0.0.13
SFNHK64.dll : 3.0.0.11
SFProc64.dll : 2.0.0.13
SFSAP064.dll : 2.0.0.13
slcshp64.dll : 1.0.3.0
slgeq64.dll : 1.0.1.0
slh36064.dll : 1.0.2.0
slinit64.dll : 1.1.3.0
slmaxv64.dll : 1.1.2.0
sltshd64.dll : 1.2.0.0
sluapo64.dll : 1.8.34.0
SRSHP64.dll : 1.1.0.0
SRSTSH64.dll : 1.1.4.0
SRSTX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
WavesGUILib.dll : 1.0.0.0
HDM Driver : -----
Vista/Win7 x86:
RtHDMV.sys : 6.0.1.6121
RtkAudioSrvATI.exe : 1.0.0.23
RtkUpd.exe : 2.8.0.3
RH3DAA32.dll : 6.0.6001.18
RH3DHT32.dll : 6.0.6001.18
RHCoInst.dll : 1.0.8.6
RHDMExt.dll : 6.0.6000.127
RTEED32H.dll : 6.1.6001.33
RTEEG32H.dll : 6.1.6001.33
RTEEL32H.dll : 6.1.6001.33
RTEEP32H.dll : 6.1.6001.33
RtkHDM.dll : 11.0.6000.151

Vista/Win7 x64:
RtHDMVX.sys : 6.0.1.6121
RtkAudioSrvATI64.exe : 1.0.0.23
RtkUpd64.exe : 2.8.0.3
RH3DAA64.dll : 6.0.6001.18
RH3DHT64.dll : 6.0.6001.18
RHCoInst64.dll : 1.0.8.6
RHDMeX64.dll : 6.0.6000.127
RTEED64H.dll : 6.1.6001.33
RTEEG64H.dll : 6.1.6001.33
RTEEL64H.dll : 6.1.6001.33
RTEEP64H.dll : 6.1.6001.33
RtkHDM64.dll : 11.0.6000.151

XP/2K x86:
RtkHDM.sys : 5.10.0.6121
Rtaupd.exe : 2.8.0.3
RHCoInstXP.dll : 1.0.8.6

```

Readme.txt

XP/2K x64:
RtkHDMX.sys : 5.10.0.6121
Rtaupd64.exe : 2.8.0.3
RHCoInst64XP.dll : 1.0.8.6

Driver Setup Program : 3.06

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.50

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC892, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC892, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680

3. HDM Device WHQL Support: ATI HDM Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 - x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :

RTKHDA64.sys : 5.10.0.6151
RTKHDAUD.sys : 5.10.0.6151
Alcmtr.exe : 1.6.0.4
AlcWzrd.exe : 1.1.0.37
MicCal.exe : 1.1.2.4
RTHDCPL.exe : 2.3.6.1
RtkAudioService.exe : 1.0.0.19
RtkAudioService64.exe : 1.0.0.19
RTLCPPL.exe : 1.0.1.66
RtlUpd.exe : 2.8.0.3
RtlUpd64.exe : 2.8.0.3
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.32
vncutil.exe : 1.0.0.38
vncutil64.exe : 1.0.0.38
AMBfilt.sys : 5.10.0.4240
AMBft64.sys : 5.10.0.4240
Mbnfilt.sys : 5.10.0.4112
Mbnft64.sys : 5.10.0.4115
OA017Afx.sys : 1.0.7.3
ALSndMgr.cpl : 1.0.0.11
RTSndMgr.cpl : 1.0.1.5
RCoInst64XP.dll : 1.0.9.9
RTCOMDLL.dll : 1.0.0.108
RtkCoInstXP.dll : 1.0.9.9
RtlCPAPI.dll : 1.0.2.3

Vista/Win7 driver : -----

Vista/Win7 driver for x86

RTKVHDA.sys : 6.0.1.6151
AERTSrv.exe : 1.0.32.10
RtHDVBg.exe : 1.0.0.38
RtHDVCpl.exe : 1.0.0.545
RtkAudioService.exe : 1.0.0.27
RtkNGUI.exe : 1.0.0.52
RtlUpd.exe : 2.8.0.3
SkyTel.exe : 2.0.2.2
vncutil.exe : 1.0.0.38
mbfilt32.sys : 6.10.0.8

	Readme.txt	
RTSndMgr.cpl	:	1.0.0.19
AERTACap.dll	:	2.0.32.11
AERTARen.dll	:	1.0.32.9
BlackSkinImages.dll	:	1.0.0.52
DarkSkinImages.dll	:	1.0.0.52
DTSBassEnhancementDLL.dll	:	1.0.0.1
DTSBoostDLL.dll	:	1.0.0.1
DTSGainCompensatorDLL.dll	:	1.0.0.1
DTSAFXAP0.dll	:	1.0.0.2
DTSAFXAPONS.dll	:	1.0.0.2
DTSLFXAP0.dll	:	1.0.0.2
DTSLimitDLL.dll	:	1.0.0.1
DTSNeoPCDLL.dll	:	1.0.0.1
DTSS2HeadphoneDLL.dll	:	1.0.0.1
DTSS2SpeakerDLL.dll	:	1.0.0.1
DTSSymmetryDLL.dll	:	1.0.0.1
DTSVoiceClarityDLL.dll	:	1.0.0.1
FMAP0.dll	:	42.5.32.66
GrayJadeSkinImages.dll	:	1.0.0.52
LightSkinImages.dll	:	1.0.0.52
MaxxAudioAP0.dll	:	1.2.2.0
MaxxAudioAP020.dll	:	2.2.8.0
MaxxAudioAP030.dll	:	3.1.0.0
MaxxAudioEQ.dll	:	5.9.7.0
MaxxAudioRealtek.dll	:	1.0.0.0
MaxxAudioRealtek2.dll	:	1.0.0.0
MaxxVolumeSDAP0.dll	:	3.1.0.0
MBAP032.dll	:	1.0.19.0
MBPPCn32.dll	:	1.0.0.110
MBpld32.dll	:	1.0.22.0
MBTHX32.dll	:	1.0.15.115
MBWrp32.dll	:	1.0.0.180
RP3DAA32.dll	:	6.0.6001.18
RP3DHT32.dll	:	6.0.6001.18
RTCOMDLL.dll	:	2.0.0.135
RTEED32A.dll	:	6.1.6001.33
RTEEG32A.dll	:	6.1.6001.33
RTEEL32A.dll	:	6.1.6001.33
RTEEP32A.dll	:	6.1.6001.33
RtkAP0.dll	:	11.0.6000.156
RtkApoApi.dll	:	1.0.0.21
RtkCfg.dll	:	1.0.0.2
RtkColInst.dll	:	1.1.0.0
RtkGuiCompLib.dll	:	1.0.0.1
RtkPgExt.dll	:	6.0.6000.138
RtlCPAPI.dll	:	1.0.2.4
SFAP0.dll	:	3.0.0.8
SFCOM.dll	:	3.0.0.8
SFFXComm.dll	:	2.0.0.12
SFFXDAP0.dll	:	2.0.0.12
SFFXHAP0.dll	:	2.0.0.12
SFFXProc.dll	:	2.0.0.12
SFFXSAP0.dll	:	2.0.0.12
SFNHK.dll	:	3.0.0.8
slcshp32.dll	:	1.0.3.0
slgeq32.dll	:	1.0.1.0
slh36032.dll	:	1.0.2.0
slinit32.dll	:	1.1.3.0
slmaxv32.dll	:	1.1.2.0
sltshd32.dll	:	1.2.0.0
sluapo32.dll	:	1.8.34.0
SRSHP360.dll	:	1.1.0.0
SRSTSHD.dll	:	1.1.4.0
SRSTSXT.dll	:	3.2.0.0
SRSWOW.dll	:	1.1.3.0
WavesGUILib.dll	:	1.0.0.0
WavesLib.dll	:	5.9.7.0
Vista/Win7 driver for x64		
RTKVHD64.sys	:	6.0.1.6151

Readme.txt

AERTSr64.exe : 1.0.64.10
 RAVBg64.exe : 1.0.0.38
 RAVCpl64.exe : 1.0.0.545
 RtkAudioService64.exe : 1.0.0.27
 RtkNGUI64.exe : 1.0.0.52
 RtlUpd64.exe : 2.8.0.3
 SkyTel.exe : 2.0.2.2
 vncutil64.exe : 1.0.0.38
 GWfilt64.sys : 6.10.0.3
 mbfilt64.sys : 6.10.0.8
 RTSnMg64.cpl : 1.0.0.19
 AERTAC64.dll : 2.0.64.11
 AERTAR64.dll : 1.0.64.9
 BlackSkinImages64.dll : 1.0.0.52
 DarkSkinImages64.dll : 1.0.0.52
 DTSBassEnhancementDLL64.dll : 1.0.0.1
 DTSTBoostDLL64.dll : 1.0.0.1
 DTSGainCompensatorDLL64.dll : 1.0.0.1
 DTSGFXAP064.dll : 1.0.0.2
 DTSGFXAPONS64.dll : 1.0.0.2
 DTSLFXAP064.dll : 1.0.0.2
 DTSLimiterDLL64.dll : 1.0.0.1
 DTSSNeoPCDLL64.dll : 1.0.0.1
 DTSS2HeadphoneDLL64.dll : 1.0.0.1
 DTSS2SpeakerDLL64.dll : 1.0.0.1
 DTSSymmetryDLL64.dll : 1.0.0.1
 DTSVoiceClarityDLL64.dll : 1.0.0.1
 FMAP064.dll : 42.6.32.66
 GrayJadeSkinImages64.dll : 1.0.0.52
 LightSkinImages64.dll : 1.0.0.52
 MaxxAudioAP020.dll : 2.2.8.0
 MaxxAudioAP030.dll : 3.1.0.0
 MaxxAudioEQ.dll : 5.9.7.0
 MaxxAudioRealtek.dll : 1.0.0.0
 MaxxAudioRealtek2.dll : 1.0.0.0
 MaxxVolumeSDAPO.dll : 3.1.0.0
 MBAP032.dll : 1.0.19.0
 MBAP064.dll : 1.0.19.0
 MBPPCn64.dll : 1.0.0.110
 MBpld64.dll : 1.0.22.0
 MBTHX32.dll : 1.0.15.115
 MBTHX64.dll : 1.0.15.115
 MBWrp64.dll : 1.0.0.180
 RCoInst64.dll : 1.1.0.0
 RP3DAA64.dll : 6.0.6001.18
 RP3DHT64.dll : 6.0.6001.18
 RtCOM64.dll : 2.0.0.135
 RTCOMDLL.dll : 2.0.0.135
 RTEED64A.dll : 6.1.6001.33
 RTEEG64A.dll : 6.1.6001.33
 RTEEL64A.dll : 6.1.6001.33
 RTEEP64A.dll : 6.1.6001.33
 RtkApi64.dll : 1.0.0.21
 RtkAP064.dll : 11.0.6000.156
 RtkCfg.dll : 1.0.0.1
 RtkCfg64.dll : 1.0.0.2
 RtkGuiCompLib.dll : 1.0.0.1
 RtlCPAPI.dll : 1.0.2.4
 RtlCPAPI64.dll : 1.0.2.4
 RtlPgEx64.dll : 6.0.6000.138
 SFAP064.dll : 3.0.0.8
 SFCOM.dll : 3.0.0.8
 SFCOM64.dll : 3.0.0.8
 SFComm64.dll : 2.0.0.12
 SFDAP064.dll : 2.0.0.12
 SFHAP064.dll : 2.0.0.12
 SFNHK64.dll : 3.0.0.8
 SFProc64.dll : 2.0.0.12
 SFSAP064.dll : 2.0.0.12

Readme.txt

```

slcshp64.dll : 1.0.3.0
slgeq64.dll : 1.0.1.0
slh36064.dll : 1.0.2.0
slInit64.dll : 1.1.3.0
slmaxv64.dll : 1.1.2.0
sltshd64.dll : 1.2.0.0
sluapo64.dll : 1.8.34.0
SRSHp64.dll : 1.1.0.0
SRSTSH64.dll : 1.1.4.0
SRSTX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
WavesGUILib.dll : 1.0.0.0
HDM Driver : -----
Vista/Win7 x86:
RtHDMV.sys : 6.0.1.6121
RtkAudioSrvATI.exe : 1.0.0.23
RtkUpd.exe : 2.8.0.3
RH3DAA32.dll : 6.0.6001.18
RH3DHT32.dll : 6.0.6001.18
RHCoInst.dll : 1.0.8.6
RHDMExt.dll : 6.0.6000.127
RTEED32H.dll : 6.1.6001.33
RTEEG32H.dll : 6.1.6001.33
RTEEL32H.dll : 6.1.6001.33
RTEEP32H.dll : 6.1.6001.33
RtkHDM.dll : 11.0.6000.151

Vista/Win7 x64:
RtHDMVX.sys : 6.0.1.6121
RtkAudioSrvATI64.exe : 1.0.0.23
RtkUpd64.exe : 2.8.0.3
RH3DAA64.dll : 6.0.6001.18
RH3DHT64.dll : 6.0.6001.18
RHCoInst64.dll : 1.0.8.6
RHDMEX64.dll : 6.0.6000.127
RTEED64H.dll : 6.1.6001.33
RTEEG64H.dll : 6.1.6001.33
RTEEL64H.dll : 6.1.6001.33
RTEEP64H.dll : 6.1.6001.33
RtkHDM64.dll : 11.0.6000.151

XP/2K x86:
RtkHDM.sys : 5.10.0.6121
Rtaupd.exe : 2.8.0.3
RHCoInstXP.dll : 1.0.8.6

XP/2K x64:
RtkHDMX.sys : 5.10.0.6121
Rtaupd64.exe : 2.8.0.3
RHCoInst64XP.dll : 1.0.8.6

Driver Setup Program : 3.01

```

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.49

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC892, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC892, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008,

Readme.txt

Windows7 - x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Driver :
 1. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :	
RTKHDA64.sys	: 5.10.0.6132
RTKHDAUD.sys	: 5.10.0.6132
Mccal.exe	: 1.1.2.4
RTHDCPL.exe	: 2.3.5.5
RtkAudioService64.exe	: 1.0.0.19
RtkAudioService.exe	: 1.0.0.19
RTLCPPL.exe	: 1.0.1.66
RtlUpd64.exe	: 2.8.0.3
RtlUpd.exe	: 2.8.0.3
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.32
vncutil64.exe	: 1.0.0.38
vncutil.exe	: 1.0.0.38
Alcmtr.exe	: 1.6.0.4
AlcWzrd.exe	: 1.1.0.37
Mnflt.sys	: 5.10.0.4112
Mnft64.sys	: 5.10.0.4115
OA017Afx.sys	: 1.0.7.3
AMBFilt.sys	: 5.10.0.4240
AMBFt64.sys	: 5.10.0.4240
RTSndMgr.cpl	: 1.0.1.5
ALSndMgr.cpl	: 1.0.0.11
RCoInst64XP.dll	: 1.0.9.2
RTCOMDLL.dll	: 1.0.0.108
RtkCoInstXP.dll	: 1.0.9.2
RtlCPAPI.dll	: 1.0.2.3

Vista/Wn7 driver : -----

Vista/Wn7 driver for x86	
RTKVHDA.sys	: 6.0.1.6132
AERTSrv.exe	: 1.0.32.10
RtHDVBg.exe	: 1.0.0.26
RtHDVCpl.exe	: 1.0.0.530
RtkAudioService.exe	: 1.0.0.24
RtkNGUI.exe	: 1.0.0.48
RtlUpd.exe	: 2.8.0.3
SkyTel.exe	: 2.0.2.2
vncutil.exe	: 1.0.0.38
mbflt32.sys	: 6.10.0.8
RTSndMgr.cpl	: 1.0.0.19
AERTACap.dll	: 2.0.32.11
AERTARen.dll	: 1.0.32.9
BlackSkinImages.dll	: 1.0.0.48
DarkSkinImages.dll	: 1.0.0.48
DTSBassEnhancementDLL.dll	: 1.0.0.1
DTSBoostDLL.dll	: 1.0.0.1
DTSGainCompensatorDLL.dll	: 1.0.0.1
DTSAFXAPO.dll	: 1.0.0.1
DTSAFXAPONS.dll	: 1.0.0.1
DTSLFXAPO.dll	: 1.0.0.1
DTSLimiterDLL.dll	: 1.0.0.1
DTSNeoPCDLL.dll	: 1.0.0.1
DTSS2HeadphoneDLL.dll	: 1.0.0.1
DTSS2SpeakerDLL.dll	: 1.0.0.1
DTSSymmetryDLL.dll	: 1.0.0.1
DTSVoiceClarityDLL.dll	: 1.0.0.1
FMAPO.dll	: 42.5.32.66
LightSkinImages.dll	: 1.0.0.48
MaxxAudioAPO.dll	: 1.2.2.0
MaxxAudioAPO20.dll	: 2.2.8.0
MaxxAudioAPO30.dll	: 3.1.0.0
MaxxAudioEQ.dll	: 5.9.7.0

	Readme.txt	
MaxxAudioRealtek.dll	:	1.0.0.0
MaxxVolumeSDAPO.dll	:	3.1.0.0
MBAP032.dll	:	1.0.19.0
MBPPCn32.dll	:	1.0.0.110
Mbpld32.dll	:	1.0.22.0
MBTHX32.dll	:	1.0.15.112
MWRp32.dll	:	1.0.0.160
RP3DAA32.dll	:	6.0.6001.18
RP3DHT32.dll	:	6.0.6001.18
RTCOMDLL.dll	:	2.0.0.134
RTEED32A.dll	:	6.1.6001.33
RTEEG32A.dll	:	6.1.6001.33
RTEEL32A.dll	:	6.1.6001.33
RTEEP32A.dll	:	6.1.6001.33
RtkAPO.dll	:	11.0.6000.152
RtkApoApi.dll	:	1.0.0.21
RtkCfg.dll	:	1.0.0.2
RtkCoInst.dll	:	1.0.9.2
RtkPgExt.dll	:	6.0.6000.130
RtlCPAPI.dll	:	1.0.2.4
SFFXComm.dll	:	2.0.0.12
SFFXDAP0.dll	:	2.0.0.12
SFFXHAP0.dll	:	2.0.0.12
SFFXProc.dll	:	2.0.0.12
SFFXSAP0.dll	:	2.0.0.12
slcshp32.dll	:	1.0.3.0
slgeq32.dll	:	1.0.1.0
slh36032.dll	:	1.0.2.0
slInit32.dll	:	1.1.3.0
slmaxv32.dll	:	1.1.2.0
sltshd32.dll	:	1.2.0.0
sluapo32.dll	:	1.8.34.0
SRSHP360.dll	:	1.1.0.0
SRSTSHD.dll	:	1.1.4.0
SRSTSXT.dll	:	3.2.0.0
SRSWOW.dll	:	1.1.3.0
WavesGUILib.dll	:	1.0.0.0
WavesLib.dll	:	5.9.7.0
Vista/Win7 driver for x64		
RTKVHD64.sys	:	6.0.1.6132
AERTSr64.exe	:	1.0.64.10
RAVBg64.exe	:	1.0.0.26
RAVCpl64.exe	:	1.0.0.530
RtkAudioService64.exe	:	1.0.0.24
RtkNGUI64.exe	:	1.0.0.48
RtlUpd64.exe	:	2.8.0.3
SkyTel.exe	:	2.0.2.2
vncutil64.exe	:	1.0.0.38
GWfilt64.sys	:	6.10.0.3
mbfilt64.sys	:	6.10.0.8
RTSnMg64.cpl	:	1.0.0.19
AERTAC64.dll	:	2.0.64.11
AERTAR64.dll	:	1.0.64.9
BlackSkinImages64.dll	:	1.0.0.48
DarkSkinImages64.dll	:	1.0.0.48
DTSBassEnhancementDLL64.dll	:	1.0.0.1
DTSBoostDLL64.dll	:	1.0.0.1
DTSGainCompensatorDLL64.dll	:	1.0.0.1
DTSAFXAP064.dll	:	1.0.0.1
DTSAFXAPONS64.dll	:	1.0.0.1
DTSLFXAP064.dll	:	1.0.0.1
DTSLimitDLL64.dll	:	1.0.0.1
DTSNeoPCDLL64.dll	:	1.0.0.1
DTSS2HeadphoneDLL64.dll	:	1.0.0.1
DTSS2SpeakerDLL64.dll	:	1.0.0.1
DTSSymmetryDLL64.dll	:	1.0.0.1
DTSVoiceClarityDLL64.dll	:	1.0.0.1
FMAP064.dll	:	42.6.32.66
LightSkinImages64.dll	:	1.0.0.48

Readme.txt

MaxxAudioAP020.dll	: 2.2.8.0
MaxxAudioAP030.dll	: 3.1.0.0
MaxxAudioEQ.dll	: 5.9.7.0
MaxxAudioRealtek.dll	: 1.0.0.0
MaxxVolumeSDAPO.dll	: 3.1.0.0
MBAP032.dll	: 1.0.19.0
MBAP064.dll	: 1.0.19.0
MBPPCn64.dll	: 1.0.0.110
Mbpld64.dll	: 1.0.22.0
MBTHX32.dll	: 1.0.15.112
MBTHX64.dll	: 1.0.15.112
MBWrp64.dll	: 1.0.0.160
RCoInst64.dll	: 1.0.9.2
RP3DAA64.dll	: 6.0.6001.18
RP3DHT64.dll	: 6.0.6001.18
RtCOMB4.dll	: 2.0.0.134
RTCOMDLL.dll	: 2.0.0.134
RTEED64A.dll	: 6.1.6001.33
RTEEG64A.dll	: 6.1.6001.33
RTEEL64A.dll	: 6.1.6001.33
RTEEP64A.dll	: 6.1.6001.33
RtkApi64.dll	: 1.0.0.21
RtkAPO64.dll	: 11.0.6000.152
RtkCfg.dll	: 1.0.0.1
RtkCfg64.dll	: 1.0.0.2
RtLCPAPI.dll	: 1.0.2.4
RtLCPAPI64.dll	: 1.0.2.4
RtPgEx64.dll	: 6.0.6000.130
SFComm64.dll	: 2.0.0.12
SFDAP064.dll	: 2.0.0.12
SFHAP064.dll	: 2.0.0.12
SFProc64.dll	: 2.0.0.12
SFSAP064.dll	: 2.0.0.12
slcshp64.dll	: 1.0.3.0
slgeq64.dll	: 1.0.1.0
slh36064.dll	: 1.0.2.0
slInit64.dll	: 1.1.3.0
slmaxv64.dll	: 1.1.2.0
sltshd64.dll	: 1.2.0.0
sluapo64.dll	: 1.8.34.0
SRSHP64.dll	: 1.1.0.0
SRSTSH64.dll	: 1.1.4.0
SRSTSX64.dll	: 3.2.0.0
SRSWOW64.dll	: 1.1.3.0
WavesGUILib.dll	: 1.0.0.0
HDMI Driver : -----	
Vista/Win7 x86:	
RtHDMV.sys	: 6.0.1.6121
RtkAudioSrvATI.exe	: 1.0.0.23
RtkUpd.exe	: 2.8.0.3
RH3DAA32.dll	: 6.0.6001.18
RH3DHT32.dll	: 6.0.6001.18
RHCoInst.dll	: 1.0.8.6
RHDMExt.dll	: 6.0.6000.127
RTEED32H.dll	: 6.1.6001.33
RTEEG32H.dll	: 6.1.6001.33
RTEEL32H.dll	: 6.1.6001.33
RTEEP32H.dll	: 6.1.6001.33
RtkHDM.dll	: 11.0.6000.151
Vista/Win7 x64:	
RtHDMVX.sys	: 6.0.1.6121
RtkAudioSrvATI64.exe	: 1.0.0.23
RtkUpd64.exe	: 2.8.0.3
RH3DAA64.dll	: 6.0.6001.18
RH3DHT64.dll	: 6.0.6001.18
RHCoInst64.dll	: 1.0.8.6
RHDMEx64.dll	: 6.0.6000.127
RTEED64H.dll	: 6.1.6001.33

Readme.txt

RTEEG64H.dll : 6.1.6001.33
RTEEL64H.dll : 6.1.6001.33
RTEEP64H.dll : 6.1.6001.33
RtkHDM64.dll : 11.0.6000.151

XP/2K x86:
RtkHDM.sys : 5.10.0.6121
Rtaupd.exe : 2.8.0.3
RHCoInstXP.dll : 1.0.8.6

XP/2K x64:
RtkHDMX.sys : 5.10.0.6121
Rtaupd64.exe : 2.8.0.3
RHCoInst64XP.dll : 1.0.8.6

Driver Setup Program : 2.99

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.48

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC892, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC892, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 - x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :

RTKHDA64.sys : 5.10.0.6101
RTKHDAUD.sys : 5.10.0.6101
Alcmtr.exe : 1.6.0.4
AlcWzrd.exe : 1.1.0.37
MicCal.exe : 1.1.2.3
RTHDCPL.exe : 2.3.4.9
RtkAudioService.exe : 1.0.0.19
RtkAudioService64.exe : 1.0.0.19
RTLCPPL.exe : 1.0.1.66
RtlUpd.exe : 2.8.0.3
RtlUpd64.exe : 2.8.0.3
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.32
vncutil.exe : 1.0.0.38
vncutil64.exe : 1.0.0.38
AMBfilt.sys : 5.10.0.4240
AMBft64.sys : 5.10.0.4240
Mbnfilt.sys : 5.10.0.4112
Mbnft64.sys : 5.10.0.4115
OA017Afx.sys : 1.0.7.3
ALSndMgr.cpl : 1.0.0.11
RTSndMgr.cpl : 1.0.1.4
RCoInst64XP.dll : 1.0.8.6
RtCOMDLL.dll : 1.0.0.107
RtkCoInstXP.dll : 1.0.8.6
RtlCPAPI.dll : 1.0.2.3

Vista/Wn7 driver : -----

Vista/Wn7 driver for x86

Readme.txt

RTKVHDA.sys : 6.0.1.6101
 AERTSrv.exe : 1.0.32.10
 RtHDVBg.exe : 1.0.0.18
 RtHDVCpl.exe : 1.0.0.513
 RtkAudioService.exe : 1.0.0.24
 RtkNGUI.exe : 1.0.0.39
 RtUpd.exe : 2.8.0.3
 SkyTel.exe : 2.0.2.2
 vncutil.exe : 1.0.0.38
 mbfilt32.sys : 6.10.0.8
 RTSndMgr.cpl : 1.0.0.18
 AERTACap.dll : 2.0.32.11
 AERTARen.dll : 1.0.32.9
 BlackSkinImages.dll : 1.0.0.39
 DarkSkinImages.dll : 1.0.0.39
 DTSBassEnhancementDLL.dll : 1.0.0.1
 DTSTBoostDLL.dll : 1.0.0.1
 DTSGainCompensatorDLL.dll : 1.0.0.1
 DTSGFXAPO.dll : 1.0.0.1
 DTSGFXAPONS.dll : 1.0.0.1
 DTSLFXAPO.dll : 1.0.0.1
 DTSLimiterDLL.dll : 1.0.0.1
 DTSSNeoPCDLL.dll : 1.0.0.1
 DTSS2HeadphoneDLL.dll : 1.0.0.1
 DTSS2SpeakerDLL.dll : 1.0.0.1
 DTSSymmetryDLL.dll : 1.0.0.1
 DTSVoiceClarityDLL.dll : 1.0.0.1
 FMAP0.dll : 42.5.32.66
 LightSkinImages.dll : 1.0.0.39
 MaxxAudioAPO.dll : 1.2.2.0
 MaxxAudioAPO20.dll : 2.2.8.0
 MaxxAudioAPO30.dll : 3.1.0.0
 MaxxAudioEQ.dll : 5.9.7.0
 MaxxAudioRealtek.dll : 1.0.0.0
 MaxxVolumeSDAPO.dll : 3.1.0.0
 MBAP032.dll : 1.0.19.0
 MBPPCn32.dll : 1.0.0.110
 MBpld32.dll : 1.0.22.0
 MBTHX32.dll : 1.0.15.110
 MBWp32.dll : 1.0.0.110
 RP3DAA32.dll : 6.0.6001.18
 RP3DHT32.dll : 6.0.6001.18
 RTCOMDLL.dll : 2.0.0.130
 RTEED32A.dll : 6.1.6001.33
 RTEEG32A.dll : 6.1.6001.33
 RTEEL32A.dll : 6.1.6001.33
 RTEEP32A.dll : 6.1.6001.33
 RtkAPO.dll : 11.0.6000.149
 RtkApoApi.dll : 1.0.0.21
 RtkCfg.dll : 1.0.0.2
 RtkColInst.dll : 1.0.8.7
 RtkPgExt.dll : 6.0.6000.122
 RtLCPAPI.dll : 1.0.2.4
 SFFXComm.dll : 2.0.0.12
 SFFXDAP0.dll : 2.0.0.12
 SFFXHAP0.dll : 2.0.0.12
 SFFXProc.dll : 2.0.0.12
 SFFXSAP0.dll : 2.0.0.12
 slcshp32.dll : 1.0.3.0
 slgeq32.dll : 1.0.1.0
 slh36032.dll : 1.0.2.0
 slInit32.dll : 1.1.3.0
 slmaxv32.dll : 1.1.2.0
 sltshd32.dll : 1.1.1.0
 sluapo32.dll : 1.8.24.0
 SRSHP360.dll : 1.1.0.0
 SRSTSHD.dll : 1.1.4.0
 SRSTSXT.dll : 3.2.0.0
 SRSWOW.dll : 1.1.3.0

WavesGUILib.dll	: 1.0.0.0
WavesLib.dll	: 5.9.7.0
Vista/Win7 driver for x64	
RTKVHD64.sys	: 6.0.1.6101
AERTSr64.exe	: 1.0.64.10
RAVBg64.exe	: 1.0.0.18
RAVCpl64.exe	: 1.0.0.513
RtkAudioService64.exe	: 1.0.0.24
RtkNGUI64.exe	: 1.0.0.39
RtlUpd64.exe	: 2.8.0.3
SkyTel.exe	: 2.0.2.2
vncutil64.exe	: 1.0.0.38
GWfilt64.sys	: 6.10.0.3
mbfilt64.sys	: 6.10.0.8
RTSnMg64.cpl	: 1.0.0.18
AERTAC64.dll	: 2.0.64.11
AERTAR64.dll	: 1.0.64.9
BlackSkinImages64.dll	: 1.0.0.39
DarkSkinImages64.dll	: 1.0.0.39
DTSBassEnhancementDLL64.dll	: 1.0.0.1
DTSBoostDLL64.dll	: 1.0.0.1
DTSGainCompensatorDLL64.dll	: 1.0.0.1
DTSAFXAP064.dll	: 1.0.0.1
DTSAFXAPONS64.dll	: 1.0.0.1
DTSLFXAP064.dll	: 1.0.0.1
DTSLimitDLL64.dll	: 1.0.0.1
DTSNeoPCDLL64.dll	: 1.0.0.1
DTSS2HeadphoneDLL64.dll	: 1.0.0.1
DTSS2SpeakerDLL64.dll	: 1.0.0.1
DTSSymmetryDLL64.dll	: 1.0.0.1
DTSVoiceClarityDLL64.dll	: 1.0.0.1
FMAP064.dll	: 42.6.32.66
LightSkinImages64.dll	: 1.0.0.39
MaxxAudioAP020.dll	: 2.2.8.0
MaxxAudioAP030.dll	: 3.1.0.0
MaxxAudioEQ.dll	: 5.9.7.0
MaxxAudioRealtek.dll	: 1.0.0.0
MaxxVolumeSDAP0.dll	: 3.1.0.0
MBAP032.dll	: 1.0.19.0
MBAP064.dll	: 1.0.19.0
MBPPCn64.dll	: 1.0.0.110
MBpld64.dll	: 1.0.22.0
MBTHX32.dll	: 1.0.15.110
MBTHX64.dll	: 1.0.15.110
MBWrp64.dll	: 1.0.0.110
RCoInst64.dll	: 1.0.8.7
RP3DAA64.dll	: 6.0.6001.18
RP3DHT64.dll	: 6.0.6001.18
RtCOM64.dll	: 2.0.0.130
RTCOMDLL.dll	: 2.0.0.130
RTEED64A.dll	: 6.1.6001.33
RTEEG64A.dll	: 6.1.6001.33
RTEEL64A.dll	: 6.1.6001.33
RTEEP64A.dll	: 6.1.6001.33
RtkApi64.dll	: 1.0.0.21
RtkAP064.dll	: 11.0.6000.149
RtkCfg.dll	: 1.0.0.1
RtkCfg64.dll	: 1.0.0.2
RtlCPAPI.dll	: 1.0.2.4
RtlCPAPI64.dll	: 1.0.2.4
RtPgEx64.dll	: 6.0.6000.122
SFComm64.dll	: 2.0.0.12
SFDAP064.dll	: 2.0.0.12
SFHAP064.dll	: 2.0.0.12
SFProc64.dll	: 2.0.0.12
SFSAP064.dll	: 2.0.0.12
slcshp64.dll	: 1.0.3.0
slgeq64.dll	: 1.0.1.0
slh36064.dll	: 1.0.2.0


```

Readme.txt
slInit64.dll : 1.1.3.0
slmaxv64.dll : 1.1.2.0
sltshd64.dll : 1.1.1.0
sluapo64.dll : 1.8.24.0
SRSHp64.dll : 1.1.0.0
SRSTSH64.dll : 1.1.4.0
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
WavesGUILib.dll : 1.0.0.0
HDM Driver : -----
Vista/Win7 x86:
RtHDMV.sys : 6.0.1.6034
RtkAudioSrvATI.exe : 1.0.0.23
RtkUpd.exe : 2.8.0.1
RH3DAA32.dll : 6.0.6001.18
RH3DHT32.dll : 6.0.6001.18
RHCoInst.dll : 1.0.8.2
RHDmExt.dll : 6.0.6000.113
RTEED32H.dll : 6.1.6001.33
RTEEG32H.dll : 6.1.6001.33
RTEEL32H.dll : 6.1.6001.33
RTEEP32H.dll : 6.1.6001.33
RtkHDM.dll : 11.0.6000.132

Vista/Win7 x64:
RtHDMVX.sys : 6.0.1.6034
RtkAudioSrvATI64.exe : 1.0.0.23
RtkUpd64.exe : 2.8.0.1
RH3DAA64.dll : 6.0.6001.18
RH3DHT64.dll : 6.0.6001.18
RHCoInst64.dll : 1.0.8.2
RHDmEx64.dll : 6.0.6000.113
RTEED64H.dll : 6.1.6001.33
RTEEG64H.dll : 6.1.6001.33
RTEEL64H.dll : 6.1.6001.33
RTEEP64H.dll : 6.1.6001.33
RtkHDM64.dll : 11.0.6000.132

XP/2K x86:
RtkHDM.sys : 5.10.0.6034
Rtaupd.exe : 2.8.0.1
RHCoInstXP.dll : 1.0.8.2

XP/2K x64:
RtkHDMX.sys : 5.10.0.6034
Rtaupd64.exe : 2.8.0.1
RHCoInst64XP.dll : 1.0.8.2

Driver Setup Program : 2.99

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

```

//=====

Driver Package R2.47

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC892, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC892, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 - x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix

Readme.txt

- 1.) Driver :
 1. Customizations.

Windows 2000/XP : -----
 Windows 2000/XP :
 RTKHDA64.sys : 5.10.0.6083
 RTKHDAUD.sys : 5.10.0.6083
 McCal.exe : 1.1.2.3
 RTHDCPL.exe : 2.3.4.7
 RtkAudioService64.exe : 1.0.0.19
 RtkAudioService.exe : 1.0.0.19
 RTLCPL.exe : 1.0.1.66
 RtlUpd64.exe : 2.8.0.1
 RtlUpd.exe : 2.8.0.1
 SkyTel.exe : 2.0.2.0
 SoundMan.exe : 1.0.0.32
 vncutil64.exe : 1.0.0.38
 vncutil.exe : 1.0.0.38
 Alcmtr.exe : 1.6.0.4
 AlcWzrd.exe : 1.1.0.37
 AMBFilt.sys : 5.10.0.4240
 AMBFt64.sys : 5.10.0.4240
 Mbnfilt.sys : 5.10.0.4112
 Mbnft64.sys : 5.10.0.4115
 OA017Afx.sys : 1.0.7.3
 RTSndMgr.cpl : 1.0.1.4
 ALSndMgr.cpl : 1.0.0.11
 RCoInst64XP.dll : 1.0.8.6
 RTCOMDLL.dll : 1.0.0.107
 RtkCoInstXP.dll : 1.0.8.6
 RtlCPAPI.dll : 1.0.2.3

Vista/Win7 driver : -----
 Vista/Win7 driver for x86
 RTKVHDA.sys : 6.0.1.6083
 AERTSrv.exe : 1.0.32.10
 RtHDVBg.exe : 1.0.0.13
 RtHDVCpl.exe : 1.0.0.504
 RtkAudioService.exe : 1.0.0.24
 RtkNGUI.exe : 1.0.0.38
 RtlUpd.exe : 2.8.0.1
 SkyTel.exe : 2.0.2.2
 vncutil.exe : 1.0.0.38
 mbfilt32.sys : 6.10.0.8
 RTSndMgr.cpl : 1.0.0.18
 AERTACap.dll : 2.0.32.11
 AERTARen.dll : 1.0.32.9
 BlackSkinImages.dll : 1.0.0.38
 DarkSkinImages.dll : 1.0.0.38
 DTSBassEnhancementDLL.dll : 1.0.0.1
 DTSSBoostDLL.dll : 1.0.0.1
 DTSGainCompensatorDLL.dll : 1.0.0.1
 DTSGFXAPO.dll : 1.0.0.1
 DTSGFXAPONS.dll : 1.0.0.1
 DTSLFXAPO.dll : 1.0.0.1
 DTSLimiterDLL.dll : 1.0.0.1
 DTSSNeoPCDLL.dll : 1.0.0.1
 DTSS2HeadphoneDLL.dll : 1.0.0.1
 DTSS2SpeakerDLL.dll : 1.0.0.1
 DTSSymmetryDLL.dll : 1.0.0.1
 DTSSVoiceClarityDLL.dll : 1.0.0.1
 FMAP0.dll : 42.5.30.65
 LightSkinImages.dll : 1.0.0.38
 MaxxAudioAPO.dll : 1.2.2.0
 MaxxAudioAPO20.dll : 2.2.6.0
 MaxxAudioEQ.dll : 5.9.7.0
 MBAP032.dll : 1.0.19.0
 MBPPCn32.dll : 1.0.0.110
 MBpld32.dll : 1.0.22.0
 MBTHX32.dll : 1.0.15.108

	Readme.txt	: 1. 0. 0. 110
MBWrp32.dll		: 6. 0. 6001. 18
RP3DAA32.dll		: 6. 0. 6001. 18
RP3DHT32.dll		: 2. 0. 0. 130
RTCOMDLL.dll		: 6. 1. 6001. 33
RTEED32A.dll		: 6. 1. 6001. 33
RTEEG32A.dll		: 6. 1. 6001. 33
RTEEL32A.dll		: 6. 1. 6001. 33
RTEEP32A.dll		: 6. 1. 6001. 33
RtkAPO.dll		: 11. 0. 6000. 145
RtkApoApi.dll		: 1. 0. 0. 21
RtkCfg.dll		: 1. 0. 0. 2
RtkCoInst.dll		: 1. 0. 8. 6
RtkPgExt.dll		: 6. 0. 6000. 120
RtlCPAPI.dll		: 1. 0. 2. 4
SFFXComm.dll		: 2. 0. 0. 12
SFFXDAP0.dll		: 2. 0. 0. 12
SFFXHAP0.dll		: 2. 0. 0. 12
SFFXProc.dll		: 2. 0. 0. 12
SFFXSAP0.dll		: 2. 0. 0. 12
slcshp32.dll		: 1. 0. 3. 0
slgeq32.dll		: 1. 0. 1. 0
slh36032.dll		: 1. 0. 2. 0
slInit32.dll		: 1. 1. 3. 0
slmaxv32.dll		: 1. 1. 2. 0
sltshd32.dll		: 1. 1. 1. 0
sluapo32.dll		: 1. 8. 24. 0
SRSHP360.dll		: 1. 1. 0. 0
SRSTSHD.dll		: 1. 1. 4. 0
SRSTSXT.dll		: 3. 2. 0. 0
Vista/Win7 driver for x64		
RTKVHD64.sys		: 6. 0. 1. 6083
AERTSr64.exe		: 1. 0. 64. 10
RAVBg64.exe		: 1. 0. 0. 13
RAVCpl64.exe		: 1. 0. 0. 504
RtkAudioService64.exe		: 1. 0. 0. 24
RtkNGUI64.exe		: 1. 0. 0. 38
RtlUpd64.exe		: 2. 8. 0. 1
SkyTel.exe		: 2. 0. 2. 2
vncutil64.exe		: 1. 0. 0. 38
GWfilt64.sys		: 6. 10. 0. 3
mbfilt64.sys		: 6. 10. 0. 8
RTSnMg64.cpl		: 1. 0. 0. 18
AERTAC64.dll		: 2. 0. 64. 11
AERTAR64.dll		: 1. 0. 64. 9
BlackSkinImages64.dll		: 1. 0. 0. 38
DarkSkinImages64.dll		: 1. 0. 0. 38
DTSBassEnhancementDLL64.dll		: 1. 0. 0. 1
DTSBoostDLL64.dll		: 1. 0. 0. 1
DTSGainCompensatorDLL64.dll		: 1. 0. 0. 1
DTSAFXAP064.dll		: 1. 0. 0. 1
DTSAFXAPONS64.dll		: 1. 0. 0. 1
DTSAFXAP064.dll		: 1. 0. 0. 1
DTSLimitDLL64.dll		: 1. 0. 0. 1
DTSNeoPCDLL64.dll		: 1. 0. 0. 1
DTSS2HeadphoneDLL64.dll		: 1. 0. 0. 1
DTSS2SpeakerDLL64.dll		: 1. 0. 0. 1
DTSSymmetryDLL64.dll		: 1. 0. 0. 1
DTSVoiceClarityDLL64.dll		: 1. 0. 0. 1
FMAP064.dll		: 42. 6. 30. 65
LightSkinImages64.dll		: 1. 0. 0. 38
MaxxAudioAP020.dll		: 2. 2. 7. 0
MaxxAudioEQ.dll		: 5. 9. 7. 0
MBAP032.dll		: 1. 0. 19. 0
MBAP064.dll		: 1. 0. 19. 0
MBPPCn64.dll		: 1. 0. 0. 110
MBpld64.dll		: 1. 0. 22. 0
MBTHX32.dll		: 1. 0. 15. 108
MBTHX64.dll		: 1. 0. 15. 108
MBWrp64.dll		: 1. 0. 0. 110

Readme.txt

RCoInst64.dll	: 1.0.8.6
RP3DAA64.dll	: 6.0.6001.18
RP3DHT64.dll	: 6.0.6001.18
RtCOMB4.dll	: 2.0.0.130
RTCOMDLL.dll	: 2.0.0.130
RTEED64A.dll	: 6.1.6001.33
RTEEG64A.dll	: 6.1.6001.33
RTEEL64A.dll	: 6.1.6001.33
RTEEP64A.dll	: 6.1.6001.33
RtkApi64.dll	: 1.0.0.21
RtkAPO64.dll	: 11.0.6000.145
RtkCfg.dll	: 1.0.0.1
RtkCfg64.dll	: 1.0.0.2
RtLCPAPI.dll	: 1.0.2.4
RtLCPAPI64.dll	: 1.0.2.4
RtPgEx64.dll	: 6.0.6000.120
SFComm64.dll	: 2.0.0.12
SFDAP064.dll	: 2.0.0.12
SFHAP064.dll	: 2.0.0.12
SFProc64.dll	: 2.0.0.12
SFSAP064.dll	: 2.0.0.12
slcshp64.dll	: 1.0.3.0
slgeq64.dll	: 1.0.1.0
slh36064.dll	: 1.0.2.0
slInit64.dll	: 1.1.3.0
slmaxv64.dll	: 1.1.2.0
sltshd64.dll	: 1.1.1.0
sluapo64.dll	: 1.8.24.0
SRSHP64.dll	: 1.1.0.0
SRSTSH64.dll	: 1.1.4.0
SRSTX64.dll	: 3.2.0.0
SRSWOW64.dll	: 1.1.3.0
WavesGUILib.dll	: 1.2.3.4

HDM Driver :	
Vista/Win7 x86:	
RtHDMV.sys	: 6.0.1.6034
RtkAudioSrvATI.exe	: 1.0.0.23
RtkUpd.exe	: 2.8.0.1
RH3DAA32.dll	: 6.0.6001.18
RH3DHT32.dll	: 6.0.6001.18
RHCoInst.dll	: 1.0.8.2
RHDMExt.dll	: 6.0.6000.113
RTEED32H.dll	: 6.1.6001.33
RTEEG32H.dll	: 6.1.6001.33
RTEEL32H.dll	: 6.1.6001.33
RTEEP32H.dll	: 6.1.6001.33
RtkHDM.dll	: 11.0.6000.132
Vista/Win7 x64:	
RtHDMVX.sys	: 6.0.1.6034
RtkAudioSrvATI64.exe	: 1.0.0.23
RtkUpd64.exe	: 2.8.0.1
RH3DAA64.dll	: 6.0.6001.18
RH3DHT64.dll	: 6.0.6001.18
RHCoInst64.dll	: 1.0.8.2
RHDMEx64.dll	: 6.0.6000.113
RTEED64H.dll	: 6.1.6001.33
RTEEG64H.dll	: 6.1.6001.33
RTEEL64H.dll	: 6.1.6001.33
RTEEP64H.dll	: 6.1.6001.33
RtkHDM64.dll	: 11.0.6000.132
XP/2K x86:	
RtkHDM.sys	: 5.10.0.6034
Rtaupd.exe	: 2.8.0.1
RHCoInstXP.dll	: 1.0.8.2
XP/2K x64:	
RtkHDMX.sys	: 5.10.0.6034

Readme.txt

Rtaupd64.exe : 2.8.0.1
RHCoInst64XP.dll : 1.0.8.2

Driver Setup Program : 2.97

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.46

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC892, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC892, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680

3. HDMI Device WHQL Support: ATI HDM Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 - x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

2. Fix BSOD issue under Windows 2000. (Issue happened from driver V6066).

Windows 2000/XP : -----

Windows 2000/XP :

RTKHDA64.sys : 5.10.0.6077
RTKHDAUD.sys : 5.10.0.6077
Alcmtr.exe : 1.6.0.4
AlcWzrd.exe : 1.1.0.37
McCal.exe : 1.1.2.3
RTHDCPL.exe : 2.3.4.6
RtkAudioService.exe : 1.0.0.19
RtkAudioService64.exe : 1.0.0.19
RTLCPPL.exe : 1.0.1.66
RtlUpd.exe : 2.8.0.1
RtlUpd64.exe : 2.8.0.1
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.32
vncutil.exe : 1.0.0.38
vncutil64.exe : 1.0.0.38
AMBfilt.sys : 5.10.0.4240
AMBft64.sys : 5.10.0.4240
Mnftlt.sys : 5.10.0.4112
Mnft64.sys : 5.10.0.4115
OA017Afx.sys : 1.0.7.3
ALSndMgr.cpl : 1.0.0.11
RTSndMgr.cpl : 1.0.1.4
RCoInst64XP.dll : 1.0.8.6
RTCOMDLL.dll : 1.0.0.107
RtkCoInstXP.dll : 1.0.8.6
RtlCPAPI.dll : 1.0.2.3

Vista/Win7 driver : -----

Vista/Win7 driver for x86

RTKVHDA.sys : 6.0.1.6077
AERTSrv.exe : 1.0.32.10
RtHDVBg.exe : 1.0.0.9
RtHDVCpl.exe : 1.0.0.501
RtkAudioService.exe : 1.0.0.24
RtkNGUI.exe : 1.0.0.35
RtlUpd.exe : 2.8.0.1
SkyTel.exe : 2.0.2.2
vncutil.exe : 1.0.0.38
mbfilt32.sys : 6.10.0.8
RTSndMgr.cpl : 1.0.0.18

	Readme.txt	
AERTACap.dll		: 2.0.32.11
AERTARen.dll		: 1.0.32.9
BlackSkinImages.dll		: 1.0.0.35
DarkSkinImages.dll		: 1.0.0.35
DTSBassEnhancementDLL.dll		: 1.0.0.1
DTSBoostDLL.dll		: 1.0.0.1
DTSGainCompensatorDLL.dll		: 1.0.0.1
DTS GFXAPO.dll		: 1.0.0.1
DTS GFXAPONS.dll		: 1.0.0.1
DTS LFXAPO.dll		: 1.0.0.1
DTS LimiterDLL.dll		: 1.0.0.1
DTS NeoPCDLL.dll		: 1.0.0.1
DTS S2HeadphoneDLL.dll		: 1.0.0.1
DTS S2SpeakerDLL.dll		: 1.0.0.1
DTS SymmetryDLL.dll		: 1.0.0.1
DTS VoiceClarityDLL.dll		: 1.0.0.1
FMAP0.dll		: 42.5.29.67
LightSkinImages.dll		: 1.0.0.35
MaxxAudioAPO.dll		: 1.2.2.0
MaxxAudioAPO20.dll		: 2.2.6.0
MaxxAudioEQ.dll		: 5.9.7.0
MBAP032.dll		: 1.0.19.0
MBPPCn32.dll		: 1.0.0.110
MBpld32.dll		: 1.0.22.0
MBTHX32.dll		: 1.0.15.108
MBWrp32.dll		: 1.0.0.110
RP3DAA32.dll		: 6.0.6001.18
RP3DHT32.dll		: 6.0.6001.18
RTCOMDLL.dll		: 2.0.0.130
RTEED32A.dll		: 6.1.6001.33
RTEEG32A.dll		: 6.1.6001.33
RTEEL32A.dll		: 6.1.6001.33
RTEEP32A.dll		: 6.1.6001.33
RtkAPO.dll		: 11.0.6000.144
RtkApoApi.dll		: 1.0.0.20
RtkCfg.dll		: 1.0.0.2
RtkColInst.dll		: 1.0.8.6
RtkPgExt.dll		: 6.0.6000.119
RtlCPAPI.dll		: 1.0.2.4
SFFXComm.dll		: 2.0.0.12
SFFXDAP0.dll		: 2.0.0.12
SFFXHAP0.dll		: 2.0.0.12
SFFXProc.dll		: 2.0.0.12
SFFXSAP0.dll		: 2.0.0.12
slcshp32.dll		: 1.0.3.0
slgeq32.dll		: 1.0.1.0
slh36032.dll		: 1.0.2.0
slInit32.dll		: 1.1.3.0
slmaxv32.dll		: 1.1.2.0
sltshd32.dll		: 1.1.1.0
sluapo32.dll		: 1.8.24.0
SRSHP360.dll		: 1.1.0.0
SRSTSHD.dll		: 1.1.4.0
SRSTSXT.dll		: 3.2.0.0
SRSWOW.dll		: 1.1.3.0
WavesLib.dll		: 5.9.7.0
Vista/Win7 driver for x64		
RTKVHD64.sys		: 6.0.1.6077
AERTSr64.exe		: 1.0.64.10
RAVBg64.exe		: 1.0.0.9
RAVCpl64.exe		: 1.0.0.501
RtkAudioService64.exe		: 1.0.0.24
RtkNGUI64.exe		: 1.0.0.35
RtlUpd64.exe		: 2.8.0.1
SkyTel.exe		: 2.0.2.2
vncutil64.exe		: 1.0.0.38
GWfilt64.sys		: 6.10.0.3
mbfilt64.sys		: 6.10.0.8
RTSnMg64.cpl		: 1.0.0.18

Readme.txt

AERTAC64.dll	: 2.0.64.11
AERTAR64.dll	: 1.0.64.9
BlackSkinImages64.dll	: 1.0.0.35
DarkSkinImages64.dll	: 1.0.0.35
DTSBassEnhancementDLL64.dll	: 1.0.0.1
DTSBoostDLL64.dll	: 1.0.0.1
DTSGainCompensatorDLL64.dll	: 1.0.0.1
DTS GFXAP064.dll	: 1.0.0.1
DTS GFXAPONS64.dll	: 1.0.0.1
DTS LFXAP064.dll	: 1.0.0.1
DTS LimiterDLL64.dll	: 1.0.0.1
DTS NeoPCDLL64.dll	: 1.0.0.1
DTSS2HeadphoneDLL64.dll	: 1.0.0.1
DTSS2SpeakerDLL64.dll	: 1.0.0.1
DTSSymmetryDLL64.dll	: 1.0.0.1
DTSVoiceClarityDLL64.dll	: 1.0.0.1
FMAP064.dll	: 42.6.29.67
LightSkinImages64.dll	: 1.0.0.35
MaxxAudioAP020.dll	: 2.2.7.0
MaxxAudioEQ.dll	: 5.9.7.0
MBAP032.dll	: 1.0.19.0
MBAP064.dll	: 1.0.19.0
MBPPCn64.dll	: 1.0.0.110
MBpld64.dll	: 1.0.22.0
MBTHX32.dll	: 1.0.15.108
MBTHX64.dll	: 1.0.15.108
MBWrp64.dll	: 1.0.0.110
RCoInst64.dll	: 1.0.8.6
RP3DAA64.dll	: 6.0.6001.18
RP3DHT64.dll	: 6.0.6001.18
RtCOM64.dll	: 2.0.0.130
RTCOMDLL.dll	: 2.0.0.130
RTEED64A.dll	: 6.1.6001.33
RTEEG64A.dll	: 6.1.6001.33
RTEEL64A.dll	: 6.1.6001.33
RTEEP64A.dll	: 6.1.6001.33
RtkApi64.dll	: 1.0.0.20
RtkAPO64.dll	: 11.0.6000.144
RtkCfg.dll	: 1.0.0.1
RtkCfg64.dll	: 1.0.0.2
RtLCPAPI.dll	: 1.0.2.4
RtLCPAPI64.dll	: 1.0.2.4
RtPgEx64.dll	: 6.0.6000.119
SFComm64.dll	: 2.0.0.12
SFDAP064.dll	: 2.0.0.12
SFHAP064.dll	: 2.0.0.12
SFProc64.dll	: 2.0.0.12
SFSAP064.dll	: 2.0.0.12
slcshp64.dll	: 1.0.3.0
slgeq64.dll	: 1.0.1.0
slh36064.dll	: 1.0.2.0
slInit64.dll	: 1.1.3.0
slmaxv64.dll	: 1.1.2.0
sltshd64.dll	: 1.1.1.0
sluapo64.dll	: 1.8.24.0
SRSHP64.dll	: 1.1.0.0
SRSTSH64.dll	: 1.1.4.0
SRSTX64.dll	: 3.2.0.0
SRSWOW64.dll	: 1.1.3.0
WavesGUILib.dll	: 1.2.3.4
HDMI Driver : -----	
Vista/Win7 x86:	
RtHDMV.sys	: 6.0.1.6034
RtkAudioSrvATI.exe	: 1.0.0.23
RtkUpd.exe	: 2.8.0.1
RH3DAA32.dll	: 6.0.6001.18
RH3DHT32.dll	: 6.0.6001.18
RHCoInst.dll	: 1.0.8.2
RHDMExt.dll	: 6.0.6000.113

Readme.txt

RTEED32H.dll : 6.1.6001.33
RTEEG32H.dll : 6.1.6001.33
RTEEL32H.dll : 6.1.6001.33
RTEEP32H.dll : 6.1.6001.33
RtkHDM.dll : 11.0.6000.132

Vista/Win7 x64:

RtHDMVX.sys : 6.0.1.6034
RtkAudioSrvATI64.exe : 1.0.0.23
RtkUpd64.exe : 2.8.0.1
RH3DAA64.dll : 6.0.6001.18
RH3DHT64.dll : 6.0.6001.18
RHCoInst64.dll : 1.0.8.2
RHDME64.dll : 6.0.6000.113
RTEED64H.dll : 6.1.6001.33
RTEEG64H.dll : 6.1.6001.33
RTEEL64H.dll : 6.1.6001.33
RTEEP64H.dll : 6.1.6001.33
RtkHDM64.dll : 11.0.6000.132

XP/2K x86:

RtkHDM.sys : 5.10.0.6034
Rtaupd.exe : 2.8.0.1
RHCoInstXP.dll : 1.0.8.2

XP/2K x64:

RtkHDMX.sys : 5.10.0.6034
Rtaupd64.exe : 2.8.0.1
RHCoInst64XP.dll : 1.0.8.2

Driver Setup Program : 2.97

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.45

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC892, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC892, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680

3. HDM Device WHQL Support: ATI HDM Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 - x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :

RTKHDA64.sys : 5.10.0.6069
RTKHDAUD.sys : 5.10.0.6069
McCal.exe : 1.1.2.3
RTHDCPL.exe : 2.3.4.2
RtkAudioService64.exe : 1.0.0.19
RtkAudioService.exe : 1.0.0.19
RTLCPPL.exe : 1.0.1.66
RtlUpd64.exe : 2.8.0.1
RtlUpd.exe : 2.8.0.1
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.32
vncutil64.exe : 1.0.0.38
vncutil.exe : 1.0.0.38

Readme.txt

```

Alcmtr.exe : 1.6.0.4
AlcWzrd.exe : 1.1.0.37
Mnfiltr.sys : 5.10.0.4112
Mnft64.sys : 5.10.0.4115
OA017Afx.sys : 1.0.7.3
AMBfiltr.sys : 5.10.0.4240
AMBft64.sys : 5.10.0.4240
RTSndMgr.cpl : 1.0.1.4
ALSndMgr.cpl : 1.0.0.11
RCoInst64XP.dll : 1.0.8.6
RTCOMDLL.dll : 1.0.0.107
RtkCoInstXP.dll : 1.0.8.6
RtlCPAPI.dll : 1.0.2.3
Vista/Win7 driver : -----
Vista/Win7 driver for x86
RTKVHDA.sys : 6.0.1.6069
AERTSrv.exe : 1.0.32.10
RtHDVBg.exe : 1.0.0.9
RtHDVCpl.exe : 1.0.0.500
RtkAudioService.exe : 1.0.0.24
RtkNGUI.exe : 1.0.0.31
RtlUpd.exe : 2.8.0.1
SkyTel.exe : 2.0.2.2
vncutil.exe : 1.0.0.38
mbfiltr32.sys : 6.10.0.8
RTSndMgr.cpl : 1.0.0.18
AERTACap.dll : 2.0.32.11
AERTARen.dll : 1.0.32.9
BlackSkinImages.dll : 1.0.0.31
DarkSkinImages.dll : 1.0.0.31
DTSBassEnhancementDLL.dll : 1.0.0.1
DTSBoostDLL.dll : 1.0.0.1
DTSGainCompensatorDLL.dll : 1.0.0.1
DTSAFXAPO.dll : 1.0.0.1
DTSAFXAPONS.dll : 1.0.0.1
DTSAFXAPO.dll : 1.0.0.1
DTSLimitDLL.dll : 1.0.0.1
DTSNeoPCDLL.dll : 1.0.0.1
DTSS2HeadphoneDLL.dll : 1.0.0.1
DTSS2SpeakerDLL.dll : 1.0.0.1
DTSymmetryDLL.dll : 1.0.0.1
DTSVoiceClarityDLL.dll : 1.0.0.1
FMAP0.dll : 42.5.29.67
LightSkinImages.dll : 1.0.0.31
MaxxAudioAPO.dll : 1.2.2.0
MaxxAudioAPO20.dll : 2.2.6.0
MaxxAudioEQ.dll : 5.9.7.0
MBAP032.dll : 1.0.19.0
MBPPCn32.dll : 1.0.0.110
MBpld32.dll : 1.0.22.0
MBTHX32.dll : 1.0.15.108
MBWrp32.dll : 1.0.0.110
RP3DAA32.dll : 6.0.6001.18
RP3DHT32.dll : 6.0.6001.18
RTCOMDLL.dll : 2.0.0.129
RTEED32A.dll : 6.1.6001.33
RTEEG32A.dll : 6.1.6001.33
RTEEL32A.dll : 6.1.6001.33
RTEEP32A.dll : 6.1.6001.33
RtkAPO.dll : 11.0.6000.144
RtkApoApi.dll : 1.0.0.20
RtkCfg.dll : 1.0.0.2
RtkCoInst.dll : 1.0.8.6
RtkPgExt.dll : 6.0.6000.119
RtlCPAPI.dll : 1.0.2.4
SFFXComm.dll : 2.0.0.12
SFFXDAP0.dll : 2.0.0.12
SFFXHAP0.dll : 2.0.0.12
SFFXProc.dll : 2.0.0.12

```

	Readme.txt	
SFFXSAP0.dll	:	2.0.0.12
slcshp32.dll	:	1.0.3.0
slgeq32.dll	:	1.0.1.0
slh36032.dll	:	1.0.2.0
slInit32.dll	:	1.1.3.0
slmaxv32.dll	:	1.1.2.0
sltshd32.dll	:	1.1.1.0
sluapo32.dll	:	1.8.24.0
SRSH360.dll	:	1.1.0.0
SRSTSHD.dll	:	1.1.4.0
SRSTSXT.dll	:	3.2.0.0
SRSWOW.dll	:	1.1.3.0
WavesLib.dll	:	5.9.7.0
Vista/Win7 driver for x64		
RTKVHD64.sys	:	6.0.1.6069
AERTSr64.exe	:	1.0.64.10
RAVBg64.exe	:	1.0.0.9
RAVCpl64.exe	:	1.0.0.500
RtkAudioService64.exe	:	1.0.0.24
RtkNGUI64.exe	:	1.0.0.31
RtlUpd64.exe	:	2.8.0.1
SkyTel.exe	:	2.0.2.2
vncutil64.exe	:	1.0.0.38
GWfilt64.sys	:	6.10.0.3
mbfilt64.sys	:	6.10.0.8
RTSnMg64.cpl	:	1.0.0.18
AERTAC64.dll	:	2.0.64.11
AERTAR64.dll	:	1.0.64.9
BlackSkinImages64.dll	:	1.0.0.31
DarkSkinImages64.dll	:	1.0.0.31
DTSBassEnhancementDLL64.dll	:	1.0.0.1
DTSBoostDLL64.dll	:	1.0.0.1
DTSGainCompensatorDLL64.dll	:	1.0.0.1
DTSAFXAP064.dll	:	1.0.0.1
DTSAFXAPONS64.dll	:	1.0.0.1
DTSLFXAP064.dll	:	1.0.0.1
DTSLimitDLL64.dll	:	1.0.0.1
DTSNeoPCDLL64.dll	:	1.0.0.1
DTSS2HeadphoneDLL64.dll	:	1.0.0.1
DTSS2SpeakerDLL64.dll	:	1.0.0.1
DTSSymmetryDLL64.dll	:	1.0.0.1
DTSVoiceClarityDLL64.dll	:	1.0.0.1
FMAP064.dll	:	42.6.29.67
LightSkinImages64.dll	:	1.0.0.31
MaxxAudioAP020.dll	:	2.2.7.0
MaxxAudioEQ.dll	:	5.9.7.0
MBAP032.dll	:	1.0.19.0
MBAP064.dll	:	1.0.19.0
MBPPCn64.dll	:	1.0.0.110
MBpld64.dll	:	1.0.22.0
MBTHX32.dll	:	1.0.15.108
MBTHX64.dll	:	1.0.15.108
MBWrp64.dll	:	1.0.0.110
RCoInst64.dll	:	1.0.8.6
RP3DAA64.dll	:	6.0.6001.18
RP3DHT64.dll	:	6.0.6001.18
RtCOM64.dll	:	2.0.0.129
RTCOMDLL.dll	:	2.0.0.129
RTEED64A.dll	:	6.1.6001.33
RTEEG64A.dll	:	6.1.6001.33
RTEEL64A.dll	:	6.1.6001.33
RTEEP64A.dll	:	6.1.6001.33
RtkApi64.dll	:	1.0.0.20
RtkAP064.dll	:	11.0.6000.144
RtkCfg.dll	:	1.0.0.1
RtkCfg64.dll	:	1.0.0.2
RtlCPAPI.dll	:	1.0.2.4
RtlCPAPI64.dll	:	1.0.2.4
RtPgEx64.dll	:	6.0.6000.119

```

Readme.txt
SFComm64.dll : 2.0.0.12
SFDAP064.dll : 2.0.0.12
SFHAP064.dll : 2.0.0.12
SFProc64.dll : 2.0.0.12
SFSAP064.dll : 2.0.0.12
slcshp64.dll : 1.0.3.0
slgeq64.dll : 1.0.1.0
slh36064.dll : 1.0.2.0
slInit64.dll : 1.1.3.0
slmaxv64.dll : 1.1.2.0
sltshd64.dll : 1.1.1.0
sluapo64.dll : 1.8.24.0
SRSHP64.dll : 1.1.0.0
SRSTSH64.dll : 1.1.4.0
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
WavesGUILib.dll : 1.2.3.4
HDM Driver : -----
Vista/Win7 x86:
RtHDMV.sys : 6.0.1.6034
RtkAudioSrvATI.exe : 1.0.0.23
RtkUpd.exe : 2.8.0.1
RH3DAA32.dll : 6.0.6001.18
RH3DHT32.dll : 6.0.6001.18
RHCoInst.dll : 1.0.8.2
RHDMEExt.dll : 6.0.6000.113
RTEED32H.dll : 6.1.6001.33
RTEEG32H.dll : 6.1.6001.33
RTEEL32H.dll : 6.1.6001.33
RTEEP32H.dll : 6.1.6001.33
RtkHDM.dll : 11.0.6000.132

Vista/Win7 x64:
RtHDMVX.sys : 6.0.1.6034
RtkAudioSrvATI64.exe : 1.0.0.23
RtkUpd64.exe : 2.8.0.1
RH3DAA64.dll : 6.0.6001.18
RH3DHT64.dll : 6.0.6001.18
RHCoInst64.dll : 1.0.8.2
RHDME64.dll : 6.0.6000.113
RTEED64H.dll : 6.1.6001.33
RTEEG64H.dll : 6.1.6001.33
RTEEL64H.dll : 6.1.6001.33
RTEEP64H.dll : 6.1.6001.33
RtkHDM64.dll : 11.0.6000.132

XP/2K x86:
RtkHDM.sys : 5.10.0.6034
Rtaupd.exe : 2.8.0.1
RHCoInstXP.dll : 1.0.8.2

XP/2K x64:
RtkHDMX.sys : 5.10.0.6034
Rtaupd64.exe : 2.8.0.1
RHCoInst64XP.dll : 1.0.8.2

Driver Setup Program : 2.96

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

```

//=====

Driver Package R2.44

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC892, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680

Readme.txt

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC892, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 - x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :

RTKHDA64.sys : 5.10.0.6066
RTKHDAUD.sys : 5.10.0.6066
McCal.exe : 1.1.2.3
RTHDCPL.exe : 2.3.4.0
RtkAudioService64.exe : 1.0.0.19
RtkAudioService.exe : 1.0.0.19
RTLCPPL.exe : 1.0.1.66
RtlUpd64.exe : 2.8.0.1
RtlUpd.exe : 2.8.0.1
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.32
vncutil64.exe : 1.0.0.38
vncutil.exe : 1.0.0.38
Alcmtr.exe : 1.6.0.4
AlcWzrd.exe : 1.1.0.37
AMBft64.sys : 5.10.0.4240
Mnflt.sys : 5.10.0.4112
Mnft64.sys : 5.10.0.4115
OA017Afx.sys : 1.0.7.3
AMBflt.sys : 5.10.0.4240
RTSndMgr.cpl : 1.0.1.4
ALSndMgr.cpl : 1.0.0.11
RCoInst64XP.dll : 1.0.8.6
RTCOMDLL.dll : 1.0.0.107
RtkCoInstXP.dll : 1.0.8.6
RtlCPAPI.dll : 1.0.2.3

Vista/Win7 driver : -----

Vista/Win7 driver for x86

RTKVHDA.sys : 6.0.1.6066
AERTSrv.exe : 1.0.32.10
RtHDVbg.exe : 1.0.0.9
RtHDVCpl.exe : 1.0.0.499
RtkAudioService.exe : 1.0.0.24
RtkNGUI.exe : 1.0.0.29
RtlUpd.exe : 2.8.0.1
SkyTel.exe : 2.0.2.2
vncutil.exe : 1.0.0.38
mbflt32.sys : 6.10.0.8
RTSndMgr.cpl : 1.0.0.18
AERTACap.dll : 2.0.32.11
AERTARen.dll : 1.0.32.9
BlackSkinImages.dll : 1.0.0.29
DarkSkinImages.dll : 1.0.0.29
DTSBassEnhancementDLL.dll : 1.0.0.1
DTSBoostDLL.dll : 1.0.0.1
DTSGainCompensatorDLL.dll : 1.0.0.1
DTSGFXAPO.dll : 1.0.0.1
DTSGFXAPONS.dll : 1.0.0.1
DTSLFXAPO.dll : 1.0.0.1
DTS LimiterDLL.dll : 1.0.0.1
DTSNeoPCDLL.dll : 1.0.0.1
DTSS2HeadphoneDLL.dll : 1.0.0.1
DTSS2SpeakerDLL.dll : 1.0.0.1
DTSSymmetryDLL.dll : 1.0.0.1
DTSVoiceClarityDLL.dll : 1.0.0.1
FMAP0.dll : 42.5.28.65

LightSkinImages.dll	: 1.0.0.29
MaxxAudioAPO.dll	: 1.2.2.0
MaxxAudioAPO20.dll	: 2.2.6.0
MaxxAudioEQ.dll	: 5.9.7.0
MBAP032.dll	: 1.0.19.0
MBPPCn32.dll	: 1.0.0.110
Mbpld32.dll	: 1.0.22.0
MBTHX32.dll	: 1.0.15.108
MBWrp32.dll	: 1.0.0.110
RP3DAA32.dll	: 6.0.6001.18
RP3DHT32.dll	: 6.0.6001.18
RTCOMDLL.dll	: 2.0.0.128
RTEED32A.dll	: 6.1.6001.33
RTEEG32A.dll	: 6.1.6001.33
RTEEL32A.dll	: 6.1.6001.33
RTEEP32A.dll	: 6.1.6001.33
RtkAPO.dll	: 11.0.6000.142
RtkApoApi.dll	: 1.0.0.20
RtkCfg.dll	: 1.0.0.2
RtkCoInst.dll	: 1.0.8.6
RtkPgExt.dll	: 6.0.6000.119
RtlCPAPI.dll	: 1.0.2.4
SFFXComm.dll	: 2.0.0.12
SFFXDAP0.dll	: 2.0.0.12
SFFXHAP0.dll	: 2.0.0.12
SFFXProc.dll	: 2.0.0.12
SFFXSAP0.dll	: 2.0.0.12
slcshp32.dll	: 1.0.3.0
slgeq32.dll	: 1.0.1.0
slh36032.dll	: 1.0.2.0
slInit32.dll	: 1.1.3.0
slmaxv32.dll	: 1.1.2.0
sltshd32.dll	: 1.1.1.0
sluapo32.dll	: 1.8.24.0
SRSHP360.dll	: 1.1.0.0
SRSTSHD.dll	: 1.1.4.0
SRSTSXT.dll	: 3.2.0.0
SRSWOW.dll	: 1.1.3.0
WavesLib.dll	: 5.9.7.0
Vista/Win7 driver for x64	
RTKVHD64.sys	: 6.0.1.6066
AERTSr64.exe	: 1.0.64.10
RAVBg64.exe	: 1.0.0.9
RAVCpl64.exe	: 1.0.0.499
RtkAudioService64.exe	: 1.0.0.24
RtkNGUI64.exe	: 1.0.0.29
RtlUpd64.exe	: 2.8.0.1
SkyTel.exe	: 2.0.2.2
vncutil64.exe	: 1.0.0.38
GWfilt64.sys	: 6.10.0.3
mbfilt64.sys	: 6.10.0.8
RTSnMg64.cpl	: 1.0.0.18
AERTAC64.dll	: 2.0.64.11
AERTAR64.dll	: 1.0.64.9
BlackSkinImages64.dll	: 1.0.0.29
DarkSkinImages64.dll	: 1.0.0.29
DTSBassEnhancementDLL64.dll	: 1.0.0.1
DTSBoostDLL64.dll	: 1.0.0.1
DTSGainCompensatorDLL64.dll	: 1.0.0.1
DTSAFXAP064.dll	: 1.0.0.1
DTSAFXAPONS64.dll	: 1.0.0.1
DTSLFXAP064.dll	: 1.0.0.1
DTSLimitDLL64.dll	: 1.0.0.1
DTSNeoPCDLL64.dll	: 1.0.0.1
DTSS2HeadphoneDLL64.dll	: 1.0.0.1
DTSS2SpeakerDLL64.dll	: 1.0.0.1
DTSSymmetryDLL64.dll	: 1.0.0.1
DTSVoiceClarityDLL64.dll	: 1.0.0.1
FMAP064.dll	: 42.6.28.65

Readme.txt

LightSkinImages64.dll	: 1.0.0.29
MaxxAudioAP020.dll	: 2.2.7.0
MaxxAudioEQ.dll	: 5.9.7.0
MBAP032.dll	: 1.0.19.0
MBAP064.dll	: 1.0.19.0
MBPPCn64.dll	: 1.0.0.110
Mbpld64.dll	: 1.0.22.0
MBTHX32.dll	: 1.0.15.108
MBTHX64.dll	: 1.0.15.108
MBWrp64.dll	: 1.0.0.110
RCoInst64.dll	: 1.0.8.6
RP3DAA64.dll	: 6.0.6001.18
RP3DHT64.dll	: 6.0.6001.18
RtCOMB4.dll	: 2.0.0.128
RTCOMDLL.dll	: 2.0.0.128
RTEED64A.dll	: 6.1.6001.33
RTEEG64A.dll	: 6.1.6001.33
RTEEL64A.dll	: 6.1.6001.33
RTEEP64A.dll	: 6.1.6001.33
RtkApi64.dll	: 1.0.0.20
RtkAP064.dll	: 11.0.6000.142
RtkCfg.dll	: 1.0.0.1
RtkCfg64.dll	: 1.0.0.2
RtLCPAPI.dll	: 1.0.2.4
RtLCPAPI64.dll	: 1.0.2.4
RtPgEx64.dll	: 6.0.6000.119
SFComm64.dll	: 2.0.0.12
SFDAP064.dll	: 2.0.0.12
SFHAP064.dll	: 2.0.0.12
SFProc64.dll	: 2.0.0.12
SFSAP064.dll	: 2.0.0.12
slcshp64.dll	: 1.0.3.0
slgeq64.dll	: 1.0.1.0
slh36064.dll	: 1.0.2.0
slInit64.dll	: 1.1.3.0
slmaxv64.dll	: 1.1.2.0
sltshd64.dll	: 1.1.1.0
sluapo64.dll	: 1.8.24.0
SRSHP64.dll	: 1.1.0.0
SRSTSH64.dll	: 1.1.4.0
SRSTX64.dll	: 3.2.0.0
SRSWOW64.dll	: 1.1.3.0
WavesGUILib.dll	: 1.2.3.4
HDMI Driver : -----	
Vista/Win7 x86:	
RtHDMV.sys	: 6.0.1.6034
RtkAudioSrvATI.exe	: 1.0.0.23
RtkUpd.exe	: 2.8.0.1
RH3DAA32.dll	: 6.0.6001.18
RH3DHT32.dll	: 6.0.6001.18
RHCoInst.dll	: 1.0.8.2
RHDMExt.dll	: 6.0.6000.113
RTEED32H.dll	: 6.1.6001.33
RTEEG32H.dll	: 6.1.6001.33
RTEEL32H.dll	: 6.1.6001.33
RTEEP32H.dll	: 6.1.6001.33
RtkHDM.dll	: 11.0.6000.132
Vista/Win7 x64:	
RtHDMVX.sys	: 6.0.1.6034
RtkAudioSrvATI64.exe	: 1.0.0.23
RtkUpd64.exe	: 2.8.0.1
RH3DAA64.dll	: 6.0.6001.18
RH3DHT64.dll	: 6.0.6001.18
RHCoInst64.dll	: 1.0.8.2
RHDMEx64.dll	: 6.0.6000.113
RTEED64H.dll	: 6.1.6001.33
RTEEG64H.dll	: 6.1.6001.33
RTEEL64H.dll	: 6.1.6001.33

Readme.txt

RTEEP64H.dll : 6.1.6001.33
RtkHDM64.dll : 11.0.6000.132

XP/2K x86:
RtkHDM.sys : 5.10.0.6034
Rtaupd.exe : 2.8.0.1
RHCoInstXP.dll : 1.0.8.2

XP/2K x64:
RtkHDMX.sys : 5.10.0.6034
Rtaupd64.exe : 2.8.0.1
RHCoInst64XP.dll : 1.0.8.2

Driver Setup Program : 2.96

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.43

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC892, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC892, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680

3. HDM Device WHQL Support: ATI HDM Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 - x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :

RTKHDA64.sys : 5.10.0.6050
RTKHDAUD.sys : 5.10.0.6050
McCal.exe : 1.1.2.3
RTHDCPL.exe : 2.3.3.8
RtkAudioService64.exe : 1.0.0.19
RtkAudioService.exe : 1.0.0.19
RTLCPPL.exe : 1.0.1.66
RtlUpd64.exe : 2.8.0.1
RtlUpd.exe : 2.8.0.1
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.32
vncutil64.exe : 1.0.0.38
vncutil.exe : 1.0.0.38
Alcmtr.exe : 1.6.0.4
AlcWzrd.exe : 1.1.0.37
Mnfilt.sys : 5.10.0.4112
Mnft64.sys : 5.10.0.4115
OA017Afx.sys : 1.0.7.3
AMBFilt.sys : 5.10.0.4240
AMBft64.sys : 5.10.0.4240
RTSndMgr.cpl : 1.0.1.4
ALSndMgr.cpl : 1.0.0.11
RCoInst64XP.dll : 1.0.8.4
RTCOMDLL.dll : 1.0.0.106
RtkCoInstXP.dll : 1.0.8.4
RtlCPAPI.dll : 1.0.2.3

Vista/Win7 driver : -----

Vista/Win7 driver for x86

RTKVHDA.sys : 6.0.1.6050
AERTSrv.exe : 1.0.32.10

	Readme.txt	
RtHDVBg.exe	:	1.0.0.8
RtHDVCpl.exe	:	1.0.0.489
RtkAudioService.exe	:	1.0.0.24
RtkNGUI.exe	:	0.0.0.25
RtlUpd.exe	:	2.8.0.1
SkyTel.exe	:	2.0.2.2
vncutil.exe	:	1.0.0.38
mbfilt32.sys	:	6.10.0.8
RTSndMgr.cpl	:	1.0.0.18
AERTACap.dll	:	2.0.32.11
AERTARen.dll	:	1.0.32.9
BlackSkinImages.dll	:	0.0.0.25
DarkSkinImages.dll	:	0.0.0.25
DTSBassEnhancementDLL.dll	:	1.0.0.1
DTSBoostDLL.dll	:	1.0.0.1
DTSGainCompensatorDLL.dll	:	1.0.0.1
DTSAFXAPO.dll	:	1.0.0.1
DTSAFXAPONS.dll	:	1.0.0.1
DTSLFXAPO.dll	:	1.0.0.1
DTSLimitDLL.dll	:	1.0.0.1
DTSNeoPCDLL.dll	:	1.0.0.1
DTSS2HeadphoneDLL.dll	:	1.0.0.1
DTSS2SpeakerDLL.dll	:	1.0.0.1
DTSSymmetryDLL.dll	:	1.0.0.1
DTSVoiceClarityDLL.dll	:	1.0.0.1
FMAPO.dll	:	42.5.26.65
LightSkinImages.dll	:	0.0.0.25
MaxxAudioAPO.dll	:	1.2.2.0
MaxxAudioAPO20.dll	:	2.2.6.0
MaxxAudioEQ.dll	:	5.9.7.0
MBAP032.dll	:	1.0.19.0
MBPPCn32.dll	:	1.0.0.110
MBpld32.dll	:	1.0.22.0
MBTHX32.dll	:	1.0.15.106
MBWrp32.dll	:	1.0.0.110
RP3DAA32.dll	:	6.0.6001.18
RP3DHT32.dll	:	6.0.6001.18
RTCOMDLL.dll	:	2.0.0.128
RTEED32A.dll	:	6.1.6001.33
RTEEG32A.dll	:	6.1.6001.33
RTEEL32A.dll	:	6.1.6001.33
RTEEP32A.dll	:	6.1.6001.33
RtkAPO.dll	:	11.0.6000.137
RtkApoApi.dll	:	1.0.0.20
RtkCfg.dll	:	1.0.0.2
RtkCoInst.dll	:	1.0.8.4
RtkPgExt.dll	:	6.0.6000.116
RtlCPAPI.dll	:	1.0.2.4
SFFXComm.dll	:	2.0.0.9
SFFXDAPO.dll	:	2.0.0.9
SFFXHAP0.dll	:	2.0.0.9
SFFXProc.dll	:	2.0.0.9
SFFXSAP0.dll	:	2.0.0.9
slcshp32.dll	:	1.0.3.0
slgeq32.dll	:	1.0.1.0
slh36032.dll	:	1.0.2.0
slInit32.dll	:	1.1.3.0
slmaxv32.dll	:	1.1.2.0
sltshd32.dll	:	1.1.1.0
sluapo32.dll	:	1.8.24.0
SRSHP360.dll	:	1.1.0.0
SRSTSHD.dll	:	1.1.4.0
SRSTSXT.dll	:	3.2.0.0
SRSWOW.dll	:	1.1.3.0
WavesLib.dll	:	5.9.7.0
Vista/Win7 driver for x64		
RTKVHD64.sys	:	6.0.1.6050
AERTSr64.exe	:	1.0.64.10
RAVBg64.exe	:	1.0.0.8

	Readme.txt	
RAVCpl64.exe	:	1.0.0.489
RtkAudioService64.exe	:	1.0.0.24
RtkNGUI64.exe	:	0.0.0.25
RtlUpd64.exe	:	2.8.0.1
SkyTel.exe	:	2.0.2.2
vncutil64.exe	:	1.0.0.38
GWfilt64.sys	:	6.10.0.3
mbfilt64.sys	:	6.10.0.8
RTSnMg64.cpl	:	1.0.0.18
AERTAC64.dll	:	2.0.64.11
AERTAR64.dll	:	1.0.64.9
BlackSkinImages64.dll	:	0.0.0.25
DarkSkinImages64.dll	:	0.0.0.25
DTSBassEnhancementDLL64.dll	:	1.0.0.1
DTSBoostDLL64.dll	:	1.0.0.1
DTSGainCompensatorDLL64.dll	:	1.0.0.1
DTSAFXAP064.dll	:	1.0.0.1
DTSAFXAPONS64.dll	:	1.0.0.1
DTSAFXAP064.dll	:	1.0.0.1
DTSLimitDLL64.dll	:	1.0.0.1
DTSNeoPCDLL64.dll	:	1.0.0.1
DTSS2HeadphoneDLL64.dll	:	1.0.0.1
DTSS2SpeakerDLL64.dll	:	1.0.0.1
DTSSymmetryDLL64.dll	:	1.0.0.1
DTSVoiceClarityDLL64.dll	:	1.0.0.1
FMAP064.dll	:	42.6.26.65
LightSkinImages64.dll	:	0.0.0.25
MaxxAudioAP020.dll	:	2.2.7.0
MaxxAudioEQ.dll	:	5.9.7.0
MBAP032.dll	:	1.0.19.0
MBAP064.dll	:	1.0.19.0
MBPPCn64.dll	:	1.0.0.110
Mbpld64.dll	:	1.0.22.0
MBTHX32.dll	:	1.0.15.106
MBTHX64.dll	:	1.0.15.106
MBWrp64.dll	:	1.0.0.110
RCoInst64.dll	:	1.0.8.4
RP3DAA64.dll	:	6.0.6001.18
RP3DHT64.dll	:	6.0.6001.18
RtCOMB4.dll	:	2.0.0.128
RTCOMDLL.dll	:	2.0.0.128
RTEED64A.dll	:	6.1.6001.33
RTEEG64A.dll	:	6.1.6001.33
RTEEL64A.dll	:	6.1.6001.33
RTEEP64A.dll	:	6.1.6001.33
RtkApi64.dll	:	1.0.0.20
RtkAP064.dll	:	11.0.6000.137
RtkCfg.dll	:	1.0.0.1
RtkCfg64.dll	:	1.0.0.2
RtlCPAPI.dll	:	1.0.2.4
RtlCPAPI64.dll	:	1.0.2.4
RtPgEx64.dll	:	6.0.6000.116
SFComm64.dll	:	2.0.0.9
SFDAPO64.dll	:	2.0.0.9
SFHAP064.dll	:	2.0.0.9
SFProc64.dll	:	2.0.0.9
SFSAP064.dll	:	2.0.0.9
slcshp64.dll	:	1.0.3.0
slgeq64.dll	:	1.0.1.0
slh36064.dll	:	1.0.2.0
slInit64.dll	:	1.1.3.0
slmaxv64.dll	:	1.1.2.0
sltshd64.dll	:	1.1.1.0
sluapo64.dll	:	1.8.24.0
SRSHP64.dll	:	1.1.0.0
SRSTSH64.dll	:	1.1.4.0
SRSTX64.dll	:	3.2.0.0
SRSWOW64.dll	:	1.1.3.0
WavesGUILib.dll	:	1.2.3.4

Readme.txt

```

HDM Driver : -----
Vista/Win7 x86:
RtHDMV.sys : 6.0.1.6034
RtkAudioSrvATI.exe : 1.0.0.23
RtkUpd.exe : 2.8.0.1
RH3DAA32.dll : 6.0.6001.18
RH3DHT32.dll : 6.0.6001.18
RHCoInst.dll : 1.0.8.2
RHDMEExt.dll : 6.0.6000.113
RTEED32H.dll : 6.1.6001.33
RTEEG32H.dll : 6.1.6001.33
RTEEL32H.dll : 6.1.6001.33
RTEEP32H.dll : 6.1.6001.33
RtkHDM.dll : 11.0.6000.132

Vista/Win7 x64:
RtHDMVX.sys : 6.0.1.6034
RtkAudioSrvATI64.exe : 1.0.0.23
RtkUpd64.exe : 2.8.0.1
RH3DAA64.dll : 6.0.6001.18
RH3DHT64.dll : 6.0.6001.18
RHCoInst64.dll : 1.0.8.2
RHDMEx64.dll : 6.0.6000.113
RTEED64H.dll : 6.1.6001.33
RTEEG64H.dll : 6.1.6001.33
RTEEL64H.dll : 6.1.6001.33
RTEEP64H.dll : 6.1.6001.33
RtkHDM64.dll : 11.0.6000.132

XP/2K x86:
RtkHDM.sys : 5.10.0.6034
Rtaupd.exe : 2.8.0.1
RHCoInstXP.dll : 1.0.8.2

XP/2K x64:
RtkHDMX.sys : 5.10.0.6034
Rtaupd64.exe : 2.8.0.1
RHCoInst64XP.dll : 1.0.8.2

Driver Setup Program : 2.95

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

```

//=====

Driver Package R2.42

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC892, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC892, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680

3. HDM Device WHQL Support: ATI HDM Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008,

Windows7 - x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

```

Windows 2000/XP : -----
Windows 2000/XP :
RTKHDA64.sys : 5.10.0.6043
RTKHDAUD.sys : 5.10.0.6043
Alcmtr.exe : 1.6.0.4
AlcWzrd.exe : 1.1.0.37

```

Readme.txt

```

Mccal.exe : 1.1.2.3
RTHDCPL.exe : 2.3.3.6
RtkAudioService64.exe : 1.0.0.19
RtkAudioService.exe : 1.0.0.19
RTLCP.exe : 1.0.1.66
RtlUpd64.exe : 2.8.0.1
RtlUpd.exe : 2.8.0.1
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.32
vncutil64.exe : 1.0.0.38
vncutil.exe : 1.0.0.38
AMBfilt.sys : 5.10.0.4240
AMBft64.sys : 5.10.0.4240
Mnft64.sys : 5.10.0.4112
Mnft64.sys : 5.10.0.4115
OA017Afx.sys : 1.0.7.3
ALSndMgr.cpl : 1.0.0.11
RTSndMgr.cpl : 1.0.1.4
RCoInst64XP.dll : 1.0.8.2
RTCOMDLL.dll : 1.0.0.105
RtkCoInstXP.dll : 1.0.8.2
RtlCPAPI.dll : 1.0.2.3
Vista/Wn7 driver : -----
Vista/Wn7 driver for x86
RTKVHDA.sys : 6.0.1.6043
AERTSrv.exe : 1.0.32.10
RtHDVBg.exe : 1.0.0.8
RtHDVCpl.exe : 1.0.0.484
RtkAudioService.exe : 1.0.0.24
RtkNGUI.exe : 0.0.0.24
RtlUpd.exe : 2.8.0.1
SkyTel.exe : 2.0.2.2
vncutil.exe : 1.0.0.38
mbfilt32.sys : 6.10.0.8
RTSndMgr.cpl : 1.0.0.18
AERTACap.dll : 2.0.32.11
AERTARen.dll : 1.0.32.9
BlackSkinImages.dll : 0.0.0.24
DarkSkinImages.dll : 0.0.0.24
DTSBassEnhancementDLL.dll : 1.0.0.1
DTSBoostDLL.dll : 1.0.0.1
DTSGainCompensatorDLL.dll : 1.0.0.1
DTSGFXAPO.dll : 1.0.0.1
DTSGFXAPONS.dll : 1.0.0.1
DTSLFXAPO.dll : 1.0.0.1
DTSLimitterDLL.dll : 1.0.0.1
DTSNeoPCDLL.dll : 1.0.0.1
DTSS2HeadphoneDLL.dll : 1.0.0.1
DTSS2SpeakerDLL.dll : 1.0.0.1
DTSSymmetryDLL.dll : 1.0.0.1
DTSVoiceClarityDLL.dll : 1.0.0.1
FMAP0.dll : 42.5.26.65
LightSkinImages.dll : 0.0.0.24
MaxxAudioAPO.dll : 1.2.2.0
MaxxAudioAPO20.dll : 2.2.6.0
MaxxAudioEQ.dll : 5.9.7.0
MBAP032.dll : 1.0.19.0
MBPPCn32.dll : 1.0.0.110
Mbpld32.dll : 1.0.22.0
MBTHX32.dll : 1.0.15.106
MBWrp32.dll : 1.0.0.110
RP3DAA32.dll : 6.0.6001.18
RP3DHT32.dll : 6.0.6001.18
RTCOMDLL.dll : 2.0.0.127
RTEED32A.dll : 6.1.6001.33
RTEEG32A.dll : 6.1.6001.33
RTEEL32A.dll : 6.1.6001.33
RTEEP32A.dll : 6.1.6001.33
RtkAPO.dll : 11.0.6000.134

```

	Readme.txt	
RtkApoApi.dll	:	1.0.0.20
RtkCfg.dll	:	1.0.0.2
RtkCoInst.dll	:	1.0.8.4
RtkPgExt.dll	:	6.0.6000.114
RtlCPAPI.dll	:	1.0.2.4
SFFXComm.dll	:	2.0.0.9
SFFXDAP0.dll	:	2.0.0.9
SFFXHAP0.dll	:	2.0.0.9
SFFXProc.dll	:	2.0.0.9
SFFXSAP0.dll	:	2.0.0.9
slcshp32.dll	:	1.0.3.0
slgeq32.dll	:	1.0.1.0
slh36032.dll	:	1.0.2.0
slInit32.dll	:	1.1.3.0
slmaxv32.dll	:	1.1.2.0
sltshd32.dll	:	1.1.1.0
sluapo32.dll	:	1.8.24.0
SRSHP360.dll	:	1.1.0.0
SRSTSHD.dll	:	1.1.4.0
SRSTSXT.dll	:	3.2.0.0
SRSWOW.dll	:	1.1.3.0
WavesLib.dll	:	5.9.7.0
Vista/Win7 driver for x64		
RTKVHD64.sys	:	6.0.1.6043
AERTSr64.exe	:	1.0.64.10
RAVBg64.exe	:	1.0.0.8
RAVCpl64.exe	:	1.0.0.484
RtkAudioService64.exe	:	1.0.0.24
RtkNGUI64.exe	:	0.0.0.24
RtlUpd64.exe	:	2.8.0.1
SkyTel.exe	:	2.0.2.2
vncutil64.exe	:	1.0.0.38
GWfilt64.sys	:	6.10.0.3
mbfilt64.sys	:	6.10.0.8
RTSnMg64.cpl	:	1.0.0.18
AERTAC64.dll	:	2.0.64.11
AERTAR64.dll	:	1.0.64.9
BlackSkinImages64.dll	:	0.0.0.24
DarkSkinImages64.dll	:	0.0.0.24
DTSBassEnhancementDLL64.dll	:	1.0.0.1
DTSBoostDLL64.dll	:	1.0.0.1
DTSGainCompensatorDLL64.dll	:	1.0.0.1
DTSAFXAP064.dll	:	1.0.0.1
DTSAFXAPONS64.dll	:	1.0.0.1
DTSLFXAP064.dll	:	1.0.0.1
DTSLimitDLL64.dll	:	1.0.0.1
DTSNeoPCDLL64.dll	:	1.0.0.1
DTSS2HeadphoneDLL64.dll	:	1.0.0.1
DTSS2SpeakerDLL64.dll	:	1.0.0.1
DTSSymmetryDLL64.dll	:	1.0.0.1
DTSVoiceClarityDLL64.dll	:	1.0.0.1
FMAP064.dll	:	42.6.26.65
LghtSkinImages64.dll	:	0.0.0.24
MaxxAudioAP020.dll	:	2.2.7.0
MaxxAudioEQ.dll	:	5.9.7.0
MBAP032.dll	:	1.0.19.0
MBAP064.dll	:	1.0.19.0
MBPPCn64.dll	:	1.0.0.110
Mbpld64.dll	:	1.0.22.0
MBTHX32.dll	:	1.0.15.106
MBTHX64.dll	:	1.0.15.106
MBWrp64.dll	:	1.0.0.110
RCoInst64.dll	:	1.0.8.4
RP3DAA64.dll	:	6.0.6001.18
RP3DHT64.dll	:	6.0.6001.18
RtCOMB4.dll	:	2.0.0.127
RTCOMDLL.dll	:	2.0.0.127
RTEED64A.dll	:	6.1.6001.33
RTEEG64A.dll	:	6.1.6001.33

	Readme.txt	
RTEEL64A.dll		: 6.1.6001.33
RTEEP64A.dll		: 6.1.6001.33
RtkApi64.dll		: 1.0.0.20
RtkAPO64.dll		: 11.0.6000.134
RtkCfg.dll		: 1.0.0.1
RtkCfg64.dll		: 1.0.0.2
RtLCPAPI.dll		: 1.0.2.4
RtLCPAPI64.dll		: 1.0.2.4
RtPgEx64.dll		: 6.0.6000.114
SFComm64.dll		: 2.0.0.9
SFDAP064.dll		: 2.0.0.9
SFHAP064.dll		: 2.0.0.9
SFProc64.dll		: 2.0.0.9
SFSAP064.dll		: 2.0.0.9
slcshp64.dll		: 1.0.3.0
slgeq64.dll		: 1.0.1.0
slh36064.dll		: 1.0.2.0
slInit64.dll		: 1.1.3.0
slmaxv64.dll		: 1.1.2.0
sltshd64.dll		: 1.1.1.0
sluapo64.dll		: 1.8.24.0
SRSHP64.dll		: 1.1.0.0
SRSTSH64.dll		: 1.1.4.0
SRSTX64.dll		: 3.2.0.0
SRSW064.dll		: 1.1.3.0
WavesGUILib.dll		: 1.2.3.4
HDM Driver :-----		
Vista/Win7 x86:		
RtHDMV.sys		: 6.0.1.6034
RtkAudioSrvATI.exe		: 1.0.0.23
RtkUpd.exe		: 2.8.0.1
RH3DAA32.dll		: 6.0.6001.18
RH3DHT32.dll		: 6.0.6001.18
RHCoInst.dll		: 1.0.8.2
RHDMExt.dll		: 6.0.6000.113
RTEED32H.dll		: 6.1.6001.33
RTEEG32H.dll		: 6.1.6001.33
RTEEL32H.dll		: 6.1.6001.33
RTEEP32H.dll		: 6.1.6001.33
RtkHDM.dll		: 11.0.6000.132
Vista/Win7 x64:		
RtHDMVX.sys		: 6.0.1.6034
RtkAudioSrvATI64.exe		: 1.0.0.23
RtkUpd64.exe		: 2.8.0.1
RH3DAA64.dll		: 6.0.6001.18
RH3DHT64.dll		: 6.0.6001.18
RHCoInst64.dll		: 1.0.8.2
RHDMEx64.dll		: 6.0.6000.113
RTEED64H.dll		: 6.1.6001.33
RTEEG64H.dll		: 6.1.6001.33
RTEEL64H.dll		: 6.1.6001.33
RTEEP64H.dll		: 6.1.6001.33
RtkHDM64.dll		: 11.0.6000.132
XP/2K x86:		
RtkHDM.sys		: 5.10.0.6034
Rtaupd.exe		: 2.8.0.1
RHCoInstXP.dll		: 1.0.8.2
XP/2K x64:		
RtkHDMX.sys		: 5.10.0.6034
Rtaupd64.exe		: 2.8.0.1
RHCoInst64XP.dll		: 1.0.8.2
Driver Setup Program		: 2.94

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111

Readme.txt

Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.41

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC892, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC892, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 - x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :

RTKHDA64.sys	: 5.10.0.6029
RTKHDAUD.sys	: 5.10.0.6029
Alcmtr.exe	: 1.6.0.4
AlcWzrd.exe	: 1.1.0.37
McCal.exe	: 1.1.2.3
RTHDCPL.exe	: 2.3.3.2
RtkAudioService.exe	: 1.0.0.19
RtkAudioService64.exe	: 1.0.0.19
RTLCPPL.exe	: 1.0.1.66
RtlUpd.exe	: 2.8.0.1
RtlUpd64.exe	: 2.8.0.1
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.32
vncutil.exe	: 1.0.0.38
vncutil64.exe	: 1.0.0.38
AMBFilt.sys	: 5.10.0.4240
AMBFt64.sys	: 5.10.0.4240
Mnfilt.sys	: 5.10.0.4112
Mnft64.sys	: 5.10.0.4115
OA017Afx.sys	: 1.0.7.3
ALSndMgr.cpl	: 1.0.0.11
RTSndMgr.cpl	: 1.0.1.4
RCoInst64XP.dll	: 1.0.8.2
RTCOMDLL.dll	: 1.0.0.104
RtkCoInstXP.dll	: 1.0.8.2
RtlCPAPI.dll	: 1.0.2.3

Vista/Wn7 driver : -----

Vista/Wn7 driver for x86

RTKVHDA.sys	: 6.0.1.6029
AERTSrv.exe	: 1.0.32.10
RtHDVBg.exe	: 1.0.0.8
RtHDVCpl.exe	: 1.0.0.477
RtkAudioService.exe	: 1.0.0.24
RtkNGUI.exe	: 0.0.0.22
RtlUpd.exe	: 2.8.0.1
SkyTel.exe	: 2.0.2.2
vncutil.exe	: 1.0.0.38
mbfilt32.sys	: 6.10.0.8
RTSndMgr.cpl	: 1.0.0.18
AERTACap.dll	: 2.0.32.9
AERTARen.dll	: 1.0.32.9
BlackSkinImages.dll	: 0.0.0.22
DarkSkinImages.dll	: 0.0.0.22
DTSBassEnhancementDLL.dll	: 1.0.0.1
DTSBoostDLL.dll	: 1.0.0.1
DTSGainCompensatorDLL.dll	: 1.0.0.1
DTSGFXAPO.dll	: 1.0.0.1

	Readme.txt	
DTSGFXAPONS.dll		: 1.0.0.1
DTSLFXAPO.dll		: 1.0.0.1
DTSLimiterDLL.dll		: 1.0.0.1
DTSSNeoPCDLL.dll		: 1.0.0.1
DTSS2HeadphoneDLL.dll		: 1.0.0.1
DTSS2SpeakerDLL.dll		: 1.0.0.1
DTSSymmetryDLL.dll		: 1.0.0.1
DTSVoiceClarityDLL.dll		: 1.0.0.1
FMAP0.dll		: 42.5.24.65
LightSkinImages.dll		: 0.0.0.22
MaxxAudioAPO.dll		: 1.2.2.0
MaxxAudioAPO20.dll		: 2.2.6.0
MaxxAudioEQ.dll		: 5.9.7.0
MBAP032.dll		: 1.0.19.0
MBPPCn32.dll		: 1.0.0.110
MBpld32.dll		: 1.0.22.0
MBTHX32.dll		: 1.0.8.109
MBWrp32.dll		: 1.0.0.110
RP3DAA32.dll		: 6.0.6001.18
RP3DHT32.dll		: 6.0.6001.18
RTCOMDLL.dll		: 2.0.0.125
RTEED32A.dll		: 6.1.6001.33
RTEEG32A.dll		: 6.1.6001.33
RTEEL32A.dll		: 6.1.6001.33
RTEEP32A.dll		: 6.1.6001.33
RtkAPO.dll		: 11.0.6000.132
RtkApoApi.dll		: 1.0.0.20
RtkCfg.dll		: 1.0.0.2
RtkColnst.dll		: 1.0.8.3
RtkPgExt.dll		: 6.0.6000.113
RtlCPAPI.dll		: 1.0.2.4
SFFXComm.dll		: 2.0.0.9
SFFXDAP0.dll		: 2.0.0.9
SFFXHAP0.dll		: 2.0.0.9
SFFXProc.dll		: 2.0.0.9
SFFXSAP0.dll		: 2.0.0.9
slcshp32.dll		: 1.0.3.0
slgeq32.dll		: 1.0.1.0
slh36032.dll		: 1.0.2.0
slInit32.dll		: 1.1.3.0
slmaxv32.dll		: 1.1.2.0
sltshd32.dll		: 1.1.1.0
sluapo32.dll		: 1.8.24.0
SRSHP360.dll		: 1.1.0.0
SRSTSHD.dll		: 1.1.4.0
SRSTSXT.dll		: 3.2.0.0
SRSWOW.dll		: 1.1.3.0
WavesLib.dll		: 5.9.7.0
Vista/Win7 driver for x64		
RTKVHD64.sys		: 6.0.1.6029
AERTSr64.exe		: 1.0.64.10
RAVBg64.exe		: 1.0.0.8
RAVCpl64.exe		: 1.0.0.477
RtkAudioService64.exe		: 1.0.0.24
RtkNGUI64.exe		: 0.0.0.22
RtlUpd64.exe		: 2.8.0.1
SkyTel.exe		: 2.0.2.2
vncutil64.exe		: 1.0.0.38
GWfilt64.sys		: 6.10.0.3
mbfilt64.sys		: 6.10.0.8
RTSnMg64.cpl		: 1.0.0.18
AERTAC64.dll		: 2.0.64.9
AERTAR64.dll		: 1.0.64.9
BlackSkinImages64.dll		: 0.0.0.22
DarkSkinImages64.dll		: 0.0.0.22
DTSBassEnhancementDLL64.dll		: 1.0.0.1
DTSBoostDLL64.dll		: 1.0.0.1
DTSGainCompensatorDLL64.dll		: 1.0.0.1
DTSGFXAP064.dll		: 1.0.0.1

Readme.txt

DTSGFXAPONS64.dll	: 1.0.0.1
DTSLFXAP064.dll	: 1.0.0.1
DTSLi mi terDLL64.dll	: 1.0.0.1
DTSSNeoPCDLL64.dll	: 1.0.0.1
DTSS2HeadphoneDLL64.dll	: 1.0.0.1
DTSS2SpeakerDLL64.dll	: 1.0.0.1
DTSSymmetryDLL64.dll	: 1.0.0.1
DTSVoi ceCl ari tyDLL64.dll	: 1.0.0.1
FMAP064.dll	: 42.6.24.65
Li ghtSkinI mages64.dll	: 0.0.0.22
MaxxAudi oAP020.dll	: 2.2.6.0
MaxxAudi oEQ.dll	: 5.9.7.0
MBAP032.dll	: 1.0.19.0
MBAP064.dll	: 1.0.19.0
MBPPCn64.dll	: 1.0.0.110
MBpl d64.dll	: 1.0.22.0
MBTHX32.dll	: 1.0.8.109
MBTHX64.dll	: 1.0.8.109
MBWrp64.dll	: 1.0.0.110
RCoInst64.dll	: 1.0.8.3
RP3DAA64.dll	: 6.0.6001.18
RP3DHT64.dll	: 6.0.6001.18
RtCOM64.dll	: 2.0.0.125
RTCOMDLL.dll	: 2.0.0.125
RTEED64A.dll	: 6.1.6001.33
RTEEG64A.dll	: 6.1.6001.33
RTEEL64A.dll	: 6.1.6001.33
RTEEP64A.dll	: 6.1.6001.33
RtkApi 64.dll	: 1.0.0.20
RtkAP064.dll	: 11.0.6000.132
RtkCfg.dll	: 1.0.0.1
RtkCfg64.dll	: 1.0.0.2
RtLCPAPI.dll	: 1.0.2.4
RtLCPAPI64.dll	: 1.0.2.4
RtPgEx64.dll	: 6.0.6000.113
SFComm64.dll	: 2.0.0.9
SFDAP064.dll	: 2.0.0.9
SFHAP064.dll	: 2.0.0.9
SFProc64.dll	: 2.0.0.9
SFSAP064.dll	: 2.0.0.9
sl cshp64.dll	: 1.0.3.0
sl geq64.dll	: 1.0.1.0
sl h36064.dll	: 1.0.2.0
sl Ini t64.dll	: 1.1.3.0
sl maxv64.dll	: 1.1.2.0
sl tshd64.dll	: 1.1.1.0
sl uapo64.dll	: 1.8.24.0
SRSHP64.dll	: 1.1.0.0
SRSTSH64.dll	: 1.1.4.0
SRSTX64.dll	: 3.2.0.0
SRSW064.dll	: 1.1.3.0
WavesGUILib.dll	: 1.2.3.4

HDMI Driver :	
Vista/Wi n7 x86:	
RtHDMV.sys	: 6.0.1.5992
RtkAudioSrvATI.exe	: 1.0.0.23
RtkUpd.exe	: 2.8.0.1
RH3DAA32.dll	: 6.0.6001.18
RH3DHT32.dll	: 6.0.6001.18
RHCoInst.dll	: 1.0.7.0
RHDMExt.dll	: 6.0.6000.109
RtkHDM.dll	: 11.0.6000.126
Vista/Wi n7 x64:	
RtHDMVX.sys	: 6.0.1.5992
RtkAudioSrvATI64.exe	: 1.0.0.23
RtkUpd64.exe	: 2.8.0.1
RH3DAA64.dll	: 6.0.6001.18
RH3DHT64.dll	: 6.0.6001.18

Readme.txt

RHCoInst64.dll : 1.0.7.0
RHDME64.dll : 6.0.6000.109
RtkHDM64.dll : 11.0.6000.126

XP/2K x86:
RtkHDM.sys : 5.10.0.5992
Rtaupd.exe : 2.8.0.1
RHCoInstXP.dll : 1.0.7.0

XP/2K x64:
RtkHDMX.sys : 5.10.0.5992
Rtaupd64.exe : 2.8.0.1
RHCoInst64XP.dll : 1.0.7.0

Driver Setup Program : 2.92

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.40

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC892, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC892, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680

3. HDM Device WHQL Support: ATI HDM Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 - x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :
RTKHDA64.sys : 5.10.0.6013
RTKHDAUD.sys : 5.10.0.6013
McCal.exe : 1.1.2.2
RTHDCPL.exe : 2.3.2.8
RtkAudioService64.exe : 1.0.0.19
RtkAudioService.exe : 1.0.0.19
RTLCPPL.exe : 1.0.1.66
RtlUpd64.exe : 2.8.0.1
RtlUpd.exe : 2.8.0.1
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.32
vncutil64.exe : 1.0.0.38
vncutil.exe : 1.0.0.38
Alcmtr.exe : 1.6.0.4
AlcWzrd.exe : 1.1.0.37
Mnfilt.sys : 5.10.0.4112
Mnft64.sys : 5.10.0.4115
OA017Afx.sys : 1.0.7.3
AMBfilt.sys : 5.10.0.4240
AMBft64.sys : 5.10.0.4240
RTSndMgr.cpl : 1.0.1.4
ALSndMgr.cpl : 1.0.0.11
RCoInst64XP.dll : 1.0.7.9
RTCOMDLL.dll : 1.0.0.103
RtkCoInstXP.dll : 1.0.7.9
RtlCPAPI.dll : 1.0.2.3

Vista/Win7 driver : -----

Vista/Win7 driver for x86
RTKVHDA.sys : 6.0.1.6013

	Readme.txt	
AERTSrv.exe	:	1.0.32.10
APOPCH.exe	:	1.0.0.0
RtHDVBg.exe	:	1.0.0.8
RtHDVCpl.exe	:	1.0.0.463
RtkAudioService.exe	:	1.0.0.24
RtkNGUI.exe	:	0.0.0.21
RtlUpd.exe	:	2.8.0.1
SkyTel.exe	:	2.0.2.2
vncutil.exe	:	1.0.0.38
mbfilt32.sys	:	6.10.0.8
RTSndMgr.cpl	:	1.0.0.18
AERTACap.dll	:	2.0.32.9
AERTARen.dll	:	1.0.32.9
BlackSkinImages.dll	:	0.0.0.21
DarkSkinImages.dll	:	0.0.0.21
DTSBassEnhancementDLL.dll	:	1.0.0.1
DTSBoostDLL.dll	:	1.0.0.1
DTSGainCompensatorDLL.dll	:	1.0.0.1
DTSAFXAPO.dll	:	1.0.0.1
DTSLFXAPO.dll	:	1.0.0.1
DTS LimiterDLL.dll	:	1.0.0.1
DTSNeoPCDLL.dll	:	1.0.0.1
DTSS2HeadphoneDLL.dll	:	1.0.0.1
DTSS2SpeakerDLL.dll	:	1.0.0.1
DTSVoiceClarityDLL.dll	:	1.0.0.1
FMAPO.dll	:	42.5.23.65
LightSkinImages.dll	:	0.0.0.21
MaxxAudioAPO.dll	:	1.2.2.0
MaxxAudioAPO20.dll	:	2.2.6.0
MaxxAudioEQ.dll	:	5.9.7.0
MBAP032.dll	:	1.0.19.0
MBPPCn32.dll	:	1.0.0.110
MBpld32.dll	:	1.0.22.0
MBTHX32.dll	:	1.0.15.103
MBWrp32.dll	:	1.0.0.110
RP3DAA32.dll	:	6.0.6001.18
RP3DHT32.dll	:	6.0.6001.18
RTCOMDLL.dll	:	2.0.0.124
RTEED32A.dll	:	6.1.6001.33
RTEEG32A.dll	:	6.1.6001.33
RTEEL32A.dll	:	6.1.6001.33
RTEEP32A.dll	:	6.1.6001.33
RtkAPO.dll	:	11.0.6000.130
RtkApoApi.dll	:	1.0.0.20
RtkCfg.dll	:	1.0.0.2
RtkCoInst.dll	:	1.0.7.9
RtkPgExt.dll	:	6.0.6000.112
RtlCPAPI.dll	:	1.0.2.4
SFFXComm.dll	:	2.0.0.9
SFFXDAP0.dll	:	2.0.0.9
SFFXHAP0.dll	:	2.0.0.9
SFFXProc.dll	:	2.0.0.9
SFFXSAP0.dll	:	2.0.0.9
slcshp32.dll	:	1.0.3.0
slgeq32.dll	:	1.0.1.0
slh36032.dll	:	1.0.2.0
slInit32.dll	:	1.1.3.0
slmaxv32.dll	:	1.1.2.0
sltshd32.dll	:	1.1.1.0
sluapo32.dll	:	1.8.24.0
SRSHP360.dll	:	1.1.0.0
SRSTSHD.dll	:	1.1.4.0
SRSTSXT.dll	:	3.2.0.0
SRSWOW.dll	:	1.1.3.0
WavesLib.dll	:	5.9.7.0
Vista/Win7 driver for x64		
RTKVHD64.sys	:	6.0.1.6013
AERTSr64.exe	:	1.0.64.10
APOPCH.exe	:	1.0.0.0

	Readme.txt	
RAVBg64.exe	:	1.0.0.8
RAVCpl64.exe	:	1.0.0.463
RtkAudioService64.exe	:	1.0.0.24
RtkNGUI64.exe	:	0.0.0.21
RtlUpd64.exe	:	2.8.0.1
SkyTel.exe	:	2.0.2.2
vncutil64.exe	:	1.0.0.38
GWfilt64.sys	:	6.10.0.3
mbfilt64.sys	:	6.10.0.8
RTSnMg64.cpl	:	1.0.0.18
AERTAC64.dll	:	2.0.64.9
AERTAR64.dll	:	1.0.64.9
BlackSkinImages64.dll	:	0.0.0.21
DarkSkinImages64.dll	:	0.0.0.21
DTSBassEnhancementDLL64.dll	:	1.0.0.1
DTSBoostDLL64.dll	:	1.0.0.1
DTSGainCompensatorDLL64.dll	:	1.0.0.1
DTSAFXAP064.dll	:	1.0.0.1
DTSAFXAP064.dll	:	1.0.0.1
DTSLimitDLL64.dll	:	1.0.0.1
DTSNeoPCDLL64.dll	:	1.0.0.1
DTSS2HeadphoneDLL64.dll	:	1.0.0.1
DTSS2SpeakerDLL64.dll	:	1.0.0.1
DTSVoiceClarityDLL64.dll	:	1.0.0.1
FMAP064.dll	:	42.6.23.65
LightSkinImages64.dll	:	0.0.0.21
MaxxAudioAP020.dll	:	2.2.6.0
MaxxAudioEQ.dll	:	5.9.7.0
MBAP032.dll	:	1.0.19.0
MBAP064.dll	:	1.0.19.0
MBPPCn64.dll	:	1.0.0.110
MBpld64.dll	:	1.0.22.0
MBTHX32.dll	:	1.0.15.103
MBTHX64.dll	:	1.0.15.103
MBWrp64.dll	:	1.0.0.110
RCoInst64.dll	:	1.0.7.9
RP3DAA64.dll	:	6.0.6001.18
RP3DHT64.dll	:	6.0.6001.18
RtCOM64.dll	:	2.0.0.123
RTCOMDLL.dll	:	2.0.0.123
RTEED64A.dll	:	6.1.6001.33
RTEEG64A.dll	:	6.1.6001.33
RTEEL64A.dll	:	6.1.6001.33
RTEEP64A.dll	:	6.1.6001.33
RtkApi64.dll	:	1.0.0.20
RtkAP064.dll	:	11.0.6000.130
RtkCfg.dll	:	1.0.0.1
RtkCfg64.dll	:	1.0.0.2
RtlCPAPI.dll	:	1.0.2.4
RtlCPAPI64.dll	:	1.0.2.4
RtPgEx64.dll	:	6.0.6000.112
SFComm64.dll	:	2.0.0.9
SFDAP064.dll	:	2.0.0.9
SFHAP064.dll	:	2.0.0.9
SFProc64.dll	:	2.0.0.9
SFSAP064.dll	:	2.0.0.9
slcshp64.dll	:	1.0.3.0
slgeq64.dll	:	1.0.1.0
slh36064.dll	:	1.0.2.0
slInit64.dll	:	1.1.3.0
slmaxv64.dll	:	1.1.2.0
sltshd64.dll	:	1.1.1.0
sluapo64.dll	:	1.8.24.0
SRSHP64.dll	:	1.1.0.0
SRSTSH64.dll	:	1.1.4.0
SRSTX64.dll	:	3.2.0.0
SRSW064.dll	:	1.1.3.0
WavesGUILib.dll	:	1.2.3.4
HDM Driver :	-----	

Readme.txt

Vista/Win7 x86:
RtHDMV.sys : 6.0.1.5992
RtkAudioSrvATI.exe : 1.0.0.23
RtkUpd.exe : 2.8.0.1
RH3DAA32.dll : 6.0.6001.18
RH3DHT32.dll : 6.0.6001.18
RHCoInst.dll : 1.0.7.0
RHDMExt.dll : 6.0.6000.109
RtkHDM.dll : 11.0.6000.126

Vista/Win7 x64:
RtHDMVX.sys : 6.0.1.5992
RtkAudioSrvATI64.exe : 1.0.0.23
RtkUpd64.exe : 2.8.0.1
RH3DAA64.dll : 6.0.6001.18
RH3DHT64.dll : 6.0.6001.18
RHCoInst64.dll : 1.0.7.0
RHDMEx64.dll : 6.0.6000.109
RtkHDM64.dll : 11.0.6000.126

XP/2K x86:
RtkHDM.sys : 5.10.0.5992
Rtaupd.exe : 2.8.0.1
RHCoInstXP.dll : 1.0.7.0

XP/2K x64:
RtkHDMX.sys : 5.10.0.5992
Rtaupd64.exe : 2.8.0.1
RHCoInst64XP.dll : 1.0.7.0

Driver Setup Program : 2.89

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.39

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC892, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC892, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 - x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :
RTKHDA64.sys : 5.10.0.6000
RTKHDAUD.sys : 5.10.0.6000
McCal.exe : 1.1.2.2
RTHDCPL.exe : 2.3.2.5
RtkAudioService64.exe : 1.0.0.19
RtkAudioService.exe : 1.0.0.19
RTLCPPL.exe : 1.0.1.66
RtlUpd64.exe : 2.8.0.1
RtlUpd.exe : 2.8.0.1
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.32
vncutil64.exe : 1.0.0.38
vncutil.exe : 1.0.0.38

Readme.txt

```

Alcmtr.exe : 1.6.0.4
AlcWzrd.exe : 1.1.0.37
AMBfilt.sys : 5.10.0.4240
AMBft64.sys : 5.10.0.4240
Mbnfilt.sys : 5.10.0.4112
Mbnft64.sys : 5.10.0.4115
0A017Afx.sys : 1.0.7.3
RTSndMgr.cpl : 1.0.1.4
ALSndMgr.cpl : 1.0.0.11
RCoInst64XP.dll : 1.0.7.8
RTCOMDLL.dll : 1.0.0.103
RtkCoInstXP.dll : 1.0.7.8
RtlCPAPI.dll : 1.0.2.3
Vista/Win7 driver : -----
Vista/Win7 driver for x86
RTKVHDA.sys : 6.0.1.6000
AERTSrv.exe : 1.0.32.10
APOPCH.exe : 1.0.0.0
RtHDVBg.exe : 1.0.0.8
RtHDVCpl.exe : 1.0.0.456
RtkAudioService.exe : 1.0.0.24
RtkNGUI.exe : 0.0.0.17
RtlUpd.exe : 2.8.0.1
SkyTel.exe : 2.0.2.2
vncutil.exe : 1.0.0.38
mbfilt32.sys : 6.10.0.8
RTSndMgr.cpl : 1.0.0.18
AERTACap.dll : 2.0.32.9
AERTARen.dll : 1.0.32.9
BlackSkinImages.dll : 0.0.0.17
DarkSkinImages.dll : 0.0.0.17
FMAP0.dll : 42.5.21.67
LightSkinImages.dll : 0.0.0.17
MaxxAudioAPO.dll : 1.2.2.0
MaxxAudioAPO20.dll : 2.2.6.0
MaxxAudioEQ.dll : 5.9.7.0
MBAP032.dll : 1.0.19.0
MBPPCn32.dll : 1.0.0.110
MBppld32.dll : 1.0.22.0
MBTHX32.dll : 1.0.8.108
MBWrp32.dll : 1.0.0.110
RP3DAA32.dll : 6.0.6001.18
RP3DHT32.dll : 6.0.6001.18
RTCOMDLL.dll : 2.0.0.124
RTEED32A.dll : 6.1.6001.32
RTEEG32A.dll : 6.1.6001.32
RTEEL32A.dll : 6.1.6001.32
RTEEP32A.dll : 6.1.6001.32
RtkAPO.dll : 11.0.6000.129
RtkApoApi.dll : 1.0.0.19
RtkCfg.dll : 1.0.0.2
RtkCoInst.dll : 1.0.7.8
RtkPgExt.dll : 6.0.6000.112
RtlCPAPI.dll : 1.0.2.4
SFFXComm.dll : 2.0.0.9
SFFXDAP0.dll : 2.0.0.9
SFFXHAP0.dll : 2.0.0.9
SFFXProc.dll : 2.0.0.9
SFFXSAP0.dll : 2.0.0.9
slcshp32.dll : 1.0.3.0
slgeq32.dll : 1.0.1.0
slh36032.dll : 1.0.2.0
slInit32.dll : 1.1.3.0
slmaxv32.dll : 1.1.2.0
sltshd32.dll : 1.1.1.0
sluapo32.dll : 1.8.24.0
SRSHP360.dll : 1.1.0.0
SRSTSHD.dll : 1.1.4.0
SRSTSXT.dll : 3.2.0.0

```

	Readme.txt	
SRSWOW.dll		: 1.1.3.0
WavesLib.dll		: 5.9.7.0
Vista/Win7 driver for x64		
RTKVHD64.sys		: 6.0.1.6000
AERTSr64.exe		: 1.0.64.10
APOPCHEX64.exe		: 1.0.0.0
RAVBg64.exe		: 1.0.0.8
RAVCpl64.exe		: 1.0.0.456
RtkAudioService64.exe		: 1.0.0.24
RtkNGUI64.exe		: 0.0.0.17
RtlUpd64.exe		: 2.8.0.1
SkyTel.exe		: 2.0.2.2
vncutil64.exe		: 1.0.0.38
GWfilt64.sys		: 6.10.0.3
mbfilt64.sys		: 6.10.0.8
RTSnMg64.cpl		: 1.0.0.18
AERTAC64.dll		: 2.0.64.9
AERTAR64.dll		: 1.0.64.9
BlackSkinImages64.dll		: 0.0.0.17
DarkSkinImages64.dll		: 0.0.0.17
FMAP064.dll		: 42.6.21.67
LightSkinImages64.dll		: 0.0.0.17
MaxxAudioAPO20.dll		: 2.2.6.0
MaxxAudioEQ.dll		: 5.9.7.0
MBAP032.dll		: 1.0.19.0
MBAP064.dll		: 1.0.19.0
MBPPCn64.dll		: 1.0.0.110
MBpld64.dll		: 1.0.22.0
MBTHX32.dll		: 1.0.8.108
MBTHX64.dll		: 1.0.8.108
MBWrp64.dll		: 1.0.0.110
RCoInst64.dll		: 1.0.7.8
RP3DAA64.dll		: 6.0.6001.18
RP3DHT64.dll		: 6.0.6001.18
RtCOM64.dll		: 2.0.0.123
RTCOMDLL.dll		: 2.0.0.123
RTEED64A.dll		: 6.1.6001.32
RTEEG64A.dll		: 6.1.6001.32
RTEEL64A.dll		: 6.1.6001.32
RTEEP64A.dll		: 6.1.6001.32
RtkApi64.dll		: 1.0.0.19
RtkAPO64.dll		: 11.0.6000.129
RtkCfg.dll		: 1.0.0.1
RtkCfg64.dll		: 1.0.0.2
RtlCPAPI.dll		: 1.0.2.4
RtlCPAPI64.dll		: 1.0.2.4
RtPgEx64.dll		: 6.0.6000.112
SFComm64.dll		: 2.0.0.9
SFDAP064.dll		: 2.0.0.9
SFHAP064.dll		: 2.0.0.9
SFProc64.dll		: 2.0.0.9
SFSAP064.dll		: 2.0.0.9
slcshp64.dll		: 1.0.3.0
slgeq64.dll		: 1.0.1.0
slh36064.dll		: 1.0.2.0
slInit64.dll		: 1.1.3.0
slmaxv64.dll		: 1.1.2.0
sltshd64.dll		: 1.1.1.0
sluapo64.dll		: 1.8.24.0
SRSHP64.dll		: 1.1.0.0
SRSTSH64.dll		: 1.1.4.0
SRSTX64.dll		: 3.2.0.0
SRSWOW64.dll		: 1.1.3.0
WavesGUILib.dll		: 1.2.3.4
HDMI Driver : -----		
Vista/Win7 x86:		
RtHDMV.sys		: 6.0.1.5992
RtkAudioSrvATI.exe		: 1.0.0.23
RtkUpd.exe		: 2.8.0.1

Readme.txt

RH3DAA32.dll : 6.0.6001.18
RH3DHT32.dll : 6.0.6001.18
RHCoInst.dll : 1.0.7.0
RHDMExt.dll : 6.0.6000.109
RtkHDM.dll : 11.0.6000.126

Vista/Win7 x64:

RtHDMVX.sys : 6.0.1.5992
RtkAudioSrvATI64.exe : 1.0.0.23
RtkUpd64.exe : 2.8.0.1
RH3DAA64.dll : 6.0.6001.18
RH3DHT64.dll : 6.0.6001.18
RHCoInst64.dll : 1.0.7.0
RHDMEx64.dll : 6.0.6000.109
RtkHDM64.dll : 11.0.6000.126

XP/2K x86:

RtkHDM.sys : 5.10.0.5992
Rtaupd.exe : 2.8.0.1
RHCoInstXP.dll : 1.0.7.0

XP/2K x64:

RtkHDMX.sys : 5.10.0.5992
Rtaupd64.exe : 2.8.0.1
RHCoInst64XP.dll : 1.0.7.0

Driver Setup Program : 2.89

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.38

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC892, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC892, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275

3. HDM Device WHQL Support: ATI HDM Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 - x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.
2. Support graphic EQ feature.

Windows 2000/XP : -----

Windows 2000/XP :

RTKHDA64.sys : 5.10.0.5995
RTKHDAUD.sys : 5.10.0.5995
Alcmtr.exe : 1.6.0.4
AlcWzrd.exe : 1.1.0.37
McCal.exe : 1.1.2.2
RTHDCPL.exe : 2.3.2.4
RtkAudioService64.exe : 1.0.0.19
RtkAudioService.exe : 1.0.0.19
RTLCPPL.exe : 1.0.1.66
RtlUpd64.exe : 2.8.0.1
RtlUpd.exe : 2.8.0.1
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.32
vncutil64.exe : 1.0.0.38
vncutil.exe : 1.0.0.38
AMBfilt.sys : 5.10.0.4240

	Readme.txt	
AMBft64.sys		: 5.10.0.4240
Mnfil t.sys		: 5.10.0.4112
Mnft64.sys		: 5.10.0.4115
OA017Afx.sys		: 1.0.7.3
ALSndMgr.cpl		: 1.0.0.11
RTSndMgr.cpl		: 1.0.1.4
RCoInst64XP.dll		: 1.0.7.6
RTCOMDLL.dll		: 1.0.0.103
RtkCoInstXP.dll		: 1.0.7.6
RtLCPAPI.dll		: 1.0.2.3
Vista/Win7 driver :	-----	
Vista/Win7 driver for x86		
RTKVHDA.sys		: 6.0.1.5995
AERTSrv.exe		: 1.0.32.10
APOPCH.exe		: 1.0.0.0
RtHDVBg.exe		: 1.0.0.8
RtHDVCpl.exe		: 1.0.0.453
RtkAudioService.exe		: 1.0.0.24
RtkNGUI.exe		: 0.0.0.15
RtlUpd.exe		: 2.8.0.1
SkyTel.exe		: 2.0.2.2
vncutil.exe		: 1.0.0.38
mbfil t32.sys		: 6.10.0.8
RTSndMgr.cpl		: 1.0.0.18
AERTACap.dll		: 2.0.32.9
AERTARen.dll		: 1.0.32.9
BlackSkinImages.dll		: 0.0.0.15
DarkSkinImages.dll		: 0.0.0.15
FMAP0.dll		: 42.5.21.66
LightSkinImages.dll		: 0.0.0.15
MaxxAudioAPO.dll		: 1.2.2.0
MaxxAudioAPO20.dll		: 2.2.6.0
MaxxAudioEQ.dll		: 5.9.7.0
MBAP032.dll		: 1.0.19.0
MBPPCn32.dll		: 1.0.0.110
MBpld32.dll		: 1.0.22.0
MBTHX32.dll		: 1.0.8.108
MBWrp32.dll		: 1.0.0.110
RP3DAA32.dll		: 6.0.6001.18
RP3DHT32.dll		: 6.0.6001.18
RTCOMDLL.dll		: 2.0.0.124
RTEED32A.dll		: 6.1.6001.32
RTEEG32A.dll		: 6.1.6001.32
RTEEL32A.dll		: 6.1.6001.32
RTEEP32A.dll		: 6.1.6001.32
RtkAPO.dll		: 11.0.6000.127
RtkApoApi.dll		: 1.0.0.17
RtkCfg.dll		: 1.0.0.2
RtkCoInst.dll		: 1.0.7.7
RtkPgExt.dll		: 6.0.6000.109
RtLCPAPI.dll		: 1.0.2.4
SFFXComm.dll		: 2.0.0.9
SFFXDAP0.dll		: 2.0.0.9
SFFXHAP0.dll		: 2.0.0.9
SFFXProc.dll		: 2.0.0.9
SFFXSAP0.dll		: 2.0.0.9
slcshp32.dll		: 1.0.3.0
slgeq32.dll		: 1.0.1.0
slh36032.dll		: 1.0.2.0
slInit32.dll		: 1.1.3.0
slmaxv32.dll		: 1.1.2.0
sltshd32.dll		: 1.1.1.0
sluapo32.dll		: 1.8.24.0
SRSHP360.dll		: 1.1.0.0
SRSTSHD.dll		: 1.1.4.0
SRSTSXT.dll		: 3.2.0.0
SRSWOW.dll		: 1.1.3.0
WavesLib.dll		: 5.9.7.0
Vista/Win7 driver for x64		

Readme.txt

RTKVHD64.sys	: 6.0.1.5995
AERTSr64.exe	: 1.0.64.10
APOPCH.exe	: 1.0.0.0
RAVBg64.exe	: 1.0.0.8
RAVCpl64.exe	: 1.0.0.453
RtkAudioService64.exe	: 1.0.0.24
RtkNGUI64.exe	: 0.0.0.15
RtlUpd64.exe	: 2.8.0.1
SkyTel.exe	: 2.0.2.2
vncutil64.exe	: 1.0.0.38
GWfilt64.sys	: 6.10.0.3
mbfilt64.sys	: 6.10.0.8
RTSnMg64.cpl	: 1.0.0.18
AERTAC64.dll	: 2.0.64.9
AERTAR64.dll	: 1.0.64.9
BlackSkinImages64.dll	: 0.0.0.15
DarkSkinImages64.dll	: 0.0.0.15
FMAP064.dll	: 42.6.21.66
LightSkinImages64.dll	: 0.0.0.15
MaxxAudioAP020.dll	: 2.2.6.0
MaxxAudioEQ.dll	: 5.9.7.0
MBAP032.dll	: 1.0.19.0
MBAP064.dll	: 1.0.19.0
MBPPCn64.dll	: 1.0.0.110
Mbpld64.dll	: 1.0.22.0
MBTHX32.dll	: 1.0.8.108
MBTHX64.dll	: 1.0.8.108
MBWrp64.dll	: 1.0.0.110
RCoInst64.dll	: 1.0.7.7
RP3DAA64.dll	: 6.0.6001.18
RP3DHT64.dll	: 6.0.6001.18
RtCOMB4.dll	: 2.0.0.123
RTCOMDLL.dll	: 2.0.0.123
RTEED64A.dll	: 6.1.6001.32
RTEEG64A.dll	: 6.1.6001.32
RTEEL64A.dll	: 6.1.6001.32
RTEEP64A.dll	: 6.1.6001.32
RtkApi64.dll	: 1.0.0.17
RtkAP064.dll	: 11.0.6000.127
RtkCfg.dll	: 1.0.0.1
RtkCfg64.dll	: 1.0.0.2
RtlCPAPI.dll	: 1.0.2.4
RtlCPAPI64.dll	: 1.0.2.4
RtPgEx64.dll	: 6.0.6000.109
SFComm64.dll	: 2.0.0.9
SFDAPO64.dll	: 2.0.0.9
SFHAP064.dll	: 2.0.0.9
SFProc64.dll	: 2.0.0.9
SFSAP064.dll	: 2.0.0.9
slcshp64.dll	: 1.0.3.0
slgeq64.dll	: 1.0.1.0
slh36064.dll	: 1.0.2.0
slInit64.dll	: 1.1.3.0
slmaxv64.dll	: 1.1.2.0
sltshd64.dll	: 1.1.1.0
sluapo64.dll	: 1.8.24.0
SRSHP64.dll	: 1.1.0.0
SRSTSH64.dll	: 1.1.4.0
SRSTX64.dll	: 3.2.0.0
SRSWOW64.dll	: 1.1.3.0
WavesGUILib.dll	: 1.2.3.4

HDM Driver :	
Vista/WIn7 x86:	
RtHDMV.sys	: 6.0.1.5945
RtkAudioSrvATI.exe	: 1.0.0.23
RtkUpd.exe	: 2.8.0.0
RH3DAA32.dll	: 6.0.6001.18
RH3DHT32.dll	: 6.0.6001.18
RHCoInst.dll	: 1.0.7.0

Readme.txt

RHDMExt.dll : 6.0.6000.100
 RtkHDM.dll : 11.0.6000.113

Vista/Win7 x64:

RtHDMVX.sys : 6.0.1.5945
 RtkAudioSrvATI64.exe : 1.0.0.23
 RtkUpd64.exe : 2.8.0.0
 RH3DAA64.dll : 6.0.6001.18
 RH3DHT64.dll : 6.0.6001.18
 RHCoInst64.dll : 1.0.7.0
 RHDMEx64.dll : 6.0.6000.100
 RtkHDM64.dll : 11.0.6000.113

XP/2K x86:

RtkHDM.sys : 5.10.0.5945
 Rtaupd.exe : 2.8.0.0
 RHCoInstXP.dll : 1.0.7.0

XP/2K x64:

RtkHDMX.sys : 5.10.0.5945
 Rtaupd64.exe : 2.8.0.0
 RHCoInst64XP.dll : 1.0.7.0

Driver Setup Program

: 2.89

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111
 Package file version (kb888111.exe) : 6.1.22.0
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.37

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC892, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC660, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC892, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008,

Windows7 - x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :

RTKHDA64.sys : 5.10.0.5983
 RTKHDAUD.sys : 5.10.0.5983
 MicCal.exe : 1.1.2.2
 RTHDCPL.exe : 2.3.2.4
 RtkAudioService64.exe : 1.0.0.19
 RtkAudioService.exe : 1.0.0.19
 RTLCPL.exe : 1.0.1.66
 RtlUpd64.exe : 2.8.0.0
 RtlUpd.exe : 2.8.0.0
 SkyTel.exe : 2.0.2.0
 SoundMan.exe : 1.0.0.32
 vncutil64.exe : 1.0.0.37
 vncutil.exe : 1.0.0.37
 Alcmtr.exe : 1.6.0.4
 AlcWzrd.exe : 1.1.0.37
 ANBFt64.sys : 5.10.0.4240
 Mbnfilt.sys : 5.10.0.4112
 Mbnft64.sys : 5.10.0.4115
 OA017Afx.sys : 1.0.7.3
 ANBFilt.sys : 5.10.0.4240

	Readme.txt	
RTSndMgr.cpl	:	1.0.1.4
ALSndMgr.cpl	:	1.0.0.11
RCoInst64XP.dll	:	1.0.7.6
RTCOMDLL.dll	:	1.0.0.103
RtkCoInstXP.dll	:	1.0.7.6
RtICPAPI.dll	:	1.0.2.3
Vista/Win7 driver : -----		
Vista/Win7 driver for x86		
RTKVHDA.sys	:	6.0.1.5983
AERTSrv.exe	:	1.0.32.9
APOPCH.exe	:	1.0.0.0
RtHDVBg.exe	:	1.0.0.6
RtHDVCpl.exe	:	1.0.0.447
RtkAudioService.exe	:	1.0.0.24
RtlUpd.exe	:	2.8.0.0
SkyTel.exe	:	2.0.2.2
vncutil.exe	:	1.0.0.37
mbfilt32.sys	:	6.10.0.8
RTSndMgr.cpl	:	1.0.0.17
AERTACap.dll	:	2.0.32.8
AERTARen.dll	:	1.0.32.8
FMAPO.dll	:	42.5.21.66
MaxxAudioAPO.dll	:	1.2.2.0
MaxxAudioAPO20.dll	:	2.2.6.0
MaxxAudioEQ.dll	:	5.9.7.0
MBAP032.dll	:	1.0.19.0
MBPPCn32.dll	:	1.0.0.110
MBpld32.dll	:	1.0.22.0
MBTHX32.dll	:	1.0.8.107
MBWrp32.dll	:	1.0.0.110
RP3DAA32.dll	:	6.0.6001.18
RP3DHT32.dll	:	6.0.6001.18
RTCOMDLL.dll	:	2.0.0.123
RTEED32A.dll	:	6.1.6001.32
RTEEG32A.dll	:	6.1.6001.32
RTEEL32A.dll	:	6.1.6001.32
RTEEP32A.dll	:	6.1.6001.32
RtkAPO.dll	:	11.0.6000.125
RtkApoApi.dll	:	1.0.0.15
RtkCfg.dll	:	1.0.0.2
RtkCoInst.dll	:	1.0.7.6
RtkPgExt.dll	:	6.0.6000.108
RtICPAPI.dll	:	1.0.2.4
SFFXComm.dll	:	2.0.0.8
SFFXDAP0.dll	:	2.0.0.8
SFFXHAP0.dll	:	2.0.0.8
SFFXProc.dll	:	2.0.0.8
SFFXSAP0.dll	:	2.0.0.8
slcshp32.dll	:	1.0.3.0
slgeq32.dll	:	1.0.1.0
slh36032.dll	:	1.0.2.0
slInit32.dll	:	1.1.3.0
slmaxv32.dll	:	1.1.2.0
sltshd32.dll	:	1.1.1.0
sluapo32.dll	:	1.8.22.0
SRSHP360.dll	:	1.1.0.0
SRSTSHD.dll	:	1.1.4.0
SRSTSXT.dll	:	3.2.0.0
SRSWOW.dll	:	1.1.3.0
WavesLib.dll	:	5.9.7.0
Vista/Win7 driver for x64		
RTKVHD64.sys	:	6.0.1.5983
AERTSr64.exe	:	1.0.64.9
APOPCH.exe	:	1.0.0.0
RAVBg64.exe	:	1.0.0.6
RAVCpl64.exe	:	1.0.0.447
RtkAudioService64.exe	:	1.0.0.24
RtlUpd64.exe	:	2.8.0.0
SkyTel.exe	:	2.0.2.2

Readme.txt

```

vncutil64.exe : 1.0.0.37
GWfilt64.sys : 6.10.0.3
mbfilt64.sys : 6.10.0.8
RTSnMg64.cpl : 1.0.0.17
AERTAC64.dll : 2.0.64.8
AERTAR64.dll : 1.0.64.8
FNAP064.dll : 42.6.21.66
MaxxAudioAP020.dll : 2.2.6.0
MaxxAudioEQ.dll : 5.9.7.0
MBAP032.dll : 1.0.19.0
MBAP064.dll : 1.0.19.0
MBPPCn64.dll : 1.0.0.110
Mbppld64.dll : 1.0.22.0
MBTHX32.dll : 1.0.8.107
MBTHX64.dll : 1.0.8.107
MBWrp64.dll : 1.0.0.110
RCoInst64.dll : 1.0.7.6
RP3DAA64.dll : 6.0.6001.18
RP3DHT64.dll : 6.0.6001.18
RtCOMB4.dll : 2.0.0.123
RtCOMDLL.dll : 2.0.0.123
RTEED64A.dll : 6.1.6001.32
RTEEG64A.dll : 6.1.6001.32
RTEEL64A.dll : 6.1.6001.32
RTEEP64A.dll : 6.1.6001.32
RtkApi64.dll : 1.0.0.15
RtkAP064.dll : 11.0.6000.125
RtkCfg.dll : 1.0.0.1
RtkCfg64.dll : 1.0.0.2
RtlCPAPI.dll : 1.0.2.4
RtlCPAPI64.dll : 1.0.2.4
RtPgEx64.dll : 6.0.6000.108
SFComm64.dll : 2.0.0.8
SFDAP064.dll : 2.0.0.8
SFHAP064.dll : 2.0.0.8
SFProc64.dll : 2.0.0.8
SFSAP064.dll : 2.0.0.8
slcshp64.dll : 1.0.3.0
slgeq64.dll : 1.0.1.0
slh36064.dll : 1.0.2.0
slInit64.dll : 1.1.3.0
slmaxv64.dll : 1.1.2.0
sltshd64.dll : 1.1.1.0
sluapo64.dll : 1.8.22.0
SRSHP64.dll : 1.1.0.0
SRSTSH64.dll : 1.1.4.0
SRSTX64.dll : 3.2.0.0
SRSWW64.dll : 1.1.3.0
WavesGUILib.dll : 1.2.3.4
-----
HDM Driver :
Vista/Win7 x86:
RtHDMV.sys : 6.0.1.5945
RtkAudioSrvATI.exe : 1.0.0.23
RtkUpd.exe : 2.8.0.0
RH3DAA32.dll : 6.0.6001.18
RH3DHT32.dll : 6.0.6001.18
RHCoInst.dll : 1.0.7.0
RHDMExt.dll : 6.0.6000.100
RtkHDM.dll : 11.0.6000.113

Vista/Win7 x64:
RtHDMVX.sys : 6.0.1.5945
RtkAudioSrvATI64.exe : 1.0.0.23
RtkUpd64.exe : 2.8.0.0
RH3DAA64.dll : 6.0.6001.18
RH3DHT64.dll : 6.0.6001.18
RHCoInst64.dll : 1.0.7.0
RHDMEx64.dll : 6.0.6000.100
RtkHDM64.dll : 11.0.6000.113

```

Readme.txt

XP/2K x86:
RtkHDM.sys : 5.10.0.5945
Rtaupd.exe : 2.8.0.0
RHCoInstXP.dll : 1.0.7.0

XP/2K x64:
RtkHDMX.sys : 5.10.0.5945
Rtaupd64.exe : 2.8.0.0
RHCoInst64XP.dll : 1.0.7.0

Driver Setup Program : 2.88

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.36

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275

3. HDM Device WHQL Support: ATI HDM Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 - x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

2.) Package :

1. Fix some presentation string of Upgraded dialog in small VGA Mode .

Windows 2000/XP : -----

Windows 2000/XP :

RTKHDA64.sys : 5.10.0.5969
RTKHDAUD.sys : 5.10.0.5969
Alcmtr.exe : 1.6.0.4
AlcWzrd.exe : 1.1.0.37
MicCal.exe : 1.1.2.2
RTHDCPL.exe : 2.3.2.1
RtkAudioService64.exe : 1.0.0.19
RtkAudioService.exe : 1.0.0.19
RTLCPPL.exe : 1.0.1.66
RtlUpd64.exe : 2.8.0.0
RtlUpd.exe : 2.8.0.0
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.32
vncutil64.exe : 1.0.0.33
vncutil.exe : 1.0.0.33
AMBfilt.sys : 5.10.0.4240
AMBft64.sys : 5.10.0.4240
Mnft64.sys : 5.10.0.4112
Mnft64.sys : 5.10.0.4115
ALSndMgr.cpl : 1.0.0.11
RTSndMgr.cpl : 1.0.1.4
RCoInst64XP.dll : 1.0.7.5
RtCOMDLL.dll : 1.0.0.103
RtkCoInstXP.dll : 1.0.7.5
RtlCPAPI.dll : 1.0.2.3

Vista/Wn7 driver : -----

Vista/Wn7 driver for x86

RTKVHDA.sys : 6.0.1.5969
AERTSrv.exe : 1.0.32.9
APOPCH.exe : 1.0.0.0

	Readme.txt	
RtHdVBg.exe	:	1.0.0.6
RtHdVCpl.exe	:	1.0.0.439
RtkAudioService.exe	:	1.0.0.24
RtlUpd.exe	:	2.8.0.0
SkyTel.exe	:	2.0.2.2
vncutil.exe	:	1.0.0.33
mbfilt32.sys	:	6.10.0.8
RTSndMgr.cpl	:	1.0.0.17
AERTACap.dll	:	2.0.32.8
AERTARen.dll	:	1.0.32.8
FMAP0.dll	:	42.5.21.65
MaxxAudioAP0.dll	:	1.2.2.0
MaxxAudioAP020.dll	:	2.2.6.0
MaxxAudioEQ.dll	:	5.9.7.0
MBAP032.dll	:	1.0.19.0
MBPPCn32.dll	:	1.0.0.110
MBpld32.dll	:	1.0.22.0
MBTHX32.dll	:	1.0.8.107
MBWrp32.dll	:	1.0.0.110
RP3DAA32.dll	:	6.0.6001.18
RP3DHT32.dll	:	6.0.6001.18
RTCOMDLL.dll	:	2.0.0.121
RTEED32A.dll	:	6.1.6001.29
RTEEG32A.dll	:	6.1.6001.29
RTEEL32A.dll	:	6.1.6001.29
RTEEP32A.dll	:	6.1.6001.29
RtkAP0.dll	:	11.0.6000.121
RtkApoApi.dll	:	1.0.0.13
RtkCfg.dll	:	1.0.0.1
RtkCoInst.dll	:	1.0.7.5
RtkPgExt.dll	:	6.0.6000.108
RtlCPAPI.dll	:	1.0.2.4
SFFXComm.dll	:	2.0.0.8
SFFXDAP0.dll	:	2.0.0.8
SFFXHAP0.dll	:	2.0.0.8
SFFXProc.dll	:	2.0.0.8
SFFXSAP0.dll	:	2.0.0.8
slcshp32.dll	:	1.0.3.0
slgeq32.dll	:	1.0.1.0
slh36032.dll	:	1.0.2.0
slInit32.dll	:	1.1.3.0
slmaxv32.dll	:	1.1.2.0
sltshd32.dll	:	1.1.1.0
sluapo32.dll	:	1.4.8.0
SRSHP360.dll	:	1.1.0.0
SRSTSHD.dll	:	1.1.4.0
SRSTSXT.dll	:	3.2.0.0
SRSWOW.dll	:	1.1.3.0
WavesLib.dll	:	5.9.7.0
Vista/Win7 driver for x64		
RTKVHD64.sys	:	6.0.1.5969
AERTSr64.exe	:	1.0.64.9
APOPCH.exe	:	1.0.0.0
RAVBg64.exe	:	1.0.0.6
RAVCpl64.exe	:	1.0.0.439
RtkAudioService64.exe	:	1.0.0.24
RtlUpd64.exe	:	2.8.0.0
SkyTel.exe	:	2.0.2.2
vncutil64.exe	:	1.0.0.33
GWfilt64.sys	:	6.10.0.3
mbfilt64.sys	:	6.10.0.8
RTSnMg64.cpl	:	1.0.0.17
AERTAC64.dll	:	2.0.64.8
AERTAR64.dll	:	1.0.64.8
FMAP064.dll	:	42.6.21.65
MaxxAudioAP020.dll	:	2.2.6.0
MBAP032.dll	:	1.0.19.0
MBAP064.dll	:	1.0.19.0
MBPPCn64.dll	:	1.0.0.110

	Readme.txt	
Mbpld64.dll		: 1.0.22.0
MBTHX32.dll		: 1.0.8.107
MBTHX64.dll		: 1.0.8.107
MBWrp64.dll		: 1.0.0.110
RCoInst64.dll		: 1.0.7.5
RP3DAA64.dll		: 6.0.6001.18
RP3DHT64.dll		: 6.0.6001.18
RtCOMB4.dll		: 2.0.0.121
RTCOMDLL.dll		: 2.0.0.121
RTEED64A.dll		: 6.1.6001.29
RTEEG64A.dll		: 6.1.6001.29
RTEEL64A.dll		: 6.1.6001.29
RTEEP64A.dll		: 6.1.6001.29
RtkApi64.dll		: 1.0.0.13
RtkAPO64.dll		: 11.0.6000.121
RtkCfg.dll		: 1.0.0.1
RtkCfg64.dll		: 1.0.0.1
RtlCPAPI.dll		: 1.0.2.4
RtlCPAPI64.dll		: 1.0.2.4
RtPgEx64.dll		: 6.0.6000.108
SFComm64.dll		: 2.0.0.8
SFDAP064.dll		: 2.0.0.8
SFHAP064.dll		: 2.0.0.8
SFProc64.dll		: 2.0.0.8
SFSAP064.dll		: 2.0.0.8
slcshp64.dll		: 1.0.3.0
slgeq64.dll		: 1.0.1.0
slh36064.dll		: 1.0.2.0
slInit64.dll		: 1.1.3.0
slmaxv64.dll		: 1.1.2.0
sltshd64.dll		: 1.1.1.0
sluapo64.dll		: 1.4.8.0
SRSHP64.dll		: 1.1.0.0
SRSTSH64.dll		: 1.1.4.0
SRSTSX64.dll		: 3.2.0.0
SRSWOW64.dll		: 1.1.3.0
HDM Driver : -----		
Vista/Win7 x86:		
RtHDMV.sys		: 6.0.1.5945
RtkAudioSrvATI.exe		: 1.0.0.23
RtkUpd.exe		: 2.8.0.0
RH3DAA32.dll		: 6.0.6001.18
RH3DHT32.dll		: 6.0.6001.18
RHCoInst.dll		: 1.0.7.0
RHDMExt.dll		: 6.0.6000.100
RtkHDM.dll		: 11.0.6000.113
Vista/Win7 x64:		
RtHDMVX.sys		: 6.0.1.5945
RtkAudioSrvATI64.exe		: 1.0.0.23
RtkUpd64.exe		: 2.8.0.0
RH3DAA64.dll		: 6.0.6001.18
RH3DHT64.dll		: 6.0.6001.18
RHCoInst64.dll		: 1.0.7.0
RHDMEx64.dll		: 6.0.6000.100
RtkHDM64.dll		: 11.0.6000.113
XP/2K x86:		
RtkHDM.sys		: 5.10.0.5945
Rtaupd.exe		: 2.8.0.0
RHCoInstXP.dll		: 1.0.7.0
XP/2K x64:		
RtkHDMX.sys		: 5.10.0.5945
Rtaupd64.exe		: 2.8.0.0
RHCoInst64XP.dll		: 1.0.7.0
Driver Setup Program		: 2.86

Readme.txt

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.35

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275

3. HDM Device WHQL Support: ATI HDM Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008,

Windows7 - x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

2.) Package :

1. Fix some presentation of Spanish language .

2. Add "Windows Server 2008 x64 R2" identification folder.

Windows 2000/XP : -----

Windows 2000/XP :

RTKHDA64.sys	: 5.10.0.5953
RTKHDAUD.sys	: 5.10.0.5953
Alcmtr.exe	: 1.6.0.4
AlcWzrd.exe	: 1.1.0.37
McCal.exe	: 1.1.2.2
RTHDCPL.exe	: 2.3.1.8
RtkAudioService64.exe	: 1.0.0.19
RtkAudioService.exe	: 1.0.0.19
RTLCPPL.exe	: 1.0.1.66
RtlUpd64.exe	: 2.8.0.0
RtlUpd.exe	: 2.8.0.0
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.32
vncutil64.exe	: 1.0.0.32
vncutil.exe	: 1.0.0.32
AMBFilt.sys	: 5.10.0.4240
AMBFt64.sys	: 5.10.0.4240
Mnft64.sys	: 5.10.0.4112
Mnft64.sys	: 5.10.0.4115
ALSndMgr.cpl	: 1.0.0.11
RTSndMgr.cpl	: 1.0.1.4
RCoInst64XP.dll	: 1.0.7.0
RTCOMDLL.dll	: 1.0.0.103
RtkCoInstXP.dll	: 1.0.7.0
RtlCPAPI.dll	: 1.0.2.3

Vista/Win7 driver : -----

Vista/Win7 driver for x86

RTKVHDA.sys	: 6.0.1.5953
AERTSrv.exe	: 1.0.32.9
APOPCH.exe	: 1.0.0.0
RtHDVBg.exe	: 1.0.0.6
RtHDVCpl.exe	: 1.0.0.426
RtkAudioService.exe	: 1.0.0.24
RtlUpd.exe	: 2.8.0.0
SkyTel.exe	: 2.0.2.2
vncutil.exe	: 1.0.0.32
mbfilt32.sys	: 6.10.0.8
RTSndMgr.cpl	: 1.0.0.17
AERTACap.dll	: 2.0.32.8
AERTARen.dll	: 1.0.32.8
FMAPO.dll	: 42.5.19.65
MaxxAudioAPO.dll	: 1.2.2.0

	Readme.txt	: 2.2.6.0
MaxxAudioAP020.dll		: 5.9.7.0
MaxxAudioEQ.dll		: 1.0.19.0
MBAP032.dll		: 1.0.0.110
MBPPCn32.dll		: 1.0.22.0
Mbpld32.dll		: 1.0.8.103
MBTHX32.dll		: 1.0.0.110
MBWrp32.dll		: 6.0.6001.18
RP3DAA32.dll		: 6.0.6001.18
RP3DHT32.dll		: 2.0.0.120
RTCOMDLL.dll		: 6.1.6001.29
RTEED32A.dll		: 6.1.6001.29
RTEEG32A.dll		: 6.1.6001.29
RTEEL32A.dll		: 6.1.6001.29
RTEEP32A.dll		: 6.1.6001.29
RtkAPO.dll		: 11.0.6000.116
RtkApoApi.dll		: 1.0.0.13
RtkCfg.dll		: 1.0.0.1
RtkCoInst.dll		: 1.0.7.1
RtkPgExt.dll		: 6.0.6000.103
RtLCPAPI.dll		: 1.0.2.4
SFFXComm.dll		: 2.0.0.8
SFFXDAP0.dll		: 2.0.0.8
SFFXHAP0.dll		: 2.0.0.8
SFFXProc.dll		: 2.0.0.8
SFFXSAP0.dll		: 2.0.0.8
slcshp32.dll		: 1.0.3.0
slgeq32.dll		: 1.0.1.0
slh36032.dll		: 1.0.2.0
slInit32.dll		: 1.1.3.0
slmaxv32.dll		: 1.1.2.0
sltshd32.dll		: 1.1.1.0
sluapo32.dll		: 1.4.8.0
SRSHP360.dll		: 1.1.0.0
SRSTSHD.dll		: 1.1.4.0
SRSTSXT.dll		: 3.2.0.0
SRSWOW.dll		: 1.1.3.0
WavesLib.dll		: 5.9.7.0
Vista/Win7 driver for x64		
RTKVHD64.sys		: 6.0.1.5953
AERTSr64.exe		: 1.0.64.9
APOPCH.exe		: 1.0.0.0
RAVBg64.exe		: 1.0.0.6
RAVCpl64.exe		: 1.0.0.426
RtkAudioService64.exe		: 1.0.0.24
RtlUpd64.exe		: 2.8.0.0
SkyTel.exe		: 2.0.2.2
vncutil64.exe		: 1.0.0.32
GWfilt64.sys		: 6.10.0.3
mbfilt64.sys		: 6.10.0.8
RTSnMg64.cpl		: 1.0.0.17
AERTAC64.dll		: 2.0.64.8
AERTAR64.dll		: 1.0.64.8
FMAP064.dll		: 42.6.19.65
MaxxAudioAP020.dll		: 2.2.6.0
MBAP032.dll		: 1.0.19.0
MBAP064.dll		: 1.0.19.0
MBPPCn64.dll		: 1.0.0.110
Mbpld64.dll		: 1.0.22.0
MBTHX32.dll		: 1.0.8.103
MBTHX64.dll		: 1.0.8.103
MBWrp64.dll		: 1.0.0.110
RCoInst64.dll		: 1.0.7.1
RP3DAA64.dll		: 6.0.6001.18
RP3DHT64.dll		: 6.0.6001.18
RtCOM64.dll		: 2.0.0.120
RTCOMDLL.dll		: 2.0.0.120
RTEED64A.dll		: 6.1.6001.29
RTEEG64A.dll		: 6.1.6001.29
RTEEL64A.dll		: 6.1.6001.29

Readme.txt

RTEEP64A.dll : 6.1.6001.29
 RtkApi64.dll : 1.0.0.13
 RtkAPO64.dll : 11.0.6000.116
 RtkCfg.dll : 1.0.0.1
 RtkCfg64.dll : 1.0.0.1
 RtlCPAPI.dll : 1.0.2.4
 RtlCPAPI64.dll : 1.0.2.4
 RtlPgEx64.dll : 6.0.6000.103
 SFComm64.dll : 2.0.0.8
 SFDAP064.dll : 2.0.0.8
 SFHAP064.dll : 2.0.0.8
 SFProc64.dll : 2.0.0.8
 SFSAP064.dll : 2.0.0.8
 slcshp64.dll : 1.0.3.0
 slgeq64.dll : 1.0.1.0
 slh36064.dll : 1.0.2.0
 slInit64.dll : 1.1.3.0
 slmaxv64.dll : 1.1.2.0
 sltshd64.dll : 1.1.1.0
 sluapo64.dll : 1.4.8.0
 SRSHP64.dll : 1.1.0.0
 SRSTSH64.dll : 1.1.4.0
 SRSTSX64.dll : 3.2.0.0
 SRSWOW64.dll : 1.1.3.0

 HDM Driver :

Vista/Win7 x86:

RtHDMV.sys : 6.0.1.5945
 RtkAudioSrvATI.exe : 1.0.0.23
 RtkUpd.exe : 2.8.0.0
 RH3DAA32.dll : 6.0.6001.18
 RH3DHT32.dll : 6.0.6001.18
 RHCoInst.dll : 1.0.7.0
 RHDMExt.dll : 6.0.6000.100
 RtkHDM.dll : 11.0.6000.113

Vista/Win7 x64:

RtHDMVX.sys : 6.0.1.5945
 RtkAudioSrvATI64.exe : 1.0.0.23
 RtkUpd64.exe : 2.8.0.0
 RH3DAA64.dll : 6.0.6001.18
 RH3DHT64.dll : 6.0.6001.18
 RHCoInst64.dll : 1.0.7.0
 RHDMEx64.dll : 6.0.6000.100
 RtkHDM64.dll : 11.0.6000.113

XP/2K x86:

RtkHDM.sys : 5.10.0.5945
 Rtaupd.exe : 2.8.0.0
 RHCoInstXP.dll : 1.0.7.0

XP/2K x64:

RtkHDMX.sys : 5.10.0.5945
 Rtaupd64.exe : 2.8.0.0
 RHCoInst64XP.dll : 1.0.7.0

Driver Setup Program : 2.85

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111
 Package file version (kb888111.exe) : 6.1.22.0
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.34

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273,

Readme.txt

ALC887, ALC670, ALC275

3. HDM Device WHQL Support: ATI HDM Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 - x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :

RTKHDA64.sys	: 5.10.0.5943
RTKHDAUD.sys	: 5.10.0.5943
MicCal.exe	: 1.1.2.2
RTHDCPL.exe	: 2.3.1.4
RtkAudioService64.exe	: 1.0.0.19
RtkAudioService.exe	: 1.0.0.19
RTLCPPL.exe	: 1.0.1.66
RtlUpd64.exe	: 2.8.0.0
RtlUpd.exe	: 2.8.0.0
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.32
vncutil64.exe	: 1.0.0.31
vncutil.exe	: 1.0.0.31
Alcmtr.exe	: 1.6.0.4
AlcWzrd.exe	: 1.1.0.37
Mnfilt.sys	: 5.10.0.4112
Mnft64.sys	: 5.10.0.4115
AMBFilt.sys	: 5.10.0.4240
AMBFt64.sys	: 5.10.0.4240
RTSndMgr.cpl	: 1.0.1.4
ALSndMgr.cpl	: 1.0.0.11
RCoInst64XP.dll	: 1.0.7.0
RTCOMDLL.dll	: 1.0.0.103
RtkCoInstXP.dll	: 1.0.7.0
RtlCPAPI.dll	: 1.0.2.3

Vista/Wn7 driver : -----

Vista/Wn7 driver for x86

RTKVHDA.sys	: 6.0.1.5943
AERTSrv.exe	: 1.0.32.9
APOPCH.exe	: 1.0.0.0
RtHDVBg.exe	: 1.0.0.6
RtHDVCpl.exe	: 1.0.0.422
RtkAudioService.exe	: 1.0.0.24
RtlUpd.exe	: 2.8.0.0
SkyTel.exe	: 2.0.2.2
vncutil.exe	: 1.0.0.31
mbfilt32.sys	: 6.10.0.8
RTSndMgr.cpl	: 1.0.0.17
AERTACap.dll	: 2.0.32.8
AERTARen.dll	: 1.0.32.8
FMAPO.dll	: 42.5.18.67
MaxxAudioAPO.dll	: 1.2.2.0
MaxxAudioAPO20.dll	: 2.2.6.0
MaxxAudioEQ.dll	: 5.9.7.0
MBAP032.dll	: 1.0.19.0
MBPPCn32.dll	: 1.0.0.110
MBpld32.dll	: 1.0.19.0
MBTHX32.dll	: 1.0.8.102
MBWrp32.dll	: 1.0.0.110
RP3DAA32.dll	: 6.0.6001.18
RP3DHT32.dll	: 6.0.6001.18
RTCOMDLL.dll	: 2.0.0.120
RTEED32A.dll	: 6.1.6001.29
RTEEG32A.dll	: 6.1.6001.29
RTEEL32A.dll	: 6.1.6001.29
RTEEP32A.dll	: 6.1.6001.29
RtkAPO.dll	: 11.0.6000.113
RtkApoApi.dll	: 1.0.0.13

	Readme.txt	
RtkCfg.dll	:	1.0.0.1
RtkCoInst.dll	:	1.0.7.0
RtkPgExt.dll	:	6.0.6000.99
RtLCPAPI.dll	:	1.0.2.4
SFFXComm.dll	:	2.0.0.8
SFFXDAP0.dll	:	2.0.0.8
SFFXHAP0.dll	:	2.0.0.8
SFFXProc.dll	:	2.0.0.8
SFFXSAP0.dll	:	2.0.0.8
slcshp32.dll	:	1.0.3.0
slgeq32.dll	:	1.0.1.0
slh36032.dll	:	1.0.2.0
slInit32.dll	:	1.1.3.0
slmaxv32.dll	:	1.1.2.0
sltshd32.dll	:	1.1.1.0
sluapo32.dll	:	1.4.8.0
SRSH360.dll	:	1.1.0.0
SRSTSHD.dll	:	1.1.4.0
SRSTSXT.dll	:	3.2.0.0
SRSWOW.dll	:	1.1.3.0
WavesLib.dll	:	5.9.7.0
Vista/Win7 driver for x64		
RTKVHD64.sys	:	6.0.1.5943
AERTSr64.exe	:	1.0.64.9
APOPCH.exe	:	1.0.0.0
RAVBg64.exe	:	1.0.0.6
RAVCpl64.exe	:	1.0.0.422
RtkAudioService64.exe	:	1.0.0.24
RtlUpd64.exe	:	2.8.0.0
SkyTel.exe	:	2.0.2.2
vncutil64.exe	:	1.0.0.31
GWfilt64.sys	:	6.10.0.3
mbfilt64.sys	:	6.10.0.8
RTSnMg64.cpl	:	1.0.0.17
AERTAC64.dll	:	2.0.64.8
AERTAR64.dll	:	1.0.64.8
FMAP064.dll	:	42.6.18.67
MaxxAudioAP020.dll	:	2.2.6.0
MBAP032.dll	:	1.0.19.0
MBAP064.dll	:	1.0.19.0
MBPPCn64.dll	:	1.0.0.110
MBpld64.dll	:	1.0.19.0
MBTHX32.dll	:	1.0.8.102
MBTHX64.dll	:	1.0.8.102
MBWrp64.dll	:	1.0.0.110
RCoInst64.dll	:	1.0.7.0
RP3DAA64.dll	:	6.0.6001.18
RP3DHT64.dll	:	6.0.6001.18
RtCOM64.dll	:	2.0.0.120
RTCOMDLL.dll	:	2.0.0.120
RTEED64A.dll	:	6.1.6001.29
RTEEG64A.dll	:	6.1.6001.29
RTEEL64A.dll	:	6.1.6001.29
RTEEP64A.dll	:	6.1.6001.29
RtkApi64.dll	:	1.0.0.13
RtkAP064.dll	:	11.0.6000.113
RtkCfg.dll	:	1.0.0.1
RtkCfg64.dll	:	1.0.0.1
RtLCPAPI.dll	:	1.0.2.4
RtLCPAPI64.dll	:	1.0.2.4
RtPgEx64.dll	:	6.0.6000.99
SFComm64.dll	:	2.0.0.8
SFDAP064.dll	:	2.0.0.8
SFHAP064.dll	:	2.0.0.8
SFProc64.dll	:	2.0.0.8
SFSAP064.dll	:	2.0.0.8
slcshp64.dll	:	1.0.3.0
slgeq64.dll	:	1.0.1.0
slh36064.dll	:	1.0.2.0

Readme.txt

slInit64.dll : 1.1.3.0
 slmaxv64.dll : 1.1.2.0
 sltshd64.dll : 1.1.1.0
 sluapo64.dll : 1.4.8.0
 SRSHp64.dll : 1.1.0.0
 SRSTSH64.dll : 1.1.4.0
 SRSTSX64.dll : 3.2.0.0
 SRSWOW64.dll : 1.1.3.0

HDMI Driver : -----
 Vista/Win7 x86:
 RtHDMV.sys : 6.0.1.5897
 RtkAudioSrvATI.exe : 1.0.0.23
 RtkUpd.exe : 2.8.0.0
 RH3DAA32.dll : 6.0.6001.18
 RH3DHT32.dll : 6.0.6001.18
 RHCoInst.dll : 1.0.6.4
 RHDMEExt.dll : 6.0.6000.82
 RtkHDM.dll : 11.0.6000.101

Vista/Win7 x64:
 RtHDMVX.sys : 6.0.1.5897
 RtkAudioSrvATI64.exe : 1.0.0.23
 RtkUpd64.exe : 2.8.0.0
 RH3DAA64.dll : 6.0.6001.18
 RH3DHT64.dll : 6.0.6001.18
 RHCoInst64.dll : 1.0.6.4
 RHDME64.dll : 6.0.6000.82
 RtkHDM64.dll : 11.0.6000.101

XP/2K x86:
 RtkHDM.sys : 5.10.0.5880
 RtkUpd.exe : 2.7.1.3
 RHCoInstXP.dll : 1.0.5.1
 XP/2K x64:
 RtkHDMX.sys : 5.10.0.5880
 RtkUpd64.exe : 2.7.1.3
 RHCoInst64XP.dll : 1.0.5.1

Driver Setup Program : 2.84

Windows 2000/XP Operate on :
 Microsoft High Definition Audio Driver Package - KB888111
 Package file version (kb888111.exe) : 6.1.22.0
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.33

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887, ALC670, ALC275

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887, ALC670, ALC275

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 - x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :
 RTKHDA64.sys : 5.10.0.5936
 RTKHDAUD.sys : 5.10.0.5936
 McCal.exe : 1.1.2.2
 RTHDCPL.exe : 2.3.1.2

```

Readme.txt
RtkAudioService64.exe : 1.0.0.19
RtkAudioService.exe : 1.0.0.19
RTLCP.L.exe : 1.0.1.66
RtlUpd64.exe : 2.8.0.0
RtlUpd.exe : 2.8.0.0
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.32
vncutil64.exe : 1.0.0.29
vncutil.exe : 1.0.0.29
Alcmtr.exe : 1.6.0.4
AlcWzrd.exe : 1.1.0.37
Mbnfilt.sys : 5.10.0.4112
Mbnft64.sys : 5.10.0.4115
AMBfilt.sys : 5.10.0.4240
AMBft64.sys : 5.10.0.4240
RTSndMgr.cpl : 1.0.1.4
ALSndMgr.cpl : 1.0.0.11
RCoInst64XP.dll : 1.0.6.9
RTCOMDLL.dll : 1.0.0.103
RtkCoInstXP.dll : 1.0.6.9
RtlCPAPI.dll : 1.0.2.3
Vista/Win7 driver : -----
Vista/Win7 driver for x86
RTKVHDA.sys : 6.0.1.5936
AERTSrv.exe : 1.0.32.9
APOPCH.exe : 1.0.0.0
RtHDVBg.exe : 1.0.0.6
RtHDVCpl.exe : 1.0.0.418
RtkAudioService.exe : 1.0.0.24
RtlUpd.exe : 2.8.0.0
SkyTel.exe : 2.0.2.2
vncutil.exe : 1.0.0.29
RTSndMgr.cpl : 1.0.0.17
mbfilt32.sys : 6.10.0.8
AERTACap.dll : 2.0.32.8
AERTARen.dll : 1.0.32.8
FMAPO.dll : 42.5.18.65
MaxxAudioAPO.dll : 1.2.2.0
MaxxAudioAPO20.dll : 2.2.6.0
MaxxAudioEQ.dll : 5.9.7.0
MBAPO32.dll : 1.0.19.0
MBPPCn32.dll : 1.0.0.110
Mbppld32.dll : 1.0.19.0
MBTHX32.dll : 1.0.8.102
MBWrp32.dll : 1.0.0.110
RP3DAA32.dll : 6.0.6001.18
RP3DHT32.dll : 6.0.6001.18
RTCOMDLL.dll : 2.0.0.120
RTEED32A.dll : 6.1.6001.29
RTEEG32A.dll : 6.1.6001.29
RTEEL32A.dll : 6.1.6001.29
RTEEP32A.dll : 6.1.6001.29
RtkAPO.dll : 11.0.6000.109
RtkApoApi.dll : 1.0.0.13
RtkCfg.dll : 1.0.0.1
RtkCoInst.dll : 1.0.6.9
RtkPgExt.dll : 6.0.6000.96
RtlCPAPI.dll : 1.0.2.4
SFFXComm.dll : 2.0.0.8
SFFXDAP0.dll : 2.0.0.8
SFFXHAP0.dll : 2.0.0.8
SFFXProc.dll : 2.0.0.8
SFFXSAP0.dll : 2.0.0.8
slcshp32.dll : 1.0.3.0
slgeq32.dll : 1.0.1.0
slh36032.dll : 1.0.2.0
slInit32.dll : 1.1.3.0
slmaxv32.dll : 1.1.2.0
sltshd32.dll : 1.1.1.0

```

Readme.txt

sluapo32.dll	: 1.4.8.0
SRSHP360.dll	: 1.1.0.0
SRSTSHD.dll	: 1.1.4.0
SRSTSXT.dll	: 3.2.0.0
SRSWOW.dll	: 1.1.3.0
WavesLib.dll	: 5.9.7.0
Vista/Win7 driver for x64	
RTKVHD64.sys	: 6.0.1.5936
AERTSr64.exe	: 1.0.64.9
APOPCH.exe	: 1.0.0.0
RAVBg64.exe	: 1.0.0.6
RAVCpl64.exe	: 1.0.0.418
RtkAudioService64.exe	: 1.0.0.24
RtlUpd64.exe	: 2.8.0.0
SkyTel.exe	: 2.0.2.2
vncutil64.exe	: 1.0.0.29
GWfilt64.sys	: 6.10.0.3
mbfilt64.sys	: 6.10.0.8
RTSnMg64.cpl	: 1.0.0.17
AERTAC64.dll	: 2.0.64.8
AERTAR64.dll	: 1.0.64.8
FMAP064.dll	: 42.6.18.65
MaxxAudioAP020.dll	: 2.2.6.0
MBAP032.dll	: 1.0.19.0
MBAP064.dll	: 1.0.19.0
MBPPCn64.dll	: 1.0.0.110
Mbpld64.dll	: 1.0.19.0
MBTHX32.dll	: 1.0.8.102
MBTHX64.dll	: 1.0.8.102
MBWrp64.dll	: 1.0.0.110
RCoInst64.dll	: 1.0.6.9
RP3DAA64.dll	: 6.0.6001.18
RP3DHT64.dll	: 6.0.6001.18
RtCOMB4.dll	: 2.0.0.120
RTCOMDLL.dll	: 2.0.0.120
RTEED64A.dll	: 6.1.6001.29
RTEEG64A.dll	: 6.1.6001.29
RTEEL64A.dll	: 6.1.6001.29
RTEEP64A.dll	: 6.1.6001.29
RtkApi64.dll	: 1.0.0.13
RtkAP064.dll	: 11.0.6000.109
RtkCfg.dll	: 1.0.0.1
RtkCfg64.dll	: 1.0.0.1
RtlCPAPI.dll	: 1.0.2.4
RtlCPAPI64.dll	: 1.0.2.4
RtPgEx64.dll	: 6.0.6000.96
SFComm64.dll	: 2.0.0.8
SFDAPO64.dll	: 2.0.0.8
SFHAP064.dll	: 2.0.0.8
SFProc64.dll	: 2.0.0.8
SFSAP064.dll	: 2.0.0.8
slcshp64.dll	: 1.0.3.0
slgeq64.dll	: 1.0.1.0
slh36064.dll	: 1.0.2.0
slInit64.dll	: 1.1.3.0
slmaxv64.dll	: 1.1.2.0
sltshd64.dll	: 1.1.1.0
sluapo64.dll	: 1.4.8.0
SRSHP64.dll	: 1.1.0.0
SRSTSH64.dll	: 1.1.4.0
SRSTSX64.dll	: 3.2.0.0
SRSWOW64.dll	: 1.1.3.0
HDMI Driver : -----	
Vista/Win7 x86:	
RtHDMV.sys	: 6.0.1.5897
RtkAudioSrvATI.exe	: 1.0.0.23
RtkUpd.exe	: 2.8.0.0
RH3DAA32.dll	: 6.0.6001.18
RH3DHT32.dll	: 6.0.6001.18

Readme.txt

RHCoInst.dll : 1.0.6.4
RHDMEExt.dll : 6.0.6000.82
RtkHDM.dll : 11.0.6000.101

Vista/Win7 x64:
RtHDMVX.sys : 6.0.1.5897
RtkAudioSrvATI64.exe : 1.0.0.23
RtkUpd64.exe : 2.8.0.0
RH3DAA64.dll : 6.0.6001.18
RH3DHT64.dll : 6.0.6001.18
RHCoInst64.dll : 1.0.6.4
RHDME64.dll : 6.0.6000.82
RtkHDM64.dll : 11.0.6000.101

XP/2K x86:
RtkHDM.sys : 5.10.0.5880
RtkUpd.exe : 2.7.1.3
RHCoInstXP.dll : 1.0.5.1
XP/2K x64:
RtkHDMX.sys : 5.10.0.5880
RtkUpd64.exe : 2.7.1.3
RHCoInst64XP.dll : 1.0.5.1

Driver Setup Program : 2.84

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.32

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887, ALC670, ALC275

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887, ALC670, ALC275

3. HDM Device WHQL Support: ATI HDM Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 - x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :
RTKHDA64.sys : 5.10.0.5928
RTKHDAUD.sys : 5.10.0.5928
McCal.exe : 1.1.2.2
RTHDCPL.exe : 2.3.1.0
RtkAudioService64.exe : 1.0.0.19
RtkAudioService.exe : 1.0.0.19
RTLCPPL.exe : 1.0.1.66
RtlUpd64.exe : 2.8.0.0
RtlUpd.exe : 2.8.0.0
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.32
vncutil64.exe : 1.0.0.27
vncutil.exe : 1.0.0.27
Alcmtr.exe : 1.6.0.4
AlcWzrd.exe : 1.1.0.37
Mnfltl.sys : 5.10.0.4112
Mnft64.sys : 5.10.0.4115
AMBFltl.sys : 5.10.0.4240
AMBft64.sys : 5.10.0.4240

	Readme.txt	
RTSndMgr.cpl	:	1.0.1.4
ALSndMgr.cpl	:	1.0.0.11
RCoInst64XP.dll	:	1.0.6.5
RTCOMDLL.dll	:	1.0.0.103
RtkCoInstXP.dll	:	1.0.6.5
RtlCPAPI.dll	:	1.0.2.3
Vista/Win7 driver : -----		
Vista/Win7 driver for x86		
RTKVHDA.sys	:	6.0.1.5928
AERTSrv.exe	:	1.0.32.9
APOPCH.exe	:	1.0.0.0
RtHDVBg.exe	:	1.0.0.6
RtHDVCpl.exe	:	1.0.0.411
RtkAudioService.exe	:	1.0.0.24
RtlUpd.exe	:	2.8.0.0
SkyTel.exe	:	2.0.2.2
vncutil.exe	:	1.0.0.27
mbfilt32.sys	:	6.10.0.8
RTSndMgr.cpl	:	1.0.0.17
AERTACap.dll	:	2.0.32.8
AERTARen.dll	:	1.0.32.8
FMAPO.dll	:	42.5.17.68
MaxxAudioAPO.dll	:	1.2.2.0
MaxxAudioAPO20.dll	:	2.2.2.0
MaxxAudioEQ.dll	:	5.9.7.0
MBAP032.dll	:	1.0.19.0
MBPPCn32.dll	:	1.0.0.110
MBpld32.dll	:	1.0.19.0
MBTHX32.dll	:	1.0.8.0
MBWrp32.dll	:	1.0.0.110
RP3DAA32.dll	:	6.0.6001.18
RP3DHT32.dll	:	6.0.6001.18
RTCOMDLL.dll	:	2.0.0.119
RTEED32A.dll	:	6.1.6001.29
RTEEG32A.dll	:	6.1.6001.29
RTEEL32A.dll	:	6.1.6001.29
RTEEP32A.dll	:	6.1.6001.29
RtkAPO.dll	:	11.0.6000.106
RtkApoApi.dll	:	1.0.0.12
RtkCfg.dll	:	1.0.0.1
RtkCoInst.dll	:	1.0.6.7
RtkPgExt.dll	:	6.0.6000.93
RtlCPAPI.dll	:	1.0.2.4
SFFXComm.dll	:	2.0.0.8
SFFXDAP0.dll	:	2.0.0.8
SFFXHAP0.dll	:	2.0.0.8
SFFXProc.dll	:	2.0.0.8
SFFXSAP0.dll	:	2.0.0.8
slcshp32.dll	:	1.0.3.0
slgeq32.dll	:	1.0.1.0
slh36032.dll	:	1.0.2.0
slinit32.dll	:	1.1.3.0
slmaxv32.dll	:	1.1.2.0
sltshd32.dll	:	1.1.1.0
sluapo32.dll	:	1.4.8.0
SRSHP360.dll	:	1.1.0.0
SRSTSHD.dll	:	1.1.4.0
SRSTSXT.dll	:	3.2.0.0
SRSWOW.dll	:	1.1.3.0
WavesLib.dll	:	5.9.7.0
Vista/Win7 driver for x64		
RTKVHD64.sys	:	6.0.1.5928
AERTSr64.exe	:	1.0.64.9
APOPCH.exe	:	1.0.0.0
RAVBg64.exe	:	1.0.0.6
RAVCpl64.exe	:	1.0.0.411
RtkAudioService64.exe	:	1.0.0.24
RtlUpd64.exe	:	2.8.0.0
SkyTel.exe	:	2.0.2.2

Readme.txt

```

vncutil64.exe           : 1.0.0.27
GWfilt64.sys           : 6.10.0.3
mbfilt64.sys           : 6.10.0.8
RTSnMg64.cpl           : 1.0.0.17
AERTAC64.dll           : 2.0.64.8
AERTAR64.dll           : 1.0.64.8
FMAP064.dll            : 42.6.17.68
MaxxAudioAP020.dll    : 2.2.2.0
MBAP032.dll            : 1.0.19.0
MBAP064.dll            : 1.0.19.0
MBPPCn64.dll           : 1.0.0.110
MBpld64.dll            : 1.0.19.0
MBTHX32.dll            : 1.0.8.0
MBTHX64.dll            : 1.0.8.0
MBWrp64.dll            : 1.0.0.110
RCoInst64.dll          : 1.0.6.7
RP3DAA64.dll           : 6.0.6001.18
RP3DHT64.dll           : 6.0.6001.18
RtCOM64.dll            : 2.0.0.119
RTCOMDLL.dll           : 2.0.0.119
RTEED64A.dll           : 6.1.6001.29
RTEEG64A.dll           : 6.1.6001.29
RTEEL64A.dll           : 6.1.6001.29
RTEEP64A.dll           : 6.1.6001.29
RtkApi64.dll           : 1.0.0.12
RtkAPO64.dll           : 11.0.6000.106
RtkCfg.dll             : 1.0.0.1
RtkCfg64.dll           : 1.0.0.1
RtLCPAPI.dll           : 1.0.2.4
RtLCPAPI64.dll         : 1.0.2.4
RtPgEx64.dll           : 6.0.6000.93
SFComm64.dll           : 2.0.0.8
SFDAPO64.dll           : 2.0.0.8
SFHAPO64.dll           : 2.0.0.8
SFProc64.dll           : 2.0.0.8
SFSAPO64.dll           : 2.0.0.8
slcshp64.dll           : 1.0.3.0
slgeq64.dll            : 1.0.1.0
slh36064.dll           : 1.0.2.0
slInit64.dll           : 1.1.3.0
slmaxv64.dll           : 1.1.2.0
sltshd64.dll           : 1.1.1.0
sluapo64.dll           : 1.4.8.0
SRSHp64.dll            : 1.1.0.0
SRSTSH64.dll           : 1.1.4.0
SRSTSX64.dll           : 3.2.0.0
SRSWOV64.dll           : 1.1.3.0
HDMI Driver : -----
Vista/Win7 x86:
RtHDMV.sys              : 6.0.1.5897
RtkAudioSrvATI.exe     : 1.0.0.23
RtkUpd.exe              : 2.8.0.0
RH3DAA32.dll            : 6.0.6001.18
RH3DHT32.dll            : 6.0.6001.18
RHCoInst.dll            : 1.0.6.4
RHDMExt.dll             : 6.0.6000.82
RtkHDM.dll              : 11.0.6000.101

Vista/Win7 x64:
RtHDMVX.sys             : 6.0.1.5897
RtkAudioSrvATI64.exe   : 1.0.0.23
RtkUpd64.exe            : 2.8.0.0
RH3DAA64.dll            : 6.0.6001.18
RH3DHT64.dll            : 6.0.6001.18
RHCoInst64.dll          : 1.0.6.4
RHDMEx64.dll            : 6.0.6000.82
RtkHDM64.dll            : 11.0.6000.101

```

Readme.txt

XP/2K x86:
RtkHDM.sys : 5.10.0.5880
RtkUpd.exe : 2.7.1.3
RHCoInstXP.dll : 1.0.5.1
XP/2K x64:
RtkHDMX.sys : 5.10.0.5880
RtkUpd64.exe : 2.7.1.3
RHCoInst64XP.dll : 1.0.5.1
Driver Setup Program : 2.83

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.31

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887, ALC670, ALC275
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887, ALC670, ALC275
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 - x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.
2. Fix DTM KS position testing fail issue when turn on Microphone effect under Win7.

2.) Package

1. Reboot message in log file. (WLL_REBOOT)
2. Copy all of AP files to system

Windows 2000/XP : -----

Windows 2000/XP :
RTKHDA64.sys : 5.10.0.5919
RTKHDAUD.sys : 5.10.0.5919
Alcmtr.exe : 1.6.0.4
AlcWzrd.exe : 1.1.0.37
MicCal.exe : 1.1.2.2
RTHDCPL.exe : 2.3.0.9
RtkAudioService64.exe : 1.0.0.19
RtkAudioService.exe : 1.0.0.19
RTLCPPL.exe : 1.0.1.66
RtlUpd64.exe : 2.8.0.0
RtlUpd.exe : 2.8.0.0
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.32
vncutil64.exe : 1.0.0.24
vncutil.exe : 1.0.0.25
AMBfilt.sys : 5.10.0.4240
AMBft64.sys : 5.10.0.4240
Mbnfilt.sys : 5.10.0.4112
Mbnft64.sys : 5.10.0.4115
ALSndMgr.cpl : 1.0.0.11
RTSndMgr.cpl : 1.0.1.4
RCoInst64XP.dll : 1.0.6.5
RTCOMDLL.dll : 1.0.0.103
RtkCoInstXP.dll : 1.0.6.5
RtlCPAPI.dll : 1.0.2.3

Vista/Win7 driver : -----

Vista/Win7 driver for x86
RTKVHDA.sys : 6.0.1.5919
AERTSrv.exe : 1.0.32.9
APOPCH.exe : 1.0.0.0

	Readme.txt	
RtHdVBg.exe	:	1.0.0.5
RtHdVCpl.exe	:	1.0.0.401
RtkAudioService.exe	:	1.0.0.24
RtlUpd.exe	:	2.8.0.0
SkyTel.exe	:	2.0.2.2
vncutil.exe	:	1.0.0.25
mbfilt32.sys	:	6.10.0.6
RTSndMgr.cpl	:	1.0.0.17
AERTACap.dll	:	2.0.32.8
AERTARen.dll	:	1.0.32.8
FMAP0.dll	:	42.5.1.1
MaxxAudioAP0.dll	:	1.2.2.0
MaxxAudioAP020.dll	:	2.2.2.0
MaxxAudioEQ.dll	:	5.9.7.0
MBAP032.dll	:	1.0.9.0
MBPPCn32.dll	:	1.0.0.110
Mbpld32.dll	:	1.0.9.0
MBTHX32.dll	:	1.0.8.0
MBWrp32.dll	:	1.0.0.110
RP3DAA32.dll	:	6.0.6001.18
RP3DHT32.dll	:	6.0.6001.18
RTCOMDLL.dll	:	2.0.0.117
RtkAPO.dll	:	11.0.6000.104
RtkApoApi.dll	:	1.0.0.10
RtkCfg.dll	:	1.0.0.1
RtkCoInst.dll	:	1.0.6.7
RtkPgExt.dll	:	6.0.6000.89
RtLCPAPI.dll	:	1.0.2.4
SFFXComm.dll	:	2.0.0.8
SFFXDAP0.dll	:	2.0.0.8
SFFXHAP0.dll	:	2.0.0.8
SFFXProc.dll	:	2.0.0.8
SFFXSAP0.dll	:	2.0.0.8
slcshp32.dll	:	1.0.3.0
slgeq32.dll	:	1.0.1.0
slh36032.dll	:	1.0.2.0
slInit32.dll	:	1.1.3.0
slmaxv32.dll	:	1.1.2.0
sltshd32.dll	:	1.1.1.0
sluapo32.dll	:	1.4.8.0
SRSHP360.dll	:	1.1.0.0
SRSTSHD.dll	:	1.1.4.0
SRSTSXT.dll	:	3.2.0.0
SRSWOW.dll	:	1.1.3.0
WavesLib.dll	:	5.9.7.0
Vista/Win7 driver for x64		
RTKVHD64.sys	:	6.0.1.5919
AERTSr64.exe	:	1.0.64.9
APOPCH.exe	:	1.0.0.0
RAVBg64.exe	:	1.0.0.5
RAVCpl64.exe	:	1.0.0.401
RtkAudioService64.exe	:	1.0.0.24
RtlUpd64.exe	:	2.8.0.0
SkyTel.exe	:	2.0.2.2
vncutil64.exe	:	1.0.0.24
GWfilt64.sys	:	6.10.0.3
mbfilt64.sys	:	6.10.0.8
RTSndMgr64.cpl	:	1.0.0.17
AERTAC64.dll	:	2.0.64.8
AERTAR64.dll	:	1.0.64.8
FMAP064.dll	:	42.6.1.1
MaxxAudioAP020.dll	:	2.2.2.0
MBAP032.dll	:	1.0.19.0
MBAP064.dll	:	1.0.19.0
MBPPCn64.dll	:	1.0.0.110
Mbpld64.dll	:	1.0.19.0
MBTHX32.dll	:	1.0.8.0
MBTHX64.dll	:	1.0.8.0
MBWrp64.dll	:	1.0.0.110

Readme.txt

RCoInst64.dll : 1.0.6.7
 RP3DAA64.dll : 6.0.6001.18
 RP3DHT64.dll : 6.0.6001.18
 RtCOMB4.dll : 2.0.0.117
 RTCOMDLL.dll : 2.0.0.117
 RtkApi64.dll : 1.0.0.10
 RtkAPO64.dll : 11.0.6000.104
 RtkCfg.dll : 1.0.0.1
 RtkCfg64.dll : 1.0.0.1
 RtLCPAPI.dll : 1.0.2.4
 RtLCPAPI64.dll : 1.0.2.4
 RtPgEx64.dll : 6.0.6000.89
 SFComm64.dll : 2.0.0.8
 SFDAP064.dll : 2.0.0.8
 SFHAP064.dll : 2.0.0.8
 SFProc64.dll : 2.0.0.8
 SFSAP064.dll : 2.0.0.8
 slcshp64.dll : 1.0.3.0
 slgeq64.dll : 1.0.1.0
 slh36064.dll : 1.0.2.0
 slInit64.dll : 1.1.3.0
 slmaxv64.dll : 1.1.2.0
 sltshd64.dll : 1.1.1.0
 sluapo64.dll : 1.4.8.0
 SRSHP64.dll : 1.1.0.0
 SRSTSH64.dll : 1.1.4.0
 SRSTX64.dll : 3.2.0.0
 SRSWOW64.dll : 1.1.3.0

HDM Driver : -----

Vista/Win7 x86:
 RtHDMV.sys : 6.0.1.5897
 RtkAudioSrvATI.exe : 1.0.0.23
 RtkUpd.exe : 2.8.0.0
 RH3DAA32.dll : 6.0.6001.18
 RH3DHT32.dll : 6.0.6001.18
 RHCoInst.dll : 1.0.6.4
 RHDMEt.dll : 6.0.6000.82
 RtkHDM.dll : 11.0.6000.101

Vista/Win7 x64:
 RtHDMVX.sys : 6.0.1.5897
 RtkAudioSrvATI64.exe : 1.0.0.23
 RtkUpd64.exe : 2.8.0.0
 RH3DAA64.dll : 6.0.6001.18
 RH3DHT64.dll : 6.0.6001.18
 RHCoInst64.dll : 1.0.6.4
 RHDMEt64.dll : 6.0.6000.82
 RtkHDM64.dll : 11.0.6000.101

XP/2K x86:
 RtkHDM.sys : 5.10.0.5880
 RtkUpd.exe : 2.7.1.3
 RHCoInstXP.dll : 1.0.5.1
 XP/2K x64:
 RtkHDMX.sys : 5.10.0.5880
 RtkUpd64.exe : 2.7.1.3
 RHCoInst64XP.dll : 1.0.5.1

Driver Setup Program : 2.83

Windows 2000/XP Operate on :
 Microsoft High Definition Audio Driver Package - KB888111
 Package file version (kb888111.exe) : 6.1.22.0
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.30

Readme.txt

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887, ALC670, ALC275
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887, ALC670, ALC275
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 - x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Driver :
 1. Customizations.
 2. Fix DTM testing issue under Win7.

Windows 2000/XP : -----

Windows 2000/XP :
RTKHDA64.sys : 5.10.0.5911
RTKHDAUD.sys : 5.10.0.5911
Mccal.exe : 1.1.2.2
RTHDCPL.exe : 2.3.0.7
RtkAudioService64.exe : 1.0.0.19
RtkAudioService.exe : 1.0.0.19
RTLCP.exe : 1.0.1.66
RtlUpd64.exe : 2.8.0.0
RtlUpd.exe : 2.8.0.0
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.32
vncutil64.exe : 1.0.0.23
vncutil.exe : 1.0.0.23
Alcmtr.exe : 1.6.0.4
AlcWzrd.exe : 1.1.0.37
Mnft64.sys : 5.10.0.4112
Mnft64.sys : 5.10.0.4115
AMBf64.sys : 5.10.0.4240
AMBf64.sys : 5.10.0.4240
RTSndMgr.cpl : 1.0.1.4
ALSndMgr.cpl : 1.0.0.11
RCoInst64XP.dll : 1.0.6.5
RTCOMDLL.dll : 1.0.0.103
RtkCoInstXP.dll : 1.0.6.5
RtlCPAPI.dll : 1.0.2.3

Vista/Win7 driver : -----

Vista/Win7 driver for x86
RTKVHDA.sys : 6.0.1.5911
AERTSrv.exe : 1.0.32.9
APOPCH.exe : 1.0.0.0
RtHDVbg.exe : 1.0.0.5
RtHDVCpl.exe : 1.0.0.395
RtkAudioService.exe : 1.0.0.24
RtlUpd.exe : 2.8.0.0
SkyTel.exe : 2.0.2.2
vncutil.exe : 1.0.0.23
mbf64.sys : 6.10.0.6
RTSndMgr.cpl : 1.0.0.17
AERTACap.dll : 2.0.32.8
AERTARen.dll : 1.0.32.8
FMPO.dll : 42.5.1.1
MaxxAudioAPO.dll : 1.2.2.0
MaxxAudioAPO20.dll : 2.2.2.0
MaxxAudioEQ.dll : 5.9.7.0
MBAPO32.dll : 1.0.9.0
MBPPCn32.dll : 1.0.0.110
MBpld32.dll : 1.0.9.0
MBTHX32.dll : 1.0.8.0
MBWp32.dll : 1.0.0.110
RP3DAA32.dll : 6.0.6001.18
RP3DHT32.dll : 6.0.6001.18
RTCOMDLL.dll : 2.0.0.117

	Readme.txt	
RtkAPO.dll	:	11.0.6000.101
RtkApoApi.dll	:	1.0.0.10
RtkCfg.dll	:	1.0.0.1
RtkCoInst.dll	:	1.0.6.5
RtkPgExt.dll	:	6.0.6000.87
RtlCPAPI.dll	:	1.0.2.4
SFFXComm.dll	:	2.0.0.8
SFFXDAP0.dll	:	2.0.0.8
SFFXHAP0.dll	:	2.0.0.8
SFFXProc.dll	:	2.0.0.8
SFFXSAP0.dll	:	2.0.0.8
slcshp32.dll	:	1.0.3.0
slgeq32.dll	:	1.0.1.0
slh36032.dll	:	1.0.2.0
slInit32.dll	:	1.1.3.0
slmaxv32.dll	:	1.1.2.0
sltshd32.dll	:	1.1.1.0
sluapo32.dll	:	1.4.8.0
SRSHP360.dll	:	1.1.0.0
SRSTSHD.dll	:	1.1.4.0
SRSTSXT.dll	:	3.2.0.0
SRSWOW.dll	:	1.1.3.0
WavesLib.dll	:	5.9.7.0
Vista/Win7 driver for x64		
RTKVHD64.sys	:	6.0.1.5911
AERTSr64.exe	:	1.0.64.9
APOPCH.exe	:	1.0.0.0
RAVBg64.exe	:	1.0.0.5
RAVCpl64.exe	:	1.0.0.395
RtkAudioService64.exe	:	1.0.0.24
RtlUpd64.exe	:	2.8.0.0
SkyTel.exe	:	2.0.2.2
vncutil64.exe	:	1.0.0.23
GWfilt64.sys	:	6.10.0.3
mbfilt64.sys	:	6.10.0.6
RTSnMg64.cpl	:	1.0.0.17
AERTAC64.dll	:	2.0.64.8
AERTAR64.dll	:	1.0.64.8
FMAP064.dll	:	42.6.1.1
MaxxAudioAP020.dll	:	2.2.2.0
MBAP032.dll	:	1.0.9.0
MBAP064.dll	:	1.0.9.0
MBPPCn64.dll	:	1.0.0.110
MBpld64.dll	:	1.0.9.0
MBTHX32.dll	:	1.0.8.0
MBTHX64.dll	:	1.0.8.0
MBWrp64.dll	:	1.0.0.110
RCoInst64.dll	:	1.0.6.5
RP3DAA64.dll	:	6.0.6001.18
RP3DHT64.dll	:	6.0.6001.18
RtCOM64.dll	:	2.0.0.117
RTCOMDLL.dll	:	2.0.0.117
RtkApi64.dll	:	1.0.0.10
RtkAPO64.dll	:	11.0.6000.101
RtkCfg.dll	:	1.0.0.1
RtkCfg64.dll	:	1.0.0.1
RtlCPAPI.dll	:	1.0.2.4
RtlCPAPI64.dll	:	1.0.2.4
RtPgEx64.dll	:	6.0.6000.87
SFComm64.dll	:	2.0.0.8
SFDAP064.dll	:	2.0.0.8
SFHAP064.dll	:	2.0.0.8
SFProc64.dll	:	2.0.0.8
SFSAP064.dll	:	2.0.0.8
slcshp64.dll	:	1.0.3.0
slgeq64.dll	:	1.0.1.0
slh36064.dll	:	1.0.2.0
slInit64.dll	:	1.1.3.0
slmaxv64.dll	:	1.1.2.0

Readme.txt

sltshd64.dll : 1.1.1.0
 sluapo64.dll : 1.4.8.0
 SRSHP64.dll : 1.1.0.0
 SRSTSH64.dll : 1.1.4.0
 SRSTSX64.dll : 3.2.0.0
 SRSWOW64.dll : 1.1.3.0

HDMI Driver : -----
 Vista/Win7 x86:
 RtHDMV.sys : 6.0.1.5897
 RtkAudioSrvATI.exe : 1.0.0.23
 RtkUpd.exe : 2.8.0.0
 RH3DAA32.dll : 6.0.6001.18
 RH3DHT32.dll : 6.0.6001.18
 RHCoInst.dll : 1.0.6.4
 RHDMEExt.dll : 6.0.6000.82
 RtkHDM.dll : 11.0.6000.101

Vista/Win7 x64:
 RtHDMVX.sys : 6.0.1.5897
 RtkAudioSrvATI64.exe : 1.0.0.23
 RtkUpd64.exe : 2.8.0.0
 RH3DAA64.dll : 6.0.6001.18
 RH3DHT64.dll : 6.0.6001.18
 RHCoInst64.dll : 1.0.6.4
 RHDME64.dll : 6.0.6000.82
 RtkHDM64.dll : 11.0.6000.101

XP/2K x86:
 RtkHDM.sys : 5.10.0.5880
 RtkUpd.exe : 2.7.1.3
 RHCoInstXP.dll : 1.0.5.1

XP/2K x64:
 RtkHDMX.sys : 5.10.0.5880
 RtkUpd64.exe : 2.7.1.3
 RHCoInst64XP.dll : 1.0.5.1

Driver Setup Program : 2.81

Windows 2000/XP Operate on :
 Microsoft High Definition Audio Driver Package - KB888111
 Package file version (kb888111.exe) : 6.1.22.0
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.29

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887, ALC670

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887, ALC670

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008,

Windows7 - x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :
 RTKHDA64.sys : 5.10.0.5898
 RTKHDAUD.sys : 5.10.0.5898
 Alcmtr.exe : 1.6.0.4
 AlcWzrd.exe : 1.1.0.37
 McCal.exe : 1.1.2.1
 RTHDCPL.exe : 2.3.0.0


```

Readme.txt
RtkAudioService.exe : 1.0.0.19
RtkAudioService64.exe : 1.0.0.19
RTLCP.L.exe : 1.0.1.66
RtlUpd.exe : 2.8.0.0
RtlUpd64.exe : 2.8.0.0
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.32
vncutil.exe : 1.0.0.23
vncutil64.exe : 1.0.0.23
AMBFilt.sys : 5.10.0.4240
AMBft64.sys : 5.10.0.4240
Mnfilt.sys : 5.10.0.4112
Mnft64.sys : 5.10.0.4115
ALSndMgr.cpl : 1.0.0.11
RTSndMgr.cpl : 1.0.1.3
RCoInst64XP.dll : 1.0.6.3
RTCOMDLL.dll : 1.0.0.103
RtkCoInstXP.dll : 1.0.6.3
RtlCPAPI.dll : 1.0.2.3
Vista/Win7 driver : -----
Vista/Win7 driver for x86
RTKVHDA.sys : 6.0.1.5898
AERTSrv.exe : 1.0.32.9
APOPCH.exe : 1.0.0.0
RtHDVBg.exe : 1.0.0.5
RtHDVCpl.exe : 1.0.0.386
RtkAudioService.exe : 1.0.0.24
RtlUpd.exe : 2.8.0.0
SkyTel.exe : 2.0.2.2
vncutil.exe : 1.0.0.23
mbfilt32.sys : 6.10.0.6
RTSndMgr.cpl : 1.0.0.16
AERTACap.dll : 2.0.32.8
AERTARen.dll : 1.0.32.8
FMAP0.dll : 0.0.18.2
MaxxAudioAP0.dll : 1.2.2.0
MaxxAudioAP020.dll : 2.2.2.0
MaxxAudioEQ.dll : 5.9.7.0
MBAP032.dll : 1.0.9.0
MBPPCn32.dll : 1.0.0.110
MBpld32.dll : 1.0.9.0
MBTHX32.dll : 1.0.6.0
MBWrp32.dll : 1.0.0.110
RP3DAA32.dll : 6.0.6001.18
RP3DHT32.dll : 6.0.6001.18
RTCOMDLL.dll : 2.0.0.117
RtkAPO.dll : 11.0.6000.101
RtkApoApi.dll : 1.0.0.10
RtkCfg.dll : 1.0.0.1
RtkCoInst.dll : 1.0.6.4
RtkPgExt.dll : 6.0.6000.84
RtlCPAPI.dll : 1.0.2.4
SFFXComm.dll : 2.0.0.6
SFFXDAP0.dll : 2.0.0.6
SFFXHAP0.dll : 2.0.0.6
SFFXProc.dll : 2.0.0.6
SFFXSAP0.dll : 2.0.0.6
slcshp32.dll : 1.0.3.0
slgeq32.dll : 1.0.1.0
slh36032.dll : 1.0.2.0
slInit32.dll : 1.1.3.0
slmaxv32.dll : 1.1.2.0
sltshd32.dll : 1.1.1.0
sluapo32.dll : 1.4.8.0
SRSHP360.dll : 1.1.0.0
SRSTSHD.dll : 1.1.4.0
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.1.3.0
WavesLib.dll : 5.9.7.0

```

Readme.txt

Vista/Win7 driver for x64

RTKVHD64.sys : 6.0.1.5898
 AERTSr64.exe : 1.0.64.9
 APOPCH.exe : 1.0.0.0
 RAVBg64.exe : 1.0.0.5
 RAVCpl64.exe : 1.0.0.386
 RtkAudioService64.exe : 1.0.0.24
 RtlUpd64.exe : 2.8.0.0
 SkyTel.exe : 2.0.2.2
 vncutil64.exe : 1.0.0.23
 GWfilt64.sys : 6.10.0.3
 mbfilt64.sys : 6.10.0.6
 RTSnMg64.cpl : 1.0.0.16
 AERTAC64.dll : 2.0.64.8
 AERTAR64.dll : 1.0.64.8
 FMAP064.dll : 0.0.18.2
 MaxxAudioAPO20.dll : 2.2.2.0
 MBAP032.dll : 1.0.9.0
 MBAP064.dll : 1.0.9.0
 MBPPCn64.dll : 1.0.0.110
 Mbpld64.dll : 1.0.9.0
 MBTHX32.dll : 1.0.6.0
 MBTHX64.dll : 1.0.6.0
 MBWrp64.dll : 1.0.0.110
 RCoInst64.dll : 1.0.6.4
 RP3DAA64.dll : 6.0.6001.18
 RP3DHT64.dll : 6.0.6001.18
 RtCOMB4.dll : 2.0.0.117
 RTCOMLL.dll : 2.0.0.117
 RtkApi64.dll : 1.0.0.10
 RtkAPO64.dll : 11.0.6000.101
 RtkCfg.dll : 1.0.0.1
 RtkCfg64.dll : 1.0.0.1
 RtlCPAPI.dll : 1.0.2.4
 RtlCPAPI64.dll : 1.0.2.4
 RtpgEx64.dll : 6.0.6000.84
 SFComm64.dll : 2.0.0.6
 SFDAP064.dll : 2.0.0.6
 SFHAP064.dll : 2.0.0.6
 SFProc64.dll : 2.0.0.6
 SFSAP064.dll : 2.0.0.6
 slcshp64.dll : 1.0.3.0
 slgeq64.dll : 1.0.1.0
 slh36064.dll : 1.0.2.0
 slInit64.dll : 1.1.3.0
 slmaxv64.dll : 1.1.2.0
 sltshd64.dll : 1.1.1.0
 sluapo64.dll : 1.4.8.0
 SRSHp64.dll : 1.1.0.0
 SRSTSH64.dll : 1.1.4.0
 SRSTSX64.dll : 3.2.0.0
 SRSWOW64.dll : 1.1.3.0

HDMI Driver : -----

Vista/Win7 x86:

RtHDMV.sys : 6.0.1.5897
 RtkAudioSrvATI.exe : 1.0.0.23
 RtkUpd.exe : 2.8.0.0
 RH3DAA32.dll : 6.0.6001.18
 RH3DHT32.dll : 6.0.6001.18
 RHCoInst.dll : 1.0.6.4
 RHDMExt.dll : 6.0.6000.82
 RtkHDM.dll : 11.0.6000.101

Vista/Win7 x64:

RtHDMVX.sys : 6.0.1.5897
 RtkAudioSrvATI64.exe : 1.0.0.23
 RtkUpd64.exe : 2.8.0.0
 RH3DAA64.dll : 6.0.6001.18

Readme.txt

RH3DHT64.dll	: 6.0.6001.18
RHCoInst64.dll	: 1.0.6.4
RHDMEx64.dll	: 6.0.6000.82
RtkHDM64.dll	: 11.0.6000.101

XP/2K x86:	
RtkHDM.sys	: 5.10.0.5880
RtkUpd.exe	: 2.7.1.3
RHCoInstXP.dll	: 1.0.5.1
XP/2K x64:	
RtkHDMX.sys	: 5.10.0.5880
RtkUpd64.exe	: 2.7.1.3
RHCoInst64XP.dll	: 1.0.5.1
Driver Setup Program	: 2.81

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.28

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887, ALC670
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887, ALC670
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008,

Windows7 - x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix

- 1.) Driver :
 1. Customizations.
- 2.) Package :
 1. Fix uninstallation driver issue under Windows x64 system .

Windows 2000/XP : -----

Windows 2000/XP :	
Windows 2000/XP :	
Windows 2000/XP :	
RTKHDA64.sys	: 5.10.0.5888
RTKHDAUD.sys	: 5.10.0.5888
Alcmtr.exe	: 1.6.0.4
AlcWzrd.exe	: 1.1.0.37
McCal.exe	: 1.1.2.1
RTHDCPL.exe	: 2.2.9.7
RtkAudioService.exe	: 1.0.0.19
RtkAudioService64.exe	: 1.0.0.19
RTLCPPL.exe	: 1.0.1.66
RtlUpd.exe	: 2.8.0.0
RtlUpd64.exe	: 2.8.0.0
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.32
vncutil.exe	: 1.0.0.23
vncutil64.exe	: 1.0.0.23
AMBFilt.sys	: 5.10.0.4240
AMBft64.sys	: 5.10.0.4240
Mbnfilt.sys	: 5.10.0.4112
Mbnft64.sys	: 5.10.0.4115
ALSndMgr.cpl	: 1.0.0.11
RTSndMgr.cpl	: 1.0.1.3
RCoInst64XP.dll	: 1.0.6.2
RTCOMDLL.dll	: 1.0.0.103
RtkCoInstXP.dll	: 1.0.6.2
RtlCPAPI.dll	: 1.0.2.3

Vista/Win7 driver : -----

Vista/Win7 driver for x86

	Readme.txt	
RTKVHDA.sys		: 6.0.1.5888
AERTSrv.exe		: 1.0.32.9
APOPCH.exe		: 1.0.0.0
RtHDVbg.exe		: 1.0.0.5
RtHDVCpl.exe		: 1.0.0.376
RtkAudioService.exe		: 1.0.0.22
RtlUpd.exe		: 2.8.0.0
SkyTel.exe		: 2.0.2.2
vncutil.exe		: 1.0.0.23
RTSndMgr.cpl		: 1.0.0.15
AERTACap.dll		: 2.0.32.8
AERTARen.dll		: 1.0.32.8
FMAP0.dll		: 0.0.18.2
MaxxAudioAP0.dll		: 1.2.2.0
MaxxAudioAP020.dll		: 2.2.2.0
MaxxAudioEQ.dll		: 5.9.7.0
MBAP032.dll		: 1.0.9.0
MBPPCn32.dll		: 1.0.0.110
MBppld32.dll		: 1.0.9.0
MBWrp32.dll		: 1.0.0.110
RP3DAA32.dll		: 6.0.6001.18
RP3DHT32.dll		: 6.0.6001.18
RTCOMDLL.dll		: 2.0.0.116
RtkAPO.dll		: 11.0.6000.101
RtkApoApi.dll		: 1.0.0.10
RtkCfg.dll		: 1.0.0.1
RtkCoInst.dll		: 1.0.6.2
RtkPgExt.dll		: 6.0.6000.82
RtlCPAPI.dll		: 1.0.2.4
SFFXComm.dll		: 2.0.0.6
SFFXDAP0.dll		: 2.0.0.6
SFFXHAP0.dll		: 2.0.0.6
SFFXProc.dll		: 2.0.0.6
SFFXSAP0.dll		: 2.0.0.6
slcshp32.dll		: 1.0.3.0
slgeq32.dll		: 1.0.1.0
slh36032.dll		: 1.0.2.0
slInit32.dll		: 1.1.3.0
slmaxv32.dll		: 1.1.2.0
sltshd32.dll		: 1.1.1.0
sluapo32.dll		: 1.4.8.0
SRSHP360.dll		: 1.1.0.0
SRSTSHD.dll		: 1.1.4.0
SRSTSXT.dll		: 3.2.0.0
SRSWOW.dll		: 1.1.3.0
WavesLib.dll		: 5.9.7.0
RCORES.dat		: 1.0.0.5
Vista/Win7 driver for x64		
RTKVHD64.sys		: 6.0.1.5888
AERTSr64.exe		: 1.0.64.9
APOPCH.exe		: 1.0.0.0
RAVBg64.exe		: 1.0.0.5
RAVCpl64.exe		: 1.0.0.376
RtkAudioService64.exe		: 1.0.0.22
RtlUpd64.exe		: 2.8.0.0
SkyTel.exe		: 2.0.2.2
vncutil64.exe		: 1.0.0.23
GWfilt64.sys		: 6.10.0.3
RTSnm64.cpl		: 1.0.0.15
AERTAC64.dll		: 2.0.64.8
AERTAR64.dll		: 1.0.64.8
FMAP064.dll		: 0.0.18.2
MaxxAudioAP020.dll		: 2.2.2.0
MBAP032.dll		: 1.0.9.0
MBAP064.dll		: 1.0.9.0
MBPPCn64.dll		: 1.0.0.110
MBppld64.dll		: 1.0.9.0
MBWrp64.dll		: 1.0.0.110
RCoInst64.dll		: 1.0.6.2

Readme.txt

RP3DAA64.dll : 6.0.6001.18
RP3DHT64.dll : 6.0.6001.18
RtCOM64.dll : 2.0.0.116
RTCOMDLL.dll : 2.0.0.116
RtkApi64.dll : 1.0.0.10
RtkAPO64.dll : 11.0.6000.101
RtkCfg.dll : 1.0.0.1
RtkCfg64.dll : 1.0.0.1
RtLCPAPI.dll : 1.0.2.4
RtLCPAPI64.dll : 1.0.2.4
RtPgEx64.dll : 6.0.6000.82
SFComm64.dll : 2.0.0.6
SFDAP064.dll : 2.0.0.6
SFHAP064.dll : 2.0.0.6
SFProc64.dll : 2.0.0.6
SFSAP064.dll : 2.0.0.6
slcshp64.dll : 1.0.3.0
slgeq64.dll : 1.0.1.0
slh36064.dll : 1.0.2.0
slInit64.dll : 1.1.3.0
slmaxv64.dll : 1.1.2.0
sltshd64.dll : 1.1.1.0
sluapo64.dll : 1.4.8.0
SRSHP64.dll : 1.1.0.0
SRSTSH64.dll : 1.1.4.0
SRSTX64.dll : 3.2.0.0
SRSW064.dll : 1.1.3.0
RCORES64.dat : 1.0.0.5

HDMI Driver : -----
Vista/Win7 x86:
RtHDMV.sys : 6.0.1.5880
RtkUpd.exe : 2.7.1.3
RH3DAA32.dll : 6.0.6001.18
RH3DHT32.dll : 6.0.6001.18
RHCoInst.dll : 1.0.6.0
RHDMEExt.dll : 6.0.6000.82
RtkHDM.dll : 11.0.6000.100

Vista/Win7 x64:
RtHDMVX.sys : 6.0.1.5880
RtkUpd64.exe : 2.7.1.3
RH3DAA64.dll : 6.0.6001.18
RH3DHT64.dll : 6.0.6001.18
RHCoInst64.dll : 1.0.6.0
RHDME64.dll : 6.0.6000.82
RtkHDM64.dll : 11.0.6000.100

XP/2K x86:
RtkHDM.sys : 5.10.0.5880
RtkUpd.exe : 2.7.1.3
RHCoInstXP.dll : 1.0.5.1
XP/2K x64:
RtkHDMX.sys : 5.10.0.5880
RtkUpd64.exe : 2.7.1.3
RHCoInst64XP.dll : 1.0.5.1

Driver Setup Program : 2.80

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====
Driver Package R2.27

Realtek HD Audio Driver support all of Realtek HD Audio Codec .
1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662,

Readme.txt

ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 - x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

2. Fix GUI issue which can't launch Windows MediaPlayer under Win7 OS.

Windows 2000/XP : -----

Windows 2000/XP :

RTKHDA64.sys : 5.10.0.5874
RTKHDAUD.sys : 5.10.0.5874
McCal.exe : 1.1.2.1
RTHDCPL.exe : 2.2.9.2
RtkAudioService64.exe : 1.0.0.19
RtkAudioService.exe : 1.0.0.19
RTLCPPL.exe : 1.0.1.66
RtlUpd64.exe : 2.7.1.4
RtlUpd.exe : 2.7.1.4
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.32
vncutil64.exe : 1.0.0.23
vncutil.exe : 1.0.0.23
Alcmtr.exe : 1.6.0.4
AlcWzrd.exe : 1.1.0.37
Mnfil.t.sys : 5.10.0.4112
Mnft64.sys : 5.10.0.4115
AMBfil.t.sys : 5.10.0.4240
AMBft64.sys : 5.10.0.4240
RTSndMgr.cpl : 1.0.1.3
ALSndMgr.cpl : 1.0.0.11
RCoInst64XP.dll : 1.0.5.9
RTCOMDLL.dll : 1.0.0.103
RtkCoInstXP.dll : 1.0.5.9
RtlCPAPI.dll : 1.0.2.3

Vista/Win7 driver : -----

Vista/Win7 driver for x86

RTKVHDA.sys : 6.0.1.5874
AERTSrv.exe : 1.0.32.9
APOPCH.exe : 1.0.0.0
RtHDVCpl.exe : 1.0.0.366
RtkAudioService.exe : 1.0.0.21
RtlUpd.exe : 2.7.1.4
SkyTel.exe : 2.0.2.2
vncutil.exe : 1.0.0.23
RTSndMgr.cpl : 1.0.0.15
AERTACap.dll : 2.0.32.8
AERTARen.dll : 1.0.32.8
FMAPO.dll : 0.0.14.1
MaxxAudioAPO.dll : 1.2.2.0
MaxxAudioAPO20.dll : 2.2.2.0
MaxxAudioEQ.dll : 5.9.7.0
MBAP032.dll : 1.0.9.0
MBPPCn32.dll : 1.0.0.110
MBppld32.dll : 1.0.9.0
MBWp32.dll : 1.0.0.110
RP3DAA32.dll : 6.0.6001.18
RP3DHT32.dll : 6.0.6001.18
RTCOMDLL.dll : 2.0.0.113
RtkAPO.dll : 11.0.6000.100
RtkApoApi.dll : 1.0.0.10
RtkCfg.dll : 1.0.0.1
RtkCoInst.dll : 1.0.6.0
RtkPgExt.dll : 6.0.6000.82
RtlCPAPI.dll : 1.0.2.4

Readme.txt

SFFXComm.dll	: 2.0.0.6
SFFXDAP0.dll	: 2.0.0.6
SFFXHAP0.dll	: 2.0.0.6
SFFXProc.dll	: 2.0.0.6
SFFXSAP0.dll	: 2.0.0.6
slcshp32.dll	: 1.0.3.0
slgeq32.dll	: 1.0.1.0
slh36032.dll	: 1.0.2.0
slInit32.dll	: 1.1.3.0
slmaxv32.dll	: 1.1.2.0
sltshd32.dll	: 1.1.1.0
sluapo32.dll	: 1.4.8.0
SRSHP360.dll	: 1.1.0.0
SRSTSHD.dll	: 1.1.4.0
SRSTSXT.dll	: 3.2.0.0
SRSWOW.dll	: 1.1.3.0
WavesLib.dll	: 5.9.7.0
Vista/Win7 driver for x64	
RTKVHD64.sys	: 6.0.1.5874
AERTSr64.exe	: 1.0.64.9
APOPCH.exe	: 1.0.0.0
RAVCpl64.exe	: 1.0.0.366
RtkAudioService64.exe	: 1.0.0.21
RtlUpd64.exe	: 2.7.1.4
SkyTel.exe	: 2.0.2.2
vncutil64.exe	: 1.0.0.23
GWfilt64.sys	: 6.10.0.3
RTSnMg64.cpl	: 1.0.0.15
AERTAC64.dll	: 2.0.64.8
AERTAR64.dll	: 1.0.64.8
FMAP064.dll	: 0.0.14.1
MaxxAudioAP020.dll	: 2.2.2.0
MBAP032.dll	: 1.0.9.0
MBAP064.dll	: 1.0.9.0
MBPPCn64.dll	: 1.0.0.110
MBpld64.dll	: 1.0.9.0
MBWrp64.dll	: 1.0.0.110
RCoInst64.dll	: 1.0.6.0
RP3DAA64.dll	: 6.0.6001.18
RP3DHT64.dll	: 6.0.6001.18
RtCOM64.dll	: 2.0.0.113
RTCOMDLL.dll	: 2.0.0.113
RtkApi64.dll	: 1.0.0.10
RtkAPO64.dll	: 11.0.6000.100
RtkCfg.dll	: 1.0.0.1
RtkCfg64.dll	: 1.0.0.1
RtlCPAPI.dll	: 1.0.2.4
RtlCPAPI64.dll	: 1.0.2.4
RtPgEx64.dll	: 6.0.6000.82
SFComm64.dll	: 2.0.0.6
SFDAP064.dll	: 2.0.0.6
SFHAP064.dll	: 2.0.0.6
SFProc64.dll	: 2.0.0.6
SFSAP064.dll	: 2.0.0.6
slcshp64.dll	: 1.0.3.0
slgeq64.dll	: 1.0.1.0
slh36064.dll	: 1.0.2.0
slInit64.dll	: 1.1.3.0
slmaxv64.dll	: 1.1.2.0
sltshd64.dll	: 1.1.1.0
sluapo64.dll	: 1.4.8.0
SRSHP64.dll	: 1.1.0.0
SRSTSH64.dll	: 1.1.4.0
SRSTX64.dll	: 3.2.0.0
SRSWOW64.dll	: 1.1.3.0

HDMI Driver :	
Vista/Win7 x86:	
RtHDMV.sys	: 6.0.1.5857
RtkUpd.exe	: 2.7.1.3

Readme.txt

RH3DAA32.dll : 6.0.6001.18
RH3DHT32.dll : 6.0.6001.18
RHCoInst.dll : 1.0.4.9
RHDMExt.dll : 6.0.6000.79
RtkHDM.dll : 11.0.6000.99

Vista/Win7 x64:

RtHDMVX.sys : 6.0.1.5857
RtkUpd64.exe : 2.7.1.3
RH3DAA64.dll : 6.0.6001.18
RH3DHT64.dll : 6.0.6001.18
RHCoInst64.dll : 1.0.4.4
RHDMEx64.dll : 6.0.6000.79
RtkHDM64.dll : 11.0.6000.99

XP/2K x86:

RtkHDM.sys : 5.10.0.5857
RtkUpd.exe : 2.7.1.3
RHCoInstXP.dll : 1.0.5.1

XP/2K x64:

RtkHDMX.sys : 5.10.0.5857
RtkUpd64.exe : 2.7.1.3
RHCoInst64XP.dll : 1.0.5.1

Driver Setup Program : 2.77

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.26

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887

3. HDM Device WHQL Support: ATI HDM Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 - x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.
2. Update SRS components.

Windows 2000/XP : -----

Windows 2000/XP :
RTKHDA64.sys : 5.10.0.5864
RTKHDAUD.sys : 5.10.0.5864
McCal.exe : 1.1.2.1
RTHDCPL.exe : 2.2.9.0
RtkAudioService64.exe : 1.0.0.19
RtkAudioService.exe : 1.0.0.19
RTLCPPL.exe : 1.0.1.66
RtlUpd64.exe : 2.7.1.3
RtlUpd.exe : 2.7.1.3
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.32
vncutil64.exe : 1.0.0.23
vncutil.exe : 1.0.0.23
Alcmtr.exe : 1.6.0.4
AlcWzrd.exe : 1.1.0.37
AMBft64.sys : 5.10.0.4240
Mbnfilt.sys : 5.10.0.4112
Mnft64.sys : 5.10.0.4115
AMBFilt.sys : 5.10.0.4240

	Readme.txt	
RTSndMgr. cpl	:	1.0.1.3
ALSndMgr. cpl	:	1.0.0.11
RCoInst64XP. dll	:	1.0.5.6
RTCOMDLL. dll	:	1.0.0.103
RtkCoInstXP. dll	:	1.0.5.6
RtICPAPI. dll	:	1.0.2.3
Vista/Win7 driver : -----		
Vista/Win7 driver for x86		
RTKVHDA. sys	:	6.0.1.5864
AERTSrv. exe	:	1.0.32.9
APOPCH. exe	:	1.0.0.0
RtHDVCpl. exe	:	1.0.0.356
RtkAudioService. exe	:	1.0.0.19
RtlUpd. exe	:	2.7.1.3
SkyTel. exe	:	2.0.2.2
vncutil. exe	:	1.0.0.23
RTSndMgr. cpl	:	1.0.0.15
AERTACap. dll	:	2.0.32.8
AERTARen. dll	:	1.0.32.8
FMAP0. dll	:	0.0.14.1
MaxxAudioAP0. dll	:	1.2.2.0
MaxxAudioAP020. dll	:	2.2.2.0
MaxxAudioEQ. dll	:	5.9.7.0
MBAP032. dll	:	1.0.9.0
MBPPCn32. dll	:	1.0.0.110
MBpld32. dll	:	1.0.9.0
MBWrp32. dll	:	1.0.0.110
RP3DAA32. dll	:	6.0.6001.18
RP3DHT32. dll	:	6.0.6001.18
RTCOMDLL. dll	:	2.0.0.113
RtkAP0. dll	:	11.0.6000.99
RtkApoApi. dll	:	1.0.0.10
RtkCfg. dll	:	1.0.0.1
RtkCoInst. dll	:	1.0.5.8
RtkPgExt. dll	:	6.0.6000.79
RtICPAPI. dll	:	1.0.2.4
SFFXComm. dll	:	2.0.0.6
SFFXDAP0. dll	:	2.0.0.6
SFFXHAP0. dll	:	2.0.0.6
SFFXProc. dll	:	2.0.0.6
SFFXSAP0. dll	:	2.0.0.6
slcshp32. dll	:	1.0.3.0
slgeq32. dll	:	1.0.1.0
slh36032. dll	:	1.0.2.0
slInit32. dll	:	1.1.3.0
slmaxv32. dll	:	1.1.1.0
sltshd32. dll	:	1.1.1.0
sluapo32. dll	:	1.4.6.0
SRSHP360. dll	:	1.1.0.0
SRSTSHD. dll	:	1.1.4.0
SRSTSXT. dll	:	3.2.0.0
SRSWOW. dll	:	1.1.3.0
WavesLib. dll	:	5.9.7.0
Vista/Win7 driver for x64		
RTKVHD64. sys	:	6.0.1.5864
AERTSr64. exe	:	1.0.64.9
APOPCH. exe	:	1.0.0.0
RAVCpl64. exe	:	1.0.0.356
RtkAudioService64. exe	:	1.0.0.19
RtlUpd64. exe	:	2.7.1.3
SkyTel. exe	:	2.0.2.2
vncutil64. exe	:	1.0.0.23
GWfilt64. sys	:	6.10.0.3
RTSnMg64. cpl	:	1.0.0.15
AERTAC64. dll	:	2.0.64.8
AERTAR64. dll	:	1.0.64.8
FMAP064. dll	:	0.0.14.1
MaxxAudioAP020. dll	:	2.2.2.0
MBAP032. dll	:	1.0.9.0

Readme.txt

```

MBAP064. dll           : 1. 0. 9. 0
MBPPCn64. dll         : 1. 0. 0. 110
Mbppld64. dll         : 1. 0. 9. 0
MBWrp64. dll          : 1. 0. 0. 110
RCoInst64. dll        : 1. 0. 5. 8
RP3DAA64. dll         : 6. 0. 6001. 18
RP3DHT64. dll         : 6. 0. 6001. 18
RtCOMB4. dll          : 2. 0. 0. 113
RTCOMDLL. dll         : 2. 0. 0. 113
RtkApi 64. dll        : 1. 0. 0. 10
RtkAP064. dll         : 11. 0. 6000. 99
RtkCfg. dll           : 1. 0. 0. 1
RtkCfg64. dll         : 1. 0. 0. 1
RtlCPAPI. dll         : 1. 0. 2. 4
RtlCPAPI64. dll       : 1. 0. 2. 4
RtPgEx64. dll         : 6. 0. 6000. 79
SFComm64. dll         : 2. 0. 0. 6
SFDAP064. dll         : 2. 0. 0. 6
SFHAP064. dll         : 2. 0. 0. 6
SFProc64. dll         : 2. 0. 0. 6
SFSAP064. dll         : 2. 0. 0. 6
slcshp64. dll         : 1. 0. 3. 0
slgeq64. dll          : 1. 0. 1. 0
slh36064. dll         : 1. 0. 2. 0
slInit64. dll         : 1. 1. 3. 0
slmaxv64. dll         : 1. 1. 1. 0
sltshd64. dll         : 1. 1. 1. 0
sluapo64. dll         : 1. 4. 6. 0
SRSHP64. dll          : 1. 1. 0. 0
SRSTSH64. dll         : 1. 1. 4. 0
SRSTX64. dll          : 3. 2. 0. 0
SRSWOW64. dll         : 1. 1. 3. 0
-----
HDM Driver :
Vista/Win7 x86:
RtHDMV. sys           : 6. 0. 1. 5857
RtkUpd. exe           : 2. 7. 1. 3
RH3DAA32. dll         : 6. 0. 6001. 18
RH3DHT32. dll         : 6. 0. 6001. 18
RHCoInst. dll         : 1. 0. 4. 9
RHDMExt. dll          : 6. 0. 6000. 79
RtkHDM. dll           : 11. 0. 6000. 99

Vista/Win7 x64:
RtHDMVX. sys          : 6. 0. 1. 5857
RtkUpd64. exe         : 2. 7. 1. 3
RH3DAA64. dll         : 6. 0. 6001. 18
RH3DHT64. dll         : 6. 0. 6001. 18
RHCoInst64. dll       : 1. 0. 4. 4
RHDMEx64. dll         : 6. 0. 6000. 79
RtkHDM64. dll         : 11. 0. 6000. 99

XP/2K x86:
RtkHDM. sys           : 5. 10. 0. 5857
RtkUpd. exe           : 2. 7. 1. 3
RHCoInstXP. dll       : 1. 0. 5. 1

XP/2K x64:
RtkHDMX. sys          : 5. 10. 0. 5857
RtkUpd64. exe         : 2. 7. 1. 3
RHCoInst64XP. dll     : 1. 0. 5. 1

Driver Setup Program  : 2. 76

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6. 1. 22. 0
Hdaudiobus. sys version : 5. 10. 00. 5013

```

//=====

Readme.txt

Driver Package R2.25

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 - x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Driver :
 1. Customizations.
 2. Windows 7 WHQL Driver.

Windows 2000/XP : -----

Windows 2000/XP :
RTKHDA64.sys : 5.10.0.5859
RTKHDAUD.sys : 5.10.0.5859
Alcmtr.exe : 1.6.0.4
AlcWzrd.exe : 1.1.0.37
Mccal.exe : 1.1.2.1
RTHDCPL.exe : 2.2.9.0
RtkAudioService.exe : 1.0.0.19
RtkAudioService64.exe : 1.0.0.19
RTLCPPL.exe : 1.0.1.66
RtlUpd.exe : 2.7.1.3
RtlUpd64.exe : 2.7.1.3
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.32
vncutil.exe : 1.0.0.23
vncutil64.exe : 1.0.0.23
AMBfilt.sys : 5.10.0.4240
AMBft64.sys : 5.10.0.4240
Mbnfilt.sys : 5.10.0.4112
Mnft64.sys : 5.10.0.4115
ALSndMgr.cpl : 1.0.0.11
RTSndMgr.cpl : 1.0.1.3
RCoInst64XP.dll : 1.0.5.6
RTCOMDLL.dll : 1.0.0.103
RtkCoInstXP.dll : 1.0.5.6
RtlCPAPI.dll : 1.0.2.3

Vista/Win7 driver : -----

Vista/Win7 driver for x86
RTKVHDA.sys : 6.0.1.5859
AERTSrv.exe : 1.0.32.9
APOPCH.exe : 1.0.0.0
RtHDVCpl.exe : 1.0.0.353
RtkAudioService.exe : 1.0.0.19
RtlUpd.exe : 2.7.1.3
SkyTel.exe : 2.0.2.2
vncutil.exe : 1.0.0.23
RTSndMgr.cpl : 1.0.0.15
AERTACap.dll : 2.0.32.8
AERTARen.dll : 1.0.32.8
FMAPO.dll : 0.0.14.1
MaxxAudioAPO.dll : 1.2.2.0
MaxxAudioAPO20.dll : 2.2.2.0
MaxxAudioEQ.dll : 5.9.7.0
MBAPO32.dll : 1.0.9.0
MBPPCn32.dll : 1.0.0.110
MBppld32.dll : 1.0.9.0
MBWrp32.dll : 1.0.0.110
RP3DAA32.dll : 6.0.6001.18
RP3DHT32.dll : 6.0.6001.18
RTCOMDLL.dll : 2.0.0.113
RtkAPO.dll : 11.0.6000.99
RtkApoApi.dll : 1.0.0.10
RtkCfg.dll : 1.0.0.1

Readme.txt

RtkCoInst.dll	: 1.0.5.8
RtkPgExt.dll	: 6.0.6000.79
RtlCPAPI.dll	: 1.0.2.4
SFFXComm.dll	: 2.0.0.6
SFFXDAP0.dll	: 2.0.0.6
SFFXHAP0.dll	: 2.0.0.6
SFFXProc.dll	: 2.0.0.6
SFFXSAP0.dll	: 2.0.0.6
slcshp32.dll	: 1.0.3.0
slgeq32.dll	: 1.0.1.0
slh36032.dll	: 1.0.2.0
slInit32.dll	: 1.1.3.0
slmaxv32.dll	: 1.0.4.0
sltshd32.dll	: 1.1.1.0
sluapo32.dll	: 1.3.4.0
SRSHp360.dll	: 1.1.0.0
SRSTSHD.dll	: 1.1.4.0
SRSTSXT.dll	: 3.2.0.0
SRSWOW.dll	: 1.1.3.0
WavesLib.dll	: 5.9.7.0
Vista/Win7 driver for x64	
RTKVHD64.sys	: 6.0.1.5859
AERTSr64.exe	: 1.0.64.9
APOPCH.exe	: 1.0.0.0
RAVCpl64.exe	: 1.0.0.353
RtkAudioService64.exe	: 1.0.0.19
RtlUpd64.exe	: 2.7.1.3
SkyTel.exe	: 2.0.2.2
vncutil64.exe	: 1.0.0.23
GWfilt64.sys	: 6.10.0.3
RTSnMg64.cpl	: 1.0.0.15
AERTAC64.dll	: 2.0.64.8
AERTAR64.dll	: 1.0.64.8
FMAP064.dll	: 0.0.14.1
MaxxAudioAP020.dll	: 2.2.2.0
MBAP032.dll	: 1.0.9.0
MBAP064.dll	: 1.0.9.0
MBPPcn64.dll	: 1.0.0.110
MBppld64.dll	: 1.0.9.0
MBWrp64.dll	: 1.0.0.110
RCoInst64.dll	: 1.0.5.8
RP3DAA64.dll	: 6.0.6001.18
RP3DHT64.dll	: 6.0.6001.18
RtCOMB4.dll	: 2.0.0.113
RTCOMDLL.dll	: 2.0.0.113
RtkApi64.dll	: 1.0.0.10
RtkAP064.dll	: 11.0.6000.99
RtkCfg.dll	: 1.0.0.1
RtkCfg64.dll	: 1.0.0.1
RtlCPAPI.dll	: 1.0.2.4
RtlCPAPI64.dll	: 1.0.2.4
RtPgEx64.dll	: 6.0.6000.79
SFComm64.dll	: 2.0.0.6
SFDAP064.dll	: 2.0.0.6
SFHAP064.dll	: 2.0.0.6
SFProc64.dll	: 2.0.0.6
SFSAP064.dll	: 2.0.0.6
slcshp64.dll	: 1.0.3.0
slgeq64.dll	: 1.0.1.0
slh36064.dll	: 1.0.2.0
slInit64.dll	: 1.1.3.0
slmaxv64.dll	: 1.0.4.0
sltshd64.dll	: 1.1.1.0
sluapo64.dll	: 1.3.4.0
SRSHp64.dll	: 1.1.0.0
SRSTSH64.dll	: 1.1.4.0
SRSTSx64.dll	: 3.2.0.0
SRSWOW64.dll	: 1.1.3.0

HDMI Driver : -----

Readme.txt

Vista/Win7 x86:
RtHDMV.sys : 6.0.1.5857
RtkUpd.exe : 2.7.1.3
RH3DAA32.dll : 6.0.6001.18
RH3DHT32.dll : 6.0.6001.18
RHCoInst.dll : 1.0.4.9
RHDMExt.dll : 6.0.6000.79
RtkHDM.dll : 11.0.6000.99

Vista/Win7 x64:
RtHDMVX.sys : 6.0.1.5857
RtkUpd64.exe : 2.7.1.3
RH3DAA64.dll : 6.0.6001.18
RH3DHT64.dll : 6.0.6001.18
RHCoInst64.dll : 1.0.4.4
RHDMEx64.dll : 6.0.6000.79
RtkHDM64.dll : 11.0.6000.99

XP/2K x86:
RtkHDM.sys : 5.10.0.5857
RtkUpd.exe : 2.7.1.3
RHCoInstXP.dll : 1.0.5.1

XP/2K x64:
RtkHDMX.sys : 5.10.0.5857
RtkUpd64.exe : 2.7.1.3
RHCoInst64XP.dll : 1.0.5.1

Driver Setup Program : 2.76

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.24

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 - x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Driver :
 1. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :
RTKHDA64.sys : 5.10.0.5854
RTKHDAUD.sys : 5.10.0.5854
McCal.exe : 1.1.2.1
RTHDCPL.exe : 2.2.8.8
RtkAudioService64.exe : 1.0.0.19
RtkAudioService.exe : 1.0.0.19
RTLCPPL.exe : 1.0.1.66
RtlUpd64.exe : 2.7.1.3
RtlUpd.exe : 2.7.1.3
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.32
vncutil64.exe : 1.0.0.23
vncutil.exe : 1.0.0.23
Alcmtr.exe : 1.6.0.4
AlcWzrd.exe : 1.1.0.37
Mnfiltr.sys : 5.10.0.4112
Mnft64.sys : 5.10.0.4115

```

Readme.txt
AMBfil t. sys : 5.10.0.4240
AMBft64. sys : 5.10.0.4240
RTSndMgr. cpl : 1.0.1.3
ALSndMgr. cpl : 1.0.0.11
RCoInst64XP. dll : 1.0.5.6
RTCOMDLL. dll : 1.0.0.102
RtkCoInstXP. dll : 1.0.5.6
RtlCPAPI. dll : 1.0.2.3
Vista driver : -----
Vista driver for x86
RTKVHDA. sys : 6.0.1.5854
AERTSrv. exe : 1.0.32.9
APOPCH. exe : 1.0.0.0
RtHDVCpl. exe : 1.0.0.352
RtkAudioService. exe : 1.0.0.19
RtlUpd. exe : 2.7.1.3
SkyTel. exe : 2.0.2.2
vncutil. exe : 1.0.0.23
RTSndMgr. cpl : 1.0.0.15
AERTACap. dll : 2.0.32.8
AERTARen. dll : 1.0.32.8
FMAP0. dll : 0.0.14.1
MaxxAudioAPO. dll : 1.2.2.0
MaxxAudioAPO20. dll : 2.2.2.0
MaxxAudioEQ. dll : 5.9.7.0
MBAP032. dll : 1.0.0.630
MBPPCn32. dll : 1.0.0.80
MBpld32. dll : 1.0.0.630
MBWrp32. dll : 1.0.0.80
RP3DAA32. dll : 6.0.6001.18
RP3DHT32. dll : 6.0.6001.18
RTCOMDLL. dll : 2.0.0.113
RtkAPO. dll : 11.0.6000.99
RtkApoApi. dll : 1.0.0.10
RtkCfg. dll : 1.0.0.1
RtkCoInst. dll : 1.0.5.7
RtkPgExt. dll : 6.0.6000.79
RtlCPAPI. dll : 1.0.2.4
SFFXComm. dll : 2.0.0.6
SFFXDAP0. dll : 2.0.0.6
SFFXHAP0. dll : 2.0.0.6
SFFXProc. dll : 2.0.0.6
SFFXSAP0. dll : 2.0.0.6
slcshp32. dll : 1.0.3.0
slgeq32. dll : 1.0.1.0
slh36032. dll : 1.0.2.0
slInit32. dll : 1.1.3.0
slmaxv32. dll : 1.0.4.0
sltshd32. dll : 1.1.1.0
sluapo32. dll : 1.3.4.0
SRSHP360. dll : 1.1.0.0
SRSTSHD. dll : 1.1.4.0
SRSTSXT. dll : 3.2.0.0
SRSWOW. dll : 1.1.3.0
WavesLib. dll : 5.9.7.0
Vista driver for x64
RTKVHD64. sys : 6.0.1.5854
AERTSr64. exe : 1.0.64.9
APOPCH. exe : 1.0.0.0
RAVCpl64. exe : 1.0.0.352
RtkAudioService64. exe : 1.0.0.19
RtlUpd64. exe : 2.7.1.3
SkyTel. exe : 2.0.2.2
vncutil64. exe : 1.0.0.23
GWfil64. sys : 6.10.0.3
RTSnMg64. cpl : 1.0.0.15
AERTAC64. dll : 2.0.64.8
AERTAR64. dll : 1.0.64.8
FMAP064. dll : 0.0.14.1

```

	Readme.txt	
MaxxAudioAP020.dll	:	2.2.2.0
MBAP032.dll	:	1.0.0.630
MBAP064.dll	:	1.0.0.630
MBPPCn64.dll	:	1.0.0.80
Mbpld64.dll	:	1.0.0.630
MBWrp64.dll	:	1.0.0.80
RCoInst64.dll	:	1.0.5.7
RP3DAA64.dll	:	6.0.6001.18
RP3DHT64.dll	:	6.0.6001.18
RtCOMB4.dll	:	2.0.0.113
RTCOMDLL.dll	:	2.0.0.113
RtkApi64.dll	:	1.0.0.10
RtkAP064.dll	:	11.0.6000.99
RtkCfg.dll	:	1.0.0.1
RtkCfg64.dll	:	1.0.0.1
RtLCPAPI.dll	:	1.0.2.4
RtLCPAPI64.dll	:	1.0.2.4
RtPgEx64.dll	:	6.0.6000.79
SFComm64.dll	:	2.0.0.6
SFDAPO64.dll	:	2.0.0.6
SFHAP064.dll	:	2.0.0.6
SFProc64.dll	:	2.0.0.6
SFSAP064.dll	:	2.0.0.6
slcshp64.dll	:	1.0.3.0
slgeq64.dll	:	1.0.1.0
slh36064.dll	:	1.0.2.0
slInit64.dll	:	1.1.3.0
slmaxv64.dll	:	1.0.4.0
sltshd64.dll	:	1.1.1.0
sluapo64.dll	:	1.3.4.0
SRSHP64.dll	:	1.1.0.0
SRSTSH64.dll	:	1.1.4.0
SRSTSX64.dll	:	3.2.0.0
SRSWOW64.dll	:	1.1.3.0
HDMI Driver : -----		
Vista x86:		
RtHDMV.sys	:	6.0.1.5832
RtkUpd.exe	:	2.7.1.3
RH3DAA32.dll	:	6.0.6001.18
RH3DHT32.dll	:	6.0.6001.18
RHCoInst.dll	:	1.0.4.9
RHDMExt.dll	:	6.0.6000.75
RtkHDM.dll	:	11.0.6000.95
Vista x64:		
RtHDMVX.sys	:	6.0.1.5832
RtkUpd64.exe	:	2.7.1.3
RH3DAA64.dll	:	6.0.6001.18
RH3DHT64.dll	:	6.0.6001.18
RHCoInst64.dll	:	1.0.4.4
RHDMEx64.dll	:	6.0.6000.75
RtkHDM64.dll	:	11.0.6000.95
XP/2K x86:		
RtkHDM.sys	:	5.10.0.5832
RtkUpd.exe	:	2.7.1.3
RHCoInstXP.dll	:	1.0.5.1
XP/2K x64:		
RtkHDMX.sys	:	5.10.0.5832
RtkUpd64.exe	:	2.7.1.3
RHCoInst64XP.dll	:	1.0.5.1
Driver Setup Program	:	2.76
Windows 2000/XP Operate on :		
Microsoft High Definition Audio Driver Package - KB888111		
Package file version (kb888111.exe) : 6.1.22.0		
Hdaudio.sys version : 5.10.00.5013		

Readme.txt

//=====

Driver Package R2.23

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 - x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Driver :
 1. Customizations.
 2. Fix DTM 1.4 lullaby test & wave pull mode test issue.

Windows 2000/XP : -----

Windows 2000/XP :

RTKHDA64.sys	: 5.10.0.5845
RTKHDAUD.sys	: 5.10.0.5845
Alcmtr.exe	: 1.6.0.4
AlcWzrd.exe	: 1.1.0.37
McCal.exe	: 1.1.2.1
RTHDCPL.exe	: 2.2.8.4
RtkAudioService64.exe	: 1.0.0.19
RtkAudioService.exe	: 1.0.0.19
RTLCPPL.exe	: 1.0.1.66
RtlUpd64.exe	: 2.7.1.3
RtlUpd.exe	: 2.7.1.3
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.32
vncutil64.exe	: 1.0.0.23
vncutil.exe	: 1.0.0.23
AMBFilt.sys	: 5.10.0.4240
AMBFt64.sys	: 5.10.0.4240
Mnft64.sys	: 5.10.0.4112
Mnft64.sys	: 5.10.0.4115
ALSndMgr.cpl	: 1.0.0.11
RTSndMgr.cpl	: 1.0.1.3
RCoInst64XP.dll	: 1.0.5.3
RTCOMDLL.dll	: 1.0.0.102
RtkCoInstXP.dll	: 1.0.5.3
RtlCPAPI.dll	: 1.0.2.3

Vista driver : -----

Vista driver for x86

RTKVHDA.sys	: 6.0.1.5845
AERTSrv.exe	: 1.0.32.9
APOPCH.exe	: 1.0.0.0
RtHDVCpl.exe	: 1.0.0.345
RtkAudioService.exe	: 1.0.0.19
RtlUpd.exe	: 2.7.1.3
SkyTel.exe	: 2.0.2.2
vncutil.exe	: 1.0.0.23
RTSndMgr.cpl	: 1.0.0.15
AERTACap.dll	: 2.0.32.8
AERTARen.dll	: 1.0.32.8
FMAPO.dll	: 0.0.14.1
MaxxAudioAPO.dll	: 1.2.2.0
MaxxAudioAPO20.dll	: 2.2.2.0
MaxxAudioEQ.dll	: 5.9.7.0
MBAPO32.dll	: 1.0.0.630
MBPPCn32.dll	: 1.0.0.80
MBpld32.dll	: 1.0.0.630
MBWrp32.dll	: 1.0.0.80
RP3DAA32.dll	: 6.0.6001.18
RP3DHT32.dll	: 6.0.6001.18
RTCOMDLL.dll	: 2.0.0.113
RtkAPO.dll	: 11.0.6000.98

	Readme.txt	
RtkApoApi.dll		: 1.0.0.10
RtkCfg.dll		: 1.0.0.1
RtkCoInst.dll		: 1.0.5.5
RtkPgExt.dll		: 6.0.6000.78
RtlCPAPI.dll		: 1.0.2.4
SFFXComm.dll		: 2.0.0.6
SFFXDAP0.dll		: 2.0.0.6
SFFXHAP0.dll		: 2.0.0.6
SFFXProc.dll		: 2.0.0.6
SFFXSAP0.dll		: 2.0.0.6
slcshp32.dll		: 1.0.3.0
slgeq32.dll		: 1.0.1.0
slh36032.dll		: 1.0.2.0
slInit32.dll		: 1.1.3.0
slmaxv32.dll		: 1.0.4.0
sltshd32.dll		: 1.1.1.0
sluapo32.dll		: 1.3.4.0
SRSHP360.dll		: 1.1.0.0
SRSTSHD.dll		: 1.1.4.0
SRSTSXT.dll		: 3.2.0.0
SRSWOW.dll		: 1.1.3.0
WavesLib.dll		: 5.9.7.0
Vista driver for x64		
RTKVHD64.sys		: 6.0.1.5845
AERTSr64.exe		: 1.0.64.9
APOPCH.exe		: 1.0.0.0
RAVCpl64.exe		: 1.0.0.345
RtkAudioService64.exe		: 1.0.0.19
RtlUpd64.exe		: 2.7.1.3
SkyTel.exe		: 2.0.2.2
vncutil64.exe		: 1.0.0.23
GWfilt64.sys		: 6.10.0.3
RTSnMg64.cpl		: 1.0.0.15
AERTAC64.dll		: 2.0.64.8
AERTAR64.dll		: 1.0.64.8
FMAP064.dll		: 0.0.14.1
MaxxAudioAPO20.dll		: 2.2.2.0
MBAP032.dll		: 1.0.0.630
MBAP064.dll		: 1.0.0.630
MBPPCn64.dll		: 1.0.0.80
Mbpld64.dll		: 1.0.0.630
MBWrp64.dll		: 1.0.0.80
RCoInst64.dll		: 1.0.5.5
RP3DAA64.dll		: 6.0.6001.18
RP3DHT64.dll		: 6.0.6001.18
RtCOMB4.dll		: 2.0.0.113
RTCOMDLL.dll		: 2.0.0.113
RtkApi64.dll		: 1.0.0.10
RtkAPO64.dll		: 11.0.6000.98
RtkCfg.dll		: 1.0.0.1
RtkCfg64.dll		: 1.0.0.1
RtlCPAPI.dll		: 1.0.2.4
RtlCPAPI64.dll		: 1.0.2.4
RtPgEx64.dll		: 6.0.6000.78
SFComm64.dll		: 2.0.0.6
SFDAP064.dll		: 2.0.0.6
SFHAP064.dll		: 2.0.0.6
SFProc64.dll		: 2.0.0.6
SFSAP064.dll		: 2.0.0.6
slcshp64.dll		: 1.0.3.0
slgeq64.dll		: 1.0.1.0
slh36064.dll		: 1.0.2.0
slInit64.dll		: 1.1.3.0
slmaxv64.dll		: 1.0.4.0
sltshd64.dll		: 1.1.1.0
sluapo64.dll		: 1.3.4.0
SRSHP64.dll		: 1.1.0.0
SRSTSH64.dll		: 1.1.4.0
SRSTSX64.dll		: 3.2.0.0

Readme.txt

SRSWOW64.dll : 1.1.3.0
HDM Driver : -----
Vista x86:
RtHDMV.sys : 6.0.1.5832
RtkUpd.exe : 2.7.1.3
RH3DAA32.dll : 6.0.6001.18
RH3DHT32.dll : 6.0.6001.18
RHCoInst.dll : 1.0.4.9
RHDMExt.dll : 6.0.6000.75
RtkHDM.dll : 11.0.6000.95

Vista x64:
RtHDMVX.sys : 6.0.1.5832
RtkUpd64.exe : 2.7.1.3
RH3DAA64.dll : 6.0.6001.18
RH3DHT64.dll : 6.0.6001.18
RHCoInst64.dll : 1.0.4.4
RHDMEx64.dll : 6.0.6000.75
RtkHDM64.dll : 11.0.6000.95

XP/2K x86:
RtkHDM.sys : 5.10.0.5832
RtkUpd.exe : 2.7.1.3
RHCoInstXP.dll : 1.0.5.1

XP/2K x64:
RtkHDMX.sys : 5.10.0.5832
RtkUpd64.exe : 2.7.1.3
RHCoInst64XP.dll : 1.0.5.1

Driver Setup Program : 2.75

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.22

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 - x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Driver :
 1. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :
RTKHDA64.sys : 5.10.0.5832
RTKHDAUD.sys : 5.10.0.5832
McCal.exe : 1.1.2.1
RTHDCPL.exe : 2.2.7.8
RtkAudioService64.exe : 1.0.0.19
RtkAudioService.exe : 1.0.0.19
RTLCPPL.exe : 1.0.1.66
RtlUpd64.exe : 2.7.1.3
RtlUpd.exe : 2.7.1.3
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.32
vncutil64.exe : 1.0.0.23
vncutil.exe : 1.0.0.23
Alcmtr.exe : 1.6.0.4
AlcWzrd.exe : 1.1.0.37

Readme.txt

```

Mnfil t. sys : 5.10.0.4112
Mnft64. sys : 5.10.0.4115
AMBFil t. sys : 5.10.0.4240
AMBft64. sys : 5.10.0.4240
RTSndMgr. cpl : 1.0.1.2
ALSndMgr. cpl : 1.0.0.11
RCoInst64XP. dll : 1.0.5.0
RTCOMDLL. dll : 1.0.0.101
RtkCoInstXP. dll : 1.0.5.0
RtlCPAPI. dll : 1.0.2.2
Vista driver : -----
Vista driver for x86
RTKVHDA. sys : 6.0.1.5832
AERTSrv. exe : 1.0.32.8
APOPCH. exe : 1.0.0.0
RtHDVCpl. exe : 1.0.0.334
RtkAudioService. exe : 1.0.0.19
RtlUpd. exe : 2.7.1.3
SkyTel. exe : 2.0.2.2
vncutil. exe : 1.0.0.23
RTSndMgr. cpl : 1.0.0.15
AERTACap. dll : 2.0.32.7
AERTARen. dll : 1.0.32.7
FMAP0. dll : 0.0.14.1
MaxxAudioAP0. dll : 1.2.2.0
MaxxAudioAP020. dll : 2.2.2.0
MaxxAudioEQ. dll : 5.9.7.0
MBAP032. dll : 1.0.0.630
MBPPCn32. dll : 1.0.0.80
MBpld32. dll : 1.0.0.630
MBWrp32. dll : 1.0.0.80
RP3DAA32. dll : 6.0.6001.18
RP3DHT32. dll : 6.0.6001.18
RTCOMDLL. dll : 2.0.0.111
RtkAPO. dll : 11.0.6000.95
RtkApoApi. dll : 1.0.0.10
RtkCfg. dll : 1.0.0.1
RtkCoInst. dll : 1.0.5.2
RtkPgExt. dll : 6.0.6000.75
RtlCPAPI. dll : 1.0.2.2
SFCPStr. dll : 1.1.0.3
SFFXComm. dll : 1.1.0.3
SFFXCP. dll : 1.1.0.3
SFFXLAP0. dll : 1.1.0.3
SFFXProc. dll : 1.1.0.3
SFFXSAP0. dll : 1.1.0.3
slcshp32. dll : 1.0.3.0
slgeq32. dll : 1.0.1.0
slh36032. dll : 1.0.2.0
slInit32. dll : 1.1.3.0
slmaxv32. dll : 1.0.4.0
sltshd32. dll : 1.1.1.0
sluapo32. dll : 1.3.4.0
SRSHP360. dll : 1.1.0.0
SRSTSHD. dll : 1.1.4.0
SRSTSXT. dll : 3.2.0.0
SRSWOW. dll : 1.1.3.0
WavesLib. dll : 5.9.7.0
Vista driver for x64
RTKVHD64. sys : 6.0.1.5832
AERTSr64. exe : 1.0.64.8
APOPCH. exe : 1.0.0.0
RAVCpl64. exe : 1.0.0.334
RtkAudioService64. exe : 1.0.0.19
RtlUpd64. exe : 2.7.1.3
SkyTel. exe : 2.0.2.2
vncutil64. exe : 1.0.0.23
GWfilt64. sys : 6.10.0.3
RTSnm64. cpl : 1.0.0.15

```

Readme.txt

AERTAC64.dll	: 2.0.64.7
AERTAR64.dll	: 1.0.64.7
FMAP064.dll	: 0.0.14.1
MaxxAudioAP020.dll	: 2.2.2.0
MBAP032.dll	: 1.0.0.630
MBAP064.dll	: 1.0.0.630
MBPPCn64.dll	: 1.0.0.80
MBpld64.dll	: 1.0.0.630
MBWrp64.dll	: 1.0.0.80
RCoInst64.dll	: 1.0.5.2
RP3DAA64.dll	: 6.0.6001.18
RP3DHT64.dll	: 6.0.6001.18
RtCOM64.dll	: 2.0.0.111
RTCOMDLL.dll	: 2.0.0.111
RtkApi64.dll	: 1.0.0.10
RtkAPO64.dll	: 11.0.6000.95
RtkCfg.dll	: 1.0.0.1
RtkCfg64.dll	: 1.0.0.1
RtLCPAPI.dll	: 1.0.2.2
RtLCPAPI64.dll	: 1.0.2.2
RtPgEx64.dll	: 6.0.6000.75
SFCOMM64.dll	: 1.1.0.3
SFCP64.dll	: 1.1.0.3
SFCPStr.dll	: 1.1.0.3
SFLAPO64.dll	: 1.1.0.3
SFProc64.dll	: 1.1.0.3
SFSAP064.dll	: 1.1.0.3
slcshp64.dll	: 1.0.3.0
slgeq64.dll	: 1.0.1.0
slh36064.dll	: 1.0.2.0
slInit64.dll	: 1.1.3.0
slmaxv64.dll	: 1.0.4.0
sltshd64.dll	: 1.1.1.0
sluapo64.dll	: 1.3.4.0
SRSHP64.dll	: 1.1.0.0
SRSTSH64.dll	: 1.1.4.0
SRSTSX64.dll	: 3.2.0.0
SRSWOW64.dll	: 1.1.3.0
HDMI Driver : -----	
Vista x86:	
RtHDMV.sys	: 6.0.1.5796
RtkUpd.exe	: 2.7.1.2
AHPCEE32.dll	: 6.0.6001.17
RHCoInst.dll	: 1.0.4.4
RHDMExt.dll	: 6.0.6000.69
RtkHDM.dll	: 11.0.6000.88
Vista x64:	
RtHDMVX.sys	: 6.0.1.5796
RtkUpd64.exe	: 2.7.1.2
AHPCEE64.dll	: 6.0.6001.17
RHCoInst64.dll	: 1.0.4.4
RHDMEx64.dll	: 6.0.6000.69
RtkHDM64.dll	: 11.0.6000.88
XP/2K x86:	
RtkHDM.sys	: 5.10.0.5796
RtkUpd.exe	: 2.7.1.2
XP/2K x64:	
RtkHDMX.sys	: 5.10.0.5796
RtkUpd64.exe	: 2.7.1.2
Driver Setup Program	: 2.75
Windows 2000/XP Operate on :	
Microsoft High Definition Audio Driver Package - KB888111	
Package file version (kb888111.exe) : 6.1.22.0	
Hdaudio.sys version : 5.10.00.5013	

Readme.txt

//=====

Driver Package R2.21

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 - x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Driver :
 1. Customizations.
 2. Support ALC275.

Windows 2000/XP : -----

Windows 2000/XP :

RTKHDA64.sys	: 5.10.0.5821
RTKHAUD.sys	: 5.10.0.5821
MicCal.exe	: 1.1.2.1
RTHDCPL.exe	: 2.2.7.5
RtkAudioService64.exe	: 1.0.0.19
RtkAudioService.exe	: 1.0.0.19
RTLCPPL.exe	: 1.0.1.66
RtlUpd64.exe	: 2.7.1.2
RtlUpd.exe	: 2.7.1.2
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.32
vncutil64.exe	: 1.0.0.23
vncutil.exe	: 1.0.0.23
Alcmtr.exe	: 1.6.0.4
AlcWzrd.exe	: 1.1.0.37
Mnfilt.sys	: 5.10.0.4112
Mnft64.sys	: 5.10.0.4115
AMBfilt.sys	: 5.10.0.4240
AMBft64.sys	: 5.10.0.4240
RTSndMgr.cpl	: 1.0.1.2
ALSndMgr.cpl	: 1.0.0.11
RCoInst64XP.dll	: 1.0.5.0
RTCOMDLL.dll	: 1.0.0.100
RtkCoInstXP.dll	: 1.0.5.0
RtlCPAPI.dll	: 1.0.2.2

Vista driver : -----

Vista driver for x86

RTKVHDA.sys	: 6.0.1.5821
AERTSrv.exe	: 1.0.32.8
APOPCH.exe	: 1.0.0.0
RtHDVCpl.exe	: 1.0.0.323
RtkAudioService.exe	: 1.0.0.19
RtlUpd.exe	: 2.7.1.2
SkyTel.exe	: 2.0.2.2
vncutil.exe	: 1.0.0.23
RTSndMgr.cpl	: 1.0.0.15
AERTACap.dll	: 2.0.32.7
AERTARen.dll	: 1.0.32.7
FMAPO.dll	: 0.0.14.1
MaxxAudioAPO.dll	: 1.2.2.0
MaxxAudioAPO20.dll	: 2.2.2.0
MaxxAudioEQ.dll	: 5.9.7.0
MBAPO32.dll	: 1.0.0.630
MBPPCn32.dll	: 1.0.0.80
MBpld32.dll	: 1.0.0.630
MBWrp32.dll	: 1.0.0.80
RTCOMDLL.dll	: 2.0.0.110
RtkAPO.dll	: 11.0.6000.90
RtkApoApi.dll	: 1.0.0.10
RtkCfg.dll	: 1.0.0.1

Readme.txt

RtkCoInst.dll	: 1.0.5.0
RtkPgExt.dll	: 6.0.6000.70
RtlCPAPI.dll	: 1.0.2.2
RTPCEE32.dll	: 6.0.6001.17
slcshp32.dll	: 1.0.3.0
slgeq32.dll	: 1.0.1.0
slh36032.dll	: 1.0.2.0
slInit32.dll	: 1.1.3.0
slmaxv32.dll	: 1.0.4.0
sltshd32.dll	: 1.1.1.0
sluapo32.dll	: 1.3.4.0
SRSHP360.dll	: 1.1.0.0
SRSTSHD.dll	: 1.1.4.0
SRSTSXT.dll	: 3.2.0.0
SRSWOW.dll	: 1.1.3.0
WavesLib.dll	: 5.9.7.0
Vista driver for x64	
RTKVHD64.sys	: 6.0.1.5821
AERTSr64.exe	: 1.0.64.8
APOPCH.exe	: 1.0.0.0
RAVCpl64.exe	: 1.0.0.323
RtkAudioService64.exe	: 1.0.0.19
RtlUpd64.exe	: 2.7.1.2
SkyTel.exe	: 2.0.2.2
vncutil64.exe	: 1.0.0.23
GWfilt64.sys	: 6.10.0.3
RTSnMg64.cpl	: 1.0.0.15
AERTAC64.dll	: 2.0.64.7
AERTAR64.dll	: 1.0.64.7
FMAP064.dll	: 0.0.14.1
MaxxAudioAP020.dll	: 2.2.2.0
MBAP032.dll	: 1.0.0.630
MBAP064.dll	: 1.0.0.630
MBPPCn64.dll	: 1.0.0.80
Mbpld64.dll	: 1.0.0.630
MBWrp64.dll	: 1.0.0.80
RCoInst64.dll	: 1.0.5.0
RtCOMB4.dll	: 2.0.0.110
RTCOMDLL.dll	: 2.0.0.110
RtkApi64.dll	: 1.0.0.10
RtkAP064.dll	: 11.0.6000.90
RtkCfg.dll	: 1.0.0.1
RtkCfg64.dll	: 1.0.0.1
RtlCPAPI.dll	: 1.0.2.2
RtlCPAPI64.dll	: 1.0.2.2
RTPCEE64.dll	: 6.0.6001.17
RtPgEx64.dll	: 6.0.6000.70
slcshp64.dll	: 1.0.3.0
slgeq64.dll	: 1.0.1.0
slh36064.dll	: 1.0.2.0
slInit64.dll	: 1.1.3.0
slmaxv64.dll	: 1.0.4.0
sltshd64.dll	: 1.1.1.0
sluapo64.dll	: 1.3.4.0
SRSHP64.dll	: 1.1.0.0
SRSTSH64.dll	: 1.1.4.0
SRSTSX64.dll	: 3.2.0.0
SRSWOW64.dll	: 1.1.3.0
HDMI Driver : -----	
Vista x86:	
RtHDMV.sys	: 6.0.1.5796
RtkUpd.exe	: 2.7.1.2
AHPCEE32.dll	: 6.0.6001.17
RHCoInst.dll	: 1.0.4.4
RHDMExt.dll	: 6.0.6000.69
RtkHDM.dll	: 11.0.6000.88
Vista x64:	
RtHDMVX.sys	: 6.0.1.5796

Readme.txt

RtkUpd64.exe : 2.7.1.2
 AHPCEE64.dll : 6.0.6001.17
 RHCoInst64.dll : 1.0.4.4
 RHDME64.dll : 6.0.6000.69
 RtkHDM64.dll : 11.0.6000.88

XP/2K x86:
 RtkHDM.sys : 5.10.0.5796
 RtkUpd.exe : 2.7.1.2

XP/2K x64:
 RtkHDMX.sys : 5.10.0.5796
 RtkUpd64.exe : 2.7.1.2

Driver Setup Program : 2.74

Windows 2000/XP Operate on :
 Microsoft High Definition Audio Driver Package - KB888111
 Package file version (kb888111.exe) : 6.1.22.0
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.20

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 - x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Driver :
 1. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :
 RTKHDA64.sys : 5.10.0.5817
 RTKHDAUD.sys : 5.10.0.5817
 Alcmtr.exe : 1.6.0.4
 AlcWzrd.exe : 1.1.0.37
 MicCal.exe : 1.1.2.1
 RTHDCPL.exe : 2.2.7.4
 RtkAudioService64.exe : 1.0.0.19
 RtkAudioService.exe : 1.0.0.19
 RTLCPL.exe : 1.0.1.66
 RtlUpd64.exe : 2.7.1.2
 RtlUpd.exe : 2.7.1.2
 SkyTel.exe : 2.0.2.0
 SoundMan.exe : 1.0.0.32
 vncutil64.exe : 1.0.0.23
 vncutil.exe : 1.0.0.23
 AMBFilt.sys : 5.10.0.4240
 AMBFt64.sys : 5.10.0.4240
 Mbnfilt.sys : 5.10.0.4112
 Mbnft64.sys : 5.10.0.4115
 ALSndMgr.cpl : 1.0.0.11
 RTSndMgr.cpl : 1.0.1.2
 RCoInst64XP.dll : 1.0.5.0
 RTCOMDLL.dll : 1.0.0.99
 RtkCoInstXP.dll : 1.0.5.0
 RtlCPAPI.dll : 1.0.2.2

Vista driver : -----

Vista driver for x86
 RTKVHDA.sys : 6.0.1.5817
 AERTSrv.exe : 1.0.32.8
 APOPCH.exe : 1.0.0.0

	Readme.txt	
RtHdVcPl.exe		: 1.0.0.319
RtkAudioService.exe		: 1.0.0.19
RtlUpd.exe		: 2.7.1.2
SkyTel.exe		: 2.0.2.2
vncutil.exe		: 1.0.0.23
RTSndMgr.cpl		: 1.0.0.15
AERTACap.dll		: 2.0.32.5
AERTARen.dll		: 1.0.32.7
FMAP0.dll		: 0.0.14.1
MaxxAudioAPO.dll		: 1.2.2.0
MaxxAudioAPO20.dll		: 2.2.2.0
MaxxAudioEQ.dll		: 5.9.7.0
MBAP032.dll		: 1.0.0.630
MBPPCn32.dll		: 1.0.0.80
MBpld32.dll		: 1.0.0.630
MBWrp32.dll		: 1.0.0.80
RTCOMDLL.dll		: 2.0.0.109
RtkAPO.dll		: 11.0.6000.90
RtkApoApi.dll		: 1.0.0.10
RtkCfg.dll		: 1.0.0.1
RtkCoInst.dll		: 1.0.5.0
RtkPgExt.dll		: 6.0.6000.70
RtlCPAPI.dll		: 1.0.2.2
RTPCEE32.dll		: 6.0.6001.17
slcshp32.dll		: 1.0.3.0
slgeq32.dll		: 1.0.1.0
slh36032.dll		: 1.0.2.0
slInit32.dll		: 1.1.1.0
sltshd32.dll		: 1.1.0.0
sluapo32.dll		: 1.2.6.0
SRSHP360.dll		: 1.1.0.0
SRSTSHD.dll		: 1.1.4.0
SRSTSXT.dll		: 3.2.0.0
SRSWOW.dll		: 1.1.3.0
WavesLib.dll		: 5.9.7.0
Vista driver for x64		
RTKVHD64.sys		: 6.0.1.5817
AERTSr64.exe		: 1.0.64.8
APOPCH.exe		: 1.0.0.0
RAVCpl64.exe		: 1.0.0.319
RtkAudioService64.exe		: 1.0.0.19
RtlUpd64.exe		: 2.7.1.2
SkyTel.exe		: 2.0.2.2
vncutil64.exe		: 1.0.0.23
GWfilt64.sys		: 6.10.0.3
RTSnm64.cpl		: 1.0.0.15
AERTAC64.dll		: 2.0.64.1
AERTAR64.dll		: 1.0.64.7
FMAP064.dll		: 0.0.14.1
MaxxAudioAPO20.dll		: 2.2.2.0
MBAP032.dll		: 1.0.0.630
MBAP064.dll		: 1.0.0.630
MBPPCn64.dll		: 1.0.0.80
MBpld64.dll		: 1.0.0.630
MBWrp64.dll		: 1.0.0.80
RCoInst64.dll		: 1.0.5.0
RtCOM64.dll		: 2.0.0.109
RTCOMDLL.dll		: 2.0.0.109
RtkApi64.dll		: 1.0.0.10
RtkAPO64.dll		: 11.0.6000.90
RtkCfg.dll		: 1.0.0.1
RtkCfg64.dll		: 1.0.0.1
RtlCPAPI.dll		: 1.0.2.2
RtlCPAPI64.dll		: 1.0.2.2
RTPCEE64.dll		: 6.0.6001.17
RtPgEx64.dll		: 6.0.6000.70
slcshp64.dll		: 1.0.3.0
slgeq64.dll		: 1.0.1.0
slh36064.dll		: 1.0.2.0

Readme.txt

```

slInit64.dll           : 1.1.1.0
sltshd64.dll          : 1.1.0.0
sluapo64.dll          : 1.2.6.0
SRSHp64.dll           : 1.1.0.0
SRSTSH64.dll          : 1.1.4.0
SRSTX64.dll           : 3.2.0.0
SRSWOW64.dll          : 1.1.3.0
HDM Driver : -----
Vista x86:
RtHDM.V.sys           : 6.0.1.5796
RtkUpd.exe            : 2.7.1.2
AHPCEE32.dll          : 6.0.6001.17
RHCoInst.dll          : 1.0.4.4
RHDMExt.dll           : 6.0.6000.69
RtkHDM.dll            : 11.0.6000.88

Vista x64:
RtHDM.VX.sys          : 6.0.1.5796
RtkUpd64.exe          : 2.7.1.2
AHPCEE64.dll          : 6.0.6001.17
RHCoInst64.dll        : 1.0.4.4
RHDMEx64.dll          : 6.0.6000.69
RtkHDM64.dll          : 11.0.6000.88

XP/2K x86:
RtkHDM.sys            : 5.10.0.5796
RtkUpd.exe            : 2.7.1.2

XP/2K x64:
RtkHDMX.sys           : 5.10.0.5796
RtkUpd64.exe          : 2.7.1.2

Driver Setup Program  : 2.74

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

```

//=====

Driver Package R2.19

- Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .
1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
 2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
 3. HDM Device WHQL Support: ATI HDM Devices
 4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista, Windows7 x86/x64
 5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
 6. Add/Fix
 - 1.) Driver :
 1. Customizations.
 - 2.) Package :
 1. Fix upgraded warning dialog for Small VGA mode .
 2. Add failed run installation by count .

Windows 2000/XP : -----

```

Windows 2000/XP :
RTKHDA64.sys          : 5.10.0.5809
RTKHDAUD.sys          : 5.10.0.5809
Alcmtr.exe            : 1.6.0.4
AlcWzrd.exe           : 1.1.0.37
McCal.exe             : 1.1.2.1
RTHDCPL.exe           : 2.2.7.1
RtkAudioService64.exe : 1.0.0.17
RtkAudioService.exe  : 1.0.0.16
RTLCPPL.exe           : 1.0.1.66
RtlUpd64.exe          : 2.7.1.2
RtlUpd.exe            : 2.7.1.2

```

	Readme.txt	
SkyTel.exe	:	2.0.2.0
SoundMan.exe	:	1.0.0.32
vncutil64.exe	:	1.0.0.23
vncutil.exe	:	1.0.0.23
AMBfilt.sys	:	5.10.0.4240
AMBft64.sys	:	5.10.0.4240
Mnfilt.sys	:	5.10.0.4112
Mnft64.sys	:	5.10.0.4115
ALSndMgr.cpl	:	1.0.0.11
RTSndMgr.cpl	:	1.0.1.0
RCoInst64XP.dll	:	1.0.4.9
RTCOMDLL.dll	:	1.0.0.99
RtkCoInstXP.dll	:	1.0.4.9
RtlCPAPI.dll	:	1.0.2.2
Vista driver :	-----	
Vista driver for x86		
RTKVHDA.sys	:	6.0.1.5809
AERTSrv.exe	:	1.0.32.8
APOPCH.exe	:	1.0.0.0
RtHDVCpl.exe	:	1.0.0.314
RtkAudioService.exe	:	1.0.0.17
RtlUpd.exe	:	2.7.1.2
SkyTel.exe	:	2.0.2.2
vncutil.exe	:	1.0.0.23
RTSndMgr.cpl	:	1.0.0.15
AERTACap.dll	:	2.0.32.1
AERTARen.dll	:	1.0.32.7
FMAP0.dll	:	0.0.14.1
MaxxAudioAPO.dll	:	1.2.2.0
MaxxAudioAPO20.dll	:	2.2.2.0
MaxxAudioEQ.dll	:	5.9.7.0
MBAP032.dll	:	1.0.0.630
MBPPCn32.dll	:	1.0.0.80
MBpld32.dll	:	1.0.0.630
MBWrp32.dll	:	1.0.0.80
RTCOMDLL.dll	:	2.0.0.109
RtkAPO.dll	:	11.0.6000.89
RtkApoApi.dll	:	1.0.0.10
RtkCfg.dll	:	1.0.0.1
RtkCoInst.dll	:	1.0.4.9
RtkPgExt.dll	:	6.0.6000.70
RtlCPAPI.dll	:	1.0.2.2
RTPCEE32.dll	:	6.0.6001.17
slcshp32.dll	:	1.0.3.0
slgeq32.dll	:	1.0.1.0
slh36032.dll	:	1.0.2.0
slinit32.dll	:	1.1.1.0
sltshd32.dll	:	1.1.0.0
sluapo32.dll	:	1.2.6.0
SRSHP360.dll	:	1.1.0.0
SRSTSHD.dll	:	1.1.4.0
SRSTSXT.dll	:	3.2.0.0
SRSWOW.dll	:	1.1.3.0
WavesLib.dll	:	5.9.7.0
Vista driver for x64		
RTKVHD64.sys	:	6.0.1.5809
AERTSr64.exe	:	1.0.64.8
APOPCH.exe	:	1.0.0.0
RAVCpl64.exe	:	1.0.0.314
RtkAudioService64.exe	:	1.0.0.17
RtlUpd64.exe	:	2.7.1.2
SkyTel.exe	:	2.0.2.2
vncutil64.exe	:	1.0.0.23
GWfilt64.sys	:	6.10.0.3
RTSnMg64.cpl	:	1.0.0.15
AERTAC64.dll	:	2.0.64.1
AERTAR64.dll	:	1.0.64.7
FMAP064.dll	:	0.0.14.1
MaxxAudioAPO20.dll	:	2.2.2.0

Readme.txt

```

MBAP032.dll : 1.0.0.630
MBAP064.dll : 1.0.0.630
MBPPCn64.dll : 1.0.0.80
MBpld64.dll : 1.0.0.630
MBWrp64.dll : 1.0.0.80
RCoInst64.dll : 1.0.4.9
RtCOM64.dll : 2.0.0.109
RTCOMDLL.dll : 2.0.0.109
RtkApi64.dll : 1.0.0.10
RtkAP064.dll : 11.0.6000.89
RtkCfg.dll : 1.0.0.1
RtkCfg64.dll : 1.0.0.1
RtLCPAPI.dll : 1.0.2.2
RtLCPAPI64.dll : 1.0.2.2
RTPCEE64.dll : 6.0.6001.17
RtPgEx64.dll : 6.0.6000.70
slcshp64.dll : 1.0.3.0
slgeq64.dll : 1.0.1.0
slh36064.dll : 1.0.2.0
slInit64.dll : 1.1.1.0
sltshd64.dll : 1.1.0.0
sluapo64.dll : 1.2.6.0
SRSHP64.dll : 1.1.0.0
SRSTSH64.dll : 1.1.4.0
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
HDMI Driver : -----
Vista x86:
RtHDMV.sys : 6.0.1.5796
RtkUpd.exe : 2.7.1.2
AHPCEE32.dll : 6.0.6001.17
RHCoInst.dll : 1.0.4.4
RHDMExt.dll : 6.0.6000.69
RtkHDM.dll : 11.0.6000.88

Vista x64:
RtHDMVX.sys : 6.0.1.5796
RtkUpd64.exe : 2.7.1.2
AHPCEE64.dll : 6.0.6001.17
RHCoInst64.dll : 1.0.4.4
RHDMEx64.dll : 6.0.6000.69
RtkHDM64.dll : 11.0.6000.88

XP/2K x86:
RtkHDM.sys : 5.10.0.5796
RtkUpd.exe : 2.7.1.2

XP/2K x64:
RtkHDMX.sys : 5.10.0.5796
RtkUpd64.exe : 2.7.1.2

Driver Setup Program : 2.73

```

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.18

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/Wi nXP/Wi n2000/Wi n2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista, Windows7 x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix

Readme.txt

- 1.) Driver :
 1. Customizations.
- 2.) Package :
 1. Support driver folder of Windows Server 2008 in package .
 2. Disable Status Dialog when small VGA Mode enabled .
 3. Fix CreativeUp folder disappear issue .

Windows 2000/XP : -----

Windows 2000/XP :

RTKHDA64.sys	: 5.10.0.5804
RTKHDAUD.sys	: 5.10.0.5804
MicCal.exe	: 1.1.2.0
RTHDCPL.exe	: 2.2.6.9
RtkAudioService64.exe	: 1.0.0.17
RtkAudioService.exe	: 1.0.0.16
RTLCPLEX.exe	: 1.0.1.66
RtlUpd64.exe	: 2.7.1.2
RtlUpd.exe	: 2.7.1.2
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.32
vncutil64.exe	: 1.0.0.23
vncutil.exe	: 1.0.0.23
Alcmtr.exe	: 1.6.0.4
AlcWzrd.exe	: 1.1.0.37
Mnft64.sys	: 5.10.0.4112
Mnft64.sys	: 5.10.0.4115
AMBFilt.sys	: 5.10.0.4240
AMBFt64.sys	: 5.10.0.4240
RTSndMgr.cpl	: 1.0.1.0
ALSndMgr.cpl	: 1.0.0.11
RCoInst64XP.dll	: 1.0.4.8
RTCOMDLL.dll	: 1.0.0.98
RtkCoInstXP.dll	: 1.0.4.8
RtlCPAPI.dll	: 1.0.2.1

Vista driver : -----

Vista driver for x86

RTKVHDA.sys	: 6.0.1.5804
AERTSrv.exe	: 1.0.32.8
APOPCH.exe	: 1.0.0.0
RtHDVCpl.exe	: 1.0.0.311
RtkAudioService.exe	: 1.0.0.17
RtlUpd.exe	: 2.7.1.2
SkyTel.exe	: 2.0.2.2
vncutil.exe	: 1.0.0.23
RTSndMgr.cpl	: 1.0.0.15
AERTACap.dll	: 2.0.32.1
AERTARen.dll	: 1.0.32.7
FMAPO.dll	: 0.0.14.1
MaxxAudioAPO.dll	: 1.2.2.0
MaxxAudioAPO20.dll	: 2.2.2.0
MaxxAudioEQ.dll	: 5.9.7.0
MBAPO32.dll	: 1.0.0.630
MBPPCn32.dll	: 1.0.0.80
MBpld32.dll	: 1.0.0.630
MBWrp32.dll	: 1.0.0.80
RTCOMDLL.dll	: 2.0.0.108
RtkAPO.dll	: 11.0.6000.89
RtkApoApi.dll	: 1.0.0.10
RtkCfg.dll	: 1.0.0.1
RtkCoInst.dll	: 1.0.4.8
RtkPgExt.dll	: 6.0.6000.69
RtlCPAPI.dll	: 1.0.2.1
RTPCEE32.dll	: 6.0.6001.17
slcshp32.dll	: 1.0.3.0
slgeq32.dll	: 1.0.1.0
slh36032.dll	: 1.0.2.0
slinit32.dll	: 1.1.1.0
sltshd32.dll	: 1.1.0.0
sluapo32.dll	: 1.2.6.0

Readme.txt

SRSHp360.dll	: 1.1.0.0
SRSTSHD.dll	: 1.1.4.0
SRSTSXT.dll	: 3.2.0.0
SRSWOW.dll	: 1.1.3.0
WavesLib.dll	: 5.9.7.0
Vista driver for x64	
RTKVHD64.sys	: 6.0.1.5804
AERTSr64.exe	: 1.0.64.8
APOPCH.exe	: 1.0.0.0
RAVCpl64.exe	: 1.0.0.311
RtkAudioService64.exe	: 1.0.0.17
RtlUpd64.exe	: 2.7.1.2
SkyTel.exe	: 2.0.2.2
vncutil64.exe	: 1.0.0.23
GWfilt64.sys	: 6.10.0.3
RTSnMg64.cpl	: 1.0.0.15
AERTAC64.dll	: 2.0.64.1
AERTAR64.dll	: 1.0.64.7
FMAP064.dll	: 0.0.14.1
MaxxAudioAP020.dll	: 2.2.2.0
MBAP032.dll	: 1.0.0.630
MBAP064.dll	: 1.0.0.630
MBPPCn64.dll	: 1.0.0.80
MBpld64.dll	: 1.0.0.630
MBWrp64.dll	: 1.0.0.80
RCoInst64.dll	: 1.0.4.8
RtCOM64.dll	: 2.0.0.108
RTCOMDLL.dll	: 2.0.0.108
RtkApi64.dll	: 1.0.0.10
RtkAPO64.dll	: 11.0.6000.89
RtkCfg.dll	: 1.0.0.1
RtkCfg64.dll	: 1.0.0.1
RtlCPAPI.dll	: 1.0.2.1
RtlCPAPI64.dll	: 1.0.2.1
RTPCEE64.dll	: 6.0.6001.17
RtPgEx64.dll	: 6.0.6000.69
slcshp64.dll	: 1.0.3.0
slgeq64.dll	: 1.0.1.0
slh36064.dll	: 1.0.2.0
slInit64.dll	: 1.1.1.0
sltshd64.dll	: 1.1.0.0
sluapo64.dll	: 1.2.6.0
SRSHp64.dll	: 1.1.0.0
SRSTSH64.dll	: 1.1.4.0
SRSTSx64.dll	: 3.2.0.0
SRSWOW64.dll	: 1.1.3.0
HDMI Driver : -----	
Vista x86:	
RtHDMV.sys	: 6.0.1.5796
RtkUpd.exe	: 2.7.1.2
AHPCEE32.dll	: 6.0.6001.17
RHCoInst.dll	: 1.0.4.4
RHDMExt.dll	: 6.0.6000.69
RtkHDM.dll	: 11.0.6000.88
Vista x64:	
RtHDMVX.sys	: 6.0.1.5796
RtkUpd64.exe	: 2.7.1.2
AHPCEE64.dll	: 6.0.6001.17
RHCoInst64.dll	: 1.0.4.4
RHDMEx64.dll	: 6.0.6000.69
RtkHDM64.dll	: 11.0.6000.88
XP/2K x86:	
RtkHDM.sys	: 5.10.0.5796
RtkUpd.exe	: 2.7.1.2
XP/2K x64:	
RtkHDMX.sys	: 5.10.0.5796

Readme.txt

RtkUpd64.exe : 2.7.1.2

Driver Setup Program : 2.72

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.17

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista, Windows7 x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :

RTKHDA64.sys : 5.10.0.5794
RTKHDAUD.sys : 5.10.0.5794
McCal.exe : 1.1.2.0
RTHDCPL.exe : 2.2.6.5
RtkAudioService64.exe : 1.0.0.17
RtkAudioService.exe : 1.0.0.16
RTLCPLEX.exe : 1.0.1.66
RtlUpd64.exe : 2.7.1.2
RtlUpd.exe : 2.7.1.2
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.32
vncutil64.exe : 1.0.0.23
vncutil.exe : 1.0.0.23
Alcmtr.exe : 1.6.0.3
AlcWzrd.exe : 1.1.0.37
Mnft64.sys : 5.10.0.4112
Mnft64.sys : 5.10.0.4115
AMBfilt.sys : 5.10.0.4240
AMBft64.sys : 5.10.0.4240
RTSndMgr.cpl : 1.0.1.0
ALSndMgr.cpl : 1.0.0.11
RCoInst64XP.dll : 1.0.4.8
RTCOMDLL.dll : 1.0.0.97
RtkCoInstXP.dll : 1.0.4.8
RtlCPAPI.dll : 1.0.2.1

Vista driver : -----

Vista driver for x86

RTKVHDA.sys : 6.0.1.5794
AERTSrv.exe : 1.0.32.8
APOPCH.exe : 1.0.0.0
RtHDVCpl.exe : 1.0.0.306
RtkAudioService.exe : 1.0.0.17
RtlUpd.exe : 2.7.1.2
SkyTel.exe : 2.0.2.2
vncutil.exe : 1.0.0.23
RTSndMgr.cpl : 1.0.0.15
AERTACap.dll : 2.0.32.1
AERTARen.dll : 1.0.32.7
FMPO.dll : 0.0.14.1
MaxxAudioAPO.dll : 1.2.2.0
MaxxAudioAPO20.dll : 2.2.2.0
MaxxAudioEQ.dll : 5.9.7.0
MBAPO32.dll : 1.0.0.630
MBPPCn32.dll : 1.0.0.80

	Readme.txt	: 1.0.0.630
Mbpld32.dll		: 1.0.0.80
MBWrp32.dll		: 2.0.0.106
RTCOMDLL.dll		: 11.0.6000.88
RtkAPO.dll		: 1.0.0.10
RtkApoApi.dll		: 1.0.0.1
RtkCfg.dll		: 1.0.4.8
RtkCoInst.dll		: 6.0.6000.69
RtkPgExt.dll		: 1.0.2.1
RtLCPAPI.dll		: 6.0.6001.17
RTPCEE32.dll		: 1.0.3.0
slcshp32.dll		: 1.0.1.0
slgeq32.dll		: 1.0.2.0
slh36032.dll		: 1.1.1.0
slInit32.dll		: 1.1.0.0
sltshd32.dll		: 1.2.6.0
sluapo32.dll		: 1.1.0.0
SRSHP360.dll		: 1.1.4.0
SRSTSHD.dll		: 3.2.0.0
SRSTSXT.dll		: 1.1.3.0
SRSWOW.dll		: 5.9.7.0
WavesLib.dll		
Vista driver for x64		
RTKVHD64.sys		: 6.0.1.5794
AERTSr64.exe		: 1.0.64.8
APOPCH.exe		: 1.0.0.0
RAVCpl64.exe		: 1.0.0.306
RtkAudioService64.exe		: 1.0.0.17
RtlUpd64.exe		: 2.7.1.2
SkyTel.exe		: 2.0.2.2
vncutil64.exe		: 1.0.0.23
GWfilt64.sys		: 6.10.0.3
RTSnMg64.cpl		: 1.0.0.15
AERTAC64.dll		: 2.0.64.1
AERTAR64.dll		: 1.0.64.7
FMAP064.dll		: 0.0.14.1
MaxxAudioAP020.dll		: 2.2.2.0
MBAP032.dll		: 1.0.0.630
MBAP064.dll		: 1.0.0.630
MBPPCn64.dll		: 1.0.0.80
Mbpld64.dll		: 1.0.0.630
MBWrp64.dll		: 1.0.0.80
RCoInst64.dll		: 1.0.4.8
RtCOM64.dll		: 2.0.0.106
RTCOMDLL.dll		: 2.0.0.106
RtkApi64.dll		: 1.0.0.10
RtkAPO64.dll		: 11.0.6000.88
RtkCfg.dll		: 1.0.0.1
RtkCfg64.dll		: 1.0.0.1
RtLCPAPI.dll		: 1.0.2.1
RtLCPAPI64.dll		: 1.0.2.1
RTPCEE64.dll		: 6.0.6001.17
RtPgEx64.dll		: 6.0.6000.69
slcshp64.dll		: 1.0.3.0
slgeq64.dll		: 1.0.1.0
slh36064.dll		: 1.0.2.0
slInit64.dll		: 1.1.1.0
sltshd64.dll		: 1.1.0.0
sluapo64.dll		: 1.2.6.0
SRSHP64.dll		: 1.1.0.0
SRSTSH64.dll		: 1.1.4.0
SRSTSX64.dll		: 3.2.0.0
SRSWOW64.dll		: 1.1.3.0
HDMI Driver : -----		
Vista x86:		
RtHDMV.sys		: 6.0.1.5766
RtkUpd.exe		: 2.7.1.1
RHCoInst.dll		: 1.0.3.2
RHDMExt.dll		: 6.0.6000.66
RtkHDM.dll		: 11.0.6000.85

Readme.txt

Vista x64:
RtHDM VX. sys : 6.0.1.5766
RtkUpd64.exe : 2.7.1.1
RHCoInst64.dll : 1.0.3.2
RHDME64.dll : 6.0.6000.66
RtkHDM64.dll : 11.0.6000.85

XP/2K x86:
RtkHDM. sys : 5.10.0.5766
RtkUpd.exe : 2.7.1.1

XP/2K x64:
RtHDMX. sys : 5.10.0.5766
RtkUpd64.exe : 2.7.1.1

Driver Setup Program : 2.70

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.16

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista, Windows7 x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix

1.) Driver :

1. Customizations.
2. Update directsound acceleration engine for XP driver.

Windows 2000/XP : -----

Windows 2000/XP :
RTKHDA64.sys : 5.10.0.5791
RTKHDAUD.sys : 5.10.0.5791
McCal.exe : 1.1.2.0
RTHDCPL.exe : 2.2.6.3
RtkAudioService64.exe : 1.0.0.17
RtkAudioService.exe : 1.0.0.16
RTLCPPL.exe : 1.0.1.66
RtlUpd64.exe : 2.7.1.2
RtlUpd.exe : 2.7.1.2
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.32
vncutil64.exe : 1.0.0.23
vncutil.exe : 1.0.0.23
Alcmtr.exe : 1.6.0.3
AlcWzrd.exe : 1.1.0.37
Mnfilt.sys : 5.10.0.4112
Mnft64.sys : 5.10.0.4115
AMBfilt.sys : 5.10.0.4240
AMBft64.sys : 5.10.0.4240
RTSndMgr.cpl : 1.0.1.0
ALSndMgr.cpl : 1.0.0.11
RCoInst64XP.dll : 1.0.4.8
RTCOMDLL.dll : 1.0.0.97
RtkCoInstXP.dll : 1.0.4.8
RtlCPAPI.dll : 1.0.2.1

Vista driver : -----

Vista driver for x86
RTKVHDA.sys : 6.0.1.5791
AERTSrv.exe : 1.0.32.8

	Readme.txt	
APOPCH.exe		: 1.0.0.0
RtHdVcpl.exe		: 1.0.0.304
RtkAudioService.exe		: 1.0.0.17
RtlUpd.exe		: 2.7.1.2
SkyTel.exe		: 2.0.2.2
vncutil.exe		: 1.0.0.23
RTSndMgr.cpl		: 1.0.0.15
AERTACap.dll		: 2.0.32.1
AERTARen.dll		: 1.0.32.7
FMAP0.dll		: 0.0.14.1
MaxxAudioAPO.dll		: 1.2.2.0
MaxxAudioAPO20.dll		: 2.2.2.0
MaxxAudioEQ.dll		: 5.9.7.0
MBAP032.dll		: 1.0.0.630
MBPPCn32.dll		: 1.0.0.80
MBpld32.dll		: 1.0.0.630
MBWrp32.dll		: 1.0.0.80
RTCOMDLL.dll		: 2.0.0.106
RtkAPO.dll		: 11.0.6000.88
RtkApoApi.dll		: 1.0.0.10
RtkCfg.dll		: 1.0.0.1
RtkCoInst.dll		: 1.0.4.8
RtkPgExt.dll		: 6.0.6000.69
RtlCPAPI.dll		: 1.0.2.1
RTPCEE32.dll		: 6.0.6001.17
slcshp32.dll		: 1.0.3.0
slgeq32.dll		: 1.0.1.0
slh36032.dll		: 1.0.2.0
slinit32.dll		: 1.1.1.0
sltshd32.dll		: 1.1.0.0
sluapo32.dll		: 1.2.6.0
SRSHP360.dll		: 1.1.0.0
SRSTSHD.dll		: 1.1.4.0
SRSTSXT.dll		: 3.2.0.0
SRSWOW.dll		: 1.1.3.0
WavesLib.dll		: 5.9.7.0
Vista driver for x64		
RTKVHD64.sys		: 6.0.1.5791
AERTSr64.exe		: 1.0.64.8
APOPCH.exe		: 1.0.0.0
RAVCpl64.exe		: 1.0.0.304
RtkAudioService64.exe		: 1.0.0.17
RtlUpd64.exe		: 2.7.1.2
SkyTel.exe		: 2.0.2.2
vncutil64.exe		: 1.0.0.23
GWfilt64.sys		: 6.10.0.3
RTSndMgr64.cpl		: 1.0.0.15
AERTAC64.dll		: 2.0.64.1
AERTAR64.dll		: 1.0.64.7
FMAP064.dll		: 0.0.14.1
MaxxAudioAPO20.dll		: 2.2.2.0
MBAP032.dll		: 1.0.0.630
MBAP064.dll		: 1.0.0.630
MBPPCn64.dll		: 1.0.0.80
MBpld64.dll		: 1.0.0.630
MBWrp64.dll		: 1.0.0.80
RCoInst64.dll		: 1.0.4.8
RtCOMB4.dll		: 2.0.0.106
RTCOMDLL.dll		: 2.0.0.106
RtkApi64.dll		: 1.0.0.10
RtkAPO64.dll		: 11.0.6000.88
RtkCfg.dll		: 1.0.0.1
RtkCfg64.dll		: 1.0.0.1
RtlCPAPI.dll		: 1.0.2.1
RtlCPAPI64.dll		: 1.0.2.1
RTPCEE64.dll		: 6.0.6001.17
RtPgEx64.dll		: 6.0.6000.69
slcshp64.dll		: 1.0.3.0
slgeq64.dll		: 1.0.1.0

Readme.txt

```

slh36064.dll           : 1.0.2.0
slInit64.dll           : 1.1.1.0
sltshd64.dll           : 1.1.0.0
sluapo64.dll           : 1.2.6.0
SRSHp64.dll           : 1.1.0.0
SRSTSH64.dll          : 1.1.4.0
SRSTSX64.dll          : 3.2.0.0
SRSWOW64.dll          : 1.1.3.0
HDMI Driver : -----
Vista x86:
RtHDMV.sys            : 6.0.1.5766
RtkUpd.exe            : 2.7.1.1
RHCoInst.dll         : 1.0.3.2
RHDMExt.dll           : 6.0.6000.66
RtkHDM.dll           : 11.0.6000.85

Vista x64:
RtHDMVX.sys          : 6.0.1.5766
RtkUpd64.exe         : 2.7.1.1
RHCoInst64.dll       : 1.0.3.2
RHDMEx64.dll         : 6.0.6000.66
RtkHDM64.dll         : 11.0.6000.85

XP/2K x86:
RtkHDM.sys           : 5.10.0.5766
RtkUpd.exe           : 2.7.1.1

XP/2K x64:
RtHDMX.sys           : 5.10.0.5766
RtkUpd64.exe         : 2.7.1.1

Driver Setup Program : 2.70

```

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.15

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/Wi nXP/Wi n2000/Wi n2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix

- 1.) Driver :
 1. Customizations.
 2. Change Creative components for the certain customers.
- 2.) Package :
 1. Change Japanese language on finish Dialog of installation .
 2. Fix DCC uninstalled issue. Both MSI and GUID uninstllation procedure supported .
 3. Fix uninstll problem in Windows 7 . The DIFxAPI DLL file supported in Windows 7 .

Windows 2000/XP : -----

```

Windows 2000/XP :
RTKHDA64.sys        : 5.10.0.5783
RTKHDAUD.sys        : 5.10.0.5783
McCal.exe           : 1.1.2.0
RTHDCPL.exe         : 2.2.6.2
RtkAudioService64.exe : 1.0.0.17
RtkAudioService.exe : 1.0.0.16
RTLCPPL.exe         : 1.0.1.66
RtlUpd64.exe        : 2.7.1.2
RtlUpd.exe          : 2.7.1.2
SkyTel.exe          : 2.0.2.0

```

```

Readme.txt
SoundMan.exe : 1.0.0.32
vncutil64.exe : 1.0.0.23
vncutil.exe : 1.0.0.23
Alcmtr.exe : 1.6.0.3
AlcWzrd.exe : 1.1.0.37
Mnfiltr.sys : 5.10.0.4112
Mnft64.sys : 5.10.0.4115
AMBfiltr.sys : 5.10.0.4240
AMBft64.sys : 5.10.0.4240
RTSndMgr.cpl : 1.0.1.0
ALSndMgr.cpl : 1.0.0.11
RCoInst64XP.dll : 1.0.4.8
RTCOMDLL.dll : 1.0.0.97
RtkCoInstXP.dll : 1.0.4.8
RtlCPAPI.dll : 1.0.1.9
Vista driver : -----
Vista driver for x86
RTKVHDA.sys : 6.0.1.5783
AERTSrv.exe : 1.0.32.8
APOPCH.exe : 1.0.0.0
RtHDVCpl.exe : 1.0.0.300
RtkAudioService.exe : 1.0.0.17
RtlUpd.exe : 2.7.1.2
SkyTel.exe : 2.0.2.2
vncutil.exe : 1.0.0.23
RTSndMgr.cpl : 1.0.0.13
AERTACap.dll : 2.0.32.1
AERTARen.dll : 1.0.32.7
FNAP0.dll : 0.0.12.1
MaxxAudioAPO.dll : 1.2.2.0
MaxxAudioAPO20.dll : 2.2.2.0
MaxxAudioEQ.dll : 5.9.7.0
MBAP032.dll : 1.0.0.630
MBPPCn32.dll : 1.0.0.80
MBppld32.dll : 1.0.0.630
MBWrp32.dll : 1.0.0.80
RTCOMDLL.dll : 2.0.0.106
RtkAPO.dll : 11.0.6000.87
RtkApoApi.dll : 1.0.0.10
RtkCfg.dll : 1.0.0.1
RtkColnst.dll : 1.0.4.8
RtkPgExt.dll : 6.0.6000.67
RtlCPAPI.dll : 1.0.2.1
RTPCEE32.dll : 6.0.6001.14
slcshp32.dll : 1.0.3.0
slgeq32.dll : 1.0.1.0
slh36032.dll : 1.0.2.0
slInit32.dll : 1.1.1.0
sltshd32.dll : 1.1.0.0
sluapo32.dll : 1.2.6.0
SRSHP360.dll : 1.1.0.0
SRSTSHD.dll : 1.1.4.0
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.1.3.0
WavesLib.dll : 5.9.7.0
Vista driver for x64
RTKVHD64.sys : 6.0.1.5783
AERTSr64.exe : 1.0.64.8
APOPCH.exe : 1.0.0.0
RAVCpl64.exe : 1.0.0.300
RtkAudioService64.exe : 1.0.0.17
RtlUpd64.exe : 2.7.1.2
SkyTel.exe : 2.0.2.2
vncutil64.exe : 1.0.0.23
GWfiltr64.sys : 6.10.0.3
RTSnMg64.cpl : 1.0.0.13
AERTAC64.dll : 2.0.64.1
AERTAR64.dll : 1.0.64.7
FNAP064.dll : 0.0.12.1

```

```

Readme.txt
MaxxAudioAP020.dll : 2.2.2.0
MBAP032.dll : 1.0.0.630
MBAP064.dll : 1.0.0.630
MBPPCn64.dll : 1.0.0.80
Mbppld64.dll : 1.0.0.630
MBWrp64.dll : 1.0.0.80
RCoInst64.dll : 1.0.4.8
RtCOMB4.dll : 2.0.0.106
RTCOMDLL.dll : 2.0.0.106
RtkApi64.dll : 1.0.0.10
RtkAP064.dll : 11.0.6000.87
RtkCfg.dll : 1.0.0.1
RtkCfg64.dll : 1.0.0.1
RtlCPAPI.dll : 1.0.2.1
RtlCPAPI64.dll : 1.0.2.1
RTPCEE64.dll : 6.0.6001.14
RtPgEx64.dll : 6.0.6000.67
slcshp64.dll : 1.0.3.0
slgeq64.dll : 1.0.1.0
slh36064.dll : 1.0.2.0
slInit64.dll : 1.1.1.0
sltshd64.dll : 1.1.0.0
sluapo64.dll : 1.2.6.0
SRSHp64.dll : 1.1.0.0
SRSTSH64.dll : 1.1.4.0
SRSTX64.dll : 3.2.0.0
SRSW064.dll : 1.1.3.0
HDMI Driver : -----
Vista x86:
RtHDMV.sys : 6.0.1.5766
RtkUpd.exe : 2.7.1.1
RHCoInst.dll : 1.0.3.2
RHDMExt.dll : 6.0.6000.66
RtkHDM.dll : 11.0.6000.85

Vista x64:
RtHDMVX.sys : 6.0.1.5766
RtkUpd64.exe : 2.7.1.1
RHCoInst64.dll : 1.0.3.2
RHDMEx64.dll : 6.0.6000.66
RtkHDM64.dll : 11.0.6000.85

XP/2K x86:
RtkHDM.sys : 5.10.0.5766
RtkUpd.exe : 2.7.1.1

XP/2K x64:
RtHDMX.sys : 5.10.0.5766
RtkUpd64.exe : 2.7.1.1

Driver Setup Program : 2.70

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

```

//=====

Driver Package R2.14

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Driver :

Readme.txt

1. Customizations.
2. Change EAPD control method for the certain codecs.

```

Windows 2000/XP : -----
Windows 2000/XP :
RTKHDA64.sys      : 5.10.0.5772
RTKHDAUD.sys     : 5.10.0.5772
Alcmtr.exe       : 1.6.0.3
AlcWzrd.exe      : 1.1.0.37
Mccal.exe        : 1.1.2.0
RTHDCPL.exe      : 2.2.5.9
RtkAudioService64.exe : 1.0.0.17
RtkAudioService.exe : 1.0.0.16
RTLCPPL.exe      : 1.0.1.66
RtlUpd64.exe     : 2.7.1.1
RtlUpd.exe       : 2.7.1.1
SkyTel.exe       : 2.0.2.0
SoundMan.exe     : 1.0.0.32
vncutil64.exe    : 1.0.0.23
vncutil.exe      : 1.0.0.23
AMBfilt64.sys   : 5.10.0.4240
AMBfilt.sys     : 5.10.0.4240
Mbnfilt64.sys   : 5.10.0.4115
Mbnfilt.sys     : 5.10.0.4112
ALSndMgr.cpl    : 1.0.0.11
RTSndMgr.cpl    : 1.0.1.0
RCoInst64XP.dll : 1.0.4.4
RTCOMDLL.dll    : 1.0.0.97
RtkCoInstXP.dll : 1.0.4.4
RtlCPAPI.dll    : 1.0.1.9

Vista driver : -----
Vista driver for x86
RTKVHDA.sys      : 6.0.1.5772
AERTSrv.exe      : 1.0.32.8
RtHDVCpl.exe     : 1.0.0.291
RtkAudioService.exe : 1.0.0.17
RtlUpd.exe       : 2.7.1.1
SkyTel.exe       : 2.0.2.2
vncutil.exe      : 1.0.0.23
RTSndMgr.cpl    : 1.0.0.13
AERTACap.dll    : 2.0.32.1
AERTARen.dll    : 1.0.32.7
CTAP032.dll     : 1.0.0.530
ctpld.dll       : 1.0.0.530
DaisyWrp.dll    : 1.0.0.70
FMAP0.dll       : 0.0.12.1
MaxxAudioAPO.dll : 1.2.2.0
MaxxAudioAPO20.dll : 2.2.2.0
MaxxAudioEQ.dll : 5.9.7.0
ppchain.dll     : 1.0.0.70
RTCOMDLL.dll    : 2.0.0.105
RtkAPO.dll      : 11.0.6000.85
RtkApoApi.dll   : 1.0.0.9
RtkCfg.dll      : 1.0.0.1
RtkCoInst.dll   : 1.0.4.4
RtkPgExt.dll    : 6.0.6000.66
RtlCPAPI.dll    : 1.0.2.1
slcshp32.dll    : 1.0.3.0
slgeq32.dll     : 1.0.1.0
slh36032.dll    : 1.0.2.0
slinit32.dll    : 1.1.1.0
sltshd32.dll    : 1.1.0.0
sluapo32.dll    : 1.2.6.0
SRSHP360.dll    : 1.1.0.0
SRSTSHD.dll     : 1.1.4.0
SRSTSXT.dll     : 3.2.0.0
SRSWOW.dll      : 1.1.3.0
WavesLib.dll    : 5.9.7.0
Vista driver for x64

```

```

Readme.txt
RTKVHD64.sys : 6.0.1.5772
AERTSr64.exe : 1.0.64.8
RAVCpl64.exe : 1.0.0.291
RtkAudioService64.exe : 1.0.0.17
RtlUpd64.exe : 2.7.1.1
SkyTel.exe : 2.0.2.2
vncutil64.exe : 1.0.0.23
GWfilt64.sys : 6.10.0.3
RTSnMg64.cpl : 1.0.0.13
AERTAC64.dll : 2.0.64.1
AERTAR64.dll : 1.0.64.7
CTAP032.dll : 1.0.0.530
CTAP064.dll : 1.0.0.530
ctpld.dll : 1.0.0.530
DaisyWrp.dll : 1.0.0.70
FMAP064.dll : 0.0.12.1
MaxxAudioAP020.dll : 2.2.2.0
ppchain.dll : 1.0.0.70
RCoInst64.dll : 1.0.4.4
RtCOMB4.dll : 2.0.0.105
RtCOMDLL.dll : 2.0.0.105
RtkApi64.dll : 1.0.0.9
RtkAPO64.dll : 11.0.6000.85
RtkCfg.dll : 1.0.0.1
RtkCfg64.dll : 1.0.0.1
RtlCPAPI.dll : 1.0.2.1
RtlCPAPI64.dll : 1.0.2.1
RtPgEx64.dll : 6.0.6000.66
slcshp64.dll : 1.0.3.0
slgeq64.dll : 1.0.1.0
slh36064.dll : 1.0.2.0
slInit64.dll : 1.1.1.0
sltshd64.dll : 1.1.0.0
sluapo64.dll : 1.2.6.0
SRSHP64.dll : 1.1.0.0
SRSTSH64.dll : 1.1.4.0
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
HDMI Driver : -----
Vista x86:
RtHDMV.sys : 6.0.1.5766
RtkUpd.exe : 2.7.1.1
RHCoInst.dll : 1.0.3.2
RHDMExt.dll : 6.0.6000.66
RtkHDM.dll : 11.0.6000.85

Vista x64:
RtHDMVX.sys : 6.0.1.5766
RtkUpd64.exe : 2.7.1.1
RHCoInst64.dll : 1.0.3.2
RHDMEx64.dll : 6.0.6000.66
RtkHDM64.dll : 11.0.6000.85

XP/2K x86:
RtkHDM.sys : 5.10.0.5766
RtkUpd.exe : 2.7.1.1

XP/2K x64:
RtHDMX.sys : 5.10.0.5766
RtkUpd64.exe : 2.7.1.1

Driver Setup Program : 2.69

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

```

//=====

Readme.txt

Driver Package R2.13

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Driver :
 1. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :

RTKHDA64.sys	: 5.10.0.5767
RTKHDAUD.sys	: 5.10.0.5767
MicCal.exe	: 1.1.2.0
RTHDCPL.exe	: 2.2.5.8
RtkAudioService64.exe	: 1.0.0.17
RtkAudioService.exe	: 1.0.0.16
RTLCPPL.exe	: 1.0.1.66
RtlUpd64.exe	: 2.7.1.1
RtlUpd.exe	: 2.7.1.1
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.32
vncutil64.exe	: 1.0.0.23
vncutil.exe	: 1.0.0.23
Alcmtr.exe	: 1.6.0.3
AlcWzrd.exe	: 1.1.0.37
AMBFilt64.sys	: 5.10.0.4240
AMBFilt.sys	: 5.10.0.4240
Mnfil64.sys	: 5.10.0.4115
Mnfil.sys	: 5.10.0.4112
RTSndMgr.cpl	: 1.0.1.0
ALSndMgr.cpl	: 1.0.0.11
RCoInst64XP.dll	: 1.0.4.3
RTCOMDLL.dll	: 1.0.0.97
RtkCoInstXP.dll	: 1.0.4.3
RtlCPAPI.dll	: 1.0.1.9

Vista driver : -----

Vista driver for x86

RTKVHDA.sys	: 6.0.1.5767
AERTSrv.exe	: 1.0.32.8
RtHDVCpl.exe	: 1.0.0.288
RtkAudioService.exe	: 1.0.0.17
RtlUpd.exe	: 2.7.1.1
SkyTel.exe	: 2.0.2.2
vncutil.exe	: 1.0.0.23
RTSndMgr.cpl	: 1.0.0.13
AERTACap.dll	: 2.0.32.1
AERTARen.dll	: 1.0.32.7
CTAP032.dll	: 1.0.0.530
ctpld.dll	: 1.0.0.530
DaisyWrp.dll	: 1.0.0.70
FMAP0.dll	: 0.0.12.1
MaxxAudioAPO.dll	: 1.2.2.0
MaxxAudioAPO20.dll	: 2.2.2.0
MaxxAudioEQ.dll	: 5.9.7.0
ppchain.dll	: 1.0.0.70
RTCOMDLL.dll	: 2.0.0.105
RtkAPO.dll	: 11.0.6000.85
RtkApoApi.dll	: 1.0.0.9
RtkCfg.dll	: 1.0.0.1
RtkCoInst.dll	: 1.0.4.3
RtkPgExt.dll	: 6.0.6000.66
RtlCPAPI.dll	: 1.0.2.1
slcshp32.dll	: 1.0.3.0
slgeq32.dll	: 1.0.1.0

	Readme.txt	
slh36032.dll	:	1.0.2.0
slInit32.dll	:	1.1.1.0
sltshd32.dll	:	1.1.0.0
sluapo32.dll	:	1.2.6.0
SRSHP360.dll	:	1.1.0.0
SRSTSHD.dll	:	1.1.4.0
SRSTSXT.dll	:	3.2.0.0
SRSWOW.dll	:	1.1.3.0
WavesLib.dll	:	5.9.7.0
Vista driver for x64		
RTKVHD64.sys	:	6.0.1.5767
AERTSr64.exe	:	1.0.64.8
RAVCpl64.exe	:	1.0.0.288
RtkAudioService64.exe	:	1.0.0.17
RtlUpd64.exe	:	2.7.1.1
SkyTel.exe	:	2.0.2.2
vncutil64.exe	:	1.0.0.23
GWfilt64.sys	:	6.10.0.3
RTSnMg64.cpl	:	1.0.0.13
AERTAC64.dll	:	2.0.64.1
AERTAR64.dll	:	1.0.64.7
CTAP032.dll	:	1.0.0.530
CTAP064.dll	:	1.0.0.530
ctpld.dll	:	1.0.0.530
DaisyWrp.dll	:	1.0.0.70
FMAP064.dll	:	0.0.12.1
MaxxAudioAP020.dll	:	2.2.2.0
ppchain.dll	:	1.0.0.70
RCoInst64.dll	:	1.0.4.3
RtCOMB4.dll	:	2.0.0.105
RTCOMDLL.dll	:	2.0.0.105
RtkApi64.dll	:	1.0.0.9
RtkAP064.dll	:	11.0.6000.85
RtkCfg.dll	:	1.0.0.1
RtkCfg64.dll	:	1.0.0.1
RtlCPAPI.dll	:	1.0.2.1
RtlCPAPI64.dll	:	1.0.2.1
RtPgEx64.dll	:	6.0.6000.66
slcshp64.dll	:	1.0.3.0
slgeq64.dll	:	1.0.1.0
slh36064.dll	:	1.0.2.0
slInit64.dll	:	1.1.1.0
sltshd64.dll	:	1.1.0.0
sluapo64.dll	:	1.2.6.0
SRSHP64.dll	:	1.1.0.0
SRSTSH64.dll	:	1.1.4.0
SRSTSX64.dll	:	3.2.0.0
SRSWOW64.dll	:	1.1.3.0
HDMI Driver :	-----	
Vista x86:		
RtHDMV.sys	:	6.0.1.5766
RtkUpd.exe	:	2.7.1.1
RHCoInst.dll	:	1.0.3.2
RHDMExt.dll	:	6.0.6000.66
RtkHDM.dll	:	11.0.6000.85
Vista x64:		
RtHDMVX.sys	:	6.0.1.5766
RtkUpd64.exe	:	2.7.1.1
RHCoInst64.dll	:	1.0.3.2
RHDMEx64.dll	:	6.0.6000.66
RtkHDM64.dll	:	11.0.6000.85
XP/2K x86:		
RtkHDM.sys	:	5.10.0.5766
RtkUpd.exe	:	2.7.1.1
XP/2K x64:		
RtHDMX.sys	:	5.10.0.5766

Readme.txt

RtkUpd64.exe : 2.7.1.1

Driver Setup Program : 2.69

Windows 2000/XP Operate on :
 Microsoft High Definition Audio Driver Package - KB888111
 Package file version (kb888111.exe) : 6.1.22.0
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.12

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Driver :
 1. Customizations.
 2. Support encryption feature for ALC670.

Windows 2000/XP : -----

Windows 2000/XP :

RTKHDA64.sys	: 5.10.0.5764
RTKHDAUD.sys	: 5.10.0.5764
Alcmtr.exe	: 1.6.0.3
AlcWzrd.exe	: 1.1.0.37
McCal.exe	: 1.1.2.0
RTHDCPL.exe	: 2.2.5.6
RtkAudioService64.exe	: 1.0.0.17
RtkAudioService.exe	: 1.0.0.16
RTLCPPL.exe	: 1.0.1.66
RtlUpd64.exe	: 2.7.1.1
RtlUpd.exe	: 2.7.1.1
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.32
vncutil64.exe	: 1.0.0.23
vncutil.exe	: 1.0.0.23
AMBfilt64.sys	: 5.10.0.4240
AMBfilt.sys	: 5.10.0.4240
Mbnfilt64.sys	: 5.10.0.4115
Mbnfilt.sys	: 5.10.0.4112
ALSndMgr.cpl	: 1.0.0.11
RTSndMgr.cpl	: 1.0.1.0
RCoInst64XP.dll	: 1.0.4.3
RTCOMDLL.dll	: 1.0.0.97
RtkCoInstXP.dll	: 1.0.4.3
RtlCPAPI.dll	: 1.0.1.9

Vista driver : -----

Vista driver for x86

RTKVHDA.sys	: 6.0.1.5764
AERTSrv.exe	: 1.0.32.8
RtHDVCpl.exe	: 1.0.0.286
RtkAudioService.exe	: 1.0.0.17
RtlUpd.exe	: 2.7.1.1
SkyTel.exe	: 2.0.2.2
vncutil.exe	: 1.0.0.23
RTSndMgr.cpl	: 1.0.0.13
AERTACap.dll	: 2.0.32.1
AERTARen.dll	: 1.0.32.7
CTAP032.dll	: 1.0.0.530
ctpld.dll	: 1.0.0.530
DaisyWrp.dll	: 1.0.0.70
FMAPO.dll	: 0.0.12.1
MaxxAudioAPO.dll	: 1.2.2.0

	Readme.txt	
MaxxAudioAP020.dll	:	2.2.2.0
MaxxAudioEQ.dll	:	5.9.7.0
ppchain.dll	:	1.0.0.70
RTCOMDLL.dll	:	2.0.0.105
RtkAPO.dll	:	11.0.6000.85
RtkApoApi.dll	:	1.0.0.9
RtkCfg.dll	:	1.0.0.1
RtkCoInst.dll	:	1.0.4.3
RtkPgExt.dll	:	6.0.6000.66
RtLCPAPI.dll	:	1.0.2.1
slcshp32.dll	:	1.0.3.0
slgeq32.dll	:	1.0.1.0
slh36032.dll	:	1.0.2.0
slInit32.dll	:	1.1.1.0
sltshd32.dll	:	1.1.0.0
sluapo32.dll	:	1.2.6.0
SRSH360.dll	:	1.1.0.0
SRSTSHD.dll	:	1.1.4.0
SRSTSXT.dll	:	3.2.0.0
SRSWOW.dll	:	1.1.3.0
WavesLib.dll	:	5.9.7.0
Vista driver for x64		
RTKVHD64.sys	:	6.0.1.5764
AERTSr64.exe	:	1.0.64.8
RAVCpl64.exe	:	1.0.0.286
RtkAudioService64.exe	:	1.0.0.17
RtlUpd64.exe	:	2.7.1.1
SkyTel.exe	:	2.0.2.2
vncutil64.exe	:	1.0.0.23
GWfilt64.sys	:	6.10.0.3
RTSnMg64.cpl	:	1.0.0.13
AERTAC64.dll	:	2.0.64.1
AERTAR64.dll	:	1.0.64.7
CTAP032.dll	:	1.0.0.530
CTAP064.dll	:	1.0.0.530
ctpld.dll	:	1.0.0.530
DaisyWrp.dll	:	1.0.0.70
FMAP064.dll	:	0.0.12.1
MaxxAudioAP020.dll	:	2.2.2.0
ppchain.dll	:	1.0.0.70
RCoInst64.dll	:	1.0.4.3
RtCOMB4.dll	:	2.0.0.105
RTCOMDLL.dll	:	2.0.0.105
RtkApi64.dll	:	1.0.0.9
RtkAPO64.dll	:	11.0.6000.85
RtkCfg.dll	:	1.0.0.1
RtkCfg64.dll	:	1.0.0.1
RtLCPAPI.dll	:	1.0.2.1
RtLCPAPI64.dll	:	1.0.2.1
RtPgEx64.dll	:	6.0.6000.66
slcshp64.dll	:	1.0.3.0
slgeq64.dll	:	1.0.1.0
slh36064.dll	:	1.0.2.0
slInit64.dll	:	1.1.1.0
sltshd64.dll	:	1.1.0.0
sluapo64.dll	:	1.2.6.0
SRSH64.dll	:	1.1.0.0
SRSTSH64.dll	:	1.1.4.0
SRSTSX64.dll	:	3.2.0.0
SRSWOW64.dll	:	1.1.3.0
HDMI Driver :	-----	
Vista x86:		
RtHDMV.sys	:	6.0.1.5735
RtkUpd.exe	:	2.7.1.1
RHCoInst.dll	:	1.0.3.2
RHDMExt.dll	:	6.0.6000.64
RtkHDM.dll	:	11.0.6000.80

Readme.txt

Vista x64:
 RtHDM VX. sys : 6.0.1.5735
 RtkUpd64.exe : 2.7.1.1
 RHCoInst64.dll : 1.0.3.2
 RHDME64.dll : 6.0.6000.64
 RtkHDM64.dll : 11.0.6000.80

XP/2K x86:
 RtHDM.sys : 5.10.0.5735
 RtkUpd.exe : 2.7.1.1
 XP/2K x64:
 RtHDMX.sys : 5.10.0.5735
 RtkUpd64.exe : 2.7.1.1

Driver Setup Program : 2.69

Windows 2000/XP Operate on :
 Microsoft High Definition Audio Driver Package - KB888111
 Package file version (kb888111.exe) : 6.1.22.0
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.11

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC272, ALC273, ALC887
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Driver :
 1. Customizations.
 2. Add DisplayVersion registry key in INF files.

Windows 2000/XP : -----

Windows 2000/XP :
 RTKHDA64.sys : 5.10.0.5755
 RTKHDAUD.sys : 5.10.0.5755
 Alcmtr.exe : 1.6.0.3
 AlcWzrd.exe : 1.1.0.37
 MicCal.exe : 1.1.2.0
 RTHDCPL.exe : 2.2.5.5
 RtkAudioService64.exe : 1.0.0.17
 RtkAudioService.exe : 1.0.0.16
 RTLCPL.exe : 1.0.1.66
 RtlUpd64.exe : 2.7.1.1
 RtlUpd.exe : 2.7.1.1
 SkyTel.exe : 2.0.2.0
 SoundMan.exe : 1.0.0.32
 vncutil64.exe : 1.0.0.22
 vncutil.exe : 1.0.0.22
 AMBFilt64.sys : 5.10.0.4240
 AMBFilt.sys : 5.10.0.4240
 Mbnfilt64.sys : 5.10.0.4115
 Mbnfilt.sys : 5.10.0.4112
 ALSndMgr.cpl : 1.0.0.11
 RTSndMgr.cpl : 1.0.1.0
 RCoInst64XP.dll : 1.0.4.1
 RTCOMDLL.dll : 1.0.0.97
 RtkCoInstXP.dll : 1.0.4.1
 RtlCPAPI.dll : 1.0.1.9

Vista driver : -----

Vista driver for x86
 RTKVHDA.sys : 6.0.1.5755
 AERTSrv.exe : 1.0.32.8
 RtHDVCpl.exe : 1.0.0.281

	Readme.txt	
RtkAudioService.exe	:	1.0.0.17
RtlUpd.exe	:	2.7.1.1
SkyTel.exe	:	2.0.2.2
vncutil.exe	:	1.0.0.23
RTSndMgr.cpl	:	1.0.0.13
AERTACap.dll	:	2.0.32.1
AERTARen.dll	:	1.0.32.7
CTAP032.dll	:	1.0.0.530
ctpld.dll	:	1.0.0.530
DaisyWrp.dll	:	1.0.0.70
FMAP0.dll	:	0.0.12.1
MaxxAudioAPO.dll	:	1.2.2.0
MaxxAudioAPO20.dll	:	2.2.2.0
MaxxAudioEQ.dll	:	5.9.7.0
ppchain.dll	:	1.0.0.70
RTCOMDLL.dll	:	2.0.0.103
RtkAPO.dll	:	11.0.6000.81
RtkApoApi.dll	:	1.0.0.9
RtkCfg.dll	:	1.0.0.1
RtkCoInst.dll	:	1.0.4.1
RtkPgExt.dll	:	6.0.6000.65
RtlCPAPI.dll	:	1.0.2.1
slcshp32.dll	:	1.0.3.0
slgeq32.dll	:	1.0.1.0
slh36032.dll	:	1.0.2.0
slInit32.dll	:	1.1.1.0
sltshd32.dll	:	1.1.0.0
sluapo32.dll	:	1.2.6.0
SRSHP360.dll	:	1.1.0.0
SRSTSHD.dll	:	1.1.4.0
SRSTSXT.dll	:	3.2.0.0
SRSWOW.dll	:	1.1.3.0
WavesLib.dll	:	5.9.7.0
Vista driver for x64		
RTKVHD64.sys	:	6.0.1.5755
AERTSr64.exe	:	1.0.64.8
RAVCpl64.exe	:	1.0.0.281
RtkAudioService64.exe	:	1.0.0.17
RtlUpd64.exe	:	2.7.1.1
SkyTel.exe	:	2.0.2.2
vncutil64.exe	:	1.0.0.23
GWfilt64.sys	:	6.10.0.3
RTSndMgr64.cpl	:	1.0.0.13
AERTAC64.dll	:	2.0.64.1
AERTAR64.dll	:	1.0.64.7
CTAP032.dll	:	1.0.0.530
CTAP064.dll	:	1.0.0.530
ctpld.dll	:	1.0.0.530
DaisyWrp.dll	:	1.0.0.70
FMAP064.dll	:	0.0.12.1
MaxxAudioAPO20.dll	:	2.2.2.0
ppchain.dll	:	1.0.0.70
RCoInst64.dll	:	1.0.4.1
RtCOMB4.dll	:	2.0.0.103
RTCOMDLL.dll	:	2.0.0.103
RtkApi64.dll	:	1.0.0.9
RtkAPO64.dll	:	11.0.6000.81
RtkCfg.dll	:	1.0.0.1
RtkCfg64.dll	:	1.0.0.1
RtlCPAPI.dll	:	1.0.2.1
RtlCPAPI64.dll	:	1.0.2.1
RtPgEx64.dll	:	6.0.6000.65
slcshp64.dll	:	1.0.3.0
slgeq64.dll	:	1.0.1.0
slh36064.dll	:	1.0.2.0
slInit64.dll	:	1.1.1.0
sltshd64.dll	:	1.1.0.0
sluapo64.dll	:	1.2.6.0
SRSHP64.dll	:	1.1.0.0

Readme.txt

SRSTSH64.dll : 1.1.4.0
 SRSTX64.dll : 3.2.0.0
 SRSWOW64.dll : 1.1.3.0

HDMI Driver : -----
 Vista x86:
 RtHDMV.sys : 6.0.1.5735
 RtkUpd.exe : 2.7.1.1
 RHCoInst.dll : 1.0.3.2
 RHDMEExt.dll : 6.0.6000.64
 RtkHDM.dll : 11.0.6000.80

Vista x64:
 RtHDMVX.sys : 6.0.1.5735
 RtkUpd64.exe : 2.7.1.1
 RHCoInst64.dll : 1.0.3.2
 RHDMEExt64.dll : 6.0.6000.64
 RtkHDM64.dll : 11.0.6000.80

XP/2K x86:
 RtHDM.sys : 5.10.0.5735
 RtkUpd.exe : 2.7.1.1
 XP/2K x64:
 RtHDMX.sys : 5.10.0.5735
 RtkUpd64.exe : 2.7.1.1

Driver Setup Program : 2.69

Windows 2000/XP Operate on :
 Microsoft High Definition Audio Driver Package - KB888111
 Package file version (kb888111.exe) : 6.1.22.0
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.10

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Driver :
 1. Customizations.
 2. Support ALC665.

Windows 2000/XP : -----

Windows 2000/XP :
 RTKHDA64.sys : 5.10.0.5745
 RTKHDAUD.sys : 5.10.0.5745
 McCal.exe : 1.1.2.0
 RTHDCPL.exe : 2.2.5.2
 RtkAudioService64.exe : 1.0.0.17
 RtkAudioService.exe : 1.0.0.16
 RTLCPL.exe : 1.0.1.66
 RtlUpd64.exe : 2.7.1.1
 RtlUpd.exe : 2.7.1.1
 SkyTel.exe : 2.0.2.0
 SoundMan.exe : 1.0.0.32
 vncutil64.exe : 1.0.0.22
 vncutil.exe : 1.0.0.22
 Alcmtr.exe : 1.6.0.3
 AlcWzrd.exe : 1.1.0.37
 AMBFilt64.sys : 5.10.0.4240
 AMBFilt.sys : 5.10.0.4240

Readme.txt

```

Mnfil t64.sys : 5.10.0.4115
Mnfil t.sys : 5.10.0.4112
RTSndMgr.cpl : 1.0.1.0
ALSndMgr.cpl : 1.0.0.11
RCoInst64XP.dll : 1.0.4.1
RTCOMDLL.dll : 1.0.0.97
RtkCoInstXP.dll : 1.0.4.1
RtlCPAPI.dll : 1.0.1.9
Vista driver : -----
Vista driver for x86
RTKVHDA.sys : 6.0.1.5745
AERTSrv.exe : 1.0.32.8
RtHDVCpl.exe : 1.0.0.273
RtkAudioService.exe : 1.0.0.17
RtlUpd.exe : 2.7.1.1
SkyTel.exe : 2.0.2.2
vncutil.exe : 1.0.0.22
RTSndMgr.cpl : 1.0.0.13
AERTACap.dll : 2.0.32.1
AERTARen.dll : 1.0.32.7
CTAP032.dll : 1.0.0.530
ctpld.dll : 1.0.0.530
DaisyWrp.dll : 1.0.0.70
FMAP0.dll : 0.0.12.1
MaxxAudioAP0.dll : 1.2.2.0
MaxxAudioAP020.dll : 2.2.2.0
MaxxAudioEQ.dll : 5.9.7.0
ppchain.dll : 1.0.0.70
RCoInst64.dll : 1.0.4.0
RTCOMDLL.dll : 2.0.0.103
RtkAP0.dll : 11.0.6000.81
RtkApoApi.dll : 1.0.0.9
RtkCfg.dll : 1.0.0.1
RtkCoInst.dll : 1.0.4.1
RtkPgExt.dll : 6.0.6000.65
RtlCPAPI.dll : 1.0.2.1
slcshp32.dll : 1.0.3.0
slgeq32.dll : 1.0.1.0
slh36032.dll : 1.0.2.0
slInit32.dll : 1.1.1.0
sltshd32.dll : 1.1.0.0
sluapo32.dll : 1.2.6.0
SRSHP360.dll : 1.1.0.0
SRSTSHD.dll : 1.1.4.0
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.1.3.0
WavesLib.dll : 5.9.7.0
Vista driver for x64
RTKVHD64.sys : 6.0.1.5745
AERTSr64.exe : 1.0.64.8
RAVCpl64.exe : 1.0.0.273
RtkAudioService64.exe : 1.0.0.17
RtlUpd64.exe : 2.7.1.1
SkyTel.exe : 2.0.2.2
vncutil64.exe : 1.0.0.22
GWfil t64.sys : 6.10.0.3
RTSnMg64.cpl : 1.0.0.13
AERTAC64.dll : 2.0.64.1
AERTAR64.dll : 1.0.64.7
CTAP032.dll : 1.0.0.530
CTAP064.dll : 1.0.0.530
ctpld.dll : 1.0.0.530
DaisyWrp.dll : 1.0.0.70
FMAP064.dll : 0.0.12.1
MaxxAudioAP020.dll : 2.2.2.0
ppchain.dll : 1.0.0.70
RCoInst64.dll : 1.0.4.1
RtCOMB4.dll : 2.0.0.103
RTCOMDLL.dll : 2.0.0.103

```

Readme.txt

```

RtkApi 64. dll           : 1. 0. 0. 9
RtkAPO64. dll           : 11. 0. 6000. 81
RtkCfg. dll             : 1. 0. 0. 1
RtkCfg64. dll           : 1. 0. 0. 1
RtkColnst. dll          : 1. 0. 4. 0
RtlCPAPI. dll           : 1. 0. 2. 1
RtlCPAPI64. dll         : 1. 0. 2. 1
RtPgEx64. dll           : 6. 0. 6000. 65
slcshp64. dll           : 1. 0. 3. 0
slgeq64. dll            : 1. 0. 1. 0
slh36064. dll           : 1. 0. 2. 0
slInit64. dll           : 1. 1. 1. 0
sltshd64. dll           : 1. 1. 0. 0
sluapo64. dll           : 1. 2. 6. 0
SRSHp64. dll            : 1. 1. 0. 0
SRSTSH64. dll           : 1. 1. 4. 0
SRSTSX64. dll           : 3. 2. 0. 0
SRSWOW64. dll           : 1. 1. 3. 0
HDMI Driver : -----
Vista x86:
RtHDMV. sys             : 6. 0. 1. 5735
RtkUpd. exe              : 2. 7. 1. 1
RHColnst. dll            : 1. 0. 3. 2
RHDMExt. dll             : 6. 0. 6000. 64
RtkHDM. dll              : 11. 0. 6000. 80

Vista x64:
RtHDMVX. sys             : 6. 0. 1. 5735
RtkUpd64. exe            : 2. 7. 1. 1
RHColnst64. dll          : 1. 0. 3. 2
RHDMEx64. dll            : 6. 0. 6000. 64
RtkHDM64. dll            : 11. 0. 6000. 80

XP/2K x86:
RtHDM. sys               : 5. 10. 0. 5735
RtkUpd. exe              : 2. 7. 1. 1
XP/2K x64:
RtHDMX. sys              : 5. 10. 0. 5735
RtkUpd64. exe            : 2. 7. 1. 1

Driver Setup Program     : 2. 69

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudiobus.sys version : 5.10.00.5013

//=====
Driver Package R2.09
Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .
1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663,
ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD,
ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
1.) Driver :
1. Customizations.

Windows 2000/XP : -----
Windows 2000/XP :
RTKHDA64. sys           : 5. 10. 0. 5735
RTKHDAUD. sys           : 5. 10. 0. 5735
Alcmtr. exe             : 1. 6. 0. 3

```

	Readme.txt	
AlcWzrd.exe	:	1.1.0.37
MicCal.exe	:	1.1.2.0
RTHDCPL.exe	:	2.2.5.1
RtkAudioService.exe	:	1.0.0.16
RtkAudioService64.exe	:	1.0.0.17
RTLCPPL.exe	:	1.0.1.66
RtlUpd.exe	:	2.7.1.1
RtlUpd64.exe	:	2.7.1.1
SkyTel.exe	:	2.0.2.0
SoundMan.exe	:	1.0.0.32
vncutil.exe	:	1.0.0.22
vncutil64.exe	:	1.0.0.22
AMBfilt.sys	:	5.10.0.4240
AMBfilt64.sys	:	5.10.0.4240
Mbnfilt.sys	:	5.10.0.4112
Mbnfilt64.sys	:	5.10.0.4115
ALSndMgr.cpl	:	1.0.0.11
RTSndMgr.cpl	:	1.0.1.0
RCoInst64XP.dll	:	1.0.3.9
RTCOMDLL.dll	:	1.0.0.97
RtkCoInstXP.dll	:	1.0.3.9
RtlCPAPI.dll	:	1.0.1.9
Vista driver :	-----	
Vista driver for x86		
RTKVHDA.sys	:	6.0.1.5735
AERTSrv.exe	:	1.0.32.8
RtHDVCpl.exe	:	1.0.0.264
RtkAudioService.exe	:	1.0.0.17
RtlUpd.exe	:	2.7.1.1
SkyTel.exe	:	2.0.2.1
vncutil.exe	:	1.0.0.22
RTSndMgr.cpl	:	1.0.0.13
AERTACap.dll	:	2.0.32.1
AERTARen.dll	:	1.0.32.7
CTAP032.dll	:	1.0.0.530
ctpld.dll	:	1.0.0.530
DaisyWrp.dll	:	1.0.0.70
FMAP0.dll	:	0.0.12.1
MaxxAudioAPO.dll	:	1.2.2.0
MaxxAudioAPO20.dll	:	2.2.2.0
MaxxAudioEQ.dll	:	5.9.7.0
ppchain.dll	:	1.0.0.70
RTCOMDLL.dll	:	2.0.0.100
RtkAPO.dll	:	11.0.6000.80
RtkApoApi.dll	:	1.0.0.8
RtkCoInst.dll	:	1.0.3.9
RtkPgExt.dll	:	6.0.6000.64
RtlCPAPI.dll	:	1.0.1.9
slcshp32.dll	:	1.0.3.0
slgeq32.dll	:	1.0.1.0
slh36032.dll	:	1.0.2.0
slinit32.dll	:	1.1.1.0
sltshd32.dll	:	1.1.0.0
sluapo32.dll	:	1.2.6.0
SRSHP360.dll	:	1.1.0.0
SRSTSHD.dll	:	1.1.4.0
SRSTSXT.dll	:	3.2.0.0
SRSWOW.dll	:	1.1.3.0
WavesLib.dll	:	5.9.7.0
Vista driver for x64		
RTKVHD64.sys	:	6.0.1.5735
AERTSr64.exe	:	1.0.64.8
RAVCpl64.exe	:	1.0.0.264
RtkAudioService64.exe	:	1.0.0.17
RtlUpd64.exe	:	2.7.1.1
SkyTel.exe	:	2.0.2.1
vncutil64.exe	:	1.0.0.22
GWfilt64.sys	:	6.10.0.3
RTSnMg64.cpl	:	1.0.0.13

Readme.txt

AERTAC64.dll : 2.0.64.1
 AERTAR64.dll : 1.0.64.7
 CTAP032.dll : 1.0.0.530
 CTAP064.dll : 1.0.0.530
 ctppld.dll : 1.0.0.530
 DaisyWrp.dll : 1.0.0.70
 FMAP064.dll : 0.0.12.1
 MaxxAudioAP020.dll : 2.2.2.0
 ppchain.dll : 1.0.0.70
 RCoInst64.dll : 1.0.3.9
 RtCOM64.dll : 2.0.0.100
 RTCOMDLL.dll : 2.0.0.100
 RtkApi64.dll : 1.0.0.8
 RtkAPO64.dll : 11.0.6000.80
 RtlCPAPI.dll : 1.0.1.9
 RtlPgEx64.dll : 6.0.6000.64
 slcshp64.dll : 1.0.3.0
 slgeq64.dll : 1.0.1.0
 slh36064.dll : 1.0.2.0
 slInit64.dll : 1.1.1.0
 sltshd64.dll : 1.1.0.0
 sluapo64.dll : 1.2.6.0
 SRSHP64.dll : 1.1.0.0
 SRSTSH64.dll : 1.1.4.0
 SRSTSX64.dll : 3.2.0.0
 SRSWOW64.dll : 1.1.3.0
 HDM Driver : -----
 Vista x86:
 RtHDMV.sys : 6.0.1.5735
 RtkUpd.exe : 2.7.1.1
 RHCoinst.dll : 1.0.3.2
 RHDMExt.dll : 6.0.6000.64
 RtkHDM.dll : 11.0.6000.80

 Vista x64:
 RtHDMVX.sys : 6.0.1.5735
 RtkUpd64.exe : 2.7.1.1
 RHCoinst64.dll : 1.0.3.2
 RHDMEx64.dll : 6.0.6000.64
 RtkHDM64.dll : 11.0.6000.80

 XP/2K x86:
 RtHDM.sys : 5.10.0.5735
 RtkUpd.exe : 2.7.1.1
 XP/2K x64:
 RtHDMX.sys : 5.10.0.5735
 RtkUpd64.exe : 2.7.1.1

 Driver Setup Program : 2.67

 Windows 2000/XP Operate on :
 Microsoft High Definition Audio Driver Package - KB888111
 Package file version (kb888111.exe) : 6.1.22.0
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.08

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Driver :
 1. Customizations.

Readme.txt

2. Support Andrea microphone effect mixer type GUI.
 2.) Package:

1. Change setup program install location to meet the requirements of OEM Ready Certification Tool

1.1.0.1101

```

Windows 2000/XP : -----
Windows 2000/XP :
RTKHDA64.sys      : 5.10.0.5730
RTKHDAUD.sys     : 5.10.0.5730
Mccal.exe        : 1.1.2.0
RTHDCPL.exe      : 2.2.4.9
RtkAudioService64.exe : 1.0.0.17
RtkAudioService.exe : 1.0.0.16
RTLCPPL.exe      : 1.0.1.66
RtlUpd64.exe     : 2.7.1.1
RtlUpd.exe       : 2.7.1.1
SkyTel.exe       : 2.0.2.0
SoundMan.exe     : 1.0.0.32
vncutil64.exe   : 1.0.0.22
vncutil.exe      : 1.0.0.22
Alcmtr.exe       : 1.6.0.3
AlcWzrd.exe      : 1.1.0.37
Mnfil64.sys      : 5.10.0.4115
Mnfil.sys        : 5.10.0.4112
AMBFil64.sys     : 5.10.0.4240
AMBFil.sys       : 5.10.0.4240
RTSndMgr.cpl     : 1.0.1.0
ALSndMgr.cpl     : 1.0.0.11
RCoInst64XP.dll  : 1.0.3.8
RTCOMDLL.dll    : 1.0.0.97
RtkCoInstXP.dll  : 1.0.3.8
RtlCPAPI.dll     : 1.0.1.9

Vista driver : -----
Vista driver for x86
RTKVHDA.sys      : 6.0.1.5730
AERTSrv.exe      : 1.0.32.8
RtHDVCpl.exe     : 1.0.0.257
RtkAudioService.exe : 1.0.0.17
RtlUpd.exe       : 2.7.1.1
SkyTel.exe       : 2.0.2.1
vncutil.exe      : 1.0.0.22
RTSndMgr.cpl     : 1.0.0.10
AERTACap.dll    : 2.0.32.1
AERTARen.dll    : 1.0.32.7
CTAP032.dll     : 1.0.0.530
ctpld.dll       : 1.0.0.530
DaisyWrp.dll    : 1.0.0.70
FMAP0.dll       : 0.0.12.1
MaxxAudioAPO.dll : 1.2.2.0
MaxxAudioAPO20.dll : 2.0.13.0
MaxxAudioEQ.dll : 5.9.7.0
ppchain.dll     : 1.0.0.70
RTCOMDLL.dll    : 2.0.0.100
RtkAPO.dll      : 11.0.6000.79
RtkApoApi.dll   : 1.0.0.8
RtkCoInst.dll   : 1.0.3.8
RtkPgExt.dll    : 6.0.6000.64
RtlCPAPI.dll    : 1.0.1.9
slcshp32.dll    : 1.0.3.0
slgeq32.dll     : 1.0.1.0
slh36032.dll    : 1.0.2.0
slinit32.dll    : 1.1.1.0
sltshd32.dll    : 1.1.0.0
sluapo32.dll    : 1.2.6.0
SRSHP360.dll    : 1.1.0.0
SRSTSHD.dll     : 1.1.4.0
SRSTSXT.dll     : 3.2.0.0
  
```

```

Readme.txt
SRSWOW.dll : 1.1.3.0
WavesLib.dll : 5.9.7.0
Vista driver for x64
RTKVHD64.sys : 6.0.1.5730
AERTSr64.exe : 1.0.64.8
RAVCpl64.exe : 1.0.0.257
RtkAudioService64.exe : 1.0.0.17
RtlUpd64.exe : 2.7.1.1
SkyTel.exe : 2.0.2.1
vncutil64.exe : 1.0.0.22
GWfilt64.sys : 6.10.0.3
RTSnMg64.cpl : 1.0.0.10
AERTAC64.dll : 2.0.64.1
AERTAR64.dll : 1.0.64.7
CTAP032.dll : 1.0.0.530
CTAP064.dll : 1.0.0.530
ctppld.dll : 1.0.0.530
DaisyWrp.dll : 1.0.0.70
FMAP064.dll : 0.0.12.1
MaxxAudioAP020.dll : 2.0.12.0
ppchain.dll : 1.0.0.70
RCoInst64.dll : 1.0.3.8
RtCOM64.dll : 2.0.0.100
RTCOMDLL.dll : 2.0.0.100
RtkApi64.dll : 1.0.0.8
RtkAPO64.dll : 11.0.6000.79
RtlCPAPI.dll : 1.0.1.9
RtPgEx64.dll : 6.0.6000.64
slcshp64.dll : 1.0.3.0
slgeq64.dll : 1.0.1.0
slh36064.dll : 1.0.2.0
slInit64.dll : 1.1.1.0
sltshd64.dll : 1.1.0.0
sluapo64.dll : 1.2.6.0
SRSHP64.dll : 1.1.0.0
SRSTSH64.dll : 1.1.4.0
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
HDMI Driver : -----
Vista x86:
RtHDMV.sys : 6.0.1.5692
RtkUpd.exe : 2.7.1.0
RHCoInst.dll : 1.0.3.2
RHDMExt.dll : 6.0.6000.54
RtkHDM.dll : 11.0.6000.72

Vista x64:
RtHDMVX.sys : 6.0.1.5692
RtkUpd64.exe : 2.7.1.0
RHCoInst64.dll : 1.0.3.2
RHDMEx64.dll : 6.0.6000.54
RtkHDM64.dll : 11.0.6000.72

XP/2K x86:
RtHDM.sys : 5.10.0.5692
RtkUpd.exe : 2.7.1.0
XP/2K x64:
RtHDMX.sys : 5.10.0.5692
RtkUpd64.exe : 2.7.1.0

Driver Setup Program : 2.67

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

```

//=====
Driver Package R2.07

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/Wi nXP/Wi n2000/Wi n2003 .

Readme.txt

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Driver :
 1. Customizations.

Windows 2000/XP : -----
Windows 2000/XP :
RTKHDA64.sys : 5.10.0.5717
RTKHDAUD.sys : 5.10.0.5717
Alcmtr.exe : 1.6.0.3
AlcWzrd.exe : 1.1.0.37
McCal.exe : 1.1.2.0
RTHDCPL.exe : 2.2.4.8
RTLCPPL.exe : 1.0.1.66
RtlUpd.exe : 2.7.1.1
RtlUpd64.exe : 2.7.1.1
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.32
AMBFilt.sys : 5.10.0.4240
AMBFilt64.sys : 5.10.0.4240
Mbnfilt.sys : 5.10.0.4112
Mbnfilt64.sys : 5.10.0.4115
ALSndMgr.cpl : 1.0.0.11
RTSndMgr.cpl : 1.0.1.0
RTCOMDLL.dll : 1.0.0.97
RtlCPAPI.dll : 1.0.1.9

Vista driver : -----
Vista driver for x86
RTKVHDA.sys : 6.0.1.5717
AERTSrv.exe : 1.0.32.7
RtHDVCpl.exe : 1.0.0.251
RtkAudioService.exe : 1.0.0.17
RtlUpd.exe : 2.7.1.1
SkyTel.exe : 2.0.2.1
vncutil.exe : 1.0.0.22
RTSndMgr.cpl : 1.0.0.10
AERTACap.dll : 1.0.32.7
AERTARen.dll : 1.0.32.3
CTAPO32.dll : 1.0.0.530
ctppld.dll : 1.0.0.530
DaisyWrp.dll : 1.0.0.70
FMAP0.dll : 40.59.0.0
MaxxAudioAPO.dll : 1.2.2.0
MaxxAudioAPO20.dll : 2.0.13.0
MaxxAudioEQ.dll : 5.9.7.0
ppchain.dll : 1.0.0.70
RTCOMDLL.dll : 2.0.0.100
RtkAPO.dll : 11.0.6000.78
RtkApoApi.dll : 1.0.0.6
RtkColnst.dll : 1.0.3.7
RtkPgExt.dll : 6.0.6000.61
RtlCPAPI.dll : 1.0.1.9
slcshp32.dll : 1.0.3.0
slgeq32.dll : 1.0.1.0
slh36032.dll : 1.0.2.0
slInit32.dll : 1.1.1.0
sltshd32.dll : 1.1.0.0
sluapo32.dll : 1.2.6.0
SRSHP360.dll : 1.1.0.0
SRSTSHD.dll : 1.1.4.0
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.1.3.0

Readme.txt
WavesLib.dll : 5.9.7.0
Vista driver for x64
RTKVHD64.sys : 6.0.1.5717
AERTSr64.exe : 1.0.64.7
RAVCpl64.exe : 1.0.0.251
RtkAudioService.exe : 1.0.0.17
RtlUpd64.exe : 2.7.1.1
SkyTel.exe : 2.0.2.1
vncutil.exe : 1.0.0.22
GWfilt64.sys : 6.10.0.3
RTSnMg64.cpl : 1.0.0.10
AERTAC64.dll : 1.0.64.7
AERTAR64.dll : 1.0.64.3
CTAP032.dll : 1.0.0.530
CTAP064.dll : 1.0.0.530
ctpld.dll : 1.0.0.530
DaisyWrp.dll : 1.0.0.70
FMAP064.dll : 40.59.0.0
MaxxAudioAP020.dll : 2.0.12.0
ppchain.dll : 1.0.0.70
RCoInst64.dll : 1.0.3.7
RtCOMB4.dll : 2.0.0.100
RtCOMDLL.dll : 2.0.0.100
RtkApi64.dll : 1.0.0.6
RtkAP064.dll : 11.0.6000.78
RtlCPAPI.dll : 1.0.1.9
RtPgEx64.dll : 6.0.6000.61
slcshp64.dll : 1.0.3.0
slgeq64.dll : 1.0.1.0
slh36064.dll : 1.0.2.0
slInit64.dll : 1.1.1.0
sltshd64.dll : 1.1.0.0
sluapo64.dll : 1.2.6.0
SRSHp64.dll : 1.1.0.0
SRSTSH64.dll : 1.1.4.0
SRSTSX64.dll : 3.2.0.0
SRSW064.dll : 1.1.3.0

HDM Driver : -----

Vista x86:
RtHDM.V.sys : 6.0.1.5692
RtkUpd.exe : 2.7.1.0
RHCoInst.dll : 1.0.3.2
RHDMExt.dll : 6.0.6000.54
RtkHDM.dll : 11.0.6000.72

Vista x64:
RtHDM.VX.sys : 6.0.1.5692
RtkUpd64.exe : 2.7.1.0
RHCoInst64.dll : 1.0.3.2
RHDMEx64.dll : 6.0.6000.54
RtkHDM64.dll : 11.0.6000.72

XP/2K x86:
RtHDM.sys : 5.10.0.5692
RtkUpd.exe : 2.7.1.0
XP/2K x64:
RtHDMX.sys : 5.10.0.5692
RtkUpd64.exe : 2.7.1.0

Driver Setup Program : 2.64

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.06

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .
1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663,

Readme.txt

- ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
 2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
 3. HDMI Device WHQL Support: ATI HDMI Devices
 4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
 5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
 6. Add/Fix
 1.) Driver :
 1. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :
 RTKHDA64.sys : 5.10.0.5713
 RTKHDAUD.sys : 5.10.0.5713
 Alcmtr.exe : 1.6.0.3
 AlcWzrd.exe : 1.1.0.37
 McCal.exe : 1.1.2.0
 RTHDCPL.exe : 2.2.4.6
 RTLCPL.exe : 1.0.1.66
 RtlUpd64.exe : 2.7.1.1
 RtlUpd.exe : 2.7.1.1
 SkyTel.exe : 2.0.2.0
 SoundMan.exe : 1.0.0.32
 AMBFilt64.sys : 5.10.0.4240
 AMBFilt.sys : 5.10.0.4240
 Mbnfilt64.sys : 5.10.0.4115
 Mbnfilt.sys : 5.10.0.4112
 ALSndMgr.cpl : 1.0.0.11
 RTSndMgr.cpl : 1.0.1.0
 RTCOMDLL.dll : 1.0.0.97
 RtlCPAPI.dll : 1.0.1.9

Vista driver : -----

Vista driver for x86
 RTKVHDA.sys : 6.0.1.5713
 AERTSrv.exe : 1.0.32.7
 RtkHDVCpl.exe : 1.0.0.248
 RtkAudioService.exe : 1.0.0.16
 RtlUpd.exe : 2.7.1.1
 SkyTel.exe : 2.0.2.1
 vncutil.exe : 1.0.0.22
 RTSndMgr.cpl : 1.0.0.10
 AERTACap.dll : 1.0.32.7
 AERTARen.dll : 1.0.32.3
 CTAP032.dll : 1.0.0.530
 ctpld.dll : 1.0.0.530
 DaisyWrp.dll : 1.0.0.70
 FMAP0.dll : 40.59.0.0
 MaxxAudioAPO.dll : 1.2.2.0
 MaxxAudioAPO20.dll : 2.0.13.0
 MaxxAudioEQ.dll : 5.9.7.0
 ppchain.dll : 1.0.0.70
 RTCOMDLL.dll : 2.0.0.100
 RtkAPO.dll : 11.0.6000.77
 RtkApoApi.dll : 1.0.0.6
 RtkCoInst.dll : 1.0.3.6
 RtkPgExt.dll : 6.0.6000.61
 RtlCPAPI.dll : 1.0.1.9
 slcshp32.dll : 1.0.3.0
 slgeq32.dll : 1.0.1.0
 slh36032.dll : 1.0.2.0
 slinit32.dll : 1.1.1.0
 sltshd32.dll : 1.1.0.0
 sluapo32.dll : 1.2.6.0
 SRSHP360.dll : 1.1.0.0
 SRSTSHD.dll : 1.1.4.0
 SRSTSXT.dll : 3.2.0.0
 SRSWOW.dll : 1.1.3.0
 WavesLib.dll : 5.9.7.0

Readme.txt

```

Vista driver for x64
RTKVHD64.sys : 6.0.1.5713
AERTSr64.exe : 1.0.64.7
RAVCpl64.exe : 1.0.0.248
RtkAudioService.exe : 1.0.0.16
RtlUpd64.exe : 2.7.1.1
SkyTel.exe : 2.0.2.1
vncutil.exe : 1.0.0.22
GWFilt64.sys : 6.10.0.3
RTSnMg64.cpl : 1.0.0.10
AERTAC64.dll : 1.0.64.7
AERTAR64.dll : 1.0.64.3
CTAP032.dll : 1.0.0.530
CTAP064.dll : 1.0.0.530
ctppld.dll : 1.0.0.530
DaisyWrp.dll : 1.0.0.70
FMAP064.dll : 40.59.0.0
MaxxAudioAP020.dll : 2.0.12.0
ppchain.dll : 1.0.0.70
RCoInst64.dll : 1.0.3.6
RtCOM64.dll : 2.0.0.100
RTCOMDLL.dll : 2.0.0.100
RtkApi64.dll : 1.0.0.6
RtkAPO64.dll : 11.0.6000.77
RtlCPAPI.dll : 1.0.1.9
RtPgEx64.dll : 6.0.6000.61
slcshp64.dll : 1.0.3.0
slgeq64.dll : 1.0.1.0
slh36064.dll : 1.0.2.0
slInit64.dll : 1.1.1.0
sltshd64.dll : 1.1.0.0
sluapo64.dll : 1.2.6.0
SRSHp64.dll : 1.1.0.0
SRSTSH64.dll : 1.1.4.0
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
-----
HDMI Driver :
Vista x86:
RtHDMV.sys : 6.0.1.5692
RtkUpd.exe : 2.7.1.0
RHCoInst.dll : 1.0.3.2
RHDMExt.dll : 6.0.6000.54
RtkHDM.dll : 11.0.6000.72

Vista x64:
RtHDMVX.sys : 6.0.1.5692
RtkUpd64.exe : 2.7.1.0
RHCoInst64.dll : 1.0.3.2
RHDMEx64.dll : 6.0.6000.54
RtkHDM64.dll : 11.0.6000.72

XP/2K x86:
RtHDM.sys : 5.10.0.5692
RtkUpd.exe : 2.7.1.0
XP/2K x64:
RtHDMX.sys : 5.10.0.5692
RtkUpd64.exe : 2.7.1.0

Driver Setup Program : 2.64

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013
//=====
Driver Package R2.05
Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/Wi nXP/Wi n2000/Wi n2003 .
1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663,
ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887

```

Readme.txt

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
3. HDMI Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Driver :
 1. Customizations.
 2. Meet Microsoft OEM Ready program requirements.
 - 2.) Package :
 1. Meet Microsoft OEM Ready program requirements.

Windows 2000/XP : -----

Windows 2000/XP :

RTKHDA64.sys	: 5.10.0.5708
RTKHDAUD.sys	: 5.10.0.5708
MicCal.exe	: 1.1.1.9
RTHDCPL.exe	: 2.2.4.5
RTLCPPL.exe	: 1.0.1.66
RtlUpd64.exe	: 2.7.1.1
RtlUpd.exe	: 2.7.1.1
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.32
Alcmtr.exe	: 1.6.0.3
AlcWzrd.exe	: 1.1.0.37
Mnfil64.sys	: 5.10.0.4115
Mnfil.sys	: 5.10.0.4112
AMBFil64.sys	: 5.10.0.4240
AMBFil.sys	: 5.10.0.4240
RTSndMgr.cpl	: 1.0.1.0
ALSndMgr.cpl	: 1.0.0.11
RTCOMDLL.dll	: 1.0.0.97
RtICPAPI.dll	: 1.0.1.9

Vista driver : -----

Vista driver for x86

RTKVHDA.sys	: 6.0.1.5708
AERTSrv.exe	: 1.0.32.7
RtHDVCpl.exe	: 1.0.0.246
RtkAudioService.exe	: 1.0.0.16
RtlUpd.exe	: 2.7.1.1
SkyTel.exe	: 2.0.2.1
vncutil.exe	: 1.0.0.21
RTSndMgr.cpl	: 1.0.0.10
AERTACap.dll	: 1.0.32.7
AERTARen.dll	: 1.0.32.3
CTAP032.dll	: 1.0.0.530
ctpld.dll	: 1.0.0.530
DaisyWrp.dll	: 1.0.0.70
FMAP0.dll	: 40.59.0.0
MaxxAudioAPO.dll	: 1.2.2.0
MaxxAudioAPO20.dll	: 2.0.13.0
MaxxAudioEQ.dll	: 5.9.7.0
ppchain.dll	: 1.0.0.70
RTCOMDLL.dll	: 2.0.0.100
RtkAPO.dll	: 11.0.6000.76
RtkApoApi.dll	: 1.0.0.4
RtkCoInst.dll	: 1.0.3.5
RtkPgExt.dll	: 6.0.6000.60
RtICPAPI.dll	: 1.0.1.9
slcshp32.dll	: 1.0.3.0
slgeq32.dll	: 1.0.1.0
slh36032.dll	: 1.0.2.0
slinit32.dll	: 1.1.1.0
sltshd32.dll	: 1.1.0.0
sluapo32.dll	: 1.2.6.0
SRSHP360.dll	: 1.1.0.0
SRSTSHD.dll	: 1.1.4.0
SRSTSXT.dll	: 3.2.0.0


```

Readme.txt
SRSWOW.dll : 1.1.3.0
WavesLib.dll : 5.9.7.0
Vista driver for x64
RTKVHD64.sys : 6.0.1.5708
AERTSr64.exe : 1.0.64.7
RAVCpl64.exe : 1.0.0.246
RtkAudioService.exe : 1.0.0.16
RtlUpd64.exe : 2.7.1.1
SkyTel.exe : 2.0.2.1
vncutil.exe : 1.0.0.21
GWfilt64.sys : 6.10.0.3
RTSnMg64.cpl : 1.0.0.10
AERTAC64.dll : 1.0.64.7
AERTAR64.dll : 1.0.64.3
CTAP032.dll : 1.0.0.530
CTAP064.dll : 1.0.0.530
ctpld.dll : 1.0.0.530
DaisyWrp.dll : 1.0.0.70
FMAP064.dll : 40.59.0.0
MaxxAudioAP020.dll : 2.0.12.0
ppchain.dll : 1.0.0.70
RCoInst64.dll : 1.0.3.5
RtCOM64.dll : 2.0.0.100
RTCOMDLL.dll : 2.0.0.100
RtkApi64.dll : 1.0.0.4
RtkAPO64.dll : 11.0.6000.76
RtlCPAPI.dll : 1.0.1.9
RtPgEx64.dll : 6.0.6000.60
slcshp64.dll : 1.0.3.0
slgeq64.dll : 1.0.1.0
slh36064.dll : 1.0.2.0
slInit64.dll : 1.1.1.0
sltshd64.dll : 1.1.0.0
sluapo64.dll : 1.2.6.0
SRSHP64.dll : 1.1.0.0
SRSTSH64.dll : 1.1.4.0
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
HDMI Driver : -----
Vista x86:
RtHDMV.sys : 6.0.1.5692
RtkUpd.exe : 2.7.1.0
RHCoInst.dll : 1.0.3.2
RHDMExt.dll : 6.0.6000.54
RtkHDM.dll : 11.0.6000.72

Vista x64:
RtHDMVX.sys : 6.0.1.5692
RtkUpd64.exe : 2.7.1.0
RHCoInst64.dll : 1.0.3.2
RHDMEx64.dll : 6.0.6000.54
RtkHDM64.dll : 11.0.6000.72

XP/2K x86:
RtHDM.sys : 5.10.0.5692
RtkUpd.exe : 2.7.1.0
XP/2K x64:
RtHDMX.sys : 5.10.0.5692
RtkUpd64.exe : 2.7.1.0

Driver Setup Program : 2.64

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

```

```
//=====
Driver Package R2.04
```

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/Wi nXP/Wi n2000/Wi n2003 .

Readme.txt

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Driver :
 1. Customizations.
 2. Support ALC887.

Windows 2000/XP : -----

Windows 2000/XP :

RTKHDA64.sys	: 5.10.0.5700
RTKHDAUD.sys	: 5.10.0.5700
Alcmtr.exe	: 1.6.0.3
AlcWzrd.exe	: 1.1.0.37
MicCal.exe	: 1.1.1.8
RTHDCPL.exe	: 2.2.4.0
RTLCPPL.exe	: 1.0.1.66
RtlUpd64.exe	: 2.7.1.0
RtlUpd.exe	: 2.7.1.0
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.32
AMBFilt64.sys	: 5.10.0.4240
AMBFilt.sys	: 5.10.0.4240
Mnfil64.sys	: 5.10.0.4115
Mnfil.sys	: 5.10.0.4112
ALSndMgr.cpl	: 1.0.0.11
RTSndMgr.cpl	: 1.0.1.0
RTCOMDLL.dll	: 1.0.0.97
RtLCPAPI.dll	: 1.0.1.9

Vista driver : -----

Vista driver for x86

RTKVHDA.sys	: 6.0.1.5700
AERTSrv.exe	: 1.0.32.7
RtHDVCpl.exe	: 1.0.0.240
RtkAudioService.exe	: 1.0.0.16
RtlUpd.exe	: 2.7.1.0
SkyTel.exe	: 2.0.2.1
vncutil.exe	: 1.0.0.21
RTSndMgr.cpl	: 1.0.0.9
AERTACap.dll	: 1.0.32.7
AERTARen.dll	: 1.0.32.3
CTAP032.dll	: 1.0.0.520
ctpld.dll	: 1.0.0.510
DaisyWrp.dll	: 1.0.0.70
FMAP0.dll	: 40.59.0.0
MaxxAudioAPO.dll	: 1.2.2.0
MaxxAudioAPO20.dll	: 2.0.13.0
MaxxAudioEQ.dll	: 5.9.7.0
ppchain.dll	: 1.0.0.70
RTCOMDLL.dll	: 2.0.0.100
RtkAPO.dll	: 11.0.6000.74
RtkApoApi.dll	: 1.0.0.4
RtkCoInst.dll	: 1.0.3.2
RtkPgExt.dll	: 6.0.6000.56
RtLCPAPI.dll	: 1.0.1.9
SRSHP360.dll	: 1.1.0.0
SRSTSHD.dll	: 1.1.4.0
SRSTSXT.dll	: 3.2.0.0
SRSWOW.dll	: 1.1.3.0
WavesLib.dll	: 5.9.7.0

Vista driver for x64

GWfilt64.sys	: 6.10.0.3
RTKVHD64.sys	: 6.0.1.5700
AERTSr64.exe	: 1.0.64.7

```

Readme.txt
RAVCpl64.exe : 1.0.0.240
RtkAudioService.exe : 1.0.0.16
RtlUpd64.exe : 2.7.1.0
SkyTel.exe : 2.0.2.1
vncutil.exe : 1.0.0.21
RTSnMg64.cpl : 1.0.0.9
AERTAC64.dll : 1.0.64.7
AERTAR64.dll : 1.0.64.3
CTAP032.dll : 1.0.0.520
CTAP064.dll : 1.0.0.520
ctppld.dll : 1.0.0.510
DaisyWrp.dll : 1.0.0.70
FMAP064.dll : 40.59.0.0
MaxxAudioAP020.dll : 2.0.12.0
ppchain.dll : 1.0.0.70
RCoInst64.dll : 1.0.3.2
RtCOM64.dll : 2.0.0.100
RTCOMDLL.dll : 2.0.0.100
RtkApi64.dll : 1.0.0.4
RtkAPO64.dll : 11.0.6000.74
RtlCPAPI.dll : 1.0.1.9
RtPgEx64.dll : 6.0.6000.56
SRSHP64.dll : 1.1.0.0
SRSTSH64.dll : 1.1.4.0
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
HDMI Driver : -----
Vista x86:
RtHDMV.sys : 6.0.1.5692
RtkUpd.exe : 2.7.1.0
RHCoInst.dll : 1.0.3.2
RHDMExt.dll : 6.0.6000.54
RtkHDM.dll : 11.0.6000.72

Vista x64:
RtHDMVX.sys : 6.0.1.5692
RtkUpd64.exe : 2.7.1.0
RHCoInst64.dll : 1.0.3.2
RHDMEx64.dll : 6.0.6000.54
RtkHDM64.dll : 11.0.6000.72

XP/2K x86:
RtHDM.sys : 5.10.0.5692
RtkUpd.exe : 2.7.1.0
XP/2K x64:
RtHDMX.sys : 5.10.0.5692
RtkUpd64.exe : 2.7.1.0

Driver Setup Program : 2.62

```

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.03

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/Wi nXP/Wi n2000/Wi n2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Driver :
 1. Customizations.

Readme.txt

```

Windows 2000/XP : -----
Windows 2000/XP :
RTKHDA64.sys : 5.10.0.5694
RTKHDAUD.sys : 5.10.0.5694
Alcmtr.exe : 1.6.0.3
AlcWzrd.exe : 1.1.0.37
McCal.exe : 1.1.1.8
RTHDCPL.exe : 2.2.3.8
RTLCPPL.exe : 1.0.1.66
RtlUpd64.exe : 2.7.1.0
RtlUpd.exe : 2.7.1.0
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.32
ALSndMgr.cpl : 1.0.0.11
RTSndMgr.cpl : 1.0.1.0
RTCOMDLL.dll : 1.0.0.97
RtlCPAPI.dll : 1.0.1.9
Vista driver : -----
Vista driver for x86
RTKVHDA.sys : 6.0.1.5694
AERTSrv.exe : 1.0.32.7
RtHDVCpl.exe : 1.0.0.235
RtkAudioService.exe : 1.0.0.16
RtlUpd.exe : 2.7.1.0
SkyTel.exe : 2.0.2.1
vncutil.exe : 1.0.0.21
RTSndMgr.cpl : 1.0.0.9
AERTACap.dll : 1.0.32.7
AERTARen.dll : 1.0.32.3
FMAP0.dll : 40.59.0.0
MaxxAudioAPO.dll : 1.2.2.0
MaxxAudioAPO20.dll : 2.0.13.0
MaxxAudioEQ.dll : 5.9.7.0
RTCOMDLL.dll : 2.0.0.99
RtkAPO.dll : 11.0.6000.72
RtkApoApi.dll : 1.0.0.4
RtkCoInst.dll : 1.0.3.2
RtkPgExt.dll : 6.0.6000.54
RtlCPAPI.dll : 1.0.1.9
SRSH360.dll : 1.1.0.0
SRSTSHD.dll : 1.1.4.0
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.1.3.0
WavesLib.dll : 5.9.7.0
Vista driver for x64
RTKVHD64.sys : 6.0.1.5694
AERTSr64.exe : 1.0.64.7
RAVCpl64.exe : 1.0.0.235
RtkAudioService.exe : 1.0.0.16
RtlUpd64.exe : 2.7.1.0
SkyTel.exe : 2.0.2.1
vncutil.exe : 1.0.0.21
RTSnMg64.cpl : 1.0.0.9
AERTAC64.dll : 1.0.64.7
AERTAR64.dll : 1.0.64.3
FMAP064.dll : 40.59.0.0
MaxxAudioAPO20.dll : 2.0.12.0
RCoInst64.dll : 1.0.3.2
RtCOM64.dll : 2.0.0.99
RTCOMDLL.dll : 2.0.0.99
RtkApi64.dll : 1.0.0.4
RtkAPO64.dll : 11.0.6000.72
RtlCPAPI.dll : 1.0.1.9
RtPgEx64.dll : 6.0.6000.54
SRSH64.dll : 1.1.0.0
SRSTSH64.dll : 1.1.4.0
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
HDM Driver : -----

```

Readme.txt

Vista x86:
RtHDM.V.sys : 6.0.1.5692
RtkUpd.exe : 2.7.1.0
RHCoInst.dll : 1.0.3.2
RHDMEExt.dll : 6.0.6000.54
RtkHDM.dll : 11.0.6000.72

Vista x64:
RtHDM.VX.sys : 6.0.1.5692
RtkUpd64.exe : 2.7.1.0
RHCoInst64.dll : 1.0.3.2
RHDMEExt64.dll : 6.0.6000.54
RtkHDM64.dll : 11.0.6000.72

XP/2K x86:
RtHDM.sys : 5.10.0.5692
RtkUpd.exe : 2.7.1.0
XP/2K x64:
RtHDM.X.sys : 5.10.0.5692
RtkUpd64.exe : 2.7.1.0

Driver Setup Program : 2.62

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.02

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix

1.) Driver :

1. Customizations.
2. Update ForteMedia microphone effect library.

2.) Package :

1. Delete driver file by Rtlupd.exe in Windows 2000/2003/XP System . (Rtlupd.exe 2.7.1.0)

Windows 2000/XP : -----

Windows 2000/XP :
RTKHDA64.sys : 5.10.0.5683
RTKHDAUD.sys : 5.10.0.5683
Alcmtr.exe : 1.6.0.3
AlcWzrd.exe : 1.1.0.37
McCal.exe : 1.1.1.8
RTHDCPL.exe : 2.2.3.3
RTLCPPL.exe : 1.0.1.66
RtlUpd64.exe : 2.7.1.0
RtlUpd.exe : 2.7.1.0
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.31
ALSndMgr.cpl : 1.0.0.11
RTSndMgr.cpl : 1.0.1.0
RTCOMDLL.dll : 1.0.0.97
RtlCPAPI.dll : 1.0.1.9

Vista driver : -----

Vista driver for x86
RTKVHDA.sys : 6.0.1.5683
AERTSrv.exe : 1.0.32.7
RtHDVCpl.exe : 1.0.0.227
RtkAudioService.exe : 1.0.0.16

	Readme.txt	
RtlUpd.exe	:	2.7.1.0
SkyTel.exe	:	2.0.2.1
vncutil.exe	:	1.0.0.19
RTSndMgr.cpl	:	1.0.0.8
AERTACap.dll	:	1.0.32.7
AERTARen.dll	:	1.0.32.3
FMAP0.dll	:	40.59.0.0
MaxxAudioAP0.dll	:	1.2.2.0
MaxxAudioAP020.dll	:	2.0.13.0
MaxxAudioEQ.dll	:	5.9.7.0
RTCOMDLL.dll	:	2.0.0.99
RtkAP0.dll	:	11.0.6000.71
RtkApoApi.dll	:	1.0.0.4
RtkCoInst.dll	:	1.0.3.2
RtkPgExt.dll	:	6.0.6000.53
RtLCPAPI.dll	:	1.0.1.9
SRSHP360.dll	:	1.1.0.0
SRSTSHD.dll	:	1.1.4.0
SRSTSXT.dll	:	3.2.0.0
SRSWOW.dll	:	1.1.3.0
WavesLib.dll	:	5.9.7.0
Vista driver for x64		
RTKVHD64.sys	:	6.0.1.5683
AERTSr64.exe	:	1.0.64.7
RAVCpl64.exe	:	1.0.0.227
RtkAudioService.exe	:	1.0.0.16
RtlUpd64.exe	:	2.7.1.0
SkyTel.exe	:	2.0.2.1
vncutil.exe	:	1.0.0.19
RTSnMg64.cpl	:	1.0.0.8
AERTAC64.dll	:	1.0.64.7
AERTAR64.dll	:	1.0.64.3
FMAP064.dll	:	40.59.0.0
MaxxAudioAP020.dll	:	2.0.12.0
RCoInst64.dll	:	1.0.3.2
RtCOMB4.dll	:	2.0.0.99
RTCOMDLL.dll	:	2.0.0.99
RtkApi64.dll	:	1.0.0.4
RtkAP064.dll	:	11.0.6000.71
RtLCPAPI.dll	:	1.0.1.9
RtPgEx64.dll	:	6.0.6000.53
SRSHP64.dll	:	1.1.0.0
SRSTSH64.dll	:	1.1.4.0
SRSTSX64.dll	:	3.2.0.0
SRSWOW64.dll	:	1.1.3.0
HDMI Driver :	-----	
Vista x86:		
RtHDMV.sys	:	6.0.1.5668
RtkUpd.exe	:	2.7.0.9
RHCoInst.dll	:	1.0.2.9
RHDMExt.dll	:	6.0.6000.52
RtkHDM.dll	:	11.0.6000.69
Vista x64:		
RtHDMVX.sys	:	6.0.1.5668
RtkUpd64.exe	:	2.7.0.9
RHCoInst64.dll	:	1.0.2.9
RHDMEx64.dll	:	6.0.6000.52
RtkHDM64.dll	:	11.0.6000.69
XP/2K x86:		
RtHDM.sys	:	5.10.0.5668
RtkUpd.exe	:	2.7.0.9
XP/2K x64:		
RtHDMX.sys	:	5.10.0.5668
RtkUpd64.exe	:	2.7.0.9
Driver Setup Program	:	2.62

Readme.txt

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.01

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Driver :
 1. Customizations.
 2. Support ALC273.
 - 2.) Package :
 1. Change warning message for upgrade driver .
 2. ChCfg.exe add version and manifest embedded feature .
 3. Add Manifest to Rtlupd.exe and HideWin.exe .
 4. The SetCDFmt function was included by RtlExUpd.dll Ver.1.0.1.1

Windows 2000/XP : -----

Windows 2000/XP :

RTKHDA64.sys	: 5.10.0.5680
RTKHDAUD.sys	: 5.10.0.5680
Alcmttr.exe	: 1.6.0.3
AlcWzrd.exe	: 1.1.0.37
McCal.exe	: 1.1.1.8
RTHDCPL.exe	: 2.2.3.3
RTLCPPL.exe	: 1.0.1.66
RtlUpd64.exe	: 2.7.0.9
RtlUpd.exe	: 2.7.0.9
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.31
ALSndMgr.cpl	: 1.0.0.11
RTSndMgr.cpl	: 1.0.1.0
RTCOMDLL.dll	: 1.0.0.97
RtlCPAPI.dll	: 1.0.1.9

Vista driver : -----

Vista driver for x86

RTKVHDA.sys	: 6.0.1.5680
AERTSrv.exe	: 1.0.32.7
RtHDVCpl.exe	: 1.0.0.224
RtkAudioService.exe	: 1.0.0.16
RtlUpd.exe	: 2.7.0.9
SkyTel.exe	: 2.0.2.1
vncutil.exe	: 1.0.0.19
RTSndMgr.cpl	: 1.0.0.8
AERTACap.dll	: 1.0.32.7
AERTARen.dll	: 1.0.32.3
FMAPO.dll	: 40.59.0.0
MaxxAudioAPO.dll	: 1.2.2.0
MaxxAudioAPO20.dll	: 2.0.13.0
MaxxAudioEQ.dll	: 5.9.7.0
RTCOMDLL.dll	: 2.0.0.99
RtkAPO.dll	: 11.0.6000.71
RtkApoApi.dll	: 1.0.0.4
RtkColnst.dll	: 1.0.3.2
RtkPgExt.dll	: 6.0.6000.53
RtlCPAPI.dll	: 1.0.1.9
SRSHP360.dll	: 1.1.0.0
SRSTSHD.dll	: 1.1.4.0
SRSTSXT.dll	: 3.2.0.0
SRSWOW.dll	: 1.1.3.0

```

Readme.txt
: 5.9.7.0
WavesLib.dll
Vista driver for x64
RTKVHD64.sys
AERTSr64.exe
RAVCpl64.exe
RtkAudioService.exe
RtlUpd64.exe
SkyTel.exe
vncutil.exe
RTSnMg64.cpl
AERTAC64.dll
AERTAR64.dll
FMAP064.dll
MaxxAudioAP020.dll
RCoInst64.dll
RtCOMB4.dll
RtCOMDL.dll
RtkApi64.dll
RtkAPO64.dll
RtLCPAPI.dll
RtPgEx64.dll
SRSHp64.dll
SRSTSH64.dll
SRSTX64.dll
SRSWOW64.dll
HDM Driver : -----
Vista x86:
RtHDMV.sys
RtkUpd.exe
RHCoInst.dll
RHDMExt.dll
RtkHDM.dll
: 6.0.1.5668
: 2.7.0.9
: 1.0.2.9
: 6.0.6000.52
: 11.0.6000.69
Vista x64:
RtHDMVX.sys
RtkUpd64.exe
RHCoInst64.dll
RHDMEx64.dll
RtkHDM64.dll
: 6.0.1.5668
: 2.7.0.9
: 1.0.2.9
: 6.0.6000.52
: 11.0.6000.69
XP/2K x86:
RtHDM.sys
RtkUpd.exe
XP/2K x64:
RtHDMX.sys
RtkUpd64.exe
: 5.10.0.5668
: 2.7.0.9
: 5.10.0.5668
: 2.7.0.9
Driver Setup Program
: 2.61

```

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.00

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Driver :
 1. Customizations.

Windows 2000/XP : -----

Readme.txt

Windows 2000/XP :

RTKHDA64.sys : 5.10.0.5672
 RTKHDAUD.sys : 5.10.0.5672
 Alcmtr.exe : 1.6.0.3
 AlcWzrd.exe : 1.1.0.37
 Mccal.exe : 1.1.1.8
 RTHDCPL.exe : 2.2.3.1
 RTLCPL.exe : 1.0.1.66
 RtlUpd64.exe : 2.7.0.9
 RtlUpd.exe : 2.7.0.9
 SkyTel.exe : 2.0.2.0
 SoundMan.exe : 1.0.0.31
 ALSndMgr.cpl : 1.0.0.11
 RTSndMgr.cpl : 1.0.1.0
 RTCOMDLL.dll : 1.0.0.97
 RtlCPAPI.dll : 1.0.1.9

Vista driver : -----

Vista driver for x86

RTKVHDA.sys : 6.0.1.5672
 AERTSrv.exe : 1.0.32.7
 RthDVCpl.exe : 1.0.0.219
 RtkAudioService.exe : 1.0.0.16
 RtlUpd.exe : 2.7.0.9
 SkyTel.exe : 2.0.2.1
 vncutil.exe : 1.0.0.19
 RTSndMgr.cpl : 1.0.0.8
 AERTACap.dll : 1.0.32.7
 AERTARen.dll : 1.0.32.3
 FMAP0.dll : 40.59.0.0
 MaxxAudioAPO.dll : 1.2.2.0
 MaxxAudioAPO20.dll : 2.0.13.0
 MaxxAudioEQ.dll : 5.9.7.0
 RTCOMDLL.dll : 2.0.0.98
 RtkAPO.dll : 11.0.6000.70
 RtkApoApi.dll : 1.0.0.4
 RtkCoInst.dll : 1.0.3.1
 RtkPgExt.dll : 6.0.6000.53
 RtlCPAPI.dll : 1.0.1.9
 SRSHP360.dll : 1.1.0.0
 SRSTSHD.dll : 1.1.4.0
 SRSTSXT.dll : 3.2.0.0
 SRSWOW.dll : 1.1.3.0
 WavesLib.dll : 5.9.7.0

Vista driver for x64

RTKVHD64.sys : 6.0.1.5672
 AERTSr64.exe : 1.0.64.7
 RAVCpl64.exe : 1.0.0.219
 RtkAudioService.exe : 1.0.0.16
 RtlUpd64.exe : 2.7.0.9
 SkyTel.exe : 2.0.2.1
 vncutil.exe : 1.0.0.19
 RTSnMg64.cpl : 1.0.0.8
 AERTAC64.dll : 1.0.64.7
 AERTAR64.dll : 1.0.64.3
 FMAP064.dll : 40.59.0.0
 MaxxAudioAPO20.dll : 2.0.12.0
 RCoInst64.dll : 1.0.3.1
 RtCOMB4.dll : 2.0.0.98
 RTCOMDLL.dll : 2.0.0.98
 RtkApi64.dll : 1.0.0.4
 RtkAPO64.dll : 11.0.6000.70
 RtlCPAPI.dll : 1.0.1.9
 RtpgEx64.dll : 6.0.6000.53
 SRSHP64.dll : 1.1.0.0
 SRSTSH64.dll : 1.1.4.0
 SRSTSX64.dll : 3.2.0.0
 SRSWOW64.dll : 1.1.3.0

HDMI Driver : -----

Vista x86:

Readme.txt

RtHDMV.sys : 6.0.1.5668
 RtkUpd.exe : 2.7.0.9
 RHCoInst.dll : 1.0.2.9
 RHDMExt.dll : 6.0.6000.52
 RtkHDM.dll : 11.0.6000.69

Vista x64:
 RtHDMVX.sys : 6.0.1.5668
 RtkUpd64.exe : 2.7.0.9
 RHCoInst64.dll : 1.0.2.9
 RHDMEx64.dll : 6.0.6000.52
 RtkHDM64.dll : 11.0.6000.69

XP/2K x86:
 RtHDM.sys : 5.10.0.5668
 RtkUpd.exe : 2.7.0.9
 XP/2K x64:
 RtHDMX.sys : 5.10.0.5668
 RtkUpd64.exe : 2.7.0.9

Driver Setup Program : 2.60

Windows 2000/XP Operate on :
 Microsoft High Definition Audio Driver Package - KB888111
 Package file version (kb888111.exe) : 6.1.22.0
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.99

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/Wi nXP/Wi n2000/Wi n2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Driver :
 1. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :
 RTKHDA64.sys : 5.10.0.5667
 RTKHDAUD.sys : 5.10.0.5667
 McCal.exe : 1.1.1.8
 RTHDCPL.exe : 2.2.3.0
 RTLCPL.exe : 1.0.1.66
 RtlUpd64.exe : 2.7.0.9
 RtlUpd.exe : 2.7.0.9
 SkyTel.exe : 2.0.2.0
 SoundMan.exe : 1.0.0.31
 Alcmtr.exe : 1.6.0.3
 AlcWzrd.exe : 1.1.0.37
 RTSndMgr.cpl : 1.0.1.0
 ALSndMgr.cpl : 1.0.0.11
 RTCOMDLL.dll : 1.0.0.97
 RtlCPAPI.dll : 1.0.1.9

Vista driver : -----

Vista driver for x86
 RTKVHDA.sys : 6.0.1.5667
 AERTSrv.exe : 1.0.32.2
 RtHDVCpl.exe : 1.0.0.215
 RtkAudioService.exe : 1.0.0.16
 RtlUpd.exe : 2.7.0.9
 SkyTel.exe : 2.0.2.1
 vncutil.exe : 1.0.0.18
 RTSndMgr.cpl : 1.0.0.8
 AERTACap.dll : 1.0.32.7

Readme.txt

```

AERTARen.dll : 1.0.32.3
FMAP0.dll : 40.59.0.0
MaxxAudioAPO.dll : 1.2.2.0
MaxxAudioAPO20.dll : 2.0.13.0
MaxxAudioEQ.dll : 5.9.7.0
RTCOMDLL.dll : 2.0.0.98
RtkAPO.dll : 11.0.6000.69
RtkApoApi.dll : 1.0.0.4
RtkCoInst.dll : 1.0.3.1
RtkPgExt.dll : 6.0.6000.52
RtlCPAPI.dll : 1.0.1.9
SRSH360.dll : 1.1.0.0
SRSTSHD.dll : 1.1.4.0
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.1.3.0
WavesLib.dll : 5.9.7.0
Vista driver for x64
RTKVHD64.sys : 6.0.1.5667
AERTSr64.exe : 1.0.64.2
RAVCpl64.exe : 1.0.0.215
RtkAudioService.exe : 1.0.0.16
RtlUpd64.exe : 2.7.0.9
SkyTel.exe : 2.0.2.1
vncutil.exe : 1.0.0.18
RTSnMg64.cpl : 1.0.0.8
AERTAC64.dll : 1.0.64.7
AERTAR64.dll : 1.0.64.3
FMAP064.dll : 40.59.0.0
MaxxAudioAPO20.dll : 2.0.12.0
RCoInst64.dll : 1.0.3.1
RtCOM64.dll : 2.0.0.98
RTCOMDLL.dll : 2.0.0.98
RtkApi64.dll : 1.0.0.4
RtkAPO64.dll : 11.0.6000.69
RtlCPAPI.dll : 1.0.1.9
RtPgEx64.dll : 6.0.6000.52
SRSH64.dll : 1.1.0.0
SRSTSH64.dll : 1.1.4.0
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
HDMI Driver : -----
Vista x86:
RtHDMV.sys : 6.0.1.5645
RtkUpd.exe : 2.7.0.9
RHCoInst.dll : 1.0.2.9
RHDMExt.dll : 6.0.6000.50
RtkHDM.dll : 11.0.6000.67

Vista x64:
RtHDMVX.sys : 6.0.1.5645
RtkUpd64.exe : 2.7.0.9
RHCoInst64.dll : 1.0.2.9
RHDMEx64.dll : 6.0.6000.50
RtkHDM64.dll : 11.0.6000.67

XP/2K x86:
RtHDM.sys : 5.10.0.5645
RtkUpd.exe : 2.7.0.9
XP/2K x64:
RtHDMX.sys : 5.10.0.5645
RtkUpd64.exe : 2.7.0.9

Driver Setup Program : 2.60

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013
//=====

```

Readme.txt

Driver Package R1.98

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Driver :
 1. Customizations.
 2. Fix the potential risk that audio driver can't be installed completely under Vista.

Windows 2000/XP : -----

Windows 2000/XP :
RTKHDA64.sys : 5.10.0.5657
RTKHDAUD.sys : 5.10.0.5657
Alcmtr.exe : 1.6.0.3
AlcWzrd.exe : 1.1.0.37
Mccal.exe : 1.1.1.8
RTHDCPL.exe : 2.2.2.5
RTLCPAPI.exe : 1.0.1.66
RtlUpd64.exe : 2.7.0.9
RtlUpd.exe : 2.7.0.9
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.31
ALSndMgr.cpl : 1.0.0.11
RTSndMgr.cpl : 1.0.1.0
RTCOMDLL.dll : 1.0.0.97
RtlCPAPI.dll : 1.0.1.9

Vista driver : -----

Vista driver for x86
RTKVHDA.sys : 6.0.1.5657
AERTSrv.exe : 1.0.32.2
RtHDVCpl.exe : 1.0.0.208
RtkAudioService.exe : 1.0.0.16
RtlUpd.exe : 2.7.0.9
SkyTel.exe : 2.0.2.1
vncutil.exe : 1.0.0.14
RTSndMgr.cpl : 1.0.0.8
AERTACap.dll : 1.0.32.7
AERTARen.dll : 1.0.32.3
FMAPO.dll : 40.59.0.0
MaxxAudioAPO.dll : 1.2.2.0
MaxxAudioAPO20.dll : 2.0.13.0
MaxxAudioEQ.dll : 5.9.7.0
RTCOMDLL.dll : 2.0.0.98
RtkAPO.dll : 11.0.6000.69
RtkApoApi.dll : 1.0.0.4
RtkCoInst.dll : 1.0.2.10
RtkPgExt.dll : 6.0.6000.52
RtlCPAPI.dll : 1.0.1.9
SRSHP360.dll : 1.1.0.0
SRSTSHD.dll : 1.1.4.0
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.1.3.0
WavesLib.dll : 5.9.7.0
Vista driver for x64
RTKVHD64.sys : 6.0.1.5657
AERTSr64.exe : 1.0.64.2
RAVCpl64.exe : 1.0.0.208
RtkAudioService.exe : 1.0.0.16
RtlUpd64.exe : 2.7.0.9
SkyTel.exe : 2.0.2.1
vncutil.exe : 1.0.0.14
RTSnMg64.cpl : 1.0.0.8
AERTAC64.dll : 1.0.64.7

```

Readme.txt
AERTAR64.dll : 1.0.64.3
FMAP064.dll : 40.59.0.0
MaxxAudioAPO20.dll : 2.0.12.0
RCoInst64.dll : 1.0.2.10
RtCOM64.dll : 2.0.0.98
RTCOMDLL.dll : 2.0.0.98
RtkApi64.dll : 1.0.0.4
RtkAPO64.dll : 11.0.6000.69
RtLCPAPI.dll : 1.0.1.9
RtPgEx64.dll : 6.0.6000.52
SRSHP64.dll : 1.1.0.0
SRSTSH64.dll : 1.1.4.0
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
HDMI Driver : -----
Vista x86:
RtHDMV.sys : 6.0.1.5645
RtkUpd.exe : 2.7.0.9
RHCoInst.dll : 1.0.2.9
RHDMExt.dll : 6.0.6000.50
RtkHDM.dll : 11.0.6000.67

Vista x64:
RtHDMVX.sys : 6.0.1.5645
RtkUpd64.exe : 2.7.0.9
RHCoInst64.dll : 1.0.2.9
RHDMEx64.dll : 6.0.6000.50
RtkHDM64.dll : 11.0.6000.67

XP/2K x86:
RtHDM.sys : 5.10.0.5645
RtkUpd.exe : 2.7.0.9
XP/2K x64:
RtHDMX.sys : 5.10.0.5645
RtkUpd64.exe : 2.7.0.9

Driver Setup Program : 2.60

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013
//=====
Driver Package R1.97
Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .
1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663,
ALC260, ALC262, ALC267, ALC268, ALC269, ALC272
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD,
ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
1.) Driver :
1. Customizations.
2. Add 24-bits recording feature.
3. Fix EAX direct parameter issue under XP.
4. Fix dummy noise issue under XP.

Windows 2000/XP : -----
Windows 2000/XP :
RTKHDA64.sys : 5.10.0.5653
RTKHDAUD.sys : 5.10.0.5653
Alcmtr.exe : 1.6.0.3
AlcWzrd.exe : 1.1.0.37
McCal.exe : 1.1.1.8
RTHDCPL.exe : 2.2.2.4
RTLCPPL.exe : 1.0.1.66

```

	Readme.txt	
RtlUpd64.exe	:	2.7.0.9
RtlUpd.exe	:	2.7.0.9
SkyTel.exe	:	2.0.2.0
SoundMan.exe	:	1.0.0.31
ALSndMgr.cpl	:	1.0.0.11
RTSndMgr.cpl	:	1.0.1.0
RTCOMDLL.dll	:	1.0.0.97
RtlCPAPI.dll	:	1.0.1.9
Vista driver : -----		
Vista driver for x86		
RTKVHDA.sys	:	6.0.1.5653
AERTSrv.exe	:	1.0.32.2
RtHDVCpl.exe	:	1.0.0.206
RtkAudioService.exe	:	1.0.0.16
RtlUpd.exe	:	2.7.0.9
SkyTel.exe	:	2.0.2.1
vncutil.exe	:	1.0.0.12
RTSndMgr.cpl	:	1.0.0.8
AERTACap.dll	:	1.0.32.7
AERTARen.dll	:	1.0.32.3
FMAP0.dll	:	40.59.0.0
MaxxAudioAPO.dll	:	1.2.2.0
MaxxAudioAPO20.dll	:	2.0.13.0
MaxxAudioEQ.dll	:	5.9.7.0
RTCOMDLL.dll	:	2.0.0.98
RtkAPO.dll	:	11.0.6000.67
RtkApoApi.dll	:	1.0.0.4
RtkCoInst.dll	:	1.0.2.10
RtkPgExt.dll	:	6.0.6000.50
RtlCPAPI.dll	:	1.0.1.9
SRSHP360.dll	:	1.1.0.0
SRSTSHD.dll	:	1.1.4.0
SRSTSXT.dll	:	3.2.0.0
SRSWOW.dll	:	1.1.3.0
WavesLib.dll	:	5.9.7.0
Vista driver for x64		
RTKVHD64.sys	:	6.0.1.5653
AERTSr64.exe	:	1.0.64.2
RAVCpl64.exe	:	1.0.0.206
RtkAudioService.exe	:	1.0.0.16
RtlUpd64.exe	:	2.7.0.9
SkyTel.exe	:	2.0.2.1
vncutil.exe	:	1.0.0.12
RTSnMgr64.cpl	:	1.0.0.8
AERTAC64.dll	:	1.0.64.7
AERTAR64.dll	:	1.0.64.3
FMAP064.dll	:	40.59.0.0
MaxxAudioAPO20.dll	:	2.0.12.0
RCoInst64.dll	:	1.0.2.10
RtCOMB4.dll	:	2.0.0.98
RTCOMDLL.dll	:	2.0.0.98
RtkApi64.dll	:	1.0.0.4
RtkAPO64.dll	:	11.0.6000.67
RtlCPAPI.dll	:	1.0.1.9
RtPgEx64.dll	:	6.0.6000.50
SRSHP64.dll	:	1.1.0.0
SRSTSH64.dll	:	1.1.4.0
SRSTSX64.dll	:	3.2.0.0
SRSWOW64.dll	:	1.1.3.0
HDMI Driver : -----		
Vista x86:		
RtHDMV.sys	:	6.0.1.5645
RtkUpd.exe	:	2.7.0.9
RHCoInst.dll	:	1.0.2.9
RHDMExt.dll	:	6.0.6000.50
RtkHDM.dll	:	11.0.6000.67
Vista x64:		
RtHDMVX.sys	:	6.0.1.5645

```

Readme.txt
RtkUpd64.exe           : 2.7.0.9
RHCoInst64.dll        : 1.0.2.9
RHDME64.dll           : 6.0.6000.50
RtkHDM64.dll          : 11.0.6000.67

XP/2K x86:
RtHDM.sys             : 5.10.0.5645
RtkUpd.exe            : 2.7.0.9
XP/2K x64:
RtHDMX.sys            : 5.10.0.5645
RtkUpd64.exe          : 2.7.0.9

Driver Setup Program   : 2.60

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013
//=====
Driver Package R1.96
Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/Wi nXP/Wi n2000/Wi n2003 .
1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663,
ALC260, ALC262, ALC267, ALC268, ALC269, ALC272
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD,
ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
1.) Driver :
1. Customizations.

2.) Package :
1. Fix uninstalled message_2 problem ( French language ) .

Windows 2000/XP : -----
Windows 2000/XP :
RTKHDA64.sys           : 5.10.0.5643
RTKHDAUD.sys          : 5.10.0.5643
Alcmtr.exe            : 1.6.0.2
AlcWzrd.exe           : 1.1.0.36
McCal.exe             : 1.1.1.8
RTHDCPL.exe           : 2.2.1.8
RTLCPPL.exe           : 1.0.1.65
RtlUpd64.exe          : 2.7.0.9
RtlUpd.exe            : 2.7.0.9
SkyTel.exe            : 2.0.2.0
SoundMan.exe          : 1.0.0.30
ALSndMgr.cpl          : 1.0.0.10
RTSndMgr.cpl          : 1.0.1.0
RTCOMDLL.dll         : 1.0.0.97
RtlCPAPI.dll          : 1.0.1.9

Vista driver : -----
Vista driver for x86
RTKVHDA.sys           : 6.0.1.5643
AERTSrv.exe           : 1.0.32.2
RtHDVCpl.exe          : 1.0.0.198
RtkAudioService.exe  : 1.0.0.14
RtlUpd.exe            : 2.7.0.9
SkyTel.exe            : 2.0.2.0
vncutil.exe           : 1.0.0.7
RTSndMgr.cpl          : 1.0.0.8
AERTACap.dll          : 1.0.32.7
AERTARen.dll          : 1.0.32.3
FMAPO.dll             : 40.59.0.0
MaxxAudioAPO.dll     : 1.2.2.0
MaxxAudioAPO20.dll   : 2.0.13.0
MaxxAudioEQ.dll      : 5.9.7.0

```

```

Readme.txt
RTCOMDLL.dll : 2.0.0.98
RtkAPO.dll : 11.0.6000.67
RtkApoApi.dll : 1.0.0.4
RtkCoInst.dll : 1.0.2.6
RtkPgExt.dll : 6.0.6000.49
RtLCPAPI.dll : 1.0.1.9
SRSH360.dll : 1.1.0.0
SRSTSHD.dll : 1.1.4.0
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.1.3.0
WavesLib.dll : 5.9.7.0
Vista driver for x64
RTKVHD64.sys : 6.0.1.5643
AERTSr64.exe : 1.0.64.2
RAVCpl64.exe : 1.0.0.198
RtkAudioService.exe : 1.0.0.14
RtlUpd64.exe : 2.7.0.9
SkyTel.exe : 2.0.2.0
vncutil.exe : 1.0.0.7
RTSnMg64.cpl : 1.0.0.8
AERTAC64.dll : 1.0.64.7
AERTAR64.dll : 1.0.64.3
FMAP064.dll : 40.59.0.0
MaxxAudioAPO20.dll : 2.0.12.0
RCoInst64.dll : 1.0.2.6
RtCOMB4.dll : 2.0.0.98
RTCOMDLL.dll : 2.0.0.98
RtkApi64.dll : 1.0.0.4
RtkAPO64.dll : 11.0.6000.67
RtLCPAPI.dll : 1.0.1.9
RtPgEx64.dll : 6.0.6000.49
SRSH64.dll : 1.1.0.0
SRSTSH64.dll : 1.1.4.0
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
HDMI Driver : -----
Vista x86:
RtHDMV.sys : 6.0.1.5633
RtkUpd.exe : 2.7.0.9
RHDMExt.dll : 6.0.6000.48
RtkHDM.dll : 11.0.6000.66

Vista x64:
RtHDMVX.sys : 6.0.1.5633
RtkUpd64.exe : 2.7.0.9
RHDMEx64.dll : 6.0.6000.48
RtkHDM64.dll : 11.0.6000.66

XP/2K x86:
RtHDM.sys : 5.10.0.5633
RtkUpd.exe : 2.7.0.9
XP/2K x64:
RtHDMX.sys : 5.10.0.5633
RtkUpd64.exe : 2.7.0.9

```

Driver Setup Program : 2.60

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.95

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272

3. HDMI Device WHQL Support: ATI HDMI Devices

Readme.txt

4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Driver :
 1. Customizations.
 2. Fix encryption stream issue for ALC889.
 3. Fix DRM issue.

```

Windows 2000/XP : -----
Windows 2000/XP :
RTKHDA64.sys           : 5.10.0.5636
RTKHDAUD.sys          : 5.10.0.5636
Alcmtr.exe            : 1.6.0.2
AlcWzrd.exe           : 1.1.0.36
MmcCal.exe            : 1.1.1.8
RTHDCPL.exe           : 2.2.1.6
RTLCPPL.exe           : 1.0.1.65
RtlUpd64.exe          : 2.7.0.9
RtlUpd.exe            : 2.7.0.9
SkyTel.exe            : 2.0.2.0
SoundMan.exe          : 1.0.0.30
ALSndMgr.cpl          : 1.0.0.10
RTSndMgr.cpl          : 1.0.1.0
RTCOMDLL.dll          : 1.0.0.96
RtlCPAPI.dll          : 1.0.1.9
Vista driver : -----
RTKVHDA.sys           : 6.0.1.5636
AERTSrv.exe           : 1.0.32.2
RtHDVCpl.exe          : 1.0.0.192
RtkAudioService.exe  : 1.0.0.12
RtlUpd.exe            : 2.7.0.9
SkyTel.exe            : 2.0.2.0
vncutil.exe           : 1.0.0.5
RTSndMgr.cpl          : 1.0.0.8
AERTACap.dll          : 1.0.32.7
AERTARen.dll          : 1.0.32.3
FMAP0.dll             : 40.59.0.0
MaxxAudioAPO.dll     : 1.2.2.0
MaxxAudioAPO20.dll   : 2.0.13.0
MaxxAudioEQ.dll      : 5.9.7.0
RTCOMDLL.dll          : 2.0.0.98
RtkAPO.dll            : 11.0.6000.66
RtkApoApi.dll         : 1.0.0.4
RtkCoInst.dll         : 1.0.2.5
RtkPgExt.dll          : 6.0.6000.48
RtlCPAPI.dll          : 1.0.1.9
SRSH360.dll           : 1.1.0.0
SRSTSHD.dll           : 1.1.4.0
SRSTSXT.dll           : 3.2.0.0
SRSWOW.dll            : 1.1.3.0
WavesLib.dll          : 5.9.7.0
Vista driver for x64
RTKVHD64.sys          : 6.0.1.5636
AERTSr64.exe          : 1.0.64.2
RAVCpl64.exe          : 1.0.0.192
RtkAudioService.exe  : 1.0.0.12
RtlUpd64.exe          : 2.7.0.9
SkyTel.exe            : 2.0.2.0
vncutil.exe           : 1.0.0.5
RTSnMg64.cpl          : 1.0.0.8
AERTAC64.dll          : 1.0.64.7
AERTAR64.dll          : 1.0.64.3
FMAP064.dll           : 40.59.0.0
MaxxAudioAPO20.dll   : 2.0.12.0
RCoInst64.dll         : 1.0.2.5
RtCOM64.dll           : 2.0.0.98
RTCOMDLL.dll          : 2.0.0.98
RtkApi64.dll          : 1.0.0.4

```

```

Readme.txt
RtkAPO64.dll : 11.0.6000.66
RtLCPAPI.dll : 1.0.1.9
RtPgEx64.dll : 6.0.6000.48
SRSHp64.dll : 1.1.0.0
SRSTSH64.dll : 1.1.4.0
SRSTX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
HDM Driver : -----
Vista x86:
RtHDM.V.sys : 6.0.1.5612
RtkUpd.exe : 2.7.0.9
RHDM Ext.dll : 6.0.6000.44
RtkHDM.dll : 11.0.6000.63

Vista x64:
RtHDM.VX.sys : 6.0.1.5612
RtkUpd64.exe : 2.7.0.9
RHDMEx64.dll : 6.0.6000.44
RtkHDM64.dll : 11.0.6000.63

XP/2K x86:
RtHDM.sys : 5.10.0.5612
RtkUpd.exe : 2.7.0.9

XP/2K x64:
RtHDM.X.sys : 5.10.0.5612
RtkUpd64.exe : 2.7.0.9

Driver Setup Program : 2.59

```

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.94

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix

- 1.) Driver :
 1. Customizations.
 2. Zero recorded data for SPDIF-IN copy-protection stream under Vista.

```

Windows 2000/XP : -----
Windows 2000/XP :
RTKHDA64.sys : 5.10.0.5628
RTKHDAUD.sys : 5.10.0.5628
Alcmtr.exe : 1.6.0.2
AlcWzrd.exe : 1.1.0.36
McCal.exe : 1.1.1.8
RTHDCPL.exe : 2.2.1.3
RTLCPPL.exe : 1.0.1.65
RtlUpd.exe : 2.7.0.9
RtlUpd64.exe : 2.7.0.9
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.30
ALSndMgr.cpl : 1.0.0.10
RTSndMgr.cpl : 1.0.1.0
RTCOMDLL.dll : 1.0.0.96
RtLCPAPI.dll : 1.0.1.9
Vista driver : -----
RTKVHDA.sys : 6.0.1.5628

```

```

Readme.txt
AERTSrv.exe : 1.0.32.2
RtHdVcpl.exe : 1.0.0.188
RtkAudioService.exe : 1.0.0.12
RtkSmbus.exe : 1.0.0.2
RtlUpd.exe : 2.7.0.9
SkyTel.exe : 2.0.2.0
RTSndMgr.cpl : 1.0.0.8
AERTACap.dll : 1.0.32.7
AERTARen.dll : 1.0.32.3
FMAP0.dll : 40.59.0.0
MaxxAudioAPO.dll : 1.2.2.0
MaxxAudioAPO20.dll : 2.0.13.0
MaxxAudioEQ.dll : 5.9.7.0
RTCOMDLL.dll : 2.0.0.97
RtkAPO.dll : 11.0.6000.65
RtkApoApi.dll : 1.0.0.4
RtkCoInst.dll : 1.0.2.3
RtkPgExt.dll : 6.0.6000.47
RtlCPAPI.dll : 1.0.1.9
SRSH360.dll : 1.1.0.0
SRSTSHD.dll : 1.1.4.0
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.1.3.0
WavesLib.dll : 5.9.7.0
Vista driver for x64
RTKVHD64.sys : 6.0.1.5628
AERTSr64.exe : 1.0.64.2
RAVCpl64.exe : 1.0.0.188
RtkAudioService.exe : 1.0.0.12
RtkSmbus.exe : 1.0.0.2
RtlUpd64.exe : 2.7.0.9
SkyTel.exe : 2.0.2.0
RTSnMgr64.cpl : 1.0.0.8
AERTAC64.dll : 1.0.64.7
AERTAR64.dll : 1.0.64.3
FMAP064.dll : 40.59.0.0
MaxxAudioAPO20.dll : 2.0.12.0
RCoInst64.dll : 1.0.2.3
RtCOM64.dll : 2.0.0.97
RTCOMDLL.dll : 2.0.0.97
RtkApi64.dll : 1.0.0.4
RtkAPO64.dll : 11.0.6000.65
RtlCPAPI.dll : 1.0.1.9
RtPgEx64.dll : 6.0.6000.47
SRSH64.dll : 1.1.0.0
SRSTSH64.dll : 1.1.4.0
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
HDMI Driver : -----
Vista x86:
RtHDMV.sys : 6.0.1.5612
RtkUpd.exe : 2.7.0.9
RHDMExt.dll : 6.0.6000.44
RtkHDM.dll : 11.0.6000.63

Vista x64:
RtHDMVX.sys : 6.0.1.5612
RtkUpd64.exe : 2.7.0.9
RHDMEx64.dll : 6.0.6000.44
RtkHDM64.dll : 11.0.6000.63

XP/2K x86:
RtHDM.sys : 5.10.0.5612
RtkUpd.exe : 2.7.0.9

XP/2K x64:
RtHDMX.sys : 5.10.0.5612
RtkUpd64.exe : 2.7.0.9

```

Readme.txt

Driver Setup Program

: 2.59

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.93

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Driver :
 1. Customizations.
 - 2.) Package :
 1. Small VGA mode should not be checked in silent installation .

Windows 2000/XP : -----

Windows 2000/XP :

RTKHDA64.sys	: 5.10.0.5624
RTKHDAUD.sys	: 5.10.0.5624
Alcmtr.exe	: 1.6.0.2
AlcWzrd.exe	: 1.1.0.36
MicCal.exe	: 1.1.1.8
RTHDCPL.exe	: 2.2.1.1
RTLCPPL.exe	: 1.0.1.65
RtlUpd64.exe	: 2.7.0.9
RtlUpd.exe	: 2.7.0.9
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.30
ALSndMgr.cpl	: 1.0.0.10
RTSndMgr.cpl	: 1.0.1.0
RTCOMDLL.dll	: 1.0.0.96
RtlCPAPI.dll	: 1.0.1.9

Vista driver : -----

RTKVHDA.sys	: 6.0.1.5624
AERTSrv.exe	: 1.0.32.2
RtHDVCpl.exe	: 1.0.0.185
RtkAudioService.exe	: 1.0.0.12
RtkSmbus.exe	: 1.0.0.2
RtlUpd.exe	: 2.7.0.9
SkyTel.exe	: 2.0.2.0
RTSndMgr.cpl	: 1.0.0.7
AERTACap.dll	: 1.0.32.7
AERTARen.dll	: 1.0.32.3
FMAPO.dll	: 40.59.0.0
MaxxAudioAPO.dll	: 1.2.2.0
MaxxAudioAPO20.dll	: 2.0.13.0
MaxxAudioEQ.dll	: 5.9.7.0
RTCOMDLL.dll	: 2.0.0.97
RtkAPO.dll	: 11.0.6000.65
RtkApoApi.dll	: 1.0.0.4
RtkColInst.dll	: 1.0.2.3
RtkPgExt.dll	: 6.0.6000.46
RtlCPAPI.dll	: 1.0.1.9
SRSH360.dll	: 1.1.0.0
SRSTSHD.dll	: 1.1.4.0
SRSTSXT.dll	: 3.2.0.0
SRSWOW.dll	: 1.1.3.0
WavesLib.dll	: 5.9.7.0
Vista driver for x64	
RTKVHD64.sys	: 6.0.1.5624
AERTSr64.exe	: 1.0.64.2

Readme.txt

```

RAVCpl64.exe           : 1.0.0.185
RtkAudioService.exe   : 1.0.0.12
RtkSmbus.exe          : 1.0.0.2
RtlUpd64.exe          : 2.7.0.9
SkyTel.exe            : 2.0.2.0
RTSnMg64.cpl         : 1.0.0.7
AERTAC64.dll          : 1.0.64.7
AERTAR64.dll          : 1.0.64.3
FMAP064.dll           : 40.59.0.0
MaxxAudioAP020.dll   : 2.0.12.0
RCoInst64.dll         : 1.0.2.3
RtCOMB4.dll           : 2.0.0.97
RtCOMDLL.dll          : 2.0.0.97
RtkApi64.dll          : 1.0.0.4
RtkAPO64.dll          : 11.0.6000.65
RtLCPAPI.dll          : 1.0.1.9
RtPgEx64.dll          : 6.0.6000.46
SRSHp64.dll           : 1.1.0.0
SRSTSH64.dll          : 1.1.4.0
SRSTSX64.dll          : 3.2.0.0
SRSWOW64.dll          : 1.1.3.0
-----
HDMI Driver :
Vista x86:
RtHDMV.sys             : 6.0.1.5612
RtkUpd.exe             : 2.7.0.9
RHDMExt.dll            : 6.0.6000.44
RtkHDM.dll             : 11.0.6000.63

Vista x64:
RtHDMVX.sys            : 6.0.1.5612
RtkUpd64.exe           : 2.7.0.9
RHDMEx64.dll           : 6.0.6000.44
RtkHDM64.dll           : 11.0.6000.63

XP/2K x86:
RtHDM.sys              : 5.10.0.5612
RtkUpd.exe             : 2.7.0.9

XP/2K x64:
RtHDMX.sys             : 5.10.0.5612
RtkUpd64.exe           : 2.7.0.9

Driver Setup Program   : 2.59

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013
//=====
Driver Package R1.92
Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .
1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663,
ALC260, ALC262, ALC267, ALC268, ALC269, ALC272
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD,
ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
1.) Driver :
1. Fix Stereo Mix issue with codec which support capless output pin.
2. Customizations.

Windows 2000/XP : -----
Windows 2000/XP :
RTKHDA64.sys         : 5.10.0.5618
RTKHDAUD.sys         : 5.10.0.5618
McCal.exe            : 1.1.1.8

```

Readme.txt

RTHDCPL.exe	: 2.2.1.0
RTLCPPL.exe	: 1.0.1.65
RtlUpd64.exe	: 2.7.0.9
RtlUpd.exe	: 2.7.0.9
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.30
AlcMtr.exe	: 1.6.0.2
AlcWzrd.exe	: 1.1.0.36
RTSndMgr.cpl	: 1.0.1.0
ALSndMgr.cpl	: 1.0.0.10
RTCOMDLL.dll	: 1.0.0.96
RtlCPAPI.dll	: 1.0.1.9
Vista driver : -----	
Vista driver for x86	
RTKVHDA.sys	: 6.0.1.5618
AERTSrv.exe	: 1.0.32.2
RtHDVCpl.exe	: 1.0.0.183
RtkAudioService.exe	: 1.0.0.12
RtkSmbus.exe	: 1.0.0.2
RtlUpd.exe	: 2.7.0.9
SkyTel.exe	: 2.0.2.0
RTSndMgr.cpl	: 1.0.0.7
AERTACap.dll	: 1.0.32.7
AERTARen.dll	: 1.0.32.3
FMAP0.dll	: 40.58.0.0
MaxxAudioAP0.dll	: 1.2.2.0
MaxxAudioAP020.dll	: 2.0.13.0
MaxxAudioEQ.dll	: 5.9.7.0
RTCOMDLL.dll	: 2.0.0.97
RtkAP0.dll	: 11.0.6000.64
RtkApoApi.dll	: 1.0.0.4
RtkCoInst.dll	: 1.0.2.1
RtkPgExt.dll	: 6.0.6000.45
RtlCPAPI.dll	: 1.0.1.9
SRSHP360.dll	: 1.0.1.0
SRSTSHD.dll	: 1.1.4.0
SRSTXST.dll	: 3.2.0.0
SRSWOW.dll	: 1.1.3.0
WavesLib.dll	: 5.9.7.0
Vista driver for x64	
RTKVHD64.sys	: 6.0.1.5618
AERTSr64.exe	: 1.0.64.2
RAVCpl64.exe	: 1.0.0.183
RtkAudioService.exe	: 1.0.0.12
RtkSmbus.exe	: 1.0.0.2
RtlUpd64.exe	: 2.7.0.9
SkyTel.exe	: 2.0.2.0
RTSnMg64.cpl	: 1.0.0.7
AERTAC64.dll	: 1.0.64.7
AERTAR64.dll	: 1.0.64.3
FMAP064.dll	: 40.58.0.0
MaxxAudioAP020.dll	: 2.0.12.0
RCoInst64.dll	: 1.0.2.1
RtCOMB4.dll	: 2.0.0.97
RTCOMDLL.dll	: 2.0.0.97
RtkApi64.dll	: 1.0.0.4
RtkAP064.dll	: 11.0.6000.64
RtlCPAPI.dll	: 1.0.1.9
RtPgEx64.dll	: 6.0.6000.45
SRSHP64.dll	: 1.0.1.0
SRSTSH64.dll	: 1.1.4.0
SRSTX64.dll	: 3.2.0.0
SRSWOW64.dll	: 1.1.3.0
HDMI Driver : -----	
Vista x86:	
RtHDMV.sys	: 6.0.1.5612
RtkUpd.exe	: 2.7.0.9
RHDMExt.dll	: 6.0.6000.44
RtkHDM.dll	: 11.0.6000.63

Readme.txt

Vista x64:
 RtHDM VX. sys : 6.0.1.5612
 RtkUpd64.exe : 2.7.0.9
 RHDMEx64.dll : 6.0.6000.44
 RtkHDM64.dll : 11.0.6000.63

XP/2K x86:
 RtHDM. sys : 5.10.0.5612
 RtkUpd.exe : 2.7.0.9

XP/2K x64:
 RtHDMX. sys : 5.10.0.5612
 RtkUpd64.exe : 2.7.0.9

Driver Setup Program : 2.58

Windows 2000/XP Operate on :
 Microsoft High Definition Audio Driver Package - KB888111
 Package file version (kb888111.exe) : 6.1.22.0
 Hdaudiobus.sys version : 5.10.00.5013

//=====

Driver Package R1.91

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Driver :
 1. Fix DTM 1.2 KS topology test fail issue.
 2. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :
 RTKHDA64.sys : 5.10.0.5605
 RTKHDAUD.sys : 5.10.0.5605
 McCal.exe : 1.1.1.8
 RTHDCPL.exe : 2.2.0.2
 RTLCPL.exe : 1.0.1.65
 RtlUpd64.exe : 2.7.0.9
 RtlUpd.exe : 2.7.0.9
 SkyTel.exe : 2.0.2.0
 SoundMan.exe : 1.0.0.30
 Alcmtr.exe : 1.6.0.2
 AlcWzrd.exe : 1.1.0.36
 RTSndMgr.cpl : 1.0.1.0
 ALSndMgr.cpl : 1.0.0.10
 RTCOMDLL.dll : 1.0.0.96
 RtlCPAPI.dll : 1.0.1.9

Vista driver : -----

Vista driver for x86
 RTKVHDA.sys : 6.0.1.5605
 AERTSrv.exe : 1.0.32.2
 RtHDVCpl.exe : 1.0.0.172
 RtkAudioService.exe : 1.0.0.11
 RtkSmbus.exe : 1.0.0.1
 RtlUpd.exe : 2.7.0.9
 SkyTel.exe : 2.0.2.0
 RTSndMgr.cpl : 1.0.0.7
 AERTACap.dll : 1.0.32.7
 AERTARen.dll : 1.0.32.3
 FMAPO.dll : 6.0.6000.16386
 MaxxAudioAPO.dll : 1.2.2.0
 MaxxAudioAPO20.dll : 2.0.12.0

Readme.txt

```

MaxxAudioEQ.dll : 5.9.7.0
RTCOMDLL.dll : 2.0.0.96
RtkAPO.dll : 11.0.6000.63
RtkApoApi.dll : 1.0.0.4
RtkCoInst.dll : 1.0.2.0
RtkPgExt.dll : 6.0.6000.42
RtlCPAPI.dll : 1.0.1.9
SRSH360.dll : 1.0.1.0
SRSTSHD.dll : 1.1.4.0
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.1.3.0
WavesLib.dll : 5.9.7.0
Vista driver for x64
RTKVHD64.sys : 6.0.1.5605
AERTSr64.exe : 1.0.64.2
RAVCpl64.exe : 1.0.0.172
RtkAudioService.exe : 1.0.0.11
RtkSmbus.exe : 1.0.0.1
RtlUpd64.exe : 2.7.0.9
SkyTel.exe : 2.0.2.0
RTSnMg64.cpl : 1.0.0.7
AERTAC64.dll : 1.0.64.7
AERTAR64.dll : 1.0.64.3
FMAP064.dll : 6.0.6000.16386
MaxxAudioAP020.dll : 2.0.12.0
RCoInst64.dll : 1.0.2.0
RtCOM64.dll : 2.0.0.96
RTCOMDLL.dll : 2.0.0.96
RtkApi64.dll : 1.0.0.4
RtkAPO64.dll : 11.0.6000.63
RtlCPAPI.dll : 1.0.1.9
RtPgEx64.dll : 6.0.6000.42
SRSH64.dll : 1.0.1.0
SRSTSH64.dll : 1.1.4.0
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
HDM Driver : -----
Vista x86:
RtHDMV.sys : 6.0.1.5602
RtkUpd.exe : 2.7.0.9
RHDMExt.dll : 6.0.6000.42
RtkHDM.dll : 11.0.6000.62

Vista x64:
RtHDMVX.sys : 6.0.1.5602
RtkUpd64.exe : 2.7.0.9
RHDMEx64.dll : 6.0.6000.42
RtkHDM64.dll : 11.0.6000.62

XP/2K x86:
RtHDM.sys : 5.10.0.5602
RtkUpd.exe : 2.7.0.9

XP/2K x64:
RtHDMX.sys : 5.10.0.5602
RtkUpd64.exe : 2.7.0.9

Driver Setup Program : 2.58

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

```

//=====

Driver Package R1.90
 Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .
 1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272
 2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD,

Readme.txt

- ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272
3. HDM Device WHQL Support: ATI HDM Devices
 4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
 5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
 6. Add/Fix
 - 1.) Driver :
 1. Support ALC663/ALC272.
 2. Support ForteMedia microphone effect APO feature.
 3. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :

WDM driver for Win2000/WinXP	: 5.10.0.5591
WDM driver for Winx64	: 5.10.0.5591
Realtek Soundman	: 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl)	: 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl)	: 1.0.1.0
Realtek Sound Effect Manager(RtlCpl)	: 1.0.1.65
Realtek Sound Effect Manager(RTHDCPL)	: 2.1.9.6
Alcwzrd.exe	: 1.1.0.36
SkyTel.exe	: 2.0.2.0

Vista driver : -----

Vista driver for x86	: 6.0.1.5591
RtHDVCpl.exe	: 1.0.0.159
RtkAPO.dll	: 11.0.6000.60
RtkPgExt.dll	: 6.0.6000.40
RTCOMDLL.dll	: 2.0.0.96
RtlCPAPI.dll	: 1.0.1.8
RTSndMgr.cpl	: 1.0.0.7
RtkCoInst.dll	: 1.0.1.29
SRSTSXT.dll	: 3.2.0.0
SRSWOW.dll	: 1.1.3.0
SRSHP360.dll	: 1.0.1.0
SRSTSHD.dll	: 1.1.4.0
RtkApoApi.dll	: 1.0.0.3
Vista driver for x64	: 6.0.1.5591
RAVCpl64.exe	: 1.0.0.159
RtkAPO64.dll	: 11.0.6000.60
RtPgEx64.dll	: 6.0.6000.40
RTCOMDLL.dll	: 2.0.0.96
RtlCPAPI.dll	: 1.0.1.8
RTSnMgr64.cpl	: 1.0.0.7
RCoInst64.dll	: 1.0.1.29
SRSTSX64.dll	: 3.2.0.0
SRSWOW64.dll	: 1.1.3.0
SRSHP64.dll	: 1.0.1.0
SRSTSH64.dll	: 1.1.4.0
RtkApi64.dll	: 1.0.0.3

HDM Driver : -----

Vista x64:	
RtHDMVX.sys	: 6.0.1.5575
RtkHDM64.dll	: 6.0.6000.57
RHDMEx64.dll	: 6.0.6000.39
Vista x86:	
RtHDMV.sys	: 6.0.1.5575
RtkHDM.dll	: 6.0.6000.57
RHDMExt.dll	: 6.0.6000.39
XP/2K x64:	
RtHDMX.sys	: 5.10.0.5575
XP/2K x86:	
RtHDM.sys	: 5.10.0.5575

Driver Setup Program : 2.57

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111
 Package file version (kb888111.exe) : 6.1.22.0
 Hdaudio.sys version : 5.10.00.5013

Readme.txt

//=====

Driver Package R1.89

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/Wi nXP/Wi n2000/Wi n2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268, ALC269
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268, ALC269
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Driver :
 1. Support "Event/Notification mode" under Vista.
 2. Fix Vista GUI issue when video adapter's resolution is low.
 3. Customizations.
 - 2.) Package :
 1. Uninstallation language selected by OS system .
 2. "Uninstall" word issue in Japanese language .

Windows 2000/XP : -----

Windows 2000/XP :

WDM driver for Win2000/Wi nXP : 5.10.0.5582
WDM driver for Winx64 : 5.10.0.5582
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.65
Realtek Sound Effect Manager(RTHDCPL) : 2.1.9.3
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 2.0.2.0

Vista driver : -----

Vista driver for x86 : 6.0.1.5582
RtHdVCpl.exe : 1.0.0.153
RtkAPO.dll : 11.0.6000.59
RtkPgExt.dll : 6.0.6000.40
RTCOMDLL.dll : 2.0.0.93
RtlCPAPI.dll : 1.0.1.7
RTSndMgr.cpl : 1.0.0.7
RtkCoInst.dll : 1.0.1.27
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.1.3.0
SRSHP360.dll : 1.0.1.0
SRSTSHD.dll : 1.1.4.0
RtkApoApi.dll : 1.0.0.3
Vista driver for x64 : 6.0.1.5582
RAVCpl64.exe : 1.0.0.153
RtkAPO64.dll : 11.0.6000.59
RtkPgEx64.dll : 6.0.6000.40
RTCOMDLL.dll : 2.0.0.93
RtlCPAPI.dll : 1.0.1.7
RTSnMg64.cpl : 1.0.0.7
RCoInst64.dll : 1.0.1.27
SRSTX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
SRSHP64.dll : 1.0.1.0
SRSTSH64.dll : 1.1.4.0
RtkApi64.dll : 1.0.0.3

HDM Driver : -----

Vista x64:
RtHDM.VX.sys : 6.0.1.5575
RtkHDM64.dll : 6.0.6000.57
RHDMEx64.dll : 6.0.6000.39
Vista x86:
RtHDM.V.sys : 6.0.1.5575
RtkHDM.dll : 6.0.6000.57
RHDMExt.dll : 6.0.6000.39
XP/2K x64:
RtHDMX.sys : 5.10.0.5575

Readme.txt

XP/2K x86:
RtHDM.sys : 5.10.0.5575

Driver Setup Program : 2.56

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.88

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268, ALC269
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268, ALC269
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix

1.) Driver :

1. Fix BSOD issue for WLK 1.1 System-Common Scenario Stress With IO test and System-Disable Enable With IO test under XP.
2. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :
WDM driver for Win2000/WinXP : 5.10.0.5574
WDM driver for Winx64 : 5.10.0.5574
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.65
Realtek Sound Effect Manager(RTHDCPL) : 2.1.9.1
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 2.0.2.0

Vista driver : -----

Vista driver for x86 : 6.0.1.5574
RtHDVCpl.exe : 1.0.0.145
RtkAPO.dll : 11.0.6000.58
RtkPgExt.dll : 6.0.6000.38
RTCOMDLL.dll : 2.0.0.90
RtlCPAPI.dll : 1.0.1.7
RTSndMgr.cpl : 1.0.0.7
RtkCoInst.dll : 1.0.1.25
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.1.3.0
SRSH360.dll : 1.0.1.0
SRSTSHD.dll : 1.1.4.0
RtkApoApi.dll : 1.0.0.3
Vista driver for x64 : 6.0.1.5574
RAVCpl64.exe : 1.0.0.145
RtkAPO64.dll : 11.0.6000.58
RtkPgEx64.dll : 6.0.6000.38
RTCOMDLL.dll : 2.0.0.90
RtlCPAPI.dll : 1.0.1.7
RTSnMg64.cpl : 1.0.0.7
RCoInst64.dll : 1.0.1.25
SRSTX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
SRSH64.dll : 1.0.1.0
SRSTSH64.dll : 1.1.4.0
RtkApi64.dll : 1.0.0.3

HDM Driver : -----

Vista x64:
RtHDM.VX.sys : 6.0.1.5413
RtkHDM64.dll : 6.0.6000.37
RHDME64.dll : 6.0.6000.25

Readme.txt

Vista x86:
 RtHDM.V.sys : 6.0.1.5413
 RtkHDM.dll : 6.0.6000.37
 RHDMExt.dll : 6.0.6000.25
 XP/2K x64:
 RtHDMX.sys : 5.10.0.5413
 XP/2K x86:
 RtHDM.sys : 5.10.0.5413
 Driver Setup Program : 2.55

Windows 2000/XP Operate on :
 Microsoft High Definition Audio Driver Package - KB888111
 Package file version (kb888111.exe) : 6.1.22.0
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.87

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268, ALC269
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268, ALC269
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Driver :
 1. Fix recording issue for ALC269.
 2. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :
 WDM driver for Win2000/WinXP : 5.10.0.5567
 WDM driver for Winx64 : 5.10.0.5567
 Realtek Soundman : 1.0.0.30
 Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
 Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
 Realtek Sound Effect Manager(RtlCpl) : 1.0.1.65
 Realtek Sound Effect Manager(RTHDCPL) : 2.1.8.9
 Alcwzrd.exe : 1.1.0.36
 SkyTel.exe : 2.0.2.0

Vista driver : -----

Vista driver for x86 : 6.0.1.5567
 RtHDVCpl.exe : 1.0.0.139
 RtkAPO.dll : 11.0.6000.56
 RtkPgExt.dll : 6.0.6000.35
 RTCOMDLL.dll : 2.0.0.89
 RtlCPAPI.dll : 1.0.1.7
 RTSndMgr.cpl : 1.0.0.7
 RtkCoInst.dll : 1.0.1.25
 SRSTSXT.dll : 3.2.0.0
 SRSWOW.dll : 1.1.3.0
 SRSHP360.dll : 1.0.1.0
 SRSTSHD.dll : 1.1.4.0
 RtkApoApi.dll : 1.0.0.3
 Vista driver for x64 : 6.0.1.5567
 RAVCpl64.exe : 1.0.0.139
 RtkAPO64.dll : 11.0.6000.56
 RtkPgEx64.dll : 6.0.6000.35
 RTCOMDLL.dll : 2.0.0.89
 RtlCPAPI.dll : 1.0.1.7
 RTSnMg64.cpl : 1.0.0.7
 RCoInst64.dll : 1.0.1.25
 SRSTSX64.dll : 3.2.0.0
 SRSWOW64.dll : 1.1.3.0
 SRSHP64.dll : 1.0.1.0
 SRSTSH64.dll : 1.1.4.0
 RtkApi64.dll : 1.0.0.3

Readme.txt

```

HDM Driver : -----
Vista x64:
RtHDMVX.sys : 6.0.1.5413
RtkHDM64.dll : 6.0.6000.37
RHDME64.dll : 6.0.6000.25
Vista x86:
RtHDMV.sys : 6.0.1.5413
RtkHDM.dll : 6.0.6000.37
RHDMEExt.dll : 6.0.6000.25
XP/2K x64:
RtHDMX.sys : 5.10.0.5413
XP/2K x86:
RtHDM.sys : 5.10.0.5413

Driver Setup Program : 2.54
  
```

```

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013
  
```

//=====

Driver Package R1.86

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/Wi nXP/Wi n2000/Wi n2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268, ALC269
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268, ALC269
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Driver :
 1. Fix the issue that SPDIF-out device broadcast 2nd output device's stream when turn on multi-streaming under Windows XP.
 2. Indexed DRC file supported.
 3. Customizations.
 - 2.) Package :
 1. Installer failed code.
 2. Copy .dat file rule.

```

Windows 2000/XP : -----
Windows 2000/XP :
WDM driver for Wi n2000/Wi nXP : 5.10.0.5559
WDM driver for Wi nx64 : 5.10.0.5559
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.65
Realtek Sound Effect Manager(RTHDCPL) : 2.1.8.7
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 2.0.2.0
  
```

```

Vista driver : -----
Vista driver for x86 : 6.0.1.5559
RtHDVCpl.exe : 1.0.0.132
RtkAPO.dll : 11.0.6000.54
RtkPgExt.dll : 6.0.6000.35
RTCOMDLL.dll : 2.0.0.87
RtlCPAPI.dll : 1.0.1.7
RTSndMgr.cpl : 1.0.0.7
RtkColnst.dll : 1.0.1.25
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.1.3.0
SRSHP360.dll : 1.0.1.0
SRSTSHD.dll : 1.1.4.0
RtkApoApi.dll : 1.0.0.3
Vista driver for x64 : 6.0.1.5559
RAVCpl64.exe : 1.0.0.132
RtkAP064.dll : 11.0.6000.54
  
```

```

Readme.txt
RtPgEx64.dll : 6.0.6000.35
RTCOMDLL.dll : 2.0.0.87
RtLCPAPI.dll : 1.0.1.7
RTSnMg64.cpl : 1.0.0.7
RCoInst64.dll : 1.0.1.25
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
SRSHP64.dll : 1.0.1.0
SRSTSH64.dll : 1.1.4.0
RtkApi64.dll : 1.0.0.3
HDM Driver : -----
Vista x64:
RtHDMVX.sys : 6.0.1.5413
RtkHDM64.dll : 6.0.6000.37
RHDMEx64.dll : 6.0.6000.25
Vista x86:
RtHDMV.sys : 6.0.1.5413
RtkHDM.dll : 6.0.6000.37
RHDMExt.dll : 6.0.6000.25
XP/2K x64:
RtHDMX.sys : 5.10.0.5413
XP/2K x86:
RtHDM.sys : 5.10.0.5413

Driver Setup Program : 2.52

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013
//=====
Driver Package R1.85
Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/Wi nXP/Wi n2000/Wi n2003 .
1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260,
ALC262, ALC267, ALC268, ALC269
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660,
ALC662, ALC260, ALC262, ALC267, ALC268, ALC269
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
1.) Driver :
1. Fix PC-Beep mute issue for ALC268/ALC267.
2. Fix the potential risk that system-thread is still running when driver is already unloaded
under Vista.
3. Customizations.

Windows 2000/XP : -----
Windows 2000/XP :
WDM driver for Win2000/Wi nXP : 5.10.0.5548
WDM driver for Winx64 : 5.10.0.5548
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtLcpl) : 1.0.1.65
Realtek Sound Effect Manager(RTHDCPL) : 2.1.8.6
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 2.0.2.0
Vista driver : -----
Vista driver for x86 : 6.0.1.5548
RtHDVCpl.exe : 1.0.0.128
RtkAPO.dll : 11.0.6000.51
RtkPgExt.dll : 6.0.6000.33
RTCOMDLL.dll : 2.0.0.86
RtLCPAPI.dll : 1.0.1.7
RTSnMgr.cpl : 1.0.0.7
RtkCoInst.dll : 1.0.1.25
SRSTSXT.dll : 3.2.0.0

```

```

Readme.txt
SRSWOW.dll : 1.1.3.0
SRSH360.dll : 1.0.1.0
SRSTSHD.dll : 1.1.4.0
RtkApoApi.dll : 1.0.0.3
Vista driver for x64 : 6.0.1.5548
RAVCpl64.exe : 1.0.0.128
RtkAPO64.dll : 11.0.6000.51
RtPgEx64.dll : 6.0.6000.33
RTCOMDLL.dll : 2.0.0.86
RtlCPAPI.dll : 1.0.1.7
RTSnMg64.cpl : 1.0.0.7
RCoInst64.dll : 1.0.1.25
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
SRSH64.dll : 1.0.1.0
SRSTSH64.dll : 1.1.4.0
RtkApi64.dll : 1.0.0.3
HDM Driver : -----
Vista x64:
RtHDMVX.sys : 6.0.1.5413
RtkHDM64.dll : 6.0.6000.37
RHDMEx64.dll : 6.0.6000.25
Vista x86:
RtHDMV.sys : 6.0.1.5413
RtkHDM.dll : 6.0.6000.37
RHDMExt.dll : 6.0.6000.25
XP/2K x64:
RtHDMX.sys : 5.10.0.5413
XP/2K x86:
RtHDM.sys : 5.10.0.5413
Driver Setup Program : 2.51
Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013
//=====
Driver Package R1.84
Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .
1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260,
ALC262, ALC267, ALC268, ALC269
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660,
ALC662, ALC260, ALC262, ALC267, ALC268, ALC269
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
1.) Driver :
1. Fix potential risk for re-direct headphone mode under Vista.
2. Customizations.
Windows 2000/XP : -----
Windows 2000/XP :
WDM driver for Win2000/WinXP : 5.10.0.5532
WDM driver for Winx64 : 5.10.0.5532
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.65
Realtek Sound Effect Manager(RTHDCPL) : 2.1.8.2
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 2.0.2.0
Vista driver : -----
Vista driver for x86 : 6.0.1.5532
RtHDVCpl.exe : 1.0.0.116
RtkAPO.dll : 11.0.6000.48
RtkPgExt.dll : 6.0.6000.31

```

```

Readme.txt
RTCOMDLL.dll : 2.0.0.86
RtlCPAPI.dll : 1.0.1.6
RTSndMgr.cpl : 1.0.0.7
RtkCoInst.dll : 1.0.1.18
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.1.3.0
SRSHP360.dll : 1.0.1.0
SRSTSHD.dll : 1.1.4.0
RtkApoApi.dll : 1.0.0.2
Vista driver for x64 : 6.0.1.5532
RAVCpl64.exe : 1.0.0.116
RtkAPO64.dll : 11.0.6000.48
RtPgEx64.dll : 6.0.6000.31
RTCOMDLL.dll : 2.0.0.86
RtlCPAPI.dll : 1.0.1.6
RTSnMg64.cpl : 1.0.0.7
RCoInst64.dll : 1.0.1.18
SRSTX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
SRSHP64.dll : 1.0.1.0
SRSTSH64.dll : 1.1.4.0
RtkApi64.dll : 1.0.0.2
HDMI Driver : -----
Vista x64:
RtHDMVX.sys : 6.0.1.5413
RtkHDM64.dll : 6.0.6000.37
RHDMEx64.dll : 6.0.6000.25
Vista x86:
RtHDMV.sys : 6.0.1.5413
RtkHDM.dll : 6.0.6000.37
RHDMExt.dll : 6.0.6000.25
XP/2K x64:
RtHDMX.sys : 5.10.0.5413
XP/2K x86:
RtHDM.sys : 5.10.0.5413
Driver Setup Program : 2.51

```

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.83

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/Wi nXP/Wi n2000/Wi n2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268, ALC269
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268, ALC269
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Driver :
 1. Support ALC269.
 2. Customizations.
 3. Turn on amplifier mask control for ALC885.
 4. Fix volume issue when turn on "Limited Output" feature under Windows XP.

Windows 2000/XP : -----

```

Windows 2000/XP :
WDM driver for Wi n2000/Wi nXP : 5.10.0.5523
WDM driver for Wi nX64 : 5.10.0.5523
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.65
Realtek Sound Effect Manager(RTHDCPL) : 2.1.7.7
Alcwzrd.exe : 1.1.0.36

```



```

Readme.txt
SkyTel.exe : 2.0.2.0
Vista driver : -----
Vista driver for x86 : 6.0.1.5523
RtHdVcpl.exe : 1.0.0.112
RtkAPO.dll : 11.0.6000.48
RtkPgExt.dll : 6.0.6000.31
RTCOMDLL.dll : 2.0.0.85
RtLCPAPI.dll : 1.0.1.6
RTSndMgr.cpl : 1.0.0.7
RtkCoInst.dll : 1.0.1.15
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.1.3.0
SRSHP360.dll : 1.0.1.0
SRSTSHD.dll : 1.1.4.0
RtkApoApi.dll : 1.0.0.2
Vista driver for x64 : 6.0.1.5523
RAVCpl64.exe : 1.0.0.112
RtkAPO64.dll : 11.0.6000.48
RtPgEx64.dll : 6.0.6000.31
RTCOMDLL.dll : 2.0.0.85
RtLCPAPI.dll : 1.0.1.6
RTSnMg64.cpl : 1.0.0.7
RCoInst64.dll : 1.0.1.15
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
SRSHP64.dll : 1.0.1.0
SRSTSH64.dll : 1.1.4.0
RtkApi64.dll : 1.0.0.2
HDMI Driver : -----
Vista x64:
RtHDMVX.sys : 6.0.1.5413
RtkHDM64.dll : 6.0.6000.37
RHDMEx64.dll : 6.0.6000.25
Vista x86:
RtHDMV.sys : 6.0.1.5413
RtkHDM.dll : 6.0.6000.37
RHDMExt.dll : 6.0.6000.25
XP/2K x64:
RtHDMX.sys : 5.10.0.5413
XP/2K x86:
RtHDM.sys : 5.10.0.5413

Driver Setup Program : 2.51

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013
//=====
Driver Package R1.82
Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/Wi nXP/Wi n2000/Wi n2003 .
1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260,
ALC262, ALC267, ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660,
ALC662, ALC260, ALC262, ALC267, ALC268
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
1.) Driver :
1. Support IMniportWaveRTStreamNotification interface under Vista.
2. Customizations.
3. Fix bug for the specific customer.
2.) Installer :
1. Add silent uninstall option .

Windows 2000/XP : -----
Windows 2000/XP :
WDM driver for Wi n2000/Wi nXP : 5.10.0.5512

```

```

Readme.txt
WDM driver for Winx64 : 5.10.0.5512
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.65
Realtek Sound Effect Manager(RTHDCPL) : 2.1.7.1
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 2.0.1.21
Vista driver : -----
Vista driver for x86 : 6.0.1.5512
RtHDVCpl.exe : 1.0.0.106
RtkAPO.dll : 11.0.6000.48
RtkPgExt.dll : 6.0.6000.31
RTCOMDLL.dll : 2.0.0.83
RtlCPAPI.dll : 1.0.1.6
RTSndMgr.cpl : 1.0.0.7
RtkCoInst.dll : 1.0.1.13
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.1.3.0
SRSHP360.dll : 1.0.1.0
SRSTSHD.dll : 1.1.4.0
RtkApoApi.dll : 1.0.0.2
Vista driver for x64 : 6.0.1.5512
RAVCpl64.exe : 1.0.0.106
RtkAPO64.dll : 11.0.6000.48
RtPgEx64.dll : 6.0.6000.31
RTCOMDLL.dll : 2.0.0.83
RtlCPAPI.dll : 1.0.1.6
RTSnMg64.cpl : 1.0.0.7
RCoInst64.dll : 1.0.1.13
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
SRSHP64.dll : 1.0.1.0
SRSTSH64.dll : 1.1.4.0
RtkApi64.dll : 1.0.0.2
HDM Driver : -----
Vista x64:
RtHDM.VX.sys : 6.0.1.5413
RtkHDM64.dll : 6.0.6000.37
RHDMEx64.dll : 6.0.6000.25
Vista x86:
RtHDM.V.sys : 6.0.1.5413
RtkHDM.dll : 6.0.6000.37
RHDMExt.dll : 6.0.6000.25
XP/2K x64:
RtHDM.X.sys : 5.10.0.5413
XP/2K x86:
RtHDM.sys : 5.10.0.5413
Driver Setup Program : 2.51

```

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.81

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix

1.) Driver :

1. Support real 2.1 output capability under Vista.
2. Improve Doppler effect for XP driver.

Readme.txt

3. Fix Vista DTM topology testing issue.
 4. Fix dead lock issue when more than 3 jacks set as headphone output under XP.
- 2.) Installer :
1. VSS event error for InstallShield .

```

Windows 2000/XP : -----
Windows 2000/XP :
WDM driver for Win2000/WinXP : 5.10.0.5506
WDM driver for Winx64 : 5.10.0.5506
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.65
Realtek Sound Effect Manager(RTHDCPL) : 2.1.7.0
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 2.0.1.21
Vista driver : -----
Vista driver for x86 : 6.0.1.5506
RtHDVCpl.exe : 1.0.0.103
RtkAPO.dll : 11.0.6000.48
RtkPgExt.dll : 6.0.6000.31
RTCOMDLL.dll : 2.0.0.82
RtlCPAPI.dll : 1.0.1.6
RTSndMgr.cpl : 1.0.0.6
RtkCoInst.dll : 1.0.1.13
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.1.3.0
SRSH360.dll : 1.0.1.0
SRSTSHD.dll : 1.1.4.0
RtkApoApi.dll : 1.0.0.2
Vista driver for x64 : 6.0.1.5506
RAVCpl64.exe : 1.0.0.103
RtkAPO64.dll : 11.0.6000.48
RtPgEx64.dll : 6.0.6000.31
RTCOMDLL.dll : 2.0.0.82
RtlCPAPI.dll : 1.0.1.6
RTSnMg64.cpl : 1.0.0.6
RCoInst64.dll : 1.0.1.13
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
SRSH64.dll : 1.0.1.0
SRSTSH64.dll : 1.1.4.0
RtkApi64.dll : 1.0.0.2
HDMI Driver : -----
Vista x64:
RtHDMVX.sys : 6.0.1.5413
RtkHDM64.dll : 6.0.6000.37
RHDMEx64.dll : 6.0.6000.25
Vista x86:
RtHDMV.sys : 6.0.1.5413
RtkHDM.dll : 6.0.6000.37
RHDMExt.dll : 6.0.6000.25
XP/2K x64:
RtHDMX.sys : 5.10.0.5413
XP/2K x86:
RtHDM.sys : 5.10.0.5413

Driver Setup Program : 2.50

```

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.80
Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660,

Readme.txt

ALC662, ALC260, ALC262, ALC267, ALC268

3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Driver :
 1. Customizations.
 2. Add new feature to smooth gap between 2 different output stream under Vista.
 - 2.) Installer :
 1. "Program Compatibility Assistant" issue for InstallShield 11.5 .
 2. VSR stop setting .

Windows 2000/XP : -----

Windows 2000/XP :
 WDM driver for Win2000/WinXP : 5.10.0.5497
 WDM driver for Winx64 : 5.10.0.5497
 Realtek Soundman : 1.0.0.30
 Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
 Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
 Realtek Sound Effect Manager(RtICpl) : 1.0.1.65
 Realtek Sound Effect Manager(RTHDCPL) : 2.1.6.7
 Alcwzrd.exe : 1.1.0.36
 SkyTel.exe : 2.0.1.21

Vista driver : -----

Vista driver for x86 :
 RtHdVCpl.exe : 1.0.0.99
 RtkAPO.dll : 11.0.6000.45
 RtkPgExt.dll : 6.0.6000.30
 RTCOMDLL.dll : 2.0.0.80
 RtICPAPI.dll : 1.0.1.6
 RTSndMgr.cpl : 1.0.0.6
 RtkCoInst.dll : 1.0.1.10
 SRSTSXT.dll : 3.2.0.0
 SRSWOW.dll : 1.1.3.0
 SRSHP360.dll : 1.0.1.0
 SRSTSHD.dll : 1.1.4.0
 RtkApoApi.dll : 1.0.0.2
 Vista driver for x64 :
 RAVCpl64.exe : 1.0.0.99
 RtkAPO64.dll : 11.0.6000.45
 RtkPgEx64.dll : 6.0.6000.30
 RTCOMDLL.dll : 2.0.0.80
 RtICPAPI.dll : 1.0.1.6
 RTSnMg64.cpl : 1.0.0.6
 RCoInst64.dll : 1.0.1.10
 SRSTSX64.dll : 3.2.0.0
 SRSWOW64.dll : 1.1.3.0
 SRSHP64.dll : 1.0.1.0
 SRSTSH64.dll : 1.1.4.0
 RtkApi64.dll : 1.0.0.2

HDM Driver : -----

Vista x64:
 RtHDMVX.sys : 6.0.1.5413
 RtkHDM64.dll : 6.0.6000.37
 RHDME64.dll : 6.0.6000.25
 Vista x86:
 RtHDMV.sys : 6.0.1.5413
 RtkHDM.dll : 6.0.6000.37
 RHDMEExt.dll : 6.0.6000.25
 XP/2K x64:
 RtHDMX.sys : 5.10.0.5413
 XP/2K x86:
 RtHDM.sys : 5.10.0.5413

Driver Setup Program : 2.49

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111
 Package file version (kb888111.exe) : 6.1.22.0

Readme.txt

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.79

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix

1.) Driver :

1. Customizations.
2. Fix potential risk from dividing by zero while the input signal power approach zero under

Windows XP.

3. Support digital mic software boost for ALC888.
- 2.) Installer :
 1. Remove Realtek registry key in upgrade mode.
 2. Change MCE GUI installation procedure for Windows Vista by Microsoft requirement.
 3. Add install procedure for VSR feature.

Windows 2000/XP : -----

Windows 2000/XP :

WDM driver for Win2000/WinXP	: 5.10.0.5490
WDM driver for Winx64	: 5.10.0.5490
Realtek Soundman	: 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl)	: 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl)	: 1.0.0.9
Realtek Sound Effect Manager(Rt1Cpl)	: 1.0.1.65
Realtek Sound Effect Manager(RTHDCPL)	: 2.1.6.2
Alcwzrd.exe	: 1.1.0.36
SkyTel.exe	: 2.0.1.20

Vista driver : -----

Vista driver for x86	: 6.0.1.5490
RtHdVcpl.exe	: 1.0.0.96
RtkAPO.dll	: 11.0.6000.45
RtkPgExt.dll	: 6.0.6000.30
RTCOMDLL.dll	: 2.0.0.79
Rt1CPAPI.dll	: 1.0.1.6
RTSndMgr.cpl	: 1.0.0.6
RtkCoInst.dll	: 1.0.1.9
SRSTSXT.dll	: 3.2.0.0
SRSWOW.dll	: 1.1.3.0
SRSHP360.dll	: 1.0.1.0
SRSTSHD.dll	: 1.1.4.0
RtkApoApi.dll	: 1.0.0.2
Vista driver for x64	: 6.0.1.5490
RAVCpl64.exe	: 1.0.0.96
RtkAPO64.dll	: 11.0.6000.45
RtPgEx64.dll	: 6.0.6000.30
RTCOMDLL.dll	: 2.0.0.79
Rt1CPAPI.dll	: 1.0.1.6
RTSnMg64.cpl	: 1.0.0.6
RCoInst64.dll	: 1.0.1.9
SRSTSX64.dll	: 3.2.0.0
SRSWOW64.dll	: 1.1.3.0
SRSHP64.dll	: 1.0.1.0
SRSTSH64.dll	: 1.1.4.0
RtkApi64.dll	: 1.0.0.2

HDM Driver : -----

Vista x64:	
RtHDM.VX.sys	: 6.0.1.5413
RtkHDM64.dll	: 6.0.6000.37
RHDMEx64.dll	: 6.0.6000.25
Vista x86:	
RtHDM.V.sys	: 6.0.1.5413
RtkHDM.dll	: 6.0.6000.37
RHDMExt.dll	: 6.0.6000.25

Readme.txt

XP/2K x64:
 RtHDMX.sys : 5.10.0.5413
 XP/2K x86:
 RtHDM.sys : 5.10.0.5413
 Driver Setup Program : 2.47

Windows 2000/XP Operate on :
 Microsoft High Definition Audio Driver Package - KB888111
 Package file version (kb888111.exe) : 6.1.22.0
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.78

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Customization.

Windows 2000/XP : -----

Windows 2000/XP :
 WDM driver for Win2000/WinXP : 5.10.0.5485
 WDM driver for Winx64 : 5.10.0.5485
 Realtek Soundman : 1.0.0.30
 Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
 Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
 Realtek Sound Effect Manager(RtlCpl) : 1.0.1.65
 Realtek Sound Effect Manager(RTHDCPL) : 2.1.6.0
 Alcwzrd.exe : 1.1.0.36
 SkyTel.exe : 2.0.1.20

Vista driver : -----

Vista driver for x86 :
 RtHDVCpl.exe : 1.0.0.92
 RtkAPO.dll : 11.0.6000.45
 RtkPgExt.dll : 6.0.6000.29
 RTCOMDLL.dll : 2.0.0.79
 RtlCPAPI.dll : 1.0.1.6
 RTSndMgr.cpl : 1.0.0.6
 RtkCoInst.dll : 1.0.1.8
 SRSTSXT.dll : 3.2.0.0
 SRSWOW.dll : 1.1.3.0
 SRSHP360.dll : 1.0.1.0
 SRSTSHD.dll : 1.1.4.0
 RtkApoApi.dll : 1.0.0.2
 Vista driver for x64 :
 RAVCpl64.exe : 1.0.0.92
 RtkAPO64.dll : 11.0.6000.45
 RtkPgEx64.dll : 6.0.6000.29
 RTCOMDLL.dll : 2.0.0.79
 RtlCPAPI.dll : 1.0.1.6
 RTSnMg64.cpl : 1.0.0.6
 RCoInst64.dll : 1.0.1.8
 SRSTX64.dll : 3.2.0.0
 SRSWOW64.dll : 1.1.3.0
 SRSHP64.dll : 1.0.1.0
 SRSTSH64.dll : 1.1.4.0
 RtkApi64.dll : 1.0.0.2

HDM Driver : -----

Vista x64:
 RtHDMVX.sys : 6.0.1.5413
 RtkHDM64.dll : 6.0.6000.37
 RHDME64.dll : 6.0.6000.25
 Vista x86:
 RtHDMV.sys : 6.0.1.5413

```

Readme.txt
RtkHDM.dll : 6.0.6000.37
RHDMExt.dll : 6.0.6000.25
XP/2K x64:
RtHDMX.sys : 5.10.0.5413
XP/2K x86:
RtHDM.sys : 5.10.0.5413

Driver Setup Program : 2.45

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013
//=====
Driver Package R1.77
Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .
1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260,
ALC262, ALC267, ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660,
ALC662, ALC260, ALC262, ALC267, ALC268
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
1.) Customization.
2.) Uninstall procedure for checking Rtlupd.exe file .

Windows 2000/XP : -----
Windows 2000/XP :
WDM driver for Win2000/WinXP : 5.10.0.5480
WDM driver for Winx64 : 5.10.0.5480
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.65
Realtek Sound Effect Manager(RTHDCPL) : 2.1.5.7
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 2.0.1.20
Vista driver : -----
Vista driver for x86 : 6.0.1.5480
RtHDVCpl.exe : 1.0.0.90
RtkAPO.dll : 11.0.6000.45
RtkPgExt.dll : 6.0.6000.29
RTCOMDLL.dll : 2.0.0.79
RtlCPAPI.dll : 1.0.1.6
RTSndMgr.cpl : 1.0.0.6
RtkCoInst.dll : 1.0.1.7
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.1.3.0
SRSHP360.dll : 1.0.1.0
SRSTSHD.dll : 1.1.4.0
RtkApoApi.dll : 1.0.0.2
Vista driver for x64 : 6.0.1.5480
RAVCpl64.exe : 1.0.0.90
RtkAPO64.dll : 11.0.6000.45
RtPgEx64.dll : 6.0.6000.29
RTCOMDLL.dll : 2.0.0.79
RtlCPAPI.dll : 1.0.1.6
RTSnMg64.cpl : 1.0.0.6
RCoInst64.dll : 1.0.1.7
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
SRSHP64.dll : 1.0.1.0
SRSTSH64.dll : 1.1.4.0
RtkApi64.dll : 1.0.0.2
HDM Driver : -----
Vista x64:
RtHDMVX.sys : 6.0.1.5413
RtkHDM64.dll : 6.0.6000.37

```

```

Readme.txt
RHDMEx64.dll : 6.0.6000.25
Vista x86:
RtHDMV.sys : 6.0.1.5413
RtkHDM.dll : 6.0.6000.37
RHDMExt.dll : 6.0.6000.25
XP/2K x64:
RtHDMX.sys : 5.10.0.5413
XP/2K x86:
RtHDM.sys : 5.10.0.5413

Driver Setup Program : 2.45

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013
//=====
Driver Package R1.76
Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/Wi nXP/Wi n2000/Wi n2003 .
1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260,
ALC262, ALC267, ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660,
ALC662, ALC260, ALC262, ALC267, ALC268
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
1.) Customization.
2.) Installer package language wrong for Japanese translation . ( Upgrade operation for Vista )

Windows 2000/XP : -----
Windows 2000/XP :
WDM driver for Win2000/Wi nXP : 5.10.0.5477
WDM driver for Winx64 : 5.10.0.5477
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtICpl) : 1.0.1.65
Realtek Sound Effect Manager(RTHDCPL) : 2.1.5.5
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 2.0.1.20
Vista driver : -----
Vista driver for x86 : 6.0.1.5477
RtHDVCpl.exe : 1.0.0.89
RtkAPO.dll : 11.0.6000.45
RtkPgExt.dll : 6.0.6000.29
RTCOMDLL.dll : 2.0.0.79
RtICPAPI.dll : 1.0.1.6
RTSndMgr.cpl : 1.0.0.6
RtkCoInst.dll : 1.0.1.7
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.1.3.0
SRSHP360.dll : 1.0.1.0
SRSTSHD.dll : 1.1.4.0
RtkApoApi.dll : 1.0.0.2
Vista driver for x64 : 6.0.1.5477
RAVCpl64.exe : 1.0.0.89
RtkAPO64.dll : 11.0.6000.45
RtPgEx64.dll : 6.0.6000.29
RTCOMDLL.dll : 2.0.0.79
RtICPAPI.dll : 1.0.1.6
RTSnMg64.cpl : 1.0.0.6
RCoInst64.dll : 1.0.1.7
SRSTX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
SRSHP64.dll : 1.0.1.0
SRSTSH64.dll : 1.1.4.0
RtkApi64.dll : 1.0.0.2
HDM Driver : -----

```


Readme.txt

Vista x64:
 RtHDM.VX.sys : 6.0.1.5413
 RtkHDM64.dll : 6.0.6000.37
 RHDME64.dll : 6.0.6000.25
 Vista x86:
 RtHDM.V.sys : 6.0.1.5413
 RtkHDM.dll : 6.0.6000.37
 RHDMEExt.dll : 6.0.6000.25
 XP/2K x64:
 RtHDM.X.sys : 5.10.0.5413
 XP/2K x86:
 RtHDM.sys : 5.10.0.5413
 Driver Setup Program : 2.44

Windows 2000/XP Operate on :
 Microsoft High Definition Audio Driver Package - KB888111
 Package file version (kb888111.exe) : 6.1.22.0
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.75

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Customization.

For New architecture:
 1.) Customization .

CPL :
 1.) Customization.

Windows 2000/XP : -----

Windows 2000/XP :
 WDM driver for Win2000/WinXP : 5.10.0.5473
 WDM driver for Winx64 : 5.10.0.5473
 Realtek Soundman : 1.0.0.30
 Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
 Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
 Realtek Sound Effect Manager(RtlCpl) : 1.0.1.65
 Realtek Sound Effect Manager(RTHDCPL) : 2.1.5.2
 Alcwzrd.exe : 1.1.0.36
 SkyTel.exe : 2.0.1.20

Vista driver : -----

Vista driver for x86 :
 RtHDVCpl.exe : 1.0.0.88
 RtkAPO.dll : 11.0.6000.44
 RtkPgExt.dll : 6.0.6000.29
 RTCOMDLL.dll : 2.0.0.79
 RtlCPAPI.dll : 1.0.1.6
 RTSndMgr.cpl : 1.0.0.6
 RtkColnst.dll : 1.0.1.7
 SRSTSXT.dll : 3.2.0.0
 SRSWOW.dll : 1.1.3.0
 SRSH360.dll : 1.0.1.0
 SRSTSHD.dll : 1.1.4.0
 RtkApoApi.dll : 1.0.0.2
 Vista driver for x64 : 6.0.1.5473
 RAVCpl64.exe : 1.0.0.88
 RtkAPO64.dll : 11.0.6000.44
 RtkPgEx64.dll : 6.0.6000.29
 RTCOMDLL.dll : 2.0.0.79
 RtlCPAPI.dll : 1.0.1.6

```

Readme.txt
RtSnMg64.cpl : 1.0.0.6
RtkColnst.dll : 1.0.1.7
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
SRSH64.dll : 1.0.1.0
SRSTSH64.dll : 1.1.4.0
RtkApi64.dll : 1.0.0.2
HDM Driver : -----
Vista x64:
RtHDM VX.sys : 6.0.1.5413
RtkHDM64.dll : 6.0.6000.37
RHDMEx64.dll : 6.0.6000.25
Vista x86:
RtHDM V.sys : 6.0.1.5413
RtkHDM.dll : 6.0.6000.37
RHDM Ext.dll : 6.0.6000.25
XP/2K x64:
RtHDM X.sys : 5.10.0.5413
XP/2K x86:
RtHDM.sys : 5.10.0.5413
Driver Setup Program : 2.42
Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013
//=====
Driver Package R1.74
Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .
1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260,
ALC262, ALC267, ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660,
ALC662, ALC260, ALC262, ALC267, ALC268
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
1.) Customization.
For New architecture:
1.) Customization .
CPL :
1.) Customization.
Windows 2000/XP : -----
Windows 2000/XP :
WDM driver for Win2000/WinXP : 5.10.0.5470
WDM driver for Winx64 : 5.10.0.5470
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.65
Realtek Sound Effect Manager(RTHDCPL) : 2.1.5.2
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 2.0.1.20
Vista driver : -----
Vista driver for x86 : 6.0.1.5470
RtHDVCpl.exe : 1.0.0.87
RtkAPO.dll : 11.0.6000.44
RtkPgExt.dll : 6.0.6000.28
RTCOMDLL.dll : 2.0.0.79
RtlCPAPI.dll : 1.0.1.6
RTSndMgr.cpl : 1.0.0.6
RtkColnst.dll : 1.0.1.7
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.1.3.0
SRSHP360.dll : 1.0.1.0

```

```

Readme.txt
SRSTSHD.dll : 1.1.4.0
RtkApoApi.dll : 1.0.0.2
Vista driver for x64 : 6.0.1.5470
RAVCpl64.exe : 1.0.0.87
RtkAPO64.dll : 11.0.6000.44
RtPgEx64.dll : 6.0.6000.28
RTCOMDLL.dll : 2.0.0.79
RtLCPAPI.dll : 1.0.1.6
RTSnMg64.cpl : 1.0.0.6
RtkColnst.dll : 1.0.1.7
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
SRSHP64.dll : 1.0.1.0
SRSTSH64.dll : 1.1.4.0
RtkApi64.dll : 1.0.0.2
HDM Driver : -----
Vista x64:
RtHDMVX.sys : 6.0.1.5413
RtkHDM64.dll : 6.0.6000.37
RHDMEx64.dll : 6.0.6000.25
Vista x86:
RtHDMV.sys : 6.0.1.5413
RtkHDM.dll : 6.0.6000.37
RHDMExt.dll : 6.0.6000.25
XP/2K x64:
RtHDMX.sys : 5.10.0.5413
XP/2K x86:
RtHDM.sys : 5.10.0.5413
Driver Setup Program : 2.40
Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013
//=====
Driver Package R1.73
Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .
1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260,
ALC262, ALC267, ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660,
ALC662, ALC260, ALC262, ALC267, ALC268
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
1.) Customization.
For New architecture:
1.) Customization .
CPL :
1.) Customization.
Windows 2000/XP : -----
Windows 2000/XP :
WDM driver for Win2000/WinXP : 5.10.0.5464
WDM driver for Winx64 : 5.10.0.5464
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtLCpl) : 1.0.1.65
Realtek Sound Effect Manager(RTHDCPL) : 2.1.4.9
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 2.0.1.20
Vista driver : -----
Vista driver for x86 : 6.0.1.5464
RtHDVCpl.exe : 1.0.0.84
RtkAPO.dll : 11.0.6000.43

```

```

Readme.txt
RtkPgExt.dll : 6.0.6000.27
RTCOMDLL.dll : 2.0.0.76
RtLCPAPI.dll : 1.0.1.6
RTSndMgr.cpl : 1.0.0.6
RtkColnst.dll : 1.0.1.7
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.1.3.0
SRSH360.dll : 1.0.1.0
SRSTSHD.dll : 1.1.4.0
RtkApoApi.dll : 1.0.0.2
Vista driver for x64 : 6.0.1.5464
RAVCpl64.exe : 1.0.0.84
RtkAPO64.dll : 11.0.6000.43
RtPgEx64.dll : 6.0.6000.27
RTCOMDLL.dll : 2.0.0.76
RtLCPAPI.dll : 1.0.1.6
RTSnMg64.cpl : 1.0.0.6
RtkColnst.dll : 1.0.1.7
SRSTX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
SRSH64.dll : 1.0.1.0
SRSTSH64.dll : 1.1.4.0
RtkApi64.dll : 1.0.0.2
HDM Driver : -----
Vista x64:
RtHDMVX.sys : 6.0.1.5413
RtkHDM64.dll : 6.0.6000.37
RHDMEx64.dll : 6.0.6000.25
Vista x86:
RtHDMV.sys : 6.0.1.5413
RtkHDM.dll : 6.0.6000.37
RHDMExt.dll : 6.0.6000.25
XP/2K x64:
RtHDMX.sys : 5.10.0.5413
XP/2K x86:
RtHDM.sys : 5.10.0.5413
Driver Setup Program : 2.38
Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013
//=====
Driver Package R1.72
Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .
1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260,
ALC262, ALC267, ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660,
ALC662, ALC260, ALC262, ALC267, ALC268
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
1.) Customization.
For New architecture:
1.) Customization .
CPL :
1.) Customization.
Windows 2000/XP : -----
Windows 2000/XP :
WDM driver for Win2000/WinXP : 5.10.0.5449
WDM driver for Winx64 : 5.10.0.5449
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9

```

```

Readme.txt
Realtek Sound Effect Manager(RtlCpl)           : 1.0.1.65
Realtek Sound Effect Manager(RTHDCPL)         : 2.1.4.2
Alcwzrd.exe                                   : 1.1.0.36
SkyTel.exe                                    : 2.0.1.19
Vista driver : -----
Vista driver for x86                          : 6.0.1.5449
RtHDVCpl.exe                                  : 1.0.0.73
RtkAPO.dll                                    : 11.0.6000.41
RtkPgExt.dll                                  : 6.0.6000.27
RTCOMDLL.dll                                  : 2.0.0.76
RtlCPAPI.dll                                  : 1.0.1.6
RTSndMgr.cpl                                  : 1.0.0.6
RtkColnst.dll                                 : 1.0.1.7
SRSTSXT.dll                                   : 3.2.0.0
SRSWOW.dll                                    : 1.1.2.0
SRSHP360.dll                                  : 1.0.1.0
SRSTSHD.dll                                   : 1.1.4.0
RtkApoApi.dll                                 : 1.0.0.2
Vista driver for x64                          : 6.0.1.5449
RAVCpl64.exe                                  : 1.0.0.73
RtkAPO64.dll                                  : 11.0.6000.41
RtPgEx64.dll                                  : 6.0.6000.27
RTCOMDLL.dll                                  : 2.0.0.76
RtlCPAPI.dll                                  : 1.0.1.6
RTSnMg64.cpl                                  : 1.0.0.6
RtkColnst.dll                                 : 1.0.1.7
SRSTSX64.dll                                  : 3.2.0.0
SRSWOW64.dll                                  : 1.1.2.0
SRSHP64.dll                                  : 1.0.1.0
SRSTSH64.dll                                  : 1.1.4.0
RtkApi64.dll                                  : 1.0.0.2
HDM Driver : -----
Vista x64:
RtHDMVX.sys                                   : 6.0.1.5413
RtkHDM64.dll                                  : 6.0.6000.37
RHDMEx64.dll                                  : 6.0.6000.25
Vista x86:
RtHDMV.sys                                    : 6.0.1.5413
RtkHDM.dll                                    : 6.0.6000.37
RHDMExt.dll                                   : 6.0.6000.25
XP/2K x64:
RtHDMX.sys                                    : 5.10.0.5413
XP/2K x86:
RtHDM.sys                                     : 5.10.0.5413
Driver Setup Program                          : 2.36

```

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.71

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Customization.

For New architecture:
1.) Customization .

CPL :
1.) Customization.

Readme.txt

```

Windows 2000/XP : -----
WDM driver for Win2000/WinXP      : 5.10.0.5443
WDM driver for Winx64             : 5.10.0.5443
Realtek Soundman                  : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtlCpl)    : 1.0.1.65
Realtek Sound Effect Manager(RTHDCPL)   : 2.1.4.2
Alcwzrd.exe                       : 1.1.0.36
SkyTel.exe                         : 2.0.1.19
Vista driver : -----
Vista driver for x86              : 6.0.1.5443
RtHdVCpl.exe                     : 1.0.0.73
RtkAPO.dll                       : 11.0.6000.40
RtkPgExt.dll                     : 6.0.6000.27
RTCOMDLL.dll                    : 2.0.0.74
RtlCPAPI.dll                    : 1.0.1.6
RTSndMgr.cpl                    : 1.0.0.6
RtkCoInst.dll                   : 1.0.1.7
SRSTSXT.dll                     : 3.2.0.0
SRSWOW.dll                      : 1.1.2.0
SRSH360.dll                     : 1.0.1.0
SRSTSHD.dll                     : 1.1.4.0
RtkApoApi.dll                   : 1.0.0.2
Vista driver for x64            : 6.0.1.5443
RAVCpl64.exe                    : 1.0.0.73
RtkAPO64.dll                    : 11.0.6000.40
RtkPgEx64.dll                   : 6.0.6000.27
RTCOMDLL.dll                   : 2.0.0.74
RtlCPAPI.dll                   : 1.0.1.6
RTSnMg64.cpl                   : 1.0.0.6
RtkCoInst.dll                  : 1.0.1.7
SRSTX64.dll                    : 3.2.0.0
SRSWOW64.dll                   : 1.1.2.0
SRSH64.dll                     : 1.0.1.0
SRSTSH64.dll                   : 1.1.4.0
RtkApi64.dll                   : 1.0.0.2
HDMI Driver : -----
Vista x64:
RtHDMVX.sys                     : 6.0.1.5413
RtkHDM64.dll                    : 6.0.6000.37
RHDMEx64.dll                    : 6.0.6000.25
Vista x86:
RtHDMV.sys                     : 6.0.1.5413
RtkHDM.dll                     : 6.0.6000.37
RHDMExt.dll                    : 6.0.6000.25
XP/2K x64:
RtHDMX.sys                     : 5.10.0.5413
XP/2K x86:
RtHDM.sys                      : 5.10.0.5413

Driver Setup Program             : 2.36

```

Windows 2000/XP Operate on :
 Microsoft High Definition Audio Driver Package - KB888111
 Package file version (kb888111.exe) : 6.1.22.0
 Hdaudio.sys version : 5.10.00.5013

//=====

- Driver Package R1.70
 Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .
1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
 2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
 3. HDMI Device WHQL Support: ATI HDMI Devices
 4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
 5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
 6. Add/Fix

1.) Customization.

For New architecture:

1.) Customization .

CPL :

1.) Customization.

```

Windows 2000/XP : -----
WDM driver for Win2000/WinXP : 5.10.0.5436
WDM driver for Winx64 : 5.10.0.5436
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.65
Realtek Sound Effect Manager(RTHDCPL) : 2.1.3.9
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 2.0.1.19
Vista driver : -----
Vista driver for x86 : 6.0.1.5436
RtHDVCpl.exe : 1.0.0.69
RtkAPO.dll : 11.0.6000.38
RtkPgExt.dll : 6.0.6000.27
RTCOMDLL.dll : 2.0.0.74
RtlCPAPI.dll : 1.0.1.6
RTSndMgr.cpl : 1.0.0.5
RtkColnst.dll : 1.0.1.5
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.1.2.0
SRSHP360.dll : 1.0.1.0
SRSTSHD.dll : 1.1.4.0
RtkApoApi.dll : 1.0.0.2
Vista driver for x64 : 6.0.1.5436
RAVCpl64.exe : 1.0.0.69
RtkAPO64.dll : 11.0.6000.38
RtPgEx64.dll : 6.0.6000.27
RTCOMDLL.dll : 2.0.0.74
RtlCPAPI.dll : 1.0.1.6
RTSnMg64.cpl : 1.0.0.5
RtkColnst.dll : 1.0.1.5
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.2.0
SRSHP64.dll : 1.0.1.0
SRSTSH64.dll : 1.1.4.0
RtkApi64.dll : 1.0.0.2
HDM Driver : -----
Vista x64:
RtHDMVX.sys : 6.0.1.5413
RtkHDM64.dll : 6.0.6000.37
RHDMEx64.dll : 6.0.6000.25
Vista x86:
RtHDMV.sys : 6.0.1.5413
RtkHDM.dll : 6.0.6000.37
RHDMExt.dll : 6.0.6000.25
XP/2K x64:
RtHDMX.sys : 5.10.0.5413
XP/2K x86:
RtHDM.sys : 5.10.0.5413

Driver Setup Program : 2.35

```

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.69

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262,

Readme.txt

ALC268

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268

3. HDM Device WHQL Support: ATI HDM Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix
1.) Customization.

For New architecture:

1.) Customization .

CPL :

1.) Customization.

Windows 2000/XP :	-----
WDM driver for Win2000/WinXP	: 5.10.0.5433
WDM driver for Winx64	: 5.10.0.5433
Realtek Soundman	: 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl)	: 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl)	: 1.0.0.9
Realtek Sound Effect Manager(Rt1Cpl)	: 1.0.1.65
Realtek Sound Effect Manager(RTHDCPL)	: 2.1.3.6
Alcwzrd.exe	: 1.1.0.36
SkyTel.exe	: 2.0.1.17
Vista driver :	-----
Vista driver for x86	: 6.0.1.5433
RtHdVCpl.exe	: 1.0.0.68
RtkAPO.dll	: 11.0.6000.38
RtkPgExt.dll	: 6.0.6000.27
RTCOMDLL.dll	: 2.0.0.74
Rt1CPAPI.dll	: 1.0.1.6
RTSndMgr.cpl	: 1.0.0.5
RtkColInst.dll	: 1.0.1.5
SRSTSXT.dll	: 3.2.0.0
SRSWOW.dll	: 1.1.2.0
SRSHP360.dll	: 1.0.1.0
SRSTSHD.dll	: 1.1.4.0
RtkApoApi.dll	: 1.0.0.2
Vista driver for x64	: 6.0.1.5433
RAVCpl64.exe	: 1.0.0.68
RtkAPO64.dll	: 11.0.6000.38
RtPgEx64.dll	: 6.0.6000.27
RTCOMDLL.dll	: 2.0.0.74
Rt1CPAPI.dll	: 1.0.1.6
RTSnMg64.cpl	: 1.0.0.5
RtkColInst.dll	: 1.0.1.5
SRSTX64.dll	: 3.2.0.0
SRSWOW64.dll	: 1.1.2.0
SRSHP64.dll	: 1.0.1.0
SRSTSH64.dll	: 1.1.4.0
RtkApi64.dll	: 1.0.0.2
HDM Driver :	-----
Vista x64:	
RtHDMVX.sys	: 6.0.1.5413
RtkHDM64.dll	: 6.0.6000.37
RHDMEx64.dll	: 6.0.6000.25
Vista x86:	
RtHDMV.sys	: 6.0.1.5413
RtkHDM.dll	: 6.0.6000.37
RHDMExt.dll	: 6.0.6000.25
XP/2K x64:	
RtHDMX.sys	: 5.10.0.5413
XP/2K x86:	
RtHDM.sys	: 5.10.0.5413
Driver Setup Program	: 2.34

Windows 2000/XP Operate on :

Readme.txt

Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.68

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization .

CPL :

- 1.) Customization.

Windows 2000/XP : -----

WDM driver for Win2000/WinXP	: 5.10.0.5413
WDM driver for Winx64	: 5.10.0.5413
Realtek Soundman	: 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl)	: 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl)	: 1.0.0.9
Realtek Sound Effect Manager(RtlCpl)	: 1.0.1.65
Realtek Sound Effect Manager(RTHDCPL)	: 2.1.3.2
Alcwzrd.exe	: 1.1.0.36
SkyTel.exe	: 2.0.1.12

Vista driver : -----

Vista driver for x86	: 6.0.1.5413
RtHDVCpl.exe	: 1.0.0.60
RtkAPO.dll	: 11.0.6000.37
RtkPgExt.dll	: 6.0.6000.25
RTCOMDLL.dll	: 2.0.0.73
RtlCPAPI.dll	: 1.0.1.6
RTSndMgr.cpl	: 1.0.0.5
RtkColnst.dll	: 1.0.1.2
SRSTSXT.dll	: 3.2.0.0
SRSWOW.dll	: 1.1.2.0
SRSH360.dll	: 1.0.1.0
SRSTSHD.dll	: 1.1.3.0
RtkApoApi.dll	: 1.0.0.2
Vista driver for x64	: 6.0.1.5413
RAVCpl64.exe	: 1.0.0.60
RtkAPO64.dll	: 11.0.6000.37
RtPgEx64.dll	: 6.0.6000.25
RTCOMDLL.dll	: 2.0.0.73
RtlCPAPI.dll	: 1.0.1.6
RTSnMg64.cpl	: 1.0.0.5
RtkColnst.dll	: 1.0.1.2
SRSTSX64.dll	: 3.2.0.0
SRSWOW64.dll	: 1.1.2.0
SRSH64.dll	: 1.0.1.0
SRSTSH64.dll	: 1.1.3.0
RtkApi64.dll	: 1.0.0.2

HDMI Driver : -----

Vista x64:	
RtHDMVX.sys	: 6.0.1.5413
RtkHDM64.dll	: 6.0.6000.37
RHDMEx64.dll	: 6.0.6000.25
Vista x86:	
RtHDMV.sys	: 6.0.1.5413
RtkHDM.dll	: 6.0.6000.37
RHDMExt.dll	: 6.0.6000.25
XP/2K x64:	

Readme.txt

RtHDMX.sys : 5.10.0.5413
 XP/2K x86:
 RtHDM.sys : 5.10.0.5413
 Driver Setup Program : 2.33

Windows 2000/XP Operate on :
 Microsoft High Definition Audio Driver Package - KB888111
 Package file version (kb888111.exe) : 6.1.22.0
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.67

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Customization.

For New architecture:
 1.) Customization .

CPL :
 1.) Customization.

Windows 2000/XP : -----

WDM driver for Win2000/WinXP : 5.10.0.5413
 WDM driver for Winx64 : 5.10.0.5413
 Realtek Soundman : 1.0.0.30
 Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
 Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
 Realtek Sound Effect Manager(RtICpl) : 1.0.1.65
 Realtek Sound Effect Manager(RTHDCPL) : 2.1.3.2
 Alcwzrd.exe : 1.1.0.36
 SkyTel.exe : 2.0.1.12

Vista driver : -----

Vista driver for x86 : 6.0.1.5413
 RtHdVCpl.exe : 1.0.0.60
 RtkAPO.dll : 11.0.6000.37
 RtkPgExt.dll : 6.0.6000.25
 RTCOMDLL.dll : 2.0.0.73
 RtICPAPI.dll : 1.0.1.6
 RTSndMgr.cpl : 1.0.0.5
 RtkCoInst.dll : 1.0.1.2
 SRSTSXT.dll : 3.2.0.0
 SRSWOW.dll : 1.1.2.0
 SRSHP360.dll : 1.0.1.0
 SRSTSHD.dll : 1.1.3.0
 RtkApoApi.dll : 1.0.0.2
 Vista driver for x64 : 6.0.1.5413
 RAVCpl64.exe : 1.0.0.60
 RtkAPO64.dll : 11.0.6000.37
 RtkPgEx64.dll : 6.0.6000.25
 RTCOMDLL.dll : 2.0.0.73
 RtICPAPI.dll : 1.0.1.6
 RTSnMg64.cpl : 1.0.0.5
 RtkCoInst.dll : 1.0.1.2
 SRSTX64.dll : 3.2.0.0
 SRSWOW64.dll : 1.1.2.0
 SRSHP64.dll : 1.0.1.0
 SRSTSH64.dll : 1.1.3.0
 RtkApi64.dll : 1.0.0.2

HDM Driver : -----

Vista x64:
 RtHDMVX.sys : 6.0.1.5368

```

Readme.txt
RtkHDM64.dll : 6.0.6000.26
RHDME64.dll : 6.0.6000.20
Vista x86:
RtHDMV.sys : 6.0.1.5368
RtkHDM.dll : 6.0.6000.26
RHDME64.dll : 6.0.6000.20
XP/2K x64:
RtHDMX.sys : 5.10.0.5368
XP/2K x86:
RtHDM.sys : 5.10.0.5368

Driver Setup Program : 2.32

```

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.66

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization .

CPL :

- 1.) Customization.

```

Windows 2000/XP : -----
WDM driver for Win2000/WinXP : 5.10.0.5404
WDM driver for Winx64 : 5.10.0.5404
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.65
Realtek Sound Effect Manager(RTHDCPL) : 2.1.3.2
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 2.0.1.11
Vista driver : -----
Vista driver for x86 : 6.0.1.5404
RtHDVCpl.exe : 1.0.0.54
RtkAPO.dll : 11.0.6000.35
RtkPgExt.dll : 6.0.6000.24
RTCOMDLL.dll : 2.0.0.72
RtlCPAPI.dll : 1.0.1.6
RTSndMgr.cpl : 1.0.0.5
RtkColnst.dll : 1.0.1.1
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.1.2.0
SRSHP360.dll : 1.0.0.0
SRSTSHD.dll : 1.1.2.0
Vista driver for x64 : 6.0.1.5404
RAVCpl64.exe : 1.0.0.54
RtkAPO64.dll : 11.0.6000.35
RtPgEx64.dll : 6.0.6000.24
RTCOMDLL.dll : 2.0.0.72
RtlCPAPI.dll : 1.0.1.6
RTSnMg64.cpl : 1.0.0.5
RtkColnst.dll : 1.0.1.1
SRSTX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.2.0

```

Readme.txt

SRSHP64.dll : 1.0.0.0
 SRSTSH64.dll : 1.1.2.0
 HDM Driver : -----
 Vista x64:
 RtHDMVX.sys : 6.0.1.5368
 RtkHDM64.dll : 6.0.6000.26
 RHDME64.dll : 6.0.6000.20
 Vista x86:
 RtHDMV.sys : 6.0.1.5368
 RtkHDM.dll : 6.0.6000.26
 RHDMEExt.dll : 6.0.6000.20
 XP/2K x64:
 RtHDMX.sys : 5.10.0.5368
 XP/2K x86:
 RtHDM.sys : 5.10.0.5368
 Driver Setup Program : 2.32

Windows 2000/XP Operate on :
 Microsoft High Definition Audio Driver Package - KB888111
 Package file version (kb888111.exe) : 6.1.22.0
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.65

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/Wi nXP/Wi n2000/Wi n2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Customization.

For New architecture:
 1.) Customization .

CPL :
 1.) Customization.

Windows 2000/XP : -----

WDM driver for Wi n2000/Wi nXP : 5.10.0.5397
 WDM driver for Wi nx64 : 5.10.0.5397
 Realtek Soundman : 1.0.0.30
 Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
 Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
 Realtek Sound Effect Manager(RtICpl) : 1.0.1.65
 Realtek Sound Effect Manager(RTHDCPL) : 2.1.3.0
 Alcwzrd.exe : 1.1.0.36
 SkyTel.exe : 2.0.1.9

Vista driver : -----

Vista driver for x86 : 6.0.1.5397
 RtHdVCpl.exe : 1.0.0.50
 RtkAPO.dll : 11.0.6000.32
 RtkPgExt.dll : 6.0.6000.22
 RTCOMDLL.dll : 2.0.0.70
 RtICPAPI.dll : 1.0.1.6
 RTSndMgr.cpl : 1.0.0.5
 RtkCoInst.dll : 1.0.1.1
 SRSTSXT.dll : 3.2.0.0
 SRSWOW.dll : 1.0.6.0
 Vista driver for x64 : 6.0.1.5397
 RAVCpl64.exe : 1.0.0.50
 RtkAPO64.dll : 11.0.6000.32
 RtkPgEx64.dll : 6.0.6000.22
 RTCOMDLL.dll : 2.0.0.70
 RtICPAPI.dll : 1.0.1.6
 RTSnMg64.cpl : 1.0.0.5

Readme.txt

```

RtkCoInst.dll           : 1.0.1.1
SRSTSX64.dll           : 3.2.0.0
SRSWOW64.dll           : 1.0.6.0
HDM Driver : -----
Vista x64:
RtHDMVX.sys            : 6.0.1.5368
RtkHDM64.dll           : 6.0.6000.26
RHDMEx64.dll           : 6.0.6000.20
Vista x86:
RtHDMV.sys             : 6.0.1.5368
RtkHDM.dll             : 6.0.6000.26
RHDMExt.dll            : 6.0.6000.20
XP/2K x64:
RtHDMX.sys             : 5.10.0.5368
XP/2K x86:
RtHDM.sys              : 5.10.0.5368

Driver Setup Program    : 2.31

```

Windows 2000/XP Operate on :
 Microsoft High Definition Audio Driver Package - KB888111
 Package file version (kb888111.exe) : 6.1.22.0
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.64

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Customization.

For New architecture:
 1.) Customization .

CPL :
 1.) Customization.

Windows 2000/XP : -----

```

WDM driver for Win2000/WinXP : 5.10.0.5391
WDM driver for Winx64       : 5.10.0.5391
Realtek Soundman           : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtlCpl)       : 1.0.1.65
Realtek Sound Effect Manager(RTHDCPL)     : 2.1.2.9
Alcwzrd.exe                 : 1.1.0.36
SkyTel.exe                  : 2.0.1.7

```

Vista driver : -----

```

Vista driver for x86       : 6.0.1.5391
RtHDVCpl.exe              : 1.0.0.46
RtkAPO.dll                : 11.0.6000.31
RtkPgExt.dll              : 6.0.6000.22
RTCOMDLL.dll              : 2.0.0.69
RtlCPAPI.dll              : 1.0.1.6
RTSndMgr.cpl              : 1.0.0.5
RtkCoInst.dll             : 1.0.0.12
SRSTSXT.dll               : 3.2.0.0
SRSWOW.dll                : 1.0.6.0
Vista driver for x64      : 6.0.1.5391
RAVCpl64.exe              : 1.0.0.46
RtkAPO64.dll              : 11.0.6000.31
RtPgEx64.dll              : 6.0.6000.22
RTCOMDLL.dll              : 2.0.0.69
RtlCPAPI.dll              : 1.0.1.6

```

```

Readme.txt
RTSnMg64.cpl : 1.0.0.5
RtkColnst.dll : 1.0.0.12
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.0.6.0
HDM Driver : -----
Vista x64:
RtHDMVX.sys : 6.0.1.5368
RtkHDM64.dll : 6.0.6000.26
RHDMEx64.dll : 6.0.6000.20
Vista x86:
RtHDMV.sys : 6.0.1.5368
RtkHDM.dll : 6.0.6000.26
RHDMExt.dll : 6.0.6000.20
XP/2K x64:
RtHDMX.sys : 5.10.0.5368
XP/2K x86:
RtHDM.sys : 5.10.0.5368
Driver Setup Program : 2.30

```

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.63

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix

1.) Customization.

For New architecture:

1.) Customization .

CPL :

1.) Customization.

```

Windows 2000/XP : -----
WDM driver for Win2000/WinXP : 5.10.0.5377
WDM driver for Winx64 : 5.10.0.5377
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtICpl) : 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL) : 2.1.2.4
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 1.0.0.0

```

```

Vista driver : -----
Vista driver for x86 : 6.0.1.5386
RtHdVCpl.exe : 1.0.0.43
RtkAPO.dll : 11.0.6000.29
RtkPgExt.dll : 6.0.6000.22
RTCOMDLL.dll : 2.0.0.69
RtICPAPI.dll : 1.0.1.6
RTSndMgr.cpl : 1.0.0.4
RtkColnst.dll : 1.0.0.9
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.0.6.0
Vista driver for x64 : 6.0.1.5386
RAVCpl64.exe : 1.0.0.43
RtkAPO64.dll : 11.0.6000.29
RtPgEx64.dll : 6.0.6000.22
RTCOMDLL.dll : 2.0.0.69

```

```

Readme.txt
RtICPAPI.dll : 1.0.1.6
RTSnMg64.cpl : 1.0.0.4
RtkColnst.dll : 1.0.0.9
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.0.6.0
HDM Driver : -----
Vista x64:
RtHDMVX.sys : 6.0.1.5368
RtkHDM64.dll : 6.0.6000.26
RHDMEx64.dll : 6.0.6000.20
Vista x86:
RtHDMV.sys : 6.0.1.5368
RtkHDM.dll : 6.0.6000.26
RHDMExt.dll : 6.0.6000.20
XP/2K x64:
RtHDMX.sys : 5.10.0.5368
XP/2K x86:
RtHDM.sys : 5.10.0.5368
Driver Setup Program : 2.30

```

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.62

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Customization.

For New architecture:
1.) Customization .

CPL :
1.) Customization.

```

Windows 2000/XP : -----
WDM driver for Win2000/WinXP : 5.10.0.5377
WDM driver for Winx64 : 5.10.0.5377
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtICpl) : 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL) : 2.1.2.4
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 1.0.0.0

```

```

Vista driver : -----
Vista driver for x86 : 6.0.1.5384
RtHDVCpl.exe : 1.0.0.41
RtkAPO.dll : 11.0.6000.28
RtkPgExt.dll : 6.0.6000.21
RTCOMDLL.dll : 2.0.0.69
RtICPAPI.dll : 1.0.1.6
RTSndMgr.cpl : 1.0.0.4
RtkColnst.dll : 1.0.0.9
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.0.6.0
Vista driver for x64 : 6.0.1.5384
RAVCpl64.exe : 1.0.0.41
RtkAPO64.dll : 11.0.6000.28
RtkPgEx64.dll : 6.0.6000.21

```

```

Readme.txt
RTCOMDLL.dll : 2.0.0.69
RtLCPAPI.dll : 1.0.1.6
RTSnMgr64.cpl : 1.0.0.4
RtkCoInst.dll : 1.0.0.9
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.0.6.0
HDMI Driver : -----
Vista x64:
RtHDMVX.sys : 6.0.1.5368
RtkHDM64.dll : 6.0.6000.26
RHDMEx64.dll : 6.0.6000.20
Vista x86:
RtHDMV.sys : 6.0.1.5368
RtkHDM.dll : 6.0.6000.26
RHDMExt.dll : 6.0.6000.20
XP/2K x64:
RtHDMX.sys : 5.10.0.5368
XP/2K x86:
RtHDM.sys : 5.10.0.5368
Driver Setup Program : 2.30

```

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.61

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/Wi nXP/Wi n2000/Wi n2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Customization.

For New architecture:
1.) Customization .

CPL :
1.) Customization.

```

Windows 2000/XP : -----
WDM driver for Win2000/Wi nXP : 5.10.0.5377
WDM driver for Winx64 : 5.10.0.5377
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtLcpl) : 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL) : 2.1.2.4
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 1.0.0.0
Vista driver : -----
Vista driver for x86 : 6.0.1.5377
RtHDVCpl.exe : 1.0.0.38
RtkAPO.dll : 11.0.6000.26
RtkPgExt.dll : 6.0.6000.20
RTCOMDLL.dll : 2.0.0.68
RtLCPAPI.dll : 1.0.1.5
RTSnMgr.cpl : 1.0.0.4
RtkCoInst.dll : 1.0.0.7
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.0.6.0
Vista driver for x64 : 6.0.1.5377
RAVCpl64.exe : 1.0.0.38
RtkAPO64.dll : 11.0.6000.26

```



```

Readme.txt
RtPgEx64.dll : 6.0.6000.20
RTCOMDLL.dll : 2.0.0.68
RtLCPAPI.dll : 1.0.1.5
RTSndMgr64.cpl : 1.0.0.4
RtkColnst.dll : 1.0.0.7
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.0.6.0
HDM Driver : -----
Vista x64:
RtHDM VX.sys : 6.0.1.5356
RtkHDM64.dll : 6.0.6000.20
RHDMEx64.dll : 6.0.6000.17
Vista x86:
RtHDM V.sys : 6.0.1.5356
RtkHDM.dll : 6.0.6000.20
RHDM Ext.dll : 6.0.6000.17
XP/2K x64:
RtHDM X.sys : 5.10.0.5356
XP/2K x86:
RtHDM.sys : 5.10.0.5356
Driver Setup Program : 2.30
Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013
//=====
Driver Package R1.60
Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .
1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262,
ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660,
ALC662, ALC260, ALC262, ALC267, ALC268
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
1.) Customization.
For New architecture:
1.) Customization .
CPL :
1.) Customization.
Windows 2000/XP : -----
WDM driver for Win2000/WinXP : 5.10.0.5366
WDM driver for Winx64 : 5.10.0.5366
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtLCpl) : 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL) : 2.1.2.0
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 1.0.0.0
Vista driver : -----
Vista driver for x86 : 6.0.1.5374
RtHDVCpl.exe : 1.0.0.36
RtkAPO.dll : 11.0.6000.25
RtkPgExt.dll : 6.0.6000.20
RTCOMDLL.dll : 2.0.0.66
RtLCPAPI.dll : 1.0.1.5
RTSndMgr.cpl : 1.0.0.4
RtkColnst.dll : 1.0.0.7
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.0.6.0
Vista driver for x64 : 6.0.1.5374
RAVCpl64.exe : 1.0.0.36

```

```

Readme.txt
RtkAPO64.dll : 11.0.6000.25
RtPgEx64.dll : 6.0.6000.20
RTCOMDLL.dll : 2.0.0.65
RtLCPAPI.dll : 1.0.1.5
RTSnMgr64.cpl : 1.0.0.4
RtkCoInst.dll : 1.0.0.7
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.0.6.0
HDMI Driver : -----
Vista x64:
RtHDMVX.sys : 6.0.1.5356
RtkHDM64.dll : 6.0.6000.20
RHDMEx64.dll : 6.0.6000.17
Vista x86:
RtHDMV.sys : 6.0.1.5356
RtkHDM.dll : 6.0.6000.20
RHDMExt.dll : 6.0.6000.17
XP/2K x64:
RtHDMX.sys : 5.10.0.5356
XP/2K x86:
RtHDM.sys : 5.10.0.5356
Driver Setup Program : 2.28
Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013
//=====
Driver Package R1.59
Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .
1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262,
ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660,
ALC662, ALC260, ALC262, ALC267, ALC268
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
1.) Customization.
For New architecture:
1.) Customization .
CPL :
1.) Customization.
Windows 2000/XP : -----
WDM driver for Win2000/WinXP : 5.10.0.5366
WDM driver for Winx64 : 5.10.0.5366
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtLcpl) : 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL) : 2.1.2.0
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 1.0.0.0
Vista driver : -----
Vista driver for x86 : 6.0.1.5372
RtHDVCpl.exe : 1.0.0.33
RtkAPO.dll : 11.0.6000.25
RtPgExt.dll : 6.0.6000.20
RTCOMDLL.dll : 2.0.0.66
RtLCPAPI.dll : 1.0.1.5
RTSnMgr.cpl : 1.0.0.4
RtkCoInst.dll : 1.0.0.7
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.0.6.0
Vista driver for x64 : 6.0.1.5372

```

```

Readme.txt
RAVCpl 64.exe           : 1.0.0.33
RtkAPO64.dll           : 11.0.6000.25
RtPgEx64.dll           : 6.0.6000.20
RTCOMDLL.dll           : 2.0.0.65
RtlCPAPI.dll           : 1.0.1.5
RTSnMgr64.cpl          : 1.0.0.4
RtkColnst.dll          : 1.0.0.7
SRSTSX64.dll           : 3.2.0.0
SRSWOW64.dll           : 1.0.6.0
HDM Driver : -----
Vista x64:
RtHDMVX.sys            : 6.0.1.5356
RtkHDM64.dll           : 6.0.6000.20
RHDME64.dll            : 6.0.6000.17
Vista x86:
RtHDMV.sys             : 6.0.1.5356
RtkHDM.dll             : 6.0.6000.20
RHDME64.dll            : 6.0.6000.17
XP/2K x64:
RtHDMX.sys             : 5.10.0.5356
XP/2K x86:
RtHDM.sys              : 5.10.0.5356
Driver Setup Program   : 2.28

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013
//=====
Driver Package R1.58
Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .
1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262,
ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660,
ALC662, ALC260, ALC262, ALC267, ALC268
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
1.) Customization.

For New architecture:
1.) Customization .

CPL :
1.) Customization.

Windows 2000/XP : -----
WDM driver for Win2000/WinXP : 5.10.0.5366
WDM driver for Winx64 : 5.10.0.5366
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL) : 2.1.2.0
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 1.0.0.0
Vista driver : -----
Vista driver for x86 : 6.0.1.5371
RtHDVCpl.exe : 1.0.0.32
RtkAPO.dll : 11.0.6000.25
RtPgExt.dll : 6.0.6000.20
RTCOMDLL.dll : 2.0.0.66
RtlCPAPI.dll : 1.0.1.5
RTSndMgr.cpl : 1.0.0.4
RtkColnst.dll : 1.0.0.7
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.0.6.0

```

```

Readme.txt
Vista driver for x64 : 6.0.1.5371
RAVCpl64.exe : 1.0.0.32
RtkAPO64.dll : 11.0.6000.25
RtPgEx64.dll : 6.0.6000.20
RTCOMDLL.dll : 2.0.0.65
RtICPAPI.dll : 1.0.1.5
RTSnMgr64.cpl : 1.0.0.4
RtkCoInst.dll : 1.0.0.7
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.0.6.0
HDMI Driver : -----
Vista x64:
RtHDMVX.sys : 6.0.1.5356
RtkHDM64.dll : 6.0.6000.20
RHDMEx64.dll : 6.0.6000.17
Vista x86:
RtHDMV.sys : 6.0.1.5356
RtkHDM.dll : 6.0.6000.20
RHDMExt.dll : 6.0.6000.17
XP/2K x64:
RtHDMX.sys : 5.10.0.5356
XP/2K x86:
RtHDM.sys : 5.10.0.5356
Driver Setup Program : 2.28
Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013
//=====
Driver Package R1.57
Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/Wi nXP/Wi n2000/Wi n2003 .
1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262,
ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660,
ALC662, ALC260, ALC262, ALC267, ALC268
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
1.) Customization.
For New architecture:
1.) Customization .
CPL :
1.) Customization.
Windows 2000/XP : -----
WDM driver for Wi n2000/Wi nXP : 5.10.0.5366
WDM driver for Wi nx64 : 5.10.0.5366
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtICpl) : 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL) : 2.1.2.0
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 1.0.0.0
Vista driver : -----
Vista driver for x86 : 6.0.1.5361
RtHDCpl.exe : 1.0.0.27
RtkAPO.dll : 11.0.6000.20
RtkPgExt.dll : 6.0.6000.17
RTCOMDLL.dll : 2.0.0.65
RtICPAPI.dll : 1.0.1.5
RTSnMgr.cpl : 1.0.0.1
RtkCoInst.dll : 1.0.0.6
SRSTSXT.dll : 3.2.0.0

```

```

Readme.txt
SRSWOW.dll : 1.0.6.0
Vista driver for x64 : 6.0.1.5361
RAVCpl64.exe : 1.0.0.27
RtkAPO64.dll : 11.0.6000.20
RtPgEx64.dll : 6.0.6000.17
RTCOMDLL.dll : 2.0.0.65
RtLCPAPI.dll : 1.0.1.5
RTSnMgr64.cpl : 1.0.0.1
RtkColnst.dll : 1.0.0.6
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.0.6.0
HDM Driver : -----
Vista x64:
RtHDMVX.sys : 6.0.1.5356
RtkHDM64.dll : 6.0.6000.20
RHDMEx64.dll : 6.0.6000.17
Vista x86:
RtHDMV.sys : 6.0.1.5356
RtkHDM.dll : 6.0.6000.20
RHDMExt.dll : 6.0.6000.17
XP/2K x64:
RtHDMX.sys : 5.10.0.5356
XP/2K x86:
RtHDM.sys : 5.10.0.5356
Driver Setup Program : 2.27
Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013
//=====
Driver Package R1.56
Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .
1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262,
ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660,
ALC662, ALC260, ALC262, ALC267, ALC268
3. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
4. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
5. Add/Fix
1.) Customization.
For New architecture:
1.) Customization .
CPL :
1.) Customization.
Windows 2000/XP :
WDM driver for Win2000/WinXP : 5.10.0.5345
WDM driver for Winx64 : 5.10.0.5345
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtLcpl) : 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL) : 2.1.1.4
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 1.0.0.0
Vista driver :
Vista driver for x86 : 6.0.1.5361
RtHDVCpl.exe : 1.0.0.27
RtkAPO.dll : 11.0.6000.20
RtkPgExt.dll : 6.0.6000.17
RTCOMDLL.dll : 2.0.0.65
RtLCPAPI.dll : 1.0.1.5
RTSndMgr.cpl : 1.0.0.1
RtkColnst.dll : 1.0.0.6
SRSTSXT.dll : 3.2.0.0

```

```

Readme.txt
SRSWOW.dll : 1.0.6.0
Vista driver for x64 : 6.0.1.5361
RAVCpl64.exe : 1.0.0.27
RtkAPO64.dll : 11.0.6000.20
RtPgEx64.dll : 6.0.6000.17
RTCOMDLL.dll : 2.0.0.65
RtLCPAPI.dll : 1.0.1.5
RTSnMgr64.cpl : 1.0.0.1
RtkCoInst.dll : 1.0.0.6
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.0.6.0

Driver Setup Program : 2.27

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013
//=====
Driver Package R1.55
1. Vista logo Codec Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262,
ALC268
2. Windows 2000/XP logo Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD,
ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
3. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
4. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
5. Add/Fix
1.) Customization.

For New architecture:
1.) Customization .

CPL :
1.) Customization.

Windows 2000/XP :
WDM driver for Win2000/WinXP : 5.10.0.5345
WDM driver for Winx64 : 5.10.0.5345
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtLcpl) : 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL) : 2.1.1.4
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 1.0.0.0
Vista driver :
Vista driver for x86 : 6.0.1.5350
RtHDVCpl.exe : 1.0.0.21
RtkAPO.dll : 11.0.6000.16
RtkPgExt.dll : 6.0.6000.15
RTCOMDLL.dll : 2.0.0.65
RtLCPAPI.dll : 1.0.1.5
RTSnMgr.cpl : 1.0.0.1
RtkCoInst.dll : 1.0.0.3
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.0.6.0
Vista driver for x64 : 6.0.1.5350
RAVCpl64.exe : 1.0.0.21
RtkAPO64.dll : 11.0.6000.16
RtPgEx64.dll : 6.0.6000.15
RTCOMDLL.dll : 2.0.0.65
RtLCPAPI.dll : 1.0.1.5
RTSnMgr64.cpl : 1.0.0.1
RtkCoInst.dll : 1.0.0.4
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.0.6.0

Driver Setup Program : 2.24

```

Readme.txt

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.54

1. Vista logo Codec Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC268
2. Windows 2000/XP logo Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
3. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
4. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
5. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization .

CPL :

- 1.) Customization.

Windows 2000/XP :

WDM driver for Win2000/WinXP	: 5.10.0.5345
WDM driver for Winx64	: 5.10.0.5345
Realtek Soundman	: 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl)	: 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl)	: 1.0.0.9
Realtek Sound Effect Manager(RtlCpl)	: 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL)	: 2.1.1.4
Alcwzrd.exe	: 1.1.0.36
SkyTel.exe	: 1.0.0.0
Vista driver :	
Vista driver for x86	: 6.0.1.5334
RtHDVCpl.exe	: 1.0.0.11
RtkAPO.dll	: 11.0.5600.13
RtkPgExt.dll	: 6.0.5600.12
RTCOMDLL.dll	: 1.0.0.63
RtlCPAPI.dll	: 1.0.1.5
RTSndMgr.cpl	: 1.0.0.1
RtkCoInst.dll	: 1.0.0.2
Vista driver for x64	: 6.0.1.5334
RAVCpl64.exe	: 1.0.0.11
RtkAPO64.dll	: 11.0.5600.13
RtPgEx64.dll	: 6.0.5600.12
RTCOMDLL.dll	: 1.0.0.63
RtlCPAPI.dll	: 1.0.1.5
RTSnMg64.cpl	: 1.0.0.1
RtkCoInst.dll	: 1.0.0.2

Driver Setup Program : 2.23

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.53

1. Vista logo Codec Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC268
2. Windows 2000/XP logo Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
3. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
4. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
5. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization .
- 2.) Fixed issue -> DTM Test \ Hal timer issue for V5331 Vista driver (Potential risk).

Readme.txt

CPL :

1.) Customization.

Windows 2000/XP :
WDM driver for Win2000/WinXP : 5.10.0.5324
WDM driver for Winx64 : 5.10.0.5324
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL) : 2.1.1.1
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 1.0.0.0
Vista driver :
Vista driver for x86 : 6.0.1.5334
RtHDVCpl.exe : 1.0.0.11
RtkAPO.dll : 11.0.5600.13
RtkPgExt.dll : 6.0.5600.12
RTCOMDLL.dll : 1.0.0.63
RtlCPAPI.dll : 1.0.1.5
RTSndMgr.cpl : 1.0.0.1
RtkColnst.dll : 1.0.0.2
Vista driver for x64 : 6.0.1.5334
RAVCpl64.exe : 1.0.0.11
RtkAPO64.dll : 11.0.5600.13
RtPgEx64.dll : 6.0.5600.12
RTCOMDLL.dll : 1.0.0.63
RtlCPAPI.dll : 1.0.1.5
RTSnMg64.cpl : 1.0.0.1
RtkColnst.dll : 1.0.0.2

Driver Setup Program : 2.21

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.52

1. Vista logo Codec Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC268
2. Windows 2000/XP logo Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
3. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
4. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
5. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization .
- 2.) Known issue -> DTM Test \ Hal timer issue for V5331 Vista driver (Potential risk).

CPL :

1.) Customization.

Windows 2000/XP :
WDM driver for Win2000/WinXP : 5.10.0.5324
WDM driver for Winx64 : 5.10.0.5324
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL) : 2.1.1.1
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 1.0.0.0
Vista driver :
Vista driver for x86 : 6.0.1.5331
RtHDVCpl.exe : 1.0.0.9

Readme.txt

RtkAPO.dll : 11.0.5600.13
RtkPgExt.dll : 6.0.5600.12
RTCOMDLL.dll : 1.0.0.63
RtlCPAPI.dll : 1.0.0.7
RTSndMgr.cpl : 1.0.0.1
RtkCoInst.dll : 1.0.0.1
Vista driver for x64 : 6.0.1.5331
RAVCpl64.exe : 1.0.0.9
RtkAPO64.dll : 11.0.5600.13
RtPgEx64.dll : 6.0.5600.12
RTCOMDLL.dll : 1.0.0.63
RtlCPAPI.dll : 1.0.0.7
RTSnMg64.cpl : 1.0.0.1
RtkCoInst.dll : 1.0.0.1

Driver Setup Program : 2.20

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.51

1. Vista logo Codec Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC268
2. Windows 2000/XP logo Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
3. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
4. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
5. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization .

CPL :

- 1.) Customization.

Windows 2000/XP :

WDM driver for Win2000/WinXP : 5.10.0.5324
WDM driver for Winx64 : 5.10.0.5324
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL) : 2.1.1.1
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 1.0.0.0
Vista driver :
Vista driver for x86 : 6.0.1.5322
RtHDVCpl.exe : 1.0.0.7
RtkAPO.dll : 11.0.5600.13
RtkPgExt.dll : 6.0.5600.12
RTCOMDLL.dll : 1.0.0.63
RtlCPAPI.dll : 1.0.0.7
RTSndMgr.cpl : 1.0.0.1
Vista driver for x64 : 6.0.1.5322
RAVCpl64.exe : 1.0.0.7
RtkAPO64.dll : 11.0.5600.13
RtPgEx64.dll : 6.0.5600.12
RTCOMDLL.dll : 1.0.0.63
RtlCPAPI.dll : 1.0.0.7
RTSnMg64.cpl : 1.0.0.1
Driver Setup Program : 2.20

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

Readme.txt

//=====

Driver Package R1.50

1. Vista logo Codec Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC268
2. Windows 2000/XP logo Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC268
3. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
4. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
5. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization .

CPL :

- 1.) Customization.

Windows 2000/XP :

WDM driver for Win2000/WinXP	: 5.10.0.5319
WDM driver for Winx64	: 5.10.0.5319
Realtek Soundman	: 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl)	: 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl)	: 1.0.0.9
Realtek Sound Effect Manager(RtlCpl)	: 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL)	: 2.1.0.8
Alcwzrd.exe	: 1.1.0.36
SkyTel.exe	: 1.0.0.0
Vista driver :	
Vista driver for x86	: 6.0.1.5322
RtHDVCpl.exe	: 1.0.0.7
RtkAPO.dll	: 11.0.5600.13
RtkPgExt.dll	: 6.0.5600.12
RTCOMDLL.dll	: 1.0.0.63
RtlCPAPI.dll	: 1.0.0.7
RTSndMgr.cpl	: 1.0.0.1
Vista driver for x64	: 6.0.1.5322
RAVCpl64.exe	: 1.0.0.7
RtkAPO64.dll	: 11.0.5600.13
RtPgEx64.dll	: 6.0.5600.12
RTCOMDLL.dll	: 1.0.0.63
RtlCPAPI.dll	: 1.0.0.7
RTSnMg64.cpl	: 1.0.0.1
Driver Setup Program	: 2.19

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.49

1. Vista logo Codec Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC268
2. Windows 2000/XP logo Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC268
3. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
4. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
5. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization .

CPL :

- 1.) Customization.

Windows 2000/XP :

WDM driver for Win2000/WinXP	: 5.10.0.5319
WDM driver for Winx64	: 5.10.0.5319
Realtek Soundman	: 1.0.0.30

Readme.txt

Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL) : 2.1.0.8
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 1.0.0.0
Vista driver :
Vista driver for x86 : 6.0.1.5317
RtHDVCpl.exe : 1.0.0.6
RtkAPO.dll : 11.0.5600.12
RtkPgExt.dll : 6.0.5600.12
RTCOMDLL.dll : 1.0.0.63
RtlCPAPI.dll : 1.0.0.7
RTSndMgr.cpl : 1.0.0.1
Vista driver for x64 : 6.0.1.5317
RAVCpl64.exe : 1.0.0.6
RtkAPO64.dll : 11.0.5600.12
RtPgEx64.dll : 6.0.5600.12
RTCOMDLL.dll : 1.0.0.63
RtlCPAPI.dll : 1.0.0.7
RTSnMg64.cpl : 1.0.0.1
Driver Setup Program : 2.19

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.48

Vista driver Version: 5.10.0.5317

1. Vista logo Codec Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC268

2. OS Supporting: Microsoft Windows Vista x86/x64

Vista driver for x86 : 6.10.0.5317
RtHDVCpl.exe : 1.0.0.6
RtkAPO.dll : 11.0.5600.12
RtkPgExt.dll : 6.0.5600.12
RTCOMDLL.dll : 1.0.0.63
RtlCPAPI.dll : 1.0.0.7
RTSndMgr.cpl : 1.0.0.1
Vista driver for x64 : 6.10.0.5317
RAVCpl64.exe : 1.0.0.6
RtkAPO64.dll : 11.0.5600.12
RtPgEx64.dll : 6.0.5600.12
RTCOMDLL.dll : 1.0.0.63
RtlCPAPI.dll : 1.0.0.7
RTSnMg64.cpl : 1.0.0.1
Driver Setup Program : 2.19

//=====

Driver Package R1.47

RtkHDAud.sys Version: 5.10.0.5296

1. Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861, ALC861VD, ALC660, ALC260, ALC262, ALC268

2. OS Supporting: Microsoft Windows XP, Windows 2000, Winx64

3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

4. Add/Fix

1.) Customization.

For New architecture:

1.) Customization .

CPL :

1.) Customization.

WDM driver for Win2000/WinXP : 5.10.0.5296
WDM driver for Winx64 : 5.10.0.5296
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10

```

Readme.txt
Realtek Sound Effect Manager(RTSndMgr.cpl)      : 1.0.0.9
Realtek Sound Effect Manager(RtlCpl)           : 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL)          : 2.0.9.8
Alcwzrd.exe                                     : 1.1.0.36
SkyTel.exe                                       : 1.0.0.0
Driver Setup Program                            : 2.18

Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013
//=====
Driver Package R1.46
RtkHDAud.sys Version: 5.10.0.5294
1. Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861, ALC861VD, ALC660, ALC260, ALC262,
ALC268
2. OS Supporting: Microsoft Windows XP, Windows 2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
   1.) Customization.

For New architecture:
   1.) Customization .

CPL :
   1.) Customization.

WDM driver for Win2000/WinXP                    : 5.10.0.5294
WDM driver for Winx64                          : 5.10.0.5294
Realtek Soundman                               : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl)     : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl)    : 1.0.0.9
Realtek Sound Effect Manager(RtlCpl)          : 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL)         : 2.0.9.6
Alcwzrd.exe                                     : 1.1.0.36
SkyTel.exe                                       : 1.0.0.0
Driver Setup Program                            : 2.16

Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013
//=====
Driver Package R1.45
RtkHDAud.sys Version: 5.10.0.5288
1. Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861, ALC861VD, ALC660, ALC260, ALC262,
ALC268
2. OS Supporting: Microsoft Windows XP, Windows 2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
   1.) Customization.

For New architecture:
   1.) Customization .

CPL :
   1.) Customization.

WDM driver for Win2000/WinXP                    : 5.10.0.5288
WDM driver for Winx64                          : 5.10.0.5288
Realtek Soundman                               : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl)     : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl)    : 1.0.0.9
Realtek Sound Effect Manager(RtlCpl)          : 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL)         : 2.0.9.1
Alcwzrd.exe                                     : 1.1.0.36
SkyTel.exe                                       : 1.0.0.0
Driver Setup Program                            : 2.15

```

Readme.txt

Operate on :

Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.44

RtkHDAud.sys Version: 5.10.0.5286

1. Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861, ALC861VD, ALC660, ALC260, ALC262, ALC268
2. OS Supporting: Microsoft Windows XP, Windows 2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization .

CPL :

- 1.) Customization.

WDM driver for Win2000/WinXP	: 5.10.0.5286
WDM driver for Winx64	: 5.10.0.5286
Realtek Soundman	: 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl)	: 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl)	: 1.0.0.8
Realtek Sound Effect Manager(RtlCpl)	: 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL)	: 2.0.8.7
Alcwzrd.exe	: 1.1.0.36
SkyTel.exe	: 1.0.0.0
Driver Setup Program	: 2.15

Operate on :

Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.43

RtkHDAud.sys Version: 5.10.0.5283

1. Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861, ALC861VD, ALC660, ALC260, ALC262, ALC268
2. OS Supporting: Microsoft Windows XP, Windows 2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization .

CPL :

- 1.) Customization.

WDM driver for Win2000/WinXP	: 5.10.0.5283
WDM driver for Winx64	: 5.10.0.5283
Realtek Soundman	: 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl)	: 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl)	: 1.0.0.8
Realtek Sound Effect Manager(RtlCpl)	: 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL)	: 2.0.8.3
Alcwzrd.exe	: 1.1.0.36
SkyTel.exe	: 1.0.0.0
Driver Setup Program	: 2.15

Operate on :

Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.42

RtkHDAud.sys Version: 5.10.0.5282

Readme.txt

- ALC268
1. Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861, ALC861VD, ALC660, ALC260, ALC262,
 2. OS Supporting: Microsoft Windows XP, Windows 2000, Winx64
 3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
 4. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization .
- 2.) Fix some game issue .

CPL :

- 1.) Customization.

WDM driver for Win2000/WinXP	: 5.10.0.5282
WDM driver for Winx64	: 5.10.0.5282
Realtek Soundman	: 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl)	: 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl)	: 1.0.0.8
Realtek Sound Effect Manager(RtlCpl)	: 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL)	: 2.0.8.0
Alcwzrd.exe	: 1.1.0.36
SkyTel.exe	: 1.0.0.0
Driver Setup Program	: 2.15

Operate on :

Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.41

RtkHDAud.sys Version: 5.10.0.5273

- ALC268
1. Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861, ALC861VD, ALC660, ALC260, ALC262,
 2. OS Supporting: Microsoft Windows XP, Windows 2000, Winx64
 3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
 4. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization.

CPL :

- 1.) Customization.

WDM driver for Win2000/WinXP	: 5.10.0.5273
WDM driver for Winx64	: 5.10.0.5273
Realtek Soundman	: 1.0.0.29
Realtek Sound Effect Manager(ALSndMgr.cpl)	: 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl)	: 1.0.0.8
Realtek Sound Effect Manager(RtlCpl)	: 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL)	: 2.0.7.3
Alcwzrd.exe	: 1.1.0.36
SkyTel.exe	: 1.0.0.0
Driver Setup Program	: 2.14

Operate on :

Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.40

RtkHDAud.sys Version: 5.10.0.5268

- ALC268
1. Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861, ALC861VD, ALC660, ALC260, ALC262,
 2. OS Supporting: Microsoft Windows XP, Windows 2000, Winx64
 3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
 4. Add/Fix
 - 1.) Customization.

Readme.txt

For New architecture:

- 1.) Customization .

CPL :

- 1.) Customization.

InstallShield package :

- 1.) Correct present driver version in "Add or Remove Programs \ Support Information" .
- 2.) Windows 2000 installation reboot twice problem .

WDM driver for Win2000/WinXP	: 5.10.0.5268
WDM driver for Winx64	: 5.10.0.5268
Realtek Soundman	: 1.0.0.29
Realtek Sound Effect Manager(ALSndMgr.cpl)	: 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl)	: 1.0.0.8
Realtek Sound Effect Manager(RtlCpl)	: 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL)	: 2.0.7.0
Alcwzrd.exe	: 1.1.0.36
SkyTel.exe	: 1.0.0.0
Driver Setup Program	: 2.14

Operate on :

Microsoft High Definition Audio Driver Package - KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.39

RtkHDAud.sys Version: 5.10.0.5265

1. Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861, ALC861VD, ALC260, ALC262
2. OS Supporting: Microsoft Windows XP, Windows 2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization .

CPL :

- 1.) Customization.
- 2.) Add support for left panel and right panel config.

InstallShield package :

- 1.) Copy file rule in Vista system .
- 2.) Show driver version in "Add or Remove Programs \ Support Information" .

WDM driver for Win2000/WinXP	: 5.10.0.5265
WDM driver for Winx64	: 5.10.0.5265
Realtek Soundman	: 1.0.0.29
Realtek Sound Effect Manager(ALSndMgr.cpl)	: 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl)	: 1.0.0.8
Realtek Sound Effect Manager(RtlCpl)	: 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL)	: 2.0.6.9
Alcwzrd.exe	: 1.1.0.36
SkyTel.exe	: 1.0.0.0
Driver Setup Program	: 2.13

Operate on :

Microsoft High Definition Audio Driver Package - KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.38

RtkHDAud.sys Version: 5.10.0.5257

1. Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861, ALC260, ALC262
2. OS Supporting: Microsoft Windows XP, Windows 2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
 - 1.) Customization.

Readme.txt

For New architecture:

- 1.) Customization .

CPL :

- 1.) Customization.

InstallShield package :

- 1.) Add "XP2K" and "Vista" folder name for installation .
- 2.) Abort flag setting .

WDM driver for Win2000/WinXP	: 5.10.0.5257
WDM driver for Winx64	: 5.10.0.5257
Realtek Soundman	: 1.0.0.29
Realtek Sound Effect Manager(ALSndMgr.cpl)	: 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl)	: 1.0.0.8
Realtek Sound Effect Manager(RtlCpl)	: 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL)	: 2.0.6.6
Alcwzrd.exe	: 1.1.0.36
SkyTel.exe	: 1.0.0.0
Driver Setup Program	: 2.11

Operate on :

Microsoft High Definition Audio Driver Package - KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.37

RtkHDAud.sys Version: 5.10.0.5253

1. Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861, ALC260, ALC262
2. OS Supporting: Microsoft Windows XP, Windows 2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization .

CPL :

- 1.) Customization.

InstallShield package :

- 1.) Upgrade to IS11.5 .

WDM driver for Win2000/WinXP	: 5.10.0.5253
WDM driver for Winx64	: 5.10.0.5253
Realtek Soundman	: 1.0.0.29
Realtek Sound Effect Manager(ALSndMgr.cpl)	: 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl)	: 1.0.0.8
Realtek Sound Effect Manager(RtlCpl)	: 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL)	: 2.0.6.4
Alcwzrd.exe	: 1.1.0.36
SkyTel.exe	: 1.0.0.0
Driver Setup Program	: 2.09

Operate on :

Microsoft High Definition Audio Driver Package - KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.36

RtkHDAud.sys Version: 5.10.0.5247

1. Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861, ALC260, ALC262
2. OS Supporting: Microsoft Windows XP, Windows 2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
 - 1.) Customization.

For New architecture:

Readme.txt

- 1.) Customization .
- 2.) Add ALC888 .

CPL :

- 1.) Customization.

InstallShield package :

WDM driver for Win2000/WinXP	: 5.10.0.5247
WDM driver for Winx64	: 5.10.0.5247
Realtek Soundman	: 1.0.0.28
Realtek Sound Effect Manager(ALSndMgr.cpl)	: 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl)	: 1.0.0.8
Realtek Sound Effect Manager(RtlCpl)	: 1.0.1.62
Realtek Sound Effect Manager(RTHDCPL)	: 2.0.5.9
Alcwzrd.exe	: 1.1.0.35
Driver Setup Program	: 2.06

Operate on :

Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.35

RtkHDAud.sys Version: 5.10.0.5242

1. Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC861, ALC260, ALC262
2. OS Supporting: Microsoft Windows XP, Windows 2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization .

CPL :

- 1.) Customization.

InstallShield package :

WDM driver for Win2000/WinXP	: 5.10.0.5242
WDM driver for Winx64	: 5.10.0.5242
Realtek Soundman	: 1.0.0.28
Realtek Sound Effect Manager(ALSndMgr.cpl)	: 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl)	: 1.0.0.8
Realtek Sound Effect Manager(RtlCpl)	: 1.0.1.62
Realtek Sound Effect Manager(RTHDCPL)	: 2.0.5.4
Alcwzrd.exe	: 1.1.0.35
Driver Setup Program	: 2.06

Operate on :

Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.34

RtkHDAud.sys Version: 5.10.0.5233

1. Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC861, ALC260, ALC262
2. OS Supporting: Microsoft Windows XP, Windows 2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization .
- 2.) Fixed Adobe Premiere Pro 1.5 Crash issue .

CPL :

- 1.) Customization.

Readme.txt

InstallShield package :

- 1.) Rtlupd termination return error code .
- 2.) Receive error code rule from Rtlupd SetupAPI .
- 3.) SetupCopyOEM install rule .

WDM driver for Win2000/WinXP : 5.10.0.5233
WDM driver for Winx64 : 5.10.0.5233
Realtek Soundman : 1.0.0.28
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.8
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.62
Realtek Sound Effect Manager(RTHDCPL) : 2.0.4.9
Alcwzrd.exe : 1.1.0.35
Driver Setup Program : 2.06

Operate on :

Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.33

RtkHDAud.sys Version: 5.10.0.5229

1. Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC861, ALC260, ALC262
2. OS Supporting: Microsoft Windows XP, Windows 2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization .

CPL :

- 1.) Customization.

InstallShield package :

- 1.) Bus driver detect issue .

WDM driver for Win2000/WinXP : 5.10.0.5229
WDM driver for Winx64 : 5.10.0.5229
Realtek Soundman : 1.0.0.28
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.8
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.61
Realtek Sound Effect Manager(RTHDCPL) : 2.0.4.7
Alcwzrd.exe : 1.1.0.34
Driver Setup Program : 2.05

Operate on :

Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.32

RtkHDAud.sys Version: 5.10.0.5224

1. Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC861, ALC260, ALC262
2. OS Supporting: Microsoft Windows XP, Windows 2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization .

CPL :

- 1.) Customization.

InstallShield package :

- 1.) Report installation progress and result to "C:\RTHSetup.log" within silent mode .
- 2.) Rtlupd setup API will not appear message dialog in silent mode .

Readme.txt

WDM driver for Win2000/WinXP : 5.10.0.5224
WDM driver for Winx64 : 5.10.0.5224
Realtek Soundman : 1.0.0.28
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.8
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.61
Realtek Sound Effect Manager(RTHDCPL) : 2.0.4.4
Alcwzrd.exe : 1.1.0.34
Driver Setup Program : 2.04

Operate on :

Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.31

RtkHDAud.sys Version: 5.10.0.5221
1. Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC861, ALC260, ALC262
2. OS Supporting: Microsoft Windows XP, Windows 2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
1.) Customization.

For New architecture:

- 1.) Customization .
- 2.) Add ALC885 HD Audio Codec for WHQL .

CPL :

- 1.) Customization.

InstallShield package :

WDM driver for Win2000/WinXP : 5.10.0.5221
WDM driver for Winx64 : 5.10.0.5221
Realtek Soundman : 1.0.0.27
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.8
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.60
Realtek Sound Effect Manager(RTHDCPL) : 2.0.4.2
Alcwzrd.exe : 1.1.0.33
Driver Setup Program : 2.03

Operate on :

Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.30

RtkHDAud.sys Version: 5.10.0.5211
1. Codec Supporting: ALC880, ALC882, ALC883, ALC861, ALC260, ALC262
2. OS Supporting: Microsoft Windows XP, Windows 2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
1.) Customization.

For New architecture:

- 1.) Customization .
- 2.) Bug fixed when recording AEC device failed on 880 .

CPL :

- 1.) Customization.

InstallShield package :

WDM driver for Win2000/WinXP : 5.10.0.5211
WDM driver for Winx64 : 5.10.0.5211
Realtek Soundman : 1.0.0.24
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10

Readme.txt

Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.8
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.58
Realtek Sound Effect Manager(RTHDCPL) : 2.0.3.9
Alcwzrd.exe : 1.1.0.31
Driver Setup Program : 2.03

Operate on :

Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.29

RtkHDAud.sys Version: 5.10.0.5202

1. Codec Supporting: ALC880, ALC882, ALC883, ALC861, ALC260, ALC262
2. OS Supporting: Microsoft Windows XP, Windows 2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization.

CPL :

- 1.) Customization.

InstallShield package :

WDM driver for Win2000/WinXP : 5.10.0.5202
WDM driver for Winx64 : 5.10.0.5202
Realtek Soundman : 1.0.0.21
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.7
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.54
Realtek Sound Effect Manager(RTHDCPL) : 2.0.3.4
Alcwzrd.exe : 1.1.0.29
Driver Setup Program : 2.02c

Operate on :

Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.28

RtkHDAud.sys Version: 5.10.0.5200

1. Codec Supporting: ALC880, ALC882, ALC883, ALC861, ALC260, ALC262
2. OS Supporting: Microsoft Windows XP, Windows 2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization.
- 2.) Add ALC265 .

CPL :

- 1.) Side speaker testing has no sound when 3D engine is disabled.

InstallShield package :

- 1.) Add Chipset ID VEN_1002&DEV_4383 .

WDM driver for Win2000/WinXP : 5.10.0.5200
WDM driver for Winx64 : 5.10.0.5200
Realtek Soundman : 1.0.0.21
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.7
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.53
Realtek Sound Effect Manager(RTHDCPL) : 2.0.3.2
Alcwzrd.exe : 1.1.0.28
Driver Setup Program : 2.02c

Readme.txt

Operate on :

Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.27

RtkHDAud.sys Version: 5.10.0.5188

1. Codec Supporting: ALC880, ALC882, ALC883, ALC861, ALC260, ALC262
2. OS Supporting: Microsoft Windows XP, Windows 2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization.

InstallShield package :

Fix :

1. Add installation file "RTHDAEQ*.dat" .
2. Add Package version in setup.ini .
3. Manual installation setting for InstallShield .

WDM driver for Win2000/WinXP	: 5.10.0.5188
WDM driver for Winx64	: 5.10.0.5188
Realtek Soundman	: 1.0.0.21
Realtek Sound Effect Manager(ALSndMgr.cpl)	: 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl)	: 1.0.0.7
Realtek Sound Effect Manager(RtlCpl)	: 1.0.1.53
Realtek Sound Effect Manager(RTHDCPL)	: 2.0.2.6
Alcwzrd.exe	: 1.1.0.28
Driver Setup Program	: 2.02a

Operate on :

Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.26

RtkHDAud.sys Version: 5.10.0.5178

1. Codec Supporting: ALC880, ALC882, ALC883, ALC861, ALC260, ALC262
2. OS Supporting: Microsoft Windows XP, Windows 2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization.

InstallShield package :

Fix :

1. Set rebooting twice for installation UAA QFE on Win2000 .

WDM driver for Win2000/WinXP	: 5.10.0.5178
WDM driver for Winx64	: 5.10.0.5178
Realtek Soundman	: 1.0.0.21
Realtek Sound Effect Manager(ALSndMgr.cpl)	: 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl)	: 1.0.0.6
Realtek Sound Effect Manager(RtlCpl)	: 1.0.1.52
Realtek Sound Effect Manager(RTHDCPL)	: 2.0.2.1
Alcwzrd.exe	: 1.1.0.28
Driver Setup Program	: 2.00

Operate on :

Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.25

Readme.txt

RtkHDAud.sys Version: 5.10.0.5172

1. Codec Supporting: ALC880, ALC882, ALC883, ALC861, ALC260, ALC262
2. OS Supporting: Microsoft Windows XP, Windows 2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization.

InstallShield package :

Fix :

1. Rtlupd.exe(2.5.0.5) fixed roll-back problem (It can not delete oem.inf file before update driver).

2. Change Azalia name in setup.ini file .
3. Don't popup Rtlupd dialog when you select "No" on Hotfix installation dialog .

Add :

1. System language identifier .
2. Change pop-up dialog Product name (Azalia->High Definition) .

WDM driver for Win2000/WinXP	: 5.10.0.5172
WDM driver for Winx64	: 5.10.0.5172
Realtek Soundman	: 1.0.0.21
Realtek Sound Effect Manager(ALSndMgr.cpl)	: 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl)	: 1.0.0.6
Realtek Sound Effect Manager(RtlCpl)	: 1.0.1.51
Realtek Sound Effect Manager(RTHDCPL)	: 2.0.1.7
Alcwzrd.exe	: 1.1.0.27
Driver Setup Program	: 1.99

Operate on :

Microsoft High Definition Audio Driver Package - KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.24

RtkHDAud.sys Version: 5.10.0.5152

1. Codec Supporting: ALC880, ALC882, ALC883, ALC861, ALC260, ALC262
2. OS Supporting: Microsoft Windows XP, Windows 2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization.
- 2.) Support 192KHz sample rate output.

InstallShield package :

Fix :

1. Reboot timing after installation MS QFE (UAA driver) .
2. Uninstallation dialog description .

Add :

1. MS hotfix KB901105 can be included by HD package (If get MS licence) .
2. Hotfix KB901105 Warning message .

WDM driver for Win2000/WinXP	: 5.10.0.5152
WDM driver for Winx64	: 5.10.0.5152
Realtek Soundman	: 1.0.0.18
Realtek Sound Effect Manager(ALSndMgr.cpl)	: 1.0.0.7
Realtek Sound Effect Manager(RTSndMgr.cpl)	: 1.0.0.4
Realtek Sound Effect Manager(RtlCpl)	: 1.0.1.46
Realtek Sound Effect Manager(RTHDCPL)	: 2.0.0.8
Alcwzrd.exe	: 1.1.0.24
Driver Setup Program	: 1.96

Operate on :

Microsoft High Definition Audio Driver Package - KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

Readme.txt

//=====

Driver Package R1.23

RtkHDAud.sys Version: 5.10.0.5136

1. Codec Supporting: ALC880, ALC882, ALC883, ALC861, ALC260, ALC262
2. OS Supporting: Microsoft Windows XP, Windows 2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization.
- 2.) Support new codec ALC262, ALC883

InstallShield package :

- 1.) Check OS service pack number with InstallShield .
- 2.) Change audio wizard quitting procedure .

WDM driver for Win2000/WinXP	: 5.10.0.5136
WDM driver for Winx64	: 5.10.0.5136
Realtek Soundman	: 1.0.0.17
Realtek Sound Effect Manager(ALSndMgr.cpl)	: 1.0.0.7
Realtek Sound Effect Manager(RTSndMgr.cpl)	: 1.0.0.4
Realtek Sound Effect Manager(RtlCpl)	: 1.0.1.43
Realtek Sound Effect Manager(RTHDCPL)	: 1.1.2.3
Alcwzrd.exe	: 1.1.0.23
Driver Setup Program	: 1.92

Operate on :

Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.22

RtkHDAud.sys Version: 5.10.0.5128

1. Codec Supporting: ALC880, ALC882, ALC861, ALC260
2. OS Supporting: Microsoft Windows XP, Windows 2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization.

InstallShield package :

- 1.) Setup progress backward .
- 2.) Driver size on Add and remove programs .
- 3.) Refresh driver size on Add and Remove Programs .
- 4.) Check RtlExupd.dll version .
- 5.) Check RtlHDCpl.exe version .

WDM driver for Win2000/WinXP	: 5.10.0.5128
WDM driver for Winx64	: 5.10.0.5128
Realtek Soundman	: 1.0.0.17
Realtek Sound Effect Manager(ALSndMgr.cpl)	: 1.0.0.7
Realtek Sound Effect Manager(RTSndMgr.cpl)	: 1.0.0.4
Realtek Sound Effect Manager(RtlCpl)	: 1.0.1.40
Realtek Sound Effect Manager(RTHDCPL)	: 1.1.1.9
Alcwzrd.exe	: 1.1.0.20
Driver Setup Program	: 1.91

Operate on :

Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.21

RtkHDAud.sys Version: 5.10.0.5127

1. Codec Supporting: ALC880, ALC882, ALC260
2. OS Supporting: Microsoft Windows XP, Windows 2000, Winx64

Readme.txt

3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization.
- 2.) Support DTS Encoder and DTS Neo for special version codec .

SoundMan.exe Version: 1.0.0.17
ALSndMgr.cpl Version: 1.0.0.7
Rtlcpl.exe Version: 1.0.1.40
Alcwzrd.exe Version: 1.1.0.20

Operate on :

Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.20

RtkHDAud.sys Version: 5.10.0.5125
1. Codec Supporting: ALC880, ALC882, ALC260
2. OS Supporting: Microsoft Windows XP, Windows 2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix

- 1.) Customization.

For New architecture:

- 1.) Customization.
- 2.) Fixed the issue of SPDIF-In capture

SoundMan.exe Version: 1.0.0.17
ALSndMgr.cpl Version: 1.0.0.7
Rtlcpl.exe Version: 1.0.1.40
Alcwzrd.exe Version: 1.1.0.20

Operate on :

Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.19

RtkHDAud.sys Version: 5.10.0.5123
1. Codec Supporting: ALC880, ALC882, ALC260
2. OS Supporting: Microsoft Windows XP, Windows 2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix

1. Customization.
2. Avoid Pop noise when toggle output sampling rate for ALC260.
3. Restore the original timer resolution first before check the original system timer resolution.

For New architecture:

- 1.) Customization.
- 2.) Driver store mixer setting after windows reboot

SoundMan.exe Version: 1.0.0.14
ALSndMgr.cpl Version: 1.0.0.5
Rtlcpl.exe Version: 1.0.1.39
Alcwzrd.exe Version: 1.1.0.19

Operate on :

Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.18

RtkHDAud.sys Version: 5.10.0.5122
1. Codec Supporting: ALC880, ALC882, ALC260
2. OS Supporting: Microsoft Windows XP, Windows 2000
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

Readme.txt

4. Add/Fix
 1. Customization.
 2. Add 2 default values of codec subsystem ID for ALC260.

For New architecture:

- 1.) Customization.
- 2.) Fixed the issue of uncontinuous sound after suspend on some machine.

SoundMan.exe Version: 1.0.0.14
ALSndMgr.cpl Version: 1.0.0.5
Rtlcpl.exe Version: 1.0.1.38
Alcwzrd.exe Version: 1.1.0.18

Operate on :

Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.17

RtkHDAud.sys Version: 5.10.0.5120
1. Codec Supporting: ALC880, ALC882, ALC260, ALC861
2. OS Supporting: Microsoft Windows XP, Windows 2000
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix

1. Customization.
2. Restore certain register value when resume from system suspend.

For New architecture:

- 1.) Customization.
- 2.) Improve reliability for switching multiple streaming.

SoundMan.exe Version: 1.0.0.14
ALSndMgr.cpl Version: 1.0.0.5
Rtlcpl.exe Version: 1.0.1.38
Alcwzrd.exe Version: 1.1.0.18

Operate on :

Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.16

RtkHDAud.sys Version: 5.10.0.5119
1. Codec Supporting: ALC880, ALC882, ALC260, ALC861
2. OS Supporting: Microsoft Windows XP, Windows 2000
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix

1. Customization.
2. Fix initial noise issue for the certain models.
3. Check codec SubsystemID verb to decide the driver path when driver initialize.
4. Don't modify Configuration byte Verbs when driver initialize.
5. Fix Buffer size un-alignment issue.

For New architecture:

- 1.) Customization.
- 2.) Fix the problem when play AC-3 stream by SPDIF interface
- 3.) Change device name for multiple streaming issue.

SoundMan.exe Version: 1.0.0.14
ALSndMgr.cpl Version: 1.0.0.5
Rtlcpl.exe Version: 1.0.1.38
Alcwzrd.exe Version: 1.1.0.17

Operate on :

Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.15

Readme.txt

RtkHDAud.sys Version: 5.10.0.5116

1. Codec Supporting: ALC880, ALC882, ALC260, ALC861
2. OS Supporting: Microsoft Windows XP, Windows 2000
3. Pack with Microsoft High Definition Audio UAAV1(5011)
4. Add/Fix
 - 1.) Customization.
 - 2.) Auto lock SPDIF-in signal when SPDIF-in signal is unlocked.
 - 3.) Fix SPDIF out copy protection issue.
 - 4.) Add patch code for ALC260 potential risk.

For New architecture:

- 1.) Customization.
- 2.) Fix new feature problem on multiple streaming.
- 3.) Fix capture problem on ALC882.

SoundMan.exe Version: 1.0.0.14

ALSndMgr.cpl Version: 1.0.0.5

Rtlcpl.exe Version: 1.0.1.38

Alcwzrd.exe Version: 1.1.0.17

Operate on :

Microsoft High Definition Audio Driver Package - KB835221
Package file version (kb835221.exe) : 6.1.1.0
Hdaudio.sys version : 5.10.00.5011

//=====

Driver Package R1.14

RtkHDAud.sys Version: 5.10.0.5109

1. Codec Supporting: ALC880, ALC882, ALC260, ALC861
2. OS Supporting: Microsoft Windows XP, Windows 2000
3. Pack with Microsoft High Definition Audio UAAV1(5011)
4. Add/Fix
 - 1.) Customization.
 - 2.) Reduce delay time when volume is adjusted.
 - 3.) Fix hang up issue when system resume from S3.

For New architecture:

- 1.) New architecture of HD audio driver formal release.

SoundMan.exe Version: 1.0.0.14

ALSndMgr.cpl Version: 1.0.0.4

Rtlcpl.exe Version: 1.0.1.37

Alcwzrd.exe Version: 1.1.0.16

Operate on :

Microsoft High Definition Audio Driver Package - KB835221
Package file version (kb835221.exe) : 6.1.1.0
Hdaudio.sys version : 5.10.00.5011

//=====

Driver Package R1.13

RtkHDAud.sys Version: 5.10.0.5038

1. Codec Supporting: ALC880, ALC260, ALC861
2. OS Supporting: Microsoft Windows XP, Windows 2000
3. Pack with Microsoft High Definition Audio UAAV1(5011)
4. Add/Fix
 - 1) Reduce initialize noise

SoundMan.exe Version: 1.0.0.14

ALSndMgr.cpl Version: 1.0.0.5

Rtlcpl.exe Version: 1.0.1.36

Alcwzrd.exe Version: 1.1.0.15

Operate on :

Microsoft High Definition Audio Driver Package - KB835221
Package file version (kb835221.exe) : 6.1.1.0
Hdaudio.sys version : 5.10.00.5011

//=====

Driver Package R1.12

RtkHDAud.sys Version: 5.10.0.5037

1. Codec Supporting: ALC880, ALC260, ALC861

Readme.txt

2. OS Supporting: Microsoft Windows XP, Windows 2000
3. Pack with Microsoft High Definition Audio UAAV1(5011)
4. Add/Fix
 - 1) Improve recording performance.
 - 2) Reduce initialize noise

SoundMan.exe Version: 1.0.0.14
ALSndMgr.cpl Version: 1.0.0.5
Rtlcpl.exe Version: 1.0.1.36
Alcwzrd.exe Version: 1.1.0.15

Operate on :

Microsoft High Definition Audio Driver Package - KB835221
Package file version (kb835221.exe) : 6.1.1.0
Hdaudio.sys version : 5.10.00.5011

//=====

Driver Package R1.11

RtkHDAud.sys Version: 5.10.0.5036

1. Codec Supporting: ALC880, ALC260, ALC861
2. OS Supporting: Microsoft Windows XP, Windows 2000
3. Pack with Microsoft High Definition Audio UAAV1(5011)
4. Add/Fix

SoundMan.exe Version: 1.0.0.14
ALSndMgr.cpl Version: 1.0.0.5
Rtlcpl.exe Version: 1.0.1.35
Alcwzrd.exe Version: 1.1.0.15

Operate on :

Microsoft High Definition Audio Driver Package - KB835221
Package file version (kb835221.exe) : 6.1.1.0
Hdaudio.sys version : 5.10.00.5011

//=====

Driver Package R1.10

RtkHDAud.sys Version: 5.10.0.5034

1. Codec Supporting: ALC880, ALC260, ALC861
2. OS Supporting: Microsoft Windows XP, Windows 2000
3. Pack with Microsoft High Definition Audio UAAV1(5011)
4. Add/Fix
 - 1) Fix the problem that there is little noise when start stream playing
 - 2) Fix the problem that in WinDVD, the SPDIF option still exist even there is no SPDIF

SoundMan.exe Version: 1.0.0.14
1. Set the default recording device as "Realtek HD Audio rear input" device

ALSndMgr.cpl Version: 1.0.0.5

Rtlcpl.exe Version: 1.0.1.34

Alcwzrd.exe Version: 1.1.0.15

1. Keep previous Jack setting.
2. Check whether have any jack plugin when restart OS, and popup the device window if wizard detect any new device plugin.

Operate on :

Microsoft High Definition Audio Driver Package - KB835221
Package file version (kb835221.exe) : 6.1.1.0
Hdaudio.sys version : 5.10.00.5011

//=====

Driver Package R1.09

RtkHDAud.sys Version: 5.10.0.5033

1. Codec Supporting: ALC880, ALC260, ALC861
2. OS Supporting: Microsoft Windows XP, Windows 2000
3. Pack with Microsoft High Definition Audio OOB Binaries V1.0

SoundMan.exe Version: 1.0.0.14
1. Set the default recording device as "Realtek HD Audio rear input" device

Readme.txt

ALSndMgr.cpl Version: 1.0.0.5
Rtlcpl.exe Version: 1.0.1.33
Alcwzrd.exe Version: 1.1.0.14

Operate on :

Microsoft High Definition Audio Driver Package - KB835221
Package file version (kb835221.exe) : 6.1.1.0
Hdaudio.sys version : 5.10.00.5010

//=====

Driver Package R1.08

RtkHDAud.sys Version: 5.10.0.5032
1. Codec Supporting: ALC880, ALC260, ALC861
2. OS Supporting: Microsoft Windows XP, Windows 2000
3. Pack with Microsoft High Definition Audio OOB Binaries V1.0

SoundMan.exe Version: 1.0.0.12
ALSndMgr.cpl Version: 1.0.0.5
Rtlcpl.exe Version: 1.0.1.33
Alcwzrd.exe Version: 1.1.0.14

Operate on :

Microsoft High Definition Audio Driver Package - KB835221
Package file version (kb835221.exe) : 6.1.1.0
Hdaudio.sys version : 5.10.00.5010

//=====

Driver Package R1.07

RtkHDAud.sys Version: 5.10.0.5031
1. Codec Supporting: ALC880, ALC260, ALC861
2. OS Supporting: Microsoft Windows XP, Windows 2000
3. Pack with Microsoft High Definition Audio OOB Binaries V1.0
4. Add/Fix
1) Fix the problem when playback with sound recorder, when change frequency from 48k to 44.1k in SPDIF page, playback will stop
2) Support for ALC880G, ALC880D, ALC260D
3) Fix the the problem that system will hang up while perform audio test in 3DMark 2003

SoundMan.exe Version: 1.0.0.12
ALSndMgr.cpl Version: 1.0.0.5

Rtlcpl.exe Version: 1.0.1.32
1. Fix word collision problem in Multi-Language.

Alcwzrd.exe Version: 1.1.0.13
1. Restore previous jack setting when reboot system

Operate on :

Microsoft High Definition Audio Driver Package - KB835221
Package file version (kb835221.exe) : 6.1.1.0
Hdaudio.sys version : 5.10.00.5010

//=====

Driver Package R1.06

RtkHDAud.sys Version: 5.10.0.5030
1. Codec Supporting: ALC880, ALC260, ALC861
2. OS Supporting: Microsoft Windows XP, Windows 2000
3. Pack with Microsoft High Definition Audio OOB Binaries V1.0
4. Add/Fix

SoundMan.exe Version: 1.0.0.12
ALSndMgr.cpl Version: 1.0.0.3
Rtlcpl.exe Version: 1.0.1.31
Alcwzrd.exe Version: 1.1.0.12

Operate on :

Microsoft High Definition Audio Driver Package - KB835221
Package file version (kb835221.exe) : 6.1.1.0
Hdaudio.sys version : 5.10.00.5010

//=====

Readme.txt

Driver Package R1.05

RtkHDAud.sys Version: 5.10.0.5029

1. Codec Supporting: ALC880, ALC260, ALC861
2. OS Supporting: Microsoft Windows XP, Windows 2000
3. Pack with Microsoft High Definition Audio OOB Binaries V1.0
4. Add/Fix
 - 1) Add support for ALC861
 - 2) Fix the noise problem that when recording from SPDIF In at 96khz

SoundMan.exe Version: 1.0.0.12

ALSndMgr.cpl Version: 1.0.0.5

Rtlcpl.exe Version: 1.0.1.31

Alcwzrd.exe Version: 1.1.0.12

Operate on :

Microsoft High Definition Audio Driver Package - KB835221

Package file version (kb835221.exe) : 6.1.1.0

Hdaudio.sys version : 5.10.00.5010

//=====

Driver Package R1.04

RtkHDAud.sys Version: 5.10.0.5028

1. Codec Supporting: ALC880, ALC260
2. OS Supporting: Microsoft Windows XP, Windows 2000
3. Pack with Microsoft High Definition Audio OOB Binaries V1.0
4. Add/Fix
 - 1) For UAJ A to A volume line, change type from KSNODETYPE_MICROPHONE to KSNODETYPE_ANALOG_CONNECTOR
 - 2) Fix the problem that SPDIF out no sound in WinDVD
 - 3) Fix the problem that there is balance control in Center and Subwoofer volume line in Wzk
 - 4) Change the component type of SPDIF-In from "KSNODETYPE_ANALOG_CONNECTOR" to "KSNODETYPE_SPDIF_INTERFACE"
 - 5) Fix the problem that mute SPDIF out in mixer doesn't work

SoundMan.exe Version: 1.0.0.12

ALSndMgr.cpl Version: 1.0.0.3

Rtlcpl.exe Version: 1.0.1.31

1. Turn off all sound effect when speaker test!

Alcwzrd.exe Version: 1.1.0.12

Operate on :

Microsoft High Definition Audio Driver Package - KB835221

Package file version (kb835221.exe) : 6.1.1.0

Hdaudio.sys version : 5.10.00.5010

//=====

Driver Package R1.03

RtkHDAud.sys Version: 5.10.0.5027

SoundMan.exe Version: 1.0.0.4

ALSndMgr.cpl Version: 1.0.0.2

Rtlcpl.exe Version: 1.0.1.29

1. Sync the status which Enable/Disable wizard with alcwzrd
2. Make the tab of "Audio Wizard" independent from menu tabs.
3. Stop the play sound when menu tab is change.

Alcwzrd.exe Version: 1.1.0.12

1. Fixed broken wizard image.
2. Sync the status which Enable/Disable wizard with rtlcpl.

Operate on :

Microsoft High Definition Audio Driver Package - KB835221

Package file version (kb835221.exe) : 6.1.1.0

Hdaudio.sys version : 5.10.00.5010

//=====

Driver Package R1.01/R1.02

Readme.txt

RtkHDAud.sys Version: 5.10.0.5022

1. Codec Supporting:
2. OS Supporting: Microsoft Windows XP, Windows 2000
3. Pack with Microsoft High Definition Audio OOB Binaries V1.0
4. Add/Fix

SoundMan.exe Version: 1.0.0.4

ALSndMgr.cpl Version: 1.0.0.2

Rtlcpl.exe Version: 1.0.1.23

Alcwzrd.exe Version: 1.1.0.5

Operate on :

Microsoft High Definition Audio Driver Package - KB835221

Package file version (kb835221.exe) : 6.1.1.0

Hdaudio.sys version : 5.10.00.5010

//=====

Driver Package R1.0

RtkHDAud.sys Version: 5.10.0.5017

1. Codec Supporting: Add ALC880/ALC880M Rev. F Rev. G, ALC860
2. OS Supporting: Microsoft Windows XP, Windows 2000
3. Pack with Microsoft High Definition Audio OOB Binaries V1.0
4. Add/Fix

SoundMan.exe Version: 1.0.0.4

ALSndMgr.cpl Version: 1.0.0.2

Rtlcpl.exe Version: 1.0.1.23

Alcwzrd.exe Version: 1.1.0.5

Operate on :

Microsoft High Definition Audio Driver Package - KB835221

Package file version (kb835221.exe) : 6.1.1.0

Hdaudio.sys version : 5.10.00.5010