



Quick Start

INSTALLATION

1. Power Cord
2. DVI Cable (Optional)
3. VGA Cable
4. Audio Cable Jack/Jack (Optional)
5. USB Cable (XD1150D/XD1250D)
6. RS232 Cable (Optional)
7. 3 RCA Component Cable (Optional)
8. VGA to Component/HDTV Adapter (XD1150D/XD1250D)
9. S-Video Cable (XD1150D/XD1250D)
10. Composite Video Cable
11. VGA Cable (Optional)



INTERFACE CONNECTOR



Connecting to a Computer

1. Ensure the projector and your computer are turned off.
2. Connect one end of the VGA cable to the "VGA In" connector on the projector; connect the other end to the VGA connector on the computer and tighten the screws.
3. Connect one end of the power cord into the AC power socket on the projector; connect the other end to an electrical outlet.

Powering On the Projector

1. Remove the lens cap.
2. Turn on the projector first and then the computer.
3. Adjust the position, focus and zoom.
4. Run your presentation.

Powering Off the Projector

1. Press the power button twice.
2. Do not remove AC power cord from outlet until the projector fan shuts down.