



# Quick Start

## INSTALLATION

1. Power Cord
2. DVI Cable (Optional)
3. VGA Cable
4. S-Video Cable
5. USB Cable
6. VGA to Component/HDTV Adapter
7. Audio Cable Jack/Jack
8. Composite Video Cable
9. RS232 Cable
10. 5V DC Output Jack for attached Dongle Device (for XD1170/ XD1270 only)



## INTERFACE CONNECTOR



### Connecting to a Computer

1. Ensure the projector and your computer are turned off.
2. Connect one end of the VGA cable to the "VGA In" connector on the projector; connect the other end to the VGA connector on the computer and tighten the screws.
3. Connect one end of the power cord into the AC power socket on the projector; connect the other end to an electrical outlet.

### Powering On the Projector

1. Remove the lens cap.
2. Turn on the projector first and then the computer.
3. Adjust the position, focus and zoom.
4. Run your presentation.

### Powering Off the Projector

1. Press the power button twice.
2. Do not remove AC power cord from outlet until the projector fan shut down.