



PRODUCTS: NUC8i3CYSN, NUC8i3CYSM (Standard BIOS)

BIOS Version 0042 - CYCNLi35.86A.0042.2019.0703.1626

About This Release:

- Date: July 03, 2019
- ROM Image Checksum: 0x05BD
- ME Firmware: 12.0.3.1094
- EC Firmware: C.13.0
- PMC Firmware: 300.1.20.1015
- Framework Reference Code: Based on 7.1.35.41
- LAN Option ROM: 0.0.19
- Visual Bios: 2.2.23
- Supported Flash Devices:
 - WinBond W25Q128FWSIQ 16MB(1.8V)
- Microcode Updates included in .ROM & .BIO Files:
 - M8060663_0000002A.mcb

New Fixes/Features:

- Updated BIOS code for security fixes.

BIOS Version 0041 - CYCNLi35.86A.0041.2019.0611.1500

About This Release:

- Date: June 11, 2019
- ROM Image Checksum: 0xDF32
- ME Firmware: 12.0.3.1094
- EC Firmware: C.13.0
- PMC Firmware: 300.1.20.1015
- Framework Reference Code: Based on 7.1.35.41
- Supported Flash Devices:
 - WinBond W25Q128FWSIQ 16MB(1.8V)
- Microcode Updates included in .ROM File:
 - M8060663_0000002A.mcb
- Additional Microcode Updates included only in .BIO File:
 - M8060663_0000002A.mcb

New Fixes/Features:

- Updated BIOS code for security fix.
- Removed "SW Control" option from "Button LED" item in BIOS Setup.

BIOS Version 0040 - CYCNLi35.86A.0040.2019.0311.1529

About This Release:

- Date: March 11, 2019
- ME Firmware: 12.0.3.1094
- EC Firmware: C.13.0
- PMC Firmware: 300.1.20.1015

- Framework Reference Code: Based on 7.1.35.41

New Fixes/Features:

- Updated BIOS code for security fixes.

BIOS Version 0039 - CYCNLi35.86A.0039.2018.1207.1801

About This Release:

- Date: December 7, 2018
- ME Firmware: 12.0.3.1094
- EC Firmware: C.13.0
- PMC Firmware: 300.1.20.1015
- Framework Reference Code: Based on 7.1.35.41
- LAN Option ROM: 0.0.19
- Visual Bios: 2.2.23

New Fixes/Features:

- Fixed blue screen issue.

BIOS Version 0038 - CYCNLi35.86A.0038.2018.1024.1115

About This Release:

- Date: October 24, 2018
- ME Firmware: 12.0.3.1094
- EC Firmware: C.13.0
- PMC Firmware: 300.1.20.1015
- Framework Reference Code: Based on 7.1.35.41

New Fixes/Features:

- Updated EC Firmware to version 13.00.
- Updated BIOS Help text of supervisor and user password settings.
- Fixed issue where Turbo boost and Primary Power settings can't load default.
- Fixed issue where S3 Indicator items loses functionality when HDD LED is set to Power State Indicator.

BIOS Version 0036 - CYCNLi35.86A.0036.2018.0801.1506

About This Release:

- Date: August 2, 2018
- ME Firmware: 12.0.3.1094
- EC Firmware: C.12.0
- PMC Firmware: 300.1.20.1015

New Fixes/Features:

- Initial production BIOS release
- Improved Failsafe Watchdog message and correct the return values.

LEGAL INFORMATION

Information in this document is provided in connection with Intel Products and for the purpose of supporting Intel developed server/desktop boards and systems.

No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel Corporation may have patents or pending patent applications, trademarks, copyrights, or other intellectual property rights that relate to the presented subject matter. The furnishing of documents and other materials and information does not provide any license, express or implied, by estoppel or otherwise, to any such patents, trademarks, copyrights, or other intellectual property rights. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Intel is a trademark of Intel Corporation in the US and other countries.
Copyright (c) 2018 Intel Corporation.