



BIOS Update Release Notes

PRODUCTS: NUC5i3MYBE, NUC5i3MYHE (Standard BIOS)

BIOS Version 0054 - MYBDWi30.86A.0054.2019.0409.1458

About This Release:

- Date: April 9, 2019
- ROM Image Checksum: 0xA969
- ME Firmware: 10.0.47.1006
- Memory Reference Code: Based on 2.9.0
- Integrated Graphics:
 - Option ROM: Build 1039
 - UEFI Driver: 5.5.1033
- SATA RAID Option ROM: 14.5.0.2241
- SATA non-RAID Option ROM: 14.5.0.2241
- AHCI Code: Based on 09
- LAN Option ROM: 1.5.55
- Visual BIOS: 2.2.23

New Fixes/Features:

- Updated BIOS code for security fixes.

BIOS Version 0053 - MYBDWi30.86A.0053.2019.0220.1732

About This Release:

- Date: February 20, 2019
- ME Firmware: 10.0.47.1006
- Memory Reference Code: Based on 2.9.0
- Integrated Graphics
 - Option ROM: Build 1039
 - UEFI Driver: 5.5.1033
- SATA RAID Option ROM: 14.5.0.2241
- SATA non-RAID Option ROM: 14.5.0.2241
- AHCI Code: Based on 09
- LAN Option ROM: 1.5.55
- Visual BIOS: 2.2.23

New Fixes/Features:

- Updated BIOS code for security fixes.
- Updated setting for "Boot Network Devices Last" item to allow user to modify IPv4/IPv6 priority when "Boot Network Devices Last" is enabled.

BIOS Version 0052 - MYBDWi30.86A.0052.2018.1106.1151

About This Release:

- Date: November 6, 2018
- ME Firmware: 10.0.47.1006

*Other names and brands may be claimed as the property of others.

- Memory Reference Code: Based on 2.9.0
- Integrated Graphics
 - Option ROM: Build 1039
 - UEFI Driver: 5.5.1033
- SATA RAID Option ROM: 14.5.0.2241
- SATA non-RAID Option ROM: 14.5.0.2241
- AHCI Code: Based on 09
- LAN Option ROM: 1.5.55
- Visual BIOS: 2.2.23

New Fixes/Features:

- Fixed issue where system hangs during POST when Western Digital 1TB MyPassport external USB drive is connected.
- Added Setup item **Power Button Menu Beeps**, with default set to enabled.

BIOS Version 0051 - MYBDWi30.86A.0051.2018.0709.2044

About This Release:

- Date: Date: July 9, 2018
- ME Firmware: 10.0.47.1006
- Memory Reference Code: Based on 2.9.0
- Integrated Graphics:
 - Option ROM: Build 1039
 - UEFI Driver: 5.5.1033
- SATA RAID Option ROM: 14.5.0.2241
- SATA non-RAID Option ROM: 14.5.0.2241
- AHCI Code: Based on 09
- LAN Option ROM: 1.5.55
- Visual BIOS: 2.2.23

New Fixes/Features:

- Updated CPU Microcode (Security Advisory-00115)
- Removed Intel® Ready Mode Technology code/items in BIOS for Intel security fix.

BIOS Version 0050 - MYBDWi30.86A.0050.2018.0601.1418

About This Release:

- Date: June 01, 2018
- ME Firmware: 10.0.47.1006
- Memory Reference Code: Based on 2.9.0
- Integrated Graphics
 - Option ROM: Build 1039
 - UEFI Driver: 5.5.1033
- SATA RAID Option ROM: 14.5.0.2241
- SATA non-RAID Option ROM: 14.5.0.2241
- AHCI Code: Based on 09
- LAN Option ROM: 1.5.55
- Visual BIOS: 2.2.23

New Fixes/Features:

- Security enhancements.
- Updated CPU Microcode (Security Advisory-00115)

*Other names and brands may be claimed as the property of others.

- Set the GPIO 10 to high when the GPIO table initializes. After the initialization, there's a 200ms delay, then the GPIO 10 goes to low.

BIOS Version 0048 - MYBDWi30.86A.0048.2018.0303.1629

About This Release:

- Date: March 3, 2018
- ME Firmware: 10.0.47.1006
- Memory Reference Code: Based on 2.9.0
- Integrated Graphics
 - Option ROM: Build 1039
 - UEFI Driver: 5.5.1033
- SATA RAID Option ROM: 14.5.0.2241
- SATA non-RAID Option ROM: 14.5.0.2241
- AHCI Code: Based on 09
- LAN Option ROM: 1.5.55
- Visual BIOS: 2.2.23

New Fixes/Features:

- Updated CPU Microcode (Security Advisory-00088)

BIOS Version 0045 - MYBDWi30.86A.0045.2017.1219.2100

About This Release:

- Date: Date: December 19, 2017
- ME Firmware: 10.0.47.1006
- Memory Reference Code: Based on 2.9.0
- Integrated Graphics
 - Option ROM: Build 1039
 - UEFI Driver: 5.5.1033
- SATA RAID Option ROM: 14.5.0.2241
- SATA non-RAID Option ROM: 14.5.0.2241
- AHCI Code: Based on 09
- LAN Option ROM: 1.5.55
- Visual BIOS: 2.2.23

New Fixes/Features:

-

BIOS Version 0044 - MYBDWi30.86A.0044.2017.1130.1251

About This Release:

- Date: Date: November 30, 2017
- ME Firmware: 10.0.47.1006
- Memory Reference Code: Based on 2.9.0
- Integrated Graphics:
 - Option ROM: Build 1039
 - UEFI Driver: 5.5.1033
- SATA RAID Option ROM: 14.5.0.2241
- SATA non-RAID Option ROM: 14.5.0.2241
- AHCI Code: Based on 09
- LAN Option ROM: 1.5.55

- Visual BIOS: 2.2.23

New Fixes/Features:

- Added a new BIOS option within the "Power" tab, which allows USB power during reboot. The default state is disabled.
- Due to a security enhancement, it will not be possible to go to any BIOS earlier than BIOS 0044.

BIOS Version 0043 - MYBDWi30.86A.0043.2017.1016.1739

About This Release:

- Date: Date: October 16, 2017
- ME Firmware: 10.0.47.1006
- Memory Reference Code: Based on 2.9.0
- Integrated Graphics
 - Option ROM: Build 1039
 - UEFI Driver: 5.5.1033
- SATA RAID Option ROM: 14.5.0.2241
- SATA non-RAID Option ROM: 14.5.0.2241
- AHCI Code: Based on 09
- LAN Option ROM: 1.5.55
- Visual BIOS: 2.2.23

New Fixes/Features:

- Security enhancements.
- Added the setup option "Allow UEFI Third Party Driver loaded" and set the default state to disabled.
- Due to security enhancements, it will not be possible to go to any BIOS earlier than BIOS 0043.

BIOS Version 0042 - MYBDWi30.86A.0042.2017.0810.1354

About This Release:

- Date: Date: Aug 10, 2017
- ME Firmware: 10.0.47.1006
- Memory Reference Code: Based on 2.9.0
- Integrated Graphics
 - Option ROM: Build 1039
 - UEFI Driver: 5.5.1033
- SATA RAID Option ROM: 14.5.0.2241
- SATA non-RAID Option ROM: 14.5.0.2241
- AHCI Code: Based on 09
- LAN Option ROM: 1.5.55
- Visual BIOS: 2.2.23

New Fixes/Features:

- Added S.M.A.R.T item and functionality.

BIOS Version 0041 - MYBDWi30.86A.0041.2017.0116.2158

About This Release:

- Date: Date: January 16, 2017
- ME Firmware: 10.0.47.1006
- EC Firmware: NA
- Memory Reference Code: Based on 2.9.0

*Other names and brands may be claimed as the property of others.

- MEBx Code: NA
- Integrated Graphics
 - Option ROM: Build 1039
 - UEFI Driver: 5.5.1033
- SATA RAID Option ROM: 14.5.0.2241
- SATA non-RAID Option ROM: 14.5.0.2241
- AHCI Code: Based on 09
- LAN Option ROM: 1.5.55
- Visual BIOS: 2.2.23

New Fixes/Features:

- Security Enhancements

BIOS Version 0040 - MYBDWi30.86A.0040.2016.1124.1654

About This Release:

- Date: November 24, 2016
- ME Firmware: 10.0.47.1006
- Memory Reference Code: Based on 2.9.0
- PXE ROM version: 1.5.55
- Visual BIOS: 2.2.23
- RST RAID: v14.5.0.2241
- Integrated Graphics
 - Option ROM: Build 1039
 - UEFI Driver: 5.5.1033

New Fixes/Features:

- Security Enhancements.
- Open SSL Q4 security enhancement.

BIOS Version 0038 - MYBDWi30.86A.0038.2016.0913.1446

About This Release:

- Date: September 13, 2016
- ME Firmware: 10.0.47.1006
- Memory Reference Code: Based on 2.9.0
- PXE ROM version: 1.5.55
- Visual BIOS: 2.2.23
- RST RAID: v14.5.0.2241
- Integrated Graphics
 - Option ROM: Build 1039
 - UEFI Driver: 5.5.1033

New Fixes/Features:

- Security Enhancements.
- Updated BootScriptHide module to BootScriptHide_02.
- Changed the SATA DevSleep setting from Enabled to Disabled.
- Updated Visual BIOS to version 2.2.23.
 - Fixed missing voltages in Cooling Page.
 - Fixed inactive Home Page 3 and Performance links on NUC theme.
 - Added support for loading data from file for platform (e.g. EDID, Secure Boot, etc).
 - Fixed issue where unsupported keys could be entered in password.

*Other names and brands may be claimed as the property of others.

- o Fixed hang when using keyboard to configure a drop down control.
- o Added support for legacy boot options to Visual Boot Manager.
- o Added support for booting to multiple partitions on the same device from Visual Boot Manager.
- o Added support to Visual Boot Manager for booting to operating systems that do not support EFI default boot path.

MYBDWi30.86A.0036.2016.0420.1451 Development BIOS
--

About This Release:

- Date: April 20, 2016
- ME Firmware: 10.0.47.1006
- Memory Reference Code: Based on 2.9.0
- PXE ROM version: 1.5.55
- Visual BIOS: 2.2.20
- RST RAID: v14.5.0.2241
- Integrated Graphics
 - Option ROM: Build 1039
 - UEFI Driver: 5.5.1033

New Fixes/Features:

- Improved BIOS update function by disabling keyboard and power button during the flash/recovery process.
- Changed the Power button menu and F4 recovery:
 - o Removed G3 power button recovery
 - o Increased the key press detection to 3.51 sec
 - o Added BIOS ID information prompt and now allow the cancellation of the recovery process if the ESC key is pressed within 20 seconds of the recovery process.
 - o Added recovery progress information
- Improved Power Button Menu:
 - o When the [ESC] key is pressed in the power button recovery menu, the BIOS turns on the SPI lock by GPIO, which globally resets the system for normal POST.
 - o Checks for a Password "F4" in power button menu if either user or supervisor password is set.
 - o Fixed an issue where the power button override invoked the power button menu in the next boot.
 - o Removed the jumper recovery message, "Please turn off power and reinstall the BIOS Security Jumper in Normal (1-2) or Lockdown (2-3) position".
 - o Added message, "If BIOS Recovery was invoked by BIOS security jumper," before "restore the BIOS Security Jumper in Normal (1-2) or Lockdown (2-3) position".
- Added NVRAM preserved variables "DmiData", "UUID" and "OA3Data".
- Hid "NFC" setup item.
- Fixed an issue where Pin12: DirectApp Launch didn't work.
- Changed the default pin8 as SMBAlert and grayed out.
- Changed the default pins 13-16 to I2C.
- Changed the default high speed custom solutions header item: Added pin7 option to GPIO35 and grayed out.
- Changed the default high speed customer solutions header item: Added pin8 option to GPIO38 and grayed out.
- Removed the NFC connection from the GPIO options.

*Other names and brands may be claimed as the property of others.

- Fixed an issue where Linux couldn't see the GPIO controller.
- Update Visual BIOS to 2.2.20 from 2.2.17.
- Hotfix to remove download driver and automatic BIOS update feature.

BIOS Version - MYBDWi30.86A.0035.2016.0307.1939

About This Release:

- Date: March 07, 2016
- ME Firmware: 10.0.47.1006
- Memory Reference Code: Based on 2.9.0
- PXE ROM version: 1.5.55
- Visual BIOS: 2.2.17
- RST RAID: v14.5.0.2241
- Integrated Graphics
 - Option ROM: Build 1039
 - UEFI Driver: 5.5.1033

New Fixes/Features:

- Fixed an issue where Toshiba x2 NVME THNSNN256GSX7 SSD would not boot.
- Added a Secure Boot and PXE security enhancement.

BIOS Version 0034 - MYBDWi30.86A.0034.2015.1204.1150

About This Release:

- Date: December 4, 2015
- ME Firmware: 10.0.47.1006
- PXE ROM version: 1.5.55
- Visual BIOS: 2.2.17
- RST RAID: v14.5.0.2241
- Integrated Graphics
 - Option ROM: Build 1039
 - UEFI Driver: 5.5.1033

New Fixes/Features:

- Fixed issue where BIOS options can be changed by users with View Only access.
- Updated Intel® ME firmware to version 10.0.47.1006.

BIOS Version 032 - MYBDWi30.86A.0032.2015.0907.1811

About This Release:

- Date: September 7, 2015
- ME Firmware: 10.0.45.1024
- PXE ROM version: 1.5.55
- Visual BIOS: 2.2.17
- RST RAID: v14.5.0.2241
- Integrated Graphics
 - Option ROM: Build 1039
 - UEFI Driver: 5.5.1033

New Fixes/Features:

- Added solution for TPM firmware update.

*Other names and brands may be claimed as the property of others.

- Fixed issue where Bluetooth test items are not listed in HLK as default.
- Fixed issue where system does not wake up from S5 using USB devices when BIOS option for **Wake on LAN from S4/S5** is set to **Stay Off**.
- Fixed issue if Intel® Dynamic Power Technology is set to Off, the system can still enter into C7. Updated VBIOS to version 1039 and GOP to version 1033.
- Updated Intel® ME firmware to version 10.0.45.1024.
- Updated processor support.
- Updated legacy and UEFI RAID OPRM to version 14.5.0.2241.
- Fixed issue where USB mouse and keyboard do not work as expected in BIOS setup.
- Fixed issue where the Ctrl + I hot key to access RAID configuration does not work.
- Updated Visual BIOS to version. Fixes include:
 - Refactored graphics resolution algorithm to find closest supported resolution to 1024x768. This should correct scaling issues with 4K monitors.
 - Removed unused assets from Performance and Mainstream themes to reduce the overall size of Visual BIOS. Size savings should be around 300KB.
- Added "Fanless" as an option for Fan Control Mode.
- Added Windows Recovery feature via F5 hotkey.

BIOS Version 0030 - MYBDWi30.86A.0030.2015.0609.1651

About This Release:

- Date: June 9, 2015
- ME Firmware: 10.0.38.1000
- PXE ROM version: 1.5.55
- Visual BIOS: 2.2.16
- RST RAID: 13.5.0.2164
- Integrated Graphics
 - Option ROM: Build 1038
 - UEFI Driver: 5.5.1032

New Fixes/Features:

- Added customizable options in Intel® Integrator Toolkit on the Primary Power Settings menu.
- Fixed issue where SMBIOS system manufacturer and system model are incorrect in MSINFO32 and other applications.
- Fixed issue where flat panel is not displayed during security recovery/power button menu.
- Added NVMe information to the SATA page.
- Updated BIOS to hide Single Max Turbo Ratio if Intel® Turbo Boost Technology is disabled.
- Fixed issue where a user with limited access can still modify certain BIOS settings.
- Fixed issue where BIOS password prompts are not suppressed in Config Mode.
- Fixed SMBIOS Type 9 issue - the Current Usage always shows In Use when an M.2 device is not installed.
- Fixed issue where SMBIOS type 8 information is not correct.
- Removed SMBIOS type 25, 26, 27, 28, 29, 34, 35, 36, 39 data that affects 3rd party tools.

*Other names and brands may be claimed as the property of others.

- Updated CRB to v28 for Intel security.

BIOS Version 0028 - MYBDWi30.86A.0028.2015.0304.1957

About This Release:

- Date: March 4, 2015
- ME Firmware: 10.0.38.1000
- PXE ROM version: 1.5.55
- Visual BIOS: 2.2.16
- RST RAID: 13.5.0.2164
- Integrated Graphics
 - Option ROM: Build 1038
 - UEFI Driver: 5.5.1032

New Fixes/Features:

- Added xHCI Mode setting to USB Configuration page in BIOS.
- Updated processor support.
- Updated GOP to version 1032 and vBIOS to version 1038.
- Fixed issue with Power Sense and GPIO Lock Down default values when updating BIOS.
- Updated Intel® Visual BIOS to version 2.2.16. Fixes include:
 - o Fixed issue in Download Drivers feature where certain drivers were not visible if multiple attachments exist in the same record.
 - o Fixed issue in Download Drivers feature where incorrect drivers would display if product was not found in database.
 - o Fixed issue in Performance page that prevented additional workspaces from showing up (i.e. Memory Timings, etc.)
- Updated Intel® ME firmware to version 10.0.38.1000.
- Removed item PCI latency Timer from BIOS Setup.
- Changed BIOS setting name Graphics Max Multiplier to Graphics Turbo Ratio.
- Fixed issue where USB S4/S5 power can't be hidden and disabled after Deep S4/S5 is set to Enabled.
- Fixed issue where the iSCSI driver does not accept "CHAP Name" to <iscsi> and "CHAP Secret" to 12 "1" or 12 "a".
- Modified NFC behavior: When NFC is enabled in BIOS, GPIO Lockdown is disabled and greyed out.
- Fixed issue with Wake on USB from S5.
- Fixed issue with Keyboard Ready Beep and Startup Sound.
- Fixed issue where NFC device shows an error in Device Manager.
- Fixed issue with [Can't use VCUST/ITK operation Near Field Communication item]
- Added additional pin functions for GPIO Lockdown.
- Fixed issue where system locks up if IGD Aperture Size is set to 2048MB or 4096MB.

BIOS Version 0020 - MYBDWi30.86A.0020.2014.1219.1243

About This Release:

- Date: December 19, 2014
- ME Firmware: 10.0.30.1072
- PXE ROM version: 1.5.55
- Visual BIOS: 2.2.14
- RST RAID: 13.5.0.2164

*Other names and brands may be claimed as the property of others.

- Integrated Graphics
Option ROM: Build 1035
UEFI Driver: 5.5.1031

New Fixes/Features:

- Updated Visual BIOS to version 2.2.14. Fixes include:
 - Fixed touch monitors not working correctly when display adapter supports greater than 1024x768 resolution.
 - Fixed AMT USB-R issue where absolute mouse position would not scale correctly in Visual BIOS.
- Added CPU Input Voltage and Power Sense setup items in BIOS.
- Fixed issue with SATA port hot plug capability.

BIOS Version 0019 - MYBDWi30.86A.0019.2014.1217.1533

About This Release:

- Date: December 17 , 2014
- ME Firmware: 10.0.30.1072
- PXE ROM version: 1.5.55
- Visual BIOS: 2.2.13
- RST RAID: 13.5.0.2164
- Integrated Graphics
Option ROM: Build 1035
UEFI Driver: 5.5.1031

New Fixes/Features:

- Added "Aperture Size" and "LAN" setup items in BIOS.
- Fixed issue where system shuts down if LAN is disabled in BIOS.
- Fixed issue where there is no display from DisplayPort 2 if system is booted to DOS via USB flash disk.
- Set default "EDID Data Source" to Flat Panel Display.
- Fixed issue where USB devices are not detected in the F10 Boot menu after enabling Fast Boot.

BIOS Version 0017 - MYBDWi30.86A.0017.2014.1127.1854

About This Release:

- Date: November 27, 2014
- ME Firmware: 10.0.30.1072
- PXE ROM version: 1.5.55
- Visual BIOS: 2.2.13
- RST RAID: 13.5.0.2164
- Integrated Graphics
Option ROM: Build 1035
UEFI Driver: 5.5.1031

New Fixes/Features:

- Initial production BIOS release

LEGAL INFORMATION

Information in this document is provided in connection with Intel Products and for the purpose of supporting Intel developed server/desktop boards and systems.

*Other names and brands may be claimed as the property of others.

No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel Corporation may have patents or pending patent applications, trademarks, copyrights, or other intellectual property rights that relate to the presented subject matter. The furnishing of documents and other materials and information does not provide any license, express or implied, by estoppel or otherwise, to any such patents, trademarks, copyrights, or other intellectual property rights. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Intel is a trademark of Intel Corporation in the US and other countries.
Copyright (c) 2014 Intel Corporation.

*Other names and brands may be claimed as the property of others.