

Readme.txt  
Realtek Semiconductor Corp. High Definition Audio System Software Ver: R2.54  
Installation and Setup

Driver Installation/Removal Procedure For Realtek High Definition Audio Codec:

=====

<<< For Windows 2000/XP/Vista/Windows7 x86/x64 Driver >>>

-----  
Setup Driver at first time:  
-----

Windows 2000 , XP :

Step 1. Before installing the Realtek High Definition Audio Driver, Press the [Cancel] button if Windows detect the Multimedia Audio device.

Step 2. Run the setup.exe program to start the installation.

Step 3. Click on [Next] to continue the procedure. If the Windows popup "Digital Signature Not Found" message, press [Yes] to continue the installation.

Step 4. Finally, select to restart the system and press [Finish] to complete the installation.

Windows Vista, Windows7 :

Step 1. Run the setup.exe program to start the installation.

Step 2. Click on [Next] to continue the procedure. If the Windows popup "Windows can't verify the publisher of this driver software" message, press "Install this driver software anyway" to continue the installation.

Step 3. Finally, select to restart the system and press [Finish] to complete the installation.

-----  
Update Driver:  
-----

Windows 2000 , XP :

Step 1. Follow Step 2,3,4 described in [Setup at first time] above to complete the procedure.

Windows Vista, Windows7 :

Step 1. Run setup.exe, it will remove the original driver in your system

Step 2. Click "Next" to remove the original audio driver in your system

Step 3. Once after the original driver removed , reboot the computer.

Step 4. Please go back to the new driver package after computer restarted.

Step 5. Run setup.exe, it will install the new audio driver then.

-----  
Remove Driver:  
-----

Windows 2000 , XP :

Step 1. Go to Start\Settings\Control Panel.

Step 2. Select [Add or Remove Programs] icon.

Step 3. Select "Realtek High Definition Audio Driver" and press [Remove] button.

Step 4. Click on [Yes] to finish the uninstallation.

Step 5. At the end of the procedure, select to restart the system and press [Finish] to complete the uninstallation.

Readme.txt

Windows Vista, Windows7 :

Step 1. Go to Start\Settings\Control Panel.

Step 2. Select [Programs] icon.

Step 3. Select [Programs and Features] icon.

Step 4. Select "Realtek High Definition Audio Driver" and press [uninstall] button.

Step 5. Click on [Yes] to finish the uninstallation.

Step 6. At the end of the procedure, select to restart the system and press [Finish] to complete the uninstallation.

<< Other Informations >>

-----  
Silent Installation:  
-----

Run "Setup.exe /s /f2<path\LogFile> /z[-rp<path\LogFile>]"  
i.e. setup.exe /s /f2c:\mylog.log /z[-rpC:\RHDS\Setup.log]

-----  
Silent Uninstallation:  
-----

Run "Setup.exe /removeonly /s /f1<path\USetup.iss> /f2<path\LogFile> /z[-rp<path\LogFile>]"  
i.e. setup.exe /removeonly /s /f1C:\AudioDriver\USetup.iss /f2c:\mylog.log /z[-rpC:\RHDS\Setup.log]

Note: 1. Please update Directx version to DirectX8.1 or above.

-----  
Version Informations:  
-----

If driver package include below drivers :

-----  
Windows 2000/XP :  
RTKHDA64.sys : 5.10.0.6235  
RtkHDAud.sys : 5.10.0.6235  
AlcWzrd.exe : 1.1.0.37  
MicCal.exe : 1.1.2.4  
RTHDCPL.exe : 2.3.7.4  
RtkAudioService64.exe : 1.0.0.19  
RtkAudioService.exe : 1.0.0.19  
RTLCPPL.exe : 1.0.1.66  
RtlUpd64.exe : 2.8.0.3  
RtlUpd.exe : 2.8.0.3  
SkyTel.exe : 2.0.2.0  
SoundMan.exe : 1.0.0.32  
vncutil64.exe : 1.0.0.38  
vncutil.exe : 1.0.0.38  
AlcMtr.exe : 1.6.0.4  
AMBFilt.sys : 5.10.0.4240  
AMBFt64.sys : 5.10.0.4240  
Mbnfilt.sys : 5.10.0.4112  
Mbnft64.sys : 5.10.0.4115  
OA017Afx.sys : 1.0.7.3  
ALSndMgr.cpl : 1.0.0.11  
RTSndMgr.cpl : 1.0.1.6  
RCoInst64XP.dll : 1.1.1.0  
RTCODLL.dll : 1.0.0.110  
RtkCoInstXP.dll : 1.1.1.0  
RtlCPAPI.dll : 1.0.2.3

Vista/Win7 driver : -----  
Vista/Win7 driver for x86

RTKVHDA.sys	: 6.0.1.6235
AERTSrv.exe	: 1.0.32.10
FMAPP.exe	: 1.32.0.1
RtHDVbg.exe	: 1.0.0.51
RtHDVCpl.exe	: 1.0.0.603
RtkAudioService.exe	: 1.0.0.27
RtkNGUI.exe	: 1.0.0.76
RtlUpd.exe	: 2.8.0.3
SkyTel.exe	: 2.0.2.2
vncutil.exe	: 1.0.0.40
mbfilt32.sys	: 6.10.0.8
RTSndMgr.cpl	: 1.0.0.19
AERTACap.dll	: 2.0.32.13
AERTARen.dll	: 1.0.32.9
BlackSkinImages.dll	: 1.0.0.76
DarkSkinImages.dll	: 1.0.0.76
DTSBassEnhancementDLL.dll	: 1.0.0.1
DTSBoostDLL.dll	: 1.0.0.1
DTSGainCompensatorDLL.dll	: 1.0.0.1
DTSAFXAPO.dll	: 1.0.0.3
DTSAFXAPONS.dll	: 1.0.0.3
DTSAFXAPO.dll	: 1.0.0.3
DTSLimitDLL.dll	: 1.0.0.1
DTSNeoPCDLL.dll	: 1.0.0.1
DTSS2HeadphoneDLL.dll	: 1.0.0.1
DTSS2SpeakerDLL.dll	: 1.0.0.1
DTSSymmetryDLL.dll	: 1.0.0.1
DTSVoiceClarityDLL.dll	: 1.0.0.1
FMAPO.dll	: 43.5.6.68
GrayJadeSkinImages.dll	: 1.0.0.76
LightSkinImages.dll	: 1.0.0.76
MaxxAudioAPO.dll	: 1.2.2.0
MaxxAudioAPO20.dll	: 2.2.9.0
MaxxAudioAPO30.dll	: 3.2.1.1
MaxxAudioEQ.dll	: 5.9.7.0
MaxxAudioRealtek.dll	: 1.1.0.0
MaxxAudioRealtek2.dll	: 1.0.3.0
MaxxVolumeSDAPO.dll	: 3.1.0.0
MBAP032.dll	: 1.0.41.0
MBPPCn32.dll	: 1.0.0.110
MBppld32.dll	: 1.0.41.0
MBTHX32.dll	: 1.0.15.122
MBWrp32.dll	: 1.0.0.180
R4EEA32A.dll	: 7.1.7000.5
R4EED32A.dll	: 7.1.7000.5
R4EEG32A.dll	: 7.1.7000.5
R4EEL32A.dll	: 7.1.7000.5
R4EEP32A.dll	: 7.1.7000.5
RP3DAA32.dll	: 6.0.6001.18
RP3DHT32.dll	: 6.0.6001.18
RTCOMDLL.dll	: 2.0.0.140
RTEED32A.dll	: 6.1.6001.33
RTEEG32A.dll	: 6.1.6001.33
RTEEL32A.dll	: 6.1.6001.33
RTEEP32A.dll	: 6.1.6001.33
RtkAPO.dll	: 11.0.6000.178
RtkApoApi.dll	: 1.0.0.31
RtkCfg.dll	: 1.0.0.2
RtkCoInst.dll	: 1.1.1.1
RtkGuiCompLib.dll	: 1.0.0.2
RtkPgExt.dll	: 6.0.6000.165
RtlCPAPI.dll	: 1.0.2.4
SFAPO.dll	: 3.0.0.11
SFCOM.dll	: 3.0.0.11
SFFXComm.dll	: 2.0.0.13
SFFXDAPO.dll	: 2.0.0.13
SFFXHAPO.dll	: 2.0.0.13
SFFXProc.dll	: 2.0.0.13
SFFXSAP0.dll	: 2.0.0.13

Readme.txt

	Readme.txt	
SFNHK.dll		: 3.0.0.11
slcshp32.dll		: 1.0.3.0
slgeq32.dll		: 1.0.1.0
slh36032.dll		: 1.0.2.0
slini32.dll		: 1.1.3.0
slmaxv32.dll		: 1.1.2.0
sltshd32.dll		: 1.2.0.0
sluapo32.dll		: 1.8.34.0
slvip32.dll		: 1.0.1.0
SRSH360.dll		: 1.1.0.0
SRSTSHD.dll		: 1.1.4.0
SRSTSXT.dll		: 3.2.0.0
SRSWOW.dll		: 1.1.3.0
WavesGUILib.dll		: 1.1.0.0
WavesLib.dll		: 5.9.7.0
RCORES.dat		: 1.0.4.7
Vista/Win7 driver for x64		
RTKVHD64.sys		: 6.0.1.6235
AERTSr64.exe		: 1.0.64.10
FMAPP.exe		: 1.64.0.1
RAVBg64.exe		: 1.0.0.51
RAVCpl64.exe		: 1.0.0.603
RtkAudioService64.exe		: 1.0.0.27
RtkNGUI64.exe		: 1.0.0.76
RtlUpd64.exe		: 2.8.0.3
SkyTel.exe		: 2.0.2.2
vncutil64.exe		: 1.0.0.40
GWfilt64.sys		: 6.10.0.3
mbfilt64.sys		: 6.10.0.8
RTSnMg64.cpl		: 1.0.0.19
AERTAC64.dll		: 2.0.64.13
AERTAR64.dll		: 1.0.64.9
BlackSkinImages64.dll		: 1.0.0.76
DarkSkinImages64.dll		: 1.0.0.76
DTSBassEnhancementDLL64.dll		: 1.0.0.1
DTSBoostDLL64.dll		: 1.0.0.1
DTSGainCompensatorDLL64.dll		: 1.0.0.1
DTSAFXAP064.dll		: 1.0.0.3
DTSAFXAPONS64.dll		: 1.0.0.3
DTSAFXAP064.dll		: 1.0.0.3
DTSLimitDLL64.dll		: 1.0.0.1
DTSNeoPCDLL64.dll		: 1.0.0.1
DTSS2HeadphoneDLL64.dll		: 1.0.0.1
DTSS2SpeakerDLL64.dll		: 1.0.0.1
DTSSymmetryDLL64.dll		: 1.0.0.1
DTSVoiceClarityDLL64.dll		: 1.0.0.1
FMAP064.dll		: 43.6.6.68
GrayJadeSkinImages64.dll		: 1.0.0.76
LightSkinImages64.dll		: 1.0.0.76
MaxxAudioAPO20.dll		: 2.2.9.0
MaxxAudioAPO30.dll		: 3.2.1.1
MaxxAudioEQ.dll		: 5.9.7.0
MaxxAudioRealtek.dll		: 1.1.0.0
MaxxAudioRealtek2.dll		: 1.0.3.0
MaxxVolumeSDAPO.dll		: 3.1.0.0
MBAP032.dll		: 1.0.41.0
MBAP064.dll		: 1.0.41.0
MBPPCn64.dll		: 1.0.0.110
MBppld64.dll		: 1.0.41.0
MBTHX32.dll		: 1.0.15.122
MBTHX64.dll		: 1.0.15.122
MBWrp64.dll		: 1.0.0.180
R4EEA64A.dll		: 7.1.7000.5
R4EED64A.dll		: 7.1.7000.5
R4EEG64A.dll		: 7.1.7000.5
R4EEL64A.dll		: 7.1.7000.5
R4EEP64A.dll		: 7.1.7000.5
RCoInst64.dll		: 1.1.1.1

	Readme.txt	
RP3DAA64.dll	:	6.0.6001.18
RP3DHT64.dll	:	6.0.6001.18
RtCOM64.dll	:	2.0.0.140
RTCOMDLL.dll	:	2.0.0.140
RTEED64A.dll	:	6.1.6001.33
RTEEG64A.dll	:	6.1.6001.33
RTEEL64A.dll	:	6.1.6001.33
RTEEP64A.dll	:	6.1.6001.33
RtkApi64.dll	:	1.0.0.31
RtkAP064.dll	:	11.0.6000.178
RtkCfg.dll	:	1.0.0.1
RtkCfg64.dll	:	1.0.0.2
RtkGuiCompLib.dll	:	1.0.0.2
RtlCPAPI.dll	:	1.0.2.4
RtlCPAPI64.dll	:	1.0.2.4
RtPgEx64.dll	:	6.0.6000.165
SFAP064.dll	:	3.0.0.11
SFCOM.dll	:	3.0.0.11
SFCOM64.dll	:	3.0.0.11
SFComm64.dll	:	2.0.0.13
SFDAP064.dll	:	2.0.0.13
SFHAP064.dll	:	2.0.0.13
SFNHK64.dll	:	3.0.0.11
SFProc64.dll	:	2.0.0.13
SFSAP064.dll	:	2.0.0.13
SFSS_APO.dll	:	1.0.0.10280
slcshp64.dll	:	1.0.3.0
slgeq64.dll	:	1.0.1.0
slh36064.dll	:	1.0.2.0
slInit64.dll	:	1.1.3.0
slmaxv64.dll	:	1.1.2.0
sltshd64.dll	:	1.2.0.0
sluapo64.dll	:	1.8.34.0
slvip64.dll	:	1.0.1.0
SRSHP64.dll	:	1.1.0.0
SRSTSH64.dll	:	1.1.4.0
SRSTSX64.dll	:	3.2.0.0
SRSWOW64.dll	:	1.1.3.0
WavesGUILib.dll	:	1.1.0.0
RCORES64.dat	:	1.0.4.7

HDMI Driver : -----

Vista/Wn7 x86:	
RtHDMV.sys	: 6.0.1.6121
RtkAudioSrvATI.exe	: 1.0.0.23
RtkUpd.exe	: 2.8.0.3
RH3DAA32.dll	: 6.0.6001.18
RH3DHT32.dll	: 6.0.6001.18
RHCoInst.dll	: 1.0.8.6
RHDMExt.dll	: 6.0.6000.127
RTEED32H.dll	: 6.1.6001.33
RTEEG32H.dll	: 6.1.6001.33
RTEEL32H.dll	: 6.1.6001.33
RTEEP32H.dll	: 6.1.6001.33
RtkHDM.dll	: 11.0.6000.151

Vista/Wn7 x64:	
RtHDMVX.sys	: 6.0.1.6121
RtkAudioSrvATI64.exe	: 1.0.0.23
RtkUpd64.exe	: 2.8.0.3
RH3DAA64.dll	: 6.0.6001.18
RH3DHT64.dll	: 6.0.6001.18
RHCoInst64.dll	: 1.0.8.6
RHDMEx64.dll	: 6.0.6000.127
RTEED64H.dll	: 6.1.6001.33
RTEEG64H.dll	: 6.1.6001.33
RTEEL64H.dll	: 6.1.6001.33
RTEEP64H.dll	: 6.1.6001.33
RtkHDM64.dll	: 11.0.6000.151

Readme.txt

XP/2K x86:  
RtkHDM.sys : 5.10.0.6121  
Rtaupd.exe : 2.8.0.3  
RHCoInstXP.dll : 1.0.8.6

XP/2K x64:  
RtkHDMX.sys : 5.10.0.6121  
Rtaupd64.exe : 2.8.0.3  
RHCoInst64XP.dll : 1.0.8.6

Driver Setup Program : 3.13

-----  
History:  
-----

Driver Package R2.54

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC887, ALC888, ALC889, ALC892, ALC899, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC670, ALC680 ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC275
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC887, ALC888, ALC889, ALC892, ALC899, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC670, ALC680 ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC275
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 - x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
  - 1.) Driver :
    1. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :  
RTKHDA64.sys : 5.10.0.6235  
RtkHDAud.sys : 5.10.0.6235  
AlcWzrd.exe : 1.1.0.37  
McCal.exe : 1.1.2.4  
RTHDCPL.exe : 2.3.7.4  
RtkAudioService64.exe : 1.0.0.19  
RtkAudioService.exe : 1.0.0.19  
RTLCPPL.exe : 1.0.1.66  
RtlUpd64.exe : 2.8.0.3  
RtlUpd.exe : 2.8.0.3  
SkyTel.exe : 2.0.2.0  
SoundMan.exe : 1.0.0.32  
vncutil64.exe : 1.0.0.38  
vncutil.exe : 1.0.0.38  
Alcmtr.exe : 1.6.0.4  
AMBfilt.sys : 5.10.0.4240  
AMBft64.sys : 5.10.0.4240  
Mbnfilt.sys : 5.10.0.4112  
Mbnft64.sys : 5.10.0.4115  
OA017Afx.sys : 1.0.7.3  
ALSndMgr.cpl : 1.0.0.11  
RTSndMgr.cpl : 1.0.1.6  
RCoInst64XP.dll : 1.1.1.0  
RTCOMDLL.dll : 1.0.0.110  
RtkCoInstXP.dll : 1.1.1.0  
RtlCPAPI.dll : 1.0.2.3

Vista/Win7 driver : -----

Vista/Win7 driver for x86  
RTKVHDA.sys : 6.0.1.6235  
AERTSrv.exe : 1.0.32.10  
FMAPP.exe : 1.32.0.1  
RtHDVBg.exe : 1.0.0.51  
RtHDVCpl.exe : 1.0.0.603  
RtkAudioService.exe : 1.0.0.27

RtkNGUI. exe	: 1. 0. 0. 76
RtlUpd. exe	: 2. 8. 0. 3
SkyTel. exe	: 2. 0. 2. 2
vncutil. exe	: 1. 0. 0. 40
mbfilt32. sys	: 6. 10. 0. 8
RTSndMgr. cpl	: 1. 0. 0. 19
AERTACap. dll	: 2. 0. 32. 13
AERTARen. dll	: 1. 0. 32. 9
BlackSkinImages. dll	: 1. 0. 0. 76
DarkSkinImages. dll	: 1. 0. 0. 76
DTSBassEnhancementDLL. dll	: 1. 0. 0. 1
DTSBassBoostDLL. dll	: 1. 0. 0. 1
DTSGainCompensatorDLL. dll	: 1. 0. 0. 1
DTSGFXAPO. dll	: 1. 0. 0. 3
DTSGFXAPONS. dll	: 1. 0. 0. 3
DTSLFXAPO. dll	: 1. 0. 0. 3
DTSLimiterDLL. dll	: 1. 0. 0. 1
DTSSNeoPCDLL. dll	: 1. 0. 0. 1
DTSS2HeadphoneDLL. dll	: 1. 0. 0. 1
DTSS2SpeakerDLL. dll	: 1. 0. 0. 1
DTSSymmetryDLL. dll	: 1. 0. 0. 1
DTSSVoiceClarityDLL. dll	: 1. 0. 0. 1
FMAP0. dll	: 43. 5. 6. 68
GrayJadeSkinImages. dll	: 1. 0. 0. 76
LightSkinImages. dll	: 1. 0. 0. 76
MaxxAudioAPO. dll	: 1. 2. 2. 0
MaxxAudioAPO20. dll	: 2. 2. 9. 0
MaxxAudioAPO30. dll	: 3. 2. 1. 1
MaxxAudioEQ. dll	: 5. 9. 7. 0
MaxxAudioRealtek. dll	: 1. 1. 0. 0
MaxxAudioRealtek2. dll	: 1. 0. 3. 0
MaxxVolumeSDAPO. dll	: 3. 1. 0. 0
MBAPO32. dll	: 1. 0. 41. 0
MBPPCn32. dll	: 1. 0. 0. 110
MBppld32. dll	: 1. 0. 41. 0
MBTHX32. dll	: 1. 0. 15. 122
MBWrp32. dll	: 1. 0. 0. 180
R4EEA32A. dll	: 7. 1. 7000. 5
R4EED32A. dll	: 7. 1. 7000. 5
R4EEG32A. dll	: 7. 1. 7000. 5
R4EEL32A. dll	: 7. 1. 7000. 5
R4EEP32A. dll	: 7. 1. 7000. 5
RP3DAA32. dll	: 6. 0. 6001. 18
RP3DHT32. dll	: 6. 0. 6001. 18
RTCOMDLL. dll	: 2. 0. 0. 140
RTEED32A. dll	: 6. 1. 6001. 33
RTEEG32A. dll	: 6. 1. 6001. 33
RTEEL32A. dll	: 6. 1. 6001. 33
RTEEP32A. dll	: 6. 1. 6001. 33
RtkAPO. dll	: 11. 0. 6000. 178
RtkApoApi. dll	: 1. 0. 0. 31
RtkCfg. dll	: 1. 0. 0. 2
RtkColnst. dll	: 1. 1. 1. 1
RtkGuiCompLib. dll	: 1. 0. 0. 2
RtkPgExt. dll	: 6. 0. 6000. 165
RtlCPAPI. dll	: 1. 0. 2. 4
SFAPO. dll	: 3. 0. 0. 11
SFCOM. dll	: 3. 0. 0. 11
SFFXComm. dll	: 2. 0. 0. 13
SFFXDAP0. dll	: 2. 0. 0. 13
SFFXHAP0. dll	: 2. 0. 0. 13
SFFXProc. dll	: 2. 0. 0. 13
SFFXSAP0. dll	: 2. 0. 0. 13
SFNHK. dll	: 3. 0. 0. 11
slcshp32. dll	: 1. 0. 3. 0
slgeq32. dll	: 1. 0. 1. 0
slh36032. dll	: 1. 0. 2. 0
slinit32. dll	: 1. 1. 3. 0
slmaxv32. dll	: 1. 1. 2. 0

Readme. txt

sltshd32.dll	: 1.2.0.0
sluapo32.dll	: 1.8.34.0
slvi pp32.dll	: 1.0.1.0
SRSHP360.dll	: 1.1.0.0
SRSTSHD.dll	: 1.1.4.0
SRSTSXT.dll	: 3.2.0.0
SRSWOW.dll	: 1.1.3.0
WavesGUILib.dll	: 1.1.0.0
WavesLib.dll	: 5.9.7.0
Vista/Win7 driver for x64	
RTKVHD64.sys	: 6.0.1.6235
AERTSr64.exe	: 1.0.64.10
FMAPP.exe	: 1.64.0.1
RAVBg64.exe	: 1.0.0.51
RAVCpl64.exe	: 1.0.0.603
RtkAudioService64.exe	: 1.0.0.27
RtkNGUI64.exe	: 1.0.0.76
RtlUpd64.exe	: 2.8.0.3
SkyTel.exe	: 2.0.2.2
vncutil64.exe	: 1.0.0.40
GWfilt64.sys	: 6.10.0.3
mbfilt64.sys	: 6.10.0.8
RTSnMg64.cpl	: 1.0.0.19
AERTAC64.dll	: 2.0.64.13
AERTAR64.dll	: 1.0.64.9
BlackSkinImages64.dll	: 1.0.0.76
DarkSkinImages64.dll	: 1.0.0.76
DTSBassEnhancementDLL64.dll	: 1.0.0.1
DTSBoostDLL64.dll	: 1.0.0.1
DTSGainCompensatorDLL64.dll	: 1.0.0.1
DTSAFXAP064.dll	: 1.0.0.3
DTSAFXAPONS64.dll	: 1.0.0.3
DTSAFXAP064.dll	: 1.0.0.3
DTSLimitDLL64.dll	: 1.0.0.1
DTSNeoPCDLL64.dll	: 1.0.0.1
DTSS2HeadphoneDLL64.dll	: 1.0.0.1
DTSS2SpeakerDLL64.dll	: 1.0.0.1
DTSSymmetryDLL64.dll	: 1.0.0.1
DTSVoiceClarityDLL64.dll	: 1.0.0.1
FMAP064.dll	: 43.6.6.68
GrayJadeSkinImages64.dll	: 1.0.0.76
LightSkinImages64.dll	: 1.0.0.76
MaxxAudioAP020.dll	: 2.2.9.0
MaxxAudioAP030.dll	: 3.2.1.1
MaxxAudioEQ.dll	: 5.9.7.0
MaxxAudioRealtek.dll	: 1.1.0.0
MaxxAudioRealtek2.dll	: 1.0.3.0
MaxxVolumeSDAPO.dll	: 3.1.0.0
MBAP032.dll	: 1.0.41.0
MBAP064.dll	: 1.0.41.0
MBPPCn64.dll	: 1.0.0.110
MBpld64.dll	: 1.0.41.0
MBTHX32.dll	: 1.0.15.122
MBTHX64.dll	: 1.0.15.122
MBWrp64.dll	: 1.0.0.180
R4EEA64A.dll	: 7.1.7000.5
R4EED64A.dll	: 7.1.7000.5
R4EEG64A.dll	: 7.1.7000.5
R4EEL64A.dll	: 7.1.7000.5
R4EEP64A.dll	: 7.1.7000.5
RCoInst64.dll	: 1.1.1.1
RP3DAA64.dll	: 6.0.6001.18
RP3DHT64.dll	: 6.0.6001.18
RtCOMB4.dll	: 2.0.0.140
RTCOMDLL.dll	: 2.0.0.140
RTEED64A.dll	: 6.1.6001.33
RTEEG64A.dll	: 6.1.6001.33
RTEEL64A.dll	: 6.1.6001.33
RTEEP64A.dll	: 6.1.6001.33

Readme.txt



Readme.txt

```

RtkApi 64. dll : 1. 0. 0. 31
RtkAPO64. dll : 11. 0. 6000. 178
RtkCfg. dll : 1. 0. 0. 1
RtkCfg64. dll : 1. 0. 0. 2
RtkGui CompLib. dll : 1. 0. 0. 2
RtlCPAPI. dll : 1. 0. 2. 4
RtlCPAPI64. dll : 1. 0. 2. 4
RtPgEx64. dll : 6. 0. 6000. 165
SFAP064. dll : 3. 0. 0. 11
SFCOM. dll : 3. 0. 0. 11
SFCOM64. dll : 3. 0. 0. 11
SFComm64. dll : 2. 0. 0. 13
SFDAP064. dll : 2. 0. 0. 13
SFHAP064. dll : 2. 0. 0. 13
SFNHK64. dll : 3. 0. 0. 11
SFProc64. dll : 2. 0. 0. 13
SFSAP064. dll : 2. 0. 0. 13
SFSS_APO. dll : 1. 0. 0. 10280
slcshp64. dll : 1. 0. 3. 0
slgeq64. dll : 1. 0. 1. 0
slh36064. dll : 1. 0. 2. 0
slInit64. dll : 1. 1. 3. 0
slmaxv64. dll : 1. 1. 2. 0
sltshd64. dll : 1. 2. 0. 0
sluapo64. dll : 1. 8. 34. 0
slvi pp64. dll : 1. 0. 1. 0
SRSHP64. dll : 1. 1. 0. 0
SRSTSH64. dll : 1. 1. 4. 0
SRSTX64. dll : 3. 2. 0. 0
SRSWOW64. dll : 1. 1. 3. 0
WavesGUILib. dll : 1. 1. 0. 0
HDM Driver : -----
Vista/WIn7 x86:
RtHDMV. sys : 6. 0. 1. 6121
RtkAudioSrvATI. exe : 1. 0. 0. 23
RtkUpd. exe : 2. 8. 0. 3
RH3DAA32. dll : 6. 0. 6001. 18
RH3DHT32. dll : 6. 0. 6001. 18
RHCoInst. dll : 1. 0. 8. 6
RHDMExt. dll : 6. 0. 6000. 127
RTEED32H. dll : 6. 1. 6001. 33
RTEEG32H. dll : 6. 1. 6001. 33
RTEEL32H. dll : 6. 1. 6001. 33
RTEEP32H. dll : 6. 1. 6001. 33
RtkHDM. dll : 11. 0. 6000. 151

Vista/WIn7 x64:
RtHDMVX. sys : 6. 0. 1. 6121
RtkAudioSrvATI64. exe : 1. 0. 0. 23
RtkUpd64. exe : 2. 8. 0. 3
RH3DAA64. dll : 6. 0. 6001. 18
RH3DHT64. dll : 6. 0. 6001. 18
RHCoInst64. dll : 1. 0. 8. 6
RHDMeX64. dll : 6. 0. 6000. 127
RTEED64H. dll : 6. 1. 6001. 33
RTEEG64H. dll : 6. 1. 6001. 33
RTEEL64H. dll : 6. 1. 6001. 33
RTEEP64H. dll : 6. 1. 6001. 33
RtkHDM64. dll : 11. 0. 6000. 151

XP/2K x86:
RtkHDM. sys : 5. 10. 0. 6121
Rtaupd. exe : 2. 8. 0. 3
RHCoInstXP. dll : 1. 0. 8. 6

XP/2K x64:
RtkHDMX. sys : 5. 10. 0. 6121
Rtaupd64. exe : 2. 8. 0. 3
RHCoInst64XP. dll : 1. 0. 8. 6

```

Readme.txt

Driver Setup Program : 3.13

Windows 2000/XP Operate on :  
Microsoft High Definition Audio Driver Package - KB888111  
Package file version (kb888111.exe) : 6.1.22.0  
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.53

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC892, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC892, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680

3. HDM Device WHQL Support: ATI HDM Devices

4. OS Supporting: Microsoft WindowsXP, Windows2000, Windows Server 2003, Vista, Windows Server 2008,

Windows7 - x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :

RTKHDA64.sys	: 5.10.0.6215
RtkHDAud.sys	: 5.10.0.6215
Alcmtr.exe	: 1.6.0.4
AlcWzrd.exe	: 1.1.0.37
McCal.exe	: 1.1.2.4
RTHDCPL.exe	: 2.3.7.2
RtkAudioService64.exe	: 1.0.0.19
RtkAudioService.exe	: 1.0.0.19
RTLCP.exe	: 1.0.1.66
RtlUpd64.exe	: 2.8.0.3
RtlUpd.exe	: 2.8.0.3
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.32
vncutil64.exe	: 1.0.0.38
vncutil.exe	: 1.0.0.38
AMBfilt.sys	: 5.10.0.4240
AMBft64.sys	: 5.10.0.4240
Mnft64.sys	: 5.10.0.4112
Mnft64.sys	: 5.10.0.4115
OA017Afx.sys	: 1.0.7.3
ALSndMgr.cpl	: 1.0.0.11
RTSndMgr.cpl	: 1.0.1.6
RCoInst64.dll	: 1.1.0.3
RCoInst64XP.dll	: 1.1.0.4
RTCOMDLL.dll	: 1.0.0.108
RtkCoInst.dll	: 1.1.0.3
RtkCoInstXP.dll	: 1.1.0.4
RtlCPAPI.dll	: 1.0.2.3

Vista/Win7 driver : -----

Vista/Win7 driver for x86

RTKVHDA.sys	: 6.0.1.6215
AERTSrv.exe	: 1.0.32.10
RtHDVBg.exe	: 1.0.0.46
RtHDVCpl.exe	: 1.0.0.590
RtkAudioService.exe	: 1.0.0.27
RtkNGUI.exe	: 1.0.0.65
RtlUpd.exe	: 2.8.0.3
SkyTel.exe	: 2.0.2.2
vncutil.exe	: 1.0.0.40
mbfilt32.sys	: 6.10.0.8
RTSndMgr.cpl	: 1.0.0.19
AERTACap.dll	: 2.0.32.13

	Readme.txt	
AERTARen.dll	:	1.0.32.9
BlackSkinImages.dll	:	1.0.0.65
DarkSkinImages.dll	:	1.0.0.65
DTSBassEnhancementDLL.dll	:	1.0.0.1
DTSBoostDLL.dll	:	1.0.0.1
DTSGainCompensatorDLL.dll	:	1.0.0.1
DTSGFXAPO.dll	:	1.0.0.3
DTSGFXAPONS.dll	:	1.0.0.3
DTSLFXAPO.dll	:	1.0.0.3
DTSLimitDLL.dll	:	1.0.0.1
DTSNeoPCDLL.dll	:	1.0.0.1
DTSS2HeadphoneDLL.dll	:	1.0.0.1
DTSS2SpeakerDLL.dll	:	1.0.0.1
DTSSymmetryDLL.dll	:	1.0.0.1
DTSVoiceClarityDLL.dll	:	1.0.0.1
FMAPO.dll	:	42.5.35.67
GrayJadeSkinImages.dll	:	1.0.0.65
LightSkinImages.dll	:	1.0.0.65
MaxxAudioAPO.dll	:	1.2.2.0
MaxxAudioAPO20.dll	:	2.2.9.0
MaxxAudioAPO30.dll	:	3.2.0.2
MaxxAudioEQ.dll	:	5.9.7.0
MaxxAudioRealtek.dll	:	1.0.0.0
MaxxAudioRealtek2.dll	:	1.0.2.0
MaxxVolumeSDAPO.dll	:	3.1.0.0
MBAPO32.dll	:	1.0.41.0
MBPPCn32.dll	:	1.0.0.110
MBpld32.dll	:	1.0.41.0
MBTHX32.dll	:	1.0.15.122
MBWp32.dll	:	1.0.0.180
RP3DAA32.dll	:	6.0.6001.18
RP3DHT32.dll	:	6.0.6001.18
RTCOMDLL.dll	:	2.0.0.137
RTEED32A.dll	:	6.1.6001.33
RTEEG32A.dll	:	6.1.6001.33
RTEEL32A.dll	:	6.1.6001.33
RTEEP32A.dll	:	6.1.6001.33
RtkAPO.dll	:	11.0.6000.168
RtkApoApi.dll	:	1.0.0.28
RtkCfg.dll	:	1.0.0.2
RtkColInst.dll	:	1.1.0.8
RtkGuiCompLib.dll	:	1.0.0.2
RtkPgExt.dll	:	6.0.6000.159
RtlCPAPI.dll	:	1.0.2.4
SFAPO.dll	:	3.0.0.11
SFCOM.dll	:	3.0.0.11
SFFXComm.dll	:	2.0.0.13
SFFXDAP0.dll	:	2.0.0.13
SFFXHAP0.dll	:	2.0.0.13
SFFXProc.dll	:	2.0.0.13
SFFXSAP0.dll	:	2.0.0.13
SFNHK.dll	:	3.0.0.11
slcshp32.dll	:	1.0.3.0
slgeq32.dll	:	1.0.1.0
slh36032.dll	:	1.0.2.0
slInit32.dll	:	1.1.3.0
slmaxv32.dll	:	1.1.2.0
sltshd32.dll	:	1.2.0.0
sluapo32.dll	:	1.8.34.0
slvip32.dll	:	1.0.1.0
SRSHP360.dll	:	1.1.0.0
SRSTSHD.dll	:	1.1.4.0
SRSTSXT.dll	:	3.2.0.0
SRSWOW.dll	:	1.1.3.0
WavesGUILib.dll	:	1.0.0.0
WavesLib.dll	:	5.9.7.0
Vista/WIn7 driver for x64		
RTKVHD64.sys	:	6.0.1.6215
AERTSr64.exe	:	1.0.64.10

	Readme.txt	
RAVBg64.exe	:	1.0.0.46
RAVCpl64.exe	:	1.0.0.590
RtkAudioService64.exe	:	1.0.0.27
RtkNGUI64.exe	:	1.0.0.65
RtlUpd64.exe	:	2.8.0.3
SkyTel.exe	:	2.0.2.2
vncutil64.exe	:	1.0.0.40
GWfilt64.sys	:	6.10.0.3
mbfilt64.sys	:	6.10.0.8
RTSnMg64.cpl	:	1.0.0.19
AERTAC64.dll	:	2.0.64.13
AERTAR64.dll	:	1.0.64.9
BlackSkinImages64.dll	:	1.0.0.65
DarkSkinImages64.dll	:	1.0.0.65
DTSBassEnhancementDLL64.dll	:	1.0.0.1
DTSBoostDLL64.dll	:	1.0.0.1
DTSGainCompensatorDLL64.dll	:	1.0.0.1
DTSAFXAP064.dll	:	1.0.0.3
DTSAFXAPONS64.dll	:	1.0.0.3
DTSAFXAP064.dll	:	1.0.0.3
DTSLimitDLL64.dll	:	1.0.0.1
DTSNeoPCDLL64.dll	:	1.0.0.1
DTSS2HeadphoneDLL64.dll	:	1.0.0.1
DTSS2SpeakerDLL64.dll	:	1.0.0.1
DTSSymmetryDLL64.dll	:	1.0.0.1
DTSVoiceClarityDLL64.dll	:	1.0.0.1
FMAP064.dll	:	42.6.35.67
GrayJadeSkinImages64.dll	:	1.0.0.65
LightSkinImages64.dll	:	1.0.0.65
MaxxAudioAP020.dll	:	2.2.9.0
MaxxAudioAP030.dll	:	3.2.0.2
MaxxAudioEQ.dll	:	5.9.7.0
MaxxAudioRealtek.dll	:	1.0.0.0
MaxxAudioRealtek2.dll	:	1.0.2.0
MaxxVolumeSDAPO.dll	:	3.1.0.0
MBAP032.dll	:	1.0.41.0
MBAP064.dll	:	1.0.41.0
MBPPCn64.dll	:	1.0.0.110
Mbpld64.dll	:	1.0.41.0
MBTHX32.dll	:	1.0.15.122
MBTHX64.dll	:	1.0.15.122
MBWrp64.dll	:	1.0.0.180
RCoInst64.dll	:	1.1.0.8
RP3DAA64.dll	:	6.0.6001.18
RP3DHT64.dll	:	6.0.6001.18
RtCOMB4.dll	:	2.0.0.137
RTCOMDLL.dll	:	2.0.0.137
RTEED64A.dll	:	6.1.6001.33
RTEEG64A.dll	:	6.1.6001.33
RTEEL64A.dll	:	6.1.6001.33
RTEEP64A.dll	:	6.1.6001.33
RtkApi64.dll	:	1.0.0.28
RtkAP064.dll	:	11.0.6000.168
RtkCfg.dll	:	1.0.0.1
RtkCfg64.dll	:	1.0.0.2
RtkGuiCompLib.dll	:	1.0.0.2
RtlCPAPI.dll	:	1.0.2.4
RtlCPAPI64.dll	:	1.0.2.4
RtPgEx64.dll	:	6.0.6000.159
SFAP064.dll	:	3.0.0.11
SFCOM.dll	:	3.0.0.11
SFCOMB4.dll	:	3.0.0.11
SFComm64.dll	:	2.0.0.13
SFDAP064.dll	:	2.0.0.13
SFHAP064.dll	:	2.0.0.13
SFNHK64.dll	:	3.0.0.11
SFProc64.dll	:	2.0.0.13
SFSAP064.dll	:	2.0.0.13
SFSS_APO.dll	:	1.0.0.8310

```

Readme.txt
slcshp64.dll : 1.0.3.0
slgeq64.dll : 1.0.1.0
slh36064.dll : 1.0.2.0
slInit64.dll : 1.1.3.0
slmaxv64.dll : 1.1.2.0
sltshd64.dll : 1.2.0.0
sluapo64.dll : 1.8.34.0
slvip64.dll : 1.0.1.0
SRSHp64.dll : 1.1.0.0
SRSTSH64.dll : 1.1.4.0
SRSTX64.dll : 3.2.0.0
SRSWW64.dll : 1.1.3.0
WavesGUILib.dll : 1.0.0.0
HDM Driver : -----
Vista/Win7 x86:
RtHDMV.sys : 6.0.1.6121
RtkAudioSrvATI.exe : 1.0.0.23
RtkUpd.exe : 2.8.0.3
RH3DAA32.dll : 6.0.6001.18
RH3DHT32.dll : 6.0.6001.18
RHCoInst.dll : 1.0.8.6
RHDMEExt.dll : 6.0.6000.127
RTEED32H.dll : 6.1.6001.33
RTEEG32H.dll : 6.1.6001.33
RTEEL32H.dll : 6.1.6001.33
RTEEP32H.dll : 6.1.6001.33
RtkHDM.dll : 11.0.6000.151

Vista/Win7 x64:
RtHDMVX.sys : 6.0.1.6121
RtkAudioSrvATI64.exe : 1.0.0.23
RtkUpd64.exe : 2.8.0.3
RH3DAA64.dll : 6.0.6001.18
RH3DHT64.dll : 6.0.6001.18
RHCoInst64.dll : 1.0.8.6
RHDMEx64.dll : 6.0.6000.127
RTEED64H.dll : 6.1.6001.33
RTEEG64H.dll : 6.1.6001.33
RTEEL64H.dll : 6.1.6001.33
RTEEP64H.dll : 6.1.6001.33
RtkHDM64.dll : 11.0.6000.151

XP/2K x86:
RtkHDM.sys : 5.10.0.6121
Rtaupd.exe : 2.8.0.3
RHCoInstXP.dll : 1.0.8.6

XP/2K x64:
RtkHDMX.sys : 5.10.0.6121
Rtaupd64.exe : 2.8.0.3
RHCoInst64XP.dll : 1.0.8.6

Driver Setup Program : 3.10

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

```

//=====

Driver Package R2.52

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC892, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC892, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680
3. HDM Device WHQL Support: ATI HDM Devices

Readme.txt

4. OS Supporting: Microsoft WindowsXP, Windows2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 - x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
  - 1.) Driver :
    1. Customizations.

Windows 2000/XP : -----  
 Windows 2000/XP :  
 RTKHDA64.sys : 5.10.0.6194  
 RtkHDAud.sys : 5.10.0.6194  
 AlcWzrd.exe : 1.1.0.37  
 McCal.exe : 1.1.2.4  
 RTHDCPL.exe : 2.3.6.9  
 RtkAudioService64.exe : 1.0.0.19  
 RtkAudioService.exe : 1.0.0.19  
 RTLCPL.exe : 1.0.1.66  
 RtlUpd64.exe : 2.8.0.3  
 RtlUpd.exe : 2.8.0.3  
 SkyTel.exe : 2.0.2.0  
 SoundMan.exe : 1.0.0.32  
 vncutil64.exe : 1.0.0.38  
 vncutil.exe : 1.0.0.38  
 Alcmtr.exe : 1.6.0.4  
 AMBFilt.sys : 5.10.0.4240  
 AMBFt64.sys : 5.10.0.4240  
 Mbnfilt.sys : 5.10.0.4112  
 Mbnft64.sys : 5.10.0.4115  
 OA017Afx.sys : 1.0.7.3  
 ALSndMgr.cpl : 1.0.0.11  
 RTSndMgr.cpl : 1.0.1.6  
 RCoInst64.dll : 1.1.0.3  
 RCoInst64XP.dll : 1.1.0.3  
 RTCOMDLL.dll : 1.0.0.108  
 RtkCoInst.dll : 1.1.0.3  
 RtkCoInstXP.dll : 1.1.0.3  
 RtlCPAPI.dll : 1.0.2.3

Vista/Win7 driver : -----  
 Vista/Win7 driver for x86  
 RTKVHDA.sys : 6.0.1.6194  
 AERTSrv.exe : 1.0.32.10  
 RtHDVBg.exe : 1.0.0.41  
 RtHDVCpl.exe : 1.0.0.576  
 RtkAudioService.exe : 1.0.0.27  
 RtkNGUI.exe : 1.0.0.57  
 RtlUpd.exe : 2.8.0.3  
 SkyTel.exe : 2.0.2.2  
 vncutil.exe : 1.0.0.40  
 mbnfilt32.sys : 6.10.0.8  
 RTSndMgr.cpl : 1.0.0.19  
 AERTACap.dll : 2.0.32.13  
 AERTARen.dll : 1.0.32.9  
 BlackSkinImages.dll : 1.0.0.57  
 DarkSkinImages.dll : 1.0.0.57  
 DTSBassEnhancementDLL.dll : 1.0.0.1  
 DTSTBoostDLL.dll : 1.0.0.1  
 DTSGainCompensatorDLL.dll : 1.0.0.1  
 DTSGFXAPO.dll : 1.0.0.2  
 DTSGFXAPONS.dll : 1.0.0.2  
 DTSLFXAPO.dll : 1.0.0.2  
 DTSLimiterDLL.dll : 1.0.0.1  
 DTSSNeoPCDLL.dll : 1.0.0.1  
 DTSS2HeadphoneDLL.dll : 1.0.0.1  
 DTSS2SpeakerDLL.dll : 1.0.0.1  
 DTSSymmetryDLL.dll : 1.0.0.1  
 DTSSVoiceClarityDLL.dll : 1.0.0.1  
 FMAP0.dll : 42.5.35.66  
 GrayJadeSkinImages.dll : 1.0.0.57  
 LightSkinImages.dll : 1.0.0.57

	Readme.txt	
MaxxAudioAPO.dll	:	1.2.2.0
MaxxAudioAPO20.dll	:	2.2.8.0
MaxxAudioAPO30.dll	:	3.2.0.2
MaxxAudioEQ.dll	:	5.9.7.0
MaxxAudioRealtek.dll	:	1.0.0.0
MaxxAudioRealtek2.dll	:	1.0.2.0
MaxxVolumeSDAPO.dll	:	3.1.0.0
MBAP032.dll	:	1.0.40.0
MBPPCn32.dll	:	1.0.0.110
MBpld32.dll	:	1.0.40.0
MBTHX32.dll	:	1.0.15.120
MBWrp32.dll	:	1.0.0.180
RP3DAA32.dll	:	6.0.6001.18
RP3DHT32.dll	:	6.0.6001.18
RTCOMDLL.dll	:	2.0.0.137
RTEED32A.dll	:	6.1.6001.33
RTEEG32A.dll	:	6.1.6001.33
RTEEL32A.dll	:	6.1.6001.33
RTEEP32A.dll	:	6.1.6001.33
RtkAPO.dll	:	11.0.6000.165
RtkApoApi.dll	:	1.0.0.24
RtkCfg.dll	:	1.0.0.2
RtkColnst.dll	:	1.1.0.3
RtkGuiCompLib.dll	:	1.0.0.2
RtkPgExt.dll	:	6.0.6000.152
RtlCPAPI.dll	:	1.0.2.4
SFAP0.dll	:	3.0.0.11
SFCOM.dll	:	3.0.0.11
SFFXComm.dll	:	2.0.0.13
SFFXDAP0.dll	:	2.0.0.13
SFFXHAP0.dll	:	2.0.0.13
SFFXProc.dll	:	2.0.0.13
SFFXSAP0.dll	:	2.0.0.13
SFNHK.dll	:	3.0.0.11
slcshp32.dll	:	1.0.3.0
slgeq32.dll	:	1.0.1.0
slh36032.dll	:	1.0.2.0
slInit32.dll	:	1.1.3.0
slmaxv32.dll	:	1.1.2.0
sltshd32.dll	:	1.2.0.0
sluapo32.dll	:	1.8.34.0
slvip32.dll	:	1.0.1.0
SRSHP360.dll	:	1.1.0.0
SRSTSHD.dll	:	1.1.4.0
SRSTSXT.dll	:	3.2.0.0
SRSWOW.dll	:	1.1.3.0
WavesGUILib.dll	:	1.0.0.0
WavesLib.dll	:	5.9.7.0
Vista/Win7 driver for x64		
RTKVHD64.sys	:	6.0.1.6194
AERTSr64.exe	:	1.0.64.10
RAVBg64.exe	:	1.0.0.41
RAVCpl64.exe	:	1.0.0.576
RtkAudioService64.exe	:	1.0.0.27
RtkNGUI64.exe	:	1.0.0.57
RtlUpd64.exe	:	2.8.0.3
SkyTel.exe	:	2.0.2.2
vncutil64.exe	:	1.0.0.40
GWfilt64.sys	:	6.10.0.3
mbfilt64.sys	:	6.10.0.8
RTSnMg64.cpl	:	1.0.0.19
AERTAC64.dll	:	2.0.64.13
AERTAR64.dll	:	1.0.64.9
BlackSkinImages64.dll	:	1.0.0.57
DarkSkinImages64.dll	:	1.0.0.57
DTSBassEnhancementDLL64.dll	:	1.0.0.1
DTSBoostDLL64.dll	:	1.0.0.1
DTSGainCompensatorDLL64.dll	:	1.0.0.1
DTS GFXAP064.dll	:	1.0.0.2

	Readme.txt	
DTSGFXAPONS64.dll		: 1.0.0.2
DTSLFXAP064.dll		: 1.0.0.2
DTSLi mi terDLL64.dll		: 1.0.0.1
DTSSNeoPCDLL64.dll		: 1.0.0.1
DTSS2HeadphoneDLL64.dll		: 1.0.0.1
DTSS2SpeakerDLL64.dll		: 1.0.0.1
DTSSymmetryDLL64.dll		: 1.0.0.1
DTSVoi ceCl ari tyDLL64.dll		: 1.0.0.1
FMAP064.dll		: 42.6.35.66
GrayJadeSkinImages64.dll		: 1.0.0.57
Li ghtSkinImages64.dll		: 1.0.0.57
MaxxAudi oAP020.dll		: 2.2.8.0
MaxxAudi oAP030.dll		: 3.2.0.2
MaxxAudi oEQ.dll		: 5.9.7.0
MaxxAudi oReal tek.dll		: 1.0.0.0
MaxxAudi oReal tek2.dll		: 1.0.2.0
MaxxVol umeSDAP0.dll		: 3.1.0.0
MBAP032.dll		: 1.0.40.0
MBAP064.dll		: 1.0.40.0
MBPPCn64.dll		: 1.0.0.110
Mbpl d64.dll		: 1.0.40.0
MBTHX32.dll		: 1.0.15.120
MBTHX64.dll		: 1.0.15.120
MBWrp64.dll		: 1.0.0.180
RCoInst64.dll		: 1.1.0.3
RP3DAA64.dll		: 6.0.6001.18
RP3DHT64.dll		: 6.0.6001.18
RtCOM64.dll		: 2.0.0.137
RTCOMDLL.dll		: 2.0.0.137
RTEED64A.dll		: 6.1.6001.33
RTEEG64A.dll		: 6.1.6001.33
RTEEL64A.dll		: 6.1.6001.33
RTEEP64A.dll		: 6.1.6001.33
RtkApi 64.dll		: 1.0.0.24
RtkAP064.dll		: 11.0.6000.165
RtkCfg.dll		: 1.0.0.1
RtkCfg64.dll		: 1.0.0.2
RtkGui CompLib.dll		: 1.0.0.2
RtLCPAPI.dll		: 1.0.2.4
RtLCPAPI64.dll		: 1.0.2.4
RtPgEx64.dll		: 6.0.6000.152
SFAP064.dll		: 3.0.0.11
SFCOM.dll		: 3.0.0.11
SFCOM64.dll		: 3.0.0.11
SFComm64.dll		: 2.0.0.13
SFDAPO64.dll		: 2.0.0.13
SFHAP064.dll		: 2.0.0.13
SFNHK64.dll		: 3.0.0.11
SFProc64.dll		: 2.0.0.13
SFSAP064.dll		: 2.0.0.13
SFSS_APO.dll		: 1.0.0.8020
sl cshp64.dll		: 1.0.3.0
sl geq64.dll		: 1.0.1.0
sl h36064.dll		: 1.0.2.0
sl Ini t64.dll		: 1.1.3.0
sl maxv64.dll		: 1.1.2.0
sl tshd64.dll		: 1.2.0.0
sl uapo64.dll		: 1.8.34.0
sl vi pp64.dll		: 1.0.1.0
SRSHP64.dll		: 1.1.0.0
SRSTSH64.dll		: 1.1.4.0
SRSTX64.dll		: 3.2.0.0
SRSW064.dll		: 1.1.3.0
WavesGUILib.dll		: 1.0.0.0
HDMI Driver : -----		
Vista/Win7 x86:		
RtHDMV.sys		: 6.0.1.6121
RtkAudioSrvATI.exe		: 1.0.0.23
RtkUpd.exe		: 2.8.0.3



Readme.txt

RH3DAA32.dll : 6.0.6001.18  
RH3DHT32.dll : 6.0.6001.18  
RHCoInst.dll : 1.0.8.6  
RHDMExt.dll : 6.0.6000.127  
RTEED32H.dll : 6.1.6001.33  
RTEEG32H.dll : 6.1.6001.33  
RTEEL32H.dll : 6.1.6001.33  
RTEEP32H.dll : 6.1.6001.33  
RtkHDM.dll : 11.0.6000.151

Vista/Win7 x64:

RtHDMVX.sys : 6.0.1.6121  
RtkAudioSrvATI64.exe : 1.0.0.23  
RtkUpd64.exe : 2.8.0.3  
RH3DAA64.dll : 6.0.6001.18  
RH3DHT64.dll : 6.0.6001.18  
RHCoInst64.dll : 1.0.8.6  
RHDMEx64.dll : 6.0.6000.127  
RTEED64H.dll : 6.1.6001.33  
RTEEG64H.dll : 6.1.6001.33  
RTEEL64H.dll : 6.1.6001.33  
RTEEP64H.dll : 6.1.6001.33  
RtkHDM64.dll : 11.0.6000.151

XP/2K x86:

RtkHDM.sys : 5.10.0.6121  
Rtaupd.exe : 2.8.0.3  
RHCoInstXP.dll : 1.0.8.6

XP/2K x64:

RtkHDMX.sys : 5.10.0.6121  
Rtaupd64.exe : 2.8.0.3  
RHCoInst64XP.dll : 1.0.8.6

Driver Setup Program : 3.07

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111  
Package file version (kb888111.exe) : 6.1.22.0  
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.51

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC892, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC892, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680

3. HDM Device WHQL Support: ATI HDM Devices

4. OS Supporting: Microsoft WindowsXP, Windows2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 - x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :  
RTKHDA64.sys : 5.10.0.6167  
RtkHDAud.sys : 5.10.0.6167  
Alcmtr.exe : 1.6.0.4  
AlcWzrd.exe : 1.1.0.37  
McCal.exe : 1.1.2.4  
RTHDCPL.exe : 2.3.6.2  
RtkAudioService64.exe : 1.0.0.19  
RtkAudioService.exe : 1.0.0.19  
RTLCP.exe : 1.0.1.66

```

Readme.txt
RtlUpd64.exe : 2.8.0.3
RtlUpd.exe : 2.8.0.3
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.32
vncutil64.exe : 1.0.0.38
vncutil.exe : 1.0.0.38
AMBfilt.sys : 5.10.0.4240
AMBft64.sys : 5.10.0.4240
Mnfilt.sys : 5.10.0.4112
Mnft64.sys : 5.10.0.4115
OA017Afx.sys : 1.0.7.3
ALSndMgr.cpl : 1.0.0.11
RTSndMgr.cpl : 1.0.1.5
RCoInst64XP.dll : 1.0.9.9
RTCOMDLL.dll : 1.0.0.108
RtkCoInstXP.dll : 1.0.9.9
RtlCPAPI.dll : 1.0.2.3
Vista/Win7 driver : -----
Vista/Win7 driver for x86
RTKVHDA.sys : 6.0.1.6167
AERTSrv.exe : 1.0.32.10
RtHDVBg.exe : 1.0.0.40
RtHDVCpl.exe : 1.0.0.553
RtkAudioService.exe : 1.0.0.27
RtkNGUI.exe : 1.0.0.53
RtlUpd.exe : 2.8.0.3
SkyTel.exe : 2.0.2.2
vncutil.exe : 1.0.0.38
mbfilt32.sys : 6.10.0.8
RTSndMgr.cpl : 1.0.0.19
AERTACap.dll : 2.0.32.13
AERTARen.dll : 1.0.32.9
BlackSkinImages.dll : 1.0.0.53
DarkSkinImages.dll : 1.0.0.53
DTSBassEnhancementDLL.dll : 1.0.0.1
DTSBoostDLL.dll : 1.0.0.1
DTSGainCompensatorDLL.dll : 1.0.0.1
DTSAFXAPO.dll : 1.0.0.2
DTSAFXAPONS.dll : 1.0.0.2
DTSAFXAPO.dll : 1.0.0.2
DTSLimitDLL.dll : 1.0.0.1
DTSNeoPCDLL.dll : 1.0.0.1
DTSS2HeadphoneDLL.dll : 1.0.0.1
DTSS2SpeakerDLL.dll : 1.0.0.1
DTSymmetryDLL.dll : 1.0.0.1
DTSVoiceClarityDLL.dll : 1.0.0.1
FMAP0.dll : 42.5.32.66
GrayJadeSkinImages.dll : 1.0.0.53
LightSkinImages.dll : 1.0.0.53
MaxxAudioAPO.dll : 1.2.2.0
MaxxAudioAPO20.dll : 2.2.8.0
MaxxAudioAPO30.dll : 3.2.0.2
MaxxAudioEQ.dll : 5.9.7.0
MaxxAudioRealtek.dll : 1.0.0.0
MaxxAudioRealtek2.dll : 1.0.0.0
MaxxVolumeSDAPO.dll : 3.1.0.0
MBAP032.dll : 1.0.19.0
MBPPCn32.dll : 1.0.0.110
Mbppld32.dll : 1.0.22.0
MBTHX32.dll : 1.0.15.115
MBWrp32.dll : 1.0.0.180
RP3DAA32.dll : 6.0.6001.18
RP3DHT32.dll : 6.0.6001.18
RTCOMDLL.dll : 2.0.0.136
RTEED32A.dll : 6.1.6001.33
RTEEG32A.dll : 6.1.6001.33
RTEEL32A.dll : 6.1.6001.33
RTEEP32A.dll : 6.1.6001.33
RtkAPO.dll : 11.0.6000.160

```

	Readme.txt	
RtkApoApi.dll	:	1.0.0.21
RtkCfg.dll	:	1.0.0.2
RtkColnst.dll	:	1.1.0.0
RtkGuiCompLib.dll	:	1.0.0.1
RtkPgExt.dll	:	6.0.6000.141
RtlCPAPI.dll	:	1.0.2.4
SFAP0.dll	:	3.0.0.11
SFCOM.dll	:	3.0.0.11
SFFXComm.dll	:	2.0.0.13
SFFXDAP0.dll	:	2.0.0.13
SFFXHAP0.dll	:	2.0.0.13
SFFXProc.dll	:	2.0.0.13
SFFXSAP0.dll	:	2.0.0.13
SFNHK.dll	:	3.0.0.11
slcshp32.dll	:	1.0.3.0
slgeq32.dll	:	1.0.1.0
slh36032.dll	:	1.0.2.0
slinit32.dll	:	1.1.3.0
slmaxv32.dll	:	1.1.2.0
sltshd32.dll	:	1.2.0.0
sluapo32.dll	:	1.8.34.0
SRSHP360.dll	:	1.1.0.0
SRSTSHD.dll	:	1.1.4.0
SRSTSXT.dll	:	3.2.0.0
SRSWOW.dll	:	1.1.3.0
WavesGUILib.dll	:	1.0.0.0
WavesLib.dll	:	5.9.7.0
Vista/Win7 driver for x64		
RTKVHD64.sys	:	6.0.1.6167
AERTSr64.exe	:	1.0.64.10
RAVBg64.exe	:	1.0.0.40
RAVCpl64.exe	:	1.0.0.553
RtkAudioService64.exe	:	1.0.0.27
RtkNGUI64.exe	:	1.0.0.53
RtlUpd64.exe	:	2.8.0.3
SkyTel.exe	:	2.0.2.2
vncutil64.exe	:	1.0.0.38
GWfilt64.sys	:	6.10.0.3
mbfilt64.sys	:	6.10.0.8
RTSnMg64.cpl	:	1.0.0.19
AERTAC64.dll	:	2.0.64.13
AERTAR64.dll	:	1.0.64.9
BlackSkinImages64.dll	:	1.0.0.53
DarkSkinImages64.dll	:	1.0.0.53
DTSBassEnhancementDLL64.dll	:	1.0.0.1
DTSBoostDLL64.dll	:	1.0.0.1
DTSGainCompensatorDLL64.dll	:	1.0.0.1
DTS GFXAP064.dll	:	1.0.0.2
DTS GFXAPONS64.dll	:	1.0.0.2
DTS LFXAP064.dll	:	1.0.0.2
DTS LimiterDLL64.dll	:	1.0.0.1
DTS NeoPCDLL64.dll	:	1.0.0.1
DTSS2HeadphoneDLL64.dll	:	1.0.0.1
DTSS2SpeakerDLL64.dll	:	1.0.0.1
DTSSymmetryDLL64.dll	:	1.0.0.1
DTS VoiceClarityDLL64.dll	:	1.0.0.1
FMAP064.dll	:	42.6.32.66
GrayJadeSkinImages64.dll	:	1.0.0.53
LightSkinImages64.dll	:	1.0.0.53
MaxxAudioAP020.dll	:	2.2.8.0
MaxxAudioAP030.dll	:	3.2.0.2
MaxxAudioEQ.dll	:	5.9.7.0
MaxxAudioRealtek.dll	:	1.0.0.0
MaxxAudioRealtek2.dll	:	1.0.0.0
MaxxVolumeSDAP0.dll	:	3.1.0.0
MBAP032.dll	:	1.0.19.0
MBAP064.dll	:	1.0.19.0
MBPPCn64.dll	:	1.0.0.110
MBpld64.dll	:	1.0.22.0

Readme.txt

MBTHX32.dll	: 1.0.15.115
MBTHX64.dll	: 1.0.15.115
MBWrp64.dll	: 1.0.0.180
RCoInst64.dll	: 1.1.0.0
RP3DAA64.dll	: 6.0.6001.18
RP3DHT64.dll	: 6.0.6001.18
RtCOM64.dll	: 2.0.0.136
RTCOMDLL.dll	: 2.0.0.136
RTEED64A.dll	: 6.1.6001.33
RTEEG64A.dll	: 6.1.6001.33
RTEEL64A.dll	: 6.1.6001.33
RTEEP64A.dll	: 6.1.6001.33
RtkApi64.dll	: 1.0.0.21
RtkAPO64.dll	: 11.0.6000.160
RtkCfg.dll	: 1.0.0.1
RtkCfg64.dll	: 1.0.0.2
RtkGuiCompLib.dll	: 1.0.0.1
RtlCPAPI.dll	: 1.0.2.4
RtlCPAPI64.dll	: 1.0.2.4
RtPgEx64.dll	: 6.0.6000.141
SFAP064.dll	: 3.0.0.11
SFCOM.dll	: 3.0.0.11
SFCOM64.dll	: 3.0.0.11
SFComm64.dll	: 2.0.0.13
SFDAP064.dll	: 2.0.0.13
SFHAP064.dll	: 2.0.0.13
SFNHK64.dll	: 3.0.0.11
SFProc64.dll	: 2.0.0.13
SFSAP064.dll	: 2.0.0.13
slcshp64.dll	: 1.0.3.0
slgeq64.dll	: 1.0.1.0
slh36064.dll	: 1.0.2.0
slInit64.dll	: 1.1.3.0
slmaxv64.dll	: 1.1.2.0
sltshd64.dll	: 1.2.0.0
sluapo64.dll	: 1.8.34.0
SRSHP64.dll	: 1.1.0.0
SRSTSH64.dll	: 1.1.4.0
SRSTX64.dll	: 3.2.0.0
SRSWOW64.dll	: 1.1.3.0
WavesGUILib.dll	: 1.0.0.0
-----	
HDM Driver :	
Vista/Win7 x86:	
RtHDMV.sys	: 6.0.1.6121
RtkAudioSrvATI.exe	: 1.0.0.23
RtkUpd.exe	: 2.8.0.3
RH3DAA32.dll	: 6.0.6001.18
RH3DHT32.dll	: 6.0.6001.18
RHCoInst.dll	: 1.0.8.6
RHDMExt.dll	: 6.0.6000.127
RTEED32H.dll	: 6.1.6001.33
RTEEG32H.dll	: 6.1.6001.33
RTEEL32H.dll	: 6.1.6001.33
RTEEP32H.dll	: 6.1.6001.33
RtkHDM.dll	: 11.0.6000.151
Vista/Win7 x64:	
RtHDMVX.sys	: 6.0.1.6121
RtkAudioSrvATI64.exe	: 1.0.0.23
RtkUpd64.exe	: 2.8.0.3
RH3DAA64.dll	: 6.0.6001.18
RH3DHT64.dll	: 6.0.6001.18
RHCoInst64.dll	: 1.0.8.6
RHDMEx64.dll	: 6.0.6000.127
RTEED64H.dll	: 6.1.6001.33
RTEEG64H.dll	: 6.1.6001.33
RTEEL64H.dll	: 6.1.6001.33
RTEEP64H.dll	: 6.1.6001.33
RtkHDM64.dll	: 11.0.6000.151

Readme.txt

XP/2K x86:  
RtkHDM.sys : 5.10.0.6121  
Rtaupd.exe : 2.8.0.3  
RHCoInstXP.dll : 1.0.8.6

XP/2K x64:  
RtkHDMX.sys : 5.10.0.6121  
Rtaupd64.exe : 2.8.0.3  
RHCoInst64XP.dll : 1.0.8.6

Driver Setup Program : 3.06

Windows 2000/XP Operate on :  
Microsoft High Definition Audio Driver Package - KB888111  
Package file version (kb888111.exe) : 6.1.22.0  
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.50

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC892, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC892, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft WindowsXP, Windows2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 - x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :

RTKHDA64.sys : 5.10.0.6151  
RTKHDAUD.sys : 5.10.0.6151  
Alcmtr.exe : 1.6.0.4  
AlcWzrd.exe : 1.1.0.37  
McCal.exe : 1.1.2.4  
RTHDCPL.exe : 2.3.6.1  
RtkAudioService.exe : 1.0.0.19  
RtkAudioService64.exe : 1.0.0.19  
RTLCPPL.exe : 1.0.1.66  
RtlUpd.exe : 2.8.0.3  
RtlUpd64.exe : 2.8.0.3  
SkyTel.exe : 2.0.2.0  
SoundMan.exe : 1.0.0.32  
vncutil.exe : 1.0.0.38  
vncutil64.exe : 1.0.0.38  
AMBfilt.sys : 5.10.0.4240  
AMBft64.sys : 5.10.0.4240  
Mbnfilt.sys : 5.10.0.4112  
Mnft64.sys : 5.10.0.4115  
OA017Afx.sys : 1.0.7.3  
ALSndMgr.cpl : 1.0.0.11  
RTSndMgr.cpl : 1.0.1.5  
RCoInst64XP.dll : 1.0.9.9  
RTCOMDLL.dll : 1.0.0.108  
RtkCoInstXP.dll : 1.0.9.9  
RtlCPAPI.dll : 1.0.2.3

Vista/Win7 driver : -----

Vista/Win7 driver for x86

RTKVHDA.sys : 6.0.1.6151  
AERTSrv.exe : 1.0.32.10  
RtHDVbg.exe : 1.0.0.38  
RtHDVCpl.exe : 1.0.0.545

	Readme.txt	
RtkAudioService.exe	:	1.0.0.27
RtkNGUI.exe	:	1.0.0.52
RtlUpd.exe	:	2.8.0.3
SkyTel.exe	:	2.0.2.2
vncutil.exe	:	1.0.0.38
mbfilt32.sys	:	6.10.0.8
RTSndMgr.cpl	:	1.0.0.19
AERTACap.dll	:	2.0.32.11
AERTARen.dll	:	1.0.32.9
BlackSkinImages.dll	:	1.0.0.52
DarkSkinImages.dll	:	1.0.0.52
DTSBassEnhancementDLL.dll	:	1.0.0.1
DTSBoostDLL.dll	:	1.0.0.1
DTSGainCompensatorDLL.dll	:	1.0.0.1
DTSAFXAPO.dll	:	1.0.0.2
DTSAFXAPONS.dll	:	1.0.0.2
DTSLFXAPO.dll	:	1.0.0.2
DTSLimitDLL.dll	:	1.0.0.1
DTSNeoPCDLL.dll	:	1.0.0.1
DTSS2HeadphoneDLL.dll	:	1.0.0.1
DTSS2SpeakerDLL.dll	:	1.0.0.1
DTSSymmetryDLL.dll	:	1.0.0.1
DTSVoiceClarityDLL.dll	:	1.0.0.1
FMAPO.dll	:	42.5.32.66
GrayJadeSkinImages.dll	:	1.0.0.52
LightSkinImages.dll	:	1.0.0.52
MaxxAudioAPO.dll	:	1.2.2.0
MaxxAudioAPO20.dll	:	2.2.8.0
MaxxAudioAPO30.dll	:	3.1.0.0
MaxxAudioEQ.dll	:	5.9.7.0
MaxxAudioRealtek.dll	:	1.0.0.0
MaxxAudioRealtek2.dll	:	1.0.0.0
MaxxVolumeSDAPO.dll	:	3.1.0.0
MBAPO32.dll	:	1.0.19.0
MBPPCn32.dll	:	1.0.0.110
MBpld32.dll	:	1.0.22.0
MBTHX32.dll	:	1.0.15.115
MBWrp32.dll	:	1.0.0.180
RP3DAA32.dll	:	6.0.6001.18
RP3DHT32.dll	:	6.0.6001.18
RTCOMDLL.dll	:	2.0.0.135
RTEED32A.dll	:	6.1.6001.33
RTEEG32A.dll	:	6.1.6001.33
RTEEL32A.dll	:	6.1.6001.33
RTEEP32A.dll	:	6.1.6001.33
RtkAPO.dll	:	11.0.6000.156
RtkApoApi.dll	:	1.0.0.21
RtkCfg.dll	:	1.0.0.2
RtkColnst.dll	:	1.1.0.0
RtkGuiCompLib.dll	:	1.0.0.1
RtkPgExt.dll	:	6.0.6000.138
RtlCPAPI.dll	:	1.0.2.4
SFAPO.dll	:	3.0.0.8
SFCOM.dll	:	3.0.0.8
SFFXComm.dll	:	2.0.0.12
SFFXDAPO.dll	:	2.0.0.12
SFFXHAP0.dll	:	2.0.0.12
SFFXProc.dll	:	2.0.0.12
SFFXSAP0.dll	:	2.0.0.12
SFNHK.dll	:	3.0.0.8
slcshp32.dll	:	1.0.3.0
slgeq32.dll	:	1.0.1.0
slh36032.dll	:	1.0.2.0
slInit32.dll	:	1.1.3.0
slmaxv32.dll	:	1.1.2.0
sltshd32.dll	:	1.2.0.0
sluapo32.dll	:	1.8.34.0
SRSHP360.dll	:	1.1.0.0
SRSTSHD.dll	:	1.1.4.0

	Readme.txt	
SRSTSXT.dll		: 3.2.0.0
SRSWOW.dll		: 1.1.3.0
WavesGUILib.dll		: 1.0.0.0
WavesLib.dll		: 5.9.7.0
Vista/Win7 driver for x64		
RTKVHD64.sys		: 6.0.1.6151
AERTSr64.exe		: 1.0.64.10
RAVBg64.exe		: 1.0.0.38
RAVCpl64.exe		: 1.0.0.545
RtkAudioService64.exe		: 1.0.0.27
RtkNGUI64.exe		: 1.0.0.52
RtlUpd64.exe		: 2.8.0.3
SkyTel.exe		: 2.0.2.2
vncutil64.exe		: 1.0.0.38
GWfilt64.sys		: 6.10.0.3
mbfilt64.sys		: 6.10.0.8
RTSnMg64.cpl		: 1.0.0.19
AERTAC64.dll		: 2.0.64.11
AERTAR64.dll		: 1.0.64.9
BlackSkinImages64.dll		: 1.0.0.52
DarkSkinImages64.dll		: 1.0.0.52
DTSBassEnhancementDLL64.dll		: 1.0.0.1
DTSBoostDLL64.dll		: 1.0.0.1
DTSGainCompensatorDLL64.dll		: 1.0.0.1
DTSAFXAP064.dll		: 1.0.0.2
DTSAFXAPONS64.dll		: 1.0.0.2
DTSAFXAP064.dll		: 1.0.0.2
DTSLimitDLL64.dll		: 1.0.0.1
DTSNeoPCDLL64.dll		: 1.0.0.1
DTSS2HeadphoneDLL64.dll		: 1.0.0.1
DTSS2SpeakerDLL64.dll		: 1.0.0.1
DTSSymmetryDLL64.dll		: 1.0.0.1
DTSVoiceClarityDLL64.dll		: 1.0.0.1
FMAP064.dll		: 42.6.32.66
GrayJadeSkinImages64.dll		: 1.0.0.52
LightSkinImages64.dll		: 1.0.0.52
MaxxAudioAP020.dll		: 2.2.8.0
MaxxAudioAP030.dll		: 3.1.0.0
MaxxAudioEQ.dll		: 5.9.7.0
MaxxAudioRealtek.dll		: 1.0.0.0
MaxxAudioRealtek2.dll		: 1.0.0.0
MaxxVolumeSDAP0.dll		: 3.1.0.0
MBAP032.dll		: 1.0.19.0
MBAP064.dll		: 1.0.19.0
MBPPCn64.dll		: 1.0.0.110
MBpld64.dll		: 1.0.22.0
MBTHX32.dll		: 1.0.15.115
MBTHX64.dll		: 1.0.15.115
MBWrp64.dll		: 1.0.0.180
RCoInst64.dll		: 1.1.0.0
RP3DAA64.dll		: 6.0.6001.18
RP3DHT64.dll		: 6.0.6001.18
RtCOM64.dll		: 2.0.0.135
RTCOMDLL.dll		: 2.0.0.135
RTEED64A.dll		: 6.1.6001.33
RTEEG64A.dll		: 6.1.6001.33
RTEEL64A.dll		: 6.1.6001.33
RTEEP64A.dll		: 6.1.6001.33
RtkApi64.dll		: 1.0.0.21
RtkAP064.dll		: 11.0.6000.156
RtkCfg.dll		: 1.0.0.1
RtkCfg64.dll		: 1.0.0.2
RtkGuiCompLib.dll		: 1.0.0.1
RtlCPAPI.dll		: 1.0.2.4
RtlCPAPI64.dll		: 1.0.2.4
RtlPgEx64.dll		: 6.0.6000.138
SFAP064.dll		: 3.0.0.8
SFCOM.dll		: 3.0.0.8
SFCOM64.dll		: 3.0.0.8

```

Readme.txt
SFComm64.dll : 2.0.0.12
SFDAP064.dll : 2.0.0.12
SFHAP064.dll : 2.0.0.12
SFNHK64.dll : 3.0.0.8
SFProc64.dll : 2.0.0.12
SFSAP064.dll : 2.0.0.12
slcshp64.dll : 1.0.3.0
slgeq64.dll : 1.0.1.0
slh36064.dll : 1.0.2.0
slInit64.dll : 1.1.3.0
slmaxv64.dll : 1.1.2.0
sltshd64.dll : 1.2.0.0
sluapo64.dll : 1.8.34.0
SRSHP64.dll : 1.1.0.0
SRSTSH64.dll : 1.1.4.0
SRSTX64.dll : 3.2.0.0
SRSW064.dll : 1.1.3.0
WavesGUILib.dll : 1.0.0.0
HDM Driver : -----
Vista/Win7 x86:
RtHDMV.sys : 6.0.1.6121
RtkAudioSrvATI.exe : 1.0.0.23
RtkUpd.exe : 2.8.0.3
RH3DAA32.dll : 6.0.6001.18
RH3DHT32.dll : 6.0.6001.18
RHCoInst.dll : 1.0.8.6
RHDMExt.dll : 6.0.6000.127
RTEED32H.dll : 6.1.6001.33
RTEEG32H.dll : 6.1.6001.33
RTEEL32H.dll : 6.1.6001.33
RTEEP32H.dll : 6.1.6001.33
RtkHDM.dll : 11.0.6000.151

Vista/Win7 x64:
RtHDMVX.sys : 6.0.1.6121
RtkAudioSrvATI64.exe : 1.0.0.23
RtkUpd64.exe : 2.8.0.3
RH3DAA64.dll : 6.0.6001.18
RH3DHT64.dll : 6.0.6001.18
RHCoInst64.dll : 1.0.8.6
RHDMEx64.dll : 6.0.6000.127
RTEED64H.dll : 6.1.6001.33
RTEEG64H.dll : 6.1.6001.33
RTEEL64H.dll : 6.1.6001.33
RTEEP64H.dll : 6.1.6001.33
RtkHDM64.dll : 11.0.6000.151

XP/2K x86:
RtkHDM.sys : 5.10.0.6121
Rtaupd.exe : 2.8.0.3
RHCoInstXP.dll : 1.0.8.6

XP/2K x64:
RtkHDMX.sys : 5.10.0.6121
Rtaupd64.exe : 2.8.0.3
RHCoInst64XP.dll : 1.0.8.6

Driver Setup Program : 3.01

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

```

//=====

Driver Package R2.49

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC892, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275,



Readme.txt

ALC680

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC892, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft WindowsXP, Windows2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 - x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :

RTKHDA64.sys	: 5.10.0.6132
RTKHDAUD.sys	: 5.10.0.6132
McCal.exe	: 1.1.2.4
RTHDCPL.exe	: 2.3.5.5
RtkAudioService64.exe	: 1.0.0.19
RtkAudioService.exe	: 1.0.0.19
RTLCPPL.exe	: 1.0.1.66
RtlUpd64.exe	: 2.8.0.3
RtlUpd.exe	: 2.8.0.3
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.32
vncutil64.exe	: 1.0.0.38
vncutil.exe	: 1.0.0.38
Alcmtr.exe	: 1.6.0.4
AlcWzrd.exe	: 1.1.0.37
Mnflt.sys	: 5.10.0.4112
Mnft64.sys	: 5.10.0.4115
OA017Afx.sys	: 1.0.7.3
AMBFlt.sys	: 5.10.0.4240
AMBft64.sys	: 5.10.0.4240
RTSndMgr.cpl	: 1.0.1.5
ALSndMgr.cpl	: 1.0.0.11
RCoInst64XP.dll	: 1.0.9.2
RTCOMDLL.dll	: 1.0.0.108
RtkCoInstXP.dll	: 1.0.9.2
RtlCPAPI.dll	: 1.0.2.3

Vista/Wn7 driver : -----

Vista/Wn7 driver for x86

RTKVHDA.sys	: 6.0.1.6132
AERTSrv.exe	: 1.0.32.10
RtHDVBg.exe	: 1.0.0.26
RtHDVCpl.exe	: 1.0.0.530
RtkAudioService.exe	: 1.0.0.24
RtkNGUI.exe	: 1.0.0.48
RtlUpd.exe	: 2.8.0.3
SkyTel.exe	: 2.0.2.2
vncutil.exe	: 1.0.0.38
mbflt32.sys	: 6.10.0.8
RTSndMgr.cpl	: 1.0.0.19
AERTACap.dll	: 2.0.32.11
AERTARen.dll	: 1.0.32.9
BlackSkinImages.dll	: 1.0.0.48
DarkSkinImages.dll	: 1.0.0.48
DTSBassEnhancementDLL.dll	: 1.0.0.1
DTSBoostDLL.dll	: 1.0.0.1
DTSGainCompensatorDLL.dll	: 1.0.0.1
DTSAFXAP0.dll	: 1.0.0.1
DTSAFXAPONS.dll	: 1.0.0.1
DTSLFXAP0.dll	: 1.0.0.1
DTSLimitDLL.dll	: 1.0.0.1
DTSNeoPCDLL.dll	: 1.0.0.1
DTSS2HeadphoneDLL.dll	: 1.0.0.1
DTSS2SpeakerDLL.dll	: 1.0.0.1
DTSSymmetryDLL.dll	: 1.0.0.1
DTSVoiceClarityDLL.dll	: 1.0.0.1

	Readme.txt	: 42.5.32.66
FMAP0.dll		: 1.0.0.48
LightSkinImages.dll		: 1.2.2.0
MaxxAudioAPO.dll		: 2.2.8.0
MaxxAudioAPO20.dll		: 3.1.0.0
MaxxAudioAPO30.dll		: 5.9.7.0
MaxxAudioEQ.dll		: 1.0.0.0
MaxxAudioRealtek.dll		: 3.1.0.0
MaxxVolumeSDAPO.dll		: 1.0.19.0
MBAP032.dll		: 1.0.0.110
MBPPCn32.dll		: 1.0.22.0
MBppld32.dll		: 1.0.15.112
MBTHX32.dll		: 1.0.0.160
MBWrp32.dll		: 6.0.6001.18
RP3DAA32.dll		: 6.0.6001.18
RP3DHT32.dll		: 2.0.0.134
RTCOMDLL.dll		: 6.1.6001.33
RTEED32A.dll		: 6.1.6001.33
RTEEG32A.dll		: 6.1.6001.33
RTEEL32A.dll		: 6.1.6001.33
RTEEP32A.dll		: 11.0.6000.152
RtkAPO.dll		: 1.0.0.21
RtkApoApi.dll		: 1.0.0.2
RtkCfg.dll		: 1.0.9.2
RtkCoInst.dll		: 6.0.6000.130
RtkPgExt.dll		: 1.0.2.4
RtlCPAPI.dll		: 2.0.0.12
SFFXComm.dll		: 2.0.0.12
SFFXDAP0.dll		: 2.0.0.12
SFFXHAP0.dll		: 2.0.0.12
SFFXProc.dll		: 2.0.0.12
SFFXSAP0.dll		: 2.0.0.12
slcshp32.dll		: 1.0.3.0
slgeq32.dll		: 1.0.1.0
slh36032.dll		: 1.0.2.0
slinit32.dll		: 1.1.3.0
slmaxv32.dll		: 1.1.2.0
sltshd32.dll		: 1.2.0.0
sluapo32.dll		: 1.8.34.0
SRSHP360.dll		: 1.1.0.0
SRSTSHD.dll		: 1.1.4.0
SRSTSXT.dll		: 3.2.0.0
SRSWOW.dll		: 1.1.3.0
WavesGUILib.dll		: 1.0.0.0
WavesLib.dll		: 5.9.7.0
Vista/Win7 driver for x64		
RTKVHD64.sys		: 6.0.1.6132
AERTSr64.exe		: 1.0.64.10
RAVBg64.exe		: 1.0.0.26
RAVCpl64.exe		: 1.0.0.530
RtkAudioService64.exe		: 1.0.0.24
RtkNGUI64.exe		: 1.0.0.48
RtlUpd64.exe		: 2.8.0.3
SkyTel.exe		: 2.0.2.2
vncutil64.exe		: 1.0.0.38
GWfilt64.sys		: 6.10.0.3
mbfilt64.sys		: 6.10.0.8
RTSnMg64.cpl		: 1.0.0.19
AERTAC64.dll		: 2.0.64.11
AERTAR64.dll		: 1.0.64.9
BlackSkinImages64.dll		: 1.0.0.48
DarkSkinImages64.dll		: 1.0.0.48
DTSBassEnhancementDLL64.dll		: 1.0.0.1
DTSBoostDLL64.dll		: 1.0.0.1
DTSGainCompensatorDLL64.dll		: 1.0.0.1
DTSGFXAP064.dll		: 1.0.0.1
DTSGFXAPONS64.dll		: 1.0.0.1
DTSLFXAP064.dll		: 1.0.0.1
DTSLimiterDLL64.dll		: 1.0.0.1
DTSNeoPCDLL64.dll		: 1.0.0.1

Readme.txt

DTSS2HeadphoneDLL64.dll	: 1.0.0.1
DTSS2SpeakerDLL64.dll	: 1.0.0.1
DTSSymmetryDLL64.dll	: 1.0.0.1
DTSVoiceClarityDLL64.dll	: 1.0.0.1
FMAP064.dll	: 42.6.32.66
LightSkinImages64.dll	: 1.0.0.48
MaxxAudioAPO20.dll	: 2.2.8.0
MaxxAudioAPO30.dll	: 3.1.0.0
MaxxAudioEQ.dll	: 5.9.7.0
MaxxAudioRealtek.dll	: 1.0.0.0
MaxxVolumeSDAPO.dll	: 3.1.0.0
MBAP032.dll	: 1.0.19.0
MBAP064.dll	: 1.0.19.0
MBPPCn64.dll	: 1.0.0.110
MBppld64.dll	: 1.0.22.0
MBTHX32.dll	: 1.0.15.112
MBTHX64.dll	: 1.0.15.112
MBWrp64.dll	: 1.0.0.160
RCoInst64.dll	: 1.0.9.2
RP3DAA64.dll	: 6.0.6001.18
RP3DHT64.dll	: 6.0.6001.18
RtCOMB4.dll	: 2.0.0.134
RTCOMDLL.dll	: 2.0.0.134
RTEED64A.dll	: 6.1.6001.33
RTEEG64A.dll	: 6.1.6001.33
RTEEL64A.dll	: 6.1.6001.33
RTEEP64A.dll	: 6.1.6001.33
RtkApi64.dll	: 1.0.0.21
RtkAPO64.dll	: 11.0.6000.152
RtkCfg.dll	: 1.0.0.1
RtkCfg64.dll	: 1.0.0.2
RtLCPAPI.dll	: 1.0.2.4
RtLCPAPI64.dll	: 1.0.2.4
RtPgEx64.dll	: 6.0.6000.130
SFComm64.dll	: 2.0.0.12
SFDAPO64.dll	: 2.0.0.12
SFHAP064.dll	: 2.0.0.12
SFProc64.dll	: 2.0.0.12
SFSAP064.dll	: 2.0.0.12
slcshp64.dll	: 1.0.3.0
slgeq64.dll	: 1.0.1.0
slh36064.dll	: 1.0.2.0
slInit64.dll	: 1.1.3.0
slmaxv64.dll	: 1.1.2.0
sltshd64.dll	: 1.2.0.0
sluapo64.dll	: 1.8.34.0
SRSHP64.dll	: 1.1.0.0
SRSTSH64.dll	: 1.1.4.0
SRSTX64.dll	: 3.2.0.0
SRSWOW64.dll	: 1.1.3.0
WavesGUILib.dll	: 1.0.0.0
<b>HDMI Driver : -----</b>	
Vista/Win7 x86:	
RtHDMV.sys	: 6.0.1.6121
RtkAudioSrvATI.exe	: 1.0.0.23
RtkUpd.exe	: 2.8.0.3
RH3DAA32.dll	: 6.0.6001.18
RH3DHT32.dll	: 6.0.6001.18
RHCoInst.dll	: 1.0.8.6
RHDMExt.dll	: 6.0.6000.127
RTEED32H.dll	: 6.1.6001.33
RTEEG32H.dll	: 6.1.6001.33
RTEEL32H.dll	: 6.1.6001.33
RTEEP32H.dll	: 6.1.6001.33
RtkHDM.dll	: 11.0.6000.151
Vista/Win7 x64:	
RtHDMVX.sys	: 6.0.1.6121
RtkAudioSrvATI64.exe	: 1.0.0.23

Readme.txt

RtkUpd64.exe : 2.8.0.3  
RH3DAA64.dll : 6.0.6001.18  
RH3DHT64.dll : 6.0.6001.18  
RHCoInst64.dll : 1.0.8.6  
RHDME64.dll : 6.0.6000.127  
RTEED64H.dll : 6.1.6001.33  
RTEEG64H.dll : 6.1.6001.33  
RTEEL64H.dll : 6.1.6001.33  
RTEEP64H.dll : 6.1.6001.33  
RtkHDM64.dll : 11.0.6000.151

XP/2K x86:  
RtkHDM.sys : 5.10.0.6121  
Rtaupd.exe : 2.8.0.3  
RHCoInstXP.dll : 1.0.8.6

XP/2K x64:  
RtkHDMX.sys : 5.10.0.6121  
Rtaupd64.exe : 2.8.0.3  
RHCoInst64XP.dll : 1.0.8.6

Driver Setup Program : 2.99

Windows 2000/XP Operate on :  
Microsoft High Definition Audio Driver Package - KB888111  
Package file version (kb888111.exe) : 6.1.22.0  
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.48

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC892, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC892, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680

3. HDM Device WHQL Support: ATI HDM Devices

4. OS Supporting: Microsoft WindowsXP, Windows2000, Windows Server 2003, Vista, Windows Server 2008,

Windows7 - x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :  
RTKHDA64.sys : 5.10.0.6101  
RTKHDAUD.sys : 5.10.0.6101  
Alcmtr.exe : 1.6.0.4  
AlcWzrd.exe : 1.1.0.37  
MicCal.exe : 1.1.2.3  
RTHDCPL.exe : 2.3.4.9  
RtkAudioService.exe : 1.0.0.19  
RtkAudioService64.exe : 1.0.0.19  
RTLCPPL.exe : 1.0.1.66  
RtlUpd.exe : 2.8.0.3  
RtlUpd64.exe : 2.8.0.3  
SkyTel.exe : 2.0.2.0  
SoundMan.exe : 1.0.0.32  
vncutil.exe : 1.0.0.38  
vncutil64.exe : 1.0.0.38  
AMBfilt.sys : 5.10.0.4240  
AMBft64.sys : 5.10.0.4240  
Mnft64.sys : 5.10.0.4112  
Mnft64.sys : 5.10.0.4115  
OA017Afx.sys : 1.0.7.3  
ALSndMgr.cpl : 1.0.0.11  
RTSndMgr.cpl : 1.0.1.4

Readme.txt

```

RCoInst64XP.dll : 1.0.8.6
RTCOMDLL.dll : 1.0.0.107
RtkCoInstXP.dll : 1.0.8.6
RtlCPAPI.dll : 1.0.2.3
Vista/Win7 driver : -----
Vista/Win7 driver for x86
RTKVHDA.sys : 6.0.1.6101
AERTSrv.exe : 1.0.32.10
RtHDVBg.exe : 1.0.0.18
RtHDVCpl.exe : 1.0.0.513
RtkAudioService.exe : 1.0.0.24
RtkNGUI.exe : 1.0.0.39
RtlUpd.exe : 2.8.0.3
SkyTel.exe : 2.0.2.2
vncutil.exe : 1.0.0.38
mbfilt32.sys : 6.10.0.8
RTSndMgr.cpl : 1.0.0.18
AERTACap.dll : 2.0.32.11
AERTARen.dll : 1.0.32.9
BlackSkinImages.dll : 1.0.0.39
DarkSkinImages.dll : 1.0.0.39
DTSBassEnhancementDLL.dll : 1.0.0.1
DTSBoostDLL.dll : 1.0.0.1
DTSGainCompensatorDLL.dll : 1.0.0.1
DTSGFXAPO.dll : 1.0.0.1
DTSGFXAPONS.dll : 1.0.0.1
DTSLFXAPO.dll : 1.0.0.1
DTSLimiterDLL.dll : 1.0.0.1
DTSNeoPCDLL.dll : 1.0.0.1
DTSS2HeadphoneDLL.dll : 1.0.0.1
DTSS2SpeakerDLL.dll : 1.0.0.1
DTSSymmetryDLL.dll : 1.0.0.1
DTSVoiceClarityDLL.dll : 1.0.0.1
FMAPO.dll : 42.5.32.66
LightSkinImages.dll : 1.0.0.39
MaxxAudioAPO.dll : 1.2.2.0
MaxxAudioAPO20.dll : 2.2.8.0
MaxxAudioAPO30.dll : 3.1.0.0
MaxxAudioEQ.dll : 5.9.7.0
MaxxAudioRealtek.dll : 1.0.0.0
MaxxVolumeSDAPO.dll : 3.1.0.0
MBAPO32.dll : 1.0.19.0
MBPPCn32.dll : 1.0.0.110
MBpld32.dll : 1.0.22.0
MBTHX32.dll : 1.0.15.110
MBWrp32.dll : 1.0.0.110
RP3DAA32.dll : 6.0.6001.18
RP3DHT32.dll : 6.0.6001.18
RTCOMDLL.dll : 2.0.0.130
RTEED32A.dll : 6.1.6001.33
RTEEG32A.dll : 6.1.6001.33
RTEEL32A.dll : 6.1.6001.33
RTEEP32A.dll : 6.1.6001.33
RtkAPO.dll : 11.0.6000.149
RtkApoApi.dll : 1.0.0.21
RtkCfg.dll : 1.0.0.2
RtkColnst.dll : 1.0.8.7
RtkPgExt.dll : 6.0.6000.122
RtlCPAPI.dll : 1.0.2.4
SFFXComm.dll : 2.0.0.12
SFFXDAP0.dll : 2.0.0.12
SFFXHAP0.dll : 2.0.0.12
SFFXProc.dll : 2.0.0.12
SFFXSAP0.dll : 2.0.0.12
slcshp32.dll : 1.0.3.0
slgeq32.dll : 1.0.1.0
slh36032.dll : 1.0.2.0
slinit32.dll : 1.1.3.0
slmaxv32.dll : 1.1.2.0

```

	Readme.txt
sltshd32.dll	: 1.1.1.0
sluapo32.dll	: 1.8.24.0
SRSHP360.dll	: 1.1.0.0
SRSTSHD.dll	: 1.1.4.0
SRSTSXT.dll	: 3.2.0.0
SRSWOW.dll	: 1.1.3.0
WavesGUILib.dll	: 1.0.0.0
WavesLib.dll	: 5.9.7.0
Vista/Win7 driver for x64	
RTKVHD64.sys	: 6.0.1.6101
AERTSr64.exe	: 1.0.64.10
RAVBg64.exe	: 1.0.0.18
RAVCpl64.exe	: 1.0.0.513
RtkAudioService64.exe	: 1.0.0.24
RtkNGUI64.exe	: 1.0.0.39
RtlUpd64.exe	: 2.8.0.3
SkyTel.exe	: 2.0.2.2
vncutil64.exe	: 1.0.0.38
GWfilt64.sys	: 6.10.0.3
mbfilt64.sys	: 6.10.0.8
RTSnMg64.cpl	: 1.0.0.18
AERTAC64.dll	: 2.0.64.11
AERTAR64.dll	: 1.0.64.9
BlackSkinImages64.dll	: 1.0.0.39
DarkSkinImages64.dll	: 1.0.0.39
DTSBassEnhancementDLL64.dll	: 1.0.0.1
DTSBoostDLL64.dll	: 1.0.0.1
DTSGainCompensatorDLL64.dll	: 1.0.0.1
DTSAFXAP064.dll	: 1.0.0.1
DTSAFXAPONS64.dll	: 1.0.0.1
DTSAFXAP064.dll	: 1.0.0.1
DTSLimitDLL64.dll	: 1.0.0.1
DTSNeoPCDLL64.dll	: 1.0.0.1
DTSS2HeadphoneDLL64.dll	: 1.0.0.1
DTSS2SpeakerDLL64.dll	: 1.0.0.1
DTSSymmetryDLL64.dll	: 1.0.0.1
DTSVoiceClarityDLL64.dll	: 1.0.0.1
FMAP064.dll	: 42.6.32.66
LightSkinImages64.dll	: 1.0.0.39
MaxxAudioAP020.dll	: 2.2.8.0
MaxxAudioAP030.dll	: 3.1.0.0
MaxxAudioEQ.dll	: 5.9.7.0
MaxxAudioRealtek.dll	: 1.0.0.0
MaxxVolumeSDAPO.dll	: 3.1.0.0
MBAP032.dll	: 1.0.19.0
MBAP064.dll	: 1.0.19.0
MBPPCn64.dll	: 1.0.0.110
MBpld64.dll	: 1.0.22.0
MBTHX32.dll	: 1.0.15.110
MBTHX64.dll	: 1.0.15.110
MBWrp64.dll	: 1.0.0.110
RCoInst64.dll	: 1.0.8.7
RP3DAA64.dll	: 6.0.6001.18
RP3DHT64.dll	: 6.0.6001.18
RtCOM64.dll	: 2.0.0.130
RTCOMDLL.dll	: 2.0.0.130
RTEED64A.dll	: 6.1.6001.33
RTEEG64A.dll	: 6.1.6001.33
RTEEL64A.dll	: 6.1.6001.33
RTEEP64A.dll	: 6.1.6001.33
RtkApi64.dll	: 1.0.0.21
RtkAPO64.dll	: 11.0.6000.149
RtkCfg.dll	: 1.0.0.1
RtkCfg64.dll	: 1.0.0.2
RtlCPAPI.dll	: 1.0.2.4
RtlCPAPI64.dll	: 1.0.2.4
RtPgEx64.dll	: 6.0.6000.122
SFComm64.dll	: 2.0.0.12
SFDAP064.dll	: 2.0.0.12

Readme.txt

```

SFHAP064.dll : 2.0.0.12
SFProc64.dll : 2.0.0.12
SFSAP064.dll : 2.0.0.12
slcshp64.dll : 1.0.3.0
slgeq64.dll : 1.0.1.0
slh36064.dll : 1.0.2.0
slinit64.dll : 1.1.3.0
slmaxv64.dll : 1.1.2.0
sltshd64.dll : 1.1.1.0
sluapo64.dll : 1.8.24.0
SRSHP64.dll : 1.1.0.0
SRSTSH64.dll : 1.1.4.0
SRSTX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
WavesGUILib.dll : 1.0.0.0
HDM Driver : -----
Vista/Win7 x86:
RtHDMV.sys : 6.0.1.6034
RtkAudioSrvATI.exe : 1.0.0.23
RtkUpd.exe : 2.8.0.1
RH3DAA32.dll : 6.0.6001.18
RH3DHT32.dll : 6.0.6001.18
RHCoInst.dll : 1.0.8.2
RHDMEExt.dll : 6.0.6000.113
RTEED32H.dll : 6.1.6001.33
RTEEG32H.dll : 6.1.6001.33
RTEEL32H.dll : 6.1.6001.33
RTEEP32H.dll : 6.1.6001.33
RtkHDM.dll : 11.0.6000.132

Vista/Win7 x64:
RtHDMVX.sys : 6.0.1.6034
RtkAudioSrvATI64.exe : 1.0.0.23
RtkUpd64.exe : 2.8.0.1
RH3DAA64.dll : 6.0.6001.18
RH3DHT64.dll : 6.0.6001.18
RHCoInst64.dll : 1.0.8.2
RHDME64.dll : 6.0.6000.113
RTEED64H.dll : 6.1.6001.33
RTEEG64H.dll : 6.1.6001.33
RTEEL64H.dll : 6.1.6001.33
RTEEP64H.dll : 6.1.6001.33
RtkHDM64.dll : 11.0.6000.132

XP/2K x86:
RtkHDM.sys : 5.10.0.6034
Rtaupd.exe : 2.8.0.1
RHCoInstXP.dll : 1.0.8.2

XP/2K x64:
RtkHDMX.sys : 5.10.0.6034
Rtaupd64.exe : 2.8.0.1
RHCoInst64XP.dll : 1.0.8.2

Driver Setup Program : 2.99

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

```

//=====
Driver Package R2.47

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC892, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC892, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273,

Readme.txt

ALC887, ALC670, ALC275, ALC680

3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 - x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :

RTKHDA64.sys	: 5.10.0.6083
RTKHDAUD.sys	: 5.10.0.6083
MicCal.exe	: 1.1.2.3
RTHDCPL.exe	: 2.3.4.7
RtkAudioService64.exe	: 1.0.0.19
RtkAudioService.exe	: 1.0.0.19
RTLCPPL.exe	: 1.0.1.66
RtlUpd64.exe	: 2.8.0.1
RtlUpd.exe	: 2.8.0.1
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.32
vncutil64.exe	: 1.0.0.38
vncutil.exe	: 1.0.0.38
Alcmtr.exe	: 1.6.0.4
AlcWzrd.exe	: 1.1.0.37
AMBFilt.sys	: 5.10.0.4240
AMBFt64.sys	: 5.10.0.4240
Mnft64.sys	: 5.10.0.4112
Mnft64.sys	: 5.10.0.4115
OA017Afx.sys	: 1.0.7.3
RTSndMgr.cpl	: 1.0.1.4
ALSndMgr.cpl	: 1.0.0.11
RCoInst64XP.dll	: 1.0.8.6
RTCOMDLL.dll	: 1.0.0.107
RtkCoInstXP.dll	: 1.0.8.6
RtlCPAPI.dll	: 1.0.2.3

Vista/Win7 driver : -----

Vista/Win7 driver for x86

RTKVHDA.sys	: 6.0.1.6083
AERTSrv.exe	: 1.0.32.10
RtHDVBg.exe	: 1.0.0.13
RtHDVCpl.exe	: 1.0.0.504
RtkAudioService.exe	: 1.0.0.24
RtkNGUI.exe	: 1.0.0.38
RtlUpd.exe	: 2.8.0.1
SkyTel.exe	: 2.0.2.2
vncutil.exe	: 1.0.0.38
mbfilt32.sys	: 6.10.0.8
RTSndMgr.cpl	: 1.0.0.18
AERTACap.dll	: 2.0.32.11
AERTARen.dll	: 1.0.32.9
BlackSkinImages.dll	: 1.0.0.38
DarkSkinImages.dll	: 1.0.0.38
DTSBassEnhancementDLL.dll	: 1.0.0.1
DTSBoostDLL.dll	: 1.0.0.1
DTSGainCompensatorDLL.dll	: 1.0.0.1
DTSAFXAPO.dll	: 1.0.0.1
DTSAFXAPONS.dll	: 1.0.0.1
DTSLFXAPO.dll	: 1.0.0.1
DTSLimitDLL.dll	: 1.0.0.1
DTSNeoPCDLL.dll	: 1.0.0.1
DTSS2HeadphoneDLL.dll	: 1.0.0.1
DTSS2SpeakerDLL.dll	: 1.0.0.1
DTSSymmetryDLL.dll	: 1.0.0.1
DTSVoiceClarityDLL.dll	: 1.0.0.1
FMAP0.dll	: 42.5.30.65
LightSkinImages.dll	: 1.0.0.38
MaxxAudioAPO.dll	: 1.2.2.0



MaxxAudioAP020.dll	: 2.2.6.0
MaxxAudioEQ.dll	: 5.9.7.0
MBAP032.dll	: 1.0.19.0
MBPPCn32.dll	: 1.0.0.110
Mbpld32.dll	: 1.0.22.0
MBTHX32.dll	: 1.0.15.108
MWrp32.dll	: 1.0.0.110
RP3DAA32.dll	: 6.0.6001.18
RP3DHT32.dll	: 6.0.6001.18
RTCOMDLL.dll	: 2.0.0.130
RTEED32A.dll	: 6.1.6001.33
RTEEG32A.dll	: 6.1.6001.33
RTEEL32A.dll	: 6.1.6001.33
RTEEP32A.dll	: 6.1.6001.33
RtkAPO.dll	: 11.0.6000.145
RtkApoApi.dll	: 1.0.0.21
RtkCfg.dll	: 1.0.0.2
RtkCoInst.dll	: 1.0.8.6
RtkPgExt.dll	: 6.0.6000.120
RtlCPAPI.dll	: 1.0.2.4
SFFXComm.dll	: 2.0.0.12
SFFXDAP0.dll	: 2.0.0.12
SFFXHAP0.dll	: 2.0.0.12
SFFXProc.dll	: 2.0.0.12
SFFXSAP0.dll	: 2.0.0.12
slcshp32.dll	: 1.0.3.0
slgeq32.dll	: 1.0.1.0
slh36032.dll	: 1.0.2.0
slInit32.dll	: 1.1.3.0
slmaxv32.dll	: 1.1.2.0
sltshd32.dll	: 1.1.1.0
sluapo32.dll	: 1.8.24.0
SRSHP360.dll	: 1.1.0.0
SRSTSHD.dll	: 1.1.4.0
SRSTSXT.dll	: 3.2.0.0
Vista/Win7 driver for x64	
RTKVHD64.sys	: 6.0.1.6083
AERTSr64.exe	: 1.0.64.10
RAVBg64.exe	: 1.0.0.13
RAVCpl64.exe	: 1.0.0.504
RtkAudioService64.exe	: 1.0.0.24
RtkNGUI64.exe	: 1.0.0.38
RtlUpd64.exe	: 2.8.0.1
SkyTel.exe	: 2.0.2.2
vncutil64.exe	: 1.0.0.38
GWfilt64.sys	: 6.10.0.3
mbfilt64.sys	: 6.10.0.8
RTSnMg64.cpl	: 1.0.0.18
AERTAC64.dll	: 2.0.64.11
AERTAR64.dll	: 1.0.64.9
BlackSkinImages64.dll	: 1.0.0.38
DarkSkinImages64.dll	: 1.0.0.38
DTSBassEnhancementDLL64.dll	: 1.0.0.1
DTSBoostDLL64.dll	: 1.0.0.1
DTSGainCompensatorDLL64.dll	: 1.0.0.1
DTSAFXAP064.dll	: 1.0.0.1
DTSAFXAPONS64.dll	: 1.0.0.1
DTSLFXAP064.dll	: 1.0.0.1
DTSLimitDLL64.dll	: 1.0.0.1
DTSNeoPCDLL64.dll	: 1.0.0.1
DTSS2HeadphoneDLL64.dll	: 1.0.0.1
DTSS2SpeakerDLL64.dll	: 1.0.0.1
DTSSymmetryDLL64.dll	: 1.0.0.1
DTSVoiceClarityDLL64.dll	: 1.0.0.1
FMAP064.dll	: 42.6.30.65
LightSkinImages64.dll	: 1.0.0.38
MaxxAudioAP020.dll	: 2.2.7.0
MaxxAudioEQ.dll	: 5.9.7.0
MBAP032.dll	: 1.0.19.0

Readme.txt

MBAP064. dll	: 1. 0. 19. 0
MBPPCn64. dll	: 1. 0. 0. 110
Mbpld64. dll	: 1. 0. 22. 0
MBTHX32. dll	: 1. 0. 15. 108
MBTHX64. dll	: 1. 0. 15. 108
MBWrp64. dll	: 1. 0. 0. 110
RCoInst64. dll	: 1. 0. 8. 6
RP3DAA64. dll	: 6. 0. 6001. 18
RP3DHT64. dll	: 6. 0. 6001. 18
RtCOMB4. dll	: 2. 0. 0. 130
RTCOMDLL. dll	: 2. 0. 0. 130
RTEED64A. dll	: 6. 1. 6001. 33
RTEEG64A. dll	: 6. 1. 6001. 33
RTEEL64A. dll	: 6. 1. 6001. 33
RTEEP64A. dll	: 6. 1. 6001. 33
RtkApi 64. dll	: 1. 0. 0. 21
RtkAP064. dll	: 11. 0. 6000. 145
RtkCfg. dll	: 1. 0. 0. 1
RtkCfg64. dll	: 1. 0. 0. 2
RtLCPAPI. dll	: 1. 0. 2. 4
RtLCPAPI64. dll	: 1. 0. 2. 4
RtPgEx64. dll	: 6. 0. 6000. 120
SFComm64. dll	: 2. 0. 0. 12
SFDAPO64. dll	: 2. 0. 0. 12
SFHAP064. dll	: 2. 0. 0. 12
SFProc64. dll	: 2. 0. 0. 12
SFSAP064. dll	: 2. 0. 0. 12
slcshp64. dll	: 1. 0. 3. 0
slgeq64. dll	: 1. 0. 1. 0
slh36064. dll	: 1. 0. 2. 0
slInit64. dll	: 1. 1. 3. 0
slmaxv64. dll	: 1. 1. 2. 0
sltshd64. dll	: 1. 1. 1. 0
sluapo64. dll	: 1. 8. 24. 0
SRSHP64. dll	: 1. 1. 0. 0
SRSTSH64. dll	: 1. 1. 4. 0
SRSTX64. dll	: 3. 2. 0. 0
SRSWOW64. dll	: 1. 1. 3. 0
WavesGUILib. dll	: 1. 2. 3. 4
<b>HDM Driver : -----</b>	
Vista/Win7 x86:	
RtHDMV. sys	: 6. 0. 1. 6034
RtkAudioSrvATI. exe	: 1. 0. 0. 23
RtkUpd. exe	: 2. 8. 0. 1
RH3DAA32. dll	: 6. 0. 6001. 18
RH3DHT32. dll	: 6. 0. 6001. 18
RHCoInst. dll	: 1. 0. 8. 2
RHDMExt. dll	: 6. 0. 6000. 113
RTEED32H. dll	: 6. 1. 6001. 33
RTEEG32H. dll	: 6. 1. 6001. 33
RTEEL32H. dll	: 6. 1. 6001. 33
RTEEP32H. dll	: 6. 1. 6001. 33
RtkHDM. dll	: 11. 0. 6000. 132
Vista/Win7 x64:	
RtHDMVX. sys	: 6. 0. 1. 6034
RtkAudioSrvATI64. exe	: 1. 0. 0. 23
RtkUpd64. exe	: 2. 8. 0. 1
RH3DAA64. dll	: 6. 0. 6001. 18
RH3DHT64. dll	: 6. 0. 6001. 18
RHCoInst64. dll	: 1. 0. 8. 2
RHDMEx64. dll	: 6. 0. 6000. 113
RTEED64H. dll	: 6. 1. 6001. 33
RTEEG64H. dll	: 6. 1. 6001. 33
RTEEL64H. dll	: 6. 1. 6001. 33
RTEEP64H. dll	: 6. 1. 6001. 33
RtkHDM64. dll	: 11. 0. 6000. 132
XP/2K x86:	

```

Readme.txt
RtkHDM.sys : 5.10.0.6034
Rtaupd.exe : 2.8.0.1
RHCoInstXP.dll : 1.0.8.2

XP/2K x64:
RtkHDMX.sys : 5.10.0.6034
Rtaupd64.exe : 2.8.0.1
RHCoInst64XP.dll : 1.0.8.2

Driver Setup Program : 2.97

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

```

//=====

Driver Package R2.46

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC892, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC892, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 - x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
  - 1.) Driver :
    1. Customizations.
    2. Fix BSOD issue under Windows 2000. (Issue happened from driver V6066).

Windows 2000/XP : -----

```

Windows 2000/XP :
RTKHDA64.sys : 5.10.0.6077
RTKHDAUD.sys : 5.10.0.6077
Alcmtr.exe : 1.6.0.4
AlcWzrd.exe : 1.1.0.37
McCal.exe : 1.1.2.3
RTHDCPL.exe : 2.3.4.6
RtkAudioService.exe : 1.0.0.19
RtkAudioService64.exe : 1.0.0.19
RTLCPPL.exe : 1.0.1.66
RtlUpd.exe : 2.8.0.1
RtlUpd64.exe : 2.8.0.1
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.32
vncutil.exe : 1.0.0.38
vncutil64.exe : 1.0.0.38
AMBfilt.sys : 5.10.0.4240
AMBft64.sys : 5.10.0.4240
Mnft64.sys : 5.10.0.4112
Mnft64.sys : 5.10.0.4115
OA017Afx.sys : 1.0.7.3
ALSndMgr.cpl : 1.0.0.11
RTSndMgr.cpl : 1.0.1.4
RCoInst64XP.dll : 1.0.8.6
RTCOMDLL.dll : 1.0.0.107
RtkCoInstXP.dll : 1.0.8.6
RtlCPAPI.dll : 1.0.2.3

```

Vista/Win7 driver : -----

```

Vista/Win7 driver for x86
RTKVHDA.sys : 6.0.1.6077
AERTSrv.exe : 1.0.32.10
RtHDVBg.exe : 1.0.0.9
RtHDVCpl.exe : 1.0.0.501
RtkAudioService.exe : 1.0.0.24

```

	Readme.txt	
RtkNGUI.exe	:	1.0.0.35
RtlUpd.exe	:	2.8.0.1
SkyTel.exe	:	2.0.2.2
vncutil.exe	:	1.0.0.38
mbfilt32.sys	:	6.10.0.8
RTSndMgr.cpl	:	1.0.0.18
AERTACap.dll	:	2.0.32.11
AERTARen.dll	:	1.0.32.9
BlackSkinImages.dll	:	1.0.0.35
DarkSkinImages.dll	:	1.0.0.35
DTSBassEnhancementDLL.dll	:	1.0.0.1
DTSBassBoostDLL.dll	:	1.0.0.1
DTSGainCompensatorDLL.dll	:	1.0.0.1
DTSGFXAPO.dll	:	1.0.0.1
DTSGFXAPONS.dll	:	1.0.0.1
DTSLFXAPO.dll	:	1.0.0.1
DTSLimiterDLL.dll	:	1.0.0.1
DTSSNeoPCDLL.dll	:	1.0.0.1
DTSS2HeadphoneDLL.dll	:	1.0.0.1
DTSS2SpeakerDLL.dll	:	1.0.0.1
DTSSymmetryDLL.dll	:	1.0.0.1
DTSSVoiceClarityDLL.dll	:	1.0.0.1
FMAP0.dll	:	42.5.29.67
LightSkinImages.dll	:	1.0.0.35
MaxxAudioAPO.dll	:	1.2.2.0
MaxxAudioAPO20.dll	:	2.2.6.0
MaxxAudioEQ.dll	:	5.9.7.0
MBAP032.dll	:	1.0.19.0
MBPPCn32.dll	:	1.0.0.110
MBpld32.dll	:	1.0.22.0
MBTHX32.dll	:	1.0.15.108
MBWp32.dll	:	1.0.0.110
RP3DAA32.dll	:	6.0.6001.18
RP3DHT32.dll	:	6.0.6001.18
RTCOMDLL.dll	:	2.0.0.130
RTEED32A.dll	:	6.1.6001.33
RTEEG32A.dll	:	6.1.6001.33
RTEEL32A.dll	:	6.1.6001.33
RTEEP32A.dll	:	6.1.6001.33
RtkAPO.dll	:	11.0.6000.144
RtkApoApi.dll	:	1.0.0.20
RtkCfg.dll	:	1.0.0.2
RtkColInst.dll	:	1.0.8.6
RtkPgExt.dll	:	6.0.6000.119
RtlCPAPI.dll	:	1.0.2.4
SFFXComm.dll	:	2.0.0.12
SFFXDAP0.dll	:	2.0.0.12
SFFXHAP0.dll	:	2.0.0.12
SFFXProc.dll	:	2.0.0.12
SFFXSAP0.dll	:	2.0.0.12
slcshp32.dll	:	1.0.3.0
slgeq32.dll	:	1.0.1.0
slh36032.dll	:	1.0.2.0
slInit32.dll	:	1.1.3.0
slmaxv32.dll	:	1.1.2.0
sltshd32.dll	:	1.1.1.0
sluapo32.dll	:	1.8.24.0
SRSHP360.dll	:	1.1.0.0
SRSTSHD.dll	:	1.1.4.0
SRSTSXT.dll	:	3.2.0.0
SRSWOW.dll	:	1.1.3.0
WavesLib.dll	:	5.9.7.0
Vista/Win7 driver for x64		
RTKVHD64.sys	:	6.0.1.6077
AERTSr64.exe	:	1.0.64.10
RAVBg64.exe	:	1.0.0.9
RAVCpl64.exe	:	1.0.0.501
RtkAudioService64.exe	:	1.0.0.24
RtkNGUI64.exe	:	1.0.0.35

Readme.txt

RtlUpd64.exe	: 2.8.0.1
SkyTel.exe	: 2.0.2.2
vncutil64.exe	: 1.0.0.38
GWfilt64.sys	: 6.10.0.3
mbfilt64.sys	: 6.10.0.8
RTSnMg64.cpl	: 1.0.0.18
AERTAC64.dll	: 2.0.64.11
AERTAR64.dll	: 1.0.64.9
BlackSkinImages64.dll	: 1.0.0.35
DarkSkinImages64.dll	: 1.0.0.35
DTSBassEnhancementDLL64.dll	: 1.0.0.1
DTSBoostDLL64.dll	: 1.0.0.1
DTSGainCompensatorDLL64.dll	: 1.0.0.1
DTS GFXAP064.dll	: 1.0.0.1
DTS GFXAPONS64.dll	: 1.0.0.1
DTS LFXAP064.dll	: 1.0.0.1
DTS LimiterDLL64.dll	: 1.0.0.1
DTS NeoPCDLL64.dll	: 1.0.0.1
DTSS2HeadphoneDLL64.dll	: 1.0.0.1
DTSS2SpeakerDLL64.dll	: 1.0.0.1
DTSSymmetryDLL64.dll	: 1.0.0.1
DTSVoiceClarityDLL64.dll	: 1.0.0.1
FMAP064.dll	: 42.6.29.67
LightSkinImages64.dll	: 1.0.0.35
MaxxAudioAP020.dll	: 2.2.7.0
MaxxAudioEQ.dll	: 5.9.7.0
MBAP032.dll	: 1.0.19.0
MBAP064.dll	: 1.0.19.0
MBPPCn64.dll	: 1.0.0.110
MBpld64.dll	: 1.0.22.0
MBTHX32.dll	: 1.0.15.108
MBTHX64.dll	: 1.0.15.108
MBWrp64.dll	: 1.0.0.110
RCoInst64.dll	: 1.0.8.6
RP3DAA64.dll	: 6.0.6001.18
RP3DHT64.dll	: 6.0.6001.18
RtCOM64.dll	: 2.0.0.130
RTCOMDLL.dll	: 2.0.0.130
RTEED64A.dll	: 6.1.6001.33
RTEEG64A.dll	: 6.1.6001.33
RTEEL64A.dll	: 6.1.6001.33
RTEEP64A.dll	: 6.1.6001.33
RtkApi64.dll	: 1.0.0.20
RtkAP064.dll	: 11.0.6000.144
RtkCfg.dll	: 1.0.0.1
RtkCfg64.dll	: 1.0.0.2
RtlCPAPI.dll	: 1.0.2.4
RtlCPAPI64.dll	: 1.0.2.4
RtPgEx64.dll	: 6.0.6000.119
SFComm64.dll	: 2.0.0.12
SFDAP064.dll	: 2.0.0.12
SFHAP064.dll	: 2.0.0.12
SFProc64.dll	: 2.0.0.12
SFSAP064.dll	: 2.0.0.12
slcshp64.dll	: 1.0.3.0
slgeq64.dll	: 1.0.1.0
slh36064.dll	: 1.0.2.0
slInit64.dll	: 1.1.3.0
slmaxv64.dll	: 1.1.2.0
sltshd64.dll	: 1.1.1.0
sluapo64.dll	: 1.8.24.0
SRSHP64.dll	: 1.1.0.0
SRSTSH64.dll	: 1.1.4.0
SRSTSX64.dll	: 3.2.0.0
SRSW064.dll	: 1.1.3.0
WavesGUILib.dll	: 1.2.3.4
<b>HDMI Driver</b> : -----	
Vista/WIn7 x86:	
RtHDMIV.sys	: 6.0.1.6034

Readme.txt

RtkAudioSrvATI.exe : 1.0.0.23  
RtkUpd.exe : 2.8.0.1  
RH3DAA32.dll : 6.0.6001.18  
RH3DHT32.dll : 6.0.6001.18  
RHCoInst.dll : 1.0.8.2  
RHDMEExt.dll : 6.0.6000.113  
RTEED32H.dll : 6.1.6001.33  
RTEEG32H.dll : 6.1.6001.33  
RTEEL32H.dll : 6.1.6001.33  
RTEEP32H.dll : 6.1.6001.33  
RtkHDM.dll : 11.0.6000.132

Vista/Win7 x64:

RtHDMVX.sys : 6.0.1.6034  
RtkAudioSrvATI64.exe : 1.0.0.23  
RtkUpd64.exe : 2.8.0.1  
RH3DAA64.dll : 6.0.6001.18  
RH3DHT64.dll : 6.0.6001.18  
RHCoInst64.dll : 1.0.8.2  
RHDME64.dll : 6.0.6000.113  
RTEED64H.dll : 6.1.6001.33  
RTEEG64H.dll : 6.1.6001.33  
RTEEL64H.dll : 6.1.6001.33  
RTEEP64H.dll : 6.1.6001.33  
RtkHDM64.dll : 11.0.6000.132

XP/2K x86:

RtkHDM.sys : 5.10.0.6034  
Rtaupd.exe : 2.8.0.1  
RHCoInstXP.dll : 1.0.8.2

XP/2K x64:

RtkHDMX.sys : 5.10.0.6034  
Rtaupd64.exe : 2.8.0.1  
RHCoInst64XP.dll : 1.0.8.2

Driver Setup Program : 2.97

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111  
Package file version (kb888111.exe) : 6.1.22.0  
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.45

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC892, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC892, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft WindowsXP, Windows2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 - x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :

RTKHDA64.sys : 5.10.0.6069  
RTKHDAUD.sys : 5.10.0.6069  
McCal.exe : 1.1.2.3  
RTHDCPL.exe : 2.3.4.2  
RtkAudioService64.exe : 1.0.0.19  
RtkAudioService.exe : 1.0.0.19  
RTLCP.exe : 1.0.1.66

Readme.txt

```

RtlUpd64.exe           : 2.8.0.1
RtlUpd.exe             : 2.8.0.1
SkyTel.exe             : 2.0.2.0
SoundMan.exe          : 1.0.0.32
vncutil64.exe         : 1.0.0.38
vncutil.exe           : 1.0.0.38
Alcmtr.exe            : 1.6.0.4
AlcWzrd.exe           : 1.1.0.37
Mnft64.sys            : 5.10.0.4112
Mnft64.sys            : 5.10.0.4115
OA017Afx.sys          : 1.0.7.3
AMBFilt.sys           : 5.10.0.4240
AMBft64.sys           : 5.10.0.4240
RTSndMgr.cpl          : 1.0.1.4
ALSndMgr.cpl          : 1.0.0.11
RCoInst64XP.dll       : 1.0.8.6
RTCOMDLL.dll         : 1.0.0.107
RtkCoInstXP.dll       : 1.0.8.6
RtlCPAPI.dll          : 1.0.2.3
Vista/Win7 driver : -----
Vista/Win7 driver for x86
RTKVHDA.sys           : 6.0.1.6069
AERTSrv.exe           : 1.0.32.10
RtHDVBg.exe           : 1.0.0.9
RtHDVCpl.exe          : 1.0.0.500
RtkAudioService.exe  : 1.0.0.24
RtkNGUI.exe           : 1.0.0.31
RtlUpd.exe            : 2.8.0.1
SkyTel.exe            : 2.0.2.2
vncutil.exe           : 1.0.0.38
mbfilt32.sys          : 6.10.0.8
RTSndMgr.cpl          : 1.0.0.18
AERTACap.dll          : 2.0.32.11
AERTARen.dll          : 1.0.32.9
BlackSkinImages.dll  : 1.0.0.31
DarkSkinImages.dll   : 1.0.0.31
DTSBassEnhancementDLL.dll : 1.0.0.1
DTSBoostDLL.dll       : 1.0.0.1
DTSGainCompensatorDLL.dll : 1.0.0.1
DTSGFXAPO.dll         : 1.0.0.1
DTSGFXAPONS.dll       : 1.0.0.1
DTSLFXAPO.dll         : 1.0.0.1
DTSLimiterDLL.dll    : 1.0.0.1
DTSNeoPCDLL.dll       : 1.0.0.1
DTSS2HeadphoneDLL.dll : 1.0.0.1
DTSS2SpeakerDLL.dll  : 1.0.0.1
DTSSymmetryDLL.dll   : 1.0.0.1
DTSVoiceClarityDLL.dll : 1.0.0.1
FMAP0.dll             : 42.5.29.67
LightSkinImages.dll  : 1.0.0.31
MaxxAudioAPO.dll      : 1.2.2.0
MaxxAudioAPO20.dll    : 2.2.6.0
MaxxAudioEQ.dll       : 5.9.7.0
MBAP032.dll           : 1.0.19.0
MBPPCn32.dll          : 1.0.0.110
MBpld32.dll           : 1.0.22.0
MBTHX32.dll           : 1.0.15.108
MBWrp32.dll           : 1.0.0.110
RP3DAA32.dll          : 6.0.6001.18
RP3DHT32.dll          : 6.0.6001.18
RTCOMDLL.dll         : 2.0.0.129
RTEED32A.dll          : 6.1.6001.33
RTEEG32A.dll          : 6.1.6001.33
RTEEL32A.dll          : 6.1.6001.33
RTEEP32A.dll          : 6.1.6001.33
RtkAPO.dll            : 11.0.6000.144
RtkApoApi.dll         : 1.0.0.20
RtkCfg.dll            : 1.0.0.2
RtkCoInst.dll         : 1.0.8.6

```

	Readme.txt	: 6.0.6000.119
RtkPgExt.dll		: 1.0.2.4
RtLCPAPI.dll		: 2.0.0.12
SFFXComm.dll		: 2.0.0.12
SFFXDAP0.dll		: 2.0.0.12
SFFXHAP0.dll		: 2.0.0.12
SFFXProc.dll		: 2.0.0.12
SFFXSAP0.dll		: 2.0.0.12
slcshp32.dll		: 1.0.3.0
slgeq32.dll		: 1.0.1.0
slh36032.dll		: 1.0.2.0
slInit32.dll		: 1.1.3.0
slmaxv32.dll		: 1.1.2.0
sltshd32.dll		: 1.1.1.0
sluapo32.dll		: 1.8.24.0
SRSHP360.dll		: 1.1.0.0
SRSTSHD.dll		: 1.1.4.0
SRSTSXT.dll		: 3.2.0.0
SRSWOW.dll		: 1.1.3.0
WavesLib.dll		: 5.9.7.0
Vista/Win7 driver for x64		
RTKVHD64.sys		: 6.0.1.6069
AERTSr64.exe		: 1.0.64.10
RAVBg64.exe		: 1.0.0.9
RAVCpl64.exe		: 1.0.0.500
RtkAudioService64.exe		: 1.0.0.24
RtkNGUI64.exe		: 1.0.0.31
RtlUpd64.exe		: 2.8.0.1
SkyTel.exe		: 2.0.2.2
vncutil64.exe		: 1.0.0.38
GWfilt64.sys		: 6.10.0.3
mbfilt64.sys		: 6.10.0.8
RTSnMg64.cpl		: 1.0.0.18
AERTAC64.dll		: 2.0.64.11
AERTAR64.dll		: 1.0.64.9
BlackSkinImages64.dll		: 1.0.0.31
DarkSkinImages64.dll		: 1.0.0.31
DTSBassEnhancementDLL64.dll		: 1.0.0.1
DTSBoostDLL64.dll		: 1.0.0.1
DTSGainCompensatorDLL64.dll		: 1.0.0.1
DTS GFXAP064.dll		: 1.0.0.1
DTS GFXAPONS64.dll		: 1.0.0.1
DTS LFXAP064.dll		: 1.0.0.1
DTS LimiterDLL64.dll		: 1.0.0.1
DTS NeoPCDLL64.dll		: 1.0.0.1
DTSS2HeadphoneDLL64.dll		: 1.0.0.1
DTSS2SpeakerDLL64.dll		: 1.0.0.1
DTSSymmetryDLL64.dll		: 1.0.0.1
DTS VoiceClarityDLL64.dll		: 1.0.0.1
FMAP064.dll		: 42.6.29.67
LightSkinImages64.dll		: 1.0.0.31
MaxxAudioAP020.dll		: 2.2.7.0
MaxxAudioEQ.dll		: 5.9.7.0
MBAP032.dll		: 1.0.19.0
MBAP064.dll		: 1.0.19.0
MBPPCn64.dll		: 1.0.0.110
MBpld64.dll		: 1.0.22.0
MBTHX32.dll		: 1.0.15.108
MBTHX64.dll		: 1.0.15.108
MBWrp64.dll		: 1.0.0.110
RCoInst64.dll		: 1.0.8.6
RP3DAA64.dll		: 6.0.6001.18
RP3DHT64.dll		: 6.0.6001.18
RtCOM64.dll		: 2.0.0.129
RTCOMDLL.dll		: 2.0.0.129
RTEED64A.dll		: 6.1.6001.33
RTEEG64A.dll		: 6.1.6001.33
RTEEL64A.dll		: 6.1.6001.33
RTEEP64A.dll		: 6.1.6001.33
RtkApi64.dll		: 1.0.0.20



Readme.txt

```

RtkAP064.dll : 11.0.6000.144
RtkCfg.dll : 1.0.0.1
RtkCfg64.dll : 1.0.0.2
RtlCPAPI.dll : 1.0.2.4
RtlCPAPI64.dll : 1.0.2.4
RtPgEx64.dll : 6.0.6000.119
SFComm64.dll : 2.0.0.12
SFDAPO64.dll : 2.0.0.12
SFHAPO64.dll : 2.0.0.12
SFProc64.dll : 2.0.0.12
SFSAP064.dll : 2.0.0.12
slcshp64.dll : 1.0.3.0
slgeq64.dll : 1.0.1.0
slh36064.dll : 1.0.2.0
slInit64.dll : 1.1.3.0
slmaxv64.dll : 1.1.2.0
sltshd64.dll : 1.1.1.0
sluapo64.dll : 1.8.24.0
SRSHP64.dll : 1.1.0.0
SRSTSH64.dll : 1.1.4.0
SRSTX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
WavesGUILib.dll : 1.2.3.4
HDM Driver : -----
Vista/Win7 x86:
RtHDMV.sys : 6.0.1.6034
RtkAudioSrvATI.exe : 1.0.0.23
RtkUpd.exe : 2.8.0.1
RH3DAA32.dll : 6.0.6001.18
RH3DHT32.dll : 6.0.6001.18
RHCoInst.dll : 1.0.8.2
RHDMExt.dll : 6.0.6000.113
RTEED32H.dll : 6.1.6001.33
RTEEG32H.dll : 6.1.6001.33
RTEEL32H.dll : 6.1.6001.33
RTEEP32H.dll : 6.1.6001.33
RtkHDM.dll : 11.0.6000.132

Vista/Win7 x64:
RtHDMVX.sys : 6.0.1.6034
RtkAudioSrvATI64.exe : 1.0.0.23
RtkUpd64.exe : 2.8.0.1
RH3DAA64.dll : 6.0.6001.18
RH3DHT64.dll : 6.0.6001.18
RHCoInst64.dll : 1.0.8.2
RHDMeX64.dll : 6.0.6000.113
RTEED64H.dll : 6.1.6001.33
RTEEG64H.dll : 6.1.6001.33
RTEEL64H.dll : 6.1.6001.33
RTEEP64H.dll : 6.1.6001.33
RtkHDM64.dll : 11.0.6000.132

XP/2K x86:
RtkHDM.sys : 5.10.0.6034
Rtaupd.exe : 2.8.0.1
RHCoInstXP.dll : 1.0.8.2

XP/2K x64:
RtkHDMX.sys : 5.10.0.6034
Rtaupd64.exe : 2.8.0.1
RHCoInst64XP.dll : 1.0.8.2

Driver Setup Program : 2.96

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

```

Readme.txt

//=====

Driver Package R2.44

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC892, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC892, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft WindowsXP, Windows2000, Windows Server 2003, Vista, Windows Server 2008,

Windows7 - x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :

RTKHDA64.sys : 5.10.0.6066  
RTKHAUD.sys : 5.10.0.6066  
McCal.exe : 1.1.2.3  
RTHDCPL.exe : 2.3.4.0  
RtkAudioService64.exe : 1.0.0.19  
RtkAudioService.exe : 1.0.0.19  
RTLCPPL.exe : 1.0.1.66  
RtlUpd64.exe : 2.8.0.1  
RtlUpd.exe : 2.8.0.1  
SkyTel.exe : 2.0.2.0  
SoundMan.exe : 1.0.0.32  
vncutil64.exe : 1.0.0.38  
vncutil.exe : 1.0.0.38  
Alcmtr.exe : 1.6.0.4  
AlcWzrd.exe : 1.1.0.37  
AMBft64.sys : 5.10.0.4240  
Mbnfilt.sys : 5.10.0.4112  
Mbnft64.sys : 5.10.0.4115  
OA017Afx.sys : 1.0.7.3  
AMBFilt.sys : 5.10.0.4240  
RTSndMgr.cpl : 1.0.1.4  
ALSndMgr.cpl : 1.0.0.11  
RCoInst64XP.dll : 1.0.8.6  
RTCOMDLL.dll : 1.0.0.107  
RtkCoInstXP.dll : 1.0.8.6  
RtlCPAPI.dll : 1.0.2.3

Vista/Win7 driver : -----

Vista/Win7 driver for x86

RTKVHDA.sys : 6.0.1.6066  
AERTSrv.exe : 1.0.32.10  
RtHDVBg.exe : 1.0.0.9  
RtHDVCpl.exe : 1.0.0.499  
RtkAudioService.exe : 1.0.0.24  
RtkNGUI.exe : 1.0.0.29  
RtlUpd.exe : 2.8.0.1  
SkyTel.exe : 2.0.2.2  
vncutil.exe : 1.0.0.38  
mbfilt32.sys : 6.10.0.8  
RTSndMgr.cpl : 1.0.0.18  
AERTACap.dll : 2.0.32.11  
AERTARen.dll : 1.0.32.9  
BlackSkinImages.dll : 1.0.0.29  
DarkSkinImages.dll : 1.0.0.29  
DTSBassEnhancementDLL.dll : 1.0.0.1  
DTSBoostDLL.dll : 1.0.0.1  
DTSGainCompensatorDLL.dll : 1.0.0.1  
DTSGFXAPO.dll : 1.0.0.1  
DTSGFXAPONS.dll : 1.0.0.1  
DTSLFXAPO.dll : 1.0.0.1  
DTS LimiterDLL.dll : 1.0.0.1

	Readme.txt	
DTSNeoPCDLL.dll	:	1.0.0.1
DTSS2HeadphoneDLL.dll	:	1.0.0.1
DTSS2SpeakerDLL.dll	:	1.0.0.1
DTSSymmetryDLL.dll	:	1.0.0.1
DTSVoiceClarityDLL.dll	:	1.0.0.1
FMAP0.dll	:	42.5.28.65
LightSkinImages.dll	:	1.0.0.29
MaxxAudioAPO.dll	:	1.2.2.0
MaxxAudioAPO20.dll	:	2.2.6.0
MaxxAudioEQ.dll	:	5.9.7.0
MBAP032.dll	:	1.0.19.0
MBPPCn32.dll	:	1.0.0.110
Mbpld32.dll	:	1.0.22.0
MBTHX32.dll	:	1.0.15.108
MBWrp32.dll	:	1.0.0.110
RP3DAA32.dll	:	6.0.6001.18
RP3DHT32.dll	:	6.0.6001.18
RTCOMDLL.dll	:	2.0.0.128
RTEED32A.dll	:	6.1.6001.33
RTEEG32A.dll	:	6.1.6001.33
RTEEL32A.dll	:	6.1.6001.33
RTEEP32A.dll	:	6.1.6001.33
RtkAPO.dll	:	11.0.6000.142
RtkApoApi.dll	:	1.0.0.20
RtkCfg.dll	:	1.0.0.2
RtkCoInst.dll	:	1.0.8.6
RtkPgExt.dll	:	6.0.6000.119
RtlCPAPI.dll	:	1.0.2.4
SFFXComm.dll	:	2.0.0.12
SFFXDAP0.dll	:	2.0.0.12
SFFXHAP0.dll	:	2.0.0.12
SFFXProc.dll	:	2.0.0.12
SFFXSAP0.dll	:	2.0.0.12
slcshp32.dll	:	1.0.3.0
slgeq32.dll	:	1.0.1.0
slh36032.dll	:	1.0.2.0
slInit32.dll	:	1.1.3.0
slmaxv32.dll	:	1.1.2.0
sltshd32.dll	:	1.1.1.0
sluapo32.dll	:	1.8.24.0
SRSHP360.dll	:	1.1.0.0
SRSTSHD.dll	:	1.1.4.0
SRSTSXT.dll	:	3.2.0.0
SRSWOW.dll	:	1.1.3.0
WavesLib.dll	:	5.9.7.0
Vista/Win7 driver for x64		
RTKVHD64.sys	:	6.0.1.6066
AERTSr64.exe	:	1.0.64.10
RAVBg64.exe	:	1.0.0.9
RAVCpl64.exe	:	1.0.0.499
RtkAudioService64.exe	:	1.0.0.24
RtkNGUI64.exe	:	1.0.0.29
RtlUpd64.exe	:	2.8.0.1
SkyTel.exe	:	2.0.2.2
vncutil64.exe	:	1.0.0.38
GWfilt64.sys	:	6.10.0.3
mbfilt64.sys	:	6.10.0.8
RTSnMg64.cpl	:	1.0.0.18
AERTAC64.dll	:	2.0.64.11
AERTAR64.dll	:	1.0.64.9
BlackSkinImages64.dll	:	1.0.0.29
DarkSkinImages64.dll	:	1.0.0.29
DTSBassEnhancementDLL64.dll	:	1.0.0.1
DTSBoostDLL64.dll	:	1.0.0.1
DTSGainCompensatorDLL64.dll	:	1.0.0.1
DTSAFXAP064.dll	:	1.0.0.1
DTSAFXAPONS64.dll	:	1.0.0.1
DTSAFXAP064.dll	:	1.0.0.1
DTSLimitDLL64.dll	:	1.0.0.1

Readme.txt

DTSNeoPCDLL64.dll	: 1.0.0.1
DTSS2HeadphoneDLL64.dll	: 1.0.0.1
DTSS2SpeakerDLL64.dll	: 1.0.0.1
DTSSymmetryDLL64.dll	: 1.0.0.1
DTSVoiceClarityDLL64.dll	: 1.0.0.1
FMAP064.dll	: 42.6.28.65
LightSkinImages64.dll	: 1.0.0.29
MaxxAudioAP020.dll	: 2.2.7.0
MaxxAudioEQ.dll	: 5.9.7.0
MBAP032.dll	: 1.0.19.0
MBAP064.dll	: 1.0.19.0
MBPPCn64.dll	: 1.0.0.110
Mbpld64.dll	: 1.0.22.0
MBTHX32.dll	: 1.0.15.108
MBTHX64.dll	: 1.0.15.108
MBWrp64.dll	: 1.0.0.110
RCoInst64.dll	: 1.0.8.6
RP3DAA64.dll	: 6.0.6001.18
RP3DHT64.dll	: 6.0.6001.18
RtCOMB4.dll	: 2.0.0.128
RTCOMDLL.dll	: 2.0.0.128
RTEED64A.dll	: 6.1.6001.33
RTEEG64A.dll	: 6.1.6001.33
RTEEL64A.dll	: 6.1.6001.33
RTEEP64A.dll	: 6.1.6001.33
RtkApi64.dll	: 1.0.0.20
RtkAP064.dll	: 11.0.6000.142
RtkCfg.dll	: 1.0.0.1
RtkCfg64.dll	: 1.0.0.2
RtLCPAPI.dll	: 1.0.2.4
RtLCPAPI64.dll	: 1.0.2.4
RtPgEx64.dll	: 6.0.6000.119
SFComm64.dll	: 2.0.0.12
SFDAPO64.dll	: 2.0.0.12
SFHAP064.dll	: 2.0.0.12
SFProc64.dll	: 2.0.0.12
SFSAP064.dll	: 2.0.0.12
slcshp64.dll	: 1.0.3.0
slgeq64.dll	: 1.0.1.0
slh36064.dll	: 1.0.2.0
slInit64.dll	: 1.1.3.0
slmaxv64.dll	: 1.1.2.0
sltshd64.dll	: 1.1.1.0
sluapo64.dll	: 1.8.24.0
SRSHP64.dll	: 1.1.0.0
SRSTSH64.dll	: 1.1.4.0
SRSTX64.dll	: 3.2.0.0
SRSWOW64.dll	: 1.1.3.0
WavesGUILib.dll	: 1.2.3.4
-----	
HDM Driver :	
Vista/Win7 x86:	
RtHDMV.sys	: 6.0.1.6034
RtkAudioSrvATI.exe	: 1.0.0.23
RtkUpd.exe	: 2.8.0.1
RH3DAA32.dll	: 6.0.6001.18
RH3DHT32.dll	: 6.0.6001.18
RHCoInst.dll	: 1.0.8.2
RHDMExt.dll	: 6.0.6000.113
RTEED32H.dll	: 6.1.6001.33
RTEEG32H.dll	: 6.1.6001.33
RTEEL32H.dll	: 6.1.6001.33
RTEEP32H.dll	: 6.1.6001.33
RtkHDM.dll	: 11.0.6000.132
Vista/Win7 x64:	
RtHDMVX.sys	: 6.0.1.6034
RtkAudioSrvATI64.exe	: 1.0.0.23
RtkUpd64.exe	: 2.8.0.1
RH3DAA64.dll	: 6.0.6001.18

Readme.txt

RH3DHT64.dll : 6.0.6001.18  
RHCoInst64.dll : 1.0.8.2  
RHDME64.dll : 6.0.6000.113  
RTEED64H.dll : 6.1.6001.33  
RTEEG64H.dll : 6.1.6001.33  
RTEEL64H.dll : 6.1.6001.33  
RTEEP64H.dll : 6.1.6001.33  
RtkHDM64.dll : 11.0.6000.132

XP/2K x86:  
RtkHDM.sys : 5.10.0.6034  
Rtaupd.exe : 2.8.0.1  
RHCoInstXP.dll : 1.0.8.2

XP/2K x64:  
RtkHDMX.sys : 5.10.0.6034  
Rtaupd64.exe : 2.8.0.1  
RHCoInst64XP.dll : 1.0.8.2

Driver Setup Program : 2.96

Windows 2000/XP Operate on :  
Microsoft High Definition Audio Driver Package - KB888111  
Package file version (kb888111.exe) : 6.1.22.0  
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.43

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC892, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC892, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680

3. HDM Device WHQL Support: ATI HDM Devices

4. OS Supporting: Microsoft WindowsXP, Windows2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 - x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :

RTKHDA64.sys : 5.10.0.6050  
RTKHDAUD.sys : 5.10.0.6050  
MicCal.exe : 1.1.2.3  
RTHDCPL.exe : 2.3.3.8  
RtkAudioService64.exe : 1.0.0.19  
RtkAudioService.exe : 1.0.0.19  
RTLCP.exe : 1.0.1.66  
RtlUpd64.exe : 2.8.0.1  
RtlUpd.exe : 2.8.0.1  
SkyTel.exe : 2.0.2.0  
SoundMan.exe : 1.0.0.32  
vncutil64.exe : 1.0.0.38  
vncutil.exe : 1.0.0.38  
Alcmtr.exe : 1.6.0.4  
AlcWzrd.exe : 1.1.0.37  
Mnft64.sys : 5.10.0.4112  
Mnft64.sys : 5.10.0.4115  
OA017Afx.sys : 1.0.7.3  
AMBfilt.sys : 5.10.0.4240  
AMBft64.sys : 5.10.0.4240  
RTSndMgr.cpl : 1.0.1.4  
ALSndMgr.cpl : 1.0.0.11  
RCoInst64XP.dll : 1.0.8.4  
RTCOMDLL.dll : 1.0.0.106

	Readme.txt	
RtkCoInstXP.dll	:	1.0.8.4
RtLCPAPI.dll	:	1.0.2.3
Vista/Win7 driver : -----		
Vista/Win7 driver for x86		
RTKVHDA.sys	:	6.0.1.6050
AERTSrv.exe	:	1.0.32.10
RtHDVBg.exe	:	1.0.0.8
RtHDVCpl.exe	:	1.0.0.489
RtkAudioService.exe	:	1.0.0.24
RtkNGUI.exe	:	0.0.0.25
RtlUpd.exe	:	2.8.0.1
SkyTel.exe	:	2.0.2.2
vncutil.exe	:	1.0.0.38
mbfilt32.sys	:	6.10.0.8
RTSndMgr.cpl	:	1.0.0.18
AERTACap.dll	:	2.0.32.11
AERTARen.dll	:	1.0.32.9
BlackSkinImages.dll	:	0.0.0.25
DarkSkinImages.dll	:	0.0.0.25
DTSBassEnhancementDLL.dll	:	1.0.0.1
DTSBoostDLL.dll	:	1.0.0.1
DTSGainCompensatorDLL.dll	:	1.0.0.1
DTSAFXAPO.dll	:	1.0.0.1
DTSAFXAPONS.dll	:	1.0.0.1
DTSAFXAPO.dll	:	1.0.0.1
DTSLimitDLL.dll	:	1.0.0.1
DTSNeoPCDLL.dll	:	1.0.0.1
DTSS2HeadphoneDLL.dll	:	1.0.0.1
DTSS2SpeakerDLL.dll	:	1.0.0.1
DTSSymmetryDLL.dll	:	1.0.0.1
DTSVoiceClarityDLL.dll	:	1.0.0.1
FMAPO.dll	:	42.5.26.65
LightSkinImages.dll	:	0.0.0.25
MaxxAudioAPO.dll	:	1.2.2.0
MaxxAudioAPO20.dll	:	2.2.6.0
MaxxAudioEQ.dll	:	5.9.7.0
MBAP032.dll	:	1.0.19.0
MBPPCn32.dll	:	1.0.0.110
MBppld32.dll	:	1.0.22.0
MBTHX32.dll	:	1.0.15.106
MBWrp32.dll	:	1.0.0.110
RP3DAA32.dll	:	6.0.6001.18
RP3DHT32.dll	:	6.0.6001.18
RTCOMDLL.dll	:	2.0.0.128
RTEED32A.dll	:	6.1.6001.33
RTEEG32A.dll	:	6.1.6001.33
RTEEL32A.dll	:	6.1.6001.33
RTEEP32A.dll	:	6.1.6001.33
RtkAPO.dll	:	11.0.6000.137
RtkApoApi.dll	:	1.0.0.20
RtkCfg.dll	:	1.0.0.2
RtkCoInst.dll	:	1.0.8.4
RtkPgExt.dll	:	6.0.6000.116
RtLCPAPI.dll	:	1.0.2.4
SFFXComm.dll	:	2.0.0.9
SFFXDAPO.dll	:	2.0.0.9
SFFXHAP0.dll	:	2.0.0.9
SFFXProc.dll	:	2.0.0.9
SFFXSAP0.dll	:	2.0.0.9
slcshp32.dll	:	1.0.3.0
slgeq32.dll	:	1.0.1.0
slh36032.dll	:	1.0.2.0
slInit32.dll	:	1.1.3.0
slmaxv32.dll	:	1.1.2.0
sltshd32.dll	:	1.1.1.0
sluapo32.dll	:	1.8.24.0
SRSHP360.dll	:	1.1.0.0
SRSTSHD.dll	:	1.1.4.0
SRSTSXT.dll	:	3.2.0.0

	Readme.txt	
SRSWOW.dll	:	1.1.3.0
WavesLib.dll	:	5.9.7.0
Vista/Win7 driver for x64		
RTKVHD64.sys	:	6.0.1.6050
AERTSr64.exe	:	1.0.64.10
RAVBg64.exe	:	1.0.0.8
RAVCpl64.exe	:	1.0.0.489
RtkAudioService64.exe	:	1.0.0.24
RtkNGUI64.exe	:	0.0.0.25
RtlUpd64.exe	:	2.8.0.1
SkyTel.exe	:	2.0.2.2
vncutil64.exe	:	1.0.0.38
GWfilt64.sys	:	6.10.0.3
mbfilt64.sys	:	6.10.0.8
RTSnMg64.cpl	:	1.0.0.18
AERTAC64.dll	:	2.0.64.11
AERTAR64.dll	:	1.0.64.9
BlackSkinImages64.dll	:	0.0.0.25
DarkSkinImages64.dll	:	0.0.0.25
DTSBassEnhancementDLL64.dll	:	1.0.0.1
DTSBoostDLL64.dll	:	1.0.0.1
DTSGainCompensatorDLL64.dll	:	1.0.0.1
DTSAFXAP064.dll	:	1.0.0.1
DTSAFXAPONS64.dll	:	1.0.0.1
DTSLFXAP064.dll	:	1.0.0.1
DTSLimitDLL64.dll	:	1.0.0.1
DTSNeoPCDLL64.dll	:	1.0.0.1
DTSS2HeadphoneDLL64.dll	:	1.0.0.1
DTSS2SpeakerDLL64.dll	:	1.0.0.1
DTSSymmetryDLL64.dll	:	1.0.0.1
DTSVoiceClarityDLL64.dll	:	1.0.0.1
FMAP064.dll	:	42.6.26.65
LightSkinImages64.dll	:	0.0.0.25
MaxxAudioAP020.dll	:	2.2.7.0
MaxxAudioEQ.dll	:	5.9.7.0
MBAP032.dll	:	1.0.19.0
MBAP064.dll	:	1.0.19.0
MBPPcn64.dll	:	1.0.0.110
MBppld64.dll	:	1.0.22.0
MBTHX32.dll	:	1.0.15.106
MBTHX64.dll	:	1.0.15.106
MBWrp64.dll	:	1.0.0.110
RCoInst64.dll	:	1.0.8.4
RP3DAA64.dll	:	6.0.6001.18
RP3DHT64.dll	:	6.0.6001.18
RtCOMB4.dll	:	2.0.0.128
RTCOMDLL.dll	:	2.0.0.128
RTEED64A.dll	:	6.1.6001.33
RTEEG64A.dll	:	6.1.6001.33
RTEEL64A.dll	:	6.1.6001.33
RTEEP64A.dll	:	6.1.6001.33
RtkApi64.dll	:	1.0.0.20
RtkAP064.dll	:	11.0.6000.137
RtkCfg.dll	:	1.0.0.1
RtkCfg64.dll	:	1.0.0.2
RtlCPAPI.dll	:	1.0.2.4
RtlCPAPI64.dll	:	1.0.2.4
RtPgEx64.dll	:	6.0.6000.116
SFComm64.dll	:	2.0.0.9
SFDAPO64.dll	:	2.0.0.9
SFHAP064.dll	:	2.0.0.9
SFProc64.dll	:	2.0.0.9
SFSAP064.dll	:	2.0.0.9
slcshp64.dll	:	1.0.3.0
slgeq64.dll	:	1.0.1.0
slh36064.dll	:	1.0.2.0
slInit64.dll	:	1.1.3.0
slmaxv64.dll	:	1.1.2.0
sltshd64.dll	:	1.1.1.0

Readme.txt

```

sluapo64.dll : 1.8.24.0
SRSHp64.dll : 1.1.0.0
SRSTSH64.dll : 1.1.4.0
SRSTX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
WavesGUILib.dll : 1.2.3.4
HDMI Driver : -----
Vista/Win7 x86:
RtHDMV.sys : 6.0.1.6034
RtkAudioSrvATI.exe : 1.0.0.23
RtkUpd.exe : 2.8.0.1
RH3DAA32.dll : 6.0.6001.18
RH3DHT32.dll : 6.0.6001.18
RHCoInst.dll : 1.0.8.2
RHDMExt.dll : 6.0.6000.113
RTEED32H.dll : 6.1.6001.33
RTEEG32H.dll : 6.1.6001.33
RTEEL32H.dll : 6.1.6001.33
RTEEP32H.dll : 6.1.6001.33
RtkHDM.dll : 11.0.6000.132

Vista/Win7 x64:
RtHDMVX.sys : 6.0.1.6034
RtkAudioSrvATI64.exe : 1.0.0.23
RtkUpd64.exe : 2.8.0.1
RH3DAA64.dll : 6.0.6001.18
RH3DHT64.dll : 6.0.6001.18
RHCoInst64.dll : 1.0.8.2
RHDMEx64.dll : 6.0.6000.113
RTEED64H.dll : 6.1.6001.33
RTEEG64H.dll : 6.1.6001.33
RTEEL64H.dll : 6.1.6001.33
RTEEP64H.dll : 6.1.6001.33
RtkHDM64.dll : 11.0.6000.132

XP/2K x86:
RtkHDM.sys : 5.10.0.6034
Rtaupd.exe : 2.8.0.1
RHCoInstXP.dll : 1.0.8.2

XP/2K x64:
RtkHDMX.sys : 5.10.0.6034
Rtaupd64.exe : 2.8.0.1
RHCoInst64XP.dll : 1.0.8.2

Driver Setup Program : 2.95

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

```

//=====

Driver Package R2.42

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC892, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC892, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft WindowsXP, Windows2000, Windows Server 2003, Vista, Windows Server 2008,

Windows7 - x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.



Readme.txt

```

Windows 2000/XP : -----
Windows 2000/XP :
RTKHDA64.sys : 5.10.0.6043
RTKHDAUD.sys : 5.10.0.6043
Alcmtr.exe : 1.6.0.4
AlcWzrd.exe : 1.1.0.37
McCal.exe : 1.1.2.3
RTHDCPL.exe : 2.3.3.6
RtkAudioService64.exe : 1.0.0.19
RtkAudioService.exe : 1.0.0.19
RTLCPPL.exe : 1.0.1.66
RtlUpd64.exe : 2.8.0.1
RtlUpd.exe : 2.8.0.1
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.32
vncutil64.exe : 1.0.0.38
vncutil.exe : 1.0.0.38
AMBfilt.sys : 5.10.0.4240
AMBft64.sys : 5.10.0.4240
Mbnfilt.sys : 5.10.0.4112
Mbnft64.sys : 5.10.0.4115
OA017Afx.sys : 1.0.7.3
ALSndMgr.cpl : 1.0.0.11
RTSndMgr.cpl : 1.0.1.4
RCoInst64XP.dll : 1.0.8.2
RTCOMDLL.dll : 1.0.0.105
RtkCoInstXP.dll : 1.0.8.2
RtlCPAPI.dll : 1.0.2.3
Vista/Wn7 driver : -----
Vista/Wn7 driver for x86
RTKVHDA.sys : 6.0.1.6043
AERTSrv.exe : 1.0.32.10
RtHDVBg.exe : 1.0.0.8
RtHDVCpl.exe : 1.0.0.484
RtkAudioService.exe : 1.0.0.24
RtkNGUI.exe : 0.0.0.24
RtlUpd.exe : 2.8.0.1
SkyTel.exe : 2.0.2.2
vncutil.exe : 1.0.0.38
mbfilt32.sys : 6.10.0.8
RTSndMgr.cpl : 1.0.0.18
AERTACap.dll : 2.0.32.11
AERTARen.dll : 1.0.32.9
BlackSkinImages.dll : 0.0.0.24
DarkSkinImages.dll : 0.0.0.24
DTSBassEnhancementDLL.dll : 1.0.0.1
DTSBoostDLL.dll : 1.0.0.1
DTSGainCompensatorDLL.dll : 1.0.0.1
DTSGFXAPO.dll : 1.0.0.1
DTSGFXAPONS.dll : 1.0.0.1
DTSLFXAPO.dll : 1.0.0.1
DTSLimiterDLL.dll : 1.0.0.1
DTSNeoPCDLL.dll : 1.0.0.1
DTSS2HeadphoneDLL.dll : 1.0.0.1
DTSS2SpeakerDLL.dll : 1.0.0.1
DTSSymmetryDLL.dll : 1.0.0.1
DTSVoiceClarityDLL.dll : 1.0.0.1
FMAPO.dll : 42.5.26.65
LightSkinImages.dll : 0.0.0.24
MaxxAudioAPO.dll : 1.2.2.0
MaxxAudioAPO20.dll : 2.2.6.0
MaxxAudioEQ.dll : 5.9.7.0
MBAP032.dll : 1.0.19.0
MBPPCh32.dll : 1.0.0.110
MBpld32.dll : 1.0.22.0
MBTHX32.dll : 1.0.15.106
MBWrp32.dll : 1.0.0.110
RP3DAA32.dll : 6.0.6001.18
RP3DHT32.dll : 6.0.6001.18

```

RTCOMDLL.dll	: 2.0.0.127
RTEED32A.dll	: 6.1.6001.33
RTEEG32A.dll	: 6.1.6001.33
RTEEL32A.dll	: 6.1.6001.33
RTEEP32A.dll	: 6.1.6001.33
RtkAPO.dll	: 11.0.6000.134
RtkApoApi.dll	: 1.0.0.20
RtkCfg.dll	: 1.0.0.2
RtkColnst.dll	: 1.0.8.4
RtkPgExt.dll	: 6.0.6000.114
RtlCPAPI.dll	: 1.0.2.4
SFFXComm.dll	: 2.0.0.9
SFFXDAP0.dll	: 2.0.0.9
SFFXHAP0.dll	: 2.0.0.9
SFFXProc.dll	: 2.0.0.9
SFFXSAP0.dll	: 2.0.0.9
slcshp32.dll	: 1.0.3.0
slgeq32.dll	: 1.0.1.0
slh36032.dll	: 1.0.2.0
slInit32.dll	: 1.1.3.0
slmaxv32.dll	: 1.1.2.0
sltshd32.dll	: 1.1.1.0
sluapo32.dll	: 1.8.24.0
SRSHP360.dll	: 1.1.0.0
SRSTSHD.dll	: 1.1.4.0
SRSTSXT.dll	: 3.2.0.0
SRSWOW.dll	: 1.1.3.0
WavesLib.dll	: 5.9.7.0
Vista/Win7 driver for x64	
RTKVHD64.sys	: 6.0.1.6043
AERTSr64.exe	: 1.0.64.10
RAVBg64.exe	: 1.0.0.8
RAVCpl64.exe	: 1.0.0.484
RtkAudioService64.exe	: 1.0.0.24
RtkNGUI64.exe	: 0.0.0.24
RtlUpd64.exe	: 2.8.0.1
SkyTel.exe	: 2.0.2.2
vncutil64.exe	: 1.0.0.38
GWfilt64.sys	: 6.10.0.3
mbfilt64.sys	: 6.10.0.8
RTSnMg64.cpl	: 1.0.0.18
AERTAC64.dll	: 2.0.64.11
AERTAR64.dll	: 1.0.64.9
BlackSkinImages64.dll	: 0.0.0.24
DarkSkinImages64.dll	: 0.0.0.24
DTSBassEnhancementDLL64.dll	: 1.0.0.1
DTSBoostDLL64.dll	: 1.0.0.1
DTSGainCompensatorDLL64.dll	: 1.0.0.1
DTSGFXAP064.dll	: 1.0.0.1
DTSGFXAPONS64.dll	: 1.0.0.1
DTSLFXAP064.dll	: 1.0.0.1
DTSLimiterDLL64.dll	: 1.0.0.1
DTSNeoPCDLL64.dll	: 1.0.0.1
DTSS2HeadphoneDLL64.dll	: 1.0.0.1
DTSS2SpeakerDLL64.dll	: 1.0.0.1
DTSSymmetryDLL64.dll	: 1.0.0.1
DTSVoiceClarityDLL64.dll	: 1.0.0.1
FMAP064.dll	: 42.6.26.65
LghtSkinImages64.dll	: 0.0.0.24
MaxxAudioAP020.dll	: 2.2.7.0
MaxxAudioEQ.dll	: 5.9.7.0
MBAP032.dll	: 1.0.19.0
MBAP064.dll	: 1.0.19.0
MBPPCn64.dll	: 1.0.0.110
MBpld64.dll	: 1.0.22.0
MBTHX32.dll	: 1.0.15.106
MBTHX64.dll	: 1.0.15.106
MBWrp64.dll	: 1.0.0.110
RCoInst64.dll	: 1.0.8.4

Readme.txt

Readme.txt

RP3DAA64.dll	: 6.0.6001.18
RP3DHT64.dll	: 6.0.6001.18
RtCOM64.dll	: 2.0.0.127
RTCOMDLL.dll	: 2.0.0.127
RTEED64A.dll	: 6.1.6001.33
RTEEG64A.dll	: 6.1.6001.33
RTEEL64A.dll	: 6.1.6001.33
RTEEP64A.dll	: 6.1.6001.33
RtkApi64.dll	: 1.0.0.20
RtkAPO64.dll	: 11.0.6000.134
RtkCfg.dll	: 1.0.0.1
RtkCfg64.dll	: 1.0.0.2
RtLCPAPI.dll	: 1.0.2.4
RtLCPAPI64.dll	: 1.0.2.4
RtPgEx64.dll	: 6.0.6000.114
SFComm64.dll	: 2.0.0.9
SFDAP064.dll	: 2.0.0.9
SFHAP064.dll	: 2.0.0.9
SFProc64.dll	: 2.0.0.9
SFSAP064.dll	: 2.0.0.9
slcshp64.dll	: 1.0.3.0
slgeq64.dll	: 1.0.1.0
slh36064.dll	: 1.0.2.0
slInit64.dll	: 1.1.3.0
slmaxv64.dll	: 1.1.2.0
sltshd64.dll	: 1.1.1.0
sluapo64.dll	: 1.8.24.0
SRSHP64.dll	: 1.1.0.0
SRSTSH64.dll	: 1.1.4.0
SRSTX64.dll	: 3.2.0.0
SRSW064.dll	: 1.1.3.0
WavesGUILib.dll	: 1.2.3.4

HDM Driver : -----

Vista/Win7 x86:	
RtHDMV.sys	: 6.0.1.6034
RtkAudioSrvATI.exe	: 1.0.0.23
RtkUpd.exe	: 2.8.0.1
RH3DAA32.dll	: 6.0.6001.18
RH3DHT32.dll	: 6.0.6001.18
RHCoInst.dll	: 1.0.8.2
RHDMExt.dll	: 6.0.6000.113
RTEED32H.dll	: 6.1.6001.33
RTEEG32H.dll	: 6.1.6001.33
RTEEL32H.dll	: 6.1.6001.33
RTEEP32H.dll	: 6.1.6001.33
RtkHDM.dll	: 11.0.6000.132

Vista/Win7 x64:	
RtHDMVX.sys	: 6.0.1.6034
RtkAudioSrvATI64.exe	: 1.0.0.23
RtkUpd64.exe	: 2.8.0.1
RH3DAA64.dll	: 6.0.6001.18
RH3DHT64.dll	: 6.0.6001.18
RHCoInst64.dll	: 1.0.8.2
RHDMEx64.dll	: 6.0.6000.113
RTEED64H.dll	: 6.1.6001.33
RTEEG64H.dll	: 6.1.6001.33
RTEEL64H.dll	: 6.1.6001.33
RTEEP64H.dll	: 6.1.6001.33
RtkHDM64.dll	: 11.0.6000.132

XP/2K x86:	
RtkHDM.sys	: 5.10.0.6034
Rtaupd.exe	: 2.8.0.1
RHCoInstXP.dll	: 1.0.8.2

XP/2K x64:	
RtkHDMX.sys	: 5.10.0.6034
Rtaupd64.exe	: 2.8.0.1

Readme.txt

RHCoInst64XP.dll : 1.0.8.2

Driver Setup Program : 2.94

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.41

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC892, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC892, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680

3. HDM Device WHQL Support: ATI HDM Devices

4. OS Supporting: Microsoft WindowsXP, Windows2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 - x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :

RTKHDA64.sys : 5.10.0.6029  
RTKHDAUD.sys : 5.10.0.6029  
Alcmtr.exe : 1.6.0.4  
AlcWzrd.exe : 1.1.0.37  
McCal.exe : 1.1.2.3  
RTHDCPL.exe : 2.3.3.2  
RtkAudioService.exe : 1.0.0.19  
RtkAudioService64.exe : 1.0.0.19  
RTLCPPL.exe : 1.0.1.66  
RtlUpd.exe : 2.8.0.1  
RtlUpd64.exe : 2.8.0.1  
SkyTel.exe : 2.0.2.0  
SoundMan.exe : 1.0.0.32  
vncutil.exe : 1.0.0.38  
vncutil64.exe : 1.0.0.38  
AMBfilt.sys : 5.10.0.4240  
AMBft64.sys : 5.10.0.4240  
Mnft64.sys : 5.10.0.4112  
Mnft64.sys : 5.10.0.4115  
OA017Afx.sys : 1.0.7.3  
ALSndMgr.cpl : 1.0.0.11  
RTSndMgr.cpl : 1.0.1.4  
RCoInst64XP.dll : 1.0.8.2  
RTCOMDLL.dll : 1.0.0.104  
RtkCoInstXP.dll : 1.0.8.2  
RtlCPAPI.dll : 1.0.2.3

Vista/Wn7 driver : -----

Vista/Wn7 driver for x86

RTKVHDA.sys : 6.0.1.6029  
AERTSrv.exe : 1.0.32.10  
RtHDVBg.exe : 1.0.0.8  
RtHDVCpl.exe : 1.0.0.477  
RtkAudioService.exe : 1.0.0.24  
RtkNGUI.exe : 0.0.0.22  
RtlUpd.exe : 2.8.0.1  
SkyTel.exe : 2.0.2.2  
vncutil.exe : 1.0.0.38  
mbfilt32.sys : 6.10.0.8  
RTSndMgr.cpl : 1.0.0.18  
AERTCap.dll : 2.0.32.9  
AERTARen.dll : 1.0.32.9

	Readme.txt	
BlackSkinImages.dll	:	0.0.0.22
DarkSkinImages.dll	:	0.0.0.22
DTSBassEnhancementDLL.dll	:	1.0.0.1
DTSBoostDLL.dll	:	1.0.0.1
DTSGainCompensatorDLL.dll	:	1.0.0.1
DTSGFXAPO.dll	:	1.0.0.1
DTSGFXAPONS.dll	:	1.0.0.1
DTSLFXAPO.dll	:	1.0.0.1
DTS LimiterDLL.dll	:	1.0.0.1
DTSNeoPCDLL.dll	:	1.0.0.1
DTSS2HeadphoneDLL.dll	:	1.0.0.1
DTSS2SpeakerDLL.dll	:	1.0.0.1
DTSSymmetryDLL.dll	:	1.0.0.1
DTSVoiceClarityDLL.dll	:	1.0.0.1
FMAP0.dll	:	42.5.24.65
LightSkinImages.dll	:	0.0.0.22
MaxxAudioAPO.dll	:	1.2.2.0
MaxxAudioAPO20.dll	:	2.2.6.0
MaxxAudioEQ.dll	:	5.9.7.0
MBAP032.dll	:	1.0.19.0
MBPPCn32.dll	:	1.0.0.110
MBpld32.dll	:	1.0.22.0
MBTHX32.dll	:	1.0.8.109
MBWp32.dll	:	1.0.0.110
RP3DAA32.dll	:	6.0.6001.18
RP3DHT32.dll	:	6.0.6001.18
RTCOMDLL.dll	:	2.0.0.125
RTEED32A.dll	:	6.1.6001.33
RTEEG32A.dll	:	6.1.6001.33
RTEEL32A.dll	:	6.1.6001.33
RTEEP32A.dll	:	6.1.6001.33
RtkAPO.dll	:	11.0.6000.132
RtkApoApi.dll	:	1.0.0.20
RtkCfg.dll	:	1.0.0.2
RtkColInst.dll	:	1.0.8.3
RtkPgExt.dll	:	6.0.6000.113
RtlCPAPI.dll	:	1.0.2.4
SFFXComm.dll	:	2.0.0.9
SFFXDAP0.dll	:	2.0.0.9
SFFXHAP0.dll	:	2.0.0.9
SFFXProc.dll	:	2.0.0.9
SFFXSAP0.dll	:	2.0.0.9
slcshp32.dll	:	1.0.3.0
slgeq32.dll	:	1.0.1.0
slh36032.dll	:	1.0.2.0
slInit32.dll	:	1.1.3.0
slmaxv32.dll	:	1.1.2.0
sltshd32.dll	:	1.1.1.0
sluapo32.dll	:	1.8.24.0
SRSHP360.dll	:	1.1.0.0
SRSTSHD.dll	:	1.1.4.0
SRSTSXT.dll	:	3.2.0.0
SRSWOW.dll	:	1.1.3.0
WavesLib.dll	:	5.9.7.0
Vista/Win7 driver for x64		
RTKVHD64.sys	:	6.0.1.6029
AERTSr64.exe	:	1.0.64.10
RAVBg64.exe	:	1.0.0.8
RAVCpl64.exe	:	1.0.0.477
RtkAudioService64.exe	:	1.0.0.24
RtkNGUI64.exe	:	0.0.0.22
RtlUpd64.exe	:	2.8.0.1
SkyTel.exe	:	2.0.2.2
vncutil64.exe	:	1.0.0.38
GWfilt64.sys	:	6.10.0.3
mbfilt64.sys	:	6.10.0.8
RTSnMg64.cpl	:	1.0.0.18
AERTAC64.dll	:	2.0.64.9
AERTAR64.dll	:	1.0.64.9

Readme.txt

BlackSkinImages64.dll	: 0.0.0.22
DarkSkinImages64.dll	: 0.0.0.22
DTSBassEnhancementDLL64.dll	: 1.0.0.1
DTSBoostDLL64.dll	: 1.0.0.1
DTSGainCompensatorDLL64.dll	: 1.0.0.1
DTSGFXAP064.dll	: 1.0.0.1
DTSGFXAPONS64.dll	: 1.0.0.1
DTSLFXAP064.dll	: 1.0.0.1
DTSLimiterDLL64.dll	: 1.0.0.1
DTSNeoPCDLL64.dll	: 1.0.0.1
DTSS2HeadphoneDLL64.dll	: 1.0.0.1
DTSS2SpeakerDLL64.dll	: 1.0.0.1
DTSSymmetryDLL64.dll	: 1.0.0.1
DTSVoiceClarityDLL64.dll	: 1.0.0.1
FMAP064.dll	: 42.6.24.65
LightSkinImages64.dll	: 0.0.0.22
MaxxAudioAP020.dll	: 2.2.6.0
MaxxAudioEQ.dll	: 5.9.7.0
MBAP032.dll	: 1.0.19.0
MBAP064.dll	: 1.0.19.0
MBPPCn64.dll	: 1.0.0.110
MBpld64.dll	: 1.0.22.0
MBTHX32.dll	: 1.0.8.109
MBTHX64.dll	: 1.0.8.109
MBWrp64.dll	: 1.0.0.110
RCoInst64.dll	: 1.0.8.3
RP3DAA64.dll	: 6.0.6001.18
RP3DHT64.dll	: 6.0.6001.18
RtCOM64.dll	: 2.0.0.125
RTCOMDLL.dll	: 2.0.0.125
RTEED64A.dll	: 6.1.6001.33
RTEEG64A.dll	: 6.1.6001.33
RTEEL64A.dll	: 6.1.6001.33
RTEEP64A.dll	: 6.1.6001.33
RtkApi64.dll	: 1.0.0.20
RtkAPO64.dll	: 11.0.6000.132
RtkCfg.dll	: 1.0.0.1
RtkCfg64.dll	: 1.0.0.2
RtLCPAPI.dll	: 1.0.2.4
RtLCPAPI64.dll	: 1.0.2.4
RtPgEx64.dll	: 6.0.6000.113
SFComm64.dll	: 2.0.0.9
SFDAP064.dll	: 2.0.0.9
SFHAP064.dll	: 2.0.0.9
SFProc64.dll	: 2.0.0.9
SFSAP064.dll	: 2.0.0.9
slcshp64.dll	: 1.0.3.0
slgeq64.dll	: 1.0.1.0
slh36064.dll	: 1.0.2.0
slInit64.dll	: 1.1.3.0
slmaxv64.dll	: 1.1.2.0
sltshd64.dll	: 1.1.1.0
sluapo64.dll	: 1.8.24.0
SRSHP64.dll	: 1.1.0.0
SRSTSH64.dll	: 1.1.4.0
SRSTSX64.dll	: 3.2.0.0
SRSW064.dll	: 1.1.3.0
WavesGUILib.dll	: 1.2.3.4
<b>HDMI Driver : -----</b>	
Vista/Win7 x86:	
RtHDMV.sys	: 6.0.1.5992
RtkAudioSrvATI.exe	: 1.0.0.23
RtkUpd.exe	: 2.8.0.1
RH3DAA32.dll	: 6.0.6001.18
RH3DHT32.dll	: 6.0.6001.18
RHCoInst.dll	: 1.0.7.0
RHDMExt.dll	: 6.0.6000.109
RtkHDM.dll	: 11.0.6000.126

Readme.txt

Vista/Win7 x64:  
RtHDM VX. sys : 6.0.1.5992  
RtkAudioSrvATI64.exe : 1.0.0.23  
RtkUpd64.exe : 2.8.0.1  
RH3DAA64.dll : 6.0.6001.18  
RH3DHT64.dll : 6.0.6001.18  
RHCoInst64.dll : 1.0.7.0  
RHDME64.dll : 6.0.6000.109  
RtkHDM64.dll : 11.0.6000.126

XP/2K x86:  
RtkHDM.sys : 5.10.0.5992  
Rtaupd.exe : 2.8.0.1  
RHCoInstXP.dll : 1.0.7.0

XP/2K x64:  
RtkHDMX.sys : 5.10.0.5992  
Rtaupd64.exe : 2.8.0.1  
RHCoInst64XP.dll : 1.0.7.0

Driver Setup Program : 2.92

Windows 2000/XP Operate on :  
Microsoft High Definition Audio Driver Package - KB888111  
Package file version (kb888111.exe) : 6.1.22.0  
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.40

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC892, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC892, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680

3. HDM Device WHQL Support: ATI HDM Devices

4. OS Supporting: Microsoft WindowsXP, Windows2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 - x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :  
RTKHDA64.sys : 5.10.0.6013  
RTKHDAUD.sys : 5.10.0.6013  
McCal.exe : 1.1.2.2  
RTHDCPL.exe : 2.3.2.8  
RtkAudioService64.exe : 1.0.0.19  
RtkAudioService.exe : 1.0.0.19  
RTLCPPL.exe : 1.0.1.66  
RtlUpd64.exe : 2.8.0.1  
RtlUpd.exe : 2.8.0.1  
SkyTel.exe : 2.0.2.0  
SoundMan.exe : 1.0.0.32  
vncutil64.exe : 1.0.0.38  
vncutil.exe : 1.0.0.38  
Alcmtr.exe : 1.6.0.4  
AlcWzrd.exe : 1.1.0.37  
Mnfltl.sys : 5.10.0.4112  
Mnft64.sys : 5.10.0.4115  
OA017Afx.sys : 1.0.7.3  
AMBFlt.sys : 5.10.0.4240  
AMBft64.sys : 5.10.0.4240  
RTSndMgr.cpl : 1.0.1.4  
ALSndMgr.cpl : 1.0.0.11  
RCoInst64XP.dll : 1.0.7.9

Readme.txt

```

RTCOMDLL.dll : 1.0.0.103
RtkCoInstXP.dll : 1.0.7.9
RtlCPAPI.dll : 1.0.2.3
Vista/Win7 driver : -----
Vista/Win7 driver for x86
RTKVHDA.sys : 6.0.1.6013
AERTSrv.exe : 1.0.32.10
APOPCH.exe : 1.0.0.0
RtHDVBg.exe : 1.0.0.8
RtHDVCpl.exe : 1.0.0.463
RtkAudioService.exe : 1.0.0.24
RtkNGUI.exe : 0.0.0.21
RtlUpd.exe : 2.8.0.1
SkyTel.exe : 2.0.2.2
vncutil.exe : 1.0.0.38
mbfilt32.sys : 6.10.0.8
RTSndMgr.cpl : 1.0.0.18
AERTACap.dll : 2.0.32.9
AERTARen.dll : 1.0.32.9
BlackSkinImages.dll : 0.0.0.21
DarkSkinImages.dll : 0.0.0.21
DTSBassEnhancementDLL.dll : 1.0.0.1
DTSBoostDLL.dll : 1.0.0.1
DTSGainCompensatorDLL.dll : 1.0.0.1
DTSGFXAPO.dll : 1.0.0.1
DTSLFXAPO.dll : 1.0.0.1
DTSLimitDLL.dll : 1.0.0.1
DTSNeoPCDLL.dll : 1.0.0.1
DTSS2HeadphoneDLL.dll : 1.0.0.1
DTSS2SpeakerDLL.dll : 1.0.0.1
DTSVoiceClarityDLL.dll : 1.0.0.1
FMAP0.dll : 42.5.23.65
LightSkinImages.dll : 0.0.0.21
MaxxAudioAPO.dll : 1.2.2.0
MaxxAudioAPO20.dll : 2.2.6.0
MaxxAudioEQ.dll : 5.9.7.0
MBAP032.dll : 1.0.19.0
MBPPCn32.dll : 1.0.0.110
MBppld32.dll : 1.0.22.0
MBTHX32.dll : 1.0.15.103
MBWrp32.dll : 1.0.0.110
RP3DAA32.dll : 6.0.6001.18
RP3DHT32.dll : 6.0.6001.18
RTCOMDLL.dll : 2.0.0.124
RTEED32A.dll : 6.1.6001.33
RTEEG32A.dll : 6.1.6001.33
RTEEL32A.dll : 6.1.6001.33
RTEEP32A.dll : 6.1.6001.33
RtkAPO.dll : 11.0.6000.130
RtkApoApi.dll : 1.0.0.20
RtkCfg.dll : 1.0.0.2
RtkCoInst.dll : 1.0.7.9
RtkPgExt.dll : 6.0.6000.112
RtlCPAPI.dll : 1.0.2.4
SFFXComm.dll : 2.0.0.9
SFFXDAP0.dll : 2.0.0.9
SFFXHAP0.dll : 2.0.0.9
SFFXProc.dll : 2.0.0.9
SFFXSAP0.dll : 2.0.0.9
slcshp32.dll : 1.0.3.0
slgeq32.dll : 1.0.1.0
slh36032.dll : 1.0.2.0
slinit32.dll : 1.1.3.0
slmaxv32.dll : 1.1.2.0
sltshd32.dll : 1.1.1.0
sluapo32.dll : 1.8.24.0
SRSHP360.dll : 1.1.0.0
SRSTSHD.dll : 1.1.4.0
SRSTSXT.dll : 3.2.0.0

```



	Readme.txt	
SRSWOW.dll	:	1.1.3.0
WavesLib.dll	:	5.9.7.0
Vista/Win7 driver for x64		
RTKVHD64.sys	:	6.0.1.6013
AERTSr64.exe	:	1.0.64.10
APOPCH.exe	:	1.0.0.0
RAVBg64.exe	:	1.0.0.8
RAVCpl64.exe	:	1.0.0.463
RtkAudioService64.exe	:	1.0.0.24
RtkNGUI64.exe	:	0.0.0.21
RtlUpd64.exe	:	2.8.0.1
SkyTel.exe	:	2.0.2.2
vncutil64.exe	:	1.0.0.38
GWfilt64.sys	:	6.10.0.3
mbfilt64.sys	:	6.10.0.8
RTSnMg64.cpl	:	1.0.0.18
AERTAC64.dll	:	2.0.64.9
AERTAR64.dll	:	1.0.64.9
BlackSkinImages64.dll	:	0.0.0.21
DarkSkinImages64.dll	:	0.0.0.21
DTSBassEnhancementDLL64.dll	:	1.0.0.1
DTSBoostDLL64.dll	:	1.0.0.1
DTSGainCompensatorDLL64.dll	:	1.0.0.1
DTSAFXAP064.dll	:	1.0.0.1
DTSLFXAP064.dll	:	1.0.0.1
DTSLimitDLL64.dll	:	1.0.0.1
DTSNeoPCDLL64.dll	:	1.0.0.1
DTSS2HeadphoneDLL64.dll	:	1.0.0.1
DTSS2SpeakerDLL64.dll	:	1.0.0.1
DTSVoiceClarityDLL64.dll	:	1.0.0.1
FMAP064.dll	:	42.6.23.65
LightSkinImages64.dll	:	0.0.0.21
MaxxAudioAP020.dll	:	2.2.6.0
MaxxAudioEQ.dll	:	5.9.7.0
MBAP032.dll	:	1.0.19.0
MBAP064.dll	:	1.0.19.0
MBPPCn64.dll	:	1.0.0.110
MBpld64.dll	:	1.0.22.0
MBTHX32.dll	:	1.0.15.103
MBTHX64.dll	:	1.0.15.103
MBWrp64.dll	:	1.0.0.110
RCoInst64.dll	:	1.0.7.9
RP3DAA64.dll	:	6.0.6001.18
RP3DHT64.dll	:	6.0.6001.18
RtCOM64.dll	:	2.0.0.123
RTCOMDLL.dll	:	2.0.0.123
RTEED64A.dll	:	6.1.6001.33
RTEEG64A.dll	:	6.1.6001.33
RTEEL64A.dll	:	6.1.6001.33
RTEEP64A.dll	:	6.1.6001.33
RtkApi64.dll	:	1.0.0.20
RtkAP064.dll	:	11.0.6000.130
RtkCfg.dll	:	1.0.0.1
RtkCfg64.dll	:	1.0.0.2
RtlCPAPI.dll	:	1.0.2.4
RtlCPAPI64.dll	:	1.0.2.4
RtPgEx64.dll	:	6.0.6000.112
SFComm64.dll	:	2.0.0.9
SFDAP064.dll	:	2.0.0.9
SFHAP064.dll	:	2.0.0.9
SFProc64.dll	:	2.0.0.9
SFSAP064.dll	:	2.0.0.9
slcshp64.dll	:	1.0.3.0
slgeq64.dll	:	1.0.1.0
slh36064.dll	:	1.0.2.0
slInit64.dll	:	1.1.3.0
slmaxv64.dll	:	1.1.2.0
sltshd64.dll	:	1.1.1.0
sluapo64.dll	:	1.8.24.0

Readme.txt

SRSHP64.dll : 1.1.0.0  
 SRSTSH64.dll : 1.1.4.0  
 SRSTXS64.dll : 3.2.0.0  
 SRSWOW64.dll : 1.1.3.0  
 WavesGUILib.dll : 1.2.3.4  
 HDM Driver : -----  
 Vista/Win7 x86:  
 RtHDMV.sys : 6.0.1.5992  
 RtkAudioSrvATI.exe : 1.0.0.23  
 RtkUpd.exe : 2.8.0.1  
 RH3DAA32.dll : 6.0.6001.18  
 RH3DHT32.dll : 6.0.6001.18  
 RHCoInst.dll : 1.0.7.0  
 RHDMEExt.dll : 6.0.6000.109  
 RtkHDM.dll : 11.0.6000.126  
  
 Vista/Win7 x64:  
 RtHDMVX.sys : 6.0.1.5992  
 RtkAudioSrvATI64.exe : 1.0.0.23  
 RtkUpd64.exe : 2.8.0.1  
 RH3DAA64.dll : 6.0.6001.18  
 RH3DHT64.dll : 6.0.6001.18  
 RHCoInst64.dll : 1.0.7.0  
 RHDME64.dll : 6.0.6000.109  
 RtkHDM64.dll : 11.0.6000.126  
  
 XP/2K x86:  
 RtkHDM.sys : 5.10.0.5992  
 Rtaupd.exe : 2.8.0.1  
 RHCoInstXP.dll : 1.0.7.0  
  
 XP/2K x64:  
 RtkHDMX.sys : 5.10.0.5992  
 Rtaupd64.exe : 2.8.0.1  
 RHCoInst64XP.dll : 1.0.7.0  
  
 Driver Setup Program : 2.89  
  
 Windows 2000/XP Operate on :  
 Microsoft High Definition Audio Driver Package - KB888111  
 Package file version (kb888111.exe) : 6.1.22.0  
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.39

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC892, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC892, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 - x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
  - 1.) Driver :
    1. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :  
 RTKHDA64.sys : 5.10.0.6000  
 RTKHDAUD.sys : 5.10.0.6000  
 McCal.exe : 1.1.2.2  
 RTHDCPL.exe : 2.3.2.5  
 RtkAudioService64.exe : 1.0.0.19  
 RtkAudioService.exe : 1.0.0.19  
 RTLCPL.exe : 1.0.1.66  
 RtlUpd64.exe : 2.8.0.1

Readme.txt

```

RtlUpd.exe           : 2.8.0.1
SkyTel.exe           : 2.0.2.0
SoundMan.exe         : 1.0.0.32
vncutil64.exe        : 1.0.0.38
vncutil.exe          : 1.0.0.38
Alcmtr.exe           : 1.6.0.4
AlcWzrd.exe          : 1.1.0.37
AMBfilt.sys          : 5.10.0.4240
AMBft64.sys          : 5.10.0.4240
Mbnfilt.sys          : 5.10.0.4112
Mbnft64.sys          : 5.10.0.4115
OA017Afx.sys         : 1.0.7.3
RTSndMgr.cpl         : 1.0.1.4
ALSndMgr.cpl         : 1.0.0.11
RCoInst64XP.dll      : 1.0.7.8
RTCOMDLL.dll         : 1.0.0.103
RtkCoInstXP.dll      : 1.0.7.8
RtlCPAPI.dll         : 1.0.2.3
Vista/Wn7 driver : -----
Vista/Wn7 driver for x86
RTKVHDA.sys          : 6.0.1.6000
AERTSrv.exe          : 1.0.32.10
APOPCH.exe           : 1.0.0.0
RtHDVBg.exe          : 1.0.0.8
RtHDVCpl.exe         : 1.0.0.456
RtkAudioService.exe : 1.0.0.24
RtkNGUI.exe          : 0.0.0.17
RtlUpd.exe           : 2.8.0.1
SkyTel.exe           : 2.0.2.2
vncutil.exe          : 1.0.0.38
mbfilt32.sys         : 6.10.0.8
RTSndMgr.cpl         : 1.0.0.18
AERTACap.dll         : 2.0.32.9
AERTARen.dll         : 1.0.32.9
BlackSkinImages.dll : 0.0.0.17
DarkSkinImages.dll  : 0.0.0.17
FMAP0.dll            : 42.5.21.67
LightSkinImages.dll : 0.0.0.17
MaxxAudioAPO.dll    : 1.2.2.0
MaxxAudioAPO20.dll  : 2.2.6.0
MaxxAudioEQ.dll     : 5.9.7.0
MBAPO32.dll          : 1.0.19.0
MBPPCn32.dll         : 1.0.0.110
MBpld32.dll          : 1.0.22.0
MBTHX32.dll          : 1.0.8.108
MBWrp32.dll          : 1.0.0.110
RP3DAA32.dll         : 6.0.6001.18
RP3DHT32.dll         : 6.0.6001.18
RTCOMDLL.dll         : 2.0.0.124
RTEED32A.dll         : 6.1.6001.32
RTEEG32A.dll         : 6.1.6001.32
RTEEL32A.dll         : 6.1.6001.32
RTEEP32A.dll         : 6.1.6001.32
RtkAPO.dll           : 11.0.6000.129
RtkApoApi.dll        : 1.0.0.19
RtkCfg.dll           : 1.0.0.2
RtkColnst.dll        : 1.0.7.8
RtkPgExt.dll         : 6.0.6000.112
RtlCPAPI.dll         : 1.0.2.4
SFFXComm.dll         : 2.0.0.9
SFFXDAP0.dll         : 2.0.0.9
SFFXHAP0.dll         : 2.0.0.9
SFFXProc.dll         : 2.0.0.9
SFFXSAP0.dll         : 2.0.0.9
slcshp32.dll         : 1.0.3.0
slgeq32.dll          : 1.0.1.0
slh36032.dll         : 1.0.2.0
slinit32.dll         : 1.1.3.0
slmaxv32.dll         : 1.1.2.0

```

	Readme.txt	
sltshd32.dll		: 1.1.1.0
sluapo32.dll		: 1.8.24.0
SRSHp360.dll		: 1.1.0.0
SRSTSHD.dll		: 1.1.4.0
SRSTsXT.dll		: 3.2.0.0
SRSWOW.dll		: 1.1.3.0
WavesLib.dll		: 5.9.7.0
Vista/Win7 driver for x64		
RTKVHD64.sys		: 6.0.1.6000
AERTSr64.exe		: 1.0.64.10
APOPCH.exe		: 1.0.0.0
RAVBg64.exe		: 1.0.0.8
RAVCpl64.exe		: 1.0.0.456
RtkAudioService64.exe		: 1.0.0.24
RtkNGUI64.exe		: 0.0.0.17
RtlUpd64.exe		: 2.8.0.1
SkyTel.exe		: 2.0.2.2
vncutil64.exe		: 1.0.0.38
GWfilt64.sys		: 6.10.0.3
mbfilt64.sys		: 6.10.0.8
RTSnMg64.cpl		: 1.0.0.18
AERTAC64.dll		: 2.0.64.9
AERTAR64.dll		: 1.0.64.9
BlackSkinImages64.dll		: 0.0.0.17
DarkSkinImages64.dll		: 0.0.0.17
FMAP064.dll		: 42.6.21.67
LightSkinImages64.dll		: 0.0.0.17
MaxxAudioAP020.dll		: 2.2.6.0
MaxxAudioEQ.dll		: 5.9.7.0
MBAP032.dll		: 1.0.19.0
MBAP064.dll		: 1.0.19.0
MBPPCn64.dll		: 1.0.0.110
Mbpld64.dll		: 1.0.22.0
MBTHX32.dll		: 1.0.8.108
MBTHX64.dll		: 1.0.8.108
MBWrp64.dll		: 1.0.0.110
RCoInst64.dll		: 1.0.7.8
RP3DAA64.dll		: 6.0.6001.18
RP3DHT64.dll		: 6.0.6001.18
RtCOMB4.dll		: 2.0.0.123
RTCOMDLL.dll		: 2.0.0.123
RTEED64A.dll		: 6.1.6001.32
RTEEG64A.dll		: 6.1.6001.32
RTEEL64A.dll		: 6.1.6001.32
RTEEP64A.dll		: 6.1.6001.32
RtkApi64.dll		: 1.0.0.19
RtkAP064.dll		: 11.0.6000.129
RtkCfg.dll		: 1.0.0.1
RtkCfg64.dll		: 1.0.0.2
RtlCPAPI.dll		: 1.0.2.4
RtlCPAPI64.dll		: 1.0.2.4
RtPgEx64.dll		: 6.0.6000.112
SFComm64.dll		: 2.0.0.9
SFDAPO64.dll		: 2.0.0.9
SFHAP064.dll		: 2.0.0.9
SFProc64.dll		: 2.0.0.9
SFSAP064.dll		: 2.0.0.9
slcshp64.dll		: 1.0.3.0
slgeq64.dll		: 1.0.1.0
slh36064.dll		: 1.0.2.0
slInit64.dll		: 1.1.3.0
slmaxv64.dll		: 1.1.2.0
sltshd64.dll		: 1.1.1.0
sluapo64.dll		: 1.8.24.0
SRSHp64.dll		: 1.1.0.0
SRSTSH64.dll		: 1.1.4.0
SRSTsX64.dll		: 3.2.0.0
SRSWOW64.dll		: 1.1.3.0
WavesGUILib.dll		: 1.2.3.4

Readme.txt

```

HDM Driver : -----
Vista/Wi n7 x86:
RtHDMV.sys : 6.0.1.5992
RtkAudioSrvATI.exe : 1.0.0.23
RtkUpd.exe : 2.8.0.1
RH3DAA32.dll : 6.0.6001.18
RH3DHT32.dll : 6.0.6001.18
RHCoInst.dll : 1.0.7.0
RHDMExt.dll : 6.0.6000.109
RtkHDM.dll : 11.0.6000.126

Vista/Wi n7 x64:
RtHDMVX.sys : 6.0.1.5992
RtkAudioSrvATI64.exe : 1.0.0.23
RtkUpd64.exe : 2.8.0.1
RH3DAA64.dll : 6.0.6001.18
RH3DHT64.dll : 6.0.6001.18
RHCoInst64.dll : 1.0.7.0
RHDMEx64.dll : 6.0.6000.109
RtkHDM64.dll : 11.0.6000.126

XP/2K x86:
RtkHDM.sys : 5.10.0.5992
Rtaupd.exe : 2.8.0.1
RHCoInstXP.dll : 1.0.7.0

XP/2K x64:
RtkHDMX.sys : 5.10.0.5992
Rtaupd64.exe : 2.8.0.1
RHCoInst64XP.dll : 1.0.7.0

Driver Setup Program : 2.89

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

```

//=====

Driver Package R2.38

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC892, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275
  2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC892, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275
  3. HDM Device WHQL Support: ATI HDM Devices
  4. OS Supporting: Microsoft WindowsXP, Windows2000, Windows Server 2003, Vista, Windows Server 2008,
- Windows7 - x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
  6. Add/Fix

1.) Driver :

1. Customizations.
2. Support graphic EQ feature.

Windows 2000/XP : -----

Windows 2000/XP :

```

RTKHDA64.sys : 5.10.0.5995
RTKHDAUD.sys : 5.10.0.5995
Alcmtr.exe : 1.6.0.4
AlcWzrd.exe : 1.1.0.37
MicCal.exe : 1.1.2.2
RTHDCPL.exe : 2.3.2.4
RtkAudioService64.exe : 1.0.0.19
RtkAudioService.exe : 1.0.0.19
RTLCPPL.exe : 1.0.1.66
RtlUpd64.exe : 2.8.0.1
RtlUpd.exe : 2.8.0.1
SkyTel.exe : 2.0.2.0

```

```

                                Readme.txt
SoundMan.exe                   : 1.0.0.32
vncutil64.exe                 : 1.0.0.38
vncutil.exe                   : 1.0.0.38
AMBFilt.sys                   : 5.10.0.4240
AMBft64.sys                   : 5.10.0.4240
Mbnfilt.sys                   : 5.10.0.4112
Mbnft64.sys                   : 5.10.0.4115
OA017Afx.sys                 : 1.0.7.3
ALSndMgr.cpl                 : 1.0.0.11
RTSndMgr.cpl                 : 1.0.1.4
RCoInst64XP.dll              : 1.0.7.6
RTCOMDLL.dll                 : 1.0.0.103
RtkCoInstXP.dll              : 1.0.7.6
RtlCPAPI.dll                 : 1.0.2.3
Vista/Wn7 driver : -----
Vista/Wn7 driver for x86
RTKVHDA.sys                   : 6.0.1.5995
AERTSrv.exe                   : 1.0.32.10
APOPCH.exe                    : 1.0.0.0
RtHDVbg.exe                   : 1.0.0.8
RtHDVcpl.exe                  : 1.0.0.453
RtkAudioService.exe          : 1.0.0.24
RtkNGUI.exe                   : 0.0.0.15
RtlUpd.exe                    : 2.8.0.1
SkyTel.exe                    : 2.0.2.2
vncutil.exe                   : 1.0.0.38
mbfilt32.sys                  : 6.10.0.8
RTSndMgr.cpl                 : 1.0.0.18
AERTACap.dll                 : 2.0.32.9
AERTARen.dll                 : 1.0.32.9
BlackSkinImages.dll          : 0.0.0.15
DarkSkinImages.dll           : 0.0.0.15
FMAP0.dll                     : 42.5.21.66
LightSkinImages.dll          : 0.0.0.15
MaxxAudioAPO.dll             : 1.2.2.0
MaxxAudioAPO20.dll           : 2.2.6.0
MaxxAudioEQ.dll              : 5.9.7.0
MBAP032.dll                   : 1.0.19.0
MBPPCn32.dll                 : 1.0.0.110
MBpld32.dll                   : 1.0.22.0
MBTHX32.dll                   : 1.0.8.108
MBWrp32.dll                   : 1.0.0.110
RP3DAA32.dll                 : 6.0.6001.18
RP3DHT32.dll                 : 6.0.6001.18
RTCOMDLL.dll                 : 2.0.0.124
RTEED32A.dll                 : 6.1.6001.32
RTEEG32A.dll                 : 6.1.6001.32
RTEEL32A.dll                 : 6.1.6001.32
RTEEP32A.dll                 : 6.1.6001.32
RtkAPO.dll                    : 11.0.6000.127
RtkApoApi.dll                : 1.0.0.17
RtkCfg.dll                   : 1.0.0.2
RtkCoInst.dll                : 1.0.7.7
RtkPgExt.dll                 : 6.0.6000.109
RtlCPAPI.dll                 : 1.0.2.4
SFFXComm.dll                 : 2.0.0.9
SFFXDAP0.dll                 : 2.0.0.9
SFFXHAP0.dll                 : 2.0.0.9
SFFXProc.dll                 : 2.0.0.9
SFFXSAP0.dll                 : 2.0.0.9
slcshp32.dll                 : 1.0.3.0
slgeq32.dll                  : 1.0.1.0
slh36032.dll                 : 1.0.2.0
slInit32.dll                 : 1.1.3.0
slmaxv32.dll                 : 1.1.2.0
sltshd32.dll                 : 1.1.1.0
sluapo32.dll                 : 1.8.24.0
SRSHP360.dll                 : 1.1.0.0
SRSTSHD.dll                  : 1.1.4.0

```

	Readme.txt	
SRSTSXT.dll	:	3.2.0.0
SRSWOW.dll	:	1.1.3.0
WavesLib.dll	:	5.9.7.0
Vista/Win7 driver for x64		
RTKVHD64.sys	:	6.0.1.5995
AERTSr64.exe	:	1.0.64.10
APOPCH.exe	:	1.0.0.0
RAVBg64.exe	:	1.0.0.8
RAVCpl64.exe	:	1.0.0.453
RtkAudioService64.exe	:	1.0.0.24
RtkNGUI64.exe	:	0.0.0.15
RtlUpd64.exe	:	2.8.0.1
SkyTel.exe	:	2.0.2.2
vncutil64.exe	:	1.0.0.38
GWfilt64.sys	:	6.10.0.3
mbfilt64.sys	:	6.10.0.8
RTSnMg64.cpl	:	1.0.0.18
AERTAC64.dll	:	2.0.64.9
AERTAR64.dll	:	1.0.64.9
BlackSkinImages64.dll	:	0.0.0.15
DarkSkinImages64.dll	:	0.0.0.15
FMAP064.dll	:	42.6.21.66
LightSkinImages64.dll	:	0.0.0.15
MaxxAudioAPO20.dll	:	2.2.6.0
MaxxAudioEQ.dll	:	5.9.7.0
MBAP032.dll	:	1.0.19.0
MBAP064.dll	:	1.0.19.0
MBPPCn64.dll	:	1.0.0.110
Mbpld64.dll	:	1.0.22.0
MBTHX32.dll	:	1.0.8.108
MBTHX64.dll	:	1.0.8.108
MBWrp64.dll	:	1.0.0.110
RCoInst64.dll	:	1.0.7.7
RP3DAA64.dll	:	6.0.6001.18
RP3DHT64.dll	:	6.0.6001.18
RtCOMB4.dll	:	2.0.0.123
RTCOMDLL.dll	:	2.0.0.123
RTEED64A.dll	:	6.1.6001.32
RTEEG64A.dll	:	6.1.6001.32
RTEEL64A.dll	:	6.1.6001.32
RTEEP64A.dll	:	6.1.6001.32
RtkApi64.dll	:	1.0.0.17
RtkAPO64.dll	:	11.0.6000.127
RtkCfg.dll	:	1.0.0.1
RtkCfg64.dll	:	1.0.0.2
RtlCPAPI.dll	:	1.0.2.4
RtlCPAPI64.dll	:	1.0.2.4
RtPgEx64.dll	:	6.0.6000.109
SFComm64.dll	:	2.0.0.9
SFDAP064.dll	:	2.0.0.9
SFHAP064.dll	:	2.0.0.9
SFProc64.dll	:	2.0.0.9
SFSAP064.dll	:	2.0.0.9
slcshp64.dll	:	1.0.3.0
slgeq64.dll	:	1.0.1.0
slh36064.dll	:	1.0.2.0
slInit64.dll	:	1.1.3.0
slmaxv64.dll	:	1.1.2.0
sltshd64.dll	:	1.1.1.0
sluapo64.dll	:	1.8.24.0
SRSHP64.dll	:	1.1.0.0
SRSTSH64.dll	:	1.1.4.0
SRSTSX64.dll	:	3.2.0.0
SRSWOW64.dll	:	1.1.3.0
WavesGUILib.dll	:	1.2.3.4
HDMI Driver :	-----	
Vista/Win7 x86:		
RtHDMV.sys	:	6.0.1.5945
RtkAudioSrvATI.exe	:	1.0.0.23

Readme.txt

RtkUpd.exe : 2.8.0.0  
RH3DAA32.dll : 6.0.6001.18  
RH3DHT32.dll : 6.0.6001.18  
RHCoInst.dll : 1.0.7.0  
RHDMEExt.dll : 6.0.6000.100  
RtkHDM.dll : 11.0.6000.113

Vista/Win7 x64:

RtHDMVX.sys : 6.0.1.5945  
RtkAudioSrvATI64.exe : 1.0.0.23  
RtkUpd64.exe : 2.8.0.0  
RH3DAA64.dll : 6.0.6001.18  
RH3DHT64.dll : 6.0.6001.18  
RHCoInst64.dll : 1.0.7.0  
RHDMEx64.dll : 6.0.6000.100  
RtkHDM64.dll : 11.0.6000.113

XP/2K x86:

RtkHDM.sys : 5.10.0.5945  
Rtaupd.exe : 2.8.0.0  
RHCoInstXP.dll : 1.0.7.0

XP/2K x64:

RtkHDMX.sys : 5.10.0.5945  
Rtaupd64.exe : 2.8.0.0  
RHCoInst64XP.dll : 1.0.7.0

Driver Setup Program : 2.89

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111  
Package file version (kb888111.exe) : 6.1.22.0  
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.37

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC892, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC892, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275

3. HDM Device WHQL Support: ATI HDM Devices

4. OS Supporting: Microsoft WindowsXP, Windows2000, Windows Server 2003, Vista, Windows Server 2008,

Windows7 - x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :

RTKHDA64.sys : 5.10.0.5983  
RTKHDAUD.sys : 5.10.0.5983  
McCal.exe : 1.1.2.2  
RTHDCPL.exe : 2.3.2.4  
RtkAudioService64.exe : 1.0.0.19  
RtkAudioService.exe : 1.0.0.19  
RTLCPPL.exe : 1.0.1.66  
RtlUpd64.exe : 2.8.0.0  
RtlUpd.exe : 2.8.0.0  
SkyTel.exe : 2.0.2.0  
SoundMan.exe : 1.0.0.32  
vncutil64.exe : 1.0.0.37  
vncutil.exe : 1.0.0.37  
Alcmtr.exe : 1.6.0.4  
AlcWzrd.exe : 1.1.0.37  
AMBFT64.sys : 5.10.0.4240  
Mbnfilt.sys : 5.10.0.4112



Readme.txt

```

Mnft64.sys : 5.10.0.4115
OA017Afx.sys : 1.0.7.3
AMBFilter.sys : 5.10.0.4240
RTSndMgr.cpl : 1.0.1.4
ALSndMgr.cpl : 1.0.0.11
RCoInst64XP.dll : 1.0.7.6
RTCOMDLL.dll : 1.0.0.103
RtkCoInstXP.dll : 1.0.7.6
RtlCPAPI.dll : 1.0.2.3
Vista/Win7 driver : -----
Vista/Win7 driver for x86
RTKVHDA.sys : 6.0.1.5983
AERTSrv.exe : 1.0.32.9
APOPCH.exe : 1.0.0.0
RtHDVBg.exe : 1.0.0.6
RtHDVCpl.exe : 1.0.0.447
RtkAudioService.exe : 1.0.0.24
RtlUpd.exe : 2.8.0.0
SkyTel.exe : 2.0.2.2
vncutil.exe : 1.0.0.37
mbfilter32.sys : 6.10.0.8
RTSndMgr.cpl : 1.0.0.17
AERTACap.dll : 2.0.32.8
AERTARen.dll : 1.0.32.8
FMAP0.dll : 42.5.21.66
MaxxAudioAP0.dll : 1.2.2.0
MaxxAudioAP020.dll : 2.2.6.0
MaxxAudioEQ.dll : 5.9.7.0
MBAP032.dll : 1.0.19.0
MBPPCn32.dll : 1.0.0.110
MBppld32.dll : 1.0.22.0
MBTHX32.dll : 1.0.8.107
MBWrp32.dll : 1.0.0.110
RP3DAA32.dll : 6.0.6001.18
RP3DHT32.dll : 6.0.6001.18
RTCOMDLL.dll : 2.0.0.123
RTEED32A.dll : 6.1.6001.32
RTEEG32A.dll : 6.1.6001.32
RTEEL32A.dll : 6.1.6001.32
RTEEP32A.dll : 6.1.6001.32
RtkAP0.dll : 11.0.6000.125
RtkApoApi.dll : 1.0.0.15
RtkCfg.dll : 1.0.0.2
RtkCoInst.dll : 1.0.7.6
RtkPgExt.dll : 6.0.6000.108
RtlCPAPI.dll : 1.0.2.4
SFFXComm.dll : 2.0.0.8
SFFXDAP0.dll : 2.0.0.8
SFFXHAP0.dll : 2.0.0.8
SFFXProc.dll : 2.0.0.8
SFFXSAP0.dll : 2.0.0.8
slcshp32.dll : 1.0.3.0
slgeq32.dll : 1.0.1.0
slh36032.dll : 1.0.2.0
slinit32.dll : 1.1.3.0
slmaxv32.dll : 1.1.2.0
sltshd32.dll : 1.1.1.0
sluapo32.dll : 1.8.22.0
SRSHP360.dll : 1.1.0.0
SRSTSHD.dll : 1.1.4.0
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.1.3.0
WavesLib.dll : 5.9.7.0
Vista/Win7 driver for x64
RTKVHD64.sys : 6.0.1.5983
AERTSr64.exe : 1.0.64.9
APOPCH.exe : 1.0.0.0
RAVBg64.exe : 1.0.0.6
RAVCpl64.exe : 1.0.0.447

```

	Readme.txt	
RtkAudioService64.exe	:	1.0.0.24
RtlUpd64.exe	:	2.8.0.0
SkyTel.exe	:	2.0.2.2
vncutil64.exe	:	1.0.0.37
GWfilt64.sys	:	6.10.0.3
mbfilt64.sys	:	6.10.0.8
RTSnMg64.cpl	:	1.0.0.17
AERTAC64.dll	:	2.0.64.8
AERTAR64.dll	:	1.0.64.8
FMAP064.dll	:	42.6.21.66
MaxxAudioAP020.dll	:	2.2.6.0
MaxxAudioEQ.dll	:	5.9.7.0
MBAP032.dll	:	1.0.19.0
MBAP064.dll	:	1.0.19.0
MBPPCn64.dll	:	1.0.0.110
MBpld64.dll	:	1.0.22.0
MBTHX32.dll	:	1.0.8.107
MBTHX64.dll	:	1.0.8.107
MBWrp64.dll	:	1.0.0.110
RCoInst64.dll	:	1.0.7.6
RP3DAA64.dll	:	6.0.6001.18
RP3DHT64.dll	:	6.0.6001.18
RtCOM64.dll	:	2.0.0.123
RTCOMDLL.dll	:	2.0.0.123
RTEED64A.dll	:	6.1.6001.32
RTEEG64A.dll	:	6.1.6001.32
RTEEL64A.dll	:	6.1.6001.32
RTEEP64A.dll	:	6.1.6001.32
RtkApi64.dll	:	1.0.0.15
RtkAP064.dll	:	11.0.6000.125
RtkCfg.dll	:	1.0.0.1
RtkCfg64.dll	:	1.0.0.2
RtlCPAPI.dll	:	1.0.2.4
RtlCPAPI64.dll	:	1.0.2.4
RtPgEx64.dll	:	6.0.6000.108
SFComm64.dll	:	2.0.0.8
SFDAPO64.dll	:	2.0.0.8
SFHAP064.dll	:	2.0.0.8
SFProc64.dll	:	2.0.0.8
SFSAP064.dll	:	2.0.0.8
slcshp64.dll	:	1.0.3.0
slgeq64.dll	:	1.0.1.0
slh36064.dll	:	1.0.2.0
slInit64.dll	:	1.1.3.0
slmaxv64.dll	:	1.1.2.0
sltshd64.dll	:	1.1.1.0
sluapo64.dll	:	1.8.22.0
SRSHP64.dll	:	1.1.0.0
SRSTSH64.dll	:	1.1.4.0
SRSTX64.dll	:	3.2.0.0
SRSW064.dll	:	1.1.3.0
WavesGUILib.dll	:	1.2.3.4
-----		
HDMI Driver :		
Vista/Win7 x86:		
RtHDMV.sys	:	6.0.1.5945
RtkAudioSrvATI.exe	:	1.0.0.23
RtkUpd.exe	:	2.8.0.0
RH3DAA32.dll	:	6.0.6001.18
RH3DHT32.dll	:	6.0.6001.18
RHCoInst.dll	:	1.0.7.0
RHDMExt.dll	:	6.0.6000.100
RtkHDM.dll	:	11.0.6000.113
Vista/Win7 x64:		
RtHDMVX.sys	:	6.0.1.5945
RtkAudioSrvATI64.exe	:	1.0.0.23
RtkUpd64.exe	:	2.8.0.0
RH3DAA64.dll	:	6.0.6001.18
RH3DHT64.dll	:	6.0.6001.18

Readme.txt

RHCoInst64.dll : 1.0.7.0  
RHDME64.dll : 6.0.6000.100  
RtkHDM64.dll : 11.0.6000.113

XP/2K x86:  
RtkHDM.sys : 5.10.0.5945  
Rtaupd.exe : 2.8.0.0  
RHCoInstXP.dll : 1.0.7.0

XP/2K x64:  
RtkHDMX.sys : 5.10.0.5945  
Rtaupd64.exe : 2.8.0.0  
RHCoInst64XP.dll : 1.0.7.0

Driver Setup Program : 2.88

Windows 2000/XP Operate on :  
Microsoft High Definition Audio Driver Package - KB888111  
Package file version (kb888111.exe) : 6.1.22.0  
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.36

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275

3. HDM Device WHQL Support: ATI HDM Devices

4. OS Supporting: Microsoft WindowsXP, Windows2000, Windows Server 2003, Vista, Windows Server 2008,

Windows7 - x86/x64  
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix  
1.) Driver :  
1. Customizations.  
2.) Package :  
1. Fix some presentation string of Upgraded dialog in small VGA Mode .

Windows 2000/XP : -----

Windows 2000/XP :  
RTKHDA64.sys : 5.10.0.5969  
RTKHDAUD.sys : 5.10.0.5969  
Alcmtr.exe : 1.6.0.4  
AlcWzrd.exe : 1.1.0.37  
McCal.exe : 1.1.2.2  
RTHDCPL.exe : 2.3.2.1  
RtkAudioService64.exe : 1.0.0.19  
RtkAudioService.exe : 1.0.0.19  
RTLCPPL.exe : 1.0.1.66  
RtlUpd64.exe : 2.8.0.0  
RtlUpd.exe : 2.8.0.0  
SkyTel.exe : 2.0.2.0  
SoundMan.exe : 1.0.0.32  
vncutil64.exe : 1.0.0.33  
vncutil.exe : 1.0.0.33  
AMBfilt.sys : 5.10.0.4240  
AMBft64.sys : 5.10.0.4240  
Mbnfilt.sys : 5.10.0.4112  
Mbnft64.sys : 5.10.0.4115  
ALSndMgr.cpl : 1.0.0.11  
RTSndMgr.cpl : 1.0.1.4  
RCoInst64XP.dll : 1.0.7.5  
RtCOMDLL.dll : 1.0.0.103  
RtkCoInstXP.dll : 1.0.7.5  
RtlCPAPI.dll : 1.0.2.3

Vista/Win7 driver : -----

Vista/Win7 driver for x86

	Readme.txt	
RTKVHDA.sys		: 6.0.1.5969
AERTSrv.exe		: 1.0.32.9
APOPCH.exe		: 1.0.0.0
RtHDVBg.exe		: 1.0.0.6
RtHDVCpl.exe		: 1.0.0.439
RtkAudioService.exe		: 1.0.0.24
RtlUpd.exe		: 2.8.0.0
SkyTel.exe		: 2.0.2.2
vncutil.exe		: 1.0.0.33
mbfilt32.sys		: 6.10.0.8
RTSndMgr.cpl		: 1.0.0.17
AERTACap.dll		: 2.0.32.8
AERTARen.dll		: 1.0.32.8
FMAP0.dll		: 42.5.21.65
MaxxAudioAPO.dll		: 1.2.2.0
MaxxAudioAPO20.dll		: 2.2.6.0
MaxxAudioEQ.dll		: 5.9.7.0
MBAP032.dll		: 1.0.19.0
MBPPCn32.dll		: 1.0.0.110
MBpld32.dll		: 1.0.22.0
MBTHX32.dll		: 1.0.8.107
MBWrp32.dll		: 1.0.0.110
RP3DAA32.dll		: 6.0.6001.18
RP3DHT32.dll		: 6.0.6001.18
RTCOMDLL.dll		: 2.0.0.121
RTEED32A.dll		: 6.1.6001.29
RTEEG32A.dll		: 6.1.6001.29
RTEEL32A.dll		: 6.1.6001.29
RTEEP32A.dll		: 6.1.6001.29
RtkAPO.dll		: 11.0.6000.121
RtkApoApi.dll		: 1.0.0.13
RtkCfg.dll		: 1.0.0.1
RtkColnst.dll		: 1.0.7.5
RtkPgExt.dll		: 6.0.6000.108
RtlCPAPI.dll		: 1.0.2.4
SFFXComm.dll		: 2.0.0.8
SFFXDAP0.dll		: 2.0.0.8
SFFXHAP0.dll		: 2.0.0.8
SFFXProc.dll		: 2.0.0.8
SFFXSAP0.dll		: 2.0.0.8
slcshp32.dll		: 1.0.3.0
slgeq32.dll		: 1.0.1.0
slh36032.dll		: 1.0.2.0
slInit32.dll		: 1.1.3.0
slmaxv32.dll		: 1.1.2.0
sltshd32.dll		: 1.1.1.0
sluapo32.dll		: 1.4.8.0
SRSHP360.dll		: 1.1.0.0
SRSTSHD.dll		: 1.1.4.0
SRSTSXT.dll		: 3.2.0.0
SRSWOW.dll		: 1.1.3.0
WavesLib.dll		: 5.9.7.0
Vista/Win7 driver for x64		
RTKVHD64.sys		: 6.0.1.5969
AERTSr64.exe		: 1.0.64.9
APOPCH.exe		: 1.0.0.0
RAVBg64.exe		: 1.0.0.6
RAVCpl64.exe		: 1.0.0.439
RtkAudioService64.exe		: 1.0.0.24
RtlUpd64.exe		: 2.8.0.0
SkyTel.exe		: 2.0.2.2
vncutil64.exe		: 1.0.0.33
GWfilt64.sys		: 6.10.0.3
mbfilt64.sys		: 6.10.0.8
RTSnMgr64.cpl		: 1.0.0.17
AERTAC64.dll		: 2.0.64.8
AERTAR64.dll		: 1.0.64.8
FMAP064.dll		: 42.6.21.65
MaxxAudioAPO20.dll		: 2.2.6.0

Readme.txt

MBAP032.dll	: 1.0.19.0
MBAP064.dll	: 1.0.19.0
MBPPCn64.dll	: 1.0.0.110
MBppld64.dll	: 1.0.22.0
MBTHX32.dll	: 1.0.8.107
MBTHX64.dll	: 1.0.8.107
MBWrp64.dll	: 1.0.0.110
RCoInst64.dll	: 1.0.7.5
RP3DAA64.dll	: 6.0.6001.18
RP3DHT64.dll	: 6.0.6001.18
RtCOM64.dll	: 2.0.0.121
RTCOMDLL.dll	: 2.0.0.121
RTEED64A.dll	: 6.1.6001.29
RTEEG64A.dll	: 6.1.6001.29
RTEEL64A.dll	: 6.1.6001.29
RTEEP64A.dll	: 6.1.6001.29
RtkApi64.dll	: 1.0.0.13
RtkAPO64.dll	: 11.0.6000.121
RtkCfg.dll	: 1.0.0.1
RtkCfg64.dll	: 1.0.0.1
RtLCPAPI.dll	: 1.0.2.4
RtLCPAPI64.dll	: 1.0.2.4
RtPgEx64.dll	: 6.0.6000.108
SFComm64.dll	: 2.0.0.8
SFDAPO64.dll	: 2.0.0.8
SFHAP064.dll	: 2.0.0.8
SFProc64.dll	: 2.0.0.8
SFSAP064.dll	: 2.0.0.8
slcshp64.dll	: 1.0.3.0
slgeq64.dll	: 1.0.1.0
slh36064.dll	: 1.0.2.0
slInit64.dll	: 1.1.3.0
slmaxv64.dll	: 1.1.2.0
sltshd64.dll	: 1.1.1.0
sluapo64.dll	: 1.4.8.0
SRSHP64.dll	: 1.1.0.0
SRSTSH64.dll	: 1.1.4.0
SRSTSX64.dll	: 3.2.0.0
SRSW064.dll	: 1.1.3.0
<b>HDM Driver : -----</b>	
Vista/Win7 x86:	
RtHDMV.sys	: 6.0.1.5945
RtkAudioSrvATI.exe	: 1.0.0.23
RtkUpd.exe	: 2.8.0.0
RH3DAA32.dll	: 6.0.6001.18
RH3DHT32.dll	: 6.0.6001.18
RHCoInst.dll	: 1.0.7.0
RHDMExt.dll	: 6.0.6000.100
RtkHDM.dll	: 11.0.6000.113
Vista/Win7 x64:	
RtHDMVX.sys	: 6.0.1.5945
RtkAudioSrvATI64.exe	: 1.0.0.23
RtkUpd64.exe	: 2.8.0.0
RH3DAA64.dll	: 6.0.6001.18
RH3DHT64.dll	: 6.0.6001.18
RHCoInst64.dll	: 1.0.7.0
RHDMEx64.dll	: 6.0.6000.100
RtkHDM64.dll	: 11.0.6000.113
XP/2K x86:	
RtkHDM.sys	: 5.10.0.5945
Rtaupd.exe	: 2.8.0.0
RHCoInstXP.dll	: 1.0.7.0
XP/2K x64:	
RtkHDMX.sys	: 5.10.0.5945
Rtaupd64.exe	: 2.8.0.0
RHCoInst64XP.dll	: 1.0.7.0

Readme.txt

Driver Setup Program : 2.86

Windows 2000/XP Operate on :  
Microsoft High Definition Audio Driver Package - KB888111  
Package file version (kb888111.exe) : 6.1.22.0  
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.35

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 - x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
  - 1.) Driver :
    1. Customizations.
  - 2.) Package :
    1. Fix some presentation of Spanish language .
    2. Add "Windows Server 2008 x64 R2" identification folder.

Windows 2000/XP : -----

Windows 2000/XP :

RTKHDA64.sys : 5.10.0.5953  
RTKHDAUD.sys : 5.10.0.5953  
Alcmtr.exe : 1.6.0.4  
AlcWzrd.exe : 1.1.0.37  
McCal.exe : 1.1.2.2  
RTHDCPL.exe : 2.3.1.8  
RtkAudioService64.exe : 1.0.0.19  
RtkAudioService.exe : 1.0.0.19  
RTLCPPL.exe : 1.0.1.66  
RtlUpd64.exe : 2.8.0.0  
RtlUpd.exe : 2.8.0.0  
SkyTel.exe : 2.0.2.0  
SoundMan.exe : 1.0.0.32  
vncutil64.exe : 1.0.0.32  
vncutil.exe : 1.0.0.32  
AMBFilt.sys : 5.10.0.4240  
AMBft64.sys : 5.10.0.4240  
Mbnfilt.sys : 5.10.0.4112  
Mbnft64.sys : 5.10.0.4115  
ALSndMgr.cpl : 1.0.0.11  
RTSndMgr.cpl : 1.0.1.4  
RCoInst64XP.dll : 1.0.7.0  
RTCOMDLL.dll : 1.0.0.103  
RtkCoInstXP.dll : 1.0.7.0  
RtlCPAPI.dll : 1.0.2.3

Vista/Win7 driver : -----

Vista/Win7 driver for x86

RTKVHDA.sys : 6.0.1.5953  
AERTSrv.exe : 1.0.32.9  
APOPCH.exe : 1.0.0.0  
RtHDVBg.exe : 1.0.0.6  
RtHDVCpl.exe : 1.0.0.426  
RtkAudioService.exe : 1.0.0.24  
RtlUpd.exe : 2.8.0.0  
SkyTel.exe : 2.0.2.2  
vncutil.exe : 1.0.0.32  
mbfilt32.sys : 6.10.0.8  
RTSndMgr.cpl : 1.0.0.17  
AERTACap.dll : 2.0.32.8

AERTARen.dll	: 1.0.32.8
FMAP0.dll	: 42.5.19.65
MaxxAudioAP0.dll	: 1.2.2.0
MaxxAudioAP020.dll	: 2.2.6.0
MaxxAudioEQ.dll	: 5.9.7.0
MBAP032.dll	: 1.0.19.0
MBPPCn32.dll	: 1.0.0.110
MBpld32.dll	: 1.0.22.0
MBTHX32.dll	: 1.0.8.103
MBWrp32.dll	: 1.0.0.110
RP3DAA32.dll	: 6.0.6001.18
RP3DHT32.dll	: 6.0.6001.18
RTCOMDLL.dll	: 2.0.0.120
RTEED32A.dll	: 6.1.6001.29
RTEEG32A.dll	: 6.1.6001.29
RTEEL32A.dll	: 6.1.6001.29
RTEEP32A.dll	: 6.1.6001.29
RtkAP0.dll	: 11.0.6000.116
RtkApoApi.dll	: 1.0.0.13
RtkCfg.dll	: 1.0.0.1
RtkColnst.dll	: 1.0.7.1
RtkPgExt.dll	: 6.0.6000.103
RtlCPAPI.dll	: 1.0.2.4
SFFXComm.dll	: 2.0.0.8
SFFXDAP0.dll	: 2.0.0.8
SFFXHAP0.dll	: 2.0.0.8
SFFXProc.dll	: 2.0.0.8
SFFXSAP0.dll	: 2.0.0.8
slcshp32.dll	: 1.0.3.0
slgeq32.dll	: 1.0.1.0
slh36032.dll	: 1.0.2.0
slInit32.dll	: 1.1.3.0
slmaxv32.dll	: 1.1.2.0
sltshd32.dll	: 1.1.1.0
sluapo32.dll	: 1.4.8.0
SRSHP360.dll	: 1.1.0.0
SRSTSHD.dll	: 1.1.4.0
SRSTSXT.dll	: 3.2.0.0
SRSWOW.dll	: 1.1.3.0
WavesLib.dll	: 5.9.7.0
Vista/Win7 driver for x64	
RTKVHD64.sys	: 6.0.1.5953
AERTSr64.exe	: 1.0.64.9
APOPCH.exe	: 1.0.0.0
RAVBg64.exe	: 1.0.0.6
RAVCpl64.exe	: 1.0.0.426
RtkAudioService64.exe	: 1.0.0.24
RtlUpd64.exe	: 2.8.0.0
SkyTel.exe	: 2.0.2.2
vncutil64.exe	: 1.0.0.32
GWfilt64.sys	: 6.10.0.3
mbfilt64.sys	: 6.10.0.8
RTSnMg64.cpl	: 1.0.0.17
AERTAC64.dll	: 2.0.64.8
AERTAR64.dll	: 1.0.64.8
FMAP064.dll	: 42.6.19.65
MaxxAudioAP020.dll	: 2.2.6.0
MBAP032.dll	: 1.0.19.0
MBAP064.dll	: 1.0.19.0
MBPPCn64.dll	: 1.0.0.110
MBpld64.dll	: 1.0.22.0
MBTHX32.dll	: 1.0.8.103
MBTHX64.dll	: 1.0.8.103
MBWrp64.dll	: 1.0.0.110
RCoInst64.dll	: 1.0.7.1
RP3DAA64.dll	: 6.0.6001.18
RP3DHT64.dll	: 6.0.6001.18
RtCOM64.dll	: 2.0.0.120
RTCOMDLL.dll	: 2.0.0.120

Readme.txt

RTEED64A.dll : 6.1.6001.29  
 RTEEG64A.dll : 6.1.6001.29  
 RTEEL64A.dll : 6.1.6001.29  
 RTEEP64A.dll : 6.1.6001.29  
 RtkApi64.dll : 1.0.0.13  
 RtkAPO64.dll : 11.0.6000.116  
 RtkCfg.dll : 1.0.0.1  
 RtkCfg64.dll : 1.0.0.1  
 RtLCPAPI.dll : 1.0.2.4  
 RtLCPAPI64.dll : 1.0.2.4  
 RtpgEx64.dll : 6.0.6000.103  
 SFComm64.dll : 2.0.0.8  
 SFDAPO64.dll : 2.0.0.8  
 SFHAPO64.dll : 2.0.0.8  
 SFProc64.dll : 2.0.0.8  
 SFSAPO64.dll : 2.0.0.8  
 slcshp64.dll : 1.0.3.0  
 slgeq64.dll : 1.0.1.0  
 slh36064.dll : 1.0.2.0  
 slInit64.dll : 1.1.3.0  
 slmaxv64.dll : 1.1.2.0  
 sltshd64.dll : 1.1.1.0  
 sluapo64.dll : 1.4.8.0  
 SRSHP64.dll : 1.1.0.0  
 SRSTSH64.dll : 1.1.4.0  
 SRSTSX64.dll : 3.2.0.0  
 SRSWOW64.dll : 1.1.3.0

HDM Driver : -----

Vista/WIn7 x86:  
 RtHDMV.sys : 6.0.1.5945  
 RtkAudioSrvATI.exe : 1.0.0.23  
 RtkUpd.exe : 2.8.0.0  
 RH3DAA32.dll : 6.0.6001.18  
 RH3DHT32.dll : 6.0.6001.18  
 RHCoInst.dll : 1.0.7.0  
 RHDMEExt.dll : 6.0.6000.100  
 RtkHDM.dll : 11.0.6000.113

Vista/WIn7 x64:  
 RtHDMVX.sys : 6.0.1.5945  
 RtkAudioSrvATI64.exe : 1.0.0.23  
 RtkUpd64.exe : 2.8.0.0  
 RH3DAA64.dll : 6.0.6001.18  
 RH3DHT64.dll : 6.0.6001.18  
 RHCoInst64.dll : 1.0.7.0  
 RHDME64.dll : 6.0.6000.100  
 RtkHDM64.dll : 11.0.6000.113

XP/2K x86:  
 RtkHDM.sys : 5.10.0.5945  
 Rtaupd.exe : 2.8.0.0  
 RHCoInstXP.dll : 1.0.7.0

XP/2K x64:  
 RtkHDMX.sys : 5.10.0.5945  
 Rtaupd64.exe : 2.8.0.0  
 RHCoInst64XP.dll : 1.0.7.0

Driver Setup Program : 2.85

Windows 2000/XP Operate on :  
 Microsoft High Definition Audio Driver Package - KB888111  
 Package file version (kb888111.exe) : 6.1.22.0  
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.34

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662,



Readme.txt

ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275  
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD,  
ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670,  
ALC275

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft WindowsXP, Windows2000, Windows Server 2003, Vista, Windows Server 2008,  
Windows7 - x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :

RTKHDA64.sys : 5.10.0.5943  
RTKHDAUD.sys : 5.10.0.5943  
McCal.exe : 1.1.2.2  
RTHDCPL.exe : 2.3.1.4  
RtkAudioService64.exe : 1.0.0.19  
RtkAudioService.exe : 1.0.0.19  
RTLCPPL.exe : 1.0.1.66  
RtlUpd64.exe : 2.8.0.0  
RtlUpd.exe : 2.8.0.0  
SkyTel.exe : 2.0.2.0  
SoundMan.exe : 1.0.0.32  
vncutil64.exe : 1.0.0.31  
vncutil.exe : 1.0.0.31  
Alcmtr.exe : 1.6.0.4  
AlcWzrd.exe : 1.1.0.37  
Mnfilt.sys : 5.10.0.4112  
Mnft64.sys : 5.10.0.4115  
AMBFilt.sys : 5.10.0.4240  
AMBft64.sys : 5.10.0.4240  
RTSndMgr.cpl : 1.0.1.4  
ALSndMgr.cpl : 1.0.0.11  
RCoInst64XP.dll : 1.0.7.0  
RTEED32A.dll : 1.0.0.103  
RtkCoInstXP.dll : 1.0.7.0  
RtlCPAPI.dll : 1.0.2.3

Vista/Win7 driver : -----

Vista/Win7 driver for x86

RTKVHDA.sys : 6.0.1.5943  
AERTSrv.exe : 1.0.32.9  
APOPCH.exe : 1.0.0.0  
RtHDVBg.exe : 1.0.0.6  
RtHDVCpl.exe : 1.0.0.422  
RtkAudioService.exe : 1.0.0.24  
RtlUpd.exe : 2.8.0.0  
SkyTel.exe : 2.0.2.2  
vncutil.exe : 1.0.0.31  
mbfilt32.sys : 6.10.0.8  
RTSndMgr.cpl : 1.0.0.17  
AERTACap.dll : 2.0.32.8  
AERTARen.dll : 1.0.32.8  
FMAPO.dll : 42.5.18.67  
MaxxAudioAPO.dll : 1.2.2.0  
MaxxAudioAPO20.dll : 2.2.6.0  
MaxxAudioEQ.dll : 5.9.7.0  
MBAP032.dll : 1.0.19.0  
MBPPCn32.dll : 1.0.0.110  
Mbpld32.dll : 1.0.19.0  
MBTHX32.dll : 1.0.8.102  
MBWrp32.dll : 1.0.0.110  
RP3DAA32.dll : 6.0.6001.18  
RP3DHT32.dll : 6.0.6001.18  
RTEED32A.dll : 2.0.0.120  
RTEED32A.dll : 6.1.6001.29  
RTEEG32A.dll : 6.1.6001.29  
RTEEL32A.dll : 6.1.6001.29

	Readme.txt	
RTEEP32A.dll		: 6.1.6001.29
RtkAPO.dll		: 11.0.6000.113
RtkApoApi.dll		: 1.0.0.13
RtkCfg.dll		: 1.0.0.1
RtkColnst.dll		: 1.0.7.0
RtkPgExt.dll		: 6.0.6000.99
RtlCPAPI.dll		: 1.0.2.4
SFFXComm.dll		: 2.0.0.8
SFFXDAP0.dll		: 2.0.0.8
SFFXHAP0.dll		: 2.0.0.8
SFFXProc.dll		: 2.0.0.8
SFFXSAP0.dll		: 2.0.0.8
slcshp32.dll		: 1.0.3.0
slgeq32.dll		: 1.0.1.0
slh36032.dll		: 1.0.2.0
slInit32.dll		: 1.1.3.0
slmaxv32.dll		: 1.1.2.0
sltshd32.dll		: 1.1.1.0
sluapo32.dll		: 1.4.8.0
SRSHP360.dll		: 1.1.0.0
SRSTSHD.dll		: 1.1.4.0
SRSTSXT.dll		: 3.2.0.0
SRSWOW.dll		: 1.1.3.0
WavesLib.dll		: 5.9.7.0
Vista/Win7 driver for x64		
RTKVHD64.sys		: 6.0.1.5943
AERTSr64.exe		: 1.0.64.9
APOPCH.exe		: 1.0.0.0
RAVBg64.exe		: 1.0.0.6
RAVCpl64.exe		: 1.0.0.422
RtkAudioService64.exe		: 1.0.0.24
RtlUpd64.exe		: 2.8.0.0
SkyTel.exe		: 2.0.2.2
vncutil64.exe		: 1.0.0.31
GWfilt64.sys		: 6.10.0.3
mbfilt64.sys		: 6.10.0.8
RTSnMg64.cpl		: 1.0.0.17
AERTAC64.dll		: 2.0.64.8
AERTAR64.dll		: 1.0.64.8
FMAP064.dll		: 42.6.18.67
MaxxAudioAPO20.dll		: 2.2.6.0
MBAP032.dll		: 1.0.19.0
MBAP064.dll		: 1.0.19.0
MBPPCn64.dll		: 1.0.0.110
Mbpld64.dll		: 1.0.19.0
MBTHX32.dll		: 1.0.8.102
MBTHX64.dll		: 1.0.8.102
MBWrp64.dll		: 1.0.0.110
RCoInst64.dll		: 1.0.7.0
RP3DAA64.dll		: 6.0.6001.18
RP3DHT64.dll		: 6.0.6001.18
RtCOMB4.dll		: 2.0.0.120
RTCOMDLL.dll		: 2.0.0.120
RTEED64A.dll		: 6.1.6001.29
RTEEG64A.dll		: 6.1.6001.29
RTEEL64A.dll		: 6.1.6001.29
RTEEP64A.dll		: 6.1.6001.29
RtkApi64.dll		: 1.0.0.13
RtkAPO64.dll		: 11.0.6000.113
RtkCfg.dll		: 1.0.0.1
RtkCfg64.dll		: 1.0.0.1
RtlCPAPI.dll		: 1.0.2.4
RtlCPAPI64.dll		: 1.0.2.4
RtPgEx64.dll		: 6.0.6000.99
SFComm64.dll		: 2.0.0.8
SFDAP064.dll		: 2.0.0.8
SFHAP064.dll		: 2.0.0.8
SFProc64.dll		: 2.0.0.8
SFSAP064.dll		: 2.0.0.8

Readme.txt

slcshp64.dll : 1.0.3.0  
slgeq64.dll : 1.0.1.0  
slh36064.dll : 1.0.2.0  
slInit64.dll : 1.1.3.0  
slmaxv64.dll : 1.1.2.0  
sltshd64.dll : 1.1.1.0  
sluapo64.dll : 1.4.8.0  
SRSHp64.dll : 1.1.0.0  
SRSTSH64.dll : 1.1.4.0  
SRSTX64.dll : 3.2.0.0  
SRSW064.dll : 1.1.3.0

HDMI Driver : -----

Vista/Win7 x86:

RtHDMV.sys : 6.0.1.5897  
RtkAudioSrvATI.exe : 1.0.0.23  
RtkUpd.exe : 2.8.0.0  
RH3DAA32.dll : 6.0.6001.18  
RH3DHT32.dll : 6.0.6001.18  
RHCoInst.dll : 1.0.6.4  
RHDMExt.dll : 6.0.6000.82  
RtkHDM.dll : 11.0.6000.101

Vista/Win7 x64:

RtHDMVX.sys : 6.0.1.5897  
RtkAudioSrvATI64.exe : 1.0.0.23  
RtkUpd64.exe : 2.8.0.0  
RH3DAA64.dll : 6.0.6001.18  
RH3DHT64.dll : 6.0.6001.18  
RHCoInst64.dll : 1.0.6.4  
RHDMEx64.dll : 6.0.6000.82  
RtkHDM64.dll : 11.0.6000.101

XP/2K x86:

RtkHDM.sys : 5.10.0.5880  
RtkUpd.exe : 2.7.1.3  
RHCoInstXP.dll : 1.0.5.1

XP/2K x64:

RtkHDMX.sys : 5.10.0.5880  
RtkUpd64.exe : 2.7.1.3  
RHCoInst64XP.dll : 1.0.5.1

Driver Setup Program : 2.84

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111  
Package file version (kb888111.exe) : 6.1.22.0  
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.33

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887, ALC670, ALC275
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887, ALC670, ALC275
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Windows Server 2003, Vista, Windows Server 2008,

Windows7 - x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :  
RTKHDA64.sys : 5.10.0.5936  
RTKHDAUD.sys : 5.10.0.5936

Readme.txt

```

McCal.exe : 1.1.2.2
RTHDCPL.exe : 2.3.1.2
RtkAudioService64.exe : 1.0.0.19
RtkAudioService.exe : 1.0.0.19
RTLCPPL.exe : 1.0.1.66
RtlUpd64.exe : 2.8.0.0
RtlUpd.exe : 2.8.0.0
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.32
vncutil64.exe : 1.0.0.29
vncutil.exe : 1.0.0.29
Alcmtr.exe : 1.6.0.4
AlcWzrd.exe : 1.1.0.37
Mbnfilt.sys : 5.10.0.4112
Mbnft64.sys : 5.10.0.4115
AMBFilt.sys : 5.10.0.4240
AMBFt64.sys : 5.10.0.4240
RTSndMgr.cpl : 1.0.1.4
ALSndMgr.cpl : 1.0.0.11
RCoInst64XP.dll : 1.0.6.9
RTCOMDLL.dll : 1.0.0.103
RtkCoInstXP.dll : 1.0.6.9
RtlCPAPI.dll : 1.0.2.3
Vista/Win7 driver : -----
Vista/Win7 driver for x86
RTKVHDA.sys : 6.0.1.5936
AERTSrv.exe : 1.0.32.9
APOPCH.exe : 1.0.0.0
RtHDVBg.exe : 1.0.0.6
RtHDVCpl.exe : 1.0.0.418
RtkAudioService.exe : 1.0.0.24
RtlUpd.exe : 2.8.0.0
SkyTel.exe : 2.0.2.2
vncutil.exe : 1.0.0.29
RTSndMgr.cpl : 1.0.0.17
mbfilt32.sys : 6.10.0.8
AERTACap.dll : 2.0.32.8
AERTARen.dll : 1.0.32.8
FMAP0.dll : 42.5.18.65
MaxxAudioAP0.dll : 1.2.2.0
MaxxAudioAP020.dll : 2.2.6.0
MaxxAudioEQ.dll : 5.9.7.0
MBAP032.dll : 1.0.19.0
MBPPCn32.dll : 1.0.0.110
MBppld32.dll : 1.0.19.0
MBTHX32.dll : 1.0.8.102
MBWrp32.dll : 1.0.0.110
RP3DAA32.dll : 6.0.6001.18
RP3DHT32.dll : 6.0.6001.18
RTCOMDLL.dll : 2.0.0.120
RTEED32A.dll : 6.1.6001.29
RTEEG32A.dll : 6.1.6001.29
RTEEL32A.dll : 6.1.6001.29
RTEEP32A.dll : 6.1.6001.29
RtkAP0.dll : 11.0.6000.109
RtkApoApi.dll : 1.0.0.13
RtkCfg.dll : 1.0.0.1
RtkCoInst.dll : 1.0.6.9
RtkPgExt.dll : 6.0.6000.96
RtlCPAPI.dll : 1.0.2.4
SFFXComm.dll : 2.0.0.8
SFFXDAP0.dll : 2.0.0.8
SFFXHAP0.dll : 2.0.0.8
SFFXProc.dll : 2.0.0.8
SFFXSAP0.dll : 2.0.0.8
slcshp32.dll : 1.0.3.0
slgeq32.dll : 1.0.1.0
slh36032.dll : 1.0.2.0
slInit32.dll : 1.1.3.0

```

	Readme.txt	
slmaxv32.dll	:	1.1.2.0
sltshd32.dll	:	1.1.1.0
sluapo32.dll	:	1.4.8.0
SRSHP360.dll	:	1.1.0.0
SRSTSHD.dll	:	1.1.4.0
SRSTSXT.dll	:	3.2.0.0
SRSWOW.dll	:	1.1.3.0
WavesLib.dll	:	5.9.7.0
Vista/Win7 driver for x64		
RTKVHD64.sys	:	6.0.1.5936
AERTSr64.exe	:	1.0.64.9
APOPCH.exe	:	1.0.0.0
RAVBg64.exe	:	1.0.0.6
RAVCpl64.exe	:	1.0.0.418
RtkAudioService64.exe	:	1.0.0.24
RtlUpd64.exe	:	2.8.0.0
SkyTel.exe	:	2.0.2.2
vncutil64.exe	:	1.0.0.29
GWfilt64.sys	:	6.10.0.3
mbfilt64.sys	:	6.10.0.8
RTSnMg64.cpl	:	1.0.0.17
AERTAC64.dll	:	2.0.64.8
AERTAR64.dll	:	1.0.64.8
FMAP064.dll	:	42.6.18.65
MaxxAudioAPO20.dll	:	2.2.6.0
MBAP032.dll	:	1.0.19.0
MBAP064.dll	:	1.0.19.0
MBPPCn64.dll	:	1.0.0.110
Mbpld64.dll	:	1.0.19.0
MBTHX32.dll	:	1.0.8.102
MBTHX64.dll	:	1.0.8.102
MBWrp64.dll	:	1.0.0.110
RCoInst64.dll	:	1.0.6.9
RP3DAA64.dll	:	6.0.6001.18
RP3DHT64.dll	:	6.0.6001.18
RtCOMB4.dll	:	2.0.0.120
RTCOMDLL.dll	:	2.0.0.120
RTEED64A.dll	:	6.1.6001.29
RTEEG64A.dll	:	6.1.6001.29
RTEEL64A.dll	:	6.1.6001.29
RTEEP64A.dll	:	6.1.6001.29
RtkApi64.dll	:	1.0.0.13
RtkAPO64.dll	:	11.0.6000.109
RtkCfg.dll	:	1.0.0.1
RtkCfg64.dll	:	1.0.0.1
RtlCPAPI.dll	:	1.0.2.4
RtlCPAPI64.dll	:	1.0.2.4
RtPgEx64.dll	:	6.0.6000.96
SFComm64.dll	:	2.0.0.8
SFDAP064.dll	:	2.0.0.8
SFHAP064.dll	:	2.0.0.8
SFProc64.dll	:	2.0.0.8
SFSAP064.dll	:	2.0.0.8
slcshp64.dll	:	1.0.3.0
slgeq64.dll	:	1.0.1.0
slh36064.dll	:	1.0.2.0
slInit64.dll	:	1.1.3.0
slmaxv64.dll	:	1.1.2.0
sltshd64.dll	:	1.1.1.0
sluapo64.dll	:	1.4.8.0
SRSHP64.dll	:	1.1.0.0
SRSTSH64.dll	:	1.1.4.0
SRSTSX64.dll	:	3.2.0.0
SRSWOW64.dll	:	1.1.3.0
HDMI Driver : -----		
Vista/Win7 x86:		
RtHDMV.sys	:	6.0.1.5897
RtkAudioSrvATI.exe	:	1.0.0.23
RtkUpd.exe	:	2.8.0.0

Readme.txt

RH3DAA32.dll : 6.0.6001.18  
RH3DHT32.dll : 6.0.6001.18  
RHCoInst.dll : 1.0.6.4  
RHDMEExt.dll : 6.0.6000.82  
RtkHDM.dll : 11.0.6000.101

Vista/WIn7 x64:

RtHDMVX.sys : 6.0.1.5897  
RtkAudioSrvATI64.exe : 1.0.0.23  
RtkUpd64.exe : 2.8.0.0  
RH3DAA64.dll : 6.0.6001.18  
RH3DHT64.dll : 6.0.6001.18  
RHCoInst64.dll : 1.0.6.4  
RHDME64.dll : 6.0.6000.82  
RtkHDM64.dll : 11.0.6000.101

XP/2K x86:

RtkHDM.sys : 5.10.0.5880  
RtkUpd.exe : 2.7.1.3  
RHCoInstXP.dll : 1.0.5.1

XP/2K x64:

RtkHDMX.sys : 5.10.0.5880  
RtkUpd64.exe : 2.7.1.3  
RHCoInst64XP.dll : 1.0.5.1

Driver Setup Program : 2.84

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111  
Package file version (kb888111.exe) : 6.1.22.0  
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.32

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887, ALC670, ALC275
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887, ALC670, ALC275
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Windows Server 2003, Vista, Windows Server 2008,

Windows7 - x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :

RTKHDA64.sys : 5.10.0.5928  
RTKHDAUD.sys : 5.10.0.5928  
McCal.exe : 1.1.2.2  
RTHDCPL.exe : 2.3.1.0  
RtkAudioService64.exe : 1.0.0.19  
RtkAudioService.exe : 1.0.0.19  
RTLCPPL.exe : 1.0.1.66  
RtlUpd64.exe : 2.8.0.0  
RtlUpd.exe : 2.8.0.0  
SkyTel.exe : 2.0.2.0  
SoundMan.exe : 1.0.0.32  
vncutil64.exe : 1.0.0.27  
vncutil.exe : 1.0.0.27  
Alcmtr.exe : 1.6.0.4  
AlcWzrd.exe : 1.1.0.37  
Mbnfilt.sys : 5.10.0.4112  
Mnft64.sys : 5.10.0.4115  
ANBFilt.sys : 5.10.0.4240

Readme.txt

```

AMBFt64.sys : 5.10.0.4240
RTSndMgr.cpl : 1.0.1.4
ALSndMgr.cpl : 1.0.0.11
RCoInst64XP.dll : 1.0.6.5
RTCOMDLL.dll : 1.0.0.103
RtkCoInstXP.dll : 1.0.6.5
RtlCPAPI.dll : 1.0.2.3
Vista/Win7 driver : -----
Vista/Win7 driver for x86
RTKVHDA.sys : 6.0.1.5928
AERTSrv.exe : 1.0.32.9
APOPCH.exe : 1.0.0.0
RtHDVBg.exe : 1.0.0.6
RtHDVCpl.exe : 1.0.0.411
RtkAudioService.exe : 1.0.0.24
RtlUpd.exe : 2.8.0.0
SkyTel.exe : 2.0.2.2
vncutil.exe : 1.0.0.27
mbfilt32.sys : 6.10.0.8
RTSndMgr.cpl : 1.0.0.17
AERTACap.dll : 2.0.32.8
AERTARen.dll : 1.0.32.8
FMAP0.dll : 42.5.17.68
MaxxAudioAP0.dll : 1.2.2.0
MaxxAudioAP020.dll : 2.2.2.0
MaxxAudioEQ.dll : 5.9.7.0
MBAP032.dll : 1.0.19.0
MBPPCn32.dll : 1.0.0.110
MBppld32.dll : 1.0.19.0
MBTHX32.dll : 1.0.8.0
MBWrp32.dll : 1.0.0.110
RP3DAA32.dll : 6.0.6001.18
RP3DHT32.dll : 6.0.6001.18
RTCOMDLL.dll : 2.0.0.119
RTEED32A.dll : 6.1.6001.29
RTEEG32A.dll : 6.1.6001.29
RTEEL32A.dll : 6.1.6001.29
RTEEP32A.dll : 6.1.6001.29
RtkAP0.dll : 11.0.6000.106
RtkApoApi.dll : 1.0.0.12
RtkCfg.dll : 1.0.0.1
RtkCoInst.dll : 1.0.6.7
RtkPgExt.dll : 6.0.6000.93
RtlCPAPI.dll : 1.0.2.4
SFFXComm.dll : 2.0.0.8
SFFXDAP0.dll : 2.0.0.8
SFFXHAP0.dll : 2.0.0.8
SFFXProc.dll : 2.0.0.8
SFFXSAP0.dll : 2.0.0.8
slcshp32.dll : 1.0.3.0
slgeq32.dll : 1.0.1.0
slh36032.dll : 1.0.2.0
slInit32.dll : 1.1.3.0
slmaxv32.dll : 1.1.2.0
sltshd32.dll : 1.1.1.0
sluapo32.dll : 1.4.8.0
SRSHP360.dll : 1.1.0.0
SRSTSHD.dll : 1.1.4.0
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.1.3.0
WavesLib.dll : 5.9.7.0
Vista/Win7 driver for x64
RTKVHD64.sys : 6.0.1.5928
AERTSr64.exe : 1.0.64.9
APOPCH.exe : 1.0.0.0
RAVBg64.exe : 1.0.0.6
RAVCpl64.exe : 1.0.0.411
RtkAudioService64.exe : 1.0.0.24
RtlUpd64.exe : 2.8.0.0

```

Readme.txt

SkyTel.exe	: 2.0.2.2
vncutil64.exe	: 1.0.0.27
GWfilt64.sys	: 6.10.0.3
mbfilt64.sys	: 6.10.0.8
RTSnMg64.cpl	: 1.0.0.17
AERTAC64.dll	: 2.0.64.8
AERTAR64.dll	: 1.0.64.8
FMAP064.dll	: 42.6.17.68
MaxxAudioAPO20.dll	: 2.2.2.0
MBAP032.dll	: 1.0.19.0
MBAP064.dll	: 1.0.19.0
MBPPCn64.dll	: 1.0.0.110
Mbpld64.dll	: 1.0.19.0
MBTHX32.dll	: 1.0.8.0
MBTHX64.dll	: 1.0.8.0
MBWrp64.dll	: 1.0.0.110
RCoInst64.dll	: 1.0.6.7
RP3DAA64.dll	: 6.0.6001.18
RP3DHT64.dll	: 6.0.6001.18
RtCOMB4.dll	: 2.0.0.119
RTCOMDLL.dll	: 2.0.0.119
RTEED64A.dll	: 6.1.6001.29
RTEEG64A.dll	: 6.1.6001.29
RTEEL64A.dll	: 6.1.6001.29
RTEEP64A.dll	: 6.1.6001.29
RtkApi64.dll	: 1.0.0.12
RtkAPO64.dll	: 11.0.6000.106
RtkCfg.dll	: 1.0.0.1
RtkCfg64.dll	: 1.0.0.1
RtLCPAPI.dll	: 1.0.2.4
RtLCPAPI64.dll	: 1.0.2.4
RtPgEx64.dll	: 6.0.6000.93
SFComm64.dll	: 2.0.0.8
SFDAPO64.dll	: 2.0.0.8
SFHAP064.dll	: 2.0.0.8
SFProc64.dll	: 2.0.0.8
SFSAP064.dll	: 2.0.0.8
slcshp64.dll	: 1.0.3.0
slgeq64.dll	: 1.0.1.0
slh36064.dll	: 1.0.2.0
slInit64.dll	: 1.1.3.0
slmaxv64.dll	: 1.1.2.0
sltshd64.dll	: 1.1.1.0
sluapo64.dll	: 1.4.8.0
SRSHP64.dll	: 1.1.0.0
SRSTSH64.dll	: 1.1.4.0
SRSTSX64.dll	: 3.2.0.0
SRSWOW64.dll	: 1.1.3.0
HDMI Driver : -----	
Vista/Win7 x86:	
RtHDMV.sys	: 6.0.1.5897
RtkAudioSrvATI.exe	: 1.0.0.23
RtkUpd.exe	: 2.8.0.0
RH3DAA32.dll	: 6.0.6001.18
RH3DHT32.dll	: 6.0.6001.18
RHCoInst.dll	: 1.0.6.4
RHDMExt.dll	: 6.0.6000.82
RtkHDM.dll	: 11.0.6000.101
Vista/Win7 x64:	
RtHDMVX.sys	: 6.0.1.5897
RtkAudioSrvATI64.exe	: 1.0.0.23
RtkUpd64.exe	: 2.8.0.0
RH3DAA64.dll	: 6.0.6001.18
RH3DHT64.dll	: 6.0.6001.18
RHCoInst64.dll	: 1.0.6.4
RHDMEx64.dll	: 6.0.6000.82
RtkHDM64.dll	: 11.0.6000.101



Readme.txt

XP/2K x86:  
RtkHDM.sys : 5.10.0.5880  
RtkUpd.exe : 2.7.1.3  
RHCoInstXP.dll : 1.0.5.1  
XP/2K x64:  
RtkHDMX.sys : 5.10.0.5880  
RtkUpd64.exe : 2.7.1.3  
RHCoInst64XP.dll : 1.0.5.1  
  
Driver Setup Program : 2.83

Windows 2000/XP Operate on :  
Microsoft High Definition Audio Driver Package - KB888111  
Package file version (kb888111.exe) : 6.1.22.0  
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.31

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887, ALC670, ALC275
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887, ALC670, ALC275
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Windows Server 2003, Vista, Windows Server 2008,

Windows7 - x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.
2. Fix DTM KS position testing fail issue when turn on Microphone effect under Win7.

2.) Package

1. Reboot message in log file. ( WLL\_REBOOT )
2. Copy all of AP files to system

Windows 2000/XP : -----

Windows 2000/XP :

RTKHDA64.sys : 5.10.0.5919  
RTKHDAUD.sys : 5.10.0.5919  
Alcmtr.exe : 1.6.0.4  
AlcWzrd.exe : 1.1.0.37  
McCal.exe : 1.1.2.2  
RTHDCPL.exe : 2.3.0.9  
RtkAudioService64.exe : 1.0.0.19  
RtkAudioService.exe : 1.0.0.19  
RTLCPPL.exe : 1.0.1.66  
RtlUpd64.exe : 2.8.0.0  
RtlUpd.exe : 2.8.0.0  
SkyTel.exe : 2.0.2.0  
SoundMan.exe : 1.0.0.32  
vncutil64.exe : 1.0.0.24  
vncutil.exe : 1.0.0.25  
AMBfilt.sys : 5.10.0.4240  
AMBft64.sys : 5.10.0.4240  
Mnft64.sys : 5.10.0.4112  
Mnft64.sys : 5.10.0.4115  
ALSndMgr.cpl : 1.0.0.11  
RTSndMgr.cpl : 1.0.1.4  
RCoInst64XP.dll : 1.0.6.5  
RtCOMDLL.dll : 1.0.0.103  
RtkCoInstXP.dll : 1.0.6.5  
RtlCPAPI.dll : 1.0.2.3

Vista/Win7 driver : -----

Vista/Win7 driver for x86

RTKVHDA.sys : 6.0.1.5919  
AERTSrv.exe : 1.0.32.9  
APOPCH.exe : 1.0.0.0

	Readme.txt	
RtHDVBg.exe	:	1.0.0.5
RtHDVCpl.exe	:	1.0.0.401
RtkAudioService.exe	:	1.0.0.24
RtlUpd.exe	:	2.8.0.0
SkyTel.exe	:	2.0.2.2
vncutil.exe	:	1.0.0.25
mbfilt32.sys	:	6.10.0.6
RTSndMgr.cpl	:	1.0.0.17
AERTACap.dll	:	2.0.32.8
AERTARen.dll	:	1.0.32.8
FMAP0.dll	:	42.5.1.1
MaxxAudioAP0.dll	:	1.2.2.0
MaxxAudioAP020.dll	:	2.2.2.0
MaxxAudioEQ.dll	:	5.9.7.0
MBAP032.dll	:	1.0.9.0
MBPPCn32.dll	:	1.0.0.110
Mbpld32.dll	:	1.0.9.0
MBTHX32.dll	:	1.0.8.0
MBWrp32.dll	:	1.0.0.110
RP3DAA32.dll	:	6.0.6001.18
RP3DHT32.dll	:	6.0.6001.18
RTCOMDLL.dll	:	2.0.0.117
RtkAPO.dll	:	11.0.6000.104
RtkApoApi.dll	:	1.0.0.10
RtkCfg.dll	:	1.0.0.1
RtkCoInst.dll	:	1.0.6.7
RtkPgExt.dll	:	6.0.6000.89
RtLCPAPI.dll	:	1.0.2.4
SFFXComm.dll	:	2.0.0.8
SFFXDAP0.dll	:	2.0.0.8
SFFXHAP0.dll	:	2.0.0.8
SFFXProc.dll	:	2.0.0.8
SFFXSAP0.dll	:	2.0.0.8
slcshp32.dll	:	1.0.3.0
slgeq32.dll	:	1.0.1.0
slh36032.dll	:	1.0.2.0
slInit32.dll	:	1.1.3.0
slmaxv32.dll	:	1.1.2.0
sltshd32.dll	:	1.1.1.0
sluapo32.dll	:	1.4.8.0
SRSHP360.dll	:	1.1.0.0
SRSTSHD.dll	:	1.1.4.0
SRSTSXT.dll	:	3.2.0.0
SRSWOW.dll	:	1.1.3.0
WavesLib.dll	:	5.9.7.0
Vista/Win7 driver for x64		
RTKVHD64.sys	:	6.0.1.5919
AERTSr64.exe	:	1.0.64.9
APOPCH.exe	:	1.0.0.0
RAVBg64.exe	:	1.0.0.5
RAVCpl64.exe	:	1.0.0.401
RtkAudioService64.exe	:	1.0.0.24
RtlUpd64.exe	:	2.8.0.0
SkyTel.exe	:	2.0.2.2
vncutil64.exe	:	1.0.0.24
GWfilt64.sys	:	6.10.0.3
mbfilt64.sys	:	6.10.0.8
RTSnMg64.cpl	:	1.0.0.17
AERTAC64.dll	:	2.0.64.8
AERTAR64.dll	:	1.0.64.8
FMAP064.dll	:	42.6.1.1
MaxxAudioAP020.dll	:	2.2.2.0
MBAP032.dll	:	1.0.19.0
MBAP064.dll	:	1.0.19.0
MBPPCn64.dll	:	1.0.0.110
Mbpld64.dll	:	1.0.19.0
MBTHX32.dll	:	1.0.8.0
MBTHX64.dll	:	1.0.8.0
MBWrp64.dll	:	1.0.0.110

Readme.txt

RCoInst64.dll : 1.0.6.7  
 RP3DAA64.dll : 6.0.6001.18  
 RP3DHT64.dll : 6.0.6001.18  
 RtCOMB4.dll : 2.0.0.117  
 RTCOMDLL.dll : 2.0.0.117  
 RtkApi64.dll : 1.0.0.10  
 RtkAPO64.dll : 11.0.6000.104  
 RtkCfg.dll : 1.0.0.1  
 RtkCfg64.dll : 1.0.0.1  
 RtLCPAPI.dll : 1.0.2.4  
 RtLCPAPI64.dll : 1.0.2.4  
 RtPgEx64.dll : 6.0.6000.89  
 SFComm64.dll : 2.0.0.8  
 SFDAP064.dll : 2.0.0.8  
 SFHAP064.dll : 2.0.0.8  
 SFProc64.dll : 2.0.0.8  
 SFSAP064.dll : 2.0.0.8  
 slcshp64.dll : 1.0.3.0  
 slgeq64.dll : 1.0.1.0  
 slh36064.dll : 1.0.2.0  
 slInit64.dll : 1.1.3.0  
 slmaxv64.dll : 1.1.2.0  
 sltshd64.dll : 1.1.1.0  
 sluapo64.dll : 1.4.8.0  
 SRSHP64.dll : 1.1.0.0  
 SRSTSH64.dll : 1.1.4.0  
 SRSTSX64.dll : 3.2.0.0  
 SRSWOW64.dll : 1.1.3.0

HDM Driver : -----

Vista/Win7 x86:  
 RtHDMV.sys : 6.0.1.5897  
 RtkAudioSrvATI.exe : 1.0.0.23  
 RtkUpd.exe : 2.8.0.0  
 RH3DAA32.dll : 6.0.6001.18  
 RH3DHT32.dll : 6.0.6001.18  
 RHCoInst.dll : 1.0.6.4  
 RHDMEExt.dll : 6.0.6000.82  
 RtkHDM.dll : 11.0.6000.101

Vista/Win7 x64:  
 RtHDMVX.sys : 6.0.1.5897  
 RtkAudioSrvATI64.exe : 1.0.0.23  
 RtkUpd64.exe : 2.8.0.0  
 RH3DAA64.dll : 6.0.6001.18  
 RH3DHT64.dll : 6.0.6001.18  
 RHCoInst64.dll : 1.0.6.4  
 RHDME64.dll : 6.0.6000.82  
 RtkHDM64.dll : 11.0.6000.101

XP/2K x86:  
 RtkHDM.sys : 5.10.0.5880  
 RtkUpd.exe : 2.7.1.3  
 RHCoInstXP.dll : 1.0.5.1  
 XP/2K x64:  
 RtkHDMX.sys : 5.10.0.5880  
 RtkUpd64.exe : 2.7.1.3  
 RHCoInst64XP.dll : 1.0.5.1

Driver Setup Program : 2.83

Windows 2000/XP Operate on :  
 Microsoft High Definition Audio Driver Package - KB888111  
 Package file version (kb888111.exe) : 6.1.22.0  
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.30

Readme.txt

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887, ALC670, ALC275
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887, ALC670, ALC275
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 - x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
  - 1.) Driver :
    1. Customizations.
    2. Fix DTM testing issue under Win7.

Windows 2000/XP : -----

Windows 2000/XP :  
RTKHDA64.sys : 5.10.0.5911  
RTKHDAUD.sys : 5.10.0.5911  
McCal.exe : 1.1.2.2  
RTHDCPL.exe : 2.3.0.7  
RtkAudioService64.exe : 1.0.0.19  
RtkAudioService.exe : 1.0.0.19  
RTLCPPL.exe : 1.0.1.66  
RtlUpd64.exe : 2.8.0.0  
RtlUpd.exe : 2.8.0.0  
SkyTel.exe : 2.0.2.0  
SoundMan.exe : 1.0.0.32  
vncutil64.exe : 1.0.0.23  
vncutil.exe : 1.0.0.23  
AlcMtr.exe : 1.6.0.4  
AlcWzrd.exe : 1.1.0.37  
Mnflt.sys : 5.10.0.4112  
Mnft64.sys : 5.10.0.4115  
AMBflt.sys : 5.10.0.4240  
AMBft64.sys : 5.10.0.4240  
RTSndMgr.cpl : 1.0.1.4  
ALSndMgr.cpl : 1.0.0.11  
RCoInst64XP.dll : 1.0.6.5  
RTCOMDLL.dll : 1.0.0.103  
RtkCoInstXP.dll : 1.0.6.5  
RtlCPAPI.dll : 1.0.2.3

Vista/Win7 driver : -----

Vista/Win7 driver for x86  
RTKVHDA.sys : 6.0.1.5911  
AERTSrv.exe : 1.0.32.9  
APOPCH.exe : 1.0.0.0  
RtHDVBg.exe : 1.0.0.5  
RtHDVCpl.exe : 1.0.0.395  
RtkAudioService.exe : 1.0.0.24  
RtlUpd.exe : 2.8.0.0  
SkyTel.exe : 2.0.2.2  
vncutil.exe : 1.0.0.23  
mbflt32.sys : 6.10.0.6  
RTSndMgr.cpl : 1.0.0.17  
AERTACap.dll : 2.0.32.8  
AERTARen.dll : 1.0.32.8  
FMAP0.dll : 42.5.1.1  
MaxxAudioAPO.dll : 1.2.2.0  
MaxxAudioAPO20.dll : 2.2.2.0  
MaxxAudioEQ.dll : 5.9.7.0  
MBAP032.dll : 1.0.9.0  
MBPPCn32.dll : 1.0.0.110  
MBppld32.dll : 1.0.9.0  
MBTHX32.dll : 1.0.8.0  
MBWrp32.dll : 1.0.0.110  
RP3DAA32.dll : 6.0.6001.18  
RP3DHT32.dll : 6.0.6001.18  
RTCOMDLL.dll : 2.0.0.117  
RtkAPO.dll : 11.0.6000.101

	Readme.txt	
RtkApoApi.dll	:	1.0.0.10
RtkCfg.dll	:	1.0.0.1
RtkCoInst.dll	:	1.0.6.5
RtkPgExt.dll	:	6.0.6000.87
RtlCPAPI.dll	:	1.0.2.4
SFFXComm.dll	:	2.0.0.8
SFFXDAP0.dll	:	2.0.0.8
SFFXHAP0.dll	:	2.0.0.8
SFFXProc.dll	:	2.0.0.8
SFFXSAP0.dll	:	2.0.0.8
slcshp32.dll	:	1.0.3.0
slgeq32.dll	:	1.0.1.0
slh36032.dll	:	1.0.2.0
slinit32.dll	:	1.1.3.0
slmaxv32.dll	:	1.1.2.0
sltshd32.dll	:	1.1.1.0
sluapo32.dll	:	1.4.8.0
SRSHP360.dll	:	1.1.0.0
SRSTSHD.dll	:	1.1.4.0
SRSTSXT.dll	:	3.2.0.0
SRSWOW.dll	:	1.1.3.0
WavesLib.dll	:	5.9.7.0
Vista/Win7 driver for x64		
RTKVHD64.sys	:	6.0.1.5911
AERTSr64.exe	:	1.0.64.9
APOPCH.exe	:	1.0.0.0
RAVBg64.exe	:	1.0.0.5
RAVCpl64.exe	:	1.0.0.395
RtkAudioService64.exe	:	1.0.0.24
RtlUpd64.exe	:	2.8.0.0
SkyTel.exe	:	2.0.2.2
vncutil64.exe	:	1.0.0.23
GWfilt64.sys	:	6.10.0.3
mbfilt64.sys	:	6.10.0.6
RTSnMg64.cpl	:	1.0.0.17
AERTAC64.dll	:	2.0.64.8
AERTAR64.dll	:	1.0.64.8
FMAP064.dll	:	42.6.1.1
MaxxAudioAP020.dll	:	2.2.2.0
MBAP032.dll	:	1.0.9.0
MBAP064.dll	:	1.0.9.0
MBPPCn64.dll	:	1.0.0.110
Mbpld64.dll	:	1.0.9.0
MBTHX32.dll	:	1.0.8.0
MBTHX64.dll	:	1.0.8.0
MBWrp64.dll	:	1.0.0.110
RCoInst64.dll	:	1.0.6.5
RP3DAA64.dll	:	6.0.6001.18
RP3DHT64.dll	:	6.0.6001.18
RtCOMB4.dll	:	2.0.0.117
RTCOMDLL.dll	:	2.0.0.117
RtkApi64.dll	:	1.0.0.10
RtkAP064.dll	:	11.0.6000.101
RtkCfg.dll	:	1.0.0.1
RtkCfg64.dll	:	1.0.0.1
RtlCPAPI.dll	:	1.0.2.4
RtlCPAPI64.dll	:	1.0.2.4
RtPgEx64.dll	:	6.0.6000.87
SFComm64.dll	:	2.0.0.8
SFDAP064.dll	:	2.0.0.8
SFHAP064.dll	:	2.0.0.8
SFProc64.dll	:	2.0.0.8
SFSAP064.dll	:	2.0.0.8
slcshp64.dll	:	1.0.3.0
slgeq64.dll	:	1.0.1.0
slh36064.dll	:	1.0.2.0
slinit64.dll	:	1.1.3.0
slmaxv64.dll	:	1.1.2.0
sltshd64.dll	:	1.1.1.0

Readme.txt

sluapo64.dll : 1.4.8.0  
 SRSHP64.dll : 1.1.0.0  
 SRSTSH64.dll : 1.1.4.0  
 SRSTSX64.dll : 3.2.0.0  
 SRSWOW64.dll : 1.1.3.0

HDMI Driver : -----  
 Vista/Wi n7 x86:  
 RtHDMV.sys : 6.0.1.5897  
 RtkAudioSrvATI.exe : 1.0.0.23  
 RtkUpd.exe : 2.8.0.0  
 RH3DAA32.dll : 6.0.6001.18  
 RH3DHT32.dll : 6.0.6001.18  
 RHCoInst.dll : 1.0.6.4  
 RHDMEExt.dll : 6.0.6000.82  
 RtkHDM.dll : 11.0.6000.101

Vista/Wi n7 x64:  
 RtHDMVX.sys : 6.0.1.5897  
 RtkAudioSrvATI64.exe : 1.0.0.23  
 RtkUpd64.exe : 2.8.0.0  
 RH3DAA64.dll : 6.0.6001.18  
 RH3DHT64.dll : 6.0.6001.18  
 RHCoInst64.dll : 1.0.6.4  
 RHDMEx64.dll : 6.0.6000.82  
 RtkHDM64.dll : 11.0.6000.101

XP/2K x86:  
 RtkHDM.sys : 5.10.0.5880  
 RtkUpd.exe : 2.7.1.3  
 RHCoInstXP.dll : 1.0.5.1  
 XP/2K x64:  
 RtkHDMX.sys : 5.10.0.5880  
 RtkUpd64.exe : 2.7.1.3  
 RHCoInst64XP.dll : 1.0.5.1

Driver Setup Program : 2.81

Windows 2000/XP Operate on :  
 Microsoft High Definition Audio Driver Package - KB888111  
 Package file version (kb888111.exe) : 6.1.22.0  
 Hdaudiobus.sys version : 5.10.00.5013

//=====

Driver Package R2.29

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887, ALC670
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887, ALC670
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Windows Server 2003, Vista, Windows Server 2008,

Windows7 - x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix

- 1.) Driver :
  1. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :  
 RTKHDA64.sys : 5.10.0.5898  
 RTKHDAUD.sys : 5.10.0.5898  
 Alcmtr.exe : 1.6.0.4  
 AlcWzrd.exe : 1.1.0.37  
 McCal.exe : 1.1.2.1  
 RTHDCPL.exe : 2.3.0.0  
 RtkAudioService.exe : 1.0.0.19  
 RtkAudioService64.exe : 1.0.0.19

```

Readme.txt
RTLCPL.exe : 1.0.1.66
RtlUpd.exe : 2.8.0.0
RtlUpd64.exe : 2.8.0.0
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.32
vncutil.exe : 1.0.0.23
vncutil64.exe : 1.0.0.23
AMBFilt.sys : 5.10.0.4240
AMBft64.sys : 5.10.0.4240
Mnfiltr.sys : 5.10.0.4112
Mnft64.sys : 5.10.0.4115
ALSndMgr.cpl : 1.0.0.11
RTSndMgr.cpl : 1.0.1.3
RCoInst64XP.dll : 1.0.6.3
RTCOMDLL.dll : 1.0.0.103
RtkCoInstXP.dll : 1.0.6.3
RtlCPAPI.dll : 1.0.2.3
Vista/Win7 driver : -----
Vista/Win7 driver for x86
RTKVHDA.sys : 6.0.1.5898
AERTSrv.exe : 1.0.32.9
APOPCH.exe : 1.0.0.0
RtHDVBg.exe : 1.0.0.5
RtHDVCpl.exe : 1.0.0.386
RtkAudioService.exe : 1.0.0.24
RtlUpd.exe : 2.8.0.0
SkyTel.exe : 2.0.2.2
vncutil.exe : 1.0.0.23
mbfiltr32.sys : 6.10.0.6
RTSndMgr.cpl : 1.0.0.16
AERTACap.dll : 2.0.32.8
AERTARen.dll : 1.0.32.8
FMAPO.dll : 0.0.18.2
MaxxAudioAPO.dll : 1.2.2.0
MaxxAudioAPO20.dll : 2.2.2.0
MaxxAudioEQ.dll : 5.9.7.0
MBAP032.dll : 1.0.9.0
MBPPCn32.dll : 1.0.0.110
Mbppld32.dll : 1.0.9.0
MBTHX32.dll : 1.0.6.0
MBWrp32.dll : 1.0.0.110
RP3DAA32.dll : 6.0.6001.18
RP3DHT32.dll : 6.0.6001.18
RTCOMDLL.dll : 2.0.0.117
RtkAPO.dll : 11.0.6000.101
RtkApoApi.dll : 1.0.0.10
RtkCfg.dll : 1.0.0.1
RtkCoInst.dll : 1.0.6.4
RtkPgExt.dll : 6.0.6000.84
RtlCPAPI.dll : 1.0.2.4
SFFXComm.dll : 2.0.0.6
SFFXDAP0.dll : 2.0.0.6
SFFXHAP0.dll : 2.0.0.6
SFFXProc.dll : 2.0.0.6
SFFXSAP0.dll : 2.0.0.6
slcshp32.dll : 1.0.3.0
slgeq32.dll : 1.0.1.0
slh36032.dll : 1.0.2.0
slinit32.dll : 1.1.3.0
slmaxv32.dll : 1.1.2.0
sltshd32.dll : 1.1.1.0
sluapo32.dll : 1.4.8.0
SRSHP360.dll : 1.1.0.0
SRSTSHD.dll : 1.1.4.0
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.1.3.0
WavesLib.dll : 5.9.7.0
Vista/Win7 driver for x64
RTKVHD64.sys : 6.0.1.5898

```

Readme.txt

AERTSr64.exe	: 1.0.64.9
APOCH.exe	: 1.0.0.0
RAVBg64.exe	: 1.0.0.5
RAVCpl64.exe	: 1.0.0.386
RtkAudioService64.exe	: 1.0.0.24
RtlUpd64.exe	: 2.8.0.0
SkyTel.exe	: 2.0.2.2
vncutil64.exe	: 1.0.0.23
GWfilt64.sys	: 6.10.0.3
mbfilt64.sys	: 6.10.0.6
RTSnMg64.cpl	: 1.0.0.16
AERTAC64.dll	: 2.0.64.8
AERTAR64.dll	: 1.0.64.8
FMAP064.dll	: 0.0.18.2
MaxxAudioAPO20.dll	: 2.2.2.0
MBAP032.dll	: 1.0.9.0
MBAP064.dll	: 1.0.9.0
MBPPcn64.dll	: 1.0.0.110
Mbpld64.dll	: 1.0.9.0
MBTHX32.dll	: 1.0.6.0
MBTHX64.dll	: 1.0.6.0
MBWrp64.dll	: 1.0.0.110
RCoInst64.dll	: 1.0.6.4
RP3DAA64.dll	: 6.0.6001.18
RP3DHT64.dll	: 6.0.6001.18
RtCOMB4.dll	: 2.0.0.117
RTCOMDLL.dll	: 2.0.0.117
RtkApi64.dll	: 1.0.0.10
RtkAPO64.dll	: 11.0.6000.101
RtkCfg.dll	: 1.0.0.1
RtkCfg64.dll	: 1.0.0.1
RtlCPAPI.dll	: 1.0.2.4
RtlCPAPI64.dll	: 1.0.2.4
RtPgEx64.dll	: 6.0.6000.84
SFComm64.dll	: 2.0.0.6
SFDAPO64.dll	: 2.0.0.6
SFHAP064.dll	: 2.0.0.6
SFProc64.dll	: 2.0.0.6
SFSAP064.dll	: 2.0.0.6
slcshp64.dll	: 1.0.3.0
slgeq64.dll	: 1.0.1.0
slh36064.dll	: 1.0.2.0
slInit64.dll	: 1.1.3.0
slmaxv64.dll	: 1.1.2.0
sltshd64.dll	: 1.1.1.0
sluapo64.dll	: 1.4.8.0
SRSHP64.dll	: 1.1.0.0
SRSTSH64.dll	: 1.1.4.0
SRSTX64.dll	: 3.2.0.0
SRSWOW64.dll	: 1.1.3.0
<b>HDMI Driver : -----</b>	
Vista/Win7 x86:	
RtHDMV.sys	: 6.0.1.5897
RtkAudioSrvATI.exe	: 1.0.0.23
RtkUpd.exe	: 2.8.0.0
RH3DAA32.dll	: 6.0.6001.18
RH3DHT32.dll	: 6.0.6001.18
RHCoInst.dll	: 1.0.6.4
RHDMExt.dll	: 6.0.6000.82
RtkHDM.dll	: 11.0.6000.101
Vista/Win7 x64:	
RtHDMVX.sys	: 6.0.1.5897
RtkAudioSrvATI64.exe	: 1.0.0.23
RtkUpd64.exe	: 2.8.0.0
RH3DAA64.dll	: 6.0.6001.18
RH3DHT64.dll	: 6.0.6001.18
RHCoInst64.dll	: 1.0.6.4



Readme.txt  
 RHDME64.dll : 6.0.6000.82  
 RtkHDM64.dll : 11.0.6000.101

XP/2K x86:  
 RtkHDM.sys : 5.10.0.5880  
 RtkUpd.exe : 2.7.1.3  
 RHCoInstXP.dll : 1.0.5.1  
 XP/2K x64:  
 RtkHDMX.sys : 5.10.0.5880  
 RtkUpd64.exe : 2.7.1.3  
 RHCoInst64XP.dll : 1.0.5.1  
 Driver Setup Program : 2.81

Windows 2000/XP Operate on :  
 Microsoft High Definition Audio Driver Package - KB888111  
 Package file version (kb888111.exe) : 6.1.22.0  
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.28

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887, ALC670
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887, ALC670
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Windows Server 2003, Vista, Windows Server 2008,

Windows7 - x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
  - 1.) Driver :
    1. Customizations.
  - 2.) Package :
    1. Fix uninstallation driver issue under Windows x64 system .

Windows 2000/XP : -----

Windows 2000/XP :  
 Windows 2000/XP :  
 RTKHDA64.sys : 5.10.0.5888  
 RTKHDAUD.sys : 5.10.0.5888  
 Alcmtr.exe : 1.6.0.4  
 AlcWzrd.exe : 1.1.0.37  
 McCal.exe : 1.1.2.1  
 RTHDCPL.exe : 2.2.9.7  
 RtkAudioService.exe : 1.0.0.19  
 RtkAudioService64.exe : 1.0.0.19  
 RTLCPL.exe : 1.0.1.66  
 RtlUpd.exe : 2.8.0.0  
 RtlUpd64.exe : 2.8.0.0  
 SkyTel.exe : 2.0.2.0  
 SoundMan.exe : 1.0.0.32  
 vncutil.exe : 1.0.0.23  
 vncutil64.exe : 1.0.0.23  
 AMBFilt.sys : 5.10.0.4240  
 AMBFt64.sys : 5.10.0.4240  
 Mbnfilt.sys : 5.10.0.4112  
 Mbnft64.sys : 5.10.0.4115  
 ALSndMgr.cpl : 1.0.0.11  
 RTSndMgr.cpl : 1.0.1.3  
 RCoInst64XP.dll : 1.0.6.2  
 RTCOMDLL.dll : 1.0.0.103  
 RtkCoInstXP.dll : 1.0.6.2  
 RtlCPAPI.dll : 1.0.2.3

Vista/Win7 driver : -----

Vista/Win7 driver for x86  
 RTKVHDA.sys : 6.0.1.5888  
 AERTSrv.exe : 1.0.32.9

	Readme.txt	
APOPCH.exe	:	1.0.0.0
RtHDVBg.exe	:	1.0.0.5
RtHDVCpl.exe	:	1.0.0.376
RtkAudioService.exe	:	1.0.0.22
RtlUpd.exe	:	2.8.0.0
SkyTel.exe	:	2.0.2.2
vncutil.exe	:	1.0.0.23
RTSndMgr.cpl	:	1.0.0.15
AERTACap.dll	:	2.0.32.8
AERTARen.dll	:	1.0.32.8
FMAP0.dll	:	0.0.18.2
MaxxAudioAP0.dll	:	1.2.2.0
MaxxAudioAP020.dll	:	2.2.2.0
MaxxAudioEQ.dll	:	5.9.7.0
MBAP032.dll	:	1.0.9.0
MBPPCn32.dll	:	1.0.0.110
MBppld32.dll	:	1.0.9.0
MBWrp32.dll	:	1.0.0.110
RP3DAA32.dll	:	6.0.6001.18
RP3DHT32.dll	:	6.0.6001.18
RTCOMDLL.dll	:	2.0.0.116
RtkAP0.dll	:	11.0.6000.101
RtkApoApi.dll	:	1.0.0.10
RtkCfg.dll	:	1.0.0.1
RtkCoInst.dll	:	1.0.6.2
RtkPgExt.dll	:	6.0.6000.82
RtlCPAPI.dll	:	1.0.2.4
SFFXComm.dll	:	2.0.0.6
SFFXDAP0.dll	:	2.0.0.6
SFFXHAP0.dll	:	2.0.0.6
SFFXProc.dll	:	2.0.0.6
SFFXSAP0.dll	:	2.0.0.6
slcshp32.dll	:	1.0.3.0
slgeq32.dll	:	1.0.1.0
slh36032.dll	:	1.0.2.0
slInit32.dll	:	1.1.3.0
slmaxv32.dll	:	1.1.2.0
sltshd32.dll	:	1.1.1.0
sluapo32.dll	:	1.4.8.0
SRSHP360.dll	:	1.1.0.0
SRSTSHD.dll	:	1.1.4.0
SRSTSXT.dll	:	3.2.0.0
SRSWOW.dll	:	1.1.3.0
WavesLib.dll	:	5.9.7.0
RCORES.dat	:	1.0.0.5
Vista/Win7 driver for x64		
RTKVHD64.sys	:	6.0.1.5888
AERTSr64.exe	:	1.0.64.9
APOPCH.exe	:	1.0.0.0
RAVBg64.exe	:	1.0.0.5
RAVCpl64.exe	:	1.0.0.376
RtkAudioService64.exe	:	1.0.0.22
RtlUpd64.exe	:	2.8.0.0
SkyTel.exe	:	2.0.2.2
vncutil64.exe	:	1.0.0.23
GWfilt64.sys	:	6.10.0.3
RTSndMgr64.cpl	:	1.0.0.15
AERTAC64.dll	:	2.0.64.8
AERTAR64.dll	:	1.0.64.8
FMAP064.dll	:	0.0.18.2
MaxxAudioAP020.dll	:	2.2.2.0
MBAP032.dll	:	1.0.9.0
MBAP064.dll	:	1.0.9.0
MBPPCn64.dll	:	1.0.0.110
MBppld64.dll	:	1.0.9.0
MBWrp64.dll	:	1.0.0.110
RCoInst64.dll	:	1.0.6.2
RP3DAA64.dll	:	6.0.6001.18
RP3DHT64.dll	:	6.0.6001.18

```

Readme.txt
RtCOMB4.dll : 2.0.0.116
RTCOMDLL.dll : 2.0.0.116
RtkApi64.dll : 1.0.0.10
RtkAPO64.dll : 11.0.6000.101
RtkCfg.dll : 1.0.0.1
RtkCfg64.dll : 1.0.0.1
RtLCPAPI.dll : 1.0.2.4
RtLCPAPI64.dll : 1.0.2.4
RtPgEx64.dll : 6.0.6000.82
SFComm64.dll : 2.0.0.6
SFDAP064.dll : 2.0.0.6
SFHAP064.dll : 2.0.0.6
SFProc64.dll : 2.0.0.6
SFSAP064.dll : 2.0.0.6
slcshp64.dll : 1.0.3.0
slgeq64.dll : 1.0.1.0
slh36064.dll : 1.0.2.0
slInit64.dll : 1.1.3.0
slmaxv64.dll : 1.1.2.0
sltshd64.dll : 1.1.1.0
sluapo64.dll : 1.4.8.0
SRSHP64.dll : 1.1.0.0
SRSTSH64.dll : 1.1.4.0
SRSTX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
RCORES64.dat : 1.0.0.5
HDM Driver :-----
Vista/Win7 x86:
RtHDMV.sys : 6.0.1.5880
RtkUpd.exe : 2.7.1.3
RH3DAA32.dll : 6.0.6001.18
RH3DHT32.dll : 6.0.6001.18
RHCoInst.dll : 1.0.6.0
RHDMExt.dll : 6.0.6000.82
RtkHDM.dll : 11.0.6000.100

Vista/Win7 x64:
RtHDMVX.sys : 6.0.1.5880
RtkUpd64.exe : 2.7.1.3
RH3DAA64.dll : 6.0.6001.18
RH3DHT64.dll : 6.0.6001.18
RHCoInst64.dll : 1.0.6.0
RHDMEx64.dll : 6.0.6000.82
RtkHDM64.dll : 11.0.6000.100

XP/2K x86:
RtkHDM.sys : 5.10.0.5880
RtkUpd.exe : 2.7.1.3
RHCoInstXP.dll : 1.0.5.1
XP/2K x64:
RtkHDMX.sys : 5.10.0.5880
RtkUpd64.exe : 2.7.1.3
RHCoInst64XP.dll : 1.0.5.1

Driver Setup Program : 2.80

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

```

```
//=====
Driver Package R2.27
```

- Realtek HD Audio Driver support all of Realtek HD Audio Codec .
1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
  2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD,

Readme.txt

ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887

3. HDM Device WHQL Support: ATI HDM Devices

4. OS Supporting: Microsoft WindowsXP, Windows2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 - x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

2. Fix GUI issue which can't launch Windows MediaPlayer under Win7 OS.

Windows 2000/XP : -----

Windows 2000/XP :

RTKHDA64.sys : 5.10.0.5874  
RTKHDAUD.sys : 5.10.0.5874  
McCal.exe : 1.1.2.1  
RTHDCPL.exe : 2.2.9.2  
RtkAudioService64.exe : 1.0.0.19  
RtkAudioService.exe : 1.0.0.19  
RTLCPPL.exe : 1.0.1.66  
RtlUpd64.exe : 2.7.1.4  
RtlUpd.exe : 2.7.1.4  
SkyTel.exe : 2.0.2.0  
SoundMan.exe : 1.0.0.32  
vncutil64.exe : 1.0.0.23  
vncutil.exe : 1.0.0.23  
AlcMtr.exe : 1.6.0.4  
AlcWzrd.exe : 1.1.0.37  
Mnflt.sys : 5.10.0.4112  
Mnft64.sys : 5.10.0.4115  
AMBflt.sys : 5.10.0.4240  
AMBft64.sys : 5.10.0.4240  
RTSndMgr.cpl : 1.0.1.3  
ALSndMgr.cpl : 1.0.0.11  
RCoInst64XP.dll : 1.0.5.9  
RTCOMDLL.dll : 1.0.0.103  
RtkCoInstXP.dll : 1.0.5.9  
RtlCPAPI.dll : 1.0.2.3

Vista/Win7 driver : -----

Vista/Win7 driver for x86

RTKVHDA.sys : 6.0.1.5874  
AERTSrv.exe : 1.0.32.9  
APOPCH.exe : 1.0.0.0  
RtHDVCpl.exe : 1.0.0.366  
RtkAudioService.exe : 1.0.0.21  
RtlUpd.exe : 2.7.1.4  
SkyTel.exe : 2.0.2.2  
vncutil.exe : 1.0.0.23  
RTSndMgr.cpl : 1.0.0.15  
AERTACap.dll : 2.0.32.8  
AERTARen.dll : 1.0.32.8  
FMAPO.dll : 0.0.14.1  
MaxxAudioAPO.dll : 1.2.2.0  
MaxxAudioAPO20.dll : 2.2.2.0  
MaxxAudioEQ.dll : 5.9.7.0  
MBAP032.dll : 1.0.9.0  
MBPPCn32.dll : 1.0.0.110  
MBppld32.dll : 1.0.9.0  
MBWp32.dll : 1.0.0.110  
RP3DAA32.dll : 6.0.6001.18  
RP3DHT32.dll : 6.0.6001.18  
RTCOMDLL.dll : 2.0.0.113  
RtkAPO.dll : 11.0.6000.100  
RtkApoApi.dll : 1.0.0.10  
RtkCfg.dll : 1.0.0.1  
RtkCoInst.dll : 1.0.6.0  
RtkPgExt.dll : 6.0.6000.82  
RtlCPAPI.dll : 1.0.2.4  
SFFXComm.dll : 2.0.0.6  
SFFXDAP0.dll : 2.0.0.6

	Readme.txt	
SFFXHAP0.dll	:	2.0.0.6
SFFXProc.dll	:	2.0.0.6
SFFXSAP0.dll	:	2.0.0.6
slcshp32.dll	:	1.0.3.0
slgeq32.dll	:	1.0.1.0
slh36032.dll	:	1.0.2.0
slInit32.dll	:	1.1.3.0
slmaxv32.dll	:	1.1.2.0
sltshd32.dll	:	1.1.1.0
sluapo32.dll	:	1.4.8.0
SRSHP360.dll	:	1.1.0.0
SRSTSHD.dll	:	1.1.4.0
SRSTSXT.dll	:	3.2.0.0
SRSWOW.dll	:	1.1.3.0
WavesLib.dll	:	5.9.7.0
Vista/Win7 driver for x64		
RTKVHD64.sys	:	6.0.1.5874
AERTSr64.exe	:	1.0.64.9
APOPCH.exe	:	1.0.0.0
RAVCpl64.exe	:	1.0.0.366
RtkAudioService64.exe	:	1.0.0.21
RtlUpd64.exe	:	2.7.1.4
SkyTel.exe	:	2.0.2.2
vncutil64.exe	:	1.0.0.23
GWfilt64.sys	:	6.10.0.3
RTSnMg64.cpl	:	1.0.0.15
AERTAC64.dll	:	2.0.64.8
AERTAR64.dll	:	1.0.64.8
FMAP064.dll	:	0.0.14.1
MaxxAudioAP020.dll	:	2.2.2.0
MBAP032.dll	:	1.0.9.0
MBAP064.dll	:	1.0.9.0
MBPPCn64.dll	:	1.0.0.110
MBpld64.dll	:	1.0.9.0
MBWrp64.dll	:	1.0.0.110
RCoInst64.dll	:	1.0.6.0
RP3DAA64.dll	:	6.0.6001.18
RP3DHT64.dll	:	6.0.6001.18
RtCOM64.dll	:	2.0.0.113
RTCOMDLL.dll	:	2.0.0.113
RtkApi64.dll	:	1.0.0.10
RtkAP064.dll	:	11.0.6000.100
RtkCfg.dll	:	1.0.0.1
RtkCfg64.dll	:	1.0.0.1
RtlCPAPI.dll	:	1.0.2.4
RtlCPAPI64.dll	:	1.0.2.4
RtPgEx64.dll	:	6.0.6000.82
SFComm64.dll	:	2.0.0.6
SFDAP064.dll	:	2.0.0.6
SFHAP064.dll	:	2.0.0.6
SFProc64.dll	:	2.0.0.6
SFSAP064.dll	:	2.0.0.6
slcshp64.dll	:	1.0.3.0
slgeq64.dll	:	1.0.1.0
slh36064.dll	:	1.0.2.0
slInit64.dll	:	1.1.3.0
slmaxv64.dll	:	1.1.2.0
sltshd64.dll	:	1.1.1.0
sluapo64.dll	:	1.4.8.0
SRSHP64.dll	:	1.1.0.0
SRSTSH64.dll	:	1.1.4.0
SRSTX64.dll	:	3.2.0.0
SRSWOW64.dll	:	1.1.3.0
HDMI Driver :	-----	
Vista/Win7 x86:		
RtHDMV.sys	:	6.0.1.5857
RtkUpd.exe	:	2.7.1.3
RH3DAA32.dll	:	6.0.6001.18
RH3DHT32.dll	:	6.0.6001.18

Readme.txt

RHCoInst.dll : 1.0.4.9  
RHDMEExt.dll : 6.0.6000.79  
RtkHDM.dll : 11.0.6000.99

Vista/Win7 x64:

RtHDMVX.sys : 6.0.1.5857  
RtkUpd64.exe : 2.7.1.3  
RH3DAA64.dll : 6.0.6001.18  
RH3DHT64.dll : 6.0.6001.18  
RHCoInst64.dll : 1.0.4.4  
RHDME64.dll : 6.0.6000.79  
RtkHDM64.dll : 11.0.6000.99

XP/2K x86:

RtkHDM.sys : 5.10.0.5857  
RtkUpd.exe : 2.7.1.3  
RHCoInstXP.dll : 1.0.5.1

XP/2K x64:

RtkHDMX.sys : 5.10.0.5857  
RtkUpd64.exe : 2.7.1.3  
RHCoInst64XP.dll : 1.0.5.1

Driver Setup Program : 2.77

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111  
Package file version (kb888111.exe) : 6.1.22.0  
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.26

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Windows Server 2003, Vista, Windows Server 2008,

Windows7 - x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.
2. Update SRS components.

Windows 2000/XP : -----

Windows 2000/XP :

RTKHDA64.sys : 5.10.0.5864  
RTKHDAUD.sys : 5.10.0.5864  
McCal.exe : 1.1.2.1  
RTHDCPL.exe : 2.2.9.0  
RtkAudioService64.exe : 1.0.0.19  
RtkAudioService.exe : 1.0.0.19  
RTLCPPL.exe : 1.0.1.66  
RtlUpd64.exe : 2.7.1.3  
RtlUpd.exe : 2.7.1.3  
SkyTel.exe : 2.0.2.0  
SoundMan.exe : 1.0.0.32  
vncutil64.exe : 1.0.0.23  
vncutil.exe : 1.0.0.23  
Alcmtr.exe : 1.6.0.4  
AlcWzrd.exe : 1.1.0.37  
AMBft64.sys : 5.10.0.4240  
Mnft64.sys : 5.10.0.4112  
Mnft64.sys : 5.10.0.4115  
AMBFilt.sys : 5.10.0.4240  
RTSndMgr.cpl : 1.0.1.3  
ALSndMgr.cpl : 1.0.0.11

Readme.txt

```

RCoInst64XP.dll : 1.0.5.6
RTCOMDLL.dll : 1.0.0.103
RtkCoInstXP.dll : 1.0.5.6
RtlCPAPI.dll : 1.0.2.3
Vista/Win7 driver : -----
Vista/Win7 driver for x86
RTKVHDA.sys : 6.0.1.5864
AERTSrv.exe : 1.0.32.9
APOPCH.exe : 1.0.0.0
RtHDVCpl.exe : 1.0.0.356
RtkAudioService.exe : 1.0.0.19
RtlUpd.exe : 2.7.1.3
SkyTel.exe : 2.0.2.2
vncutil.exe : 1.0.0.23
RTSndMgr.cpl : 1.0.0.15
AERTACap.dll : 2.0.32.8
AERTARen.dll : 1.0.32.8
FMAP0.dll : 0.0.14.1
MaxxAudioAPO.dll : 1.2.2.0
MaxxAudioAPO20.dll : 2.2.2.0
MaxxAudioEQ.dll : 5.9.7.0
MBAP032.dll : 1.0.9.0
MBPPCn32.dll : 1.0.0.110
MBpld32.dll : 1.0.9.0
MBWrp32.dll : 1.0.0.110
RP3DAA32.dll : 6.0.6001.18
RP3DHT32.dll : 6.0.6001.18
RTCOMDLL.dll : 2.0.0.113
RtkAPO.dll : 11.0.6000.99
RtkApoApi.dll : 1.0.0.10
RtkCfg.dll : 1.0.0.1
RtkCoInst.dll : 1.0.5.8
RtkPgExt.dll : 6.0.6000.79
RtlCPAPI.dll : 1.0.2.4
SFFXComm.dll : 2.0.0.6
SFFXDAP0.dll : 2.0.0.6
SFFXHAP0.dll : 2.0.0.6
SFFXProc.dll : 2.0.0.6
SFFXSAP0.dll : 2.0.0.6
slcshp32.dll : 1.0.3.0
slgeq32.dll : 1.0.1.0
slh36032.dll : 1.0.2.0
slInit32.dll : 1.1.3.0
slmaxv32.dll : 1.1.1.0
sltshd32.dll : 1.1.1.0
sluapo32.dll : 1.4.6.0
SRSHP360.dll : 1.1.0.0
SRSTSHD.dll : 1.1.4.0
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.1.3.0
WavesLib.dll : 5.9.7.0
Vista/Win7 driver for x64
RTKVHD64.sys : 6.0.1.5864
AERTSr64.exe : 1.0.64.9
APOPCH.exe : 1.0.0.0
RAVCpl64.exe : 1.0.0.356
RtkAudioService64.exe : 1.0.0.19
RtlUpd64.exe : 2.7.1.3
SkyTel.exe : 2.0.2.2
vncutil64.exe : 1.0.0.23
GWfil64.sys : 6.10.0.3
RTSndMgr64.cpl : 1.0.0.15
AERTAC64.dll : 2.0.64.8
AERTAR64.dll : 1.0.64.8
FMAP064.dll : 0.0.14.1
MaxxAudioAPO20.dll : 2.2.2.0
MBAP032.dll : 1.0.9.0
MBAP064.dll : 1.0.9.0
MBPPCn64.dll : 1.0.0.110

```

Readme.txt

```

Mbpld64.dll : 1.0.9.0
MBWrp64.dll : 1.0.0.110
RCoInst64.dll : 1.0.5.8
RP3DAA64.dll : 6.0.6001.18
RP3DHT64.dll : 6.0.6001.18
RtCOMB4.dll : 2.0.0.113
RTCOMDLL.dll : 2.0.0.113
RtkApi64.dll : 1.0.0.10
RtkAPO64.dll : 11.0.6000.99
RtkCfg.dll : 1.0.0.1
RtkCfg64.dll : 1.0.0.1
RtLCPAPI.dll : 1.0.2.4
RtLCPAPI64.dll : 1.0.2.4
RtPgEx64.dll : 6.0.6000.79
SFComm64.dll : 2.0.0.6
SFDAPO64.dll : 2.0.0.6
SFHAPO64.dll : 2.0.0.6
SFProc64.dll : 2.0.0.6
SFSAP064.dll : 2.0.0.6
slcshp64.dll : 1.0.3.0
slgeq64.dll : 1.0.1.0
slh36064.dll : 1.0.2.0
slInit64.dll : 1.1.3.0
slmaxv64.dll : 1.1.1.0
sltshd64.dll : 1.1.1.0
sluapo64.dll : 1.4.6.0
SRSHP64.dll : 1.1.0.0
SRSTSH64.dll : 1.1.4.0
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
HDMI Driver : -----
Vista/Win7 x86:
RtHDMV.sys : 6.0.1.5857
RtkUpd.exe : 2.7.1.3
RH3DAA32.dll : 6.0.6001.18
RH3DHT32.dll : 6.0.6001.18
RHCoInst.dll : 1.0.4.9
RHDMExt.dll : 6.0.6000.79
RtkHDM.dll : 11.0.6000.99

Vista/Win7 x64:
RtHDMVX.sys : 6.0.1.5857
RtkUpd64.exe : 2.7.1.3
RH3DAA64.dll : 6.0.6001.18
RH3DHT64.dll : 6.0.6001.18
RHCoInst64.dll : 1.0.4.4
RHDMEx64.dll : 6.0.6000.79
RtkHDM64.dll : 11.0.6000.99

XP/2K x86:
RtkHDM.sys : 5.10.0.5857
RtkUpd.exe : 2.7.1.3
RHCoInstXP.dll : 1.0.5.1

XP/2K x64:
RtkHDMX.sys : 5.10.0.5857
RtkUpd64.exe : 2.7.1.3
RHCoInst64XP.dll : 1.0.5.1

Driver Setup Program : 2.76

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

```

```

//=====
Driver Package R2.25
Realtek HD Audio Driver support all of Realtek HD Audio Codec .

```



Readme.txt

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 - x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
  - 1.) Driver :
    1. Customizations.
    2. Windows 7 WHQL Driver.

Windows 2000/XP : -----

Windows 2000/XP :

RTKHDA64.sys	: 5.10.0.5859
RTKHDAUD.sys	: 5.10.0.5859
Alcmtr.exe	: 1.6.0.4
AlcWzrd.exe	: 1.1.0.37
McCal.exe	: 1.1.2.1
RTHDCPL.exe	: 2.2.9.0
RtkAudioService.exe	: 1.0.0.19
RtkAudioService64.exe	: 1.0.0.19
RTLCPPL.exe	: 1.0.1.66
RtlUpd.exe	: 2.7.1.3
RtlUpd64.exe	: 2.7.1.3
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.32
vncutil.exe	: 1.0.0.23
vncutil64.exe	: 1.0.0.23
AMBFilt.sys	: 5.10.0.4240
AMBFt64.sys	: 5.10.0.4240
Mnft64.sys	: 5.10.0.4112
Mnft64.sys	: 5.10.0.4115
ALSndMgr.cpl	: 1.0.0.11
RTSndMgr.cpl	: 1.0.1.3
RCoInst64XP.dll	: 1.0.5.6
RTCOMDLL.dll	: 1.0.0.103
RtkCoInstXP.dll	: 1.0.5.6
RtlCPAPI.dll	: 1.0.2.3

Vista/Win7 driver : -----

Vista/Win7 driver for x86

RTKVHDA.sys	: 6.0.1.5859
AERTSrv.exe	: 1.0.32.9
APOPCH.exe	: 1.0.0.0
RtHDVCpl.exe	: 1.0.0.353
RtkAudioService.exe	: 1.0.0.19
RtlUpd.exe	: 2.7.1.3
SkyTel.exe	: 2.0.2.2
vncutil.exe	: 1.0.0.23
RTSndMgr.cpl	: 1.0.0.15
AERTACap.dll	: 2.0.32.8
AERTARen.dll	: 1.0.32.8
FMAPO.dll	: 0.0.14.1
MaxxAudioAPO.dll	: 1.2.2.0
MaxxAudioAPO20.dll	: 2.2.2.0
MaxxAudioEQ.dll	: 5.9.7.0
MBAPO32.dll	: 1.0.9.0
MBPPCn32.dll	: 1.0.0.110
MBpld32.dll	: 1.0.9.0
MBWrp32.dll	: 1.0.0.110
RP3DAA32.dll	: 6.0.6001.18
RP3DHT32.dll	: 6.0.6001.18
RTCOMDLL.dll	: 2.0.0.113
RtkAPO.dll	: 11.0.6000.99
RtkApoApi.dll	: 1.0.0.10
RtkCfg.dll	: 1.0.0.1
RtkCoInst.dll	: 1.0.5.8
RtkPgExt.dll	: 6.0.6000.79

Readme.txt

Rt1CPAPI.dll	: 1.0.2.4
SFFXComm.dll	: 2.0.0.6
SFFXDAPO.dll	: 2.0.0.6
SFFXHAP0.dll	: 2.0.0.6
SFFXProc.dll	: 2.0.0.6
SFFXSAP0.dll	: 2.0.0.6
slcshp32.dll	: 1.0.3.0
slgeq32.dll	: 1.0.1.0
slh36032.dll	: 1.0.2.0
slInit32.dll	: 1.1.3.0
slmaxv32.dll	: 1.0.4.0
sltshd32.dll	: 1.1.1.0
sluapo32.dll	: 1.3.4.0
SRSHP360.dll	: 1.1.0.0
SRSTSHD.dll	: 1.1.4.0
SRSTSXT.dll	: 3.2.0.0
SRSWOW.dll	: 1.1.3.0
WavesLib.dll	: 5.9.7.0
Vista/Win7 driver for x64	
RTKVHD64.sys	: 6.0.1.5859
AERTSr64.exe	: 1.0.64.9
APOPCH.exe	: 1.0.0.0
RAVCpl64.exe	: 1.0.0.353
RtkAudioService64.exe	: 1.0.0.19
RtlUpd64.exe	: 2.7.1.3
SkyTel.exe	: 2.0.2.2
vncutil64.exe	: 1.0.0.23
GWfilt64.sys	: 6.10.0.3
RTSnMg64.cpl	: 1.0.0.15
AERTAC64.dll	: 2.0.64.8
AERTAR64.dll	: 1.0.64.8
FMAP064.dll	: 0.0.14.1
MaxxAudioAPO20.dll	: 2.2.2.0
MBAP032.dll	: 1.0.9.0
MBAP064.dll	: 1.0.9.0
MBPPCn64.dll	: 1.0.0.110
MBppld64.dll	: 1.0.9.0
MBWrp64.dll	: 1.0.0.110
RCoInst64.dll	: 1.0.5.8
RP3DAA64.dll	: 6.0.6001.18
RP3DHT64.dll	: 6.0.6001.18
RtCOMB4.dll	: 2.0.0.113
RTCOMDLL.dll	: 2.0.0.113
RtkApi64.dll	: 1.0.0.10
RtkAPO64.dll	: 11.0.6000.99
RtkCfg.dll	: 1.0.0.1
RtkCfg64.dll	: 1.0.0.1
Rt1CPAPI.dll	: 1.0.2.4
Rt1CPAPI64.dll	: 1.0.2.4
RtPgEx64.dll	: 6.0.6000.79
SFComm64.dll	: 2.0.0.6
SFDAPO64.dll	: 2.0.0.6
SFHAP064.dll	: 2.0.0.6
SFProc64.dll	: 2.0.0.6
SFSAP064.dll	: 2.0.0.6
slcshp64.dll	: 1.0.3.0
slgeq64.dll	: 1.0.1.0
slh36064.dll	: 1.0.2.0
slInit64.dll	: 1.1.3.0
slmaxv64.dll	: 1.0.4.0
sltshd64.dll	: 1.1.1.0
sluapo64.dll	: 1.3.4.0
SRSHP64.dll	: 1.1.0.0
SRSTSH64.dll	: 1.1.4.0
SRSTSX64.dll	: 3.2.0.0
SRSWOW64.dll	: 1.1.3.0
HDMI Driver : -----	
Vista/Win7 x86:	
RtHDMIV.sys	: 6.0.1.5857

Readme.txt

RtkUpd.exe : 2.7.1.3  
RH3DAA32.dll : 6.0.6001.18  
RH3DHT32.dll : 6.0.6001.18  
RHCoInst.dll : 1.0.4.9  
RHDMEExt.dll : 6.0.6000.79  
RtkHDM.dll : 11.0.6000.99

Vista/Win7 x64:

RtHDMVX.sys : 6.0.1.5857  
RtkUpd64.exe : 2.7.1.3  
RH3DAA64.dll : 6.0.6001.18  
RH3DHT64.dll : 6.0.6001.18  
RHCoInst64.dll : 1.0.4.4  
RHDME64.dll : 6.0.6000.79  
RtkHDM64.dll : 11.0.6000.99

XP/2K x86:

RtkHDM.sys : 5.10.0.5857  
RtkUpd.exe : 2.7.1.3  
RHCoInstXP.dll : 1.0.5.1

XP/2K x64:

RtkHDMX.sys : 5.10.0.5857  
RtkUpd64.exe : 2.7.1.3  
RHCoInst64XP.dll : 1.0.5.1

Driver Setup Program : 2.76

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111  
Package file version (kb888111.exe) : 6.1.22.0  
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.24

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
3. HDMI Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 - x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
  - 1.) Driver :
    1. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :  
RTKHDA64.sys : 5.10.0.5854  
RTKHDAUD.sys : 5.10.0.5854  
McCal.exe : 1.1.2.1  
RTHDCPL.exe : 2.2.8.8  
RtkAudioService64.exe : 1.0.0.19  
RtkAudioService.exe : 1.0.0.19  
RTLCPPL.exe : 1.0.1.66  
RtlUpd64.exe : 2.7.1.3  
RtlUpd.exe : 2.7.1.3  
SkyTel.exe : 2.0.2.0  
SoundMan.exe : 1.0.0.32  
vncutil64.exe : 1.0.0.23  
vncutil.exe : 1.0.0.23  
Alcmtr.exe : 1.6.0.4  
AlcWzrd.exe : 1.1.0.37  
Mnfltl.sys : 5.10.0.4112  
Mnft64.sys : 5.10.0.4115  
AMBFlt.sys : 5.10.0.4240  
AMBft64.sys : 5.10.0.4240

Readme.txt

```

RTSndMgr. cpl           : 1.0.1.3
ALSndMgr. cpl          : 1.0.0.11
RCoInst64XP. dll      : 1.0.5.6
RTCOMDLL. dll         : 1.0.0.102
RtkCoInstXP. dll     : 1.0.5.6
RtICPAPI. dll        : 1.0.2.3
Vista driver : -----
Vista driver for x86
RTKVHDA. sys          : 6.0.1.5854
AERTSrv. exe          : 1.0.32.9
APOPCH. exe           : 1.0.0.0
RtHDVCpl. exe         : 1.0.0.352
RtkAudioService. exe : 1.0.0.19
RtlUpd. exe           : 2.7.1.3
SkyTel. exe           : 2.0.2.2
vncutil. exe          : 1.0.0.23
RTSndMgr. cpl         : 1.0.0.15
AERTACap. dll         : 2.0.32.8
AERTARen. dll         : 1.0.32.8
FMAP0. dll            : 0.0.14.1
MaxxAudioAP0. dll    : 1.2.2.0
MaxxAudioAP020. dll  : 2.2.2.0
MaxxAudioEQ. dll     : 5.9.7.0
MBAP032. dll          : 1.0.0.630
MBPPCn32. dll         : 1.0.0.80
MBpld32. dll          : 1.0.0.630
MBWrp32. dll          : 1.0.0.80
RP3DAA32. dll         : 6.0.6001.18
RP3DHT32. dll         : 6.0.6001.18
RTCOMDLL. dll         : 2.0.0.113
RtkAPO. dll           : 11.0.6000.99
RtkApoApi. dll        : 1.0.0.10
RtkCfg. dll           : 1.0.0.1
RtkCoInst. dll        : 1.0.5.7
RtkPgExt. dll         : 6.0.6000.79
RtICPAPI. dll         : 1.0.2.4
SFFXComm. dll         : 2.0.0.6
SFFXDAP0. dll         : 2.0.0.6
SFFXHAP0. dll         : 2.0.0.6
SFFXProc. dll         : 2.0.0.6
SFFXSAP0. dll         : 2.0.0.6
slcshp32. dll         : 1.0.3.0
slgeq32. dll          : 1.0.1.0
slh36032. dll         : 1.0.2.0
slInit32. dll         : 1.1.3.0
slmaxv32. dll         : 1.0.4.0
sltshd32. dll         : 1.1.1.0
sluapo32. dll         : 1.3.4.0
SRSHp360. dll         : 1.1.0.0
SRSTSHD. dll          : 1.1.4.0
SRSTSXT. dll          : 3.2.0.0
SRSWOW. dll           : 1.1.3.0
WavesLib. dll         : 5.9.7.0
Vista driver for x64
RTKVHD64. sys         : 6.0.1.5854
AERTSr64. exe         : 1.0.64.9
APOPCH. exe           : 1.0.0.0
RAVCpl64. exe         : 1.0.0.352
RtkAudioService64. exe : 1.0.0.19
RtlUpd64. exe         : 2.7.1.3
SkyTel. exe           : 2.0.2.2
vncutil64. exe        : 1.0.0.23
GWfilt64. sys         : 6.10.0.3
RTSnMg64. cpl         : 1.0.0.15
AERTAC64. dll         : 2.0.64.8
AERTAR64. dll         : 1.0.64.8
FMAP064. dll          : 0.0.14.1
MaxxAudioAP020. dll  : 2.2.2.0
MBAP032. dll          : 1.0.0.630

```

```

Readme.txt
MBAP064. dll : 1. 0. 0. 630
MBPPCn64. dll : 1. 0. 0. 80
Mbppld64. dll : 1. 0. 0. 630
MBWrp64. dll : 1. 0. 0. 80
RCoInst64. dll : 1. 0. 5. 7
RP3DAA64. dll : 6. 0. 6001. 18
RP3DHT64. dll : 6. 0. 6001. 18
RtCOMB4. dll : 2. 0. 0. 113
RTCOMDLL. dll : 2. 0. 0. 113
RtkApi 64. dll : 1. 0. 0. 10
RtkAP064. dll : 11. 0. 6000. 99
RtkCfg. dll : 1. 0. 0. 1
RtkCfg64. dll : 1. 0. 0. 1
RtlCPAPI. dll : 1. 0. 2. 4
RtlCPAPI64. dll : 1. 0. 2. 4
RtPgEx64. dll : 6. 0. 6000. 79
SFComm64. dll : 2. 0. 0. 6
SFDAP064. dll : 2. 0. 0. 6
SFHAP064. dll : 2. 0. 0. 6
SFProc64. dll : 2. 0. 0. 6
SFSAP064. dll : 2. 0. 0. 6
slcshp64. dll : 1. 0. 3. 0
slgeq64. dll : 1. 0. 1. 0
slh36064. dll : 1. 0. 2. 0
slInit64. dll : 1. 1. 3. 0
slmaxv64. dll : 1. 0. 4. 0
sltshd64. dll : 1. 1. 1. 0
sluapo64. dll : 1. 3. 4. 0
SRSHP64. dll : 1. 1. 0. 0
SRSTSH64. dll : 1. 1. 4. 0
SRSTSX64. dll : 3. 2. 0. 0
SRSWOW64. dll : 1. 1. 3. 0
HDM Driver : -----
Vista x86:
RtHDMV. sys : 6. 0. 1. 5832
RtkUpd. exe : 2. 7. 1. 3
RH3DAA32. dll : 6. 0. 6001. 18
RH3DHT32. dll : 6. 0. 6001. 18
RHCoInst. dll : 1. 0. 4. 9
RHDMExt. dll : 6. 0. 6000. 75
RtkHDM. dll : 11. 0. 6000. 95

Vista x64:
RtHDMVX. sys : 6. 0. 1. 5832
RtkUpd64. exe : 2. 7. 1. 3
RH3DAA64. dll : 6. 0. 6001. 18
RH3DHT64. dll : 6. 0. 6001. 18
RHCoInst64. dll : 1. 0. 4. 4
RHDMEx64. dll : 6. 0. 6000. 75
RtkHDM64. dll : 11. 0. 6000. 95

XP/2K x86:
RtkHDM. sys : 5. 10. 0. 5832
RtkUpd. exe : 2. 7. 1. 3
RHCoInstXP. dll : 1. 0. 5. 1

XP/2K x64:
RtkHDMX. sys : 5. 10. 0. 5832
RtkUpd64. exe : 2. 7. 1. 3
RHCoInst64XP. dll : 1. 0. 5. 1

Driver Setup Program : 2. 76

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6. 1. 22. 0
Hdaudiobus. sys version : 5. 10. 00. 5013

```

//=====

Readme.txt

Driver Package R2.23

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 - x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
  - 1.) Driver :
    1. Customizations.
    2. Fix DTM 1.4 lullaby test & wave pull mode test issue.

Windows 2000/XP : -----

Windows 2000/XP :  
RTKHDA64.sys : 5.10.0.5845  
RTKHDAUD.sys : 5.10.0.5845  
Alcmtr.exe : 1.6.0.4  
AlcWzrd.exe : 1.1.0.37  
Mccal.exe : 1.1.2.1  
RTHDCPL.exe : 2.2.8.4  
RtkAudioService64.exe : 1.0.0.19  
RtkAudioService.exe : 1.0.0.19  
RTLCPPL.exe : 1.0.1.66  
RtlUpd64.exe : 2.7.1.3  
RtlUpd.exe : 2.7.1.3  
SkyTel.exe : 2.0.2.0  
SoundMan.exe : 1.0.0.32  
vncutil64.exe : 1.0.0.23  
vncutil.exe : 1.0.0.23  
AMBfilt.sys : 5.10.0.4240  
AMBft64.sys : 5.10.0.4240  
Mbnfilt.sys : 5.10.0.4112  
Mnft64.sys : 5.10.0.4115  
ALSndMgr.cpl : 1.0.0.11  
RTSndMgr.cpl : 1.0.1.3  
RCoInst64XP.dll : 1.0.5.3  
RTCOMDLL.dll : 1.0.0.102  
RtkCoInstXP.dll : 1.0.5.3  
RtlCPAPI.dll : 1.0.2.3

Vista driver : -----

Vista driver for x86  
RTKVHDA.sys : 6.0.1.5845  
AERTSrv.exe : 1.0.32.9  
APOPCH.exe : 1.0.0.0  
RtHDVCpl.exe : 1.0.0.345  
RtkAudioService.exe : 1.0.0.19  
RtlUpd.exe : 2.7.1.3  
SkyTel.exe : 2.0.2.2  
vncutil.exe : 1.0.0.23  
RTSndMgr.cpl : 1.0.0.15  
AERTACap.dll : 2.0.32.8  
AERTARen.dll : 1.0.32.8  
FMAPO.dll : 0.0.14.1  
MaxxAudioAPO.dll : 1.2.2.0  
MaxxAudioAPO20.dll : 2.2.2.0  
MaxxAudioEQ.dll : 5.9.7.0  
MBAPO32.dll : 1.0.0.630  
MBPPCn32.dll : 1.0.0.80  
Mbpld32.dll : 1.0.0.630  
MBWrp32.dll : 1.0.0.80  
RP3DAA32.dll : 6.0.6001.18  
RP3DHT32.dll : 6.0.6001.18  
RTCOMDLL.dll : 2.0.0.113  
RtkAPO.dll : 11.0.6000.98  
RtkApoApi.dll : 1.0.0.10  
RtkCfgr.dll : 1.0.0.1

Readme.txt

RtkCoInst.dll	: 1.0.5.5
RtkPgExt.dll	: 6.0.6000.78
RtlCPAPI.dll	: 1.0.2.4
SFFXComm.dll	: 2.0.0.6
SFFXDAP0.dll	: 2.0.0.6
SFFXHAP0.dll	: 2.0.0.6
SFFXProc.dll	: 2.0.0.6
SFFXSAP0.dll	: 2.0.0.6
slcshp32.dll	: 1.0.3.0
slgeq32.dll	: 1.0.1.0
slh36032.dll	: 1.0.2.0
slInit32.dll	: 1.1.3.0
slmaxv32.dll	: 1.0.4.0
sltshd32.dll	: 1.1.1.0
sluapo32.dll	: 1.3.4.0
SRSHp360.dll	: 1.1.0.0
SRSTSHD.dll	: 1.1.4.0
SRSTSXT.dll	: 3.2.0.0
SRSWOW.dll	: 1.1.3.0
WavesLib.dll	: 5.9.7.0
Vista driver for x64	
RTKVHD64.sys	: 6.0.1.5845
AERTSr64.exe	: 1.0.64.9
APOPCH.exe	: 1.0.0.0
RAVCpl64.exe	: 1.0.0.345
RtkAudioService64.exe	: 1.0.0.19
RtlUpd64.exe	: 2.7.1.3
SkyTel.exe	: 2.0.2.2
vncutil64.exe	: 1.0.0.23
GWfilt64.sys	: 6.10.0.3
RTSnMg64.cpl	: 1.0.0.15
AERTAC64.dll	: 2.0.64.8
AERTAR64.dll	: 1.0.64.8
FMAP064.dll	: 0.0.14.1
MaxxAudioAP020.dll	: 2.2.2.0
MBAP032.dll	: 1.0.0.630
MBAP064.dll	: 1.0.0.630
MBPPcn64.dll	: 1.0.0.80
MBppld64.dll	: 1.0.0.630
MBWrp64.dll	: 1.0.0.80
RCoInst64.dll	: 1.0.5.5
RP3DAA64.dll	: 6.0.6001.18
RP3DHT64.dll	: 6.0.6001.18
RtCOMB4.dll	: 2.0.0.113
RTCOMDLL.dll	: 2.0.0.113
RtkApi64.dll	: 1.0.0.10
RtkAP064.dll	: 11.0.6000.98
RtkCfg.dll	: 1.0.0.1
RtkCfg64.dll	: 1.0.0.1
RtlCPAPI.dll	: 1.0.2.4
RtlCPAPI64.dll	: 1.0.2.4
RtPgEx64.dll	: 6.0.6000.78
SFComm64.dll	: 2.0.0.6
SFDAP064.dll	: 2.0.0.6
SFHAP064.dll	: 2.0.0.6
SFProc64.dll	: 2.0.0.6
SFSAP064.dll	: 2.0.0.6
slcshp64.dll	: 1.0.3.0
slgeq64.dll	: 1.0.1.0
slh36064.dll	: 1.0.2.0
slInit64.dll	: 1.1.3.0
slmaxv64.dll	: 1.0.4.0
sltshd64.dll	: 1.1.1.0
sluapo64.dll	: 1.3.4.0
SRSHp64.dll	: 1.1.0.0
SRSTSH64.dll	: 1.1.4.0
SRSTSx64.dll	: 3.2.0.0
SRSWOW64.dll	: 1.1.3.0

HDM Driver : -----

Readme.txt

Vista x86:  
 RtHDM.V.sys : 6.0.1.5832  
 RtkUpd.exe : 2.7.1.3  
 RH3DAA32.dll : 6.0.6001.18  
 RH3DHT32.dll : 6.0.6001.18  
 RHCoInst.dll : 1.0.4.9  
 RHDMEExt.dll : 6.0.6000.75  
 RtkHDM.dll : 11.0.6000.95

Vista x64:  
 RtHDM.VX.sys : 6.0.1.5832  
 RtkUpd64.exe : 2.7.1.3  
 RH3DAA64.dll : 6.0.6001.18  
 RH3DHT64.dll : 6.0.6001.18  
 RHCoInst64.dll : 1.0.4.4  
 RHDME64.dll : 6.0.6000.75  
 RtkHDM64.dll : 11.0.6000.95

XP/2K x86:  
 RtkHDM.sys : 5.10.0.5832  
 RtkUpd.exe : 2.7.1.3  
 RHCoInstXP.dll : 1.0.5.1

XP/2K x64:  
 RtkHDMX.sys : 5.10.0.5832  
 RtkUpd64.exe : 2.7.1.3  
 RHCoInst64XP.dll : 1.0.5.1

Driver Setup Program : 2.75

Windows 2000/XP Operate on :  
 Microsoft High Definition Audio Driver Package - KB888111  
 Package file version (kb888111.exe) : 6.1.22.0  
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.22

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
3. HDMI Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 - x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
  - 1.) Driver :
    1. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :  
 RTKHDA64.sys : 5.10.0.5832  
 RTKHDAUD.sys : 5.10.0.5832  
 McCal.exe : 1.1.2.1  
 RTHDCPL.exe : 2.2.7.8  
 RtkAudioService64.exe : 1.0.0.19  
 RtkAudioService.exe : 1.0.0.19  
 RTLCPL.exe : 1.0.1.66  
 RtlUpd64.exe : 2.7.1.3  
 RtlUpd.exe : 2.7.1.3  
 SkyTel.exe : 2.0.2.0  
 SoundMan.exe : 1.0.0.32  
 vncutil64.exe : 1.0.0.23  
 vncutil.exe : 1.0.0.23  
 Alcmtr.exe : 1.6.0.4  
 AlcWzrd.exe : 1.1.0.37  
 Mbnfilt.sys : 5.10.0.4112  
 Mbnft64.sys : 5.10.0.4115



	Readme.txt	
AMBfil.t.sys	:	5.10.0.4240
AMBFt64.sys	:	5.10.0.4240
RTSndMgr.cpl	:	1.0.1.2
ALSndMgr.cpl	:	1.0.0.11
RCoInst64XP.dll	:	1.0.5.0
RTCOMDLL.dll	:	1.0.0.101
RtkCoInstXP.dll	:	1.0.5.0
RtlCPAPI.dll	:	1.0.2.2
Vista driver : -----		
Vista driver for x86		
RTKVHDA.sys	:	6.0.1.5832
AERTSrv.exe	:	1.0.32.8
APOPCH.exe	:	1.0.0.0
RtHDVCpl.exe	:	1.0.0.334
RtkAudioService.exe	:	1.0.0.19
RtlUpd.exe	:	2.7.1.3
SkyTel.exe	:	2.0.2.2
vncutil.exe	:	1.0.0.23
RTSndMgr.cpl	:	1.0.0.15
AERTACap.dll	:	2.0.32.7
AERTARen.dll	:	1.0.32.7
FMAPO.dll	:	0.0.14.1
MaxxAudioAPO.dll	:	1.2.2.0
MaxxAudioAPO20.dll	:	2.2.2.0
MaxxAudioEQ.dll	:	5.9.7.0
MBAP032.dll	:	1.0.0.630
MBPPCn32.dll	:	1.0.0.80
MBpld32.dll	:	1.0.0.630
MBWrp32.dll	:	1.0.0.80
RP3DAA32.dll	:	6.0.6001.18
RP3DHT32.dll	:	6.0.6001.18
RTCOMDLL.dll	:	2.0.0.111
RtkAPO.dll	:	11.0.6000.95
RtkApoApi.dll	:	1.0.0.10
RtkCfg.dll	:	1.0.0.1
RtkCoInst.dll	:	1.0.5.2
RtkPgExt.dll	:	6.0.6000.75
RtlCPAPI.dll	:	1.0.2.2
SFCPStr.dll	:	1.1.0.3
SFFXComm.dll	:	1.1.0.3
SFFXCP.dll	:	1.1.0.3
SFFXLAP0.dll	:	1.1.0.3
SFFXProc.dll	:	1.1.0.3
SFFXSAP0.dll	:	1.1.0.3
slcshp32.dll	:	1.0.3.0
slgeq32.dll	:	1.0.1.0
slh36032.dll	:	1.0.2.0
slInit32.dll	:	1.1.3.0
slmaxv32.dll	:	1.0.4.0
sltshd32.dll	:	1.1.1.0
sluapo32.dll	:	1.3.4.0
SRSHP360.dll	:	1.1.0.0
SRSTSHD.dll	:	1.1.4.0
SRSTSXT.dll	:	3.2.0.0
SRSWOW.dll	:	1.1.3.0
WavesLib.dll	:	5.9.7.0
Vista driver for x64		
RTKVHD64.sys	:	6.0.1.5832
AERTSr64.exe	:	1.0.64.8
APOPCH.exe	:	1.0.0.0
RAVCpl64.exe	:	1.0.0.334
RtkAudioService64.exe	:	1.0.0.19
RtlUpd64.exe	:	2.7.1.3
SkyTel.exe	:	2.0.2.2
vncutil64.exe	:	1.0.0.23
GWfil64.sys	:	6.10.0.3
RTSnMgr64.cpl	:	1.0.0.15
AERTAC64.dll	:	2.0.64.7
AERTAR64.dll	:	1.0.64.7

Readme.txt

```

FMAP064.dll : 0.0.14.1
MaxxAudioAP020.dll : 2.2.2.0
MBAP032.dll : 1.0.0.630
MBAP064.dll : 1.0.0.630
MBPPCn64.dll : 1.0.0.80
MBpld64.dll : 1.0.0.630
MBWrp64.dll : 1.0.0.80
RCoInst64.dll : 1.0.5.2
RP3DAA64.dll : 6.0.6001.18
RP3DHT64.dll : 6.0.6001.18
RtCOM64.dll : 2.0.0.111
RTCOMDLL.dll : 2.0.0.111
RtkApi64.dll : 1.0.0.10
RtkAPO64.dll : 11.0.6000.95
RtkCfg.dll : 1.0.0.1
RtkCfg64.dll : 1.0.0.1
RtLCPAPI.dll : 1.0.2.2
RtLCPAPI64.dll : 1.0.2.2
RtPgEx64.dll : 6.0.6000.75
SFComm64.dll : 1.1.0.3
SFCP64.dll : 1.1.0.3
SFCPStr.dll : 1.1.0.3
SFLAP064.dll : 1.1.0.3
SFProc64.dll : 1.1.0.3
SFSAP064.dll : 1.1.0.3
slcshp64.dll : 1.0.3.0
slgeq64.dll : 1.0.1.0
slh36064.dll : 1.0.2.0
slInit64.dll : 1.1.3.0
slmaxv64.dll : 1.0.4.0
sltshd64.dll : 1.1.1.0
sluapo64.dll : 1.3.4.0
SRSHP64.dll : 1.1.0.0
SRSTSH64.dll : 1.1.4.0
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
-----
HDM Driver :
Vista x86:
RtHDMV.sys : 6.0.1.5796
RtkUpd.exe : 2.7.1.2
AHPCEE32.dll : 6.0.6001.17
RHCoInst.dll : 1.0.4.4
RHDMExt.dll : 6.0.6000.69
RtkHDM.dll : 11.0.6000.88

Vista x64:
RtHDMVX.sys : 6.0.1.5796
RtkUpd64.exe : 2.7.1.2
AHPCEE64.dll : 6.0.6001.17
RHCoInst64.dll : 1.0.4.4
RHDMEx64.dll : 6.0.6000.69
RtkHDM64.dll : 11.0.6000.88

XP/2K x86:
RtkHDM.sys : 5.10.0.5796
RtkUpd.exe : 2.7.1.2

XP/2K x64:
RtkHDMX.sys : 5.10.0.5796
RtkUpd64.exe : 2.7.1.2

Driver Setup Program : 2.75

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

```

//=====

Readme.txt

Driver Package R2.21

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 - x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
  - 1.) Driver :
    1. Customizations.
    2. Support ALC275.

Windows 2000/XP : -----

Windows 2000/XP :  
RTKHDA64.sys : 5.10.0.5821  
RTKHDAUD.sys : 5.10.0.5821  
McCal.exe : 1.1.2.1  
RTHDCPL.exe : 2.2.7.5  
RtkAudioService64.exe : 1.0.0.19  
RtkAudioService.exe : 1.0.0.19  
RTLCPPL.exe : 1.0.1.66  
RtlUpd64.exe : 2.7.1.2  
RtlUpd.exe : 2.7.1.2  
SkyTel.exe : 2.0.2.0  
SoundMan.exe : 1.0.0.32  
vncutil64.exe : 1.0.0.23  
vncutil.exe : 1.0.0.23  
Alcmtr.exe : 1.6.0.4  
AlcWzrd.exe : 1.1.0.37  
Mnft64.sys : 5.10.0.4112  
Mnft64.sys : 5.10.0.4115  
AMBFilt.sys : 5.10.0.4240  
AMBft64.sys : 5.10.0.4240  
RTSndMgr.cpl : 1.0.1.2  
ALSndMgr.cpl : 1.0.0.11  
RCoInst64XP.dll : 1.0.5.0  
RTCOMDLL.dll : 1.0.0.100  
RtkCoInstXP.dll : 1.0.5.0  
RtlCPAPI.dll : 1.0.2.2

Vista driver : -----

Vista driver for x86  
RTKVHDA.sys : 6.0.1.5821  
AERTSrv.exe : 1.0.32.8  
APOPCH.exe : 1.0.0.0  
RtHDVCpl.exe : 1.0.0.323  
RtkAudioService.exe : 1.0.0.19  
RtlUpd.exe : 2.7.1.2  
SkyTel.exe : 2.0.2.2  
vncutil.exe : 1.0.0.23  
RTSndMgr.cpl : 1.0.0.15  
AERTACap.dll : 2.0.32.7  
AERTARen.dll : 1.0.32.7  
FMAPO.dll : 0.0.14.1  
MaxxAudioAPO.dll : 1.2.2.0  
MaxxAudioAPO20.dll : 2.2.2.0  
MaxxAudioEQ.dll : 5.9.7.0  
MBAPO32.dll : 1.0.0.630  
MBPPCn32.dll : 1.0.0.80  
MBpld32.dll : 1.0.0.630  
MBWrp32.dll : 1.0.0.80  
RTCOMDLL.dll : 2.0.0.110  
RtkAPO.dll : 11.0.6000.90  
RtkApoApi.dll : 1.0.0.10  
RtkCfg.dll : 1.0.0.1  
RtkCoInst.dll : 1.0.5.0  
RtkPgExt.dll : 6.0.6000.70

	Readme.txt	
RtLCPAPI.dll	:	1.0.2.2
RTPCEE32.dll	:	6.0.6001.17
slcshp32.dll	:	1.0.3.0
slgeq32.dll	:	1.0.1.0
slh36032.dll	:	1.0.2.0
slInit32.dll	:	1.1.3.0
slmaxv32.dll	:	1.0.4.0
sltshd32.dll	:	1.1.1.0
sluapo32.dll	:	1.3.4.0
SRSHp360.dll	:	1.1.0.0
SRSTSHD.dll	:	1.1.4.0
SRSTSXT.dll	:	3.2.0.0
SRSWOW.dll	:	1.1.3.0
WavesLib.dll	:	5.9.7.0
Vista driver for x64		
RTKVHD64.sys	:	6.0.1.5821
AERTSr64.exe	:	1.0.64.8
APOPCH.exe	:	1.0.0.0
RAVCpl64.exe	:	1.0.0.323
RtkAudioService64.exe	:	1.0.0.19
RtlUpd64.exe	:	2.7.1.2
SkyTel.exe	:	2.0.2.2
vncutil64.exe	:	1.0.0.23
GWfilt64.sys	:	6.10.0.3
RTSnMg64.cpl	:	1.0.0.15
AERTAC64.dll	:	2.0.64.7
AERTAR64.dll	:	1.0.64.7
FMAP064.dll	:	0.0.14.1
MaxxAudioAPO20.dll	:	2.2.2.0
MBAP032.dll	:	1.0.0.630
MBAP064.dll	:	1.0.0.630
MBPPCn64.dll	:	1.0.0.80
Mbpld64.dll	:	1.0.0.630
MBWrp64.dll	:	1.0.0.80
RCoInst64.dll	:	1.0.5.0
RtCOMB4.dll	:	2.0.0.110
RTCOMDLL.dll	:	2.0.0.110
RtkApi64.dll	:	1.0.0.10
RtkAPO64.dll	:	11.0.6000.90
RtkCfg.dll	:	1.0.0.1
RtkCfg64.dll	:	1.0.0.1
RtLCPAPI.dll	:	1.0.2.2
RtLCPAPI64.dll	:	1.0.2.2
RTPCEE64.dll	:	6.0.6001.17
RtPgEx64.dll	:	6.0.6000.70
slcshp64.dll	:	1.0.3.0
slgeq64.dll	:	1.0.1.0
slh36064.dll	:	1.0.2.0
slInit64.dll	:	1.1.3.0
slmaxv64.dll	:	1.0.4.0
sltshd64.dll	:	1.1.1.0
sluapo64.dll	:	1.3.4.0
SRSHp64.dll	:	1.1.0.0
SRSTSH64.dll	:	1.1.4.0
SRSTSX64.dll	:	3.2.0.0
SRSWOW64.dll	:	1.1.3.0
HDMI Driver :	-----	
Vista x86:		
RtHDMV.sys	:	6.0.1.5796
RtkUpd.exe	:	2.7.1.2
AHPCEE32.dll	:	6.0.6001.17
RHCoInst.dll	:	1.0.4.4
RHDMExt.dll	:	6.0.6000.69
RtkHDM.dll	:	11.0.6000.88
Vista x64:		
RtHDMVX.sys	:	6.0.1.5796
RtkUpd64.exe	:	2.7.1.2
AHPCEE64.dll	:	6.0.6001.17

Readme.txt

RHCoInst64.dll : 1.0.4.4  
 RHDME64.dll : 6.0.6000.69  
 RtkHDM64.dll : 11.0.6000.88

XP/2K x86:  
 RtkHDM.sys : 5.10.0.5796  
 RtkUpd.exe : 2.7.1.2

XP/2K x64:  
 RtkHDMX.sys : 5.10.0.5796  
 RtkUpd64.exe : 2.7.1.2

Driver Setup Program : 2.74

Windows 2000/XP Operate on :  
 Microsoft High Definition Audio Driver Package - KB888111  
 Package file version (kb888111.exe) : 6.1.22.0  
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.20

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
3. HDMI Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 - x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
  - 1.) Driver :
    1. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :  
 RTKHDA64.sys : 5.10.0.5817  
 RTKHDAUD.sys : 5.10.0.5817  
 Alcmtr.exe : 1.6.0.4  
 AlcWzrd.exe : 1.1.0.37  
 MicCal.exe : 1.1.2.1  
 RTHDCPL.exe : 2.2.7.4  
 RtkAudioService64.exe : 1.0.0.19  
 RtkAudioService.exe : 1.0.0.19  
 RTLCPL.exe : 1.0.1.66  
 RtlUpd64.exe : 2.7.1.2  
 RtlUpd.exe : 2.7.1.2  
 SkyTel.exe : 2.0.2.0  
 SoundMan.exe : 1.0.0.32  
 vncutil64.exe : 1.0.0.23  
 vncutil.exe : 1.0.0.23  
 AMBFilt.sys : 5.10.0.4240  
 AMBFt64.sys : 5.10.0.4240  
 Mbnfilt.sys : 5.10.0.4112  
 Mnft64.sys : 5.10.0.4115  
 ALSndMgr.cpl : 1.0.0.11  
 RTSndMgr.cpl : 1.0.1.2  
 RCoInst64XP.dll : 1.0.5.0  
 RTCOMDLL.dll : 1.0.0.99  
 RtkCoInstXP.dll : 1.0.5.0  
 RtlCPAPI.dll : 1.0.2.2

Vista driver : -----

Vista driver for x86  
 RTKVHDA.sys : 6.0.1.5817  
 AERTSrv.exe : 1.0.32.8  
 APOPCH.exe : 1.0.0.0  
 RthDVCpl.exe : 1.0.0.319  
 RtkAudioService.exe : 1.0.0.19

	Readme.txt	
RtlUpd.exe	:	2.7.1.2
SkyTel.exe	:	2.0.2.2
vncutil.exe	:	1.0.0.23
RTSndMgr.cpl	:	1.0.0.15
AERTACap.dll	:	2.0.32.5
AERTARen.dll	:	1.0.32.7
FMAP0.dll	:	0.0.14.1
MaxxAudioAP0.dll	:	1.2.2.0
MaxxAudioAP020.dll	:	2.2.2.0
MaxxAudioEQ.dll	:	5.9.7.0
MBAP032.dll	:	1.0.0.630
MBPPCn32.dll	:	1.0.0.80
Mbpld32.dll	:	1.0.0.630
MBWrp32.dll	:	1.0.0.80
RTCOMDLL.dll	:	2.0.0.109
RtkAP0.dll	:	11.0.6000.90
RtkApoApi.dll	:	1.0.0.10
RtkCfg.dll	:	1.0.0.1
RtkCoInst.dll	:	1.0.5.0
RtkPgExt.dll	:	6.0.6000.70
RtlCPAPI.dll	:	1.0.2.2
RTPCEE32.dll	:	6.0.6001.17
slcshp32.dll	:	1.0.3.0
slgeq32.dll	:	1.0.1.0
slh36032.dll	:	1.0.2.0
slInit32.dll	:	1.1.1.0
sltshd32.dll	:	1.1.0.0
sluapo32.dll	:	1.2.6.0
SRSHP360.dll	:	1.1.0.0
SRSTSHD.dll	:	1.1.4.0
SRSTSXT.dll	:	3.2.0.0
SRSWOW.dll	:	1.1.3.0
WavesLib.dll	:	5.9.7.0
Vista driver for x64		
RTKVHD64.sys	:	6.0.1.5817
AERTSr64.exe	:	1.0.64.8
APOPCH.exe	:	1.0.0.0
RAVCpl64.exe	:	1.0.0.319
RtkAudioService64.exe	:	1.0.0.19
RtlUpd64.exe	:	2.7.1.2
SkyTel.exe	:	2.0.2.2
vncutil64.exe	:	1.0.0.23
GWfilt64.sys	:	6.10.0.3
RTSnMgr64.cpl	:	1.0.0.15
AERTAC64.dll	:	2.0.64.1
AERTAR64.dll	:	1.0.64.7
FMAP064.dll	:	0.0.14.1
MaxxAudioAP020.dll	:	2.2.2.0
MBAP032.dll	:	1.0.0.630
MBAP064.dll	:	1.0.0.630
MBPPCn64.dll	:	1.0.0.80
Mbpld64.dll	:	1.0.0.630
MBWrp64.dll	:	1.0.0.80
RCoInst64.dll	:	1.0.5.0
RtCOM64.dll	:	2.0.0.109
RTCOMDLL.dll	:	2.0.0.109
RtkApi64.dll	:	1.0.0.10
RtkAP064.dll	:	11.0.6000.90
RtkCfg.dll	:	1.0.0.1
RtkCfg64.dll	:	1.0.0.1
RtlCPAPI.dll	:	1.0.2.2
RtlCPAPI64.dll	:	1.0.2.2
RTPCEE64.dll	:	6.0.6001.17
RtPgEx64.dll	:	6.0.6000.70
slcshp64.dll	:	1.0.3.0
slgeq64.dll	:	1.0.1.0
slh36064.dll	:	1.0.2.0
slInit64.dll	:	1.1.1.0
sltshd64.dll	:	1.1.0.0

```

Readme.txt
sluapo64.dll           : 1.2.6.0
SRSHp64.dll           : 1.1.0.0
SRSTSH64.dll          : 1.1.4.0
SRSTSX64.dll          : 3.2.0.0
SRSWoW64.dll          : 1.1.3.0
HDM Driver : -----
Vista x86:
RtHDM.V.sys           : 6.0.1.5796
RtkUpd.exe            : 2.7.1.2
AHPCEE32.dll          : 6.0.6001.17
RHCoInst.dll          : 1.0.4.4
RHDMExt.dll           : 6.0.6000.69
RtkHDM.dll            : 11.0.6000.88

Vista x64:
RtHDM.VX.sys          : 6.0.1.5796
RtkUpd64.exe          : 2.7.1.2
AHPCEE64.dll          : 6.0.6001.17
RHCoInst64.dll        : 1.0.4.4
RHDMEx64.dll          : 6.0.6000.69
RtkHDM64.dll          : 11.0.6000.88

XP/2K x86:
RtkHDM.sys            : 5.10.0.5796
RtkUpd.exe            : 2.7.1.2

XP/2K x64:
RtkHDM.X.sys          : 5.10.0.5796
RtkUpd64.exe          : 2.7.1.2

Driver Setup Program  : 2.74

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

```

//=====

Driver Package R2.19

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista, Windows7 x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
  - 1.) Driver :
    1. Customizations.
  - 2.) Package :
    1. Fix upgraded warning dialog for Small VGA mode .
    2. Add failed run installation by count .

```

Windows 2000/XP : -----
Windows 2000/XP :
RTKHDA64.sys          : 5.10.0.5809
RTKHDAUD.sys          : 5.10.0.5809
Alcmtr.exe            : 1.6.0.4
AlcWzrd.exe           : 1.1.0.37
McCal.exe             : 1.1.2.1
RTHDCPL.exe           : 2.2.7.1
RtkAudioService64.exe : 1.0.0.17
RtkAudioService.exe  : 1.0.0.16
RTLCPPL.exe           : 1.0.1.66
RtlUpd64.exe          : 2.7.1.2
RtlUpd.exe            : 2.7.1.2
SkyTel.exe            : 2.0.2.0
SoundMan.exe          : 1.0.0.32

```

```

Readme.txt
vncutil64.exe : 1.0.0.23
vncutil.exe : 1.0.0.23
AMBFilt.sys : 5.10.0.4240
AMBFt64.sys : 5.10.0.4240
Mnft64.sys : 5.10.0.4112
Mnft64.sys : 5.10.0.4115
ALSndMgr.cpl : 1.0.0.11
RTSndMgr.cpl : 1.0.1.0
RCoInst64XP.dll : 1.0.4.9
RTCOMDLL.dll : 1.0.0.99
RtkCoInstXP.dll : 1.0.4.9
RtlCPAPI.dll : 1.0.2.2
Vista driver : -----
Vista driver for x86
RTKVHDA.sys : 6.0.1.5809
AERTSrv.exe : 1.0.32.8
APOPCH.exe : 1.0.0.0
RtHDVCpl.exe : 1.0.0.314
RtkAudioService.exe : 1.0.0.17
RtlUpd.exe : 2.7.1.2
SkyTel.exe : 2.0.2.2
vncutil.exe : 1.0.0.23
RTSndMgr.cpl : 1.0.0.15
AERTACap.dll : 2.0.32.1
AERTARen.dll : 1.0.32.7
FMAP0.dll : 0.0.14.1
MaxxAudioAPO.dll : 1.2.2.0
MaxxAudioAPO20.dll : 2.2.2.0
MaxxAudioEQ.dll : 5.9.7.0
MBAP032.dll : 1.0.0.630
MBPPCn32.dll : 1.0.0.80
MBpld32.dll : 1.0.0.630
MBWrp32.dll : 1.0.0.80
RTCOMDLL.dll : 2.0.0.109
RtkAPO.dll : 11.0.6000.89
RtkApoApi.dll : 1.0.0.10
RtkCfg.dll : 1.0.0.1
RtkCoInst.dll : 1.0.4.9
RtkPgExt.dll : 6.0.6000.70
RtlCPAPI.dll : 1.0.2.2
RTPCEE32.dll : 6.0.6001.17
slcshp32.dll : 1.0.3.0
slgeq32.dll : 1.0.1.0
slh36032.dll : 1.0.2.0
slInit32.dll : 1.1.1.0
sltshd32.dll : 1.1.0.0
sluapo32.dll : 1.2.6.0
SRSHP360.dll : 1.1.0.0
SRSTSHD.dll : 1.1.4.0
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.1.3.0
WavesLib.dll : 5.9.7.0
Vista driver for x64
RTKVHD64.sys : 6.0.1.5809
AERTSr64.exe : 1.0.64.8
APOPCH.exe : 1.0.0.0
RAVCpl64.exe : 1.0.0.314
RtkAudioService64.exe : 1.0.0.17
RtlUpd64.exe : 2.7.1.2
SkyTel.exe : 2.0.2.2
vncutil64.exe : 1.0.0.23
GWfilt64.sys : 6.10.0.3
RTSnMg64.cpl : 1.0.0.15
AERTAC64.dll : 2.0.64.1
AERTAR64.dll : 1.0.64.7
FMAP064.dll : 0.0.14.1
MaxxAudioAPO20.dll : 2.2.2.0
MBAP032.dll : 1.0.0.630
MBAP064.dll : 1.0.0.630

```



```

Readme.txt
MBPPCn64.dll : 1.0.0.80
Mbpld64.dll : 1.0.0.630
MBWrp64.dll : 1.0.0.80
RCoInst64.dll : 1.0.4.9
RtCOM64.dll : 2.0.0.109
RTCOMDLL.dll : 2.0.0.109
RtkApi64.dll : 1.0.0.10
RtkAPO64.dll : 11.0.6000.89
RtkCfg.dll : 1.0.0.1
RtkCfg64.dll : 1.0.0.1
RtLCPAPI.dll : 1.0.2.2
RtLCPAPI64.dll : 1.0.2.2
RTPCEE64.dll : 6.0.6001.17
RtPgEx64.dll : 6.0.6000.70
slcshp64.dll : 1.0.3.0
slgeq64.dll : 1.0.1.0
slh36064.dll : 1.0.2.0
slInit64.dll : 1.1.1.0
sltshd64.dll : 1.1.0.0
sluapo64.dll : 1.2.6.0
SRSHp64.dll : 1.1.0.0
SRSTSH64.dll : 1.1.4.0
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
HDMI Driver : -----
Vista x86:
RtHDMV.sys : 6.0.1.5796
RtkUpd.exe : 2.7.1.2
AHPCEE32.dll : 6.0.6001.17
RHCoInst.dll : 1.0.4.4
RHDMExt.dll : 6.0.6000.69
RtkHDM.dll : 11.0.6000.88

Vista x64:
RtHDMVX.sys : 6.0.1.5796
RtkUpd64.exe : 2.7.1.2
AHPCEE64.dll : 6.0.6001.17
RHCoInst64.dll : 1.0.4.4
RHDMEx64.dll : 6.0.6000.69
RtkHDM64.dll : 11.0.6000.88

XP/2K x86:
RtkHDM.sys : 5.10.0.5796
RtkUpd.exe : 2.7.1.2

XP/2K x64:
RtkHDMX.sys : 5.10.0.5796
RtkUpd64.exe : 2.7.1.2

Driver Setup Program : 2.73

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

```

//=====

Driver Package R2.18

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/Wi nXP/Wi n2000/Wi n2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista, Windows7 x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
  - 1.) Driver :
    1. Customizations.

Readme.txt

2.) Package :

1. Support driver folder of Windows Server 2008 in package .
2. Disable Status Dialog when small VGA Mode enabled .
3. Fix CreativeUp folder disappear issue .

Windows 2000/XP : -----

Windows 2000/XP :

RTKHDA64.sys	: 5.10.0.5804
RTKHDAUD.sys	: 5.10.0.5804
MicCal.exe	: 1.1.2.0
RTHDCPL.exe	: 2.2.6.9
RtkAudioService64.exe	: 1.0.0.17
RtkAudioService.exe	: 1.0.0.16
RTLCPPL.exe	: 1.0.1.66
RtlUpd64.exe	: 2.7.1.2
RtlUpd.exe	: 2.7.1.2
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.32
vncutil64.exe	: 1.0.0.23
vncutil.exe	: 1.0.0.23
Alcmtr.exe	: 1.6.0.4
AlcWzrd.exe	: 1.1.0.37
Mnfiltr.sys	: 5.10.0.4112
Mnft64.sys	: 5.10.0.4115
AMBFilt.sys	: 5.10.0.4240
AMBFt64.sys	: 5.10.0.4240
RTSndMgr.cpl	: 1.0.1.0
ALSndMgr.cpl	: 1.0.0.11
RCoInst64XP.dll	: 1.0.4.8
RTCOMDLL.dll	: 1.0.0.98
RtkCoInstXP.dll	: 1.0.4.8
RtlCPAPI.dll	: 1.0.2.1

Vista driver : -----

Vista driver for x86

RTKVHDA.sys	: 6.0.1.5804
AERTSrv.exe	: 1.0.32.8
APOPCH.exe	: 1.0.0.0
RtHDVCpl.exe	: 1.0.0.311
RtkAudioService.exe	: 1.0.0.17
RtlUpd.exe	: 2.7.1.2
SkyTel.exe	: 2.0.2.2
vncutil.exe	: 1.0.0.23
RTSndMgr.cpl	: 1.0.0.15
AERTACap.dll	: 2.0.32.1
AERTARen.dll	: 1.0.32.7
FMAPO.dll	: 0.0.14.1
MaxxAudioAPO.dll	: 1.2.2.0
MaxxAudioAPO20.dll	: 2.2.2.0
MaxxAudioEQ.dll	: 5.9.7.0
MBAPO32.dll	: 1.0.0.630
MBPPCn32.dll	: 1.0.0.80
MBpld32.dll	: 1.0.0.630
MBWrp32.dll	: 1.0.0.80
RTCOMDLL.dll	: 2.0.0.108
RtkAPO.dll	: 11.0.6000.89
RtkApoApi.dll	: 1.0.0.10
RtkCfg.dll	: 1.0.0.1
RtkCoInst.dll	: 1.0.4.8
RtkPgExt.dll	: 6.0.6000.69
RtlCPAPI.dll	: 1.0.2.1
RTPCEE32.dll	: 6.0.6001.17
slcshp32.dll	: 1.0.3.0
slgeq32.dll	: 1.0.1.0
slh36032.dll	: 1.0.2.0
slinit32.dll	: 1.1.1.0
sltshd32.dll	: 1.1.0.0
sluapo32.dll	: 1.2.6.0
SRSHP360.dll	: 1.1.0.0
SRSTSHD.dll	: 1.1.4.0

	Readme.txt	
SRSTSXT.dll	:	3.2.0.0
SRSWOW.dll	:	1.1.3.0
WavesLib.dll	:	5.9.7.0
Vista driver for x64		
RTKVHD64.sys	:	6.0.1.5804
AERTSr64.exe	:	1.0.64.8
APOPCH.exe	:	1.0.0.0
RAVCpl64.exe	:	1.0.0.311
RtkAudioService64.exe	:	1.0.0.17
RtlUpd64.exe	:	2.7.1.2
SkyTel.exe	:	2.0.2.2
vncutil64.exe	:	1.0.0.23
GWfilt64.sys	:	6.10.0.3
RTSnMg64.cpl	:	1.0.0.15
AERTAC64.dll	:	2.0.64.1
AERTAR64.dll	:	1.0.64.7
FMAP064.dll	:	0.0.14.1
MaxxAudioAP020.dll	:	2.2.2.0
MBAP032.dll	:	1.0.0.630
MBAP064.dll	:	1.0.0.630
MBPPCn64.dll	:	1.0.0.80
MBpld64.dll	:	1.0.0.630
MBWrp64.dll	:	1.0.0.80
RCoInst64.dll	:	1.0.4.8
RtCOM64.dll	:	2.0.0.108
RTCOMDLL.dll	:	2.0.0.108
RtkApi64.dll	:	1.0.0.10
RtkAPO64.dll	:	11.0.6000.89
RtkCfg.dll	:	1.0.0.1
RtkCfg64.dll	:	1.0.0.1
RtlCPAPI.dll	:	1.0.2.1
RtlCPAPI64.dll	:	1.0.2.1
RTPCEE64.dll	:	6.0.6001.17
RtPgEx64.dll	:	6.0.6000.69
slcshp64.dll	:	1.0.3.0
slgeq64.dll	:	1.0.1.0
slh36064.dll	:	1.0.2.0
slInit64.dll	:	1.1.1.0
sltshd64.dll	:	1.1.0.0
sluapo64.dll	:	1.2.6.0
SRSHP64.dll	:	1.1.0.0
SRSTSH64.dll	:	1.1.4.0
SRSTSX64.dll	:	3.2.0.0
SRSWOW64.dll	:	1.1.3.0
HDMI Driver :	-----	
Vista x86:		
RtHDMV.sys	:	6.0.1.5796
RtkUpd.exe	:	2.7.1.2
AHPCEE32.dll	:	6.0.6001.17
RHCoInst.dll	:	1.0.4.4
RHDMExt.dll	:	6.0.6000.69
RtkHDM.dll	:	11.0.6000.88
Vista x64:		
RtHDMVX.sys	:	6.0.1.5796
RtkUpd64.exe	:	2.7.1.2
AHPCEE64.dll	:	6.0.6001.17
RHCoInst64.dll	:	1.0.4.4
RHDMEx64.dll	:	6.0.6000.69
RtkHDM64.dll	:	11.0.6000.88
XP/2K x86:		
RtkHDM.sys	:	5.10.0.5796
RtkUpd.exe	:	2.7.1.2
XP/2K x64:		
RtkHDMX.sys	:	5.10.0.5796
RtkUpd64.exe	:	2.7.1.2

Readme.txt

Driver Setup Program : 2.72

Windows 2000/XP Operate on :  
Microsoft High Definition Audio Driver Package - KB888111  
Package file version (kb888111.exe) : 6.1.22.0  
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.17

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
3. HDMI Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista, Windows7 x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
  - 1.) Driver :
    1. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :  
RTKHDA64.sys : 5.10.0.5794  
RTKHAUD.sys : 5.10.0.5794  
McCal.exe : 1.1.2.0  
RTHDCPL.exe : 2.2.6.5  
RtkAudioService64.exe : 1.0.0.17  
RtkAudioService.exe : 1.0.0.16  
RTLCPPL.exe : 1.0.1.66  
RtlUpd64.exe : 2.7.1.2  
RtlUpd.exe : 2.7.1.2  
SkyTel.exe : 2.0.2.0  
SoundMan.exe : 1.0.0.32  
vncutil64.exe : 1.0.0.23  
vncutil.exe : 1.0.0.23  
Alcmtr.exe : 1.6.0.3  
AlcWzrd.exe : 1.1.0.37  
Mnfilt.sys : 5.10.0.4112  
Mnft64.sys : 5.10.0.4115  
AMBfilt.sys : 5.10.0.4240  
AMBft64.sys : 5.10.0.4240  
RTSndMgr.cpl : 1.0.1.0  
ALSndMgr.cpl : 1.0.0.11  
RCoInst64XP.dll : 1.0.4.8  
RTCOMDLL.dll : 1.0.0.97  
RtkCoInstXP.dll : 1.0.4.8  
RtlCPAPI.dll : 1.0.2.1

Vista driver : -----

Vista driver for x86  
RTKVHDA.sys : 6.0.1.5794  
AERTSrv.exe : 1.0.32.8  
APOPCH.exe : 1.0.0.0  
RtHDVCpl.exe : 1.0.0.306  
RtkAudioService.exe : 1.0.0.17  
RtlUpd.exe : 2.7.1.2  
SkyTel.exe : 2.0.2.2  
vncutil.exe : 1.0.0.23  
RTSndMgr.cpl : 1.0.0.15  
AERTACap.dll : 2.0.32.1  
AERTARen.dll : 1.0.32.7  
FMAPO.dll : 0.0.14.1  
MaxxAudioAPO.dll : 1.2.2.0  
MaxxAudioAPO20.dll : 2.2.2.0  
MaxxAudioEQ.dll : 5.9.7.0  
MBAPO32.dll : 1.0.0.630  
MBPPCn32.dll : 1.0.0.80  
MBpld32.dll : 1.0.0.630  
MBWrp32.dll : 1.0.0.80

	Readme.txt	
RTCOMDLL.dll	:	2.0.0.106
RtkAPO.dll	:	11.0.6000.88
RtkApoApi.dll	:	1.0.0.10
RtkCfg.dll	:	1.0.0.1
RtkColnst.dll	:	1.0.4.8
RtkPgExt.dll	:	6.0.6000.69
RtlCPAPI.dll	:	1.0.2.1
RTPCEE32.dll	:	6.0.6001.17
slcshp32.dll	:	1.0.3.0
slgeq32.dll	:	1.0.1.0
slh36032.dll	:	1.0.2.0
slInit32.dll	:	1.1.1.0
sltshd32.dll	:	1.1.0.0
sluapo32.dll	:	1.2.6.0
SRSHP360.dll	:	1.1.0.0
SRSTSHD.dll	:	1.1.4.0
SRSTSXT.dll	:	3.2.0.0
SRSWOW.dll	:	1.1.3.0
WavesLib.dll	:	5.9.7.0
Vista driver for x64		
RTKVHD64.sys	:	6.0.1.5794
AERTSr64.exe	:	1.0.64.8
APOPCH.exe	:	1.0.0.0
RAVCpl64.exe	:	1.0.0.306
RtkAudioService64.exe	:	1.0.0.17
RtlUpd64.exe	:	2.7.1.2
SkyTel.exe	:	2.0.2.2
vncutil64.exe	:	1.0.0.23
GWfilt64.sys	:	6.10.0.3
RTSnMg64.cpl	:	1.0.0.15
AERTAC64.dll	:	2.0.64.1
AERTAR64.dll	:	1.0.64.7
FMAP064.dll	:	0.0.14.1
MaxxAudioAP020.dll	:	2.2.2.0
MBAP032.dll	:	1.0.0.630
MBAP064.dll	:	1.0.0.630
MBPPCn64.dll	:	1.0.0.80
MBpld64.dll	:	1.0.0.630
MBWrp64.dll	:	1.0.0.80
RCoInst64.dll	:	1.0.4.8
RtCOM64.dll	:	2.0.0.106
RTCOMDLL.dll	:	2.0.0.106
RtkApi64.dll	:	1.0.0.10
RtkAPO64.dll	:	11.0.6000.88
RtkCfg.dll	:	1.0.0.1
RtkCfg64.dll	:	1.0.0.1
RtlCPAPI.dll	:	1.0.2.1
RtlCPAPI64.dll	:	1.0.2.1
RTPCEE64.dll	:	6.0.6001.17
RtPgEx64.dll	:	6.0.6000.69
slcshp64.dll	:	1.0.3.0
slgeq64.dll	:	1.0.1.0
slh36064.dll	:	1.0.2.0
slInit64.dll	:	1.1.1.0
sltshd64.dll	:	1.1.0.0
sluapo64.dll	:	1.2.6.0
SRSHP64.dll	:	1.1.0.0
SRSTSH64.dll	:	1.1.4.0
SRSTSX64.dll	:	3.2.0.0
SRSWOW64.dll	:	1.1.3.0
HDMI Driver :	-----	
Vista x86:		
RtHDMV.sys	:	6.0.1.5766
RtkUpd.exe	:	2.7.1.1
RHCoInst.dll	:	1.0.3.2
RHDMExt.dll	:	6.0.6000.66
RtkHDM.dll	:	11.0.6000.85

Vista x64:

Readme.txt

RtHDMVX.sys : 6.0.1.5766  
 RtkUpd64.exe : 2.7.1.1  
 RHCoInst64.dll : 1.0.3.2  
 RHDME64.dll : 6.0.6000.66  
 RtkHDM64.dll : 11.0.6000.85

XP/2K x86:  
 RtkHDM.sys : 5.10.0.5766  
 RtkUpd.exe : 2.7.1.1

XP/2K x64:  
 RtHDMX.sys : 5.10.0.5766  
 RtkUpd64.exe : 2.7.1.1

Driver Setup Program : 2.70

Windows 2000/XP Operate on :  
 Microsoft High Definition Audio Driver Package - KB888111  
 Package file version (kb888111.exe) : 6.1.22.0  
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.16

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista, Windows7 x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
  - 1.) Driver :
    1. Customizations.
    2. Update directsound acceleration engine for XP driver.

Windows 2000/XP : -----

Windows 2000/XP :  
 RTKHDA64.sys : 5.10.0.5791  
 RTKHDAUD.sys : 5.10.0.5791  
 McCal.exe : 1.1.2.0  
 RTHDCPL.exe : 2.2.6.3  
 RtkAudioService64.exe : 1.0.0.17  
 RtkAudioService.exe : 1.0.0.16  
 RTLCPL.exe : 1.0.1.66  
 RtlUpd64.exe : 2.7.1.2  
 RtlUpd.exe : 2.7.1.2  
 SkyTel.exe : 2.0.2.0  
 SoundMan.exe : 1.0.0.32  
 vncutil64.exe : 1.0.0.23  
 vncutil.exe : 1.0.0.23  
 Alcmtr.exe : 1.6.0.3  
 AlcWzrd.exe : 1.1.0.37  
 Mbnfilt.sys : 5.10.0.4112  
 Mbnft64.sys : 5.10.0.4115  
 AMBFilt.sys : 5.10.0.4240  
 AMBft64.sys : 5.10.0.4240  
 RTSndMgr.cpl : 1.0.1.0  
 ALSndMgr.cpl : 1.0.0.11  
 RCoInst64XP.dll : 1.0.4.8  
 RTCOMDLL.dll : 1.0.0.97  
 RtkCoInstXP.dll : 1.0.4.8  
 RtlCPAPI.dll : 1.0.2.1

Vista driver : -----

Vista driver for x86  
 RTKVHDA.sys : 6.0.1.5791  
 AERTSrv.exe : 1.0.32.8  
 APOPCH.exe : 1.0.0.0  
 RtHDVCpl.exe : 1.0.0.304

	Readme.txt	
RtkAudioService.exe		: 1.0.0.17
RtlUpd.exe		: 2.7.1.2
SkyTel.exe		: 2.0.2.2
vncutil.exe		: 1.0.0.23
RTSndMgr.cpl		: 1.0.0.15
AERTACap.dll		: 2.0.32.1
AERTARen.dll		: 1.0.32.7
FMAP0.dll		: 0.0.14.1
MaxxAudioAPO.dll		: 1.2.2.0
MaxxAudioAPO20.dll		: 2.2.2.0
MaxxAudioEQ.dll		: 5.9.7.0
MBAP032.dll		: 1.0.0.630
MBPPCn32.dll		: 1.0.0.80
MBpld32.dll		: 1.0.0.630
MBWrp32.dll		: 1.0.0.80
RTCOMDLL.dll		: 2.0.0.106
RtkAPO.dll		: 11.0.6000.88
RtkApoApi.dll		: 1.0.0.10
RtkCfg.dll		: 1.0.0.1
RtkCoInst.dll		: 1.0.4.8
RtkPgExt.dll		: 6.0.6000.69
RtlCPAPI.dll		: 1.0.2.1
RTPCEE32.dll		: 6.0.6001.17
slcshp32.dll		: 1.0.3.0
slgeq32.dll		: 1.0.1.0
slh36032.dll		: 1.0.2.0
slinit32.dll		: 1.1.1.0
sltshd32.dll		: 1.1.0.0
sluapo32.dll		: 1.2.6.0
SRSHP360.dll		: 1.1.0.0
SRSTSHD.dll		: 1.1.4.0
SRSTSXT.dll		: 3.2.0.0
SRSWOW.dll		: 1.1.3.0
WavesLib.dll		: 5.9.7.0
Vista driver for x64		
RTKVHD64.sys		: 6.0.1.5791
AERTSr64.exe		: 1.0.64.8
APOPCH.exe		: 1.0.0.0
RAVCpl64.exe		: 1.0.0.304
RtkAudioService64.exe		: 1.0.0.17
RtlUpd64.exe		: 2.7.1.2
SkyTel.exe		: 2.0.2.2
vncutil64.exe		: 1.0.0.23
GWfilt64.sys		: 6.10.0.3
RTSnMg64.cpl		: 1.0.0.15
AERTAC64.dll		: 2.0.64.1
AERTAR64.dll		: 1.0.64.7
FMAP064.dll		: 0.0.14.1
MaxxAudioAPO20.dll		: 2.2.2.0
MBAP032.dll		: 1.0.0.630
MBAP064.dll		: 1.0.0.630
MBPPCn64.dll		: 1.0.0.80
MBpld64.dll		: 1.0.0.630
MBWrp64.dll		: 1.0.0.80
RCoInst64.dll		: 1.0.4.8
RtCOMB4.dll		: 2.0.0.106
RTCOMDLL.dll		: 2.0.0.106
RtkApi64.dll		: 1.0.0.10
RtkAPO64.dll		: 11.0.6000.88
RtkCfg.dll		: 1.0.0.1
RtkCfg64.dll		: 1.0.0.1
RtlCPAPI.dll		: 1.0.2.1
RtlCPAPI64.dll		: 1.0.2.1
RTPCEE64.dll		: 6.0.6001.17
RtPgEx64.dll		: 6.0.6000.69
slcshp64.dll		: 1.0.3.0
slgeq64.dll		: 1.0.1.0
slh36064.dll		: 1.0.2.0
slinit64.dll		: 1.1.1.0

Readme.txt

```

sltshd64.dll : 1.1.0.0
sluapo64.dll : 1.2.6.0
SRSHp64.dll : 1.1.0.0
SRSTSH64.dll : 1.1.4.0
SRSTSx64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
HDMI Driver : -----
Vista x86:
RtHDMV.sys : 6.0.1.5766
RtkUpd.exe : 2.7.1.1
RHCoInst.dll : 1.0.3.2
RHDMExt.dll : 6.0.6000.66
RtkHDM.dll : 11.0.6000.85

Vista x64:
RtHDMVX.sys : 6.0.1.5766
RtkUpd64.exe : 2.7.1.1
RHCoInst64.dll : 1.0.3.2
RHDMEx64.dll : 6.0.6000.66
RtkHDM64.dll : 11.0.6000.85

XP/2K x86:
RtkHDM.sys : 5.10.0.5766
RtkUpd.exe : 2.7.1.1

XP/2K x64:
RtHDMX.sys : 5.10.0.5766
RtkUpd64.exe : 2.7.1.1

Driver Setup Program : 2.70

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

```

//=====

Driver Package R2.15

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
  - 1.) Driver :
    1. Customizations.
    2. Change Creative components for the certain customers.
  - 2.) Package :
    1. Change Japanese language on finish Dialog of installation .
    2. Fix DCC uninstalled issue. Both MSI and GUID uninstllation procedure supported .
    3. Fix uninstll problem in Windows 7 . The DIFxAPI DLL file supported in Windows 7 .

Windows 2000/XP : -----

```

Windows 2000/XP :
RTKHDA64.sys : 5.10.0.5783
RTKHDAUD.sys : 5.10.0.5783
McCal.exe : 1.1.2.0
RTHDCPL.exe : 2.2.6.2
RtkAudioService64.exe : 1.0.0.17
RtkAudioService.exe : 1.0.0.16
RTLCPPL.exe : 1.0.1.66
RtlUpd64.exe : 2.7.1.2
RtlUpd.exe : 2.7.1.2
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.32
vncutil64.exe : 1.0.0.23

```



Readme.txt

```

vncutil.exe : 1.0.0.23
Alcmtr.exe : 1.6.0.3
AlcWzrd.exe : 1.1.0.37
Mbnfilt.sys : 5.10.0.4112
Mbnft64.sys : 5.10.0.4115
AMBFilt.sys : 5.10.0.4240
AMBft64.sys : 5.10.0.4240
RTSndMgr.cpl : 1.0.1.0
ALSndMgr.cpl : 1.0.0.11
RCoInst64XP.dll : 1.0.4.8
RTCOMDLL.dll : 1.0.0.97
RtkCoInstXP.dll : 1.0.4.8
RtlCPAPI.dll : 1.0.1.9
Vista driver : -----
Vista driver for x86
RTKVHDA.sys : 6.0.1.5783
AERTSrv.exe : 1.0.32.8
APOPCH.exe : 1.0.0.0
RtHDVCpl.exe : 1.0.0.300
RtkAudioService.exe : 1.0.0.17
RtlUpd.exe : 2.7.1.2
SkyTel.exe : 2.0.2.2
vncutil.exe : 1.0.0.23
RTSndMgr.cpl : 1.0.0.13
AERTACap.dll : 2.0.32.1
AERTARen.dll : 1.0.32.7
FMAP0.dll : 0.0.12.1
MaxxAudioAP0.dll : 1.2.2.0
MaxxAudioAP020.dll : 2.2.2.0
MaxxAudioEQ.dll : 5.9.7.0
MBAP032.dll : 1.0.0.630
MBPPCn32.dll : 1.0.0.80
MBppld32.dll : 1.0.0.630
MBWrp32.dll : 1.0.0.80
RTCOMDLL.dll : 2.0.0.106
RtkAP0.dll : 11.0.6000.87
RtkApoApi.dll : 1.0.0.10
RtkCfg.dll : 1.0.0.1
RtkCoInst.dll : 1.0.4.8
RtkPgExt.dll : 6.0.6000.67
RtlCPAPI.dll : 1.0.2.1
RTPCEE32.dll : 6.0.6001.14
slcshp32.dll : 1.0.3.0
slgeq32.dll : 1.0.1.0
slh36032.dll : 1.0.2.0
slInit32.dll : 1.1.1.0
sltshd32.dll : 1.1.0.0
sluapo32.dll : 1.2.6.0
SRSHP360.dll : 1.1.0.0
SRSTSHD.dll : 1.1.4.0
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.1.3.0
WavesLib.dll : 5.9.7.0
Vista driver for x64
RTKVHD64.sys : 6.0.1.5783
AERTSr64.exe : 1.0.64.8
APOPCH.exe : 1.0.0.0
RAVCpl64.exe : 1.0.0.300
RtkAudioService64.exe : 1.0.0.17
RtlUpd64.exe : 2.7.1.2
SkyTel.exe : 2.0.2.2
vncutil64.exe : 1.0.0.23
GWfilt64.sys : 6.10.0.3
RTSnMg64.cpl : 1.0.0.13
AERTAC64.dll : 2.0.64.1
AERTAR64.dll : 1.0.64.7
FMAP064.dll : 0.0.12.1
MaxxAudioAP020.dll : 2.2.2.0
MBAP032.dll : 1.0.0.630

```

Readme.txt

MBAP064.dll : 1.0.0.630  
 MBPPCn64.dll : 1.0.0.80  
 MBppld64.dll : 1.0.0.630  
 MBWrp64.dll : 1.0.0.80  
 RCoInst64.dll : 1.0.4.8  
 RtCOMB4.dll : 2.0.0.106  
 RTCOMDLL.dll : 2.0.0.106  
 RtkApi64.dll : 1.0.0.10  
 RtkAPO64.dll : 11.0.6000.87  
 RtkCfg.dll : 1.0.0.1  
 RtkCfg64.dll : 1.0.0.1  
 RtLCPAPI.dll : 1.0.2.1  
 RtLCPAPI64.dll : 1.0.2.1  
 RTPCEE64.dll : 6.0.6001.14  
 RtPgEx64.dll : 6.0.6000.67  
 slcshp64.dll : 1.0.3.0  
 slgeq64.dll : 1.0.1.0  
 slh36064.dll : 1.0.2.0  
 slInit64.dll : 1.1.1.0  
 sltshd64.dll : 1.1.0.0  
 sluapo64.dll : 1.2.6.0  
 SRSHP64.dll : 1.1.0.0  
 SRSTSH64.dll : 1.1.4.0  
 SRSTX64.dll : 3.2.0.0  
 SRSWOW64.dll : 1.1.3.0

HDMI Driver : -----

Vista x86:  
 RtHDMV.sys : 6.0.1.5766  
 RtkUpd.exe : 2.7.1.1  
 RHCoInst.dll : 1.0.3.2  
 RHDMEExt.dll : 6.0.6000.66  
 RtkHDM.dll : 11.0.6000.85

Vista x64:  
 RtHDMVX.sys : 6.0.1.5766  
 RtkUpd64.exe : 2.7.1.1  
 RHCoInst64.dll : 1.0.3.2  
 RHDME64.dll : 6.0.6000.66  
 RtkHDM64.dll : 11.0.6000.85

XP/2K x86:  
 RtkHDM.sys : 5.10.0.5766  
 RtkUpd.exe : 2.7.1.1

XP/2K x64:  
 RtHDMX.sys : 5.10.0.5766  
 RtkUpd64.exe : 2.7.1.1

Driver Setup Program : 2.70

Windows 2000/XP Operate on :  
 Microsoft High Definition Audio Driver Package - KB888111  
 Package file version (kb888111.exe) : 6.1.22.0  
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.14

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix

- 1.) Driver :
  1. Customizations.
  2. Change EAPD control method for the certain codecs.

Readme.txt

```

Windows 2000/XP : -----
Windows 2000/XP :
RTKHDA64.sys : 5.10.0.5772
RTKHDAUD.sys : 5.10.0.5772
Alcmtr.exe : 1.6.0.3
AlcWzrd.exe : 1.1.0.37
Mccal.exe : 1.1.2.0
RTHDCPL.exe : 2.2.5.9
RtkAudioService64.exe : 1.0.0.17
RtkAudioService.exe : 1.0.0.16
RTLCPPL.exe : 1.0.1.66
RtlUpd64.exe : 2.7.1.1
RtlUpd.exe : 2.7.1.1
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.32
vncutil64.exe : 1.0.0.23
vncutil.exe : 1.0.0.23
AMBfilt64.sys : 5.10.0.4240
AMBfilt.sys : 5.10.0.4240
Mbnfilt64.sys : 5.10.0.4115
Mbnfilt.sys : 5.10.0.4112
ALSndMgr.cpl : 1.0.0.11
RTSndMgr.cpl : 1.0.1.0
RCoInst64XP.dll : 1.0.4.4
RTCOMDLL.dll : 1.0.0.97
RtkCoInstXP.dll : 1.0.4.4
RtlCPAPI.dll : 1.0.1.9
Vista driver : -----
Vista driver for x86
RTKVHDA.sys : 6.0.1.5772
AERTSrv.exe : 1.0.32.8
RtHDVCpl.exe : 1.0.0.291
RtkAudioService.exe : 1.0.0.17
RtlUpd.exe : 2.7.1.1
SkyTel.exe : 2.0.2.2
vncutil.exe : 1.0.0.23
RTSndMgr.cpl : 1.0.0.13
AERTACap.dll : 2.0.32.1
AERTARen.dll : 1.0.32.7
CTAP032.dll : 1.0.0.530
ctpld.dll : 1.0.0.530
DaisyWrp.dll : 1.0.0.70
FMAP0.dll : 0.0.12.1
MaxxAudioAPO.dll : 1.2.2.0
MaxxAudioAPO20.dll : 2.2.2.0
MaxxAudioEQ.dll : 5.9.7.0
ppchain.dll : 1.0.0.70
RTCOMDLL.dll : 2.0.0.105
RtkAPO.dll : 11.0.6000.85
RtkApoApi.dll : 1.0.0.9
RtkCfg.dll : 1.0.0.1
RtkCoInst.dll : 1.0.4.4
RtkPgExt.dll : 6.0.6000.66
RtlCPAPI.dll : 1.0.2.1
slcshp32.dll : 1.0.3.0
slgeq32.dll : 1.0.1.0
slh36032.dll : 1.0.2.0
slinit32.dll : 1.1.1.0
sltshd32.dll : 1.1.0.0
sluapo32.dll : 1.2.6.0
SRSHP360.dll : 1.1.0.0
SRSTSHD.dll : 1.1.4.0
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.1.3.0
WavesLib.dll : 5.9.7.0
Vista driver for x64
RTKVHD64.sys : 6.0.1.5772
AERTSr64.exe : 1.0.64.8

```

```

Readme.txt
RAVCpl64.exe : 1.0.0.291
RtkAudioService64.exe : 1.0.0.17
RtlUpd64.exe : 2.7.1.1
SkyTel.exe : 2.0.2.2
vncutil64.exe : 1.0.0.23
GWfilt64.sys : 6.10.0.3
RTSnMg64.cpl : 1.0.0.13
AERTAC64.dll : 2.0.64.1
AERTAR64.dll : 1.0.64.7
CTAP032.dll : 1.0.0.530
CTAP064.dll : 1.0.0.530
ctpld.dll : 1.0.0.530
DaisyWrp.dll : 1.0.0.70
FMAP064.dll : 0.0.12.1
MaxxAudioAP020.dll : 2.2.2.0
ppchain.dll : 1.0.0.70
RCoInst64.dll : 1.0.4.4
RtCOMB4.dll : 2.0.0.105
RtCOMDLL.dll : 2.0.0.105
RtkApi64.dll : 1.0.0.9
RtkAP064.dll : 11.0.6000.85
RtkCfg.dll : 1.0.0.1
RtkCfg64.dll : 1.0.0.1
RtlCPAPI.dll : 1.0.2.1
RtlCPAPI64.dll : 1.0.2.1
RtPgEx64.dll : 6.0.6000.66
slcshp64.dll : 1.0.3.0
slgeq64.dll : 1.0.1.0
slh36064.dll : 1.0.2.0
slInit64.dll : 1.1.1.0
sltshd64.dll : 1.1.0.0
sluapo64.dll : 1.2.6.0
SRSHp64.dll : 1.1.0.0
SRSTSH64.dll : 1.1.4.0
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0

```

```

HDMI Driver : -----
Vista x86:
RtHDMV.sys : 6.0.1.5766
RtkUpd.exe : 2.7.1.1
RHCoInst.dll : 1.0.3.2
RHDMEExt.dll : 6.0.6000.66
RtkHDM.dll : 11.0.6000.85

```

```

Vista x64:
RtHDMVX.sys : 6.0.1.5766
RtkUpd64.exe : 2.7.1.1
RHCoInst64.dll : 1.0.3.2
RHDMEx64.dll : 6.0.6000.66
RtkHDM64.dll : 11.0.6000.85

```

```

XP/2K x86:
RtkHDM.sys : 5.10.0.5766
RtkUpd.exe : 2.7.1.1

```

```

XP/2K x64:
RtHDMX.sys : 5.10.0.5766
RtkUpd64.exe : 2.7.1.1

```

```

Driver Setup Program : 2.69

```

```

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

```

```
//=====
```

```
Driver Package R2.13
```

```
Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/Wi nXP/Wi n2000/Wi n2003 .
```

Readme.txt

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC272, ALC273, ALC887
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
  - 1.) Driver :
    1. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :  
RTKHDA64.sys : 5.10.0.5767  
RTKHDAUD.sys : 5.10.0.5767  
McCal.exe : 1.1.2.0  
RTHDCPL.exe : 2.2.5.8  
RtkAudioService64.exe : 1.0.0.17  
RtkAudioService.exe : 1.0.0.16  
RTLCP.exe : 1.0.1.66  
RtlUpd64.exe : 2.7.1.1  
RtlUpd.exe : 2.7.1.1  
SkyTel.exe : 2.0.2.0  
SoundMan.exe : 1.0.0.32  
vncutil64.exe : 1.0.0.23  
vncutil.exe : 1.0.0.23  
Alcmtr.exe : 1.6.0.3  
AlcWzrd.exe : 1.1.0.37  
AMBFilt64.sys : 5.10.0.4240  
AMBFilt.sys : 5.10.0.4240  
Mnfil64.sys : 5.10.0.4115  
Mnfil.sys : 5.10.0.4112  
RTSndMgr.cpl : 1.0.1.0  
ALSndMgr.cpl : 1.0.0.11  
RCoInst64XP.dll : 1.0.4.3  
RTCOMDLL.dll : 1.0.0.97  
RtkCoInstXP.dll : 1.0.4.3  
RtlCPAPI.dll : 1.0.1.9

Vista driver : -----

Vista driver for x86  
RTKVHDA.sys : 6.0.1.5767  
AERTSrv.exe : 1.0.32.8  
RtHDVCpl.exe : 1.0.0.288  
RtkAudioService.exe : 1.0.0.17  
RtlUpd.exe : 2.7.1.1  
SkyTel.exe : 2.0.2.2  
vncutil.exe : 1.0.0.23  
RTSndMgr.cpl : 1.0.0.13  
AERTACap.dll : 2.0.32.1  
AERTARen.dll : 1.0.32.7  
CTAP032.dll : 1.0.0.530  
ctpld.dll : 1.0.0.530  
DaisyWrp.dll : 1.0.0.70  
FMAP0.dll : 0.0.12.1  
MaxxAudioAPO.dll : 1.2.2.0  
MaxxAudioAPO20.dll : 2.2.2.0  
MaxxAudioEQ.dll : 5.9.7.0  
ppchain.dll : 1.0.0.70  
RTCOMDLL.dll : 2.0.0.105  
RtkAPO.dll : 11.0.6000.85  
RtkApoApi.dll : 1.0.0.9  
RtkCfg.dll : 1.0.0.1  
RtkCoInst.dll : 1.0.4.3  
RtkPgExt.dll : 6.0.6000.66  
RtlCPAPI.dll : 1.0.2.1  
slcshp32.dll : 1.0.3.0  
slgeq32.dll : 1.0.1.0  
slh36032.dll : 1.0.2.0  
slinit32.dll : 1.1.1.0

	Readme.txt	
sltshd32.dll	:	1.1.0.0
sluapo32.dll	:	1.2.6.0
SRSHP360.dll	:	1.1.0.0
SRSTSHD.dll	:	1.1.4.0
SRSTSXT.dll	:	3.2.0.0
SRSWOW.dll	:	1.1.3.0
WavesLib.dll	:	5.9.7.0
Vista driver for x64		
RTKVHD64.sys	:	6.0.1.5767
AERTSr64.exe	:	1.0.64.8
RAVCpl64.exe	:	1.0.0.288
RtkAudioService64.exe	:	1.0.0.17
RtlUpd64.exe	:	2.7.1.1
SkyTel.exe	:	2.0.2.2
vncutil64.exe	:	1.0.0.23
GWfilt64.sys	:	6.10.0.3
RTSnMg64.cpl	:	1.0.0.13
AERTAC64.dll	:	2.0.64.1
AERTAR64.dll	:	1.0.64.7
CTAP032.dll	:	1.0.0.530
CTAP064.dll	:	1.0.0.530
ctpld.dll	:	1.0.0.530
DaisyWrp.dll	:	1.0.0.70
FMAP064.dll	:	0.0.12.1
MaxxAudioAPO20.dll	:	2.2.2.0
ppchain.dll	:	1.0.0.70
RCoInst64.dll	:	1.0.4.3
RtCOMB4.dll	:	2.0.0.105
RTCOMDLL.dll	:	2.0.0.105
RtkApi64.dll	:	1.0.0.9
RtkAPO64.dll	:	11.0.6000.85
RtkCfg.dll	:	1.0.0.1
RtkCfg64.dll	:	1.0.0.1
RtlCPAPI.dll	:	1.0.2.1
RtlCPAPI64.dll	:	1.0.2.1
RtPgEx64.dll	:	6.0.6000.66
slcshp64.dll	:	1.0.3.0
slgeq64.dll	:	1.0.1.0
slh36064.dll	:	1.0.2.0
slInit64.dll	:	1.1.1.0
sltshd64.dll	:	1.1.0.0
sluapo64.dll	:	1.2.6.0
SRSHP64.dll	:	1.1.0.0
SRSTSH64.dll	:	1.1.4.0
SRSTSX64.dll	:	3.2.0.0
SRSWOW64.dll	:	1.1.3.0
<b>HDMI Driver :</b>	-----	
Vista x86:		
RtHDMV.sys	:	6.0.1.5766
RtkUpd.exe	:	2.7.1.1
RHCoInst.dll	:	1.0.3.2
RHDMExt.dll	:	6.0.6000.66
RtkHDM.dll	:	11.0.6000.85
Vista x64:		
RtHDMVX.sys	:	6.0.1.5766
RtkUpd64.exe	:	2.7.1.1
RHCoInst64.dll	:	1.0.3.2
RHDMEx64.dll	:	6.0.6000.66
RtkHDM64.dll	:	11.0.6000.85
XP/2K x86:		
RtkHDM.sys	:	5.10.0.5766
RtkUpd.exe	:	2.7.1.1
XP/2K x64:		
RtHDMX.sys	:	5.10.0.5766
RtkUpd64.exe	:	2.7.1.1

Readme.txt

Driver Setup Program : 2.69

Windows 2000/XP Operate on :  
Microsoft High Definition Audio Driver Package - KB888111  
Package file version (kb888111.exe) : 6.1.22.0  
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.12

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
3. HDMI Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
  - 1.) Driver :
    1. Customizations.
    2. Support encryption feature for ALC670.

Windows 2000/XP : -----

Windows 2000/XP :

RTKHDA64.sys : 5.10.0.5764  
RTKHDAUD.sys : 5.10.0.5764  
Alcmtr.exe : 1.6.0.3  
AlcWzrd.exe : 1.1.0.37  
Mccal.exe : 1.1.2.0  
RTHDCPL.exe : 2.2.5.6  
RtkAudioService64.exe : 1.0.0.17  
RtkAudioService.exe : 1.0.0.16  
RTLCPPL.exe : 1.0.1.66  
RtlUpd64.exe : 2.7.1.1  
RtlUpd.exe : 2.7.1.1  
SkyTel.exe : 2.0.2.0  
SoundMan.exe : 1.0.0.32  
vncutil64.exe : 1.0.0.23  
vncutil.exe : 1.0.0.23  
AMBfilt64.sys : 5.10.0.4240  
AMBfilt.sys : 5.10.0.4240  
Mnfil64.sys : 5.10.0.4115  
Mnfil.sys : 5.10.0.4112  
ALSndMgr.cpl : 1.0.0.11  
RTSndMgr.cpl : 1.0.1.0  
RCoInst64XP.dll : 1.0.4.3  
RTCOMDLL.dll : 1.0.0.97  
RtkCoInstXP.dll : 1.0.4.3  
RtlCPAPI.dll : 1.0.1.9

Vista driver : -----

Vista driver for x86

RTKVHDA.sys : 6.0.1.5764  
AERTSrv.exe : 1.0.32.8  
RtHDVCpl.exe : 1.0.0.286  
RtkAudioService.exe : 1.0.0.17  
RtlUpd.exe : 2.7.1.1  
SkyTel.exe : 2.0.2.2  
vncutil.exe : 1.0.0.23  
RTSndMgr.cpl : 1.0.0.13  
AERTACap.dll : 2.0.32.1  
AERTARen.dll : 1.0.32.7  
CTAP032.dll : 1.0.0.530  
ctpld.dll : 1.0.0.530  
DaisyWrp.dll : 1.0.0.70  
FMAP0.dll : 0.0.12.1  
MaxxAudioAPO.dll : 1.2.2.0  
MaxxAudioAPO20.dll : 2.2.2.0  
MaxxAudioEQ.dll : 5.9.7.0

Readme.txt

```

ppchain.dll : 1.0.0.70
RTCOMDLL.dll : 2.0.0.105
RtkAPO.dll : 11.0.6000.85
RtkApoApi.dll : 1.0.0.9
RtkCfg.dll : 1.0.0.1
RtkCoInst.dll : 1.0.4.3
RtkPgExt.dll : 6.0.6000.66
RtLCPAPI.dll : 1.0.2.1
slcshp32.dll : 1.0.3.0
slgeq32.dll : 1.0.1.0
slh36032.dll : 1.0.2.0
slInit32.dll : 1.1.1.0
sltshd32.dll : 1.1.0.0
sluapo32.dll : 1.2.6.0
SRSHP360.dll : 1.1.0.0
SRSTSHD.dll : 1.1.4.0
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.1.3.0
WavesLib.dll : 5.9.7.0
Vista driver for x64
RTKVHD64.sys : 6.0.1.5764
AERTSr64.exe : 1.0.64.8
RAVCpl64.exe : 1.0.0.286
RtkAudioService64.exe : 1.0.0.17
RtlUpd64.exe : 2.7.1.1
SkyTel.exe : 2.0.2.2
vncutil64.exe : 1.0.0.23
GWfilt64.sys : 6.10.0.3
RTSnMg64.cpl : 1.0.0.13
AERTAC64.dll : 2.0.64.1
AERTAR64.dll : 1.0.64.7
CTAP032.dll : 1.0.0.530
CTAP064.dll : 1.0.0.530
ctpld.dll : 1.0.0.530
DaisyWrp.dll : 1.0.0.70
FMAP064.dll : 0.0.12.1
MaxxAudioAPO20.dll : 2.2.2.0
ppchain.dll : 1.0.0.70
RCoInst64.dll : 1.0.4.3
RtCOMB4.dll : 2.0.0.105
RTCOMDLL.dll : 2.0.0.105
RtkApi64.dll : 1.0.0.9
RtkAPO64.dll : 11.0.6000.85
RtkCfg.dll : 1.0.0.1
RtkCfg64.dll : 1.0.0.1
RtLCPAPI.dll : 1.0.2.1
RtLCPAPI64.dll : 1.0.2.1
RtPgEx64.dll : 6.0.6000.66
slcshp64.dll : 1.0.3.0
slgeq64.dll : 1.0.1.0
slh36064.dll : 1.0.2.0
slInit64.dll : 1.1.1.0
sltshd64.dll : 1.1.0.0
sluapo64.dll : 1.2.6.0
SRSHP64.dll : 1.1.0.0
SRSTSH64.dll : 1.1.4.0
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
HDMI Driver : -----
Vista x86:
RtHDMV.sys : 6.0.1.5735
RtkUpd.exe : 2.7.1.1
RHCoInst.dll : 1.0.3.2
RHDMExt.dll : 6.0.6000.64
RtkHDM.dll : 11.0.6000.80

Vista x64:
RtHDMVX.sys : 6.0.1.5735

```



Readme.txt

RtkUpd64.exe : 2.7.1.1  
 RHCoInst64.dll : 1.0.3.2  
 RHDME64.dll : 6.0.6000.64  
 RtkHDM64.dll : 11.0.6000.80

XP/2K x86:  
 RtHDM.sys : 5.10.0.5735  
 RtkUpd.exe : 2.7.1.1  
 XP/2K x64:  
 RtHDMX.sys : 5.10.0.5735  
 RtkUpd64.exe : 2.7.1.1

Driver Setup Program : 2.69

Windows 2000/XP Operate on :  
 Microsoft High Definition Audio Driver Package - KB888111  
 Package file version (kb888111.exe) : 6.1.22.0  
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.11

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix

- 1.) Driver :
  1. Customizations.
  2. Add DisplayVersion registry key in INF files.

Windows 2000/XP : -----

Windows 2000/XP :  
 RTKHDA64.sys : 5.10.0.5755  
 RTKHDAUD.sys : 5.10.0.5755  
 Alcmtr.exe : 1.6.0.3  
 AlcWzrd.exe : 1.1.0.37  
 MicCal.exe : 1.1.2.0  
 RTHDCPL.exe : 2.2.5.5  
 RtkAudioService64.exe : 1.0.0.17  
 RtkAudioService.exe : 1.0.0.16  
 RTLCPL.exe : 1.0.1.66  
 RtlUpd64.exe : 2.7.1.1  
 RtlUpd.exe : 2.7.1.1  
 SkyTel.exe : 2.0.2.0  
 SoundMan.exe : 1.0.0.32  
 vncutil64.exe : 1.0.0.22  
 vncutil.exe : 1.0.0.22  
 AMBFilt64.sys : 5.10.0.4240  
 AMBFilt.sys : 5.10.0.4240  
 Mbnfilt64.sys : 5.10.0.4115  
 Mbnfilt.sys : 5.10.0.4112  
 ALSndMgr.cpl : 1.0.0.11  
 RTSndMgr.cpl : 1.0.1.0  
 RCoInst64XP.dll : 1.0.4.1  
 RTCOMDLL.dll : 1.0.0.97  
 RtkCoInstXP.dll : 1.0.4.1  
 RtlCPAPI.dll : 1.0.1.9

Vista driver : -----

Vista driver for x86  
 RTKVHDA.sys : 6.0.1.5755  
 AERTSrv.exe : 1.0.32.8  
 RtHDVCpl.exe : 1.0.0.281  
 RtkAudioService.exe : 1.0.0.17  
 RtlUpd.exe : 2.7.1.1

	Readme.txt	
SkyTel.exe	:	2.0.2.2
vncutil.exe	:	1.0.0.23
RTSndMgr.cpl	:	1.0.0.13
AERTACap.dll	:	2.0.32.1
AERTARen.dll	:	1.0.32.7
CTAP032.dll	:	1.0.0.530
ctpld.dll	:	1.0.0.530
DaisyWrp.dll	:	1.0.0.70
FMAP0.dll	:	0.0.12.1
MaxxAudioAPO.dll	:	1.2.2.0
MaxxAudioAPO20.dll	:	2.2.2.0
MaxxAudioEQ.dll	:	5.9.7.0
ppchain.dll	:	1.0.0.70
RTCOMDLL.dll	:	2.0.0.103
RtkAPO.dll	:	11.0.6000.81
RtkApoApi.dll	:	1.0.0.9
RtkCfg.dll	:	1.0.0.1
RtkCoInst.dll	:	1.0.4.1
RtkPgExt.dll	:	6.0.6000.65
RtLCPAPI.dll	:	1.0.2.1
slcshp32.dll	:	1.0.3.0
slgeq32.dll	:	1.0.1.0
slh36032.dll	:	1.0.2.0
slInit32.dll	:	1.1.1.0
sltshd32.dll	:	1.1.0.0
sluapo32.dll	:	1.2.6.0
SRSHP360.dll	:	1.1.0.0
SRSTSHD.dll	:	1.1.4.0
SRSTSXT.dll	:	3.2.0.0
SRSWOW.dll	:	1.1.3.0
WavesLib.dll	:	5.9.7.0
Vista driver for x64		
RTKVHD64.sys	:	6.0.1.5755
AERTSr64.exe	:	1.0.64.8
RAVCpl64.exe	:	1.0.0.281
RtkAudioService64.exe	:	1.0.0.17
RtUpd64.exe	:	2.7.1.1
SkyTel.exe	:	2.0.2.2
vncutil64.exe	:	1.0.0.23
GWfilt64.sys	:	6.10.0.3
RTSnMgr64.cpl	:	1.0.0.13
AERTAC64.dll	:	2.0.64.1
AERTAR64.dll	:	1.0.64.7
CTAP032.dll	:	1.0.0.530
CTAP064.dll	:	1.0.0.530
ctpld.dll	:	1.0.0.530
DaisyWrp.dll	:	1.0.0.70
FMAP064.dll	:	0.0.12.1
MaxxAudioAPO20.dll	:	2.2.2.0
ppchain.dll	:	1.0.0.70
RCoInst64.dll	:	1.0.4.1
RtCOMB4.dll	:	2.0.0.103
RTCOMDLL.dll	:	2.0.0.103
RtkApi64.dll	:	1.0.0.9
RtkAPO64.dll	:	11.0.6000.81
RtkCfg.dll	:	1.0.0.1
RtkCfg64.dll	:	1.0.0.1
RtLCPAPI.dll	:	1.0.2.1
RtLCPAPI64.dll	:	1.0.2.1
RtPgEx64.dll	:	6.0.6000.65
slcshp64.dll	:	1.0.3.0
slgeq64.dll	:	1.0.1.0
slh36064.dll	:	1.0.2.0
slInit64.dll	:	1.1.1.0
sltshd64.dll	:	1.1.0.0
sluapo64.dll	:	1.2.6.0
SRSHP64.dll	:	1.1.0.0
SRSTSH64.dll	:	1.1.4.0
SRSTSX64.dll	:	3.2.0.0

Readme.txt

SRSWOW64.dll : 1.1.3.0

HDM Driver : -----

Vista x86:

RtHDM.V.sys : 6.0.1.5735

RtkUpd.exe : 2.7.1.1

RHCoInst.dll : 1.0.3.2

RHDMExt.dll : 6.0.6000.64

RtkHDM.dll : 11.0.6000.80

Vista x64:

RtHDM.VX.sys : 6.0.1.5735

RtkUpd64.exe : 2.7.1.1

RHCoInst64.dll : 1.0.3.2

RHDMEx64.dll : 6.0.6000.64

RtkHDM64.dll : 11.0.6000.80

XP/2K x86:

RtHDM.sys : 5.10.0.5735

RtkUpd.exe : 2.7.1.1

XP/2K x64:

RtHDM.X.sys : 5.10.0.5735

RtkUpd64.exe : 2.7.1.1

Driver Setup Program : 2.69

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.10

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887

3. HDM Device WHQL Support: ATI HDM Devices

4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

2. Support ALC665.

Windows 2000/XP : -----

Windows 2000/XP :

RTKHDA64.sys : 5.10.0.5745

RTKHDAUD.sys : 5.10.0.5745

McCal.exe : 1.1.2.0

RTHDCPL.exe : 2.2.5.2

RtkAudioService64.exe : 1.0.0.17

RtkAudioService.exe : 1.0.0.16

RTLCPPL.exe : 1.0.1.66

RtlUpd64.exe : 2.7.1.1

RtlUpd.exe : 2.7.1.1

SkyTel.exe : 2.0.2.0

SoundMan.exe : 1.0.0.32

vncutil64.exe : 1.0.0.22

vncutil.exe : 1.0.0.22

Alcmtr.exe : 1.6.0.3

AlcWzrd.exe : 1.1.0.37

AMBFilt64.sys : 5.10.0.4240

AMBFilt.sys : 5.10.0.4240

Mnfil64.sys : 5.10.0.4115

Mnfil.sys : 5.10.0.4112

Readme.txt

```

RTSndMgr. cpl           : 1.0.1.0
ALSndMgr. cpl           : 1.0.0.11
RCoInst64XP. dll       : 1.0.4.1
RTCOMDLL. dll          : 1.0.0.97
RtkCoInstXP. dll       : 1.0.4.1
RtICPAPI. dll          : 1.0.1.9
Vista driver : -----
Vista driver for x86
RTKVHDA. sys           : 6.0.1.5745
AERTSrv. exe           : 1.0.32.8
RtHDVCpl. exe          : 1.0.0.273
RtkAudioService. exe  : 1.0.0.17
RtlUpd. exe            : 2.7.1.1
SkyTel. exe            : 2.0.2.2
vncutil. exe           : 1.0.0.22
RTSndMgr. cpl           : 1.0.0.13
AERTACap. dll          : 2.0.32.1
AERTARen. dll          : 1.0.32.7
CTAP032. dll           : 1.0.0.530
ctpld. dll             : 1.0.0.530
DaisyWrp. dll          : 1.0.0.70
FMAP0. dll             : 0.0.12.1
MaxxAudioAP0. dll     : 1.2.2.0
MaxxAudioAP020. dll   : 2.2.2.0
MaxxAudioEQ. dll      : 5.9.7.0
ppchain. dll           : 1.0.0.70
RCoInst64. dll         : 1.0.4.0
RTCOMDLL. dll          : 2.0.0.103
RtkAP0. dll            : 11.0.6000.81
RtkApoApi. dll         : 1.0.0.9
RtkCfg. dll            : 1.0.0.1
RtkCoInst. dll         : 1.0.4.1
RtkPgExt. dll          : 6.0.6000.65
RtICPAPI. dll          : 1.0.2.1
slcshp32. dll          : 1.0.3.0
slgeq32. dll           : 1.0.1.0
slh36032. dll          : 1.0.2.0
slInit32. dll          : 1.1.1.0
sltshd32. dll          : 1.1.0.0
sluapo32. dll          : 1.2.6.0
SRSHP360. dll          : 1.1.0.0
SRSTSHD. dll           : 1.1.4.0
SRSTSXT. dll           : 3.2.0.0
SRSWOW. dll            : 1.1.3.0
WavesLib. dll          : 5.9.7.0
Vista driver for x64
RTKVHD64. sys          : 6.0.1.5745
AERTSr64. exe          : 1.0.64.8
RAVCpl64. exe          : 1.0.0.273
RtkAudioService64. exe : 1.0.0.17
RtlUpd64. exe          : 2.7.1.1
SkyTel. exe            : 2.0.2.2
vncutil64. exe         : 1.0.0.22
GWfilt64. sys          : 6.10.0.3
RTSnMg64. cpl          : 1.0.0.13
AERTAC64. dll          : 2.0.64.1
AERTAR64. dll          : 1.0.64.7
CTAP032. dll           : 1.0.0.530
CTAP064. dll           : 1.0.0.530
ctpld. dll             : 1.0.0.530
DaisyWrp. dll          : 1.0.0.70
FMAP064. dll           : 0.0.12.1
MaxxAudioAP020. dll   : 2.2.2.0
ppchain. dll           : 1.0.0.70
RCoInst64. dll         : 1.0.4.1
RtCOMB4. dll           : 2.0.0.103
RTCOMDLL. dll          : 2.0.0.103
RtkApi64. dll          : 1.0.0.9
RtkAP064. dll          : 11.0.6000.81

```

Readme.txt

```

RtkCfg.dll : 1.0.0.1
RtkCfg64.dll : 1.0.0.1
RtkCoInst.dll : 1.0.4.0
RtLCPAPI.dll : 1.0.2.1
RtLCPAPI64.dll : 1.0.2.1
RtPgEx64.dll : 6.0.6000.65
slcshp64.dll : 1.0.3.0
slgeq64.dll : 1.0.1.0
slh36064.dll : 1.0.2.0
slInit64.dll : 1.1.1.0
sltshd64.dll : 1.1.0.0
sluapo64.dll : 1.2.6.0
SRSHp64.dll : 1.1.0.0
SRSTSH64.dll : 1.1.4.0
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
HDM Driver : -----
Vista x86:
RtHDMV.sys : 6.0.1.5735
RtkUpd.exe : 2.7.1.1
RHCoInst.dll : 1.0.3.2
RHDMExt.dll : 6.0.6000.64
RtkHDM.dll : 11.0.6000.80

Vista x64:
RtHDMVX.sys : 6.0.1.5735
RtkUpd64.exe : 2.7.1.1
RHCoInst64.dll : 1.0.3.2
RHDMEx64.dll : 6.0.6000.64
RtkHDM64.dll : 11.0.6000.80

XP/2K x86:
RtHDM.sys : 5.10.0.5735
RtkUpd.exe : 2.7.1.1
XP/2K x64:
RtHDMX.sys : 5.10.0.5735
RtkUpd64.exe : 2.7.1.1

Driver Setup Program : 2.69

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

```

//=====

Driver Package R2.09

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/Wi nXP/Wi n2000/Wi n2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
  - 1.) Driver :
    1. Customizations.

```

Windows 2000/XP : -----
Windows 2000/XP :
RTKHDA64.sys : 5.10.0.5735
RTKHDAUD.sys : 5.10.0.5735
Alcmtr.exe : 1.6.0.3
AlcWzrd.exe : 1.1.0.37
McCal.exe : 1.1.2.0

```

```

Readme.txt
RTHDCPL.exe : 2.2.5.1
RtkAudioService.exe : 1.0.0.16
RtkAudioService64.exe : 1.0.0.17
RTLCPPL.exe : 1.0.1.66
RtlUpd.exe : 2.7.1.1
RtlUpd64.exe : 2.7.1.1
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.32
vncutil.exe : 1.0.0.22
vncutil64.exe : 1.0.0.22
AMBFilt.sys : 5.10.0.4240
AMBFilt64.sys : 5.10.0.4240
Mnfilt.sys : 5.10.0.4112
Mnfilt64.sys : 5.10.0.4115
ALSndMgr.cpl : 1.0.0.11
RTSndMgr.cpl : 1.0.1.0
RCoInst64XP.dll : 1.0.3.9
RTCOMDLL.dll : 1.0.0.97
RtkCoInstXP.dll : 1.0.3.9
RtlCPAPI.dll : 1.0.1.9
Vista driver : -----
Vista driver for x86
RTKVHDA.sys : 6.0.1.5735
AERTSrv.exe : 1.0.32.8
RtHDVCpl.exe : 1.0.0.264
RtkAudioService.exe : 1.0.0.17
RtlUpd.exe : 2.7.1.1
SkyTel.exe : 2.0.2.1
vncutil.exe : 1.0.0.22
RTSndMgr.cpl : 1.0.0.13
AERTACap.dll : 2.0.32.1
AERTARen.dll : 1.0.32.7
CTAP032.dll : 1.0.0.530
ctpld.dll : 1.0.0.530
DaisyWrp.dll : 1.0.0.70
FMAP0.dll : 0.0.12.1
MaxxAudioAPO.dll : 1.2.2.0
MaxxAudioAPO20.dll : 2.2.2.0
MaxxAudioEQ.dll : 5.9.7.0
ppchain.dll : 1.0.0.70
RTCOMDLL.dll : 2.0.0.100
RtkAPO.dll : 11.0.6000.80
RtkApoApi.dll : 1.0.0.8
RtkCoInst.dll : 1.0.3.9
RtkPgExt.dll : 6.0.6000.64
RtlCPAPI.dll : 1.0.1.9
slcshp32.dll : 1.0.3.0
slgeq32.dll : 1.0.1.0
slh36032.dll : 1.0.2.0
slinit32.dll : 1.1.1.0
sltshd32.dll : 1.1.0.0
sluapo32.dll : 1.2.6.0
SRSHP360.dll : 1.1.0.0
SRSTSHD.dll : 1.1.4.0
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.1.3.0
WavesLib.dll : 5.9.7.0
Vista driver for x64
RTKVHD64.sys : 6.0.1.5735
AERTSr64.exe : 1.0.64.8
RAVCpl64.exe : 1.0.0.264
RtkAudioService64.exe : 1.0.0.17
RtlUpd64.exe : 2.7.1.1
SkyTel.exe : 2.0.2.1
vncutil64.exe : 1.0.0.22
GWfilt64.sys : 6.10.0.3
RTSnMgr64.cpl : 1.0.0.13
AERTAC64.dll : 2.0.64.1
AERTAR64.dll : 1.0.64.7

```

Readme.txt

```

CTAP032.dll : 1.0.0.530
CTAP064.dll : 1.0.0.530
ctpld.dll : 1.0.0.530
DaisyWrp.dll : 1.0.0.70
FMAP064.dll : 0.0.12.1
MaxxAudioAP020.dll : 2.2.2.0
ppchain.dll : 1.0.0.70
RCoInst64.dll : 1.0.3.9
RtCOM64.dll : 2.0.0.100
RTCOMDLL.dll : 2.0.0.100
RtkApi64.dll : 1.0.0.8
RtkAP064.dll : 11.0.6000.80
RtLCPAPI.dll : 1.0.1.9
RtPgEx64.dll : 6.0.6000.64
slcshp64.dll : 1.0.3.0
slgeq64.dll : 1.0.1.0
slh36064.dll : 1.0.2.0
slInit64.dll : 1.1.1.0
sltshd64.dll : 1.1.0.0
sluapo64.dll : 1.2.6.0
SRSHP64.dll : 1.1.0.0
SRSTSH64.dll : 1.1.4.0
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
HDMI Driver : -----
Vista x86:
RtHDMV.sys : 6.0.1.5735
RtkUpd.exe : 2.7.1.1
RHCoInst.dll : 1.0.3.2
RHDMExt.dll : 6.0.6000.64
RtkHDM.dll : 11.0.6000.80

Vista x64:
RtHDMVX.sys : 6.0.1.5735
RtkUpd64.exe : 2.7.1.1
RHCoInst64.dll : 1.0.3.2
RHDMEx64.dll : 6.0.6000.64
RtkHDM64.dll : 11.0.6000.80

XP/2K x86:
RtHDM.sys : 5.10.0.5735
RtkUpd.exe : 2.7.1.1
XP/2K x64:
RtHDMX.sys : 5.10.0.5735
RtkUpd64.exe : 2.7.1.1

Driver Setup Program : 2.67

```

Windows 2000/XP Operate on :  
Microsoft High Definition Audio Driver Package - KB888111  
Package file version (kb888111.exe) : 6.1.22.0  
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.08

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/Wi nXP/Wi n2000/Wi n2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
  - 1.) Driver :
    1. Customizations.
    2. Support Andrea microphone effect mixer type GUI.
  - 2.) Package:

Readme.txt

1. Change setup program install location to meet the requirements of OEM Ready Certification Tool

1.1.0.1101

```

Windows 2000/XP : -----
Windows 2000/XP :
RTKHDA64.sys           : 5.10.0.5730
RTKHDAUD.sys          : 5.10.0.5730
McCal.exe             : 1.1.2.0
RTHDCPL.exe          : 2.2.4.9
RtkAudioService64.exe : 1.0.0.17
RtkAudioService.exe  : 1.0.0.16
RTLCPPL.exe          : 1.0.1.66
RtlUpd64.exe         : 2.7.1.1
RtlUpd.exe           : 2.7.1.1
SkyTel.exe           : 2.0.2.0
SoundMan.exe         : 1.0.0.32
vncutil64.exe        : 1.0.0.22
vncutil.exe          : 1.0.0.22
Alcmtr.exe           : 1.6.0.3
AlcWzrd.exe          : 1.1.0.37
Mnfiltr64.sys        : 5.10.0.4115
Mnfiltr.sys          : 5.10.0.4112
AMBfiltr64.sys       : 5.10.0.4240
AMBfiltr.sys         : 5.10.0.4240
RTSndMgr.cpl         : 1.0.1.0
ALSndMgr.cpl         : 1.0.0.11
RCoInst64XP.dll      : 1.0.3.8
RTCOMDLL.dll         : 1.0.0.97
RtkCoInstXP.dll      : 1.0.3.8
RtlCPAPI.dll         : 1.0.1.9
Vista driver : -----
Vista driver for x86
RTKVHDA.sys           : 6.0.1.5730
AERTSrv.exe           : 1.0.32.8
RtHDVCpl.exe          : 1.0.0.257
RtkAudioService.exe  : 1.0.0.17
RtlUpd.exe           : 2.7.1.1
SkyTel.exe           : 2.0.2.1
vncutil.exe          : 1.0.0.22
RTSndMgr.cpl         : 1.0.0.10
AERTACap.dll         : 2.0.32.1
AERTARen.dll         : 1.0.32.7
CTAP032.dll          : 1.0.0.530
ctpld.dll            : 1.0.0.530
DaisyWrp.dll         : 1.0.0.70
FMAP0.dll            : 0.0.12.1
MaxxAudioAPO.dll    : 1.2.2.0
MaxxAudioAPO20.dll  : 2.0.13.0
MaxxAudioEQ.dll     : 5.9.7.0
ppchain.dll          : 1.0.0.70
RTCOMDLL.dll         : 2.0.0.100
RtkAPO.dll           : 11.0.6000.79
RtkApoApi.dll        : 1.0.0.8
RtkCoInst.dll        : 1.0.3.8
RtkPgExt.dll         : 6.0.6000.64
RtlCPAPI.dll         : 1.0.1.9
slcshp32.dll         : 1.0.3.0
slgeq32.dll          : 1.0.1.0
slh36032.dll         : 1.0.2.0
slinit32.dll         : 1.1.1.0
sltshd32.dll         : 1.1.0.0
sluapo32.dll         : 1.2.6.0
SRSHP360.dll        : 1.1.0.0
SRSTSHD.dll         : 1.1.4.0
SRSTSXT.dll         : 3.2.0.0
SRSWOW.dll          : 1.1.3.0
WavesLib.dll         : 5.9.7.0

```



Readme.txt

Vista driver for x64  
 RTKVHD64.sys : 6.0.1.5730  
 AERTSr64.exe : 1.0.64.8  
 RAVCpl64.exe : 1.0.0.257  
 RtkAudioService64.exe : 1.0.0.17  
 RtlUpd64.exe : 2.7.1.1  
 SkyTel.exe : 2.0.2.1  
 vncutil64.exe : 1.0.0.22  
 GWFilt64.sys : 6.10.0.3  
 RTSnMg64.cpl : 1.0.0.10  
 AERTAC64.dll : 2.0.64.1  
 AERTAR64.dll : 1.0.64.7  
 CTAP032.dll : 1.0.0.530  
 CTAP064.dll : 1.0.0.530  
 ctppld.dll : 1.0.0.530  
 DaisyWrp.dll : 1.0.0.70  
 FMAP064.dll : 0.0.12.1  
 MaxxAudioAP020.dll : 2.0.12.0  
 ppchain.dll : 1.0.0.70  
 RCoInst64.dll : 1.0.3.8  
 RtCOM64.dll : 2.0.0.100  
 RTCOMDLL.dll : 2.0.0.100  
 RtkApi64.dll : 1.0.0.8  
 RtkAPO64.dll : 11.0.6000.79  
 RtlCPAPI.dll : 1.0.1.9  
 RtlPgEx64.dll : 6.0.6000.64  
 slcshp64.dll : 1.0.3.0  
 slgeq64.dll : 1.0.1.0  
 slh36064.dll : 1.0.2.0  
 slInit64.dll : 1.1.1.0  
 sltshd64.dll : 1.1.0.0  
 sluapo64.dll : 1.2.6.0  
 SRSHp64.dll : 1.1.0.0  
 SRSTSH64.dll : 1.1.4.0  
 SRSTSX64.dll : 3.2.0.0  
 SRSWOW64.dll : 1.1.3.0

HDMI Driver : -----  
 Vista x86:  
 RtHDMV.sys : 6.0.1.5692  
 RtkUpd.exe : 2.7.1.0  
 RHCoInst.dll : 1.0.3.2  
 RHDMEExt.dll : 6.0.6000.54  
 RtkHDM.dll : 11.0.6000.72

Vista x64:  
 RtHDMVX.sys : 6.0.1.5692  
 RtkUpd64.exe : 2.7.1.0  
 RHCoInst64.dll : 1.0.3.2  
 RHDMEx64.dll : 6.0.6000.54  
 RtkHDM64.dll : 11.0.6000.72

XP/2K x86:  
 RtHDM.sys : 5.10.0.5692  
 RtkUpd.exe : 2.7.1.0

XP/2K x64:  
 RtHDMX.sys : 5.10.0.5692  
 RtkUpd64.exe : 2.7.1.0

Driver Setup Program : 2.67

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111  
 Package file version (kb888111.exe) : 6.1.22.0  
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.07

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/Wi nXP/Wi n2000/Wi n2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887

Readme.txt

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
  - 1.) Driver :
    1. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :

RTKHDA64.sys	: 5.10.0.5717
RTKHDAUD.sys	: 5.10.0.5717
Alcmtr.exe	: 1.6.0.3
AlcWzrd.exe	: 1.1.0.37
McCal.exe	: 1.1.2.0
RTHDCPL.exe	: 2.2.4.8
RTLCPPL.exe	: 1.0.1.66
RtlUpd.exe	: 2.7.1.1
RtlUpd64.exe	: 2.7.1.1
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.32
AMBFilt.sys	: 5.10.0.4240
AMBFilt64.sys	: 5.10.0.4240
Mnfilt.sys	: 5.10.0.4112
Mnfilt64.sys	: 5.10.0.4115
ALSndMgr.cpl	: 1.0.0.11
RTSndMgr.cpl	: 1.0.1.0
RTCOMDLL.dll	: 1.0.0.97
RtlCPAPI.dll	: 1.0.1.9

Vista driver : -----

Vista driver for x86

RTKVHDA.sys	: 6.0.1.5717
AERTSrv.exe	: 1.0.32.7
RtHDVCpl.exe	: 1.0.0.251
RtkAudioService.exe	: 1.0.0.17
RtlUpd.exe	: 2.7.1.1
SkyTel.exe	: 2.0.2.1
vncutil.exe	: 1.0.0.22
RTSndMgr.cpl	: 1.0.0.10
AERTACap.dll	: 1.0.32.7
AERTARen.dll	: 1.0.32.3
CTAP032.dll	: 1.0.0.530
ctppld.dll	: 1.0.0.530
DaisyWrp.dll	: 1.0.0.70
FMAP0.dll	: 40.59.0.0
MaxxAudioAPO.dll	: 1.2.2.0
MaxxAudioAPO20.dll	: 2.0.13.0
MaxxAudioEQ.dll	: 5.9.7.0
ppchain.dll	: 1.0.0.70
RTCOMDLL.dll	: 2.0.0.100
RtkAPO.dll	: 11.0.6000.78
RtkApoApi.dll	: 1.0.0.6
RtkColnst.dll	: 1.0.3.7
RtkPgExt.dll	: 6.0.6000.61
RtlCPAPI.dll	: 1.0.1.9
slcshp32.dll	: 1.0.3.0
slgeq32.dll	: 1.0.1.0
slh36032.dll	: 1.0.2.0
slinit32.dll	: 1.1.1.0
sltshd32.dll	: 1.1.0.0
sluapo32.dll	: 1.2.6.0
SRSHP360.dll	: 1.1.0.0
SRSTSHD.dll	: 1.1.4.0
SRSTSXT.dll	: 3.2.0.0
SRSWOW.dll	: 1.1.3.0
WavesLib.dll	: 5.9.7.0

Vista driver for x64

Readme.txt

```

RTKVHD64.sys : 6.0.1.5717
AERTSr64.exe : 1.0.64.7
RAVCpl64.exe : 1.0.0.251
RtkAudioService.exe : 1.0.0.17
RtlUpd64.exe : 2.7.1.1
SkyTel.exe : 2.0.2.1
vncutil.exe : 1.0.0.22
GWfilt64.sys : 6.10.0.3
RTSnMg64.cpl : 1.0.0.10
AERTAC64.dll : 1.0.64.7
AERTAR64.dll : 1.0.64.3
CTAP032.dll : 1.0.0.530
CTAP064.dll : 1.0.0.530
ctpld.dll : 1.0.0.530
DaisyWrp.dll : 1.0.0.70
FMAP064.dll : 40.59.0.0
MaxxAudioAP020.dll : 2.0.12.0
ppchain.dll : 1.0.0.70
RCoInst64.dll : 1.0.3.7
RtCOMB4.dll : 2.0.0.100
RtCOMDLL.dll : 2.0.0.100
RtkApi64.dll : 1.0.0.6
RtkAPO64.dll : 11.0.6000.78
RtlCPAPI.dll : 1.0.1.9
RtPgEx64.dll : 6.0.6000.61
slcshp64.dll : 1.0.3.0
slgeq64.dll : 1.0.1.0
slh36064.dll : 1.0.2.0
slInit64.dll : 1.1.1.0
sltshd64.dll : 1.1.0.0
sluapo64.dll : 1.2.6.0
SRSHp64.dll : 1.1.0.0
SRSTSH64.dll : 1.1.4.0
SRSTSX64.dll : 3.2.0.0
SRSW064.dll : 1.1.3.0
HDM Driver : -----
Vista x86:
RtHDMV.sys : 6.0.1.5692
RtkUpd.exe : 2.7.1.0
RHCoInst.dll : 1.0.3.2
RHDMExt.dll : 6.0.6000.54
RtkHDM.dll : 11.0.6000.72

Vista x64:
RtHDMVX.sys : 6.0.1.5692
RtkUpd64.exe : 2.7.1.0
RHCoInst64.dll : 1.0.3.2
RHDMEx64.dll : 6.0.6000.54
RtkHDM64.dll : 11.0.6000.72

XP/2K x86:
RtHDM.sys : 5.10.0.5692
RtkUpd.exe : 2.7.1.0
XP/2K x64:
RtHDMX.sys : 5.10.0.5692
RtkUpd64.exe : 2.7.1.0

Driver Setup Program : 2.64

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

```

//=====
Driver Package R2.06

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD,

Readme.txt

ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887

3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
  - 1.) Driver :
    1. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :

RTKHDA64.sys	: 5.10.0.5713
RTKHDAUD.sys	: 5.10.0.5713
Alcmtr.exe	: 1.6.0.3
AlcWzrd.exe	: 1.1.0.37
McCal.exe	: 1.1.2.0
RTHDCPL.exe	: 2.2.4.6
RTLCPPL.exe	: 1.0.1.66
RtlUpd64.exe	: 2.7.1.1
RtlUpd.exe	: 2.7.1.1
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.32
AMBFilt64.sys	: 5.10.0.4240
AMBFilt.sys	: 5.10.0.4240
Mbnfilt64.sys	: 5.10.0.4115
Mbnfilt.sys	: 5.10.0.4112
ALSndMgr.cpl	: 1.0.0.11
RTSndMgr.cpl	: 1.0.1.0
RTCOMDLL.dll	: 1.0.0.97
RtlCPAPI.dll	: 1.0.1.9

Vista driver : -----

Vista driver for x86

RTKVHDA.sys	: 6.0.1.5713
AERTSrv.exe	: 1.0.32.7
RtHDVCpl.exe	: 1.0.0.248
RtkAudioService.exe	: 1.0.0.16
RtlUpd.exe	: 2.7.1.1
SkyTel.exe	: 2.0.2.1
vncutil.exe	: 1.0.0.22
RTSndMgr.cpl	: 1.0.0.10
AERTACap.dll	: 1.0.32.7
AERTARen.dll	: 1.0.32.3
CTAP032.dll	: 1.0.0.530
ctpld.dll	: 1.0.0.530
DaisyWrp.dll	: 1.0.0.70
FMAP0.dll	: 40.59.0.0
MaxxAudioAPO.dll	: 1.2.2.0
MaxxAudioAPO20.dll	: 2.0.13.0
MaxxAudioEQ.dll	: 5.9.7.0
ppchain.dll	: 1.0.0.70
RTCOMDLL.dll	: 2.0.0.100
RtkAPO.dll	: 11.0.6000.77
RtkApoApi.dll	: 1.0.0.6
RtkCoInst.dll	: 1.0.3.6
RtkPgExt.dll	: 6.0.6000.61
RtlCPAPI.dll	: 1.0.1.9
slcshp32.dll	: 1.0.3.0
slgeq32.dll	: 1.0.1.0
slh36032.dll	: 1.0.2.0
slInit32.dll	: 1.1.1.0
sltshd32.dll	: 1.1.0.0
sluapo32.dll	: 1.2.6.0
SRSHP360.dll	: 1.1.0.0
SRSTSHD.dll	: 1.1.4.0
SRSTSXT.dll	: 3.2.0.0
SRSWOW.dll	: 1.1.3.0
WavesLib.dll	: 5.9.7.0
Vista driver for x64	
RTKVHD64.sys	: 6.0.1.5713

Readme.txt

```

AERTSr64.exe : 1.0.64.7
RAVCpl64.exe : 1.0.0.248
RtkAudioService.exe : 1.0.0.16
RtlUpd64.exe : 2.7.1.1
SkyTel.exe : 2.0.2.1
vncutil.exe : 1.0.0.22
GWfilt64.sys : 6.10.0.3
RTSnMg64.cpl : 1.0.0.10
AERTAC64.dll : 1.0.64.7
AERTAR64.dll : 1.0.64.3
CTAP032.dll : 1.0.0.530
CTAP064.dll : 1.0.0.530
ctppld.dll : 1.0.0.530
DaisyWrp.dll : 1.0.0.70
FMAP064.dll : 40.59.0.0
MaxxAudioAP020.dll : 2.0.12.0
ppchain.dll : 1.0.0.70
RCoInst64.dll : 1.0.3.6
RtCOM64.dll : 2.0.0.100
RTCOMDLL.dll : 2.0.0.100
RtkApi64.dll : 1.0.0.6
RtkAPO64.dll : 11.0.6000.77
RtlCPAPI.dll : 1.0.1.9
RtPgEx64.dll : 6.0.6000.61
slcshp64.dll : 1.0.3.0
slgeq64.dll : 1.0.1.0
slh36064.dll : 1.0.2.0
slInit64.dll : 1.1.1.0
sltshd64.dll : 1.1.0.0
sluapo64.dll : 1.2.6.0
SRSHP64.dll : 1.1.0.0
SRSTSH64.dll : 1.1.4.0
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
HDMI Driver : -----
Vista x86:
RtHDMV.sys : 6.0.1.5692
RtkUpd.exe : 2.7.1.0
RHCoInst.dll : 1.0.3.2
RHDMExt.dll : 6.0.6000.54
RtkHDM.dll : 11.0.6000.72

Vista x64:
RtHDMVX.sys : 6.0.1.5692
RtkUpd64.exe : 2.7.1.0
RHCoInst64.dll : 1.0.3.2
RHDMEx64.dll : 6.0.6000.54
RtkHDM64.dll : 11.0.6000.72

XP/2K x86:
RtHDM.sys : 5.10.0.5692
RtkUpd.exe : 2.7.1.0
XP/2K x64:
RtHDMX.sys : 5.10.0.5692
RtkUpd64.exe : 2.7.1.0

Driver Setup Program : 2.64

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

```

//=====

Driver Package R2.05

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887

Readme.txt

3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
  - 1.) Driver :
    1. Customizations.
    2. Meet Microsoft OEM Ready program requirements.
  - 2.) Package :
    1. Meet Microsoft OEM Ready program requirements.

Windows 2000/XP : -----  
Windows 2000/XP :  
RTKHDA64.sys : 5.10.0.5708  
RTKHDAUD.sys : 5.10.0.5708  
Mccal.exe : 1.1.1.9  
RTHDCPL.exe : 2.2.4.5  
RTLCPPL.exe : 1.0.1.66  
RtlUpd64.exe : 2.7.1.1  
RtlUpd.exe : 2.7.1.1  
SkyTel.exe : 2.0.2.0  
SoundMan.exe : 1.0.0.32  
Alcmtr.exe : 1.6.0.3  
AlcWzrd.exe : 1.1.0.37  
Mnfil64.sys : 5.10.0.4115  
Mnfil.sys : 5.10.0.4112  
AMBFil64.sys : 5.10.0.4240  
AMBFil.sys : 5.10.0.4240  
RTSndMgr.cpl : 1.0.1.0  
ALSndMgr.cpl : 1.0.0.11  
RTCOMDLL.dll : 1.0.0.97  
RtlCPAPI.dll : 1.0.1.9  
-----  
Vista driver : -----  
Vista driver for x86  
RTKVHDA.sys : 6.0.1.5708  
AERTSrv.exe : 1.0.32.7  
RtHDVCpl.exe : 1.0.0.246  
RtkAudioService.exe : 1.0.0.16  
RtlUpd.exe : 2.7.1.1  
SkyTel.exe : 2.0.2.1  
vncutil.exe : 1.0.0.21  
RTSndMgr.cpl : 1.0.0.10  
AERTACap.dll : 1.0.32.7  
AERTARen.dll : 1.0.32.3  
CTAP032.dll : 1.0.0.530  
ctpld.dll : 1.0.0.530  
DaisyWrp.dll : 1.0.0.70  
FMAP0.dll : 40.59.0.0  
MaxxAudioAPO.dll : 1.2.2.0  
MaxxAudioAPO20.dll : 2.0.13.0  
MaxxAudioEQ.dll : 5.9.7.0  
ppchain.dll : 1.0.0.70  
RTCOMDLL.dll : 2.0.0.100  
RtkAPO.dll : 11.0.6000.76  
RtkApoApi.dll : 1.0.0.4  
RtkCoInst.dll : 1.0.3.5  
RtkPgExt.dll : 6.0.6000.60  
RtlCPAPI.dll : 1.0.1.9  
slcshp32.dll : 1.0.3.0  
slgeq32.dll : 1.0.1.0  
slh36032.dll : 1.0.2.0  
slInit32.dll : 1.1.1.0  
sltshd32.dll : 1.1.0.0  
sluapo32.dll : 1.2.6.0  
SRSHP360.dll : 1.1.0.0  
SRSTSHD.dll : 1.1.4.0  
SRSTSXT.dll : 3.2.0.0  
SRSWOW.dll : 1.1.3.0  
WavesLib.dll : 5.9.7.0

Readme.txt

Vista driver for x64  
 RTKVHD64.sys : 6.0.1.5708  
 AERTSr64.exe : 1.0.64.7  
 RAVCpl64.exe : 1.0.0.246  
 RtkAudioService.exe : 1.0.0.16  
 RtlUpd64.exe : 2.7.1.1  
 SkyTel.exe : 2.0.2.1  
 vncutil.exe : 1.0.0.21  
 GWFilt64.sys : 6.10.0.3  
 RTSnMg64.cpl : 1.0.0.10  
 AERTAC64.dll : 1.0.64.7  
 AERTAR64.dll : 1.0.64.3  
 CTAP032.dll : 1.0.0.530  
 CTAP064.dll : 1.0.0.530  
 ctppld.dll : 1.0.0.530  
 DaisyWrp.dll : 1.0.0.70  
 FMAP064.dll : 40.59.0.0  
 MaxxAudioAP020.dll : 2.0.12.0  
 ppchain.dll : 1.0.0.70  
 RCoInst64.dll : 1.0.3.5  
 RtCOM64.dll : 2.0.0.100  
 RTCOMDLL.dll : 2.0.0.100  
 RtkApi64.dll : 1.0.0.4  
 RtkAPO64.dll : 11.0.6000.76  
 RtlCPAPI.dll : 1.0.1.9  
 RtlPgEx64.dll : 6.0.6000.60  
 slcshp64.dll : 1.0.3.0  
 slgeq64.dll : 1.0.1.0  
 slh36064.dll : 1.0.2.0  
 slInit64.dll : 1.1.1.0  
 sltshd64.dll : 1.1.0.0  
 sluapo64.dll : 1.2.6.0  
 SRSHp64.dll : 1.1.0.0  
 SRSTSH64.dll : 1.1.4.0  
 SRSTSX64.dll : 3.2.0.0  
 SRSWOW64.dll : 1.1.3.0

HDMI Driver : -----  
 Vista x86:  
 RtHDMV.sys : 6.0.1.5692  
 RtkUpd.exe : 2.7.1.0  
 RHCoInst.dll : 1.0.3.2  
 RHDMExt.dll : 6.0.6000.54  
 RtkHDM.dll : 11.0.6000.72

Vista x64:  
 RtHDMVX.sys : 6.0.1.5692  
 RtkUpd64.exe : 2.7.1.0  
 RHCoInst64.dll : 1.0.3.2  
 RHDMEx64.dll : 6.0.6000.54  
 RtkHDM64.dll : 11.0.6000.72

XP/2K x86:  
 RtHDM.sys : 5.10.0.5692  
 RtkUpd.exe : 2.7.1.0

XP/2K x64:  
 RtHDMX.sys : 5.10.0.5692  
 RtkUpd64.exe : 2.7.1.0

Driver Setup Program : 2.64

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111  
 Package file version (kb888111.exe) : 6.1.22.0  
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.04

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/Wi nXP/Wi n2000/Wi n2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887

Readme.txt

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
  - 1.) Driver :
    1. Customizations.
    2. Support ALC887.

Windows 2000/XP : -----

Windows 2000/XP :  
RTKHDA64.sys : 5.10.0.5700  
RTKHDAUD.sys : 5.10.0.5700  
Alcmtr.exe : 1.6.0.3  
AlcWzrd.exe : 1.1.0.37  
Mccal.exe : 1.1.1.8  
RTHDCPL.exe : 2.2.4.0  
RTLCPPL.exe : 1.0.1.66  
RtlUpd64.exe : 2.7.1.0  
RtlUpd.exe : 2.7.1.0  
SkyTel.exe : 2.0.2.0  
SoundMan.exe : 1.0.0.32  
AMBfilt64.sys : 5.10.0.4240  
AMBfilt.sys : 5.10.0.4240  
Mnfiltr64.sys : 5.10.0.4115  
Mnfiltr.sys : 5.10.0.4112  
ALSndMgr.cpl : 1.0.0.11  
RTSndMgr.cpl : 1.0.1.0  
RTCOMDLL.dll : 1.0.0.97  
RtlCPAPI.dll : 1.0.1.9

Vista driver : -----

Vista driver for x86  
RTKVHDA.sys : 6.0.1.5700  
AERTSrv.exe : 1.0.32.7  
RtHDVCpl.exe : 1.0.0.240  
RtkAudioService.exe : 1.0.0.16  
RtlUpd.exe : 2.7.1.0  
SkyTel.exe : 2.0.2.1  
vncutil.exe : 1.0.0.21  
RTSndMgr.cpl : 1.0.0.9  
AERTACap.dll : 1.0.32.7  
AERTARen.dll : 1.0.32.3  
CTAP032.dll : 1.0.0.520  
ctpld.dll : 1.0.0.510  
DaisyWrp.dll : 1.0.0.70  
FMAP0.dll : 40.59.0.0  
MaxxAudioAPO.dll : 1.2.2.0  
MaxxAudioAPO20.dll : 2.0.13.0  
MaxxAudioEQ.dll : 5.9.7.0  
ppchain.dll : 1.0.0.70  
RTCOMDLL.dll : 2.0.0.100  
RtkAPO.dll : 11.0.6000.74  
RtkApoApi.dll : 1.0.0.4  
RtkCoInst.dll : 1.0.3.2  
RtkPgExt.dll : 6.0.6000.56  
RtlCPAPI.dll : 1.0.1.9  
SRSHP360.dll : 1.1.0.0  
SRSTSHD.dll : 1.1.4.0  
SRSTSXT.dll : 3.2.0.0  
SRSWOW.dll : 1.1.3.0  
WavesLib.dll : 5.9.7.0  
Vista driver for x64  
GWfilt64.sys : 6.10.0.3  
RTKVHD64.sys : 6.0.1.5700  
AERTSr64.exe : 1.0.64.7  
RAVCpl64.exe : 1.0.0.240  
RtkAudioService.exe : 1.0.0.16



Readme.txt

```

RtlUpd64.exe           : 2.7.1.0
SkyTel.exe             : 2.0.2.1
vncutil.exe           : 1.0.0.21
RTSnMg64.cpl          : 1.0.0.9
AERTAC64.dll          : 1.0.64.7
AERTAR64.dll          : 1.0.64.3
CTAP032.dll           : 1.0.0.520
CTAP064.dll           : 1.0.0.520
ctppld.dll            : 1.0.0.510
DaisyWrp.dll          : 1.0.0.70
FMAP064.dll           : 40.59.0.0
MaxxAudioAP020.dll   : 2.0.12.0
ppchain.dll           : 1.0.0.70
RCoInst64.dll         : 1.0.3.2
RtCOM64.dll           : 2.0.0.100
RTCOMDLL.dll          : 2.0.0.100
RtkApi64.dll          : 1.0.0.4
RtkAP064.dll          : 11.0.6000.74
RtlCPAPI.dll          : 1.0.1.9
RtPgEx64.dll         : 6.0.6000.56
SRSHp64.dll          : 1.1.0.0
SRSTSH64.dll         : 1.1.4.0
SRSTSX64.dll         : 3.2.0.0
SRSWOW64.dll         : 1.1.3.0
-----
HDMI Driver : -----
Vista x86:
RtHDMV.sys            : 6.0.1.5692
RtkUpd.exe            : 2.7.1.0
RHCoInst.dll         : 1.0.3.2
RHDMExt.dll          : 6.0.6000.54
RtkHDM.dll           : 11.0.6000.72

Vista x64:
RtHDMVX.sys          : 6.0.1.5692
RtkUpd64.exe         : 2.7.1.0
RHCoInst64.dll       : 1.0.3.2
RHDMEx64.dll         : 6.0.6000.54
RtkHDM64.dll         : 11.0.6000.72

XP/2K x86:
RtHDM.sys            : 5.10.0.5692
RtkUpd.exe            : 2.7.1.0
XP/2K x64:
RtHDMX.sys           : 5.10.0.5692
RtkUpd64.exe         : 2.7.1.0

Driver Setup Program : 2.62

```

Windows 2000/XP Operate on :  
 Microsoft High Definition Audio Driver Package - KB888111  
 Package file version (kb888111.exe) : 6.1.22.0  
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.03

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
  - 1.) Driver :
    1. Customizations.

Windows 2000/XP : -----  
 Windows 2000/XP :

```

Readme.txt
RTKHDA64.sys : 5.10.0.5694
RTKHDAUD.sys : 5.10.0.5694
Alcmttr.exe : 1.6.0.3
AlcWzrd.exe : 1.1.0.37
Mccal.exe : 1.1.1.8
RTHDCPL.exe : 2.2.3.8
RTLCPPL.exe : 1.0.1.66
RtlUpd64.exe : 2.7.1.0
RtlUpd.exe : 2.7.1.0
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.32
ALSndMgr.cpl : 1.0.0.11
RTSndMgr.cpl : 1.0.1.0
RTCOMDLL.dll : 1.0.0.97
RtlCPAPI.dll : 1.0.1.9
Vista driver : -----
Vista driver for x86
RTKVHDA.sys : 6.0.1.5694
AERTSrv.exe : 1.0.32.7
RtHDVCpl.exe : 1.0.0.235
RtkAudioService.exe : 1.0.0.16
RtlUpd.exe : 2.7.1.0
SkyTel.exe : 2.0.2.1
vncutil.exe : 1.0.0.21
RTSndMgr.cpl : 1.0.0.9
AERTACap.dll : 1.0.32.7
AERTARen.dll : 1.0.32.3
FMAP0.dll : 40.59.0.0
MaxxAudioAPO.dll : 1.2.2.0
MaxxAudioAPO20.dll : 2.0.13.0
MaxxAudioEQ.dll : 5.9.7.0
RTCOMDLL.dll : 2.0.0.99
RtkAPO.dll : 11.0.6000.72
RtkApoApi.dll : 1.0.0.4
RtkCoInst.dll : 1.0.3.2
RtkPgExt.dll : 6.0.6000.54
RtlCPAPI.dll : 1.0.1.9
SRSH360.dll : 1.1.0.0
SRSTSHD.dll : 1.1.4.0
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.1.3.0
WavesLib.dll : 5.9.7.0
Vista driver for x64
RTKVHD64.sys : 6.0.1.5694
AERTSr64.exe : 1.0.64.7
RAVCpl64.exe : 1.0.0.235
RtkAudioService.exe : 1.0.0.16
RtlUpd64.exe : 2.7.1.0
SkyTel.exe : 2.0.2.1
vncutil.exe : 1.0.0.21
RTSnMg64.cpl : 1.0.0.9
AERTAC64.dll : 1.0.64.7
AERTAR64.dll : 1.0.64.3
FMAP064.dll : 40.59.0.0
MaxxAudioAPO20.dll : 2.0.12.0
RCoInst64.dll : 1.0.3.2
RtCOM64.dll : 2.0.0.99
RTCOMDLL.dll : 2.0.0.99
RtkApi64.dll : 1.0.0.4
RtkAPO64.dll : 11.0.6000.72
RtlCPAPI.dll : 1.0.1.9
RtkPgEx64.dll : 6.0.6000.54
SRSH64.dll : 1.1.0.0
SRSTSH64.dll : 1.1.4.0
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
HDMI Driver : -----
Vista x86:
RtHDMIV.sys : 6.0.1.5692

```

```

Readme.txt
RtkUpd.exe : 2.7.1.0
RHCoInst.dll : 1.0.3.2
RHDMExt.dll : 6.0.6000.54
RtkHDM.dll : 11.0.6000.72

Vista x64:
RtHDMVX.sys : 6.0.1.5692
RtkUpd64.exe : 2.7.1.0
RHCoInst64.dll : 1.0.3.2
RHDMExt64.dll : 6.0.6000.54
RtkHDM64.dll : 11.0.6000.72

XP/2K x86:
RtHDM.sys : 5.10.0.5692
RtkUpd.exe : 2.7.1.0
XP/2K x64:
RtHDMX.sys : 5.10.0.5692
RtkUpd64.exe : 2.7.1.0

Driver Setup Program : 2.62

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013
//=====
Driver Package R2.02
Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .
1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663,
ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD,
ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
1.) Driver :
1. Customizations.
2. Update ForteMedia microphone effect library.

2.) Package :
1. Delete driver file by Rtlupd.exe in Windows 2000/2003/XP System . ( Rtlupd.exe 2.7.1.0 )

Windows 2000/XP : -----
Windows 2000/XP :
RTKHDA64.sys : 5.10.0.5683
RTKHDAUD.sys : 5.10.0.5683
Alcmtr.exe : 1.6.0.3
AlcWzrd.exe : 1.1.0.37
McCal.exe : 1.1.1.8
RTHDCPL.exe : 2.2.3.3
RTLCPPL.exe : 1.0.1.66
RtlUpd64.exe : 2.7.1.0
RtlUpd.exe : 2.7.1.0
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.31
ALSndMgr.cpl : 1.0.0.11
RTSndMgr.cpl : 1.0.1.0
RTCOMDLL.dll : 1.0.0.97
RtlCPAPI.dll : 1.0.1.9
Vista driver : -----
Vista driver for x86
RTKVHDA.sys : 6.0.1.5683
AERTSrv.exe : 1.0.32.7
RtHDVCpl.exe : 1.0.0.227
RtkAudioService.exe : 1.0.0.16
RtlUpd.exe : 2.7.1.0
SkyTel.exe : 2.0.2.1

```

Readme.txt

```

vncutil.exe : 1.0.0.19
RTSndMgr.cpl : 1.0.0.8
AERTACap.dll : 1.0.32.7
AERTARen.dll : 1.0.32.3
FMAP0.dll : 40.59.0.0
MaxxAudioAPO.dll : 1.2.2.0
MaxxAudioAPO20.dll : 2.0.13.0
MaxxAudioEQ.dll : 5.9.7.0
RTCOMDLL.dll : 2.0.0.99
RtkAPO.dll : 11.0.6000.71
RtkApoApi.dll : 1.0.0.4
RtkCoInst.dll : 1.0.3.2
RtkPgExt.dll : 6.0.6000.53
RtLCPAPI.dll : 1.0.1.9
SRSHP360.dll : 1.1.0.0
SRSTSHD.dll : 1.1.4.0
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.1.3.0
WavesLib.dll : 5.9.7.0
Vista driver for x64
RTKVHD64.sys : 6.0.1.5683
AERTSr64.exe : 1.0.64.7
RAVCpl64.exe : 1.0.0.227
RtkAudioService.exe : 1.0.0.16
RtlUpd64.exe : 2.7.1.0
SkyTel.exe : 2.0.2.1
vncutil.exe : 1.0.0.19
RTSnMg64.cpl : 1.0.0.8
AERTAC64.dll : 1.0.64.7
AERTAR64.dll : 1.0.64.3
FMAP064.dll : 40.59.0.0
MaxxAudioAPO20.dll : 2.0.12.0
RCoInst64.dll : 1.0.3.2
RtCOMB4.dll : 2.0.0.99
RTCOMDLL.dll : 2.0.0.99
RtkApi64.dll : 1.0.0.4
RtkAPO64.dll : 11.0.6000.71
RtLCPAPI.dll : 1.0.1.9
RtPgEx64.dll : 6.0.6000.53
SRSHP64.dll : 1.1.0.0
SRSTSH64.dll : 1.1.4.0
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
HDM Driver : -----
Vista x86:
RtHDMV.sys : 6.0.1.5668
RtkUpd.exe : 2.7.0.9
RHCoInst.dll : 1.0.2.9
RHDMExt.dll : 6.0.6000.52
RtkHDM.dll : 11.0.6000.69

Vista x64:
RtHDMVX.sys : 6.0.1.5668
RtkUpd64.exe : 2.7.0.9
RHCoInst64.dll : 1.0.2.9
RHDMEx64.dll : 6.0.6000.52
RtkHDM64.dll : 11.0.6000.69

XP/2K x86:
RtHDM.sys : 5.10.0.5668
RtkUpd.exe : 2.7.0.9
XP/2K x64:
RtHDMX.sys : 5.10.0.5668
RtkUpd64.exe : 2.7.0.9

Driver Setup Program : 2.62

```

Windows 2000/XP Operate on :  
Microsoft High Definition Audio Driver Package - KB888111

Readme.txt

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.01

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix

1.) Driver :

1. Customizations.
2. Support ALC273.

2.) Package :

1. Change warning message for upgrade driver .
2. ChCfg.exe add version and manifest embedded feature .
3. Add Manifest to Rtlupd.exe and HideWin.exe .
4. The SetCDFmt function was included by RtlExUpd.dll Ver.1.0.1.1

Windows 2000/XP : -----

Windows 2000/XP :

RTKHDA64.sys	: 5.10.0.5680
RTKHDAUD.sys	: 5.10.0.5680
Alcmtr.exe	: 1.6.0.3
AlcWzrd.exe	: 1.1.0.37
McCal.exe	: 1.1.1.8
RTHDCPL.exe	: 2.2.3.3
RTLCPPL.exe	: 1.0.1.66
RtlUpd64.exe	: 2.7.0.9
RtlUpd.exe	: 2.7.0.9
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.31
ALSndMgr.cpl	: 1.0.0.11
RTSndMgr.cpl	: 1.0.1.0
RTCOMDLL.dll	: 1.0.0.97
RtlCPAPI.dll	: 1.0.1.9

Vista driver : -----

Vista driver for x86

RTKVHDA.sys	: 6.0.1.5680
AERTSrv.exe	: 1.0.32.7
RtHDVCpl.exe	: 1.0.0.224
RtkAudioService.exe	: 1.0.0.16
RtlUpd.exe	: 2.7.0.9
SkyTel.exe	: 2.0.2.1
vncutil.exe	: 1.0.0.19
RTSndMgr.cpl	: 1.0.0.8
AERTACap.dll	: 1.0.32.7
AERTARen.dll	: 1.0.32.3
FMAPO.dll	: 40.59.0.0
MaxxAudioAPO.dll	: 1.2.2.0
MaxxAudioAPO20.dll	: 2.0.13.0
MaxxAudioEQ.dll	: 5.9.7.0
RTCOMDLL.dll	: 2.0.0.99
RtkAPO.dll	: 11.0.6000.71
RtkApoApi.dll	: 1.0.0.4
RtkCoInst.dll	: 1.0.3.2
RtkPgExt.dll	: 6.0.6000.53
RtlCPAPI.dll	: 1.0.1.9
SRSHP360.dll	: 1.1.0.0
SRSTSHD.dll	: 1.1.4.0
SRSTSXT.dll	: 3.2.0.0
SRSWOW.dll	: 1.1.3.0
WavesLib.dll	: 5.9.7.0

Vista driver for x64

Readme.txt

```

RTKVHD64.sys : 6.0.1.5680
AERTSr64.exe : 1.0.64.7
RAVCpl64.exe : 1.0.0.224
RtkAudioService.exe : 1.0.0.16
RtlUpd64.exe : 2.7.0.9
SkyTel.exe : 2.0.2.1
vncutil.exe : 1.0.0.19
RTSnMg64.cpl : 1.0.0.8
AERTAC64.dll : 1.0.64.7
AERTAR64.dll : 1.0.64.3
FMAP064.dll : 40.59.0.0
MaxxAudioAPO20.dll : 2.0.12.0
RCoInst64.dll : 1.0.3.2
RtCOMB4.dll : 2.0.0.99
RtCOMDLL.dll : 2.0.0.99
RtkApi64.dll : 1.0.0.4
RtkAPO64.dll : 11.0.6000.71
RtlCPAPI.dll : 1.0.1.9
RtPgEx64.dll : 6.0.6000.53
SRSHp64.dll : 1.1.0.0
SRSTSH64.dll : 1.1.4.0
SRSTX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
HDMI Driver : -----
Vista x86:
RtHDMV.sys : 6.0.1.5668
RtkUpd.exe : 2.7.0.9
RHCoInst.dll : 1.0.2.9
RHDMExt.dll : 6.0.6000.52
RtkHDM.dll : 11.0.6000.69

Vista x64:
RtHDMVX.sys : 6.0.1.5668
RtkUpd64.exe : 2.7.0.9
RHCoInst64.dll : 1.0.2.9
RHDMEx64.dll : 6.0.6000.52
RtkHDM64.dll : 11.0.6000.69

XP/2K x86:
RtHDM.sys : 5.10.0.5668
RtkUpd.exe : 2.7.0.9
XP/2K x64:
RtHDMX.sys : 5.10.0.5668
RtkUpd64.exe : 2.7.0.9

Driver Setup Program : 2.61

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013
//=====
Driver Package R2.00
Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .
1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663,
ALC260, ALC262, ALC267, ALC268, ALC269, ALC272
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD,
ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
1.) Driver :
1. Customizations.

Windows 2000/XP : -----
Windows 2000/XP :
RTKHDA64.sys : 5.10.0.5672

```

```

Readme.txt
RTKHDAUD.sys : 5.10.0.5672
AlcMtr.exe : 1.6.0.3
AlcWzrd.exe : 1.1.0.37
Mccal.exe : 1.1.1.8
RTHDCPL.exe : 2.2.3.1
RTLCPPL.exe : 1.0.1.66
RtlUpd64.exe : 2.7.0.9
RtlUpd.exe : 2.7.0.9
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.31
ALSndMgr.cpl : 1.0.0.11
RTSndMgr.cpl : 1.0.1.0
RTCOMDLL.dll : 1.0.0.97
RtlCPAPI.dll : 1.0.1.9
Vista driver : -----
Vista driver for x86
RTKVHDA.sys : 6.0.1.5672
AERTSrv.exe : 1.0.32.7
RtHDVCpl.exe : 1.0.0.219
RtkAudioService.exe : 1.0.0.16
RtlUpd.exe : 2.7.0.9
SkyTel.exe : 2.0.2.1
vncutil.exe : 1.0.0.19
RTSndMgr.cpl : 1.0.0.8
AERTACap.dll : 1.0.32.7
AERTARen.dll : 1.0.32.3
FMAP0.dll : 40.59.0.0
MaxxAudioAP0.dll : 1.2.2.0
MaxxAudioAP020.dll : 2.0.13.0
MaxxAudioEQ.dll : 5.9.7.0
RTCOMDLL.dll : 2.0.0.98
RtkAP0.dll : 11.0.6000.70
RtkApoApi.dll : 1.0.0.4
RtkCoInst.dll : 1.0.3.1
RtkPgExt.dll : 6.0.6000.53
RtlCPAPI.dll : 1.0.1.9
SRSHP360.dll : 1.1.0.0
SRSTSHD.dll : 1.1.4.0
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.1.3.0
WavesLib.dll : 5.9.7.0
Vista driver for x64
RTKVHD64.sys : 6.0.1.5672
AERTSr64.exe : 1.0.64.7
RAVCpl64.exe : 1.0.0.219
RtkAudioService.exe : 1.0.0.16
RtlUpd64.exe : 2.7.0.9
SkyTel.exe : 2.0.2.1
vncutil.exe : 1.0.0.19
RTSnMg64.cpl : 1.0.0.8
AERTAC64.dll : 1.0.64.7
AERTAR64.dll : 1.0.64.3
FMAP64.dll : 40.59.0.0
MaxxAudioAP020.dll : 2.0.12.0
RCoInst64.dll : 1.0.3.1
RtCOMB4.dll : 2.0.0.98
RTCOMDLL.dll : 2.0.0.98
RtkApi64.dll : 1.0.0.4
RtkAP064.dll : 11.0.6000.70
RtlCPAPI.dll : 1.0.1.9
RtPgEx64.dll : 6.0.6000.53
SRSHP64.dll : 1.1.0.0
SRSTSH64.dll : 1.1.4.0
SRSTX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
HDMI Driver : -----
Vista x86:
RtHDMV.sys : 6.0.1.5668
RtkUpd.exe : 2.7.0.9

```

```

Readme.txt
RHCoinst.dll : 1.0.2.9
RHDMExt.dll : 6.0.6000.52
RtkHDM.dll : 11.0.6000.69

Vista x64:
RtHDMVX.sys : 6.0.1.5668
RtkUpd64.exe : 2.7.0.9
RHCoinst64.dll : 1.0.2.9
RHDMEx64.dll : 6.0.6000.52
RtkHDM64.dll : 11.0.6000.69

XP/2K x86:
RtHDM.sys : 5.10.0.5668
RtkUpd.exe : 2.7.0.9
XP/2K x64:
RtHDMX.sys : 5.10.0.5668
RtkUpd64.exe : 2.7.0.9

Driver Setup Program : 2.60

```

Windows 2000/XP Operate on :  
Microsoft High Definition Audio Driver Package - KB888111  
Package file version (kb888111.exe) : 6.1.22.0  
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.99

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
  - 1.) Driver :
    1. Customizations.

Windows 2000/XP : -----

```

Windows 2000/XP :
RTKHDA64.sys : 5.10.0.5667
RTKHDAUD.sys : 5.10.0.5667
McCal.exe : 1.1.1.8
RTHDCPL.exe : 2.2.3.0
RTLCPPL.exe : 1.0.1.66
RtlUpd64.exe : 2.7.0.9
RtlUpd.exe : 2.7.0.9
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.31
Alcmtr.exe : 1.6.0.3
AlcWzrd.exe : 1.1.0.37
RTSndMgr.cpl : 1.0.1.0
ALSndMgr.cpl : 1.0.0.11
RTCOMDLL.dll : 1.0.0.97
RtlCPAPI.dll : 1.0.1.9

```

Vista driver : -----

```

Vista driver for x86
RTKVHDA.sys : 6.0.1.5667
AERTSrv.exe : 1.0.32.2
RtHDVCpl.exe : 1.0.0.215
RtkAudioService.exe : 1.0.0.16
RtlUpd.exe : 2.7.0.9
SkyTel.exe : 2.0.2.1
vncutil.exe : 1.0.0.18
RTSndMgr.cpl : 1.0.0.8
AERTACap.dll : 1.0.32.7
AERTARen.dll : 1.0.32.3
FNAP0.dll : 40.59.0.0

```



```

Readme.txt
MaxxAudioAPO.dll : 1.2.2.0
MaxxAudioAPO20.dll : 2.0.13.0
MaxxAudioEQ.dll : 5.9.7.0
RTCOMDLL.dll : 2.0.0.98
RtkAPO.dll : 11.0.6000.69
RtkApoApi.dll : 1.0.0.4
RtkCoInst.dll : 1.0.3.1
RtkPgExt.dll : 6.0.6000.52
RtlCPAPI.dll : 1.0.1.9
SRSHP360.dll : 1.1.0.0
SRSTSHD.dll : 1.1.4.0
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.1.3.0
WavesLib.dll : 5.9.7.0
Vista driver for x64
RTKVHD64.sys : 6.0.1.5667
AERTSr64.exe : 1.0.64.2
RAVCpl64.exe : 1.0.0.215
RtkAudioService.exe : 1.0.0.16
RtlUpd64.exe : 2.7.0.9
SkyTel.exe : 2.0.2.1
vncutil.exe : 1.0.0.18
RTSnMg64.cpl : 1.0.0.8
AERTAC64.dll : 1.0.64.7
AERTAR64.dll : 1.0.64.3
FMAP064.dll : 40.59.0.0
MaxxAudioAPO20.dll : 2.0.12.0
RCoInst64.dll : 1.0.3.1
RtCOM64.dll : 2.0.0.98
RTCOMDLL.dll : 2.0.0.98
RtkApi64.dll : 1.0.0.4
RtkAPO64.dll : 11.0.6000.69
RtlCPAPI.dll : 1.0.1.9
RtPgEx64.dll : 6.0.6000.52
SRSHP64.dll : 1.1.0.0
SRSTSH64.dll : 1.1.4.0
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
HDMI Driver : -----
Vista x86:
RtHDMV.sys : 6.0.1.5645
RtkUpd.exe : 2.7.0.9
RHCoInst.dll : 1.0.2.9
RHDMExt.dll : 6.0.6000.50
RtkHDM.dll : 11.0.6000.67

Vista x64:
RtHDMVX.sys : 6.0.1.5645
RtkUpd64.exe : 2.7.0.9
RHCoInst64.dll : 1.0.2.9
RHDMEx64.dll : 6.0.6000.50
RtkHDM64.dll : 11.0.6000.67

XP/2K x86:
RtHDM.sys : 5.10.0.5645
RtkUpd.exe : 2.7.0.9
XP/2K x64:
RtHDMX.sys : 5.10.0.5645
RtkUpd64.exe : 2.7.0.9

Driver Setup Program : 2.60

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

```

//=====
Driver Package R1.98

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/Wi nXP/Wi n2000/Wi n2003 .

Readme.txt

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
  - 1.) Driver :
    1. Customizations.
    2. Fix the potential risk that audio driver can't be installed completely under Vista.

Windows 2000/XP : -----

Windows 2000/XP :  
RTKHDA64.sys : 5.10.0.5657  
RTKHDAUD.sys : 5.10.0.5657  
Alcmtr.exe : 1.6.0.3  
AlcWzrd.exe : 1.1.0.37  
Mccal.exe : 1.1.1.8  
RTHDCPL.exe : 2.2.2.5  
RTLCPPL.exe : 1.0.1.66  
RtlUpd64.exe : 2.7.0.9  
RtlUpd.exe : 2.7.0.9  
SkyTel.exe : 2.0.2.0  
SoundMan.exe : 1.0.0.31  
ALSndMgr.cpl : 1.0.0.11  
RTSndMgr.cpl : 1.0.1.0  
RTCOMDLL.dll : 1.0.0.97  
RtlCPAPI.dll : 1.0.1.9

Vista driver : -----

Vista driver for x86  
RTKVHDA.sys : 6.0.1.5657  
AERTSrv.exe : 1.0.32.2  
RtHDVCpl.exe : 1.0.0.208  
RtkAudioService.exe : 1.0.0.16  
RtlUpd.exe : 2.7.0.9  
SkyTel.exe : 2.0.2.1  
vncutil.exe : 1.0.0.14  
RTSndMgr.cpl : 1.0.0.8  
AERTACap.dll : 1.0.32.7  
AERTARen.dll : 1.0.32.3  
FMAP0.dll : 40.59.0.0  
MaxxAudioAPO.dll : 1.2.2.0  
MaxxAudioAPO20.dll : 2.0.13.0  
MaxxAudioEQ.dll : 5.9.7.0  
RTCOMDLL.dll : 2.0.0.98  
RtkAPO.dll : 11.0.6000.69  
RtkApoApi.dll : 1.0.0.4  
RtkCoInst.dll : 1.0.2.10  
RtkPgExt.dll : 6.0.6000.52  
RtlCPAPI.dll : 1.0.1.9  
SRSHP360.dll : 1.1.0.0  
SRSTSHD.dll : 1.1.4.0  
SRSTSXT.dll : 3.2.0.0  
SRSWOW.dll : 1.1.3.0  
WavesLib.dll : 5.9.7.0  
Vista driver for x64  
RTKVHD64.sys : 6.0.1.5657  
AERTSr64.exe : 1.0.64.2  
RAVCpl64.exe : 1.0.0.208  
RtkAudioService.exe : 1.0.0.16  
RtlUpd64.exe : 2.7.0.9  
SkyTel.exe : 2.0.2.1  
vncutil.exe : 1.0.0.14  
RTSnMg64.cpl : 1.0.0.8  
AERTAC64.dll : 1.0.64.7  
AERTAR64.dll : 1.0.64.3  
FMAP064.dll : 40.59.0.0

Readme.txt

```

MaxxAudioAPO20.dll : 2.0.12.0
RCoInst64.dll : 1.0.2.10
RtCOM64.dll : 2.0.0.98
RTCOMDLL.dll : 2.0.0.98
RtkApi64.dll : 1.0.0.4
RtkAPO64.dll : 11.0.6000.69
RtLCPAPI.dll : 1.0.1.9
RtPgEx64.dll : 6.0.6000.52
SRSHp64.dll : 1.1.0.0
SRSTSH64.dll : 1.1.4.0
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
HDM Driver : -----
Vista x86:
RtHDMV.sys : 6.0.1.5645
RtkUpd.exe : 2.7.0.9
RHCoInst.dll : 1.0.2.9
RHDMExt.dll : 6.0.6000.50
RtkHDM.dll : 11.0.6000.67

Vista x64:
RtHDMVX.sys : 6.0.1.5645
RtkUpd64.exe : 2.7.0.9
RHCoInst64.dll : 1.0.2.9
RHDMEx64.dll : 6.0.6000.50
RtkHDM64.dll : 11.0.6000.67

XP/2K x86:
RtHDM.sys : 5.10.0.5645
RtkUpd.exe : 2.7.0.9
XP/2K x64:
RtHDMX.sys : 5.10.0.5645
RtkUpd64.exe : 2.7.0.9

Driver Setup Program : 2.60

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013
//=====
Driver Package R1.97
Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .
1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663,
ALC260, ALC262, ALC267, ALC268, ALC269, ALC272
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD,
ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
1.) Driver :
1. Customizations.
2. Add 24-bits recording feature.
3. Fix EAX direct parameter issue under XP.
4. Fix dummy noise issue under XP.

Windows 2000/XP : -----
Windows 2000/XP :
RTKHDA64.sys : 5.10.0.5653
RTKHDAUD.sys : 5.10.0.5653
Alcmtr.exe : 1.6.0.3
AlcWzrd.exe : 1.1.0.37
McCal.exe : 1.1.1.8
RTHDCPL.exe : 2.2.2.4
RTLCPPL.exe : 1.0.1.66
RtlUpd64.exe : 2.7.0.9
RtlUpd.exe : 2.7.0.9

```

Readme.txt

```

SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.31
ALSndMgr.cpl : 1.0.0.11
RTSndMgr.cpl : 1.0.1.0
RTCOMDLL.dll : 1.0.0.97
RtICPAPI.dll : 1.0.1.9
Vista driver : -----
Vista driver for x86
RTKVHDA.sys : 6.0.1.5653
AERTSrv.exe : 1.0.32.2
RtHDVCpl.exe : 1.0.0.206
RtkAudioService.exe : 1.0.0.16
RtlUpd.exe : 2.7.0.9
SkyTel.exe : 2.0.2.1
vncutil.exe : 1.0.0.12
RTSndMgr.cpl : 1.0.0.8
AERTACap.dll : 1.0.32.7
AERTARen.dll : 1.0.32.3
FMAP0.dll : 40.59.0.0
MaxxAudioAP0.dll : 1.2.2.0
MaxxAudioAP020.dll : 2.0.13.0
MaxxAudioEQ.dll : 5.9.7.0
RTCOMDLL.dll : 2.0.0.98
RtkAP0.dll : 11.0.6000.67
RtkApoApi.dll : 1.0.0.4
RtkCoInst.dll : 1.0.2.10
RtkPgExt.dll : 6.0.6000.50
RtICPAPI.dll : 1.0.1.9
SRSH360.dll : 1.1.0.0
SRSTSHD.dll : 1.1.4.0
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.1.3.0
WavesLib.dll : 5.9.7.0
Vista driver for x64
RTKVHD64.sys : 6.0.1.5653
AERTSr64.exe : 1.0.64.2
RAVCpl64.exe : 1.0.0.206
RtkAudioService.exe : 1.0.0.16
RtlUpd64.exe : 2.7.0.9
SkyTel.exe : 2.0.2.1
vncutil.exe : 1.0.0.12
RTSnMg64.cpl : 1.0.0.8
AERTAC64.dll : 1.0.64.7
AERTAR64.dll : 1.0.64.3
FMAP064.dll : 40.59.0.0
MaxxAudioAP020.dll : 2.0.12.0
RCoInst64.dll : 1.0.2.10
RtCOMB4.dll : 2.0.0.98
RTCOMDLL.dll : 2.0.0.98
RtkApi64.dll : 1.0.0.4
RtkAP064.dll : 11.0.6000.67
RtICPAPI.dll : 1.0.1.9
RtPgEx64.dll : 6.0.6000.50
SRSH64.dll : 1.1.0.0
SRSTSH64.dll : 1.1.4.0
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
HDM Driver : -----
Vista x86:
RtHDM.V.sys : 6.0.1.5645
RtkUpd.exe : 2.7.0.9
RHCoInst.dll : 1.0.2.9
RHDMExt.dll : 6.0.6000.50
RtkHDM.dll : 11.0.6000.67

Vista x64:
RtHDM.VX.sys : 6.0.1.5645
RtkUpd64.exe : 2.7.0.9
RHCoInst64.dll : 1.0.2.9

```

Readme.txt

RHDMEx64.dll : 6.0.6000.50  
 RtkHDM64.dll : 11.0.6000.67

XP/2K x86:  
 RtHDM.sys : 5.10.0.5645  
 RtkUpd.exe : 2.7.0.9

XP/2K x64:  
 RtHDMX.sys : 5.10.0.5645  
 RtkUpd64.exe : 2.7.0.9

Driver Setup Program : 2.60

Windows 2000/XP Operate on :  
 Microsoft High Definition Audio Driver Package - KB888111  
 Package file version (kb888111.exe) : 6.1.22.0  
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.96

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/Wi nXP/Wi n2000/Wi n2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft Wi ndowsXP, Wi ndows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
  - 1.) Driver :
    1. Customizations.
  - 2.) Package :
    1. Fix uninstalled message\_2 problem ( French language ) .

Windows 2000/XP : -----

Windows 2000/XP :  
 RTKHDA64.sys : 5.10.0.5643  
 RTKHDAUD.sys : 5.10.0.5643  
 Alcmtr.exe : 1.6.0.2  
 AlcWzrd.exe : 1.1.0.36  
 McCal.exe : 1.1.1.8  
 RTHDCPL.exe : 2.2.1.8  
 RTLCPL.exe : 1.0.1.65  
 RtlUpd64.exe : 2.7.0.9  
 RtlUpd.exe : 2.7.0.9  
 SkyTel.exe : 2.0.2.0  
 SoundMan.exe : 1.0.0.30  
 ALSndMgr.cpl : 1.0.0.10  
 RTSndMgr.cpl : 1.0.1.0  
 RTCOMDLL.dll : 1.0.0.97  
 RtlCPAPI.dll : 1.0.1.9

Vista driver : -----

Vista driver for x86  
 RTKVHDA.sys : 6.0.1.5643  
 AERTSrv.exe : 1.0.32.2  
 RtHDVCpl.exe : 1.0.0.198  
 RtkAudioService.exe : 1.0.0.14  
 RtlUpd.exe : 2.7.0.9  
 SkyTel.exe : 2.0.2.0  
 vncutil.exe : 1.0.0.7  
 RTSndMgr.cpl : 1.0.0.8  
 AERTACap.dll : 1.0.32.7  
 AERTARen.dll : 1.0.32.3  
 FMAPO.dll : 40.59.0.0  
 MaxxAudioAPO.dll : 1.2.2.0  
 MaxxAudioAPO20.dll : 2.0.13.0  
 MaxxAudioEQ.dll : 5.9.7.0  
 RTCOMDLL.dll : 2.0.0.98  
 RtkAPO.dll : 11.0.6000.67

```

Readme.txt
RtkApoApi.dll : 1.0.0.4
RtkCoInst.dll : 1.0.2.6
RtkPgExt.dll : 6.0.6000.49
RtLCPAPI.dll : 1.0.1.9
SRSHP360.dll : 1.1.0.0
SRSTSHD.dll : 1.1.4.0
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.1.3.0
WavesLib.dll : 5.9.7.0
Vista driver for x64
RTKVHD64.sys : 6.0.1.5643
AERTSr64.exe : 1.0.64.2
RAVCpl64.exe : 1.0.0.198
RtkAudioService.exe : 1.0.0.14
RtlUpd64.exe : 2.7.0.9
SkyTel.exe : 2.0.2.0
vncutil.exe : 1.0.0.7
RTSnMg64.cpl : 1.0.0.8
AERTAC64.dll : 1.0.64.7
AERTAR64.dll : 1.0.64.3
FMAP064.dll : 40.59.0.0
MaxxAudioAP020.dll : 2.0.12.0
RCoInst64.dll : 1.0.2.6
RtCOMB4.dll : 2.0.0.98
RtCOMDLL.dll : 2.0.0.98
RtkApi64.dll : 1.0.0.4
RtkAPO64.dll : 11.0.6000.67
RtLCPAPI.dll : 1.0.1.9
RtPgEx64.dll : 6.0.6000.49
SRSHP64.dll : 1.1.0.0
SRSTSH64.dll : 1.1.4.0
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
-----
HDM Driver :
Vista x86:
RtHDM.V.sys : 6.0.1.5633
RtkUpd.exe : 2.7.0.9
RHDMExt.dll : 6.0.6000.48
RtkHDM.dll : 11.0.6000.66

Vista x64:
RtHDM.VX.sys : 6.0.1.5633
RtkUpd64.exe : 2.7.0.9
RHDMEx64.dll : 6.0.6000.48
RtkHDM64.dll : 11.0.6000.66

XP/2K x86:
RtHDM.sys : 5.10.0.5633
RtkUpd.exe : 2.7.0.9
XP/2K x64:
RtHDMX.sys : 5.10.0.5633
RtkUpd64.exe : 2.7.0.9

Driver Setup Program : 2.60

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

```

```

//=====
Driver Package R1.95
Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .
1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663,
ALC260, ALC262, ALC267, ALC268, ALC269, ALC272
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD,
ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

```

Readme.txt

6. Add/Fix

1.) Driver :

1. Customizations.
2. Fix encryption stream issue for ALC889.
3. Fix DRM issue.

```

Windows 2000/XP : -----
Windows 2000/XP :
RTKHDA64.sys      : 5.10.0.5636
RTKHDAUD.sys     : 5.10.0.5636
Alcmtr.exe       : 1.6.0.2
AlcWzrd.exe      : 1.1.0.36
Mccal.exe        : 1.1.1.8
RTHDCPL.exe     : 2.2.1.6
RTLCPPL.exe     : 1.0.1.65
RtlUpd64.exe    : 2.7.0.9
RtlUpd.exe       : 2.7.0.9
SkyTel.exe       : 2.0.2.0
SoundMan.exe    : 1.0.0.30
ALSndMgr.cpl    : 1.0.0.10
RTSndMgr.cpl    : 1.0.1.0
RTCOMDLL.dll    : 1.0.0.96
RtlCPAPI.dll    : 1.0.1.9
-----
Vista driver : -----
RTKVHDA.sys      : 6.0.1.5636
AERTSrv.exe      : 1.0.32.2
RtHDVCpl.exe     : 1.0.0.192
RtkAudioService.exe : 1.0.0.12
RtlUpd.exe       : 2.7.0.9
SkyTel.exe       : 2.0.2.0
vncutil.exe     : 1.0.0.5
RTSndMgr.cpl    : 1.0.0.8
AERTACap.dll    : 1.0.32.7
AERTARen.dll    : 1.0.32.3
FMAP0.dll       : 40.59.0.0
MaxxAudioAPO.dll : 1.2.2.0
MaxxAudioAPO20.dll : 2.0.13.0
MaxxAudioEQ.dll : 5.9.7.0
RTCOMDLL.dll    : 2.0.0.98
RtkAPO.dll      : 11.0.6000.66
RtkApoApi.dll   : 1.0.0.4
RtkCoInst.dll   : 1.0.2.5
RtkPgExt.dll    : 6.0.6000.48
RtlCPAPI.dll    : 1.0.1.9
SRSHP360.dll    : 1.1.0.0
SRSTSHD.dll     : 1.1.4.0
SRSTSXT.dll     : 3.2.0.0
SRSWOW.dll      : 1.1.3.0
WavesLib.dll    : 5.9.7.0
-----
Vista driver for x64
RTKVHD64.sys    : 6.0.1.5636
AERTSr64.exe    : 1.0.64.2
RAVCpl64.exe    : 1.0.0.192
RtkAudioService.exe : 1.0.0.12
RtlUpd64.exe    : 2.7.0.9
SkyTel.exe      : 2.0.2.0
vncutil.exe     : 1.0.0.5
RTSnMg64.cpl   : 1.0.0.8
AERTAC64.dll    : 1.0.64.7
AERTAR64.dll   : 1.0.64.3
FMAP064.dll    : 40.59.0.0
MaxxAudioAPO20.dll : 2.0.12.0
RCoInst64.dll  : 1.0.2.5
RtCOM64.dll     : 2.0.0.98
RTCOMDLL.dll   : 2.0.0.98
RtkApi64.dll   : 1.0.0.4
RtkAPO64.dll   : 11.0.6000.66
RtlCPAPI.dll   : 1.0.1.9

```

Readme.txt

```

RtPgEx64.dll           : 6.0.6000.48
SRSHp64.dll           : 1.1.0.0
SRSTSH64.dll          : 1.1.4.0
SRSTSX64.dll          : 3.2.0.0
SRSWOW64.dll          : 1.1.3.0
HDM Driver : -----
Vista x86:
RtHDM.V.sys           : 6.0.1.5612
RtkUpd.exe            : 2.7.0.9
RHDMExt.dll           : 6.0.6000.44
RtkHDM.dll            : 11.0.6000.63

Vista x64:
RtHDM.VX.sys          : 6.0.1.5612
RtkUpd64.exe          : 2.7.0.9
RHDMEx64.dll          : 6.0.6000.44
RtkHDM64.dll          : 11.0.6000.63

XP/2K x86:
RtHDM.sys             : 5.10.0.5612
RtkUpd.exe            : 2.7.0.9

XP/2K x64:
RtHDM.X.sys           : 5.10.0.5612
RtkUpd64.exe          : 2.7.0.9

Driver Setup Program  : 2.59

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

```

//=====

Driver Package R1.94

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/Wi nXP/Wi n2000/Wi n2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
  - 1.) Driver :
    1. Customizations.
    2. Zero recorded data for SPDIF-IN copy-protection stream under Vista.

```

Windows 2000/XP : -----
Windows 2000/XP :
RTKHDA64.sys           : 5.10.0.5628
RTKHDAUD.sys          : 5.10.0.5628
Alcmtr.exe            : 1.6.0.2
AlcWzrd.exe           : 1.1.0.36
McCal.exe             : 1.1.1.8
RTHDCPL.exe           : 2.2.1.3
RTLCPPL.exe           : 1.0.1.65
RtlUpd.exe            : 2.7.0.9
RtlUpd64.exe          : 2.7.0.9
SkyTel.exe            : 2.0.2.0
SoundMan.exe          : 1.0.0.30
ALSndMgr.cpl          : 1.0.0.10
RTSndMgr.cpl          : 1.0.1.0
RTCOMDLL.dll          : 1.0.0.96
RtlCPAPI.dll          : 1.0.1.9
Vista driver : -----
RTKVHDA.sys           : 6.0.1.5628
AERTSrv.exe           : 1.0.32.2
RtHDVCpl.exe          : 1.0.0.188

```



	Readme.txt	
RtkAudioService.exe	:	1.0.0.12
RtkSmbus.exe	:	1.0.0.2
RtlUpd.exe	:	2.7.0.9
SkyTel.exe	:	2.0.2.0
RTSnMgr.cpl	:	1.0.0.8
AERTACap.dll	:	1.0.32.7
AERTARen.dll	:	1.0.32.3
FMAP0.dll	:	40.59.0.0
MaxxAudioAPO.dll	:	1.2.2.0
MaxxAudioAPO20.dll	:	2.0.13.0
MaxxAudioEQ.dll	:	5.9.7.0
RTCOMDLL.dll	:	2.0.0.97
RtkAPO.dll	:	11.0.6000.65
RtkApoApi.dll	:	1.0.0.4
RtkCoInst.dll	:	1.0.2.3
RtkPgExt.dll	:	6.0.6000.47
RtlCPAPI.dll	:	1.0.1.9
SRSHP360.dll	:	1.1.0.0
SRSTSHD.dll	:	1.1.4.0
SRSTSXT.dll	:	3.2.0.0
SRSWOW.dll	:	1.1.3.0
WavesLib.dll	:	5.9.7.0
Vista driver for x64		
RTKVHD64.sys	:	6.0.1.5628
AERTSr64.exe	:	1.0.64.2
RAVCpl64.exe	:	1.0.0.188
RtkAudioService.exe	:	1.0.0.12
RtkSmbus.exe	:	1.0.0.2
RtlUpd64.exe	:	2.7.0.9
SkyTel.exe	:	2.0.2.0
RTSnMgr64.cpl	:	1.0.0.8
AERTAC64.dll	:	1.0.64.7
AERTAR64.dll	:	1.0.64.3
FMAP064.dll	:	40.59.0.0
MaxxAudioAPO20.dll	:	2.0.12.0
RCoInst64.dll	:	1.0.2.3
RtCOM64.dll	:	2.0.0.97
RTCOMDLL.dll	:	2.0.0.97
RtkApi64.dll	:	1.0.0.4
RtkAPO64.dll	:	11.0.6000.65
RtlCPAPI.dll	:	1.0.1.9
RtPgEx64.dll	:	6.0.6000.47
SRSHP64.dll	:	1.1.0.0
SRSTSH64.dll	:	1.1.4.0
SRSTSX64.dll	:	3.2.0.0
SRSWOW64.dll	:	1.1.3.0
HDMI Driver : -----		
Vista x86:		
RtHDMV.sys	:	6.0.1.5612
RtkUpd.exe	:	2.7.0.9
RHDMExt.dll	:	6.0.6000.44
RtkHDM.dll	:	11.0.6000.63
Vista x64:		
RtHDMVX.sys	:	6.0.1.5612
RtkUpd64.exe	:	2.7.0.9
RHDMEx64.dll	:	6.0.6000.44
RtkHDM64.dll	:	11.0.6000.63
XP/2K x86:		
RtHDM.sys	:	5.10.0.5612
RtkUpd.exe	:	2.7.0.9
XP/2K x64:		
RtHDMX.sys	:	5.10.0.5612
RtkUpd64.exe	:	2.7.0.9
Driver Setup Program	:	2.59

Readme.txt

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.93

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
  - 1.) Driver :
    1. Customizations.
  - 2.) Package :
    1. Small VGA mode should not be checked in silent installation .

Windows 2000/XP : -----

Windows 2000/XP :

RTKHDA64.sys	: 5.10.0.5624
RTKHDAUD.sys	: 5.10.0.5624
Alcmtr.exe	: 1.6.0.2
AlcWzrd.exe	: 1.1.0.36
McCal.exe	: 1.1.1.8
RTHDCPL.exe	: 2.2.1.1
RTLCPPL.exe	: 1.0.1.65
RtlUpd64.exe	: 2.7.0.9
RtlUpd.exe	: 2.7.0.9
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.30
ALSndMgr.cpl	: 1.0.0.10
RTSndMgr.cpl	: 1.0.1.0
RTCOMDLL.dll	: 1.0.0.96
RtlCPAPI.dll	: 1.0.1.9

Vista driver : -----

RTKVHDA.sys	: 6.0.1.5624
AERTSrv.exe	: 1.0.32.2
RtHDVCpl.exe	: 1.0.0.185
RtkAudioService.exe	: 1.0.0.12
RtkSmbus.exe	: 1.0.0.2
RtlUpd.exe	: 2.7.0.9
SkyTel.exe	: 2.0.2.0
RTSndMgr.cpl	: 1.0.0.7
AERTACap.dll	: 1.0.32.7
AERTARen.dll	: 1.0.32.3
FMAPO.dll	: 40.59.0.0
MaxxAudioAPO.dll	: 1.2.2.0
MaxxAudioAPO20.dll	: 2.0.13.0
MaxxAudioEQ.dll	: 5.9.7.0
RTCOMDLL.dll	: 2.0.0.97
RtkAPO.dll	: 11.0.6000.65
RtkApoApi.dll	: 1.0.0.4
RtkColnst.dll	: 1.0.2.3
RtkPgExt.dll	: 6.0.6000.46
RtlCPAPI.dll	: 1.0.1.9
SRSHP360.dll	: 1.1.0.0
SRSTSHD.dll	: 1.1.4.0
SRSTSXT.dll	: 3.2.0.0
SRSWOW.dll	: 1.1.3.0
WavesLib.dll	: 5.9.7.0
Vista driver for x64	
RTKVHD64.sys	: 6.0.1.5624
AERTSr64.exe	: 1.0.64.2
RAVCpl64.exe	: 1.0.0.185
RtkAudioService.exe	: 1.0.0.12

Readme.txt

```

RtkSmbus.exe           : 1.0.0.2
RtlUpd64.exe          : 2.7.0.9
SkyTel.exe            : 2.0.2.0
RTSnMg64.cpl         : 1.0.0.7
AERTAC64.dll         : 1.0.64.7
AERTAR64.dll         : 1.0.64.3
FMAP064.dll          : 40.59.0.0
MaxxAudioAP020.dll   : 2.0.12.0
RCoInst64.dll        : 1.0.2.3
RtCOMB4.dll          : 2.0.0.97
RTCOMDLL.dll         : 2.0.0.97
RtkApi64.dll         : 1.0.0.4
RtkAP064.dll         : 11.0.6000.65
RtlCPAPI.dll         : 1.0.1.9
RtPgEx64.dll         : 6.0.6000.46
SRSHp64.dll          : 1.1.0.0
SRSTSH64.dll         : 1.1.4.0
SRSTX64.dll          : 3.2.0.0
SRSW064.dll          : 1.1.3.0
HDM Driver : -----
Vista x86:
RtHDMV.sys           : 6.0.1.5612
RtkUpd.exe           : 2.7.0.9
RHDMExt.dll          : 6.0.6000.44
RtkHDM.dll           : 11.0.6000.63

Vista x64:
RtHDMVX.sys          : 6.0.1.5612
RtkUpd64.exe         : 2.7.0.9
RHDMEx64.dll         : 6.0.6000.44
RtkHDM64.dll         : 11.0.6000.63

XP/2K x86:
RtHDM.sys            : 5.10.0.5612
RtkUpd.exe           : 2.7.0.9

XP/2K x64:
RtHDMX.sys           : 5.10.0.5612
RtkUpd64.exe         : 2.7.0.9

Driver Setup Program : 2.59

```

Windows 2000/XP Operate on :  
 Microsoft High Definition Audio Driver Package - KB888111  
 Package file version (kb888111.exe) : 6.1.22.0  
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.92  
 Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/Wi nXP/Wi n2000/Wi n2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
  - 1.) Driver :
    1. Fix Stereo Mx issue with codec which support capless output pin.
    2. Customizations.

Windows 2000/XP : -----

```

Windows 2000/XP :
RTKHDA64.sys      : 5.10.0.5618
RTKHDAUD.sys      : 5.10.0.5618
McCal.exe         : 1.1.1.8
RTHDCPL.exe       : 2.2.1.0
RTLCPPL.exe       : 1.0.1.65

```

```

Readme.txt
RtlUpd64.exe           : 2.7.0.9
RtlUpd.exe             : 2.7.0.9
SkyTel.exe             : 2.0.2.0
SoundMan.exe          : 1.0.0.30
Alcmtr.exe            : 1.6.0.2
AlcWzrd.exe           : 1.1.0.36
RTSndMgr.cpl          : 1.0.1.0
ALSndMgr.cpl          : 1.0.0.10
RTCOMDLL.dll          : 1.0.0.96
RtlCPAPI.dll          : 1.0.1.9
Vista driver : -----
Vista driver for x86
RTKVHDA.sys           : 6.0.1.5618
AERTSrv.exe           : 1.0.32.2
RtHDVCpl.exe          : 1.0.0.183
RtkAudioService.exe  : 1.0.0.12
RtkSmbus.exe          : 1.0.0.2
RtlUpd.exe            : 2.7.0.9
SkyTel.exe            : 2.0.2.0
RTSndMgr.cpl          : 1.0.0.7
AERTACap.dll          : 1.0.32.7
AERTARen.dll          : 1.0.32.3
FMAP0.dll             : 40.58.0.0
MaxxAudioAP0.dll     : 1.2.2.0
MaxxAudioAP020.dll   : 2.0.13.0
MaxxAudioEQ.dll       : 5.9.7.0
RTCOMDLL.dll          : 2.0.0.97
RtkAP0.dll            : 11.0.6000.64
RtkApoApi.dll         : 1.0.0.4
RtkCoInst.dll         : 1.0.2.1
RtkPgExt.dll          : 6.0.6000.45
RtlCPAPI.dll          : 1.0.1.9
SRSH360.dll           : 1.0.1.0
SRSTSHD.dll           : 1.1.4.0
SRSTSXT.dll           : 3.2.0.0
SRSWOW.dll            : 1.1.3.0
WavesLib.dll          : 5.9.7.0
Vista driver for x64
RTKVHD64.sys          : 6.0.1.5618
AERTSr64.exe           : 1.0.64.2
RAVCpl64.exe          : 1.0.0.183
RtkAudioService.exe  : 1.0.0.12
RtkSmbus.exe          : 1.0.0.2
RtlUpd64.exe          : 2.7.0.9
SkyTel.exe            : 2.0.2.0
RTSnMg64.cpl          : 1.0.0.7
AERTAC64.dll          : 1.0.64.7
AERTAR64.dll          : 1.0.64.3
FMAP064.dll           : 40.58.0.0
MaxxAudioAP020.dll   : 2.0.12.0
RCoInst64.dll         : 1.0.2.1
RtCOMB4.dll           : 2.0.0.97
RTCOMDLL.dll          : 2.0.0.97
RtkApi64.dll          : 1.0.0.4
RtkAP064.dll          : 11.0.6000.64
RtlCPAPI.dll          : 1.0.1.9
RtPgEx64.dll          : 6.0.6000.45
SRSH64.dll            : 1.0.1.0
SRSTSH64.dll          : 1.1.4.0
SRSTSX64.dll          : 3.2.0.0
SRSWOW64.dll          : 1.1.3.0
HDMI Driver : -----
Vista x86:
RtHDMV.sys            : 6.0.1.5612
RtkUpd.exe            : 2.7.0.9
RHDM Ext.dll          : 6.0.6000.44
RtkHDM.dll            : 11.0.6000.63
Vista x64:

```

```

Readme.txt
RtHDMVX.sys : 6.0.1.5612
RtkUpd64.exe : 2.7.0.9
RHDME64.dll : 6.0.6000.44
RtkHDM64.dll : 11.0.6000.63

XP/2K x86:
RtHDM.sys : 5.10.0.5612
RtkUpd.exe : 2.7.0.9

XP/2K x64:
RtHDMX.sys : 5.10.0.5612
RtkUpd64.exe : 2.7.0.9

Driver Setup Program : 2.58

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

```

//=====

Driver Package R1.91

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
  - 1.) Driver :
    1. Fix DTM 1.2 KS topology test fail issue.
    2. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :

```

RTKHDA64.sys : 5.10.0.5605
RTKHDAUD.sys : 5.10.0.5605
McCal.exe : 1.1.1.8
RTHDCPL.exe : 2.2.0.2
RTLCPPL.exe : 1.0.1.65
RtlUpd64.exe : 2.7.0.9
RtlUpd.exe : 2.7.0.9
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.30
Alcmtr.exe : 1.6.0.2
AlcWzrd.exe : 1.1.0.36
RTSndMgr.cpl : 1.0.1.0
ALSndMgr.cpl : 1.0.0.10
RTCOMDLL.dll : 1.0.0.96
RtlCPAPI.dll : 1.0.1.9

```

Vista driver : -----

Vista driver for x86

```

RTKVHDA.sys : 6.0.1.5605
AERTSrv.exe : 1.0.32.2
RtHDVCpl.exe : 1.0.0.172
RtkAudioService.exe : 1.0.0.11
RtkSmbus.exe : 1.0.0.1
RtlUpd.exe : 2.7.0.9
SkyTel.exe : 2.0.2.0
RTSndMgr.cpl : 1.0.0.7
AERTACap.dll : 1.0.32.7
AERTARen.dll : 1.0.32.3
FMAPO.dll : 6.0.6000.16386
MaxxAudioAPO.dll : 1.2.2.0
MaxxAudioAPO20.dll : 2.0.12.0
MaxxAudioEQ.dll : 5.9.7.0
RTCOMDLL.dll : 2.0.0.96

```

Readme.txt

```

RtkAPO.dll : 11.0.6000.63
RtkApoApi.dll : 1.0.0.4
RtkCoInst.dll : 1.0.2.0
RtkPgExt.dll : 6.0.6000.42
RtLCPAPI.dll : 1.0.1.9
SRSHP360.dll : 1.0.1.0
SRSTSHD.dll : 1.1.4.0
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.1.3.0
WavesLib.dll : 5.9.7.0
Vista driver for x64
RTKVHD64.sys : 6.0.1.5605
AERTSr64.exe : 1.0.64.2
RAVCpl64.exe : 1.0.0.172
RtkAudioService.exe : 1.0.0.11
RtkSmbus.exe : 1.0.0.1
RtlUpd64.exe : 2.7.0.9
SkyTel.exe : 2.0.2.0
RTSnMg64.cpl : 1.0.0.7
AERTAC64.dll : 1.0.64.7
AERTAR64.dll : 1.0.64.3
FMAP064.dll : 6.0.6000.16386
MaxxAudioAPO20.dll : 2.0.12.0
RCoInst64.dll : 1.0.2.0
RtCOM64.dll : 2.0.0.96
RTCOMDLL.dll : 2.0.0.96
RtkApi64.dll : 1.0.0.4
RtkAPO64.dll : 11.0.6000.63
RtLCPAPI.dll : 1.0.1.9
RtPgEx64.dll : 6.0.6000.42
SRSHP64.dll : 1.0.1.0
SRSTSH64.dll : 1.1.4.0
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
HDMI Driver : -----
Vista x86:
RtHDMV.sys : 6.0.1.5602
RtkUpd.exe : 2.7.0.9
RHDMExt.dll : 6.0.6000.42
RtkHDM.dll : 11.0.6000.62

Vista x64:
RtHDMVX.sys : 6.0.1.5602
RtkUpd64.exe : 2.7.0.9
RHDMEx64.dll : 6.0.6000.42
RtkHDM64.dll : 11.0.6000.62

XP/2K x86:
RtHDM.sys : 5.10.0.5602
RtkUpd.exe : 2.7.0.9

XP/2K x64:
RtHDMX.sys : 5.10.0.5602
RtkUpd64.exe : 2.7.0.9

Driver Setup Program : 2.58

```

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111  
 Package file version (kb888111.exe) : 6.1.22.0  
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.90

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272
3. HDMI Device WHQL Support: ATI HDMI Devices

Readme.txt

4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
  - 1.) Driver :
    1. Support ALC663/ALC272.
    2. Support ForteMedia microphone effect APO feature.
    3. Customizations.

Windows 2000/XP : -----  
 Windows 2000/XP :  
 WDM driver for Win2000/WinXP : 5.10.0.5591  
 WDM driver for Winx64 : 5.10.0.5591  
 Realtek Soundman : 1.0.0.30  
 Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10  
 Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.1.0  
 Realtek Sound Effect Manager(RtlCpl) : 1.0.1.65  
 Realtek Sound Effect Manager(RTHDCPL) : 2.1.9.6  
 Alcwzrd.exe : 1.1.0.36  
 SkyTel.exe : 2.0.2.0

Vista driver : -----  
 Vista driver for x86 : 6.0.1.5591  
 RtHDVCpl.exe : 1.0.0.159  
 RtkAPO.dll : 11.0.6000.60  
 RtkPgExt.dll : 6.0.6000.40  
 RTCOMDLL.dll : 2.0.0.96  
 RtlCPAPI.dll : 1.0.1.8  
 RTSndMgr.cpl : 1.0.0.7  
 RtkCoInst.dll : 1.0.1.29  
 SRSTSXT.dll : 3.2.0.0  
 SRSWOW.dll : 1.1.3.0  
 SRSH360.dll : 1.0.1.0  
 SRSTSHD.dll : 1.1.4.0  
 RtkApoApi.dll : 1.0.0.3  
 Vista driver for x64 : 6.0.1.5591  
 RAVCpl64.exe : 1.0.0.159  
 RtkAPO64.dll : 11.0.6000.60  
 RtkPgEx64.dll : 6.0.6000.40  
 RTCOMDLL.dll : 2.0.0.96  
 RtlCPAPI.dll : 1.0.1.8  
 RTSnMg64.cpl : 1.0.0.7  
 RCoInst64.dll : 1.0.1.29  
 SRSTSX64.dll : 3.2.0.0  
 SRSWOW64.dll : 1.1.3.0  
 SRSH64.dll : 1.0.1.0  
 SRSTSH64.dll : 1.1.4.0  
 RtkApi64.dll : 1.0.0.3

HDM Driver : -----  
 Vista x64:  
 RtHDMVX.sys : 6.0.1.5575  
 RtkHDM64.dll : 6.0.6000.57  
 RHDME64.dll : 6.0.6000.39  
 Vista x86:  
 RtHDMV.sys : 6.0.1.5575  
 RtkHDM.dll : 6.0.6000.57  
 RHDMEExt.dll : 6.0.6000.39  
 XP/2K x64:  
 RtHDMX.sys : 5.10.0.5575  
 XP/2K x86:  
 RtHDM.sys : 5.10.0.5575

Driver Setup Program : 2.57

Windows 2000/XP Operate on :  
 Microsoft High Definition Audio Driver Package - KB888111  
 Package file version (kb888111.exe) : 6.1.22.0  
 Hdaudio.sys version : 5.10.00.5013

//=====  
 Driver Package R1.89

Readme.txt

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268, ALC269
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268, ALC269
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
  - 1.) Driver :
    1. Support "Event/Notification mode" under Vista.
    2. Fix Vista GUI issue when video adapter's resolution is low.
    3. Customizations.
  - 2.) Package :
    1. Uninstallation language selected by OS system .
    2. "Uninstall" word issue in Japanese language .

Windows 2000/XP : -----

Windows 2000/XP :  
 WDM driver for Win2000/WinXP : 5.10.0.5582  
 WDM driver for Winx64 : 5.10.0.5582  
 Realtek Soundman : 1.0.0.30  
 Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10  
 Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9  
 Realtek Sound Effect Manager(RtICpl) : 1.0.1.65  
 Realtek Sound Effect Manager(RTHDCPL) : 2.1.9.3  
 Alcwzrd.exe : 1.1.0.36  
 SkyTel.exe : 2.0.2.0

Vista driver : -----

Vista driver for x86 : 6.0.1.5582  
 RtHdVcpl.exe : 1.0.0.153  
 RtkAPO.dll : 11.0.6000.59  
 RtkPgExt.dll : 6.0.6000.40  
 RTCOMDLL.dll : 2.0.0.93  
 RtICPAPI.dll : 1.0.1.7  
 RTSndMgr.cpl : 1.0.0.7  
 RtkCoInst.dll : 1.0.1.27  
 SRSTSXT.dll : 3.2.0.0  
 SRSWOW.dll : 1.1.3.0  
 SRSHP360.dll : 1.0.1.0  
 SRSTSHD.dll : 1.1.4.0  
 RtkApoApi.dll : 1.0.0.3  
 Vista driver for x64 : 6.0.1.5582  
 RAVCpl64.exe : 1.0.0.153  
 RtkAPO64.dll : 11.0.6000.59  
 RtkPgEx64.dll : 6.0.6000.40  
 RTCOMDLL.dll : 2.0.0.93  
 RtICPAPI.dll : 1.0.1.7  
 RTSnMg64.cpl : 1.0.0.7  
 RCoInst64.dll : 1.0.1.27  
 SRSTSX64.dll : 3.2.0.0  
 SRSWOW64.dll : 1.1.3.0  
 SRSHP64.dll : 1.0.1.0  
 SRSTSH64.dll : 1.1.4.0  
 RtkApi64.dll : 1.0.0.3

HDM Driver : -----

Vista x64:  
 RtHDM VX.sys : 6.0.1.5575  
 RtkHDM64.dll : 6.0.6000.57  
 RHDME64.dll : 6.0.6000.39  
 Vista x86:  
 RtHDM V.sys : 6.0.1.5575  
 RtkHDM.dll : 6.0.6000.57  
 RHDME Ext.dll : 6.0.6000.39  
 XP/2K x64:  
 RtHDM X.sys : 5.10.0.5575  
 XP/2K x86:  
 RtHDM .sys : 5.10.0.5575



Readme.txt

Driver Setup Program : 2.56

Windows 2000/XP Operate on :  
Microsoft High Definition Audio Driver Package - KB888111  
Package file version (kb888111.exe) : 6.1.22.0  
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.88

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268, ALC269
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268, ALC269
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix

1.) Driver :

1. Fix BSOD issue for WLK 1.1 System-Common Scenario Stress With IO test and System-Disable Enable With IO test under XP.
2. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :

WDM driver for Win2000/WinXP : 5.10.0.5574  
WDM driver for Winx64 : 5.10.0.5574  
Realtek Soundman : 1.0.0.30  
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10  
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9  
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.65  
Realtek Sound Effect Manager(RTHDCPL) : 2.1.9.1  
Alcwzrd.exe : 1.1.0.36  
SkyTel.exe : 2.0.2.0

Vista driver : -----

Vista driver for x86 : 6.0.1.5574  
RtHdVCpl.exe : 1.0.0.145  
RtkAPO.dll : 11.0.6000.58  
RtkPgExt.dll : 6.0.6000.38  
RTCOMDLL.dll : 2.0.0.90  
RtlCPAPI.dll : 1.0.1.7  
RTSndMgr.cpl : 1.0.0.7  
RtkCoInst.dll : 1.0.1.25  
SRSTSXT.dll : 3.2.0.0  
SRSWOW.dll : 1.1.3.0  
SRSH360.dll : 1.0.1.0  
SRSTSHD.dll : 1.1.4.0  
RtkApoApi.dll : 1.0.0.3  
Vista driver for x64 : 6.0.1.5574  
RAVCpl64.exe : 1.0.0.145  
RtkAPO64.dll : 11.0.6000.58  
RtkPgEx64.dll : 6.0.6000.38  
RTCOMDLL.dll : 2.0.0.90  
RtlCPAPI.dll : 1.0.1.7  
RTSnMg64.cpl : 1.0.0.7  
RCoInst64.dll : 1.0.1.25  
SRSTX64.dll : 3.2.0.0  
SRSWOW64.dll : 1.1.3.0  
SRSH64.dll : 1.0.1.0  
SRSTSH64.dll : 1.1.4.0  
RtkApi64.dll : 1.0.0.3

HDM Driver : -----

Vista x64:  
RtHDMVX.sys : 6.0.1.5413  
RtkHDM64.dll : 6.0.6000.37  
RHDME64.dll : 6.0.6000.25  
Vista x86:  
RtHDMV.sys : 6.0.1.5413

```

Readme.txt
RtkHDM.dll : 6.0.6000.37
RHDMExt.dll : 6.0.6000.25
XP/2K x64:
RtHDMX.sys : 5.10.0.5413
XP/2K x86:
RtHDM.sys : 5.10.0.5413

Driver Setup Program : 2.55

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013
//=====
Driver Package R1.87
Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .
1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC260,
ALC262, ALC267, ALC268, ALC269
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD,
ALC660, ALC662, ALC260, ALC262, ALC267, ALC268, ALC269
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
1.) Driver :
1. Fix recording issue for ALC269.
2. Customizations.

Windows 2000/XP : -----
Windows 2000/XP :
WDM driver for Win2000/WinXP : 5.10.0.5567
WDM driver for Winx64 : 5.10.0.5567
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.65
Realtek Sound Effect Manager(RTHDCPL) : 2.1.8.9
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 2.0.2.0
Vista driver : -----
Vista driver for x86 : 6.0.1.5567
RtHDVCpl.exe : 1.0.0.139
RtkAPO.dll : 11.0.6000.56
RtkPgExt.dll : 6.0.6000.35
RTCOMDLL.dll : 2.0.0.89
RtlCPAPI.dll : 1.0.1.7
RTSndMgr.cpl : 1.0.0.7
RtkCoInst.dll : 1.0.1.25
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.1.3.0
SRSH360.dll : 1.0.1.0
SRSTSHD.dll : 1.1.4.0
RtkApoApi.dll : 1.0.0.3
Vista driver for x64 : 6.0.1.5567
RAVCpl64.exe : 1.0.0.139
RtkAPO64.dll : 11.0.6000.56
RtPgEx64.dll : 6.0.6000.35
RTCOMDLL.dll : 2.0.0.89
RtlCPAPI.dll : 1.0.1.7
RTSnMg64.cpl : 1.0.0.7
RCoInst64.dll : 1.0.1.25
SRSTX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
SRSH64.dll : 1.0.1.0
SRSTSH64.dll : 1.1.4.0
RtkApi64.dll : 1.0.0.3
HDM Driver : -----
Vista x64:

```

Readme.txt

RtHDMVX.sys : 6.0.1.5413  
 RtkHDM64.dll : 6.0.6000.37  
 RHDME64.dll : 6.0.6000.25  
 Vista x86:  
 RtHDMV.sys : 6.0.1.5413  
 RtkHDM.dll : 6.0.6000.37  
 RHDMEExt.dll : 6.0.6000.25  
 XP/2K x64:  
 RtHDMX.sys : 5.10.0.5413  
 XP/2K x86:  
 RtHDM.sys : 5.10.0.5413  
 Driver Setup Program : 2.54

Windows 2000/XP Operate on :  
 Microsoft High Definition Audio Driver Package - KB888111  
 Package file version (kb888111.exe) : 6.1.22.0  
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.86

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/Wi nXP/Wi n2000/Wi n2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268, ALC269
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268, ALC269
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix

1.) Driver :

1. Fix the issue that SPDIF-out device broadcast 2nd output device's stream when turn on multi-streaming under Windows XP.
2. Indexed DRC file supported.
3. Customizations.

2.) Package :

1. Installer failed code.
2. Copy .dat file rule.

Windows 2000/XP : -----

Windows 2000/XP :  
 WDM driver for Wi n2000/Wi nXP : 5.10.0.5559  
 WDM driver for Wi nX64 : 5.10.0.5559  
 Realtek Soundman : 1.0.0.30  
 Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10  
 Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9  
 Realtek Sound Effect Manager(RtlCpl) : 1.0.1.65  
 Realtek Sound Effect Manager(RTHDCPL) : 2.1.8.7  
 Alcwzrd.exe : 1.1.0.36  
 SkyTel.exe : 2.0.2.0

Vista driver : -----

Vista driver for x86 : 6.0.1.5559  
 RtHDVCpl.exe : 1.0.0.132  
 RtkAPO.dll : 11.0.6000.54  
 RtkPgExt.dll : 6.0.6000.35  
 RTCOMDLL.dll : 2.0.0.87  
 RtlCPAPI.dll : 1.0.1.7  
 RTSndMgr.cpl : 1.0.0.7  
 RtkColnst.dll : 1.0.1.25  
 SRSTSXT.dll : 3.2.0.0  
 SRSWOW.dll : 1.1.3.0  
 SRSHP360.dll : 1.0.1.0  
 SRSTSHD.dll : 1.1.4.0  
 RtkApoApi.dll : 1.0.0.3  
 Vista driver for x64 : 6.0.1.5559  
 RAVCpl64.exe : 1.0.0.132  
 RtkAPO64.dll : 11.0.6000.54  
 RtpgEx64.dll : 6.0.6000.35  
 RTCOMDLL.dll : 2.0.0.87

```

Readme.txt
RtLCPAPI.dll : 1.0.1.7
RTSnMg64.cpl : 1.0.0.7
RCoInst64.dll : 1.0.1.25
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
SRSHP64.dll : 1.0.1.0
SRSTSH64.dll : 1.1.4.0
RtkApi64.dll : 1.0.0.3
HDMI Driver : -----
Vista x64:
RtHDMVX.sys : 6.0.1.5413
RtkHDM64.dll : 6.0.6000.37
RHDMeX64.dll : 6.0.6000.25
Vista x86:
RtHDMV.sys : 6.0.1.5413
RtkHDM.dll : 6.0.6000.37
RHDMeX.dll : 6.0.6000.25
XP/2K x64:
RtHDMX.sys : 5.10.0.5413
XP/2K x86:
RtHDM.sys : 5.10.0.5413

Driver Setup Program : 2.52

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013
//=====
Driver Package R1.85
Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/Wi nXP/Wi n2000/Wi n2003 .
1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260,
ALC262, ALC267, ALC268, ALC269
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660,
ALC662, ALC260, ALC262, ALC267, ALC268, ALC269
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft Wi ndowsXP, Wi ndows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
1.) Driver :
1. Fix PC-Beep mute issue for ALC268/ALC267.
2. Fix the potential risk that system-thread is still running when driver is already unloaded
under Vista.
3. Customizations.

Windows 2000/XP : -----
Windows 2000/XP :
WDM driver for Wi n2000/Wi nXP : 5.10.0.5548
WDM driver for Wi nx64 : 5.10.0.5548
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtLCpl) : 1.0.1.65
Realtek Sound Effect Manager(RTHDCPL) : 2.1.8.6
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 2.0.2.0
Vista driver : -----
Vista driver for x86 : 6.0.1.5548
RtHDVCpl.exe : 1.0.0.128
RtkAPO.dll : 11.0.6000.51
RtkPgExt.dll : 6.0.6000.33
RTCOMDLL.dll : 2.0.0.86
RtLCPAPI.dll : 1.0.1.7
RTSndMgr.cpl : 1.0.0.7
RtkCoInst.dll : 1.0.1.25
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.1.3.0
SRSHP360.dll : 1.0.1.0

```

```

Readme.txt
SRSTSHD.dll : 1.1.4.0
RtkApoApi.dll : 1.0.0.3
Vista driver for x64 : 6.0.1.5548
RAVCpl64.exe : 1.0.0.128
RtkAPO64.dll : 11.0.6000.51
RtPgEx64.dll : 6.0.6000.33
RTCOMDLL.dll : 2.0.0.86
RtlCPAPI.dll : 1.0.1.7
RTSnMg64.cpl : 1.0.0.7
RCoInst64.dll : 1.0.1.25
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
SRSHP64.dll : 1.0.1.0
SRSTSH64.dll : 1.1.4.0
RtkApi64.dll : 1.0.0.3
HDM Driver : -----
Vista x64:
RtHDM VX.sys : 6.0.1.5413
RtkHDM64.dll : 6.0.6000.37
RHDMEx64.dll : 6.0.6000.25
Vista x86:
RtHDM V.sys : 6.0.1.5413
RtkHDM.dll : 6.0.6000.37
RHDM Ext.dll : 6.0.6000.25
XP/2K x64:
RtHDM X.sys : 5.10.0.5413
XP/2K x86:
RtHDM.sys : 5.10.0.5413
Driver Setup Program : 2.51
Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013
//=====
Driver Package R1.84
Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .
1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260,
ALC262, ALC267, ALC268, ALC269
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660,
ALC662, ALC260, ALC262, ALC267, ALC268, ALC269
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
1.) Driver :
1. Fix potential risk for re-direct headphone mode under Vista.
2. Customizations.
Windows 2000/XP : -----
Windows 2000/XP :
WDM driver for Win2000/WinXP : 5.10.0.5532
WDM driver for Winx64 : 5.10.0.5532
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.65
Realtek Sound Effect Manager(RTHDCPL) : 2.1.8.2
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 2.0.2.0
Vista driver : -----
Vista driver for x86 : 6.0.1.5532
RtHDVCpl.exe : 1.0.0.116
RtkAPO.dll : 11.0.6000.48
RtkPgExt.dll : 6.0.6000.31
RTCOMDLL.dll : 2.0.0.86
RtlCPAPI.dll : 1.0.1.6

```

```

Readme.txt
RTSndMgr. cpl : 1.0.0.7
RtkCoInst. dll : 1.0.1.18
SRSTSXT. dll : 3.2.0.0
SRSWOW. dll : 1.1.3.0
SRSHP360. dll : 1.0.1.0
SRSTSHD. dll : 1.1.4.0
RtkApoApi. dll : 1.0.0.2
Vista driver for x64 : 6.0.1.5532
RAVCpl64. exe : 1.0.0.116
RtkAPO64. dll : 11.0.6000.48
RtPgEx64. dll : 6.0.6000.31
RTCOMDLL. dll : 2.0.0.86
RtLCPAPI. dll : 1.0.1.6
RTSnMg64. cpl : 1.0.0.7
RCoInst64. dll : 1.0.1.18
SRSTSX64. dll : 3.2.0.0
SRSWOW64. dll : 1.1.3.0
SRSHP64. dll : 1.0.1.0
SRSTSH64. dll : 1.1.4.0
RtkApi64. dll : 1.0.0.2
HDM Driver : -----
Vista x64:
RtHDM VX. sys : 6.0.1.5413
RtkHDM64. dll : 6.0.6000.37
RHDME64. dll : 6.0.6000.25
Vista x86:
RtHDM V. sys : 6.0.1.5413
RtkHDM. dll : 6.0.6000.37
RHDME Ext. dll : 6.0.6000.25
XP/2K x64:
RtHDM X. sys : 5.10.0.5413
XP/2K x86:
RtHDM. sys : 5.10.0.5413

Driver Setup Program : 2.51

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudiobus.sys version : 5.10.00.5013
//=====
Driver Package R1.83
Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/Wi nXP/Wi n2000/Wi n2003 .
1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260,
ALC262, ALC267, ALC268, ALC269
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660,
ALC662, ALC260, ALC262, ALC267, ALC268, ALC269
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft Wi ndowsXP, Wi dnows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
1.) Driver :
1. Support ALC269.
2. Customizations.
3. Turn on amplifier mask control for ALC885.
4. Fix volume issue when turn on "Limited Output" feature under Wi ndows XP.

Wi ndows 2000/XP : -----
Wi ndows 2000/XP :
WDM driver for Wi n2000/Wi nXP : 5.10.0.5523
WDM driver for Wi nx64 : 5.10.0.5523
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr. cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr. cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtLCP) : 1.0.1.65
Realtek Sound Effect Manager(RTHDCPL) : 2.1.7.7
Alcwzrd. exe : 1.1.0.36
SkyTel. exe : 2.0.2.0
Vista driver : -----

```

Readme.txt

```

Vista driver for x86
RtHdVCpl.exe : 6.0.1.5523
RtkAPO.dll : 1.0.0.112
RtkPgExt.dll : 11.0.6000.48
RTCOMDLL.dll : 6.0.6000.31
RtLCPAPI.dll : 2.0.0.85
RTSndMgr.cpl : 1.0.1.6
RtkCoInst.dll : 1.0.0.7
SRSTSXT.dll : 1.0.1.15
SRSWOW.dll : 3.2.0.0
SRSH360.dll : 1.1.3.0
SRSTSHD.dll : 1.0.1.0
RtkApoApi.dll : 1.1.4.0
Vista driver for x64 : 1.0.0.2
RAVCpl64.exe : 6.0.1.5523
RtkAPO64.dll : 1.0.0.112
RtkPgExt64.dll : 11.0.6000.48
RTCOMDLL64.dll : 6.0.6000.31
RtLCPAPI64.dll : 2.0.0.85
RTSnMgr64.cpl : 1.0.1.6
RCoInst64.dll : 1.0.0.7
SRSTSX64.dll : 1.0.1.15
SRSWOW64.dll : 3.2.0.0
SRSH64.dll : 1.1.3.0
SRSTSH64.dll : 1.0.1.0
RtkApi64.dll : 1.1.4.0
HDM Driver : -----
Vista x64:
RtHDMVX.sys : 6.0.1.5413
RtkHDM64.dll : 6.0.6000.37
RHDME64.dll : 6.0.6000.25
Vista x86:
RtHDMV.sys : 6.0.1.5413
RtkHDM.dll : 6.0.6000.37
RHDMEExt.dll : 6.0.6000.25
XP/2K x64:
RtHDMX.sys : 5.10.0.5413
XP/2K x86:
RtHDM.sys : 5.10.0.5413

Driver Setup Program : 2.51

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013
//=====
Driver Package R1.82
Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/Wi nXP/Wi n2000/Wi n2003 .
1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260,
ALC262, ALC267, ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660,
ALC662, ALC260, ALC262, ALC267, ALC268
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Wi dnows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
1.) Driver :
1. Support IMniportWaveRTStreamNotification interface under Vista.
2. Customizations.
3. Fix bug for the specific customer.
2.) Installer :
1. Add silent uninstall option .

Windows 2000/XP : -----
Windows 2000/XP :
WDM driver for Wi n2000/Wi nXP : 5.10.0.5512
WDM driver for Wi nx64 : 5.10.0.5512
Realtek Soundman : 1.0.0.30

```

```

Readme.txt
Realtek Sound Effect Manager(ALSndMgr. cpl)      : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr. cpl)     : 1.0.0.9
Realtek Sound Effect Manager(RtlCpl)           : 1.0.1.65
Realtek Sound Effect Manager(RTHDCPL)         : 2.1.7.1
Alcwzrd.exe                                    : 1.1.0.36
SkyTel.exe                                     : 2.0.1.21
Vista driver : -----
Vista driver for x86                          : 6.0.1.5512
RtHDVCpl.exe                                  : 1.0.0.106
RtkAPO.dll                                    : 11.0.6000.48
RtkPgExt.dll                                  : 6.0.6000.31
RTCOMDLL.dll                                  : 2.0.0.83
RtlCPAPI.dll                                  : 1.0.1.6
RTSndMgr.cpl                                  : 1.0.0.7
RtkColInst.dll                                : 1.0.1.13
SRSTSXT.dll                                   : 3.2.0.0
SRSWOW.dll                                    : 1.1.3.0
SRSHP360.dll                                  : 1.0.1.0
SRSTSHD.dll                                   : 1.1.4.0
RtkApoApi.dll                                 : 1.0.0.2
Vista driver for x64                          : 6.0.1.5512
RAVCpl64.exe                                  : 1.0.0.106
RtkAPO64.dll                                  : 11.0.6000.48
RtPgEx64.dll                                  : 6.0.6000.31
RTCOMDLL.dll                                  : 2.0.0.83
RtlCPAPI.dll                                  : 1.0.1.6
RTSnMg64.cpl                                  : 1.0.0.7
RCoInst64.dll                                 : 1.0.1.13
SRSTSX64.dll                                  : 3.2.0.0
SRSWOW64.dll                                  : 1.1.3.0
SRSHP64.dll                                   : 1.0.1.0
SRSTSH64.dll                                  : 1.1.4.0
RtkApi64.dll                                  : 1.0.0.2
HDM Driver : -----
Vista x64:
RtHDMVX.sys                                   : 6.0.1.5413
RtkHDM64.dll                                  : 6.0.6000.37
RHDMEx64.dll                                  : 6.0.6000.25
Vista x86:
RtHDMV.sys                                    : 6.0.1.5413
RtkHDM.dll                                    : 6.0.6000.37
RHDMExt.dll                                   : 6.0.6000.25
XP/2K x64:
RtHDMX.sys                                    : 5.10.0.5413
XP/2K x86:
RtHDM.sys                                     : 5.10.0.5413
Driver Setup Program                          : 2.51

```

Windows 2000/XP Operate on :  
Microsoft High Definition Audio Driver Package - KB888111  
Package file version (kb888111.exe) : 6.1.22.0  
Hdaudio.sys version : 5.10.00.5013

```

//=====
Driver Package R1.81
Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .
1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260,
ALC262, ALC267, ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660,
ALC662, ALC260, ALC262, ALC267, ALC268
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
1.) Driver :
1. Support real 2.1 output capability under Vista.
2. Improve Doppler effect for XP driver.
3. Fix Vista DTM topology testing issue.
4. Fix dead lock issue when more than 3 jacks set as headphone output under XP.

```



- 2.) Installer :  
 1. VSS event error for InstallShield .

```

Windows 2000/XP : -----
Windows 2000/XP :
WDM driver for Win2000/WinXP : 5.10.0.5506
WDM driver for Winx64 : 5.10.0.5506
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.65
Realtek Sound Effect Manager(RTHDCPL) : 2.1.7.0
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 2.0.1.21
Vista driver : -----
Vista driver for x86 : 6.0.1.5506
RtHDVCpl.exe : 1.0.0.103
RtkAPO.dll : 11.0.6000.48
RtkPgExt.dll : 6.0.6000.31
RTCOMDLL.dll : 2.0.0.82
RtlCPAPI.dll : 1.0.1.6
RTSndMgr.cpl : 1.0.0.6
RtkCoInst.dll : 1.0.1.13
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.1.3.0
SRSHP360.dll : 1.0.1.0
SRSTSHD.dll : 1.1.4.0
RtkApoApi.dll : 1.0.0.2
Vista driver for x64 : 6.0.1.5506
RAVCpl64.exe : 1.0.0.103
RtkAPO64.dll : 11.0.6000.48
RtPgEx64.dll : 6.0.6000.31
RTCOMDLL.dll : 2.0.0.82
RtlCPAPI.dll : 1.0.1.6
RTSnMg64.cpl : 1.0.0.6
RCoInst64.dll : 1.0.1.13
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
SRSHP64.dll : 1.0.1.0
SRSTSH64.dll : 1.1.4.0
RtkApi64.dll : 1.0.0.2
HDMI Driver : -----
Vista x64:
RtHDMVX.sys : 6.0.1.5413
RtkHDM64.dll : 6.0.6000.37
RHDMEx64.dll : 6.0.6000.25
Vista x86:
RtHDMV.sys : 6.0.1.5413
RtkHDM.dll : 6.0.6000.37
RHDMExt.dll : 6.0.6000.25
XP/2K x64:
RtHDMX.sys : 5.10.0.5413
XP/2K x86:
RtHDM.sys : 5.10.0.5413

Driver Setup Program : 2.50
    
```

Windows 2000/XP Operate on :  
 Microsoft High Definition Audio Driver Package - KB888111  
 Package file version (kb888111.exe) : 6.1.22.0  
 Hdaudio.sys version : 5.10.00.5013

```

//=====
Driver Package R1.80
Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .
1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260,
ALC262, ALC267, ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660,
ALC662, ALC260, ALC262, ALC267, ALC268
3. HDMI Device WHQL Support: ATI HDMI Devices
    
```

Readme.txt

4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
  - 1.) Driver :
    1. Customizations.
    2. Add new feature to smooth gap between 2 different output stream under Vista.
  - 2.) Installer :
    1. "Program Compatibility Assistant" issue for InstallShield 11.5 .
    2. VSR stop setting .

```
Windows 2000/XP : -----
Windows 2000/XP :
WDM driver for Win2000/WinXP : 5.10.0.5497
WDM driver for Winx64 : 5.10.0.5497
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(Rt1Cpl) : 1.0.1.65
Realtek Sound Effect Manager(RTHDCPL) : 2.1.6.7
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 2.0.1.21
Vista driver : -----
Vista driver for x86 : 6.0.1.5497
RtHdVCpl.exe : 1.0.0.99
RtkAPO.dll : 11.0.6000.45
RtkPgExt.dll : 6.0.6000.30
RTCOMDLL.dll : 2.0.0.80
Rt1CPAPI.dll : 1.0.1.6
RTSndMgr.cpl : 1.0.0.6
RtkCoInst.dll : 1.0.1.10
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.1.3.0
SRSH360.dll : 1.0.1.0
SRSTSHD.dll : 1.1.4.0
RtkApoApi.dll : 1.0.0.2
Vista driver for x64 : 6.0.1.5497
RAVCpl64.exe : 1.0.0.99
RtkAPO64.dll : 11.0.6000.45
RtPgEx64.dll : 6.0.6000.30
RTCOMDLL.dll : 2.0.0.80
Rt1CPAPI.dll : 1.0.1.6
RTSnMg64.cpl : 1.0.0.6
RCoInst64.dll : 1.0.1.10
SRSTX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
SRSH64.dll : 1.0.1.0
SRSTSH64.dll : 1.1.4.0
RtkApi64.dll : 1.0.0.2
HDMI Driver : -----
Vista x64:
RtHDMVX.sys : 6.0.1.5413
RtkHDM64.dll : 6.0.6000.37
RHDME64.dll : 6.0.6000.25
Vista x86:
RtHDMV.sys : 6.0.1.5413
RtkHDM.dll : 6.0.6000.37
RHDMEExt.dll : 6.0.6000.25
XP/2K x64:
RtHDMX.sys : 5.10.0.5413
XP/2K x86:
RtHDM.sys : 5.10.0.5413
Driver Setup Program : 2.49
Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013
//=====
```

Readme.txt

Driver Package R1.79

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix

1.) Driver :

1. Customizations.
2. Fix potential risk from dividing by zero while the input signal power approach zero under

Windows XP.

3. Support digital mic software boost for ALC888.

2.) Installer :

1. Remove Realtek registry key in upgrade mode.
2. Change MCE GUI installation procedure for Windows Vista by Microsoft requirement.
3. Add install procedure for VSR feature.

Windows 2000/XP : -----

Windows 2000/XP :

WDM driver for Win2000/WinXP : 5.10.0.5490  
WDM driver for Winx64 : 5.10.0.5490  
Realtek Soundman : 1.0.0.30  
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10  
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9  
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.65  
Realtek Sound Effect Manager(RTHDCPL) : 2.1.6.2  
Alcwzrd.exe : 1.1.0.36  
SkyTel.exe : 2.0.1.20

Vista driver : -----

Vista driver for x86 : 6.0.1.5490  
RtHDVCpl.exe : 1.0.0.96  
RtkAPO.dll : 11.0.6000.45  
RtkPgExt.dll : 6.0.6000.30  
RTCOMDLL.dll : 2.0.0.79  
RtlCPAPI.dll : 1.0.1.6  
RTSndMgr.cpl : 1.0.0.6  
RtkCoInst.dll : 1.0.1.9  
SRSTSXT.dll : 3.2.0.0  
SRSWOW.dll : 1.1.3.0  
SRSHP360.dll : 1.0.1.0  
SRSTSHD.dll : 1.1.4.0  
RtkApoApi.dll : 1.0.0.2  
Vista driver for x64 : 6.0.1.5490  
RAVCpl64.exe : 1.0.0.96  
RtkAPO64.dll : 11.0.6000.45  
RtkPgEx64.dll : 6.0.6000.30  
RTCOMDLL.dll : 2.0.0.79  
RtlCPAPI.dll : 1.0.1.6  
RTSnMg64.cpl : 1.0.0.6  
RCoInst64.dll : 1.0.1.9  
SRSTX64.dll : 3.2.0.0  
SRSWOW64.dll : 1.1.3.0  
SRSHP64.dll : 1.0.1.0  
SRSTSH64.dll : 1.1.4.0  
RtkApi64.dll : 1.0.0.2

HDM Driver : -----

Vista x64:  
RtHDMVX.sys : 6.0.1.5413  
RtkHDM64.dll : 6.0.6000.37  
RHDMEx64.dll : 6.0.6000.25  
Vista x86:  
RtHDMV.sys : 6.0.1.5413  
RtkHDM.dll : 6.0.6000.37  
RHDMExt.dll : 6.0.6000.25  
XP/2K x64:  
RtHDMX.sys : 5.10.0.5413

Readme.txt

XP/2K x86:  
RtHDM.sys : 5.10.0.5413

Driver Setup Program : 2.47

Windows 2000/XP Operate on :  
Microsoft High Definition Audio Driver Package - KB888111  
Package file version (kb888111.exe) : 6.1.22.0  
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.78

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
  - 1.) Customization.

Windows 2000/XP : -----

Windows 2000/XP :  
WDM driver for Win2000/WinXP : 5.10.0.5485  
WDM driver for Winx64 : 5.10.0.5485  
Realtek Soundman : 1.0.0.30  
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10  
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9  
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.65  
Realtek Sound Effect Manager(RTHDCPL) : 2.1.6.0  
Alcwzrd.exe : 1.1.0.36  
SkyTel.exe : 2.0.1.20

Vista driver : -----

Vista driver for x86 : 6.0.1.5485  
RtHdVcpl.exe : 1.0.0.92  
RtkAPO.dll : 11.0.6000.45  
RtkPgExt.dll : 6.0.6000.29  
RTCOMDLL.dll : 2.0.0.79  
RtlCPAPI.dll : 1.0.1.6  
RTSndMgr.cpl : 1.0.0.6  
RtkCoInst.dll : 1.0.1.8  
SRSTSXT.dll : 3.2.0.0  
SRSWOW.dll : 1.1.3.0  
SRSH360.dll : 1.0.1.0  
SRSTSHD.dll : 1.1.4.0  
RtkApoApi.dll : 1.0.0.2  
Vista driver for x64 : 6.0.1.5485  
RAVCpl64.exe : 1.0.0.92  
RtkAPO64.dll : 11.0.6000.45  
RtPgEx64.dll : 6.0.6000.29  
RTCOMDLL.dll : 2.0.0.79  
RtlCPAPI.dll : 1.0.1.6  
RTSnMg64.cpl : 1.0.0.6  
RCoInst64.dll : 1.0.1.8  
SRSTSX64.dll : 3.2.0.0  
SRSWOW64.dll : 1.1.3.0  
SRSH64.dll : 1.0.1.0  
SRSTSH64.dll : 1.1.4.0  
RtkApi64.dll : 1.0.0.2

HDM Driver : -----

Vista x64:  
RtHDM.VX.sys : 6.0.1.5413  
RtkHDM64.dll : 6.0.6000.37  
RHDMEx64.dll : 6.0.6000.25  
Vista x86:  
RtHDM.V.sys : 6.0.1.5413  
RtkHDM.dll : 6.0.6000.37  
RHDMExt.dll : 6.0.6000.25

Readme.txt

XP/2K x64:  
 RtHDMX.sys : 5.10.0.5413  
 XP/2K x86:  
 RtHDM.sys : 5.10.0.5413  
 Driver Setup Program : 2.45

Windows 2000/XP Operate on :  
 Microsoft High Definition Audio Driver Package - KB888111  
 Package file version (kb888111.exe) : 6.1.22.0  
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.77

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
  - 1.) Customization.
  - 2.) Uninstall procedure for checking Rtlupd.exe file .

Windows 2000/XP : -----

Windows 2000/XP :  
 WDM driver for Win2000/WinXP : 5.10.0.5480  
 WDM driver for Winx64 : 5.10.0.5480  
 Realtek Soundman : 1.0.0.30  
 Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10  
 Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9  
 Realtek Sound Effect Manager(RtlCpl) : 1.0.1.65  
 Realtek Sound Effect Manager(RTHDCPL) : 2.1.5.7  
 Alcwzrd.exe : 1.1.0.36  
 SkyTel.exe : 2.0.1.20

Vista driver : -----

Vista driver for x86 :  
 RtHDVCpl.exe : 1.0.0.90  
 RtkAPO.dll : 11.0.6000.45  
 RtkPgExt.dll : 6.0.6000.29  
 RTCOMDLL.dll : 2.0.0.79  
 RtlCPAPI.dll : 1.0.1.6  
 RTSndMgr.cpl : 1.0.0.6  
 RtkCoInst.dll : 1.0.1.7  
 SRSTSXT.dll : 3.2.0.0  
 SRSWOW.dll : 1.1.3.0  
 SRSH360.dll : 1.0.1.0  
 SRSTSHD.dll : 1.1.4.0  
 RtkApoApi.dll : 1.0.0.2  
 Vista driver for x64 :  
 RAVCpl64.exe : 1.0.0.90  
 RtkAPO64.dll : 11.0.6000.45  
 RtkPgEx64.dll : 6.0.6000.29  
 RTCOMDLL.dll : 2.0.0.79  
 RtlCPAPI.dll : 1.0.1.6  
 RTSnMg64.cpl : 1.0.0.6  
 RCoInst64.dll : 1.0.1.7  
 SRSTSX64.dll : 3.2.0.0  
 SRSWOW64.dll : 1.1.3.0  
 SRSH64.dll : 1.0.1.0  
 SRSTSH64.dll : 1.1.4.0  
 RtkApi64.dll : 1.0.0.2

HDM Driver : -----

Vista x64:  
 RtHDMVX.sys : 6.0.1.5413  
 RtkHDM64.dll : 6.0.6000.37  
 RHDME64.dll : 6.0.6000.25  
 Vista x86:

```

Readme.txt
RtHDMV.sys : 6.0.1.5413
RtkHDM.dll : 6.0.6000.37
RHDMEExt.dll : 6.0.6000.25
XP/2K x64:
RtHDMX.sys : 5.10.0.5413
XP/2K x86:
RtHDM.sys : 5.10.0.5413

Driver Setup Program : 2.45

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013
//=====
Driver Package R1.76
Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/Wi nXP/Wi n2000/Wi n2003 .
1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260,
ALC262, ALC267, ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660,
ALC662, ALC260, ALC262, ALC267, ALC268
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
1.) Customization.
2.) Installer package language wrong for Japanese translation . ( Upgrade operation for Vista )

Windows 2000/XP : -----
Windows 2000/XP :
WDM driver for Win2000/Wi nXP : 5.10.0.5477
WDM driver for Winx64 : 5.10.0.5477
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.65
Realtek Sound Effect Manager(RTHDCPL) : 2.1.5.5
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 2.0.1.20
Vista driver : -----
Vista driver for x86 : 6.0.1.5477
RtHDVCpl.exe : 1.0.0.89
RtkAPO.dll : 11.0.6000.45
RtkPgExt.dll : 6.0.6000.29
RTCOMDLL.dll : 2.0.0.79
RtlCPAPI.dll : 1.0.1.6
RTSndMgr.cpl : 1.0.0.6
RtkCoInst.dll : 1.0.1.7
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.1.3.0
SRSHP360.dll : 1.0.1.0
SRSTSHD.dll : 1.1.4.0
RtkApoApi.dll : 1.0.0.2
Vista driver for x64 : 6.0.1.5477
RAVCpl64.exe : 1.0.0.89
RtkAPO64.dll : 11.0.6000.45
RtPgEx64.dll : 6.0.6000.29
RTCOMDLL.dll : 2.0.0.79
RtlCPAPI.dll : 1.0.1.6
RTSnMg64.cpl : 1.0.0.6
RCoInst64.dll : 1.0.1.7
SRSTX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
SRSHP64.dll : 1.0.1.0
SRSTSH64.dll : 1.1.4.0
RtkApi64.dll : 1.0.0.2
HDM Driver : -----
Vista x64:
RtHDMVX.sys : 6.0.1.5413

```

```

Readme.txt
RtkHDM64.dll : 6.0.6000.37
RHDME64.dll : 6.0.6000.25
Vista x86:
RtHDMV.sys : 6.0.1.5413
RtkHDM.dll : 6.0.6000.37
RHDME64.dll : 6.0.6000.25
XP/2K x64:
RtHDMX.sys : 5.10.0.5413
XP/2K x86:
RtHDM.sys : 5.10.0.5413

Driver Setup Program : 2.44

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013
//=====
Driver Package R1.75
Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .
1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260,
ALC262, ALC267, ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660,
ALC662, ALC260, ALC262, ALC267, ALC268
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
1.) Customization.

For New architecture:
1.) Customization .

CPL :
1.) Customization.

Windows 2000/XP : -----
Windows 2000/XP :
WDM driver for Win2000/WinXP : 5.10.0.5473
WDM driver for Winx64 : 5.10.0.5473
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.65
Realtek Sound Effect Manager(RTHDCPL) : 2.1.5.2
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 2.0.1.20
Vista driver : -----
Vista driver for x86 : 6.0.1.5473
RtHDVCpl.exe : 1.0.0.88
RtkAPO.dll : 11.0.6000.44
RtkPgExt.dll : 6.0.6000.29
RTCOMDLL.dll : 2.0.0.79
RtlCPAPI.dll : 1.0.1.6
RTSndMgr.cpl : 1.0.0.6
RtkCoInst.dll : 1.0.1.7
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.1.3.0
SRSHP360.dll : 1.0.1.0
SRSTSHD.dll : 1.1.4.0
RtkApoApi.dll : 1.0.0.2
Vista driver for x64 : 6.0.1.5473
RAVCpl64.exe : 1.0.0.88
RtkAPO64.dll : 11.0.6000.44
RtkPgEx64.dll : 6.0.6000.29
RTCOMDLL.dll : 2.0.0.79
RtlCPAPI.dll : 1.0.1.6
RTSnMg64.cpl : 1.0.0.6
RtkCoInst.dll : 1.0.1.7

```

```

Readme.txt
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
SRSHP64.dll : 1.0.1.0
SRSTSH64.dll : 1.1.4.0
RtkApi64.dll : 1.0.0.2
HDM Driver : -----
Vista x64:
RtHDMVX.sys : 6.0.1.5413
RtkHDM64.dll : 6.0.6000.37
RHDMEx64.dll : 6.0.6000.25
Vista x86:
RtHDMV.sys : 6.0.1.5413
RtkHDM.dll : 6.0.6000.37
RHDMExt.dll : 6.0.6000.25
XP/2K x64:
RtHDMX.sys : 5.10.0.5413
XP/2K x86:
RtHDM.sys : 5.10.0.5413
Driver Setup Program : 2.42
Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013
//=====
Driver Package R1.74
Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .
1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260,
ALC262, ALC267, ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660,
ALC662, ALC260, ALC262, ALC267, ALC268
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
1.) Customization.
For New architecture:
1.) Customization .
CPL :
1.) Customization.
Windows 2000/XP : -----
Windows 2000/XP :
WDM driver for Win2000/WinXP : 5.10.0.5470
WDM driver for Winx64 : 5.10.0.5470
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.65
Realtek Sound Effect Manager(RTHDCPL) : 2.1.5.2
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 2.0.1.20
Vista driver : -----
Vista driver for x86 : 6.0.1.5470
RtHDVCpl.exe : 1.0.0.87
RtkAPO.dll : 11.0.6000.44
RtkPgExt.dll : 6.0.6000.28
RTCOMDLL.dll : 2.0.0.79
RtlCPAPI.dll : 1.0.1.6
RTSndMgr.cpl : 1.0.0.6
RtkCoInst.dll : 1.0.1.7
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.1.3.0
SRSHP360.dll : 1.0.1.0
SRSTSHD.dll : 1.1.4.0
RtkApoApi.dll : 1.0.0.2

```



Readme.txt

```

Vista driver for x64
RAVCpl64.exe : 6.0.1.5470
RtkAPO64.dll : 1.0.0.87
RtPgEx64.dll : 11.0.6000.44
RTCOMDLL.dll : 6.0.6000.28
RtLCPAPI.dll : 2.0.0.79
RTSnMg64.cpl : 1.0.1.6
RtkCoInst.dll : 1.0.0.6
SRSTSX64.dll : 1.0.1.7
SRSWOW64.dll : 3.2.0.0
SRSH64.dll : 1.1.3.0
SRSTSH64.dll : 1.0.1.0
RtkApi64.dll : 1.1.4.0
RtkApi64.dll : 1.0.0.2
HDM Driver : -----
Vista x64:
RtHDMVX.sys : 6.0.1.5413
RtkHDM64.dll : 6.0.6000.37
RHDME64.dll : 6.0.6000.25
Vista x86:
RtHDMV.sys : 6.0.1.5413
RtkHDM.dll : 6.0.6000.37
RHDME64.dll : 6.0.6000.25
XP/2K x64:
RtHDMX.sys : 5.10.0.5413
XP/2K x86:
RtHDM.sys : 5.10.0.5413
Driver Setup Program : 2.40

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013
//=====
Driver Package R1.73
Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .
1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260,
ALC262, ALC267, ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660,
ALC662, ALC260, ALC262, ALC267, ALC268
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
1.) Customization.

For New architecture:
1.) Customization .

CPL :
1.) Customization.

Windows 2000/XP : -----
Windows 2000/XP :
WDM driver for Win2000/WinXP : 5.10.0.5464
WDM driver for Winx64 : 5.10.0.5464
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtLCP) : 1.0.1.65
Realtek Sound Effect Manager(RTHDCPL) : 2.1.4.9
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 2.0.1.20
Vista driver : -----
Vista driver for x86 : 6.0.1.5464
RtHDVCpl.exe : 1.0.0.84
RtkAPO.dll : 11.0.6000.43
RtkPgExt.dll : 6.0.6000.27
RTCOMDLL.dll : 2.0.0.76

```

Readme.txt

```

RtICPAPI.dll : 1.0.1.6
RTSndMgr.cpl : 1.0.0.6
RtkColnst.dll : 1.0.1.7
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.1.3.0
SRSHP360.dll : 1.0.1.0
SRSTSHD.dll : 1.1.4.0
RtkApoApi.dll : 1.0.0.2
Vista driver for x64 : 6.0.1.5464
RAVCpl64.exe : 1.0.0.84
RtkAPO64.dll : 11.0.6000.43
RtPgEx64.dll : 6.0.6000.27
RTCOMDLL.dll : 2.0.0.76
RtICPAPI.dll : 1.0.1.6
RTSnMg64.cpl : 1.0.0.6
RtkColnst.dll : 1.0.1.7
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
SRSHP64.dll : 1.0.1.0
SRSTSH64.dll : 1.1.4.0
RtkApi64.dll : 1.0.0.2
HDMI Driver : -----
Vista x64:
RtHDMVX.sys : 6.0.1.5413
RtkHDM64.dll : 6.0.6000.37
RHDMEx64.dll : 6.0.6000.25
Vista x86:
RtHDMV.sys : 6.0.1.5413
RtkHDM.dll : 6.0.6000.37
RHDMExt.dll : 6.0.6000.25
XP/2K x64:
RtHDMX.sys : 5.10.0.5413
XP/2K x86:
RtHDM.sys : 5.10.0.5413

Driver Setup Program : 2.38

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====
Driver Package R1.72
Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .
1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260,
ALC262, ALC267, ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660,
ALC662, ALC260, ALC262, ALC267, ALC268
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
    1.) Customization.

For New architecture:
    1.) Customization .

CPL :
    1.) Customization.

Windows 2000/XP : -----
Windows 2000/XP :
WDM driver for Win2000/WinXP : 5.10.0.5449
WDM driver for Winx64 : 5.10.0.5449
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtICpl) : 1.0.1.65
Realtek Sound Effect Manager(RTHDCPL) : 2.1.4.2

```

```

Readme.txt
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 2.0.1.19
Vista driver : -----
Vista driver for x86 : 6.0.1.5449
RtHDVCpl.exe : 1.0.0.73
RtkAPO.dll : 11.0.6000.41
RtkPgExt.dll : 6.0.6000.27
RTCOMDLL.dll : 2.0.0.76
RtLCPAPI.dll : 1.0.1.6
RTSndMgr.cpl : 1.0.0.6
RtkColnst.dll : 1.0.1.7
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.1.2.0
SRSHP360.dll : 1.0.1.0
SRSTSHD.dll : 1.1.4.0
RtkApoApi.dll : 1.0.0.2
Vista driver for x64 : 6.0.1.5449
RAVCpl64.exe : 1.0.0.73
RtkAPO64.dll : 11.0.6000.41
RtPgEx64.dll : 6.0.6000.27
RTCOMDLL.dll : 2.0.0.76
RtLCPAPI.dll : 1.0.1.6
RTSnMg64.cpl : 1.0.0.6
RtkColnst.dll : 1.0.1.7
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.2.0
SRSHP64.dll : 1.0.1.0
SRSTSH64.dll : 1.1.4.0
RtkApi64.dll : 1.0.0.2
HDM Driver : -----
Vista x64:
RtHDMVX.sys : 6.0.1.5413
RtkHDM64.dll : 6.0.6000.37
RHDMEx64.dll : 6.0.6000.25
Vista x86:
RtHDMV.sys : 6.0.1.5413
RtkHDM.dll : 6.0.6000.37
RHDMExt.dll : 6.0.6000.25
XP/2K x64:
RtHDMX.sys : 5.10.0.5413
XP/2K x86:
RtHDM.sys : 5.10.0.5413
Driver Setup Program : 2.36

```

Windows 2000/XP Operate on :  
Microsoft High Definition Audio Driver Package - KB888111  
Package file version (kb888111.exe) : 6.1.22.0  
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.71

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
  - 1.) Customization.

For New architecture:

- 1.) Customization .

CPL :

- 1.) Customization.

Windows 2000/XP : -----

```

Readme.txt
WDM driver for Win2000/WinXP : 5.10.0.5443
WDM driver for Winx64 : 5.10.0.5443
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtLCpl) : 1.0.1.65
Realtek Sound Effect Manager(RTHDCPL) : 2.1.4.2
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 2.0.1.19
Vista driver : -----
Vista driver for x86 : 6.0.1.5443
RtHdVCpl.exe : 1.0.0.73
RtkAPO.dll : 11.0.6000.40
RtkPgExt.dll : 6.0.6000.27
RTCOMDLL.dll : 2.0.0.74
RtLCPAPI.dll : 1.0.1.6
RTSndMgr.cpl : 1.0.0.6
RtkColnst.dll : 1.0.1.7
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.1.2.0
SRSH360.dll : 1.0.1.0
SRSTSHD.dll : 1.1.4.0
RtkApoApi.dll : 1.0.0.2
Vista driver for x64 : 6.0.1.5443
RAVCpl64.exe : 1.0.0.73
RtkAPO64.dll : 11.0.6000.40
RtPgEx64.dll : 6.0.6000.27
RTCOMDLL.dll : 2.0.0.74
RtLCPAPI.dll : 1.0.1.6
RTSnMg64.cpl : 1.0.0.6
RtkColnst.dll : 1.0.1.7
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.2.0
SRSH64.dll : 1.0.1.0
SRSTSH64.dll : 1.1.4.0
RtkApi64.dll : 1.0.0.2
HDMI Driver : -----
Vista x64:
RtHDMVX.sys : 6.0.1.5413
RtkHDM64.dll : 6.0.6000.37
RHDMEx64.dll : 6.0.6000.25
Vista x86:
RtHDMV.sys : 6.0.1.5413
RtkHDM.dll : 6.0.6000.37
RHDMExt.dll : 6.0.6000.25
XP/2K x64:
RtHDMX.sys : 5.10.0.5413
XP/2K x86:
RtHDM.sys : 5.10.0.5413
Driver Setup Program : 2.36
Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013
//=====
Driver Package R1.70
Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .
1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260,
ALC262, ALC267, ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660,
ALC662, ALC260, ALC262, ALC267, ALC268
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
1.) Customization.

```

Readme.txt

For New architecture:  
1.) Customization .

CPL :  
1.) Customization.

```

Windows 2000/XP : -----
WDM driver for Win2000/WinXP           : 5.10.0.5436
WDM driver for Winx64                   : 5.10.0.5436
Realtek Soundman                        : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtlCpl)     : 1.0.1.65
Realtek Sound Effect Manager(RTHDCPL)    : 2.1.3.9
Alcwzrd.exe                             : 1.1.0.36
SkyTel.exe                               : 2.0.1.19
Vista driver : -----
Vista driver for x86                    : 6.0.1.5436
RtHDVCpl.exe                            : 1.0.0.69
RtkAPO.dll                               : 11.0.6000.38
RtkPgExt.dll                             : 6.0.6000.27
RTCOMDLL.dll                             : 2.0.0.74
RtlCPAPI.dll                             : 1.0.1.6
RTSndMgr.cpl                             : 1.0.0.5
RtkColnst.dll                            : 1.0.1.5
SRSTSXT.dll                              : 3.2.0.0
SRSWOW.dll                               : 1.1.2.0
SRSH360.dll                              : 1.0.1.0
SRSTSHD.dll                              : 1.1.4.0
RtkApoApi.dll                            : 1.0.0.2
Vista driver for x64                    : 6.0.1.5436
RAVCpl64.exe                             : 1.0.0.69
RtkAPO64.dll                             : 11.0.6000.38
RtPgEx64.dll                             : 6.0.6000.27
RTCOMDLL.dll                             : 2.0.0.74
RtlCPAPI.dll                             : 1.0.1.6
RTSnMg64.cpl                             : 1.0.0.5
RtkColnst.dll                            : 1.0.1.5
SRSTX64.dll                              : 3.2.0.0
SRSWOW64.dll                             : 1.1.2.0
SRSH64.dll                               : 1.0.1.0
SRSTSH64.dll                             : 1.1.4.0
RtkApi64.dll                             : 1.0.0.2
HDM Driver : -----
Vista x64:
RtHDM VX.sys                             : 6.0.1.5413
RtkHDM64.dll                             : 6.0.6000.37
RHDMEx64.dll                             : 6.0.6000.25
Vista x86:
RtHDM V.sys                              : 6.0.1.5413
RtkHDM.dll                               : 6.0.6000.37
RHDM Ext.dll                             : 6.0.6000.25
XP/2K x64:
RtHDM X.sys                              : 5.10.0.5413
XP/2K x86:
RtHDM.sys                                : 5.10.0.5413
Driver Setup Program                     : 2.35

```

Windows 2000/XP Operate on :  
Microsoft High Definition Audio Driver Package - KB888111  
Package file version (kb888111.exe) : 6.1.22.0  
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.69  
Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .  
1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC268  
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660,

Readme.txt

ALC662, ALC260, ALC262, ALC267, ALC268

3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
  - 1.) Customization.

For New architecture:

- 1.) Customization .

CPL :

- 1.) Customization.

Windows 2000/XP :	-----
WDM driver for Win2000/WinXP	: 5.10.0.5433
WDM driver for Winx64	: 5.10.0.5433
Realtek Soundman	: 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl)	: 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl)	: 1.0.0.9
Realtek Sound Effect Manager(RtICpl)	: 1.0.1.65
Realtek Sound Effect Manager(RTHDCPL)	: 2.1.3.6
Alcwzrd.exe	: 1.1.0.36
SkyTel.exe	: 2.0.1.17
Vista driver :	-----
Vista driver for x86	: 6.0.1.5433
RtHVCpl.exe	: 1.0.0.68
RtkAPO.dll	: 11.0.6000.38
RtkPgExt.dll	: 6.0.6000.27
RTCOMDLL.dll	: 2.0.0.74
RtICPAPI.dll	: 1.0.1.6
RTSndMgr.cpl	: 1.0.0.5
RtkColnst.dll	: 1.0.1.5
SRSTSXT.dll	: 3.2.0.0
SRSWOW.dll	: 1.1.2.0
SRSH360.dll	: 1.0.1.0
SRSTSHD.dll	: 1.1.4.0
RtkApoApi.dll	: 1.0.0.2
Vista driver for x64	: 6.0.1.5433
RAVCpl64.exe	: 1.0.0.68
RtkAPO64.dll	: 11.0.6000.38
RtkPgEx64.dll	: 6.0.6000.27
RTCOMDLL.dll	: 2.0.0.74
RtICPAPI.dll	: 1.0.1.6
RTSnMg64.cpl	: 1.0.0.5
RtkColnst.dll	: 1.0.1.5
SRSTX64.dll	: 3.2.0.0
SRSWOW64.dll	: 1.1.2.0
SRSH64.dll	: 1.0.1.0
SRSTSH64.dll	: 1.1.4.0
RtkApi64.dll	: 1.0.0.2
HDM Driver :	-----
Vista x64:	
RtHDMVX.sys	: 6.0.1.5413
RtkHDM64.dll	: 6.0.6000.37
RHDME64.dll	: 6.0.6000.25
Vista x86:	
RtHDMV.sys	: 6.0.1.5413
RtkHDM.dll	: 6.0.6000.37
RHDMExt.dll	: 6.0.6000.25
XP/2K x64:	
RtHDMX.sys	: 5.10.0.5413
XP/2K x86:	
RtHDM.sys	: 5.10.0.5413
Driver Setup Program	: 2.34

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111  
 Package file version (kb888111.exe) : 6.1.22.0

Readme.txt

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.68

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262,

ALC268

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660,

ALC662, ALC260, ALC262, ALC267, ALC268

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Customization.

For New architecture:

1.) Customization .

CPL :

1.) Customization.

Windows 2000/XP : -----

WDM driver for Win2000/WinXP	: 5.10.0.5413
WDM driver for Winx64	: 5.10.0.5413
Realtek Soundman	: 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl)	: 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl)	: 1.0.0.9
Realtek Sound Effect Manager(RtlCpl)	: 1.0.1.65
Realtek Sound Effect Manager(RTHDCPL)	: 2.1.3.2
Alcwzrd.exe	: 1.1.0.36
SkyTel.exe	: 2.0.1.12

Vista driver : -----

Vista driver for x86	: 6.0.1.5413
RtHDVCpl.exe	: 1.0.0.60
RtkAPO.dll	: 11.0.6000.37
RtkPgExt.dll	: 6.0.6000.25
RTCOMDLL.dll	: 2.0.0.73
RtlCPAPI.dll	: 1.0.1.6
RTSndMgr.cpl	: 1.0.0.5
RtkColnst.dll	: 1.0.1.2
SRSTSXT.dll	: 3.2.0.0
SRSWOW.dll	: 1.1.2.0
SRSHP360.dll	: 1.0.1.0
SRSTSHD.dll	: 1.1.3.0
RtkApoApi.dll	: 1.0.0.2
Vista driver for x64	: 6.0.1.5413
RAVCpl64.exe	: 1.0.0.60
RtkAPO64.dll	: 11.0.6000.37
RtPgEx64.dll	: 6.0.6000.25
RTCOMDLL.dll	: 2.0.0.73
RtlCPAPI.dll	: 1.0.1.6
RTSnMg64.cpl	: 1.0.0.5
RtkColnst.dll	: 1.0.1.2
SRSTX64.dll	: 3.2.0.0
SRSWOW64.dll	: 1.1.2.0
SRSHP64.dll	: 1.0.1.0
SRSTSH64.dll	: 1.1.3.0
RtkApi64.dll	: 1.0.0.2

HDMI Driver : -----

Vista x64:	
RtHDMVX.sys	: 6.0.1.5413
RtkHDM64.dll	: 6.0.6000.37
RHDMEx64.dll	: 6.0.6000.25
Vista x86:	
RtHDMV.sys	: 6.0.1.5413
RtkHDM.dll	: 6.0.6000.37
RHDMExt.dll	: 6.0.6000.25
XP/2K x64:	
RtHDMX.sys	: 5.10.0.5413
XP/2K x86:	

```

Readme.txt
RtHDM.sys : 5.10.0.5413
Driver Setup Program : 2.33

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013
//=====
Driver Package R1.67
Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .
1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262,
ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660,
ALC662, ALC260, ALC262, ALC267, ALC268
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
1.) Customization.

For New architecture:
1.) Customization .

CPL :
1.) Customization.

Windows 2000/XP : -----
WDM driver for Win2000/WinXP : 5.10.0.5413
WDM driver for Winx64 : 5.10.0.5413
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.65
Realtek Sound Effect Manager(RTHDCPL) : 2.1.3.2
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 2.0.1.12
Vista driver : -----
Vista driver for x86 : 6.0.1.5413
RtHdVcpl.exe : 1.0.0.60
RtkAPO.dll : 11.0.6000.37
RtkPgExt.dll : 6.0.6000.25
RTCOMDLL.dll : 2.0.0.73
RtlCPAPI.dll : 1.0.1.6
RTSndMgr.cpl : 1.0.0.5
RtkColnst.dll : 1.0.1.2
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.1.2.0
SRSH360.dll : 1.0.1.0
SRSTSHD.dll : 1.1.3.0
RtkApoApi.dll : 1.0.0.2
Vista driver for x64 : 6.0.1.5413
RAVCpl64.exe : 1.0.0.60
RtkAPO64.dll : 11.0.6000.37
RtPgEx64.dll : 6.0.6000.25
RTCOMDLL.dll : 2.0.0.73
RtlCPAPI.dll : 1.0.1.6
RTSnMg64.cpl : 1.0.0.5
RtkColnst.dll : 1.0.1.2
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.2.0
SRSH64.dll : 1.0.1.0
SRSTSH64.dll : 1.1.3.0
RtkApi64.dll : 1.0.0.2
HDM Driver : -----
Vista x64:
RtHDM VX.sys : 6.0.1.5368
RtkHDM64.dll : 6.0.6000.26
RHDMEx64.dll : 6.0.6000.20

```



Readme.txt

Vista x86:  
 RtHDMV.sys : 6.0.1.5368  
 RtkHDM.dll : 6.0.6000.26  
 RHDMExt.dll : 6.0.6000.20  
 XP/2K x64:  
 RtHDMX.sys : 5.10.0.5368  
 XP/2K x86:  
 RtHDM.sys : 5.10.0.5368  
 Driver Setup Program : 2.32

Windows 2000/XP Operate on :  
 Microsoft High Definition Audio Driver Package - KB888111  
 Package file version (kb888111.exe) : 6.1.22.0  
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.66

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
3. HDMI Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
  - 1.) Customization.

For New architecture:  
 1.) Customization .

CPL :  
 1.) Customization.

Windows 2000/XP : -----

WDM driver for Win2000/WinXP : 5.10.0.5404  
 WDM driver for Winx64 : 5.10.0.5404  
 Realtek Soundman : 1.0.0.30  
 Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10  
 Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9  
 Realtek Sound Effect Manager(RtlCpl) : 1.0.1.65  
 Realtek Sound Effect Manager(RTHDCPL) : 2.1.3.2  
 Alcwzrd.exe : 1.1.0.36  
 SkyTel.exe : 2.0.1.11

Vista driver : -----

Vista driver for x86 : 6.0.1.5404  
 RtHDVCpl.exe : 1.0.0.54  
 RtkAPO.dll : 11.0.6000.35  
 RtkPgExt.dll : 6.0.6000.24  
 RTCOMDLL.dll : 2.0.0.72  
 RtlCPAPI.dll : 1.0.1.6  
 RTSndMgr.cpl : 1.0.0.5  
 RtkColnst.dll : 1.0.1.1  
 SRSTSXT.dll : 3.2.0.0  
 SRSWOW.dll : 1.1.2.0  
 SRSH360.dll : 1.0.0.0  
 SRSTSHD.dll : 1.1.2.0  
 Vista driver for x64 : 6.0.1.5404  
 RAVCpl64.exe : 1.0.0.54  
 RtkAPO64.dll : 11.0.6000.35  
 RtkPgEx64.dll : 6.0.6000.24  
 RTCOMDLL.dll : 2.0.0.72  
 RtlCPAPI.dll : 1.0.1.6  
 RTSnMg64.cpl : 1.0.0.5  
 RtkColnst.dll : 1.0.1.1  
 SRSTX64.dll : 3.2.0.0  
 SRSWOW64.dll : 1.1.2.0  
 SRSH64.dll : 1.0.0.0  
 SRSTSH64.dll : 1.1.2.0

Readme.txt

```

HDM Driver : -----
Vista x64:
RtHDMVX.sys           : 6.0.1.5368
RtkHDM64.dll          : 6.0.6000.26
RHDME64.dll           : 6.0.6000.20
Vista x86:
RtHDMV.sys            : 6.0.1.5368
RtkHDM.dll            : 6.0.6000.26
RHDMEExt.dll          : 6.0.6000.20
XP/2K x64:
RtHDMX.sys            : 5.10.0.5368
XP/2K x86:
RtHDM.sys             : 5.10.0.5368

Driver Setup Program   : 2.32
  
```

Windows 2000/XP Operate on :  
 Microsoft High Definition Audio Driver Package - KB888111  
 Package file version (kb888111.exe) : 6.1.22.0  
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.65

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/Wi nXP/Wi n2000/Wi n2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft Wi ndowsXP, Wi dnows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
  - 1.) Customization.

For New architecture:

- 1.) Customization .

CPL :

- 1.) Customization.

```

Wi ndows 2000/XP : -----
WDM driver for Wi n2000/Wi nXP   : 5.10.0.5397
WDM driver for Wi nx64           : 5.10.0.5397
Realtek Soundman                 : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtlCpl)      : 1.0.1.65
Realtek Sound Effect Manager(RTHDCPL)     : 2.1.3.0
Alcwzrd.exe                       : 1.1.0.36
SkyTel.exe                         : 2.0.1.9
  
```

```

Vista driver : -----
Vista driver for x86              : 6.0.1.5397
RtHDVCpl.exe                      : 1.0.0.50
RtkAPO.dll                        : 11.0.6000.32
RtkPgExt.dll                      : 6.0.6000.22
RTCOMDLL.dll                     : 2.0.0.70
RtlCPAPI.dll                     : 1.0.1.6
RTSndMgr.cpl                     : 1.0.0.5
RtkCoInst.dll                    : 1.0.1.1
SRSTSXT.dll                      : 3.2.0.0
SRSWOW.dll                       : 1.0.6.0
Vista driver for x64             : 6.0.1.5397
RAVCpl64.exe                     : 1.0.0.50
RtkAPO64.dll                     : 11.0.6000.32
RtPgEx64.dll                     : 6.0.6000.22
RTCOMDLL.dll                     : 2.0.0.70
RtlCPAPI.dll                     : 1.0.1.6
RTSnMg64.cpl                     : 1.0.0.5
RtkCoInst.dll                    : 1.0.1.1
SRSTSX64.dll                     : 3.2.0.0
  
```

```

Readme.txt
SRSWOW64.dll : 1.0.6.0
HDM Driver : -----
Vista x64:
RtHDMVX.sys : 6.0.1.5368
RtkHDM64.dll : 6.0.6000.26
RHDME64.dll : 6.0.6000.20
Vista x86:
RtHDMV.sys : 6.0.1.5368
RtkHDM.dll : 6.0.6000.26
RHDME64.dll : 6.0.6000.20
XP/2K x64:
RtHDMX.sys : 5.10.0.5368
XP/2K x86:
RtHDM.sys : 5.10.0.5368

Driver Setup Program : 2.31

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013
//=====
Driver Package R1.64
Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .
1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262,
ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660,
ALC662, ALC260, ALC262, ALC267, ALC268
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
1.) Customization.

For New architecture:
1.) Customization .

CPL :
1.) Customization.

Windows 2000/XP : -----
WDM driver for Win2000/WinXP : 5.10.0.5391
WDM driver for Winx64 : 5.10.0.5391
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.65
Realtek Sound Effect Manager(RTHDCPL) : 2.1.2.9
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 2.0.1.7
Vista driver : -----
Vista driver for x86 : 6.0.1.5391
RtHDVCpl.exe : 1.0.0.46
RtkAPO.dll : 11.0.6000.31
RtkPgExt.dll : 6.0.6000.22
RTCOMDLL.dll : 2.0.0.69
RtlCPAPI.dll : 1.0.1.6
RTSndMgr.cpl : 1.0.0.5
RtkColInst.dll : 1.0.0.12
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.0.6.0
Vista driver for x64 : 6.0.1.5391
RAVCpl64.exe : 1.0.0.46
RtkAPO64.dll : 11.0.6000.31
RtkPgEx64.dll : 6.0.6000.22
RTCOMDLL.dll : 2.0.0.69
RtlCPAPI.dll : 1.0.1.6
RTSnMg64.cpl : 1.0.0.5
RtkColInst.dll : 1.0.0.12

```

Readme.txt

SRSTSX64.dll : 3.2.0.0  
 SRSWOW64.dll : 1.0.6.0  
 HDM Driver : -----  
 Vista x64:  
 RtHDMVX.sys : 6.0.1.5368  
 RtkHDM64.dll : 6.0.6000.26  
 RHDMEx64.dll : 6.0.6000.20  
 Vista x86:  
 RtHDMV.sys : 6.0.1.5368  
 RtkHDM.dll : 6.0.6000.26  
 RHDMEExt.dll : 6.0.6000.20  
 XP/2K x64:  
 RtHDMX.sys : 5.10.0.5368  
 XP/2K x86:  
 RtHDM.sys : 5.10.0.5368  
 Driver Setup Program : 2.30

Windows 2000/XP Operate on :  
 Microsoft High Definition Audio Driver Package - KB888111  
 Package file version (kb888111.exe) : 6.1.22.0  
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.63

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/Wi nXP/Wi n2000/Wi n2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
  - 1.) Customization.

For New architecture:  
 1.) Customization .

CPL :  
 1.) Customization.

Windows 2000/XP : -----  
 WDM driver for Win2000/Wi nXP : 5.10.0.5377  
 WDM driver for Winx64 : 5.10.0.5377  
 Realtek Soundman : 1.0.0.30  
 Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10  
 Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9  
 Realtek Sound Effect Manager(RtICpl) : 1.0.1.64  
 Realtek Sound Effect Manager(RTHDCPL) : 2.1.2.4  
 Alcwzrd.exe : 1.1.0.36  
 SkyTel.exe : 1.0.0.0

Vista driver : -----  
 Vista driver for x86 : 6.0.1.5386  
 RtHdVCpl.exe : 1.0.0.43  
 RtkAPO.dll : 11.0.6000.29  
 RtkPgExt.dll : 6.0.6000.22  
 RTCOMDLL.dll : 2.0.0.69  
 RtICPAPI.dll : 1.0.1.6  
 RTSndMgr.cpl : 1.0.0.4  
 RtkCoInst.dll : 1.0.0.9  
 SRSTSXT.dll : 3.2.0.0  
 SRSWOW.dll : 1.0.6.0  
 Vista driver for x64 : 6.0.1.5386  
 RAVCpl64.exe : 1.0.0.43  
 RtkAPO64.dll : 11.0.6000.29  
 RtkPgEx64.dll : 6.0.6000.22  
 RTCOMDLL.dll : 2.0.0.69  
 RtICPAPI.dll : 1.0.1.6  
 RTSnMg64.cpl : 1.0.0.4

```

Readme.txt
RtkCoInst.dll : 1.0.0.9
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.0.6.0
HDM Driver : -----
Vista x64:
RtHDMVX.sys : 6.0.1.5368
RtkHDM64.dll : 6.0.6000.26
RHDMEx64.dll : 6.0.6000.20
Vista x86:
RtHDMV.sys : 6.0.1.5368
RtkHDM.dll : 6.0.6000.26
RHDMExt.dll : 6.0.6000.20
XP/2K x64:
RtHDMX.sys : 5.10.0.5368
XP/2K x86:
RtHDM.sys : 5.10.0.5368

Driver Setup Program : 2.30

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013
//=====
Driver Package R1.62
Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .
1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262,
ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660,
ALC662, ALC260, ALC262, ALC267, ALC268
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
1.) Customization.

For New architecture:
1.) Customization .

CPL :
1.) Customization.

Windows 2000/XP : -----
WDM driver for Win2000/WinXP : 5.10.0.5377
WDM driver for Winx64 : 5.10.0.5377
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL) : 2.1.2.4
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 1.0.0.0
Vista driver : -----
Vista driver for x86 : 6.0.1.5384
RtHDVCpl.exe : 1.0.0.41
RtkAPO.dll : 11.0.6000.28
RtkPgExt.dll : 6.0.6000.21
RTCOMDLL.dll : 2.0.0.69
RtlCPAPI.dll : 1.0.1.6
RTSndMgr.cpl : 1.0.0.4
RtkCoInst.dll : 1.0.0.9
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.0.6.0
Vista driver for x64 : 6.0.1.5384
RAVCpl64.exe : 1.0.0.41
RtkAPO64.dll : 11.0.6000.28
RtPgEx64.dll : 6.0.6000.21
RTCOMDLL.dll : 2.0.0.69
RtlCPAPI.dll : 1.0.1.6

```

```

Readme.txt
RTSnMg64.cpl : 1.0.0.4
RtkColnst.dll : 1.0.0.9
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.0.6.0
HDM Driver : -----
Vista x64:
RtHDMVX.sys : 6.0.1.5368
RtkHDM64.dll : 6.0.6000.26
RHDMEx64.dll : 6.0.6000.20
Vista x86:
RtHDMV.sys : 6.0.1.5368
RtkHDM.dll : 6.0.6000.26
RHDMExt.dll : 6.0.6000.20
XP/2K x64:
RtHDMX.sys : 5.10.0.5368
XP/2K x86:
RtHDM.sys : 5.10.0.5368

Driver Setup Program : 2.30

```

Windows 2000/XP Operate on :  
Microsoft High Definition Audio Driver Package - KB888111  
Package file version (kb888111.exe) : 6.1.22.0  
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.61

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/Wi nXP/Wi n2000/Wi n2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft Wi ndowsXP, Wi dnows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix

1.) Customization.

For New architecture:

1.) Customization .

CPL :

1.) Customization.

```

Wi ndows 2000/XP : -----
WDM driver for Wi n2000/Wi nXP : 5.10.0.5377
WDM driver for Wi nx64 : 5.10.0.5377
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtICpl) : 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL) : 2.1.2.4
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 1.0.0.0

```

```

Vista driver : -----
Vista driver for x86 : 6.0.1.5377
RtHDVCpl.exe : 1.0.0.38
RtkAPO.dll : 11.0.6000.26
RtkPgExt.dll : 6.0.6000.20
RTCOMDLL.dll : 2.0.0.68
RtICPAPI.dll : 1.0.1.5
RTSndMgr.cpl : 1.0.0.4
RtkColnst.dll : 1.0.0.7
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.0.6.0
Vista driver for x64 : 6.0.1.5377
RAVCpl64.exe : 1.0.0.38
RtkAPO64.dll : 11.0.6000.26
RtPgEx64.dll : 6.0.6000.20
RTCOMDLL.dll : 2.0.0.68

```

```

Readme.txt
RtLCPAPI.dll : 1.0.1.5
RTSnMg64.cpl : 1.0.0.4
RtkColnst.dll : 1.0.0.7
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.0.6.0
HDM Driver : -----
Vista x64:
RtHDMVX.sys : 6.0.1.5356
RtkHDM64.dll : 6.0.6000.20
RHDMEx64.dll : 6.0.6000.17
Vista x86:
RtHDMV.sys : 6.0.1.5356
RtkHDM.dll : 6.0.6000.20
RHDMExt.dll : 6.0.6000.17
XP/2K x64:
RtHDMX.sys : 5.10.0.5356
XP/2K x86:
RtHDM.sys : 5.10.0.5356
Driver Setup Program : 2.30

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013
//=====
Driver Package R1.60
Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .
1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262,
ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660,
ALC662, ALC260, ALC262, ALC267, ALC268
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
1.) Customization.

For New architecture:
1.) Customization .

CPL :
1.) Customization.

Windows 2000/XP : -----
WDM driver for Win2000/WinXP : 5.10.0.5366
WDM driver for Winx64 : 5.10.0.5366
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtLCpl) : 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL) : 2.1.2.0
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 1.0.0.0
Vista driver : -----
Vista driver for x86 : 6.0.1.5374
RtHDVCpl.exe : 1.0.0.36
RtkAPO.dll : 11.0.6000.25
RtkPgExt.dll : 6.0.6000.20
RTCOMDLL.dll : 2.0.0.66
RtLCPAPI.dll : 1.0.1.5
RTSndMgr.cpl : 1.0.0.4
RtkColnst.dll : 1.0.0.7
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.0.6.0
Vista driver for x64 : 6.0.1.5374
RAVCpl64.exe : 1.0.0.36
RtkAPO64.dll : 11.0.6000.25
RtPgEx64.dll : 6.0.6000.20

```

```

Readme.txt
RTCOMDLL.dll : 2.0.0.65
RtLCPAPI.dll : 1.0.1.5
RTSnMgr64.cpl : 1.0.0.4
RtkCoInst.dll : 1.0.0.7
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.0.6.0
HDMI Driver : -----
Vista x64:
RtHDMVX.sys : 6.0.1.5356
RtkHDM64.dll : 6.0.6000.20
RHDMEx64.dll : 6.0.6000.17
Vista x86:
RtHDMV.sys : 6.0.1.5356
RtkHDM.dll : 6.0.6000.20
RHDMExt.dll : 6.0.6000.17
XP/2K x64:
RtHDMX.sys : 5.10.0.5356
XP/2K x86:
RtHDM.sys : 5.10.0.5356
Driver Setup Program : 2.28

```

Windows 2000/XP Operate on :  
Microsoft High Definition Audio Driver Package - KB888111  
Package file version (kb888111.exe) : 6.1.22.0  
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.59  
Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/Wi nXP/Wi n2000/Wi n2003 .  
1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC268  
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268  
3. HDMI Device WHQL Support: ATI HDMI Devices  
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64  
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)  
6. Add/Fix  
1.) Customization.  
For New architecture:  
1.) Customization .  
CPL :  
1.) Customization.

```

Windows 2000/XP : -----
WDM driver for Win2000/Wi nXP : 5.10.0.5366
WDM driver for Winx64 : 5.10.0.5366
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtLcpl) : 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL) : 2.1.2.0
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 1.0.0.0
Vista driver : -----
Vista driver for x86 : 6.0.1.5372
RtHDVCpl.exe : 1.0.0.33
RtkAPO.dll : 11.0.6000.25
RtkPgExt.dll : 6.0.6000.20
RTCOMDLL.dll : 2.0.0.66
RtLCPAPI.dll : 1.0.1.5
RTSnMgr.cpl : 1.0.0.4
RtkCoInst.dll : 1.0.0.7
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.0.6.0
Vista driver for x64 : 6.0.1.5372
RAVCpl64.exe : 1.0.0.33
RtkAPO64.dll : 11.0.6000.25

```



```

Readme.txt
RtPgEx64.dll : 6.0.6000.20
RTCOMDLL.dll : 2.0.0.65
RtLCPAPI.dll : 1.0.1.5
RTSndMgr64.cpl : 1.0.0.4
RtkColnst.dll : 1.0.0.7
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.0.6.0
HDM Driver : -----
Vista x64:
RtHDM VX.sys : 6.0.1.5356
RtkHDM64.dll : 6.0.6000.20
RHDMEx64.dll : 6.0.6000.17
Vista x86:
RtHDM V.sys : 6.0.1.5356
RtkHDM.dll : 6.0.6000.20
RHDM Ext.dll : 6.0.6000.17
XP/2K x64:
RtHDM X.sys : 5.10.0.5356
XP/2K x86:
RtHDM.sys : 5.10.0.5356

Driver Setup Program : 2.28

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013
//=====
Driver Package R1.58
Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .
1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262,
ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660,
ALC662, ALC260, ALC262, ALC267, ALC268
3. HDM Device WHQL Support: ATI HDM Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
1.) Customization.

For New architecture:
1.) Customization .

CPL :
1.) Customization.

Windows 2000/XP : -----
WDM driver for Win2000/WinXP : 5.10.0.5366
WDM driver for Winx64 : 5.10.0.5366
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL) : 2.1.2.0
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 1.0.0.0
Vista driver : -----
Vista driver for x86 : 6.0.1.5371
RtHDVCpl.exe : 1.0.0.32
RtkAPO.dll : 11.0.6000.25
RtkPgExt.dll : 6.0.6000.20
RTCOMDLL.dll : 2.0.0.66
RtLCPAPI.dll : 1.0.1.5
RTSndMgr.cpl : 1.0.0.4
RtkColnst.dll : 1.0.0.7
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.0.6.0
Vista driver for x64 : 6.0.1.5371
RAVCpl64.exe : 1.0.0.32

```

```

Readme.txt
RtkAPO64.dll : 11.0.6000.25
RtPgEx64.dll : 6.0.6000.20
RTCOMDLL.dll : 2.0.0.65
RtLCPAPI.dll : 1.0.1.5
RTSnMgr64.cpl : 1.0.0.4
RtkCoInst.dll : 1.0.0.7
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.0.6.0
HDMI Driver : -----
Vista x64:
RtHDMVX.sys : 6.0.1.5356
RtkHDM64.dll : 6.0.6000.20
RHDMEx64.dll : 6.0.6000.17
Vista x86:
RtHDMV.sys : 6.0.1.5356
RtkHDM.dll : 6.0.6000.20
RHDMExt.dll : 6.0.6000.17
XP/2K x64:
RtHDMX.sys : 5.10.0.5356
XP/2K x86:
RtHDM.sys : 5.10.0.5356
Driver Setup Program : 2.28
Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013
//=====
Driver Package R1.57
Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .
1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262,
ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660,
ALC662, ALC260, ALC262, ALC267, ALC268
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
1.) Customization.
For New architecture:
1.) Customization .
CPL :
1.) Customization.
Windows 2000/XP : -----
WDM driver for Win2000/WinXP : 5.10.0.5366
WDM driver for Winx64 : 5.10.0.5366
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtLcpl) : 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL) : 2.1.2.0
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 1.0.0.0
Vista driver : -----
Vista driver for x86 : 6.0.1.5361
RtHdVcpl.exe : 1.0.0.27
RtkAPO.dll : 11.0.6000.20
RtPgExt.dll : 6.0.6000.17
RTCOMDLL.dll : 2.0.0.65
RtLCPAPI.dll : 1.0.1.5
RTSndMgr.cpl : 1.0.0.1
RtkCoInst.dll : 1.0.0.6
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.0.6.0
Vista driver for x64 : 6.0.1.5361

```

Readme.txt

RAVCpl64.exe : 1.0.0.27  
 RtkAPO64.dll : 11.0.6000.20  
 RtpgEx64.dll : 6.0.6000.17  
 RTCOMDLL.dll : 2.0.0.65  
 RtlCPAPI.dll : 1.0.1.5  
 RTSndMgr64.cpl : 1.0.0.1  
 RtkColnst.dll : 1.0.0.6  
 SRSTSX64.dll : 3.2.0.0  
 SRSWOW64.dll : 1.0.6.0

HDM Driver : -----  
 Vista x64:  
 RtHDMVX.sys : 6.0.1.5356  
 RtkHDM64.dll : 6.0.6000.20  
 RHDME64.dll : 6.0.6000.17  
 Vista x86:  
 RtHDMV.sys : 6.0.1.5356  
 RtkHDM.dll : 6.0.6000.20  
 RHDMEExt.dll : 6.0.6000.17  
 XP/2K x64:  
 RtHDMX.sys : 5.10.0.5356  
 XP/2K x86:  
 RtHDM.sys : 5.10.0.5356

Driver Setup Program : 2.27

Windows 2000/XP Operate on :  
 Microsoft High Definition Audio Driver Package - KB888111  
 Package file version (kb888111.exe) : 6.1.22.0  
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.56

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
3. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
4. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
5. Add/Fix
  - 1.) Customization.

For New architecture:

- 1.) Customization .

CPL :

- 1.) Customization.

Windows 2000/XP :

WDM driver for Win2000/WinXP : 5.10.0.5345  
 WDM driver for Winx64 : 5.10.0.5345  
 Realtek Soundman : 1.0.0.30  
 Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10  
 Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9  
 Realtek Sound Effect Manager(RtlCpl) : 1.0.1.64  
 Realtek Sound Effect Manager(RTHDCPL) : 2.1.1.4  
 Alcwzrd.exe : 1.1.0.36  
 SkyTel.exe : 1.0.0.0  
 Vista driver :  
 Vista driver for x86 : 6.0.1.5361  
 RtHDVCpl.exe : 1.0.0.27  
 RtkAPO.dll : 11.0.6000.20  
 RtkPgExt.dll : 6.0.6000.17  
 RTCOMDLL.dll : 2.0.0.65  
 RtlCPAPI.dll : 1.0.1.5  
 RTSndMgr.cpl : 1.0.0.1  
 RtkColnst.dll : 1.0.0.6  
 SRSTSXT.dll : 3.2.0.0  
 SRSWOW.dll : 1.0.6.0  
 Vista driver for x64 : 6.0.1.5361

```

Readme.txt
RAVCpl64.exe           : 1.0.0.27
RtkAPO64.dll           : 11.0.6000.20
RtPgEx64.dll           : 6.0.6000.17
RTCOMDLL.dll          : 2.0.0.65
RtlCPAPI.dll           : 1.0.1.5
RTSnMgr64.cpl          : 1.0.0.1
RtkCoInst.dll          : 1.0.0.6
SRSTSX64.dll           : 3.2.0.0
SRSWOW64.dll           : 1.0.6.0

Driver Setup Program   : 2.27

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013
//=====
Driver Package R1.55
1. Vista logo Codec Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262,
ALC268
2. Windows 2000/XP logo Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD,
ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
3. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
4. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
5. Add/Fix
   1.) Customization.

For New architecture:
   1.) Customization .

CPL :
   1.) Customization.

Windows 2000/XP :
WDM driver for Win2000/WinXP : 5.10.0.5345
WDM driver for Winx64 : 5.10.0.5345
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL) : 2.1.1.4
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 1.0.0.0
Vista driver :
Vista driver for x86 : 6.0.1.5350
RtHDVCpl.exe : 1.0.0.21
RtkAPO.dll : 11.0.6000.16
RtPgExt.dll : 6.0.6000.15
RTCOMDLL.dll : 2.0.0.65
RtlCPAPI.dll : 1.0.1.5
RTSnMgr.cpl : 1.0.0.1
RtkCoInst.dll : 1.0.0.3
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.0.6.0
Vista driver for x64 : 6.0.1.5350
RAVCpl64.exe : 1.0.0.21
RtkAPO64.dll : 11.0.6000.16
RtPgEx64.dll : 6.0.6000.15
RTCOMDLL.dll : 2.0.0.65
RtlCPAPI.dll : 1.0.1.5
RTSnMgr64.cpl : 1.0.0.1
RtkCoInst.dll : 1.0.0.4
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.0.6.0

Driver Setup Program : 2.24

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111

```

Readme.txt

Package file version (kb888111.exe) : 6.1.22.0  
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.54

1. Vista logo Codec Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC268
2. Windows 2000/XP logo Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
3. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
4. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
5. Add/Fix
  - 1.) Customization.

For New architecture:

- 1.) Customization .

CPL :

- 1.) Customization.

Windows 2000/XP :

WDM driver for Win2000/WinXP	: 5.10.0.5345
WDM driver for Winx64	: 5.10.0.5345
Realtek Soundman	: 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl)	: 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl)	: 1.0.0.9
Realtek Sound Effect Manager(RtlCpl)	: 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL)	: 2.1.1.4
Alcwzrd.exe	: 1.1.0.36
SkyTel.exe	: 1.0.0.0
Vista driver :	
Vista driver for x86	: 6.0.1.5334
RtHDVCpl.exe	: 1.0.0.11
RtkAPO.dll	: 11.0.5600.13
RtkPgExt.dll	: 6.0.5600.12
RTCOMDLL.dll	: 1.0.0.63
RtlCPAPI.dll	: 1.0.1.5
RTSndMgr.cpl	: 1.0.0.1
RtkCoInst.dll	: 1.0.0.2
Vista driver for x64	: 6.0.1.5334
RAVCpl64.exe	: 1.0.0.11
RtkAPO64.dll	: 11.0.5600.13
RtPgEx64.dll	: 6.0.5600.12
RTCOMDLL.dll	: 1.0.0.63
RtlCPAPI.dll	: 1.0.1.5
RTSnMg64.cpl	: 1.0.0.1
RtkCoInst.dll	: 1.0.0.2

Driver Setup Program : 2.23

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111  
Package file version (kb888111.exe) : 6.1.22.0  
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.53

1. Vista logo Codec Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC268
2. Windows 2000/XP logo Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
3. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
4. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
5. Add/Fix
  - 1.) Customization.

For New architecture:

- 1.) Customization .
- 2.) Fixed issue -> DTM Test \ Hal timer issue for V5331 Vista driver ( Potential risk ).

CPL :

1.) Customization.

```

Windows 2000/XP :
WDM driver for Win2000/WinXP : 5.10.0.5324
WDM driver for Winx64 : 5.10.0.5324
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL) : 2.1.1.1
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 1.0.0.0
Vista driver :
Vista driver for x86 : 6.0.1.5334
RtHDVCpl.exe : 1.0.0.11
RtkAPO.dll : 11.0.5600.13
RtkPgExt.dll : 6.0.5600.12
RTCOMDLL.dll : 1.0.0.63
RtlCPAPI.dll : 1.0.1.5
RTSndMgr.cpl : 1.0.0.1
RtkColnst.dll : 1.0.0.2
Vista driver for x64 : 6.0.1.5334
RAVCpl64.exe : 1.0.0.11
RtkAPO64.dll : 11.0.5600.13
RtPgEx64.dll : 6.0.5600.12
RTCOMDLL.dll : 1.0.0.63
RtlCPAPI.dll : 1.0.1.5
RTSnMg64.cpl : 1.0.0.1
RtkColnst.dll : 1.0.0.2

Driver Setup Program : 2.21

```

```

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

```

//=====

Driver Package R1.52

1. Vista logo Codec Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC268
2. Windows 2000/XP logo Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
3. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
4. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
5. Add/Fix
  - 1.) Customization.

For New architecture:

- 1.) Customization .
- 2.) Known issue -> DTM Test \ Hal timer issue for V5331 Vista driver ( Potential risk ).

CPL :

- 1.) Customization.

```

Windows 2000/XP :
WDM driver for Win2000/WinXP : 5.10.0.5324
WDM driver for Winx64 : 5.10.0.5324
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL) : 2.1.1.1
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 1.0.0.0
Vista driver :
Vista driver for x86 : 6.0.1.5331
RtHDVCpl.exe : 1.0.0.9
RtkAPO.dll : 11.0.5600.13
RtkPgExt.dll : 6.0.5600.12

```

```

Readme.txt
RTCOMDLL.dll : 1.0.0.63
RtlCPAPI.dll : 1.0.0.7
RTSndMgr.cpl : 1.0.0.1
RtkCoInst.dll : 1.0.0.1
Vista driver for x64 : 6.0.1.5331
RAVCpl64.exe : 1.0.0.9
RtkAPO64.dll : 11.0.5600.13
RtPgEx64.dll : 6.0.5600.12
RTCOMDLL.dll : 1.0.0.63
RtlCPAPI.dll : 1.0.0.7
RTSndMgr64.cpl : 1.0.0.1
RtkCoInst.dll : 1.0.0.1

Driver Setup Program : 2.20

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013
//=====
Driver Package R1.51
1. Vista logo Codec Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262,
ALC268
2. Windows 2000/XP logo Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD,
ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
3. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
4. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
5. Add/Fix
1.) Customization.

For New architecture:
1.) Customization .

CPL :
1.) Customization.

Windows 2000/XP :
WDM driver for Win2000/WinXP : 5.10.0.5324
WDM driver for Winx64 : 5.10.0.5324
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL) : 2.1.1.1
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 1.0.0.0
Vista driver :
Vista driver for x86 : 6.0.1.5322
RtHDVCpl.exe : 1.0.0.7
RtkAPO.dll : 11.0.5600.13
RtkPgExt.dll : 6.0.5600.12
RTCOMDLL.dll : 1.0.0.63
RtlCPAPI.dll : 1.0.0.7
RTSndMgr.cpl : 1.0.0.1
Vista driver for x64 : 6.0.1.5322
RAVCpl64.exe : 1.0.0.7
RtkAPO64.dll : 11.0.5600.13
RtPgEx64.dll : 6.0.5600.12
RTCOMDLL.dll : 1.0.0.63
RtlCPAPI.dll : 1.0.0.7
RTSndMgr64.cpl : 1.0.0.1
Driver Setup Program : 2.20

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013
//=====
Driver Package R1.50

```

Readme.txt

1. Vista logo Codec Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC268
2. Windows 2000/XP logo Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC268
3. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
4. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
5. Add/Fix

1.) Customization.

For New architecture:

1.) Customization .

CPL :

1.) Customization.

Windows 2000/XP :

WDM driver for Win2000/WinXP	: 5.10.0.5319
WDM driver for Winx64	: 5.10.0.5319
Realtek Soundman	: 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl)	: 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl)	: 1.0.0.9
Realtek Sound Effect Manager(RtlCpl)	: 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL)	: 2.1.0.8
Alcwzrd.exe	: 1.1.0.36
SkyTel.exe	: 1.0.0.0
Vista driver :	
Vista driver for x86	: 6.0.1.5322
RtHVCpl.exe	: 1.0.0.7
RtkAPO.dll	: 11.0.5600.13
RtkPgExt.dll	: 6.0.5600.12
RTCOMDLL.dll	: 1.0.0.63
RtlCPAPI.dll	: 1.0.0.7
RTSndMgr.cpl	: 1.0.0.1
Vista driver for x64	: 6.0.1.5322
RAVCpl64.exe	: 1.0.0.7
RtkAPO64.dll	: 11.0.5600.13
RtPgEx64.dll	: 6.0.5600.12
RTCOMDLL.dll	: 1.0.0.63
RtlCPAPI.dll	: 1.0.0.7
RTSnMg64.cpl	: 1.0.0.1
Driver Setup Program	: 2.19

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.49

1. Vista logo Codec Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC268
2. Windows 2000/XP logo Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC268
3. OS Supporting: Microsoft WindowsXP, Windows2000, Vista x86/x64
4. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
5. Add/Fix

1.) Customization.

For New architecture:

1.) Customization .

CPL :

1.) Customization.

Windows 2000/XP :

WDM driver for Win2000/WinXP	: 5.10.0.5319
WDM driver for Winx64	: 5.10.0.5319
Realtek Soundman	: 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl)	: 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl)	: 1.0.0.9



Readme.txt

Realtek Sound Effect Manager(RtlCpl) : 1.0.1.64  
Realtek Sound Effect Manager(RTHDCPL) : 2.1.0.8  
Alcwzrd.exe : 1.1.0.36  
SkyTel.exe : 1.0.0.0  
Vista driver :  
Vista driver for x86 : 6.0.1.5317  
RtHDVCpl.exe : 1.0.0.6  
RtkAPO.dll : 11.0.5600.12  
RtkPgExt.dll : 6.0.5600.12  
RTCOMDLL.dll : 1.0.0.63  
RtlCPAPI.dll : 1.0.0.7  
RTSndMgr.cpl : 1.0.0.1  
Vista driver for x64 : 6.0.1.5317  
RAVCpl64.exe : 1.0.0.6  
RtkAPO64.dll : 11.0.5600.12  
RtPgEx64.dll : 6.0.5600.12  
RTCOMDLL.dll : 1.0.0.63  
RtlCPAPI.dll : 1.0.0.7  
RTSndMgr64.cpl : 1.0.0.1  
Driver Setup Program : 2.19

Windows 2000/XP Operate on :  
Microsoft High Definition Audio Driver Package - KB888111  
Package file version (kb888111.exe) : 6.1.22.0  
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.48

Vista driver Version: 5.10.0.5317

1. Vista logo Codec Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC268
2. OS Supporting: Microsoft Windows Vista x86/x64

Vista driver for x86 : 6.10.0.5317  
RtHDVCpl.exe : 1.0.0.6  
RtkAPO.dll : 11.0.5600.12  
RtkPgExt.dll : 6.0.5600.12  
RTCOMDLL.dll : 1.0.0.63  
RtlCPAPI.dll : 1.0.0.7  
RTSndMgr.cpl : 1.0.0.1  
Vista driver for x64 : 6.10.0.5317  
RAVCpl64.exe : 1.0.0.6  
RtkAPO64.dll : 11.0.5600.12  
RtPgEx64.dll : 6.0.5600.12  
RTCOMDLL.dll : 1.0.0.63  
RtlCPAPI.dll : 1.0.0.7  
RTSndMgr64.cpl : 1.0.0.1  
Driver Setup Program : 2.19

//=====

Driver Package R1.47

RtkHDAud.sys Version: 5.10.0.5296

1. Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861, ALC861VD, ALC660, ALC260, ALC262, ALC268
2. OS Supporting: Microsoft WindowsXP, Windows2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix

1.) Customization.

For New architecture:

1.) Customization .

CPL :

1.) Customization.

WDM driver for Win2000/WinXP : 5.10.0.5296  
WDM driver for Winx64 : 5.10.0.5296  
Realtek Soundman : 1.0.0.30  
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10  
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9  
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.64

Readme.txt

Realtek Sound Effect Manager(RTHDCPL) : 2.0.9.8  
Alcwzrd.exe : 1.1.0.36  
SkyTel.exe : 1.0.0.0  
Driver Setup Program : 2.18

Operate on :

Microsoft High Definition Audio Driver Package - KB888111  
Package file version (kb888111.exe) : 6.1.22.0  
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.46

RtkHDAud.sys Version: 5.10.0.5294

1. Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861, ALC861VD, ALC660, ALC260, ALC262, ALC268

2. OS Supporting: Microsoft WindowsXP, Windows2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix

1.) Customization.

For New architecture:

1.) Customization .

CPL :

1.) Customization.

WDM driver for Win2000/WinXP : 5.10.0.5294  
WDM driver for Winx64 : 5.10.0.5294  
Realtek Soundman : 1.0.0.30  
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10  
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9  
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.64  
Realtek Sound Effect Manager(RTHDCPL) : 2.0.9.6  
Alcwzrd.exe : 1.1.0.36  
SkyTel.exe : 1.0.0.0  
Driver Setup Program : 2.16

Operate on :

Microsoft High Definition Audio Driver Package - KB888111  
Package file version (kb888111.exe) : 6.1.22.0  
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.45

RtkHDAud.sys Version: 5.10.0.5288

1. Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861, ALC861VD, ALC660, ALC260, ALC262, ALC268

2. OS Supporting: Microsoft WindowsXP, Windows2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix

1.) Customization.

For New architecture:

1.) Customization .

CPL :

1.) Customization.

WDM driver for Win2000/WinXP : 5.10.0.5288  
WDM driver for Winx64 : 5.10.0.5288  
Realtek Soundman : 1.0.0.30  
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10  
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9  
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.64  
Realtek Sound Effect Manager(RTHDCPL) : 2.0.9.1  
Alcwzrd.exe : 1.1.0.36  
SkyTel.exe : 1.0.0.0  
Driver Setup Program : 2.15

Operate on :

Microsoft High Definition Audio Driver Package - KB888111

Readme.txt

Package file version (kb888111.exe) : 6.1.22.0  
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.44

RtkHDAud.sys Version: 5.10.0.5286

1. Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861, ALC861VD, ALC660, ALC260, ALC262, ALC268

2. OS Supporting: Microsoft WindowsXP, Windows2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
  - 1.) Customization.

For New architecture:

- 1.) Customization .

CPL :

- 1.) Customization.

WDM driver for Win2000/WinXP	: 5.10.0.5286
WDM driver for Winx64	: 5.10.0.5286
Realtek Soundman	: 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl)	: 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl)	: 1.0.0.8
Realtek Sound Effect Manager(RtlCpl)	: 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL)	: 2.0.8.7
Alcwzrd.exe	: 1.1.0.36
SkyTel.exe	: 1.0.0.0
Driver Setup Program	: 2.15

Operate on :

Microsoft High Definition Audio Driver Package - KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.43

RtkHDAud.sys Version: 5.10.0.5283

1. Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861, ALC861VD, ALC660, ALC260, ALC262, ALC268

2. OS Supporting: Microsoft WindowsXP, Windows2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
  - 1.) Customization.

For New architecture:

- 1.) Customization .

CPL :

- 1.) Customization.

WDM driver for Win2000/WinXP	: 5.10.0.5283
WDM driver for Winx64	: 5.10.0.5283
Realtek Soundman	: 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl)	: 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl)	: 1.0.0.8
Realtek Sound Effect Manager(RtlCpl)	: 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL)	: 2.0.8.3
Alcwzrd.exe	: 1.1.0.36
SkyTel.exe	: 1.0.0.0
Driver Setup Program	: 2.15

Operate on :

Microsoft High Definition Audio Driver Package - KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.42

RtkHDAud.sys Version: 5.10.0.5282

1. Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861, ALC861VD, ALC660, ALC260, ALC262, ALC268

Readme.txt

2. OS Supporting: Microsoft WindowsXP, Windows2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
  - 1.) Customization.

For New architecture:

- 1.) Customization .
- 2.) Fix some game issue .

CPL :

- 1.) Customization.

WDM driver for Win2000/WinXP	: 5.10.0.5282
WDM driver for Winx64	: 5.10.0.5282
Realtek Soundman	: 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl)	: 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl)	: 1.0.0.8
Realtek Sound Effect Manager(RtlCpl)	: 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL)	: 2.0.8.0
Alcwzrd.exe	: 1.1.0.36
SkyTel.exe	: 1.0.0.0
Driver Setup Program	: 2.15

Operate on :

Microsoft High Definition Audio Driver Package - KB888111  
Package file version (kb888111.exe) : 6.1.22.0  
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.41

RtkHDAud.sys Version: 5.10.0.5273

1. Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861, ALC861VD, ALC660, ALC260, ALC262, ALC268

2. OS Supporting: Microsoft WindowsXP, Windows2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
  - 1.) Customization.

For New architecture:

- 1.) Customization.

CPL :

- 1.) Customization.

WDM driver for Win2000/WinXP	: 5.10.0.5273
WDM driver for Winx64	: 5.10.0.5273
Realtek Soundman	: 1.0.0.29
Realtek Sound Effect Manager(ALSndMgr.cpl)	: 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl)	: 1.0.0.8
Realtek Sound Effect Manager(RtlCpl)	: 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL)	: 2.0.7.3
Alcwzrd.exe	: 1.1.0.36
SkyTel.exe	: 1.0.0.0
Driver Setup Program	: 2.14

Operate on :

Microsoft High Definition Audio Driver Package - KB888111  
Package file version (kb888111.exe) : 6.1.22.0  
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.40

RtkHDAud.sys Version: 5.10.0.5268

1. Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861, ALC861VD, ALC660, ALC260, ALC262, ALC268

2. OS Supporting: Microsoft WindowsXP, Windows2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
  - 1.) Customization.

For New architecture:

Readme.txt

1.) Customization .

CPL :

1.) Customization.

InstallShield package :

- 1.) Correct present driver version in "Add or Remove Programs \ Support Information" .
- 2.) Windows 2000 installation reboot twice problem .

WDM driver for Win2000/WinXP	: 5.10.0.5268
WDM driver for Winx64	: 5.10.0.5268
Realtek Soundman	: 1.0.0.29
Realtek Sound Effect Manager(ALSndMgr.cpl)	: 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl)	: 1.0.0.8
Realtek Sound Effect Manager(RtlCpl)	: 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL)	: 2.0.7.0
Alcwzrd.exe	: 1.1.0.36
SkyTel.exe	: 1.0.0.0
Driver Setup Program	: 2.14

Operate on :

Microsoft High Definition Audio Driver Package - KB888111  
Package file version (kb888111.exe) : 6.1.22.0  
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.39

RtkHDAud.sys Version: 5.10.0.5265

1. Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861, ALC861VD, ALC260, ALC262
2. OS Supporting: Microsoft WindowsXP, Windows2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
  - 1.) Customization.

For New architecture:

1.) Customization .

CPL :

- 1.) Customization.
- 2.) Add support for left panel and right panel config.

InstallShield package :

- 1.) Copy file rule in Vista system .
- 2.) Show driver version in "Add or Remove Programs \ Support Information" .

WDM driver for Win2000/WinXP	: 5.10.0.5265
WDM driver for Winx64	: 5.10.0.5265
Realtek Soundman	: 1.0.0.29
Realtek Sound Effect Manager(ALSndMgr.cpl)	: 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl)	: 1.0.0.8
Realtek Sound Effect Manager(RtlCpl)	: 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL)	: 2.0.6.9
Alcwzrd.exe	: 1.1.0.36
SkyTel.exe	: 1.0.0.0
Driver Setup Program	: 2.13

Operate on :

Microsoft High Definition Audio Driver Package - KB888111  
Package file version (kb888111.exe) : 6.1.22.0  
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.38

RtkHDAud.sys Version: 5.10.0.5257

1. Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861, ALC260, ALC262
2. OS Supporting: Microsoft WindowsXP, Windows2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
  - 1.) Customization.

For New architecture:

Readme.txt

1.) Customization .

CPL :

1.) Customization.

InstallShield package :

- 1.) Add "XP2K" and "Vista" folder name for installation .
- 2.) Abort flag setting .

WDM driver for Win2000/WinXP	: 5.10.0.5257
WDM driver for Winx64	: 5.10.0.5257
Realtek Soundman	: 1.0.0.29
Realtek Sound Effect Manager(ALSndMgr.cpl)	: 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl)	: 1.0.0.8
Realtek Sound Effect Manager(RtlCpl)	: 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL)	: 2.0.6.6
Alcwzrd.exe	: 1.1.0.36
SkyTel.exe	: 1.0.0.0
Driver Setup Program	: 2.11

Operate on :

Microsoft High Definition Audio Driver Package - KB888111  
Package file version (kb888111.exe) : 6.1.22.0  
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.37

RtkHDAud.sys Version: 5.10.0.5253

1. Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861, ALC260, ALC262
2. OS Supporting: Microsoft WindowsXP, Windows2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
  - 1.) Customization.

For New architecture:

1.) Customization .

CPL :

1.) Customization.

InstallShield package :

1.) Upgrade to IS11.5 .

WDM driver for Win2000/WinXP	: 5.10.0.5253
WDM driver for Winx64	: 5.10.0.5253
Realtek Soundman	: 1.0.0.29
Realtek Sound Effect Manager(ALSndMgr.cpl)	: 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl)	: 1.0.0.8
Realtek Sound Effect Manager(RtlCpl)	: 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL)	: 2.0.6.4
Alcwzrd.exe	: 1.1.0.36
SkyTel.exe	: 1.0.0.0
Driver Setup Program	: 2.09

Operate on :

Microsoft High Definition Audio Driver Package - KB888111  
Package file version (kb888111.exe) : 6.1.22.0  
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.36

RtkHDAud.sys Version: 5.10.0.5247

1. Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861, ALC260, ALC262
2. OS Supporting: Microsoft WindowsXP, Windows2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
  - 1.) Customization.

For New architecture:

- 1.) Customization .
- 2.) Add ALC888 .

Readme.txt

CPL :  
1.) Customization.

InstallShield package :

WDM driver for Win2000/WinXP : 5.10.0.5247  
WDM driver for Winx64 : 5.10.0.5247  
Realtek Soundman : 1.0.0.28  
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10  
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.8  
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.62  
Realtek Sound Effect Manager(RTHDCPL) : 2.0.5.9  
Alcwzrd.exe : 1.1.0.35  
Driver Setup Program : 2.06

Operate on :

Microsoft High Definition Audio Driver Package - KB888111  
Package file version (kb888111.exe) : 6.1.22.0  
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.35

RtkHDAud.sys Version: 5.10.0.5242

1. Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC861, ALC260, ALC262
2. OS Supporting: Microsoft WindowsXP, Windows2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix  
1.) Customization.

For New architecture:

- 1.) Customization .

CPL :  
1.) Customization.

InstallShield package :

WDM driver for Win2000/WinXP : 5.10.0.5242  
WDM driver for Winx64 : 5.10.0.5242  
Realtek Soundman : 1.0.0.28  
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10  
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.8  
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.62  
Realtek Sound Effect Manager(RTHDCPL) : 2.0.5.4  
Alcwzrd.exe : 1.1.0.35  
Driver Setup Program : 2.06

Operate on :

Microsoft High Definition Audio Driver Package - KB888111  
Package file version (kb888111.exe) : 6.1.22.0  
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.34

RtkHDAud.sys Version: 5.10.0.5233

1. Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC861, ALC260, ALC262
2. OS Supporting: Microsoft WindowsXP, Windows2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix  
1.) Customization.

For New architecture:

- 1.) Customization .
- 2.) Fixed Adobe Premiere Pro 1.5 Crash issue .

CPL :  
1.) Customization.

InstallShield package :

- 1.) Rtlupd termination return error code .

Readme.txt

- 2.) Receive error code rule from Rtlupd SetupAPI .
- 3.) SetupCopyOEM install rule .

WDM driver for Win2000/WinXP : 5.10.0.5233  
WDM driver for Winx64 : 5.10.0.5233  
Realtek Soundman : 1.0.0.28  
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10  
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.8  
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.62  
Realtek Sound Effect Manager(RTHDCPL) : 2.0.4.9  
Alcwzrd.exe : 1.1.0.35  
Driver Setup Program : 2.06

Operate on :

Microsoft High Definition Audio Driver Package - KB888111  
Package file version (kb888111.exe) : 6.1.22.0  
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.33

RtkHDAud.sys Version: 5.10.0.5229

1. Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC861, ALC260, ALC262
2. OS Supporting: Microsoft WindowsXP, Windows2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
  - 1.) Customization.

For New architecture:

- 1.) Customization .

CPL :

- 1.) Customization.

InstallShield package :

- 1.) Bus driver detect issue .

WDM driver for Win2000/WinXP : 5.10.0.5229  
WDM driver for Winx64 : 5.10.0.5229  
Realtek Soundman : 1.0.0.28  
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10  
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.8  
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.61  
Realtek Sound Effect Manager(RTHDCPL) : 2.0.4.7  
Alcwzrd.exe : 1.1.0.34  
Driver Setup Program : 2.05

Operate on :

Microsoft High Definition Audio Driver Package - KB888111  
Package file version (kb888111.exe) : 6.1.22.0  
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.32

RtkHDAud.sys Version: 5.10.0.5224

1. Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC861, ALC260, ALC262
2. OS Supporting: Microsoft WindowsXP, Windows2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
  - 1.) Customization.

For New architecture:

- 1.) Customization .

CPL :

- 1.) Customization.

InstallShield package :

- 1.) Report installation progress and result to "C:\RTHSetup.log" within silent mode .
- 2.) Rtlupd setup API will not appear message dialog in silent mode .

WDM driver for Win2000/WinXP : 5.10.0.5224



Readme.txt

WDM driver for Winx64 : 5.10.0.5224  
Realtek Soundman : 1.0.0.28  
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10  
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.8  
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.61  
Realtek Sound Effect Manager(RTHDCPL) : 2.0.4.4  
Alcwzrd.exe : 1.1.0.34  
Driver Setup Program : 2.04

Operate on :

Microsoft High Definition Audio Driver Package - KB888111  
Package file version (kb888111.exe) : 6.1.22.0  
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.31

RtkHDAud.sys Version: 5.10.0.5221

1. Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC861, ALC260, ALC262
2. OS Supporting: Microsoft WindowsXP, Windows2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
  - 1.) Customization.

For New architecture:

- 1.) Customization .
- 2.) Add ALC885 HD Audio Codec for WHQL .

CPL :

- 1.) Customization.

InstallShield package :

WDM driver for Win2000/WinXP : 5.10.0.5221  
WDM driver for Winx64 : 5.10.0.5221  
Realtek Soundman : 1.0.0.27  
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10  
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.8  
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.60  
Realtek Sound Effect Manager(RTHDCPL) : 2.0.4.2  
Alcwzrd.exe : 1.1.0.33  
Driver Setup Program : 2.03

Operate on :

Microsoft High Definition Audio Driver Package - KB888111  
Package file version (kb888111.exe) : 6.1.22.0  
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.30

RtkHDAud.sys Version: 5.10.0.5211

1. Codec Supporting: ALC880, ALC882, ALC883, ALC861, ALC260, ALC262
2. OS Supporting: Microsoft WindowsXP, Windows2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
  - 1.) Customization.

For New architecture:

- 1.) Customization .
- 2.) Bug fixed when recording AEC device failed on 880 .

CPL :

- 1.) Customization.

InstallShield package :

WDM driver for Win2000/WinXP : 5.10.0.5211  
WDM driver for Winx64 : 5.10.0.5211  
Realtek Soundman : 1.0.0.24  
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10  
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.8  
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.58

Readme.txt

Realtek Sound Effect Manager(RTHDCPL) : 2.0.3.9  
Alcwzrd.exe : 1.1.0.31  
Driver Setup Program : 2.03

Operate on :

Microsoft High Definition Audio Driver Package - KB888111  
Package file version (kb888111.exe) : 6.1.22.0  
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.29

RtkHDAud.sys Version: 5.10.0.5202

1. Codec Supporting: ALC880, ALC882, ALC883, ALC861, ALC260, ALC262
2. OS Supporting: Microsoft WindowsXP, Windows2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
  - 1.) Customization.

For New architecture:

- 1.) Customization.

CPL :

- 1.) Customization.

InstallShield package :

WDM driver for Win2000/WinXP : 5.10.0.5202  
WDM driver for Winx64 : 5.10.0.5202  
Realtek Soundman : 1.0.0.21  
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10  
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.7  
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.54  
Realtek Sound Effect Manager(RTHDCPL) : 2.0.3.4  
Alcwzrd.exe : 1.1.0.29  
Driver Setup Program : 2.02c

Operate on :

Microsoft High Definition Audio Driver Package - KB888111  
Package file version (kb888111.exe) : 6.1.22.0  
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.28

RtkHDAud.sys Version: 5.10.0.5200

1. Codec Supporting: ALC880, ALC882, ALC883, ALC861, ALC260, ALC262
2. OS Supporting: Microsoft WindowsXP, Windows2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
  - 1.) Customization.

For New architecture:

- 1.) Customization.
- 2.) Add ALC265 .

CPL :

- 1.) Side speaker testing has no sound when 3D engine is disabled.

InstallShield package :

- 1.) Add Chipset ID VEN\_1002&DEV\_4383 .

WDM driver for Win2000/WinXP : 5.10.0.5200  
WDM driver for Winx64 : 5.10.0.5200  
Realtek Soundman : 1.0.0.21  
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10  
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.7  
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.53  
Realtek Sound Effect Manager(RTHDCPL) : 2.0.3.2  
Alcwzrd.exe : 1.1.0.28  
Driver Setup Program : 2.02c

Operate on :

Readme.txt

Microsoft High Definition Audio Driver Package - KB888111  
Package file version (kb888111.exe) : 6.1.22.0  
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.27

RtkHDAud.sys Version: 5.10.0.5188

1. Codec Supporting: ALC880, ALC882, ALC883, ALC861, ALC260, ALC262
2. OS Supporting: Microsoft WindowsXP, Windows2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
  - 1.) Customization.

For New architecture:

- 1.) Customization.

InstallShield package :

Fix :

1. Add installation file "RTHDAEQ\*.dat" .
2. Add Package version in setup.ini .
3. Manual installation setting for InstallShield .

WDM driver for Win2000/WinXP : 5.10.0.5188  
WDM driver for Winx64 : 5.10.0.5188  
Realtek Soundman : 1.0.0.21  
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10  
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.7  
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.53  
Realtek Sound Effect Manager(RTHDCPL) : 2.0.2.6  
Alcwzrd.exe : 1.1.0.28  
Driver Setup Program : 2.02a

Operate on :

Microsoft High Definition Audio Driver Package - KB888111  
Package file version (kb888111.exe) : 6.1.22.0  
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.26

RtkHDAud.sys Version: 5.10.0.5178

1. Codec Supporting: ALC880, ALC882, ALC883, ALC861, ALC260, ALC262
2. OS Supporting: Microsoft WindowsXP, Windows2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
  - 1.) Customization.

For New architecture:

- 1.) Customization.

InstallShield package :

Fix :

1. Set rebooting twice for installation UAA QFE on Win2000 .

WDM driver for Win2000/WinXP : 5.10.0.5178  
WDM driver for Winx64 : 5.10.0.5178  
Realtek Soundman : 1.0.0.21  
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10  
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.6  
Realtek Sound Effect Manager(RtlCpl) : 1.0.1.52  
Realtek Sound Effect Manager(RTHDCPL) : 2.0.2.1  
Alcwzrd.exe : 1.1.0.28  
Driver Setup Program : 2.00

Operate on :

Microsoft High Definition Audio Driver Package - KB888111  
Package file version (kb888111.exe) : 6.1.22.0  
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.25

RtkHDAud.sys Version: 5.10.0.5172

1. Codec Supporting: ALC880, ALC882, ALC883, ALC861, ALC260, ALC262

Readme.txt

2. OS Supporting: Microsoft WindowsXP, Windows2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
  - 1.) Customization.

For New architecture:  
1.) Customization.

InstallShield package :

Fix :

1. Rtlupd.exe(2.5.0.5) fixed roll-back problem ( It can not delete oem.inf file before update driver ).
2. Change Azalia name in setup.ini file .
3. Don't popup Rtlupd dialog when you select "No" on Hotfix installation dialog .

Add :

1. System language identifier .
2. Change pop-up dialog Product name ( Azalia->High Definition ) .

WDM driver for Win2000/WinXP	: 5.10.0.5172
WDM driver for Winx64	: 5.10.0.5172
Realtek Soundman	: 1.0.0.21
Realtek Sound Effect Manager(ALSndMgr.cpl)	: 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl)	: 1.0.0.6
Realtek Sound Effect Manager(RtlCpl)	: 1.0.1.51
Realtek Sound Effect Manager(RTHDCPL)	: 2.0.1.7
Alcwzrd.exe	: 1.1.0.27
Driver Setup Program	: 1.99

Operate on :

Microsoft High Definition Audio Driver Package - KB888111  
Package file version (kb888111.exe) : 6.1.22.0  
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.24

RtkHDAud.sys Version: 5.10.0.5152

1. Codec Supporting: ALC880, ALC882, ALC883, ALC861, ALC260, ALC262
2. OS Supporting: Microsoft WindowsXP, Windows2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
  - 1.) Customization.

For New architecture:

- 1.) Customization.
- 2.) Support 192KHz sample rate output.

InstallShield package :

Fix :

1. Reboot timing after installation MS QFE ( UAA driver ) .
2. Uninstallation dialog description .

Add :

1. MS hotfix KB901105 can be included by HD package ( If get MS licence ) .
2. Hotfix KB901105 Warning message .

WDM driver for Win2000/WinXP	: 5.10.0.5152
WDM driver for Winx64	: 5.10.0.5152
Realtek Soundman	: 1.0.0.18
Realtek Sound Effect Manager(ALSndMgr.cpl)	: 1.0.0.7
Realtek Sound Effect Manager(RTSndMgr.cpl)	: 1.0.0.4
Realtek Sound Effect Manager(RtlCpl)	: 1.0.1.46
Realtek Sound Effect Manager(RTHDCPL)	: 2.0.0.8
Alcwzrd.exe	: 1.1.0.24
Driver Setup Program	: 1.96

Operate on :

Microsoft High Definition Audio Driver Package - KB888111  
Package file version (kb888111.exe) : 6.1.22.0  
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.23

Readme.txt

RtkHDAud.sys Version: 5.10.0.5136

1. Codec Supporting: ALC880, ALC882, ALC883, ALC861, ALC260, ALC262
2. OS Supporting: Microsoft WindowsXP, Windows2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
  - 1.) Customization.

For New architecture:

- 1.) Customization.
- 2.) Support new codec ALC262, ALC883

InstallShield package :

- 1.) Check OS service pack number with InstallShield .
- 2.) Change audio wizard quitting procedure .

WDM driver for Win2000/WinXP	: 5.10.0.5136
WDM driver for Winx64	: 5.10.0.5136
Realtek Soundman	: 1.0.0.17
Realtek Sound Effect Manager(ALSndMgr.cpl)	: 1.0.0.7
Realtek Sound Effect Manager(RTSndMgr.cpl)	: 1.0.0.4
Realtek Sound Effect Manager(RtlCpl)	: 1.0.1.43
Realtek Sound Effect Manager(RTHDCPL)	: 1.1.2.3
Alcwzrd.exe	: 1.1.0.23
Driver Setup Program	: 1.92

Operate on :

Microsoft High Definition Audio Driver Package - KB888111  
Package file version (kb888111.exe) : 6.1.22.0  
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.22

RtkHDAud.sys Version: 5.10.0.5128

1. Codec Supporting: ALC880, ALC882, ALC861, ALC260
2. OS Supporting: Microsoft WindowsXP, Windows2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
  - 1.) Customization.

For New architecture:

- 1.) Customization.

InstallShield package :

- 1.) Setup progress backward .
- 2.) Driver size on Add and remove programs .
- 3.) Refresh driver size on Add and Remove Programs .
- 4.) Check RtlExupd.dll version .
- 5.) Check RtlHDCpl.exe version .

WDM driver for Win2000/WinXP	: 5.10.0.5128
WDM driver for Winx64	: 5.10.0.5128
Realtek Soundman	: 1.0.0.17
Realtek Sound Effect Manager(ALSndMgr.cpl)	: 1.0.0.7
Realtek Sound Effect Manager(RTSndMgr.cpl)	: 1.0.0.4
Realtek Sound Effect Manager(RtlCpl)	: 1.0.1.40
Realtek Sound Effect Manager(RTHDCPL)	: 1.1.1.9
Alcwzrd.exe	: 1.1.0.20
Driver Setup Program	: 1.91

Operate on :

Microsoft High Definition Audio Driver Package - KB888111  
Package file version (kb888111.exe) : 6.1.22.0  
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.21

RtkHDAud.sys Version: 5.10.0.5127

1. Codec Supporting: ALC880, ALC882, ALC260
2. OS Supporting: Microsoft WindowsXP, Windows2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix

Readme.txt

1.) Customization.

For New architecture:

- 1.) Customization.
- 2.) Support DTS Encoder and DTS Neo for special version codec .

SoundMan.exe Version: 1.0.0.17  
ALSndMgr.cpl Version: 1.0.0.7  
Rtlcpl.exe Version: 1.0.1.40  
Alcwzrd.exe Version: 1.1.0.20

Operate on :

Microsoft High Definition Audio Driver Package - KB888111  
Package file version (kb888111.exe) : 6.1.22.0  
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.20

RtkHDAud.sys Version: 5.10.0.5125  
1. Codec Supporting: ALC880, ALC882, ALC260  
2. OS Supporting: Microsoft WindowsXP, Windows2000, Winx64  
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)  
4. Add/Fix  
1.) Customization.

For New architecture:

- 1.) Customization.
- 2.) Fixed the issue of SPDIF-In capture

SoundMan.exe Version: 1.0.0.17  
ALSndMgr.cpl Version: 1.0.0.7  
Rtlcpl.exe Version: 1.0.1.40  
Alcwzrd.exe Version: 1.1.0.20

Operate on :

Microsoft High Definition Audio Driver Package - KB888111  
Package file version (kb888111.exe) : 6.1.22.0  
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.19

RtkHDAud.sys Version: 5.10.0.5123  
1. Codec Supporting: ALC880, ALC882, ALC260  
2. OS Supporting: Microsoft WindowsXP, Windows2000, Winx64  
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)  
4. Add/Fix  
1. Customization.  
2. Avoid Pop noise when toggle output sampling rate for ALC260.  
3. Restore the original timer resolution first before check the original system timer resolution.

For New architecture:

- 1.) Customization.
- 2.) Driver store mixer setting after windows reboot

SoundMan.exe Version: 1.0.0.14  
ALSndMgr.cpl Version: 1.0.0.5  
Rtlcpl.exe Version: 1.0.1.39  
Alcwzrd.exe Version: 1.1.0.19

Operate on :

Microsoft High Definition Audio Driver Package - KB888111  
Package file version (kb888111.exe) : 6.1.22.0  
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.18

RtkHDAud.sys Version: 5.10.0.5122  
1. Codec Supporting: ALC880, ALC882, ALC260  
2. OS Supporting: Microsoft WindowsXP, Windows2000  
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)  
4. Add/Fix  
1. Customization.

Readme.txt

2. Add 2 default values of codec subsystem ID for ALC260.

For New architecture:

- 1.) Customization.
- 2.) Fixed the issue of uncontinuous sound after suspend on some machine.

SoundMan.exe Version: 1.0.0.14  
ALSndMgr.cpl Version: 1.0.0.5  
Rtlcpl.exe Version: 1.0.1.38  
Alcwzrd.exe Version: 1.1.0.18

Operate on :

Microsoft High Definition Audio Driver Package - KB888111  
Package file version (kb888111.exe) : 6.1.22.0  
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.17

RtkHDAud.sys Version: 5.10.0.5120  
1. Codec Supporting: ALC880, ALC882, ALC260, ALC861  
2. OS Supporting: Microsoft WindowsXP, Windows2000  
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)  
4. Add/Fix  
1. Customization.  
2. Restore certain register value when resume from system suspend.

For New architecture:

- 1.) Customization.
- 2.) Improve reliability for switching multiple streaming.

SoundMan.exe Version: 1.0.0.14  
ALSndMgr.cpl Version: 1.0.0.5  
Rtlcpl.exe Version: 1.0.1.38  
Alcwzrd.exe Version: 1.1.0.18

Operate on :

Microsoft High Definition Audio Driver Package - KB888111  
Package file version (kb888111.exe) : 6.1.22.0  
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.16

RtkHDAud.sys Version: 5.10.0.5119  
1. Codec Supporting: ALC880, ALC882, ALC260, ALC861  
2. OS Supporting: Microsoft WindowsXP, Windows2000  
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)  
4. Add/Fix  
1. Customization.  
2. Fix initial noise issue for the certain models.  
3. Check codec SubsystemID verb to decide the driver path when driver initialize.  
4. Don't modify Configuration byte Verbs when driver initialize.  
5. Fix Buffer size un-alignment issue.

For New architecture:

- 1.) Customization.
- 2.) Fix the problem when play AC-3 stream by SPDIF interface
- 3.) Change device name for multiple streaming issue.

SoundMan.exe Version: 1.0.0.14  
ALSndMgr.cpl Version: 1.0.0.5  
Rtlcpl.exe Version: 1.0.1.38  
Alcwzrd.exe Version: 1.1.0.17

Operate on :

Microsoft High Definition Audio Driver Package - KB888111  
Package file version (kb888111.exe) : 6.1.22.0  
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.15

RtkHDAud.sys Version: 5.10.0.5116  
1. Codec Supporting: ALC880, ALC882, ALC260, ALC861

Readme.txt

2. OS Supporting: Microsoft WindowsXP, Windows2000
3. Pack with Microsoft High Definition Audio UAAV1(5011)
4. Add/Fix
  - 1.) Customization.
  - 2.) Auto lock SPDIF-in signal when SPDIF-in signal is unlocked.
  - 3.) Fix SPDIF out copy protection issue.
  - 4.) Add patch code for ALC260 potential risk.

For New architecture:

- 1.) Customization.
- 2.) Fix new feature problem on multiple streaming.
- 3.) Fix capture problem on ALC882.

SoundMan.exe Version: 1.0.0.14  
ALSndMgr.cpl Version: 1.0.0.5  
Rtlcpl.exe Version: 1.0.1.38  
Alcwzrd.exe Version: 1.1.0.17

Operate on :

Microsoft High Definition Audio Driver Package - KB835221  
Package file version (kb835221.exe) : 6.1.1.0  
Hdaudio.sys version : 5.10.00.5011

//=====

Driver Package R1.14

- RtkHDAud.sys Version: 5.10.0.5109
1. Codec Supporting: ALC880, ALC882, ALC260, ALC861
  2. OS Supporting: Microsoft WindowsXP, Windows2000
  3. Pack with Microsoft High Definition Audio UAAV1(5011)
  4. Add/Fix
    - 1.) Customization.
    - 2.) Reduce delay time when volume is adjusted.
    - 3.) Fix hang up issue when system resume from S3.

For New architecture:

- 1.) New architecture of HD audio driver formal release.

SoundMan.exe Version: 1.0.0.14  
ALSndMgr.cpl Version: 1.0.0.4  
Rtlcpl.exe Version: 1.0.1.37  
Alcwzrd.exe Version: 1.1.0.16

Operate on :

Microsoft High Definition Audio Driver Package - KB835221  
Package file version (kb835221.exe) : 6.1.1.0  
Hdaudio.sys version : 5.10.00.5011

//=====

Driver Package R1.13

- RtkHDAud.sys Version: 5.10.0.5038
1. Codec Supporting: ALC880, ALC260, ALC861
  2. OS Supporting: Microsoft WindowsXP, Windows2000
  3. Pack with Microsoft High Definition Audio UAAV1(5011)
  4. Add/Fix
    - 1) Reduce initialize noise

SoundMan.exe Version: 1.0.0.14  
ALSndMgr.cpl Version: 1.0.0.5  
Rtlcpl.exe Version: 1.0.1.36  
Alcwzrd.exe Version: 1.1.0.15

Operate on :

Microsoft High Definition Audio Driver Package - KB835221  
Package file version (kb835221.exe) : 6.1.1.0  
Hdaudio.sys version : 5.10.00.5011

//=====

Driver Package R1.12

- RtkHDAud.sys Version: 5.10.0.5037
1. Codec Supporting: ALC880, ALC260, ALC861
  2. OS Supporting: Microsoft WindowsXP, Windows2000
  3. Pack with Microsoft High Definition Audio UAAV1(5011)



4. Add/Fix

- 1) Improve recording performance.
- 2) Reduce initialize noise

SoundMan.exe Version: 1.0.0.14  
ALSndMgr.cpl Version: 1.0.0.5  
Rtlcpl.exe Version: 1.0.1.36  
Alcwzrd.exe Version: 1.1.0.15

Operate on :

Microsoft High Definition Audio Driver Package - KB835221  
Package file version (kb835221.exe) : 6.1.1.0  
Hdaudio.sys version : 5.10.00.5011

//=====

Driver Package R1.11

RtkHDAud.sys Version: 5.10.0.5036  
1. Codec Supporting: ALC880, ALC260, ALC861  
2. OS Supporting: Microsoft WindowsXP, Windows2000  
3. Pack with Microsoft High Definition Audio UAAV1(5011)  
4. Add/Fix

SoundMan.exe Version: 1.0.0.14  
ALSndMgr.cpl Version: 1.0.0.5  
Rtlcpl.exe Version: 1.0.1.35  
Alcwzrd.exe Version: 1.1.0.15

Operate on :

Microsoft High Definition Audio Driver Package - KB835221  
Package file version (kb835221.exe) : 6.1.1.0  
Hdaudio.sys version : 5.10.00.5011

//=====

Driver Package R1.10

RtkHDAud.sys Version: 5.10.0.5034  
1. Codec Supporting: ALC880, ALC260, ALC861  
2. OS Supporting: Microsoft WindowsXP, Windows2000  
3. Pack with Microsoft High Definition Audio UAAV1(5011)  
4. Add/Fix

- 1) Fix the problem that there is little noise when start stream playing
- 2) Fix the problem that in WinDVD, the SPDIF option still exist even there is no SPDIF

SoundMan.exe Version: 1.0.0.14

1. Set the default recording device as "Realtek HD Audio rear input" device

ALSndMgr.cpl Version: 1.0.0.5

Rtlcpl.exe Version: 1.0.1.34

Alcwzrd.exe Version: 1.1.0.15

1. Keep previous Jack setting.
2. Check whether have any jack plugin when restart OS, and popup the device window if wizard detect any new device plugin.

Operate on :

Microsoft High Definition Audio Driver Package - KB835221  
Package file version (kb835221.exe) : 6.1.1.0  
Hdaudio.sys version : 5.10.00.5011

//=====

Driver Package R1.09

RtkHDAud.sys Version: 5.10.0.5033  
1. Codec Supporting: ALC880, ALC260, ALC861  
2. OS Supporting: Microsoft WindowsXP, Windows2000  
3. Pack with Microsoft High Definition Audio OOB Binaries V1.0

SoundMan.exe Version: 1.0.0.14

1. Set the default recording device as "Realtek HD Audio rear input" device

ALSndMgr.cpl Version: 1.0.0.5

Readme.txt

Rtlcpl.exe Version: 1.0.1.33  
Alcwzrd.exe Version: 1.1.0.14

Operate on :

Microsoft High Definition Audio Driver Package - KB835221  
Package file version (kb835221.exe) : 6.1.1.0  
Hdaudio.sys version : 5.10.00.5010

//=====

Driver Package R1.08

RtkHDAud.sys Version: 5.10.0.5032  
1. Codec Supporting: ALC880, ALC260, ALC861  
2. OS Supporting: Microsoft WindowsXP, Windows2000  
3. Pack with Microsoft High Definition Audio OOB Binaries V1.0

SoundMan.exe Version: 1.0.0.12  
ALSndMgr.cpl Version: 1.0.0.5  
Rtlcpl.exe Version: 1.0.1.33  
Alcwzrd.exe Version: 1.1.0.14

Operate on :

Microsoft High Definition Audio Driver Package - KB835221  
Package file version (kb835221.exe) : 6.1.1.0  
Hdaudio.sys version : 5.10.00.5010

//=====

Driver Package R1.07

RtkHDAud.sys Version: 5.10.0.5031  
1. Codec Supporting: ALC880, ALC260, ALC861  
2. OS Supporting: Microsoft WindowsXP, Windows2000  
3. Pack with Microsoft High Definition Audio OOB Binaries V1.0  
4. Add/Fix  
1) Fix the problem when playback with sound recorder, when change frequency from 48k to 44.1k in SPDIF page, playback will stop  
2) Support for ALC880G, ALC880D, ALC260D  
3) Fix the problem that system will hang up while perform audio test in 3DMark 2003

SoundMan.exe Version: 1.0.0.12  
ALSndMgr.cpl Version: 1.0.0.5

Rtlcpl.exe Version: 1.0.1.32  
1. Fix word collision problem in Multi-Language.

Alcwzrd.exe Version: 1.1.0.13  
1. Restore previous jack setting when reboot system

Operate on :

Microsoft High Definition Audio Driver Package - KB835221  
Package file version (kb835221.exe) : 6.1.1.0  
Hdaudio.sys version : 5.10.00.5010

//=====

Driver Package R1.06

RtkHDAud.sys Version: 5.10.0.5030  
1. Codec Supporting: ALC880, ALC260, ALC861  
2. OS Supporting: Microsoft WindowsXP, Windows2000  
3. Pack with Microsoft High Definition Audio OOB Binaries V1.0  
4. Add/Fix

SoundMan.exe Version: 1.0.0.12  
ALSndMgr.cpl Version: 1.0.0.3  
Rtlcpl.exe Version: 1.0.1.31  
Alcwzrd.exe Version: 1.1.0.12

Operate on :

Microsoft High Definition Audio Driver Package - KB835221  
Package file version (kb835221.exe) : 6.1.1.0  
Hdaudio.sys version : 5.10.00.5010

//=====

Driver Package R1.05

RtkHDAud.sys Version: 5.10.0.5029

Readme.txt

1. Codec Supporting: ALC880, ALC260, ALC861
2. OS Supporting: Microsoft WindowsXP, Windows2000
3. Pack with Microsoft High Definition Audio OOB Binaries V1.0
4. Add/Fix
  - 1) Add support for ALC861
  - 2) Fix the noise problem that when recording from SPDIF In at 96khz

SoundMan.exe Version: 1.0.0.12  
ALSndMgr.cpl Version: 1.0.0.5  
Rtlcpl.exe Version: 1.0.1.31  
Alcwzrd.exe Version: 1.1.0.12

Operate on :

Microsoft High Definition Audio Driver Package - KB835221  
Package file version (kb835221.exe) : 6.1.1.0  
Hdaudio.sys version : 5.10.00.5010

//=====

Driver Package R1.04

RtkHDAud.sys Version: 5.10.0.5028

1. Codec Supporting: ALC880, ALC260
2. OS Supporting: Microsoft WindowsXP, Windows2000
3. Pack with Microsoft High Definition Audio OOB Binaries V1.0
4. Add/Fix
  - 1) For UAJ A to A volume line, change type from KSNODETYPE\_MICROPHONE to KSNODETYPE\_ANALOG\_CONNECTOR
  - 2) Fix the problem that SPDIF out no sound in WinDVD
  - 3) Fix the problem that there is balance control in Center and Subwoofer volume line in W2k
  - 4) Change the component type of SPDIF-In from "KSNODETYPE\_ANALOG\_CONNECTOR" to "KSNODETYPE\_SPDIF\_INTERFACE"
  - 5) Fix the problem that mute SPDIF out in mixer doesn't work

SoundMan.exe Version: 1.0.0.12  
ALSndMgr.cpl Version: 1.0.0.3

Rtlcpl.exe Version: 1.0.1.31

1. Turn off all sound effect when speaker test!

Alcwzrd.exe Version: 1.1.0.12

Operate on :

Microsoft High Definition Audio Driver Package - KB835221  
Package file version (kb835221.exe) : 6.1.1.0  
Hdaudio.sys version : 5.10.00.5010

//=====

Driver Package R1.03

RtkHDAud.sys Version: 5.10.0.5027

SoundMan.exe Version: 1.0.0.4

ALSndMgr.cpl Version: 1.0.0.2

Rtlcpl.exe Version: 1.0.1.29

1. Sync the status which Enable/Disable wizard with alcwzrd
2. Make the tab of "Audio Wizard" independent from menu tabs.
3. Stop the play sound when menu tab is change.

Alcwzrd.exe Version: 1.1.0.12

1. Fixed broken wizard image.
2. Sync the status which Enable/Disable wizard with rtlcpl.

Operate on :

Microsoft High Definition Audio Driver Package - KB835221  
Package file version (kb835221.exe) : 6.1.1.0  
Hdaudio.sys version : 5.10.00.5010

//=====

Driver Package R1.01/R1.02

RtkHDAud.sys Version: 5.10.0.5022

1. Codec Supporting:

Readme.txt

2. OS Supporting: Microsoft WindowsXP, Windows2000
3. Pack with Microsoft High Definition Audio OOB Binaries V1.0
4. Add/Fix

SoundMan.exe Version: 1.0.0.4  
ALSndMgr.cpl Version: 1.0.0.2  
Rtlcpl.exe Version: 1.0.1.23

Alcwzrd.exe Version: 1.1.0.5

Operate on :

Microsoft High Definition Audio Driver Package - KB835221  
Package file version (kb835221.exe) : 6.1.1.0  
Hdaudio.sys version : 5.10.00.5010

//=====

Driver Package R1.0

RtkHDAud.sys Version: 5.10.0.5017

1. Codec Supporting: Add ALC880/ALC880M Rev. F Rev. G, ALC860
2. OS Supporting: Microsoft WindowsXP, Windows2000
3. Pack with Microsoft High Definition Audio OOB Binaries V1.0
4. Add/Fix

SoundMan.exe Version: 1.0.0.4  
ALSndMgr.cpl Version: 1.0.0.2  
Rtlcpl.exe Version: 1.0.1.23

Alcwzrd.exe Version: 1.1.0.5

Operate on :

Microsoft High Definition Audio Driver Package - KB835221  
Package file version (kb835221.exe) : 6.1.1.0  
Hdaudio.sys version : 5.10.00.5010