


# Intel® Solid State Drive Client PCIe\* Microsoft\* Windows\* Driver

## Release Notes

---

*July 2019*

*Software Version 4.3.0.1006*



Intel may make changes to specifications and product descriptions at any time, without notice. Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined". Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them. The information here is subject to change without notice. Do not finalize a design with this information.

The products described in this document may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Contact your local Intel sales office or your distributor to obtain the latest specifications and before placing your product order.


Copies of documents which have an order number and are referenced in this document, or other Intel literature, may be obtained by calling 1-800-548-4725, or go to: <http://www.intel.com/design/literature.htm>

All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice.

Intel and the Intel logo are trademarks of Intel Corporation in the U.S. and/or other countries.


\*Other names and brands may be claimed as the property of others.

Copyright © 2019 Intel Corporation. All rights reserved.




# Driver Revision History


Date	Document Version	Driver Version	Description
July	019	4.3.0.1006	Updated with certification for Microsoft Windows 10 Client family version 1903
April	017	4.3.0.1006	<p>New for this release:</p> <ul style="list-style-type: none"> <li>Resolved possible BSOD when issuing a Query Property temperature request</li> <li>Improved hot plug handling</li> </ul> <p>Known issues:</p> <ul style="list-style-type: none"> <li>Possible BSOD during System Sleep and Hibernate – currently suspected to be caused by a device/PCI error. No workaround at this time.</li> <li>Possible BSOD during System Sleep and Hibernate with multiple namespaces present</li> </ul>
November	016	4.2.0.1002	<p>New for this release:</p> <ul style="list-style-type: none"> <li>Support for Intel SSD 660p Series</li> <li>Resolved issues with hangs seen with third-party tools that monitor system status via S.M.A.R.T. interface</li> <li>Improved SCSI to NVMe command translation</li> </ul> <p>Known issues:</p> <ul style="list-style-type: none"> <li>Possible BSOD when issuing a Query Property temperature request.</li> </ul>
July	015	4.0.0.1007	<p>New for this release:</p> <ul style="list-style-type: none"> <li>DLL injection vulnerability (INTEL-SA-00154) was fixed with this release</li> <li>For more information on INTEL-SA-00154, please visit the following link - <a href="https://www.intel.com/content/www/us/en/security-center/advisory/intel-sa-00154.html">https://www.intel.com/content/www/us/en/security-center/advisory/intel-sa-00154.html</a></li> </ul>
April	014	4.0.0.1007	<p>New for this release:</p> <ul style="list-style-type: none"> <li>Support for Intel Optane 905P Series</li> </ul>



Date	Document Version	Driver Version	Description
February	013	4.0.0.1007	New for this release: <ul style="list-style-type: none"> <li>• Support for Intel SSD Pro 7600p/760p/E 6100p Series</li> <li>• Support for public Windows IOCTLs introduced in Windows 10</li> <li>• Support for features and functionality defined in the NVMe 1.3 specification</li> </ul>
December	012	3.2.0.1002	New for this release: <ul style="list-style-type: none"> <li>• Support for Intel Optane 900P Series</li> </ul>
October	011	3.1.0.1021	New for this release: <ul style="list-style-type: none"> <li>• Fixed BSOD/enumeration issue during hot plug</li> <li>• Fixed BSOD during Windows 7 OS installation</li> </ul>
August	010	3.1.0.1009	New for this release: <ul style="list-style-type: none"> <li>• Updates to SCSI translation for commands including Mode Select, Read Capacity, Security IN, and EUI64</li> </ul>
May	009	3.0.0.1013	New for this release: <ul style="list-style-type: none"> <li>• Hardened Driver Security</li> <li>• Updated to NVMe Spec 1.2c</li> <li>• Added support for Get/Set Feature Payloads when using vendor unique feature IDs</li> <li>• Added support for the Storage Firmware Update IOCTL</li> </ul>
November	008	1.8.0.1011	The following was fixed in this release: <ul style="list-style-type: none"> <li>• NVMe driver no longer installs over the RSTe driver</li> <li>• Adding support for the Windows 10 FW Update IOCTL</li> <li>• Fixed Yellow Bang after surprise hot-plug that occurs in some cases</li> <li>• Fixed BSOD during queue full condition with I/O</li> <li>• Fixed BSOD during S3 resume that occurs in some cases</li> <li>• Fixed BSOD during device power down that occurs in some cases on Windows 7</li> </ul>



Date	Document Version	Driver Version	Description
July 2016 June 2016	006	1.7.0.1002	<p>The following was fixed in this release:</p> <ul style="list-style-type: none"> <li>• BSOD during continuous reboot testing</li> <li>• NVMe DVL errors blocking Windows Server 2016 Certification</li> </ul>
April 2016	005	1.5.0.1002	<p>New for this release:</p> <ul style="list-style-type: none"> <li>• Set SCSI Mode Sense FUA bit as supported</li> <li>• Minor performance improvement</li> <li>• Implement SCSI Verify translation to NVMe*</li> </ul>
September 2015	004	1.3.0.1007	<p>New for this release:</p> <ul style="list-style-type: none"> <li>• Windows 10 Certification</li> <li>• Single installer for both x32 and x64 based Operating Systems</li> </ul> <p>The following was fixed in this release:</p> <ul style="list-style-type: none"> <li>• After Uninstall device shows an "unknown device," it now reports as PCIe* device.</li> <li>• BSOD when installed on systems with 0x120 logical Cores</li> <li>• Installer using silent install does not copy the license.</li> </ul>
June 2015	003	1.2.0.1002	<p>The following was fixed in this release:</p> <ul style="list-style-type: none"> <li>• Disable of NVMe Controller takes too long after S3+S4.</li> <li>• WHCK Trim Performance Test executable encounters a divide-by-zero error and fails to execute.</li> <li>• WHCK Rotational Rate Test Fails, Reporting 0 RPM</li> <li>• Update Windows Driver BusType to NVMe</li> </ul>
February 2015	002	1.1.0.1004	<p>The following was fixed in this release:</p> <ul style="list-style-type: none"> <li>• 0x9F BSOD during S3/S4 testing</li> <li>• BSOD due to low System Memory under 32bit</li> <li>• Drive does not translate some SCSI commands – READ CAPACITY, REQUEST SENSE and WRITE(6)</li> <li>• Windows Driver INF references Windows XP, there is no driver support and reference was removed</li> </ul>
September 2014	001	1.0.0.1023	<ul style="list-style-type: none"> <li>• Initial release version</li> </ul>
			<ul style="list-style-type: none"> <li>•</li> </ul>



Date	Document Version	Driver Version	Description